

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

| Campus Summary | | | |
|---------------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1965 | 2 | 44,825 |
| Campus Total | | | 44,825 |

Category : Exterior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------|---------------------------------------|--------------------------|----------|-----|------|-----------------------|----------|
| Entrance | | | | | | | |
| | Entrance Control - Audio | 1 - main entrance - West | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 1 - main entrance - West | 3 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Concrete | 1 - main entrance - West | 45 | LF | 6 | 10+ years | |
| | Power Door Operator and Controls | 1 - main entrance - West | 1 | EA | 7 | 6-10 years | |
| | Ramp Handrail - Steel_Ramp Handrail | 1 - main entrance - West | 40 | LF | 6 | 10+ years | |
| | Ramps - Concrete | 1 - main entrance - West | 20 | LF | 6 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | 1 - main entrance - West | 12 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 2 - Southwest | 2 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Concrete | 2 - Southwest | 20 | LF | 6 | 10+ years | |
| | Exterior Stairs - Stone | 2 - Southwest | 6 | LF | 6 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | 2 - Southwest | 4 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 3 - Southwest | 1 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Stone | 3 - Southwest | 3 | LF | 6 | 10+ years | |
| | Entrance Control - Audio | 4 - Southeast | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 4 - Southeast | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 5 - East | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 6 - East | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 7 - Northeast | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 7.1 - Northeast | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 8- North | 2 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Stone | 8- North | 6 | LF | 6 | 10+ years | |
| Foundation | | | | | | | |
| | Foundation - Concrete | Entire Building | 652 | LF | 6 | 10+ years | |

Category : Exterior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------|---|-----------------|----------|-----|------|-----------------------|----------|
| | Foundation - Concrete | Entire Building | 1 | LF | 6 | 10+ years | |
| | Foundation - Concrete | Entire Building | 5 | LF | 6 | 10+ years | |
| | Superstructure - Concrete | Entire Building | 44,825 | SF | 6 | 10+ years | |
| Lighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 12 | EA | 6 | 6-10 years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 13 | EA | 6 | 6-10 years | |
| Roof System | | | | | | | |
| | Access Ladder - Metal | 1 | 15 | EA | 7 | 10+ years | |
| | Coping - Metal | 1 | 809 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | 1 | 110 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | 1 | 19,600 | SF | 6 | 10+ years | |
| | Roof Hatch - Metal | 1 | 3 | EA | 7 | 10+ years | |
| | Roof Structure - Concrete | 1 | 19,600 | SF | 7 | 10+ years | |
| | Coping - Metal | 2 | 53 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | 2 | 21 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | 2 | 2,175 | SF | 6 | 10+ years | |
| | Roof Structure - Concrete | 2 | 2,175 | SF | 6 | 10+ years | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | 3 | 24 | LF | 7 | 10+ years | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | 3 | 15 | LF | 7 | 10+ years | |
| | Coping - Metal | 3 | 123 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | 3 | 13 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | 3 | 3,450 | SF | 7 | 10+ years | |
| | Roof Structure - Concrete | 3 | 3,450 | SF | 7 | 10+ years | |
| Walls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 166 | SF | 6 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 10,152 | SF | 6 | 10+ years | |
| | Exterior Walls - Precast Panel Wall | Entire Building | 527 | SF | 6 | 10+ years | |
| | Exterior Walls - Precast Panel Wall | Entire Building | 1 | SF | 5 | 2-5 years | |
| | Exterior Walls - Stone-Cast | Entire Building | 228 | SF | 6 | 10+ years | |
| Windows | | | | | | | |
| | Curtain wall - Louver | Entire Building | 126 | SF | 6 | 10+ years | |
| | Guard - Guards wire guard | Entire Building | 2,486 | SF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 660 | LF | 6 | 10+ years | |
| | Windows - Casement Lexan | Entire Building | 180 | SF | 5 | 6-10 years | |
| | Windows - Casement Lexan | Entire Building | 2,486 | SF | 5 | 6-10 years | |

Category : Electrical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---------------------------|--|-----------------|----------|-----|------|-----------------------|---|
| <u>Emergency System</u> | | | | | | | |
| | Automatic Transfer Switch | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Security System - CCTV | Entire Building | 44,825 | SF | 5 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 44,825 | SF | 5 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 11 | EA | 5 | 6-10 years | |
| | Exit Signs - Lunchroom | Entire Building | 2 | EA | 5 | 6-10 years | |
| | Exit Signs - Multipurpose Room | Entire Building | 6 | EA | 5 | 6-10 years | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 14 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Gym | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Lunchrooms | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 6,140 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Gym | Entire Building | 3,620 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 2,540 | SF | 6 | 10+ years | Building has EM panel |
| <u>Main Service</u> | | | | | | | |
| | Main Electrical Service - 1200 A 120/240/3PH | Electrical Room | 1 | EA | 4 | 2-5 years | Serves main building, 1965 installation, original, worn, not reliable |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | 6-10 years | 2 Meter and ATS, older functioning ATS. |
| | PA System | Entire Building | 44,825 | SF | 4 | 2-5 years | Many rooms not served by PA. Repair requested. Using held held radios |
| <u>Power Distribution</u> | | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 11 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 2 | EA | 7 | 10+ years | |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 1 | EA | 7 | 10+ years | |

Category : Electrical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|--|-----------------|----------|-----|------|-----------------------|----------|
| | Main Distribution Panels - Less than 400 amp | Entire Building | 1 | EA | 7 | 10+ years | |

Category : Fire Protection
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------|--------------------------|-----------------|----------|-----|------|-----------------------|----------|
| <u>Fire Alarm</u> | | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 10+ years | |
| | Fire Alarm Strobe Lights | Entire Building | 44,825 | SF | 6 | 10+ years | |
| | Fire Alarm_System | Entire Building | 44,825 | SF | 6 | 10+ years | |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------------|---|-----------------|----------|-----|------|-----------------------|--|
| <u>Air Conditioning</u> | | | | | | | |
| | Condensing Unit- Ground Mounted - Less than 5 tons | Mechanical Room | 1 | EA | 5 | 6-10 years | Previously not assessed, serves MDF room. Installed indoor, not outdoor |
| <u>Air Handling Systems</u> | | | | | | | |
| | Air Handling Unit-Package Single Zone-Indoor- Hot Water Coils - 4000-8000 cfm | 2nd Floor | 1 | EA | 5 | 6-10 years | AHU 1, Serves first floor, older, 1965 installation, functional, recently serviced |
| | Air Intake | 2nd Floor | 1 | EA | 5 | 6-10 years | |
| | Air Handling Unit-Package Single Zone-Indoor- Hot Water Coils - 4000-8000 cfm | 2nd Floor | 1 | EA | 5 | 6-10 years | AHU 2, Serves second floor, 1965 installation. Functional, recently serviced |
| | Air Intake | 2nd Floor | 1 | EA | 5 | 6-10 years | |
| | Air Handling Unit-Package Single Zone-Indoor- Hot Water Coils - Less than 4000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | AHU 3, Serves gym, recently serviced. Functional. 1965 installation |
| | Air Intake | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| <u>Boiler Systems</u> | | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Mechanical Room | 2 | EA | 5 | 6-10 years | |
| | Chemical Feeder | Mechanical Room | 1 | EA | 6 | 10+ years | Manually fed |
| | Combustion Dampers | Mechanical Room | 2 | EA | 5 | 6-10 years | |
| | Condensate Pump | Mechanical Room | 2 | EA | 6 | 10+ years | |
| | Feed Water Pumps and Tank | Mechanical Room | 1 | EA | 6 | 10+ years | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | Mechanical Room | 1 | EA | 5 | 6-10 years | B1, serves heat exchanger |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | Mechanical Room | 1 | EA | 5 | 6-10 years | B2, Repaired recently, serves heat exchanger |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------------------|---|-----------------|----------|-----|------|-----------------------|--|
| | Piping - Condensate Pipe- Steel | Mechanical Room | 40 | LF | 5 | 6-10 years | There are a few pipe clamps 1965 installation, serve heat exchanger. Minor leaks occasionally repaired Serve heat exchanger |
| | Piping - Steam Pipe- Steel | Mechanical Room | 40 | LF | 5 | 6-10 years | |
| | Steam Traps | Mechanical Room | 3 | EA | 5 | 6-10 years | |
| Gas Booster | | | | | | | |
| | Gas Booster | Boiler Room | 1 | EA | 6 | 10+ years | |
| | Gas Booster | Boiler Room | 1 | EA | 6 | 10+ years | |
| Heat Exchangers | | | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell Type | Boiler Room | 1 | EA | 5 | 6-10 years | HX 1, Serves air handlers and univents, 1965 installation. Functional. Tubes not internally cleaned recently |
| Heating Devices | | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 4 | EA | 5 | 6-10 years | 1965 installation, functional |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 13 | EA | 5 | 6-10 years | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 1 | EA | 5 | 6-10 years | |
| | Fin Tube - Hot Water | Entire Building | 40 | LF | 5 | 6-10 years | |
| | PTAC - Electric Heating and Self Contained Cooling | Entire Building | 4 | EA | 4 | 1-2 years | Not working, deteriorated, currently using window units for cooling. To be removed. Not needed |
| Mechanical Plumbing | | | | | | | |
| | Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 5 | 6-10 years | Serves heat exchanger |
| | Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 5 | 6-10 years | Serve heat exchanger |
| | Hydronic Supply and Return - Steel | Entire Building | 200 | LF | 5 | 10+ years | Served by heat exchanger, hot water |
| Temperature Control | | | | | | | |
| | Electric Thermostat | Entire Building | 1 | EA | 6 | 10+ years | Serve fan coil unit in MDF room |
| | Pneumatic System | Entire Building | 44,825 | SF | 5 | 6-10 years | Mostly manually controlled. Frequent maintenance needed |
| | Thermostats - Pneumatic | Entire Building | 14 | EA | 5 | 6-10 years | Serve univents and AHUs |
| | Thermostats - Pneumatic | Entire Building | 5 | EA | 4 | 2-5 years | Not calibrated, do not work, serve univents, manually operated |
| Unit Ventilation | | | | | | | |
| | Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors | Entire Building | 2 | EA | 5 | 6-10 years | Serve cafeteria |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---|-----------------|----------|-----|------|-----------------------|------------------|
| | Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors | Entire Building | 2 | EA | 5 | 6-10 years | Serve cafeteria |
| | Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only | Entire Building | 15 | EA | 5 | 6-10 years | Serve classrooms |

Ventilation

| | | | | | | | |
|--|--|-----------------|---|----|---|------------|---|
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 5 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 2 | EA | 5 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 2 | EA | 5 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 5 | 6-10 years | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 6 | 10+ years | Previously not assessed, with fire extinguishing system |

Category : Plumbing
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-------------------------------------|-------------|----------|-----|------|-----------------------|-------------------|
| | Gas Heater - 300001 - 600000 BTU/HR | Boiler Room | 1 | EA | 5 | 6-10 years | 2013 installation |

Piping

| | | | | | | | |
|--|---|-----------------|--------|----|---|-----------|-------------------|
| | Domestic Piping-Hot Water Return Lines | Entire Building | 44,825 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 44,825 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 44,825 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 44,825 | SF | 6 | 10+ years | 1965 installation |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 44,825 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 44,825 | SF | 6 | 10+ years | |
| | Sanitary Piping | Entire Building | 44,825 | SF | 6 | 10+ years | |
| | Storm Piping | Entire Building | 44,825 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 44,825 | SF | 6 | 10+ years | |

Pumps

| | | | | | | | |
|--|---------------------------------------|-------------|---|----|---|------------|------------------------------------|
| | Pumps - Domestic Booster Pump-Simplex | Boiler Room | 1 | EA | 2 | 1-2 years | Not needed, to be removed |
| | Pumps - Sump-Duplex | Boiler Room | 1 | EA | 5 | 10+ years | |
| | Pumps - Sump-Simplex | Boiler Room | 1 | EA | 5 | 6-10 years | In crawlspace, difficult to access |

Category : Plumbing
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-------------|----------|----------|-----|------|-----------------------|----------|
|-------|-------------|----------|----------|-----|------|-----------------------|----------|

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-------------|----------|----------|-----|------|-----------------------|----------|
|-------|-------------|----------|----------|-----|------|-----------------------|----------|

Administrative Suites/Offices

| | | | | | |
|-----------------------------|---------------------------------|-----|----|---|------------|
| AC Unit | 104 A | 1 | EA | 7 | 6-10 years |
| Ceiling - Plaster/Drywall | 104 A | 323 | SF | 7 | 10+ years |
| Doors - Wood Doors inclu hw | 104 A | 1 | EA | 7 | 10+ years |
| Floor - Tile | 104 A | 320 | SF | 7 | 10+ years |
| Floor - Tile | 104 A | 3 | SF | 5 | 1-2 years |
| Lighting - Pendent/Surface | 104 A | 6 | EA | 7 | 6-10 years |
| Power Distribution | 104 A | 6 | EA | 7 | 10+ years |
| Storage/ Closet | 104 A | 65 | SF | 7 | 10+ years |
| Walls - Concrete Block | 104 A | 340 | SF | 7 | 10+ years |
| Walls - Plaster/Drywall | 104 A | 240 | SF | 7 | 10+ years |
| AC Unit | 1st Floor- Main Offices | 1 | EA | 7 | 6-10 years |
| Ceiling - Plaster/Drywall | 1st Floor- Main Offices | 193 | SF | 7 | 10+ years |
| Floor - Carpet | 1st Floor- Main Offices | 193 | SF | 6 | 6-10 years |
| Lighting - Pendent/Surface | 1st Floor- Main Offices | 4 | EA | 6 | 6-10 years |
| Power Distribution | 1st Floor- Main Offices | 8 | EA | 6 | 6-10 years |
| Storage/ Closet | 1st Floor- Main Offices | 100 | SF | 7 | 10+ years |
| Walls - Concrete Block | 1st Floor- Main Offices | 300 | SF | 7 | 10+ years |
| AC Unit | 1st Floor-113 | 1 | EA | 7 | 6-10 years |
| Ceiling - Plaster/Drywall | 1st Floor-113 | 355 | SF | 7 | 10+ years |
| Doors - Wood Doors inclu hw | 1st Floor-113 | 1 | EA | 7 | 10+ years |
| Floor - Tile | 1st Floor-113 | 355 | SF | 6 | 10+ years |
| Lighting - Pendent/Surface | 1st Floor-113 | 8 | EA | 6 | 6-10 years |
| Power Distribution | 1st Floor-113 | 6 | EA | 6 | 6-10 years |
| Storage/ Closet | 1st Floor-113 | 12 | SF | 7 | 10+ years |
| Walls - Concrete Block | 1st Floor-113 | 700 | SF | 7 | 10+ years |
| Ceiling - Plaster/Drywall | 1st Floor-Copy Room in 112 | 78 | SF | 7 | 6-10 years |
| Doors - Wood Doors inclu hw | 1st Floor-Copy Room in 112 | 1 | EA | 7 | 10+ years |
| Floor - Tile | 1st Floor-Copy Room in 112 | 78 | SF | 6 | 6-10 years |
| Lighting - Lay-in | 1st Floor-Copy Room in 112 | 1 | EA | 6 | 6-10 years |
| Power Distribution | 1st Floor-Copy Room in 112 | 4 | EA | 6 | 6-10 years |
| Walls - Concrete Block | 1st Floor-Copy Room in 112 | 250 | SF | 7 | 10+ years |
| AC Unit | 1st Floor-Ex. Director's Office | 1 | EA | 7 | 6-10 years |
| Ceiling - Plaster/Drywall | 1st Floor-Ex. Director's Office | 215 | SF | 7 | 10+ years |
| Doors - Wood Doors inclu hw | 1st Floor-Ex. Director's Office | 1 | EA | 7 | 10+ years |
| Floor - Tile | 1st Floor-Ex. Director's Office | 215 | SF | 6 | 10+ years |
| Lighting - Pendent/Surface | 1st Floor-Ex. Director's Office | 4 | EA | 6 | 6-10 years |
| Power Distribution | 1st Floor-Ex. Director's Office | 6 | EA | 6 | 6-10 years |
| Storage/ Closet | 1st Floor-Ex. Director's Office | 12 | SF | 7 | 10+ years |
| Walls - Concrete Block | 1st Floor-Ex. Director's Office | 425 | SF | 7 | 10+ years |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|------------------------------|----------|-----|------|-----------------------|----------|
| | Ceiling - Plaster/Drywall | 1st Floor-Kitchen Office | 105 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor-Kitchen Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor-Kitchen Office | 105 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor-Kitchen Office | 2 | EA | 6 | 6-10 years | |
| | Power Distribution | 1st Floor-Kitchen Office | 4 | EA | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor-Kitchen Office | 24 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor-Kitchen Office | 300 | SF | 7 | 10+ years | |
| | AC Unit | 1st Floor-Principal's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 1st Floor-Principal's Office | 165 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor-Principal's Office | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 1st Floor-Principal's Office | 165 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor-Principal's Office | 4 | EA | 6 | 6-10 years | |
| | Power Distribution | 1st Floor-Principal's Office | 6 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor-Principal's Office | 215 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor-Public Reception | 125 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor-Public Reception | 12 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor-Public Reception | 1 | EA | 7 | 6-10 years | |
| | Floor - Tile | 1st Floor-Public Reception | 125 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor-Public Reception | 2 | EA | 6 | 6-10 years | |
| | Power Distribution | 1st Floor-Public Reception | 6 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor-Public Reception | 280 | SF | 7 | 10+ years | |
| | AC Unit | 2nd Floor-Director's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor-Director's Office | 400 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor-Director's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor-Director's Office | 400 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor-Director's Office | 8 | EA | 6 | 6-10 years | |
| | Power Distribution | 2nd Floor-Director's Office | 12 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor-Director's Office | 795 | SF | 6 | 10+ years | |
| | AC Unit | 2nd Floor-Team Leader Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor-Team Leader Office | 270 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor-Team Leader Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor-Team Leader Office | 270 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor-Team Leader Office | 4 | EA | 6 | 6-10 years | |
| | Power Distribution | 2nd Floor-Team Leader Office | 8 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor-Team Leader Office | 650 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor-Team Leader Office | 78 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor-Team Leader Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor-Team Leader Office | 78 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor-Team Leader Office | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor-Team Leader Office | 286 | SF | 7 | 10+ years | |

Gymnasia

| | | | | | | | |
|--|-----------------------------|-----------|-------|----|---|-----------|--|
| | Ceiling - Plaster/Drywall | 1st Floor | 3,943 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------------------------|--------------------------------|--|----------|-----|------|-----------------------|----------|
| | Floor - Sport Flooring | 1st Floor | 3,943 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 6 | 6-10 years | |
| | Scoreboards | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage | 1st Floor | 513 | SF | 7 | 6-10 years | |
| | Stage Curtain | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Stage Lift | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Stage Lighting System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage-Stairs - Wood | 1st Floor | 14 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 2,330 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,300 | SF | 7 | 10+ years | |
| Kitchen | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 590 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 590 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 6 | 6-10 years | |
| | Serving Line | 1st Floor | 30 | LF | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 265 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 915 | SF | 7 | 10+ years | |
| Locker/Shower Room | | | | | | | |
| | Benches, ped mounted | Old locker room in gym used as storage | 20 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Old locker room in gym used as storage | 96 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Old locker room in gym used as storage | 2 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | Old locker room in gym used as storage | 96 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Old locker room in gym used as storage | 2 | EA | 6 | 6-10 years | |
| | Student Lockers - One Tier | Old locker room in gym used as storage | 20 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Old locker room in gym used as storage | 240 | SF | 7 | 10+ years | |
| Lunch & Multipurpose Room | | | | | | | |
| | Ceiling - Splined | 1st Floor | 1,948 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,948 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 36 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 925 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 725 | SF | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------------------------|---------------------------------|-----------------------------------|----------|-----|------|-----------------------|----------|
| <u>MDF_IDE</u> | | | | | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Finishes | 1st Floor | 80 | SF | 7 | 6-10 years | |
| | Other Cooling Unit | 1st Floor | 1 | EA | 7 | 6-10 years | |
| <u>Mechanical/ Service Rooms</u> | | | | | | | |
| | Boiler Room | 1st Floor | 2,325 | SF | 7 | 10+ years | |
| | Crawl Space - Unfinished | 1st Floor | 3,850 | SF | 7 | 10+ years | |
| | Janitor's Closet | 1st Floor | 66 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 122 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 76 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 35 | SF | 7 | 10+ years | |
| | Vaults | 1st Floor | 55 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 95 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 295 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 165 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 85 | SF | 7 | 10+ years | |
| <u>Restroom</u> | | | | | | | |
| | Accessories | 1st Floor-Ex. Director's Restroom | 38 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor-Ex. Director's Restroom | 38 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor-Ex. Director's Restroom | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor-Ex. Director's Restroom | 38 | SF | 7 | 6-10 years | |
| | Lavatory | 1st Floor-Ex. Director's Restroom | 1 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor-Ex. Director's Restroom | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor-Ex. Director's Restroom | 200 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor-Ex. Director's Restroom | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor-Kitchen Restroom | 35 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor-Kitchen Restroom | 35 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor-Kitchen Restroom | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor-Kitchen Restroom | 35 | SF | 7 | 10+ years | |
| | Lavatory | 1st Floor-Kitchen Restroom | 1 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor-Kitchen Restroom | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor-Kitchen Restroom | 188 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor-Kitchen Restroom | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor-Main Office Restroom | 44 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor-Main Office Restroom | 44 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor-Main Office Restroom | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor-Main Office Restroom | 44 | SF | 7 | 10+ years | |
| | Lavatory | 1st Floor-Main Office Restroom | 1 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor-Main Office Restroom | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor-Main Office Restroom | 213 | SF | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|---------------------------------|----------|-----|------|-----------------------|----------|
| | Water Closet | 1st Floor-Main Office Restroom | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor-Men's Room | 250 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor-Men's Room | 250 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor-Men's Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor-Men's Room | 250 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor-Men's Room | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor-Men's Room | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor-Men's Room | 2 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor-Men's Room | 3 | EA | 7 | 10+ years | |
| | Urinals | 1st Floor-Men's Room | 3 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor-Men's Room | 537 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor-Men's Room | 3 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor-Men's Room Staff | 50 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor-Men's Room Staff | 50 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor-Men's Room Staff | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor-Men's Room Staff | 50 | SF | 7 | 6-10 years | |
| | Lavatory | 1st Floor-Men's Room Staff | 1 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor-Men's Room Staff | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor-Men's Room Staff | 230 | SF | 7 | 10+ years | |
| | Walls - Tile | 1st Floor-Men's Room Staff | 56 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor-Men's Room Staff | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor-Women's Room | 250 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor-Women's Room | 250 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor-Women's Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor-Women's Room | 250 | SF | 6 | 6-10 years | |
| | Floor Drain | 1st Floor-Women's Room | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor-Women's Room | 3 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor-Women's Room | 2 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor-Women's Room | 6 | EA | 7 | 6-10 years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor-Women's Room | 537 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor-Women's Room | 6 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor-Men's Restroom | 250 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor-Men's Restroom | 250 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor-Men's Restroom | 4 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor-Men's Restroom | 250 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor-Men's Restroom | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor-Men's Restroom | 3 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor-Men's Restroom | 1 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor-Men's Restroom | 2 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor-Men's Restroom | 3 | EA | 7 | 10+ years | |
| | Urinals | 2nd Floor-Men's Restroom | 3 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor-Men's Restroom | 555 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor-Men's Restroom | 3 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor-Men's Staff Restroom, | 50 | SF | 7 | 6-10 years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|--|----------|-----|------|-----------------------|-------------------|
| | Ceiling - Plaster/Drywall | near Women's Restroom 2nd Floor-Men's Staff Restroom, | 50 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | near Women's Restroom 2nd Floor-Men's Staff Restroom, | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | near Women's Restroom 2nd Floor-Men's Staff Restroom, | 50 | SF | 7 | 10+ years | |
| | Lavatory | near Women's Restroom 2nd Floor-Men's Staff Restroom, | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | near Women's Restroom 2nd Floor-Men's Staff Restroom, | 1 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | near Women's Restroom 2nd Floor-Men's Staff Restroom, | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | near Women's Restroom 2nd Floor-Men's Staff Restroom, | 230 | SF | 7 | 10+ years | |
| | Water Closet | near Women's Restroom 2nd Floor-Men's Staff Restroom, | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor-Women's Restroom | 270 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor-Women's Restroom | 265 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor-Women's Restroom | 5 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor-Women's Restroom | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor-Women's Restroom | 270 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor-Women's Restroom | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor-Women's Restroom | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor-Women's Restroom | 2 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor-Women's Restroom | 6 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor-Women's Restroom | 645 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor-Women's Restroom | 6 | EA | 7 | 10+ years | |
| | Accessories | E Boiler Room Restroom 2 | 100 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | E Boiler Room Restroom 2 | 100 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | E Boiler Room Restroom 2 | 2 | EA | 6 | 1-2 years | Missing door knob |
| | Floor - Concrete | E Boiler Room Restroom 2 | 100 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | E Boiler Room Restroom 2 | 2 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | E Boiler Room Restroom 2 | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | E Boiler Room Restroom 2 | 682 | SF | 7 | 10+ years | |
| | Water Closet | E Boiler Room Restroom 2 | 1 | EA | 7 | 10+ years | |
| | Accessories | W Boiler Room Restroom 1 | 100 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | W Boiler Room Restroom 1 | 92 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | W Boiler Room Restroom 1 | 8 | SF | 6 | 1-2 years | Damaged plaster |
| | Doors - Wood Doors inclu hw | W Boiler Room Restroom 1 | 2 | EA | 6 | 10+ years | |
| | Floor - Concrete | W Boiler Room Restroom 1 | 100 | SF | 7 | 10+ years | |
| | Lavatory | W Boiler Room Restroom 1 | 1 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | W Boiler Room Restroom 1 | 2 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | W Boiler Room Restroom 1 | 1 | EA | 6 | 6-10 years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|------------------------|--------------------------|----------|-----|------|-----------------------|----------|
| | Walls - Concrete Block | W Boiler Room Restroom 1 | 682 | SF | 7 | 10+ years | |
| | Water Closet | W Boiler Room Restroom 1 | 1 | EA | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--|-----------------------------|-----------|----------|-----|------|-----------------------|----------|
| Classroom #101 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 30 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 725 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Tile | 1st Floor | 725 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 1,190 | SF | 7 | 10+ years | |
| Classroom #102 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 30 | LF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 725 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Tile | 1st Floor | 725 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Tile | 1st Floor | 725 | SF | 7 | 10+ years | |
| Classroom #103 (Multi Purpose Room) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 995 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 995 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 65 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 1,293 | SF | 7 | 10+ years | |
| Classroom #104 (Computer Lab) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 30 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 672 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Floor - Tile | 1st Floor | 672 | SF | 6 | 6-10 years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|--|
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 520 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 240 | SF | 7 | 10+ years | |
| | Wireless System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Classroom #105 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 30 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 995 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 995 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 65 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,292 | SF | 7 | 10+ years | |
| Classroom #200 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 725 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 725 | SF | 6 | 10+ years | |
| Classroom #201 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 725 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 975 | SF | 6 | 10+ years | |
| Classroom #202 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 35 | LF | 6 | 1-2 years | End panels missing at cabinets. Equipment exposed |
| | Ceiling - Plaster/Drywall | 2nd Floor | 745 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|---|
| | Floor - Tile | 2nd Floor | 745 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 995 | SF | 6 | 10+ years | |
| <hr/> Classroom #203 (Regular Classroom) <hr/> | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 975 | SF | 6 | 10+ years | |
| <hr/> Classroom #204 (Regular Classroom) <hr/> | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 15 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 975 | SF | 6 | 10+ years | |
| <hr/> Classroom #205 (Computer Lab) <hr/> | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 40 | LF | 7 | 10+ years | |
| | Casework | 2nd Floor | 8 | LF | 6 | 1-2 years | End panels missing ar cabinets, equipment exposed |
| | Ceiling - Plaster/Drywall | 2nd Floor | 740 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 740 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 655 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 340 | SF | 6 | 10+ years | |
| <hr/> Classroom #206 (Regular Classroom) <hr/> | | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 360 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 360 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 8 | EA | 6 | 6-10 years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|------------------------|-----------|----------|-----|------|-----------------------|----------|
| | Marker Board | 2nd Floor | 5 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 685 | SF | 6 | 10+ years | |

Classroom #207 (Regular Classroom)

| | | | | | | | |
|--|-----------------------------|-----------|-----|----|---|------------|--|
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 15 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 975 | SF | 6 | 10+ years | |

Classroom #208 (Music Room)

| | | | | | | | |
|--|--------------------------------|-----------|-----|----|---|------------|--|
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 15 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 975 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 23 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 2 | SF | 6 | 10+ years | |

Classroom #209 (Regular Classroom)

| | | | | | | | |
|--|-----------------------------|-----------|-----|----|---|------------|---------------------------------------|
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 1-2 years | Missing end panels, equipment exposed |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 15 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 975 | SF | 6 | 10+ years | |

Category : Interior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------|-----------------------------|-----------|----------|-----|------|-----------------------|----------|
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 448 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 2,415 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 3 | EA | 6 | 6-10 years | |

Category : Interior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|--------------------------------------|-----------|----------|-----|------|-----------------------|--------------|
| | Doors - Wood Doors include hw | 1st Floor | 6 | EA | 6 | 6-10 years | |
| | Drinking Fountains - Double Fountain | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Floor - Concrete | 1st Floor | 330 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 135 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 118 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 2,405 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 10 | SF | 4 | 1-2 years | Broken tiles |
| | Lighting - Pendent/Surface | 1st Floor | 30 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 5,815 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,765 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 2,535 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 25 | SF | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 2,560 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 5 | SF | 4 | 0-1 year | |
| | Lighting - Pendent/Surface | 2nd Floor | 18 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,315 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 2,424 | SF | 6 | 10+ years | |

Safety

| | | | | | | | |
|--|------------------------|-----------------|---|----|---|------------|--|
| | Camera Viewing Station | Entire Building | 1 | EA | 7 | 6-10 years | |
| | Metal Dedector | Entire Building | 1 | EA | 7 | 10+ years | |
| | Security Cameras | Entire Building | 7 | EA | 7 | 6-10 years | |

Stairs

| | | | | | | | |
|--|--------------------------------|-----------|-----|----|---|------------|---------------------------|
| | Ceiling - Lay-in | N Stairs | 202 | SF | 6 | 6-10 years | |
| | Floor - Terrazzo | N Stairs | 120 | SF | 6 | 10+ years | |
| | Handrails | N Stairs | 50 | LF | 7 | 10+ years | |
| | Handrails | N Stairs | 5 | LF | 4 | 2-5 years | Bent guard rail |
| | Lighting - Lay-in | N Stairs | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | N Stairs | 1 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | N Stairs | 25 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | N Stairs | 385 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | N Stairs | 770 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | SE Stairs | 202 | SF | 6 | 10+ years | |
| | Ceiling - Splined | SE Stairs | 30 | SF | 5 | 0-1 year | Damaged and missing tiles |
| | Floor - Terrazzo | SE Stairs | 120 | SF | 6 | 10+ years | |
| | Handrails | SE Stairs | 55 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | SE Stairs | 2 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | SE Stairs | 25 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | SE Stairs | 385 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | SE Stairs | 770 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | SW Stairs | 202 | SF | 6 | 10+ years | |

Category : Interior

Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|--------------------------------|-----------|----------|-----|------|-----------------------|----------|
| | Floor - Terrazzo | SW Stairs | 120 | SF | 6 | 10+ years | |
| | Handrails | SW Stairs | 55 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | SW Stairs | 2 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | SW Stairs | 25 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | SW Stairs | 385 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | SW Stairs | 770 | SF | 6 | 10+ years | |

Category : Site
Building : Site

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------|---------------------------------------|-----------------------------------|----------|-----|------|-----------------------|---|
| <u>Civil/Drainage</u> | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 4 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 2 | EA | 6 | 10+ years | |
| <u>Fencing</u> | | | | | | | |
| | Fencing - Chain Link | Entire Site | 1,033 | LF | 6 | 10+ years | |
| | Fencing - Old Standard Ornamental | Entire Site | 125 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | South Parking Lot - Across Street | 200 | LF | 6 | 10+ years | |
| | Fencing - Wood Fencing w/ Steel Frame | South Parking Lot - Across Street | 200 | LF | 5 | 6-10 years | |
| <u>Landscape</u> | | | | | | | |
| | Benches | Entire Site | 1 | EA | 6 | 10+ years | |
| | Landscape - Grass | Entire Site | 1,856 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Asphalt | Entire Site | 2,300 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Pavers | Entire Site | 410 | SF | 6 | 6-10 years | Weed/vegetation in joints |
| | Parkway trees | Entire Site | 8 | EA | 6 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 400 | SF | 6 | 10+ years | |
| | Trash Receptacles | Entire Site | 2 | EA | 6 | 2-5 years | |
| <u>Parking Lot</u> | | | | | | | |
| | Surface - Asphalt | East and South Site | 22,000 | SF | 5 | 10+ years | Broken/Cracked/Webbing in areas Missing Panels/Boards/Cross bracing member broken/missing - deteriorated |
| | Trash Enclosure - Wood | East and South Site | 632 | SF | 4 | 1-2 years | |
| | Concrete Curbs | South Parking Lot - Across Street | 310 | LF | 6 | 10+ years | Debris/broken limbs - plantings dead or non-existent |
| | Interior Plantings | South Parking Lot - Across Street | 310 | LF | 4 | 1-2 years | |
| | Lighting - Pole Mounted | South Parking Lot - Across Street | 2 | EA | 6 | 6-10 years | Bulb replacement required in both fixtures |
| | Surface - Asphalt | South Parking Lot - Across Street | 720 | SF | 6 | 6-10 years | |
| | Vehicular Screening | South Parking Lot - Across Street | 185 | LF | 6 | 10+ years | |
| <u>Playground</u> | | | | | | | |
| | Equipment - School Age 5-12 | Southeast site | 1 | EA | 5 | 2-5 years | |
| | Surface - Poured Surface | Southeast site | 2,750 | SF | 4 | 1-2 years | |
| <u>Sidewalks</u> | | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 115 | LF | 6 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 6,000 | SF | 6 | 10+ years | |
| <u>Signage</u> | | | | | | | |

Category : Site

Building : Site

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---|-------------|----------|-----|------|-----------------------|----------|
| | Flag Pole - Flag Pole | Entire Site | 1 | EA | 6 | 10+ years | |
| | Marquee - Free Standing Back Lighted | Entire Site | 1 | EA | 6 | 10+ years | |
| | Monument - Building Mounted Cut Letter Sign | Entire Site | 1 | EA | 6 | 10+ years | |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Glazed Window Area | Operable Window Area | Window Stop | Smart-Board |
|------------------------|-------------------|---------------|-------------|------------------------|-----------|--------------------|----------------------|-------------|-------------|
| Building : Main | | | | | | | | | |
| Computer Lab | Kindergarten | 1st Floor | 104 | 115 | 672 | 216 | 72 | N | N |
| Computer Lab | Regular Classroom | 2nd Floor | 205 | 215 | 740 | 162 | 54 | N | N |
| Multi Purpose Room | Kindergarten | 1st Floor | 103 | 114 | 995 | 216 | 72 | N | Y |
| Music Room | Regular Classroom | 2nd Floor | 208 | 218 | 725 | 162 | 54 | N | N |
| Regular Classroom | Kindergarten | 1st Floor | 105 | 116 | 995 | 216 | 72 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 101 | 110 | 725 | 162 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 111 | 725 | 162 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 200 | 210 | 725 | 162 | 54 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 211 | 725 | 162 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 212 | 745 | 162 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 213 | 725 | 162 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 214 | 725 | 162 | 54 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 215 | 360 | 84 | 28 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 216 | 725 | 162 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 217 | 725 | 162 | 54 | N | N |