

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

| Campus Summary |                  |                  |                       |
|----------------|------------------|------------------|-----------------------|
| BuildingName   | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main           | 1914             | 3                | 142,911               |
| Branch-CPC     | 1971             | 1                | 8,525                 |
| Campus Total   |                  |                  | 151,436               |

| Catego   | ry : Exterior                         |                                 | В        | uilding | : Main |                          |                             |
|----------|---------------------------------------|---------------------------------|----------|---------|--------|--------------------------|-----------------------------|
| Group    | Item - Type                           | Location                        | Quantity | UOM     | Rank   | Recommend<br>Replacement | Comments                    |
| Cell Equ | ipment                                |                                 |          |         |        |                          |                             |
| -        | Cell Equipment - Antenna              | Roof 1                          | 2        | EA      | 7      | 10+ years                |                             |
|          | Cell Equipment - Generator            | Roof 1                          | 1        | EA      | 7      | 10+ years                |                             |
|          | Cell Equipment - Antenna              | Roof 5                          | 2        | EA      | 7      | 10+ years                |                             |
| Entrance | 3                                     |                                 |          |         |        |                          |                             |
|          | Entrance Control - Audio and Video    | 2 - West                        | 1        | EA      | 7      | 10+ years                |                             |
|          | Exterior Doors - Exterior FRP Door    | 2 - West                        | 4        | EA      | 6      | 10+ years                |                             |
|          | Exterior Doors - Transom Lite         | 2 - West                        | 3        | EA      | 6      | 10+ years                |                             |
|          | Exterior Stairs - Concrete            | 2 - West                        | 100      | LF      | 7      | 10+ years                |                             |
|          | Ramp Handrail - Steel_Ramp Handrail   | 2 - West                        | 180      | LF      | 6      | 6-10 years               |                             |
|          | Ramps - Concrete                      | 2 - West                        | 70       | LF      | 6      | 10+ years                |                             |
|          | Stair Handrail - Steel_Stair Handrail | 2 - West                        | 60       | LF      | 6      | 6-10 years               |                             |
|          | Exterior Doors - Exterior Steel Door  | 2nd Floor Fire Escape door - SW | 1        | EA      | 6      | 10+ years                |                             |
|          | Exterior Doors - Side lite            | 2nd Floor Fire Escape door - SW | 2        | EA      | 6      | 10+ years                |                             |
|          | Exterior Doors - Transom Lite         | 2nd Floor Fire Escape door - SW | 1        | EA      | 6      | 10+ years                |                             |
|          | Entrance Control - Audio and Video    | Entrance 5 - SW                 | 1        | EA      | 7      | 10+ years                |                             |
|          | Exterior Doors - Exterior FRP Door    | Entrance 5 - SW                 | 4        | EA      | 6      | 10+ years                |                             |
|          | Exterior Stairs - Concrete            | Entrance 5 - SW                 | 35       | LF      | 7      | 10+ years                |                             |
|          | Ramp Handrail - Steel_Ramp Handrail   | Entrance 5 - SW                 | 90       | LF      | 6      | 6-10 years               |                             |
|          | Ramps - Concrete                      | Entrance 5 - SW                 | 40       | LF      | 7      | 10+ years                |                             |
|          | Stair Handrail - Steel_Stair Handrail | Entrance 5 - SW                 | 15       | LF      | 6      | 6-10 years               |                             |
|          | Exterior Doors - Exterior Steel Door  | Entrance 6 - Southeast          | 1        | EA      | 6      | 6-10 years               |                             |
|          | Exterior Stairs - Concrete            | Entrance 6 - Southeast          | 5        | LF      | 6      | 10+ years                | Missed in prior assessment. |



| Catego   | ry : Exterior                         |                                | В        | uilding | : Main | _           |                             |
|----------|---------------------------------------|--------------------------------|----------|---------|--------|-------------|-----------------------------|
| J        |                                       |                                |          | Ŭ       |        | Recommend   |                             |
| Group    | Item - Type                           | Location                       | Quantity | UOM     | Rank   | Replacement | Comments                    |
|          | Ramps - Concrete                      | Entrance 6 - Southeast         | 3        | LF      | 5      | 0-1 year    | Cracking                    |
|          | Entrance Control - Audio and Video    | Entrance 8 - Southeast         | 1        | EA      | 6      | 6-10 years  | Missed in prior             |
|          | Exterior Doors - Exterior Steel Door  | Entrance 8 - Southeast         | 2        | EA      | 6      | 6-10 years  |                             |
|          | Exterior Doors - Transom Lite         | Entrance 8 - Southeast         | 2        | EA      | 6      | 10+ years   | Missed in prior assessment. |
|          | Exterior Doors - Exterior FRP Door    | Entrance 9 - West with #3 sign | 2        | EA      | 6      | 10+ years   | Painting                    |
|          | Exterior Doors - Exterior FRP Door    | Exit 10 - East                 | 4        | EA      | 6      | 10+ years   | Painting                    |
|          | Exterior Doors - Transom Lite         | Exit 10 - East                 | 3        | EΑ      | 6      | 10+ years   | -                           |
|          | Exterior Stairs - Concrete            | Exit 10 - East                 | 90       | LF      | 7      | 10+ years   |                             |
|          | Stair Handrail - Steel_Stair Handrail | Exit 10 - East                 | 23       | LF      | 3      | 0-1 year    | Rusted and rail missing     |
|          | Exterior Doors - Exterior FRP Door    | Exit 3 - West                  | 4        | EA      | 6      | 10+ years   | _                           |
|          | Exterior Doors - Transom Lite         | Exit 3 - West                  | 2        | EΑ      | 6      | 10+ years   |                             |
|          | Exterior Doors - Exterior FRP Door    | Exit 4 - South                 | 4        | EΑ      | 6      | 6-10 years  | Painting                    |
|          | Exterior Doors - Exterior Steel Door  | Exit 7 - Southeast             | 1        | EA      | 7      | 10+ years   |                             |
|          | Ramp Handrail - Steel_Ramp Handrail   | Exit 7 - Southeast             | 40       | LF      | 5      | 0-1 year    | Leaning / bent              |
|          | Ramps - Concrete                      | Exit 7 - Southeast             | 20       | LF      | 5      | 2-5 years   | 3                           |
|          | Entrance Control - Audio and Video    | Main Entrance 1 - North        | 2        | EA      | 6      | 10+ years   |                             |
|          | Exterior Doors - Exterior FRP Door    | Main Entrance 1 - North        | 8        | EA      | 6      | 10+ years   |                             |
|          | Exterior Doors - Transom Lite         | Main Entrance 1 - North        | 4        | EA      | 6      | 6-10 years  |                             |
|          | Exterior Stairs - Concrete            | Main Entrance 1 - North        | 135      | LF      | 7      | 10+ years   |                             |
|          | Ramp Handrail - Steel_Ramp Handrail   | Main Entrance 1 - North        | 170      | LF      | 7      | 10+ years   |                             |
|          | Ramps - Concrete                      | Main Entrance 1 - North        | 70       | LF      | 7      | 10+ years   |                             |
|          | Stair Handrail - Steel_Stair Handrail | Main Entrance 1 - North        | 100      | LF      | 6      | 6-10 years  |                             |
|          |                                       |                                |          |         |        | •           |                             |
| Fire Esc | ape                                   |                                |          |         |        |             |                             |
|          | Fire Escape                           | SW corner                      | 80       | LF      | 6      | 6-10 years  |                             |
| Foundat  | ion                                   |                                |          |         |        |             |                             |
|          | Foundation - Concrete                 | Entire Building                | 1,275    | LF      | 7      | 10+ years   |                             |
|          | Superstructure - Concrete             | Entire Building                | 142,911  | SF      | 7      | 10+ years   |                             |
|          |                                       | 3                              | ,-       |         |        | , , , , , , |                             |
| Lighting |                                       |                                |          |         |        |             |                             |
|          | Exterior Lighting - Wall Mounted      | Entire Building                | 15       | EA      | 6      | 6-10 years  |                             |
| Roof Sys | stem                                  |                                |          |         |        |             |                             |
| ,        | Access Ladder - Metal                 | Roof 1                         | 1        | EA      | 7      | 10+ years   | Missed prior                |
|          | Coping - Metal                        | Roof 1                         | 228      | LF      | 7      | 10+ years   | ·                           |
|          | Parapet - 16" - 30" Height            | Roof 1                         | 134      | LF      | 7      | 10+ years   |                             |
|          | Parapet - Parapet < 16" Height        | Roof 1                         | 78       | LF      | 7      | 10+ years   |                             |
|          | Parapet - Parapet > 30"               | Roof 1                         | 16       | LF      | 7      | 10+ years   |                             |
|          | Roof - Modified Bitumen               | Roof 1                         | 5,525    | SF      | 7      | 10+ years   |                             |
|          | Roof Structure - Concrete             | Roof 1                         | 5,525    | SF      | 7      | 10+ years   |                             |
|          | Coping - Metal                        | Roof 10                        | 150      | LF      | 7      | 10+ years   |                             |
|          | Downspouts - Exterior Downspouts      | Roof 10                        | 25       | LF      | 6      | 6-10 years  |                             |
|          |                                       |                                |          |         |        | •           |                             |



| Catego | ry : Exterior                             |   | В        | uilding | : Main |   | <u> </u> |  |  |
|--------|---|---|----------|---------|--------|---|----------|--|--|
|        |   |   |          |         |        | Recommend                               |          |  |  |
| Group  | Item - Type                               | Location                                    | Quantity | UOM     | Rank   | Replacement                             | Comments |  |  |
|        | Roof - Modified Bitumen                   | Roof 10                                     | 1,880    | SF      | 7      | 6-10 years                              |          |  |  |
|        | Roof Structure - Concrete                 | Roof 10                                     | 1,880    | SF      | 7      | 10+ years                               |          |  |  |
|        | Chimney - Brick Chimney- Concrete/ Mortar | Roof 11                                     | 58       | LF      | 7      | 10+ years                               |          |  |  |
|        | Liner                                     |   |          |         |        |   |          |  |  |
|        | Coping - Metal                            | Roof 11                                     | 20       | LF      | 7      | 10+ years                               |          |  |  |
|        | Downspouts - Interior Downspouts          | Roof 11                                     | 15       | LF      | 5      | 10+ years                               |          |  |  |
|        | Parapet - Parapet < 16" Height            | Roof 11                                     | 20       | LF      | 7      | 10+ years                               |          |  |  |
|        | Roof - Modified Bitumen                   | Roof 11                                     | 700      | SF      | 6      | 6-10 years                              |          |  |  |
|        | Roof Structure - Concrete                 | Roof 11                                     | 700      | SF      | 7      | 10+ years                               |          |  |  |
|        | Coping - Metal                            | Roof 12 - Above entrance 2 - west vestibule | 20       | LF      | 7      | 10+ years                               |          |  |  |
|        | Downspouts - Exterior Downspouts          | Roof 12 - Above entrance 2 - west           | 15       | LF      | 6      | 10+ years                               |          |  |  |
|        | ·   | vestibule                                   |          |         |        | •                                       |          |  |  |
|        | Parapet - Parapet < 16" Height            | Roof 12 - Above entrance 2 - west vestibule | 20       | LF      | 7      | 10+ years                               |          |  |  |
|        | Roof - Modified Bitumen                   | Roof 12 - Above entrance 2 - west           | 70       | SF      | 7      | 6-10 years                              |          |  |  |
|        |   | vestibule                                   |          |         |        | ,                                       |          |  |  |
|        | Roof Structure - Concrete                 | Roof 12 - Above entrance 2 - west vestibule | 70       | SF      | 7      | 10+ years                               |          |  |  |
|        | Coping - Stone                            | Roof 13 - Above exit 3 - west               | 35       | LF      | 6      | 10+ years                               |          |  |  |
|        | a spiring                                 | vestibule                                   |          |         | •      | , |          |  |  |
|        | Downspouts - Exterior Downspouts          | Roof 13 - Above exit 3 - west vestibule     | 15       | LF      | 6      | 10+ years                               |          |  |  |
|        | Parapet - 16" - 30" Height                | Roof 13 - Above exit 3 - west               | 35       | LF      | 6      | 10+ years                               |          |  |  |
|        | 3   | vestibule                                   |          |         |        | ,                                       |          |  |  |
|        | Roof - Modified Bitumen                   | Roof 13 - Above exit 3 - west vestibule     | 100      | SF      | 6      | 6-10 years                              |          |  |  |
|        | Roof Structure - Concrete                 | Roof 13 - Above exit 3 - west               | 100      | SF      | 7      | 10+ years                               |          |  |  |
|        |   | vestibule                                   |          |         |        | -                                       |          |  |  |
|        | Coping - Metal                            | Roof 2                                      | 460      | LF      | 7      | 10+ years                               |          |  |  |
|        | Downspouts - Exterior Downspouts          | Roof 2                                      | 40       | LF      | 6      | 6-10 years                              |          |  |  |
|        | Downspouts - Interior Downspouts          | Roof 2                                      | 480      | LF      | 6      | 6-10 years                              |          |  |  |
|        | Parapet - 16" - 30" Height                | Roof 2                                      | 460      | LF      | 6      | 6-10 years                              |          |  |  |
|        | Roof - Modified Bitumen                   | Roof 2                                      | 11,255   | SF      | 6      | 6-10 years                              |          |  |  |
|        | Roof Hatch - Metal                        | Roof 2                                      | 1        | EA      | 7      | 10+ years                               |          |  |  |
|        | Roof Structure - Concrete                 | Roof 2                                      | 11,255   | SF      | 7      | 10+ years                               |          |  |  |
|        | Coping - Stone                            | Roof 3                                      | 15       | LF      | 7      | 10+ years                               |          |  |  |
|        | Parapet - Parapet < 16" Height            | Roof 3                                      | 15       | LF      | 7      | 10+ years                               |          |  |  |
|        | Roof - Modified Bitumen                   | Roof 3                                      | 60       | SF      | 6      | 6-10 years                              |          |  |  |
|        | Roof Structure - Concrete                 | Roof 3                                      | 60       | SF      | 7      | 10+ years                               |          |  |  |
|        | Access Ladder - Metal                     | Roof 4                                      | 1        | EA      | 7      | 10+ years                               |          |  |  |
|        | Coping - Metal                            | Roof 4                                      | 245      | LF      | 7      | 10+ years                               |          |  |  |
|        | Downspouts - Exterior Downspouts          | Roof 4                                      | 200      | LF      | 6      | 6-10 years                              |          |  |  |
|        | Parapet - Parapet > 30"                   | Roof 4                                      | 245      | LF      | 7      | 10+ years                               |          |  |  |
|        | i arapot i arapot > 00                    | 1.00. 1                                     | 2-10     |         | ,      | ioi youis                               |          |  |  |



| Catego | ry : Exterior                          |                 | В        | uilding | : Main |             |          |
|--------|--|-----------------|----------|---------|--------|-------------|----------|
|        |  |                 |          | _       |        | Recommend   |          |
| Group  | Item - Type                            | Location        | Quantity | UOM     | Rank   | Replacement | Comments |
|        | Roof - Modified Bitumen                | Roof 4          | 9,260    | SF      | 7      | 10+ years   |          |
|        | Roof Hatch - Metal                     | Roof 4          | 1        | EΑ      | 7      | 10+ years   |          |
|        | Roof Structure - Concrete              | Roof 4          | 9,260    | SF      | 7      | 10+ years   |          |
|        | Access Ladder - Metal                  | Roof 5          | 3        | EΑ      | 7      | 10+ years   |          |
|        | Coping - Metal                         | Roof 5          | 240      | LF      | 7      | 10+ years   |          |
|        | Coping - Metal                         | Roof 5          | 100      | LF      | 7      | 10+ years   |          |
|        | Downspouts - Exterior Downspouts       | Roof 5          | 145      | LF      | 6      | 6-10 years  |          |
|        | Parapet - 16" - 30" Height             | Roof 5          | 75       | LF      | 7      | 10+ years   |          |
|        | Parapet - Parapet < 16" Height         | Roof 5          | 110      | LF      | 7      | 10+ years   |          |
|        | Parapet - Parapet > 30"                | Roof 5          | 55       | LF      | 7      | 10+ years   |          |
|        | Roof - Modified Bitumen                | Roof 5          | 6,795    | SF      | 7      | 10+ years   |          |
|        | Roof Hatch - Metal                     | Roof 5          | 2        | EA      | 7      | 10+ years   |          |
|        | Roof Structure - Concrete              | Roof 5          | 6,795    | SF      | 7      | 10+ years   |          |
|        | Access Ladder - Metal                  | Roof 6          | 2        | EA      | 7      | 10+ years   |          |
|        | Coping - Metal                         | Roof 6          | 245      | LF      | 7      | 10+ years   |          |
|        | Downspouts - Exterior Downspouts       | Roof 6          | 190      | LF      | 7      | 10+ years   |          |
|        | Parapet - Parapet > 30"                | Roof 6          | 245      | LF      | 7      | 10+ years   |          |
|        | Roof - Modified Bitumen                | Roof 6          | 9,260    | SF      | 7      | 10+ years   |          |
|        | Roof Hatch - Metal                     | Roof 6          | 1        | EA      | 7      | 10+ years   |          |
|        | Roof Structure - Concrete              | Roof 6          | 9,260    | SF      | 7      | 10+ years   |          |
|        | Coping - Metal                         | Roof 7          | 30       | LF      | 7      | 10+ years   |          |
|        | Downspouts - Exterior Downspouts       | Roof 7          | 80       | LF      | 7      | 10+ years   |          |
|        | Parapet - Parapet < 16" Height         | Roof 7          | 30       | LF      | 7      | 10+ years   |          |
|        | Roof - Modified Bitumen                | Roof 7          | 1,700    | SF      | 7      | 10+ years   |          |
|        | Roof Structure - Concrete              | Roof 7          | 1,700    | SF      | 7      | 10+ years   |          |
|        | Access Ladder - Metal                  | Roof 8          | 1        | ĒΑ      | 7      | 10+ years   |          |
|        | Coping - Metal                         | Roof 8          | 120      | LF      | 7      | 10+ years   |          |
|        | Downspouts - Interior Downspouts       | Roof 8          | 250      | LF      | 6      | 10+ years   |          |
|        | Parapet - 16" - 30" Height             | Roof 8          | 120      | LF      | 7      | 10+ years   |          |
|        | Roof - Modified Bitumen                | Roof 8          | 7,610    | SF      | 7      | 10+ years   |          |
|        | Roof Hatch - Metal                     | Roof 8          | 1        | EA      | 7      | 10+ years   |          |
|        | Roof Structure - Concrete              | Roof 8          | 7,610    | SF      | 7      | 10+ years   |          |
|        | Coping - Metal                         | Roof 9          | 140      | LF      | 7      | 10+ years   |          |
|        | Downspouts - Exterior Downspouts       | Roof 9          | 35       | LF      | 6      | 6-10 years  |          |
|        | Roof - Modified Bitumen                | Roof 9          | 225      | SF      | 6      | 6-10 years  |          |
|        | Roof Structure - Concrete              | Roof 9          | 225      | SF      | 7      | 10+ years   |          |
|        |  |                 | 220      | ٥.      | •      | . o . youro |          |
| Walls  |  |                 |          |         |        |             |          |
|        | Cheek-Wall - Concrete                  | Entire Building | 115      | SF      | 7      | 10+ years   |          |
|        | Cornice - Masonry Projecting Limestone | Entire Building | 980      | LF      | 7      | 10+ years   |          |
|        | Exterior Walls - Brick                 | Entire Building | 47,100   | SF      | 6      | 10+ years   |          |
|        | Exterior Walls - Stone-Cast            | Entire Building | 10,700   | SF      | 6      | 10+ years   |          |
|        | Exterior Walls - Stone-Cast            | Entire Building | 1,000    | SF      | 6      | 10+ years   |          |
|        |  | 3               | ,        |         |        | ,           |          |



| Catego    | ry : Exterior  |                                 | В        | uilding  | : Main | 0711 **              | Douglas BOOLE VARD, Chicago, IL 60623      |
|-----------|--|---------------------------------|----------|----------|--------|----------------------|--|
| Juliogo   | .y . =x.c.i.c.   |                                 | _        | ug       |        | Recommend            |  |
| Group     | Item - Type  | Location                        | Quantity | UOM      | Rank   | Replacement          | Comments                                   |
| Windows   | s  |                                 | _        |          |        | •                    |  |
|           | Guard - Guards perforated  | Entire Building                 | 7,345    | SF       | 6      | 6-10 years           |  |
|           | Lintels - Steel  | Entire Building                 | 2,060    | LF       | 7      | 10+ years            |  |
|           | Windows - Louver   | Entire Building                 | 90       | SF       | 6      | 6-10 years           |  |
|           | Windows - Sash Aluminum Double-pane                                  | Entire Building                 | 18,570   | SF       | 7      | 10+ years            |  |
|           | Trindono Gaori / Harriniani Boabio pario                             | Zman g                          | 10,010   | O.       | •      | ioi youlo            |  |
| Catego    | ry : Electrical  |                                 | В        | uilding  | : Main |                      |  |
|           |  |                                 |          |          |        | Recommend            |  |
| Group     | Item - Type  | Location                        | Quantity | UOM      | Rank   | Replacement          | Comments                                   |
| Emerger   | ncy System   |                                 | _        |          |        | •                    |  |
|           | Automatic Transfer Switch  | Boiler Room                     | 1        | EA       | 6      | 6-10 years           |  |
|           | Security System - CCTV   | Entire Building                 | 142,911  | SF       | 6      | 6-10 years           |  |
|           | Security System - Intrusion Detection                                | Entire Building                 | 142,911  | SF       | 5      | 6-10 years           |  |
|           | Emergency A/C Power - Auditoium and                                  | Entire Building                 | 6,441    | SF       | 6      | 6-10 years           |  |
|           | Aisle Lighting   | Z.i.a.o Ballanig                | 0,441    | J1       | J      | o to yours           |  |
|           | Emergency A/C Power - Corridors and                                  | Entire Building                 | 34,169   | SF       | 6      | 6-10 years           |  |
|           | Stairs   | Entire Building                 | 34,103   | Oi       | U      | 0-10 years           |  |
|           | Emergency A/C Power - Lunchrooms                                     | Entire Building                 | 3,665    | SF       | 6      | 6-10 years           |  |
|           | Exit Signs - Auditoium   | Entire Building                 | 6        | EA       | 6      | 6-10 years           |  |
|           | Exit Signs - Corridors and Stairs                                    | Entire Building                 | 37       | EA       | 5      | 2-5 years            | Some require replacing                     |
|           | Exit Signs - Gym   | Entire Building                 | 2        | EA       | 6      | 6-10 years           | Some require replacing                     |
|           | Exit Signs - Gym   | Entire Building                 | 2        | EA       | 6      | 6-10 years           |  |
|           | Automatic Transfer Switch  | Side Room in the Boiler Room    | 2        | EA       | 6      | 6-10 years           |  |
|           | Emergency Generator- Outdoor- Natural                                | South Courtyard                 | 1        | EA       | 6      | 6-10 years           |  |
|           | Gas - 60 - 100 KW  | South Courtyard                 | '        | LA       | U      | 0-10 years           |  |
| Main Se   | rvice  |                                 |          |          |        |                      |  |
| _waiii Se | Main Electrical Service - 2000 A                                     | Boiler Room                     | 1        | EA       | 4      | 0-1 year             | 50+ years old and deteriorating.           |
|           | 120/208/3PH  | Boiler Room                     | 1        | LA       | 7      | 0-1 year             | 30+ years old and deteriorating.           |
|           | Independent Electrical Service for                                   | Boiler Room                     | 1        | EA       | 6      | 6-10 years           |  |
|           | emergency power  | Bollet Koolii                   | Į.       | LA       | O      | 0-10 years           |  |
|           | PA System  | Entire Building                 | 142,911  | SF       | 6      | 6-10 years           |  |
| Power D   | Distribution   |                                 |          |          |        |                      |  |
| TOWELL    | Lighting and Power Panels - 100 A                                    | Entire Building                 | 5        | EA       | 6      | 6-10 years           |  |
|           | Lighting and Power Panels - 100 A  Lighting and Power Panels - 100 A | Entire Building                 | 2        | EA       | 4      | •                    | Outdated                                   |
|           | Lighting and Power Panels - 100 A  Lighting and Power Panels - 100 A | Entire Building Entire Building | 4        | EA       | 4      | 0-1 year<br>0-1 year | Outdated Outdated, missing breaker covers. |
|           |  |                                 | 11       | EA       | 7      | •                    | Outdated, missing breaker covers.          |
|           | Lighting and Power Panels - Above 100 A                              | Entire Building                 | 4        | EA       | 6      | 6-10 years           |  |
|           | Lighting and Power Panels - Above 100 A                              | Entire Building                 |          | EA<br>EA | _      | 6-10 years           | Outdated/missing asyers Padly              |
|           | Lighting and Power Panels - Above 100 A                              | Entire Building                 | 3        | EA       | 4      | 0-1 year             | Outdated/missing covers. Badly corroded.   |
|           | Main Distribution Panels - 400 - 600 amp                             | Entire Building                 | 1        | EA       | 7      | 6-10 years           |  |
|           | Main Distribution Panels - 400 - 600 amp                             | Entire Building                 | 1        | EA       | 7      | 6-10 years           |  |
|           |  |                                 |          |          |        |                      |  |
|           |  |                                 |          |          |        |                      |  |

Campus Name: Herzl Page : 5 of 47 Assessment Date: 04/18/2022



| Catego   | ry : Electrical  |                 | В        | uilding | : Main |             | Douglas BOOLE VAILD, Officago, IE o |
|----------|--|-----------------|----------|---------|--------|-------------|-------------------------------------|
|          |  |                 |          |         |        | Recommend   |                                     |
| oup      | Item - Type  | Location        | Quantity | UOM     | Rank   | Replacement | Comments                            |
|          | Transformers - 277/480 - 120/208   | Entire Building | 2        | EA      | 7      | 6-10 years  |                                     |
| tego     | ry : Fire Protection   |                 | В        | uilding | : Main |             |                                     |
|          |  |                 |          |         |        | Recommend   |                                     |
| oup      | Item - Type  | Location        | Quantity | UOM     | Rank   | Replacement | Comments                            |
| e Alar   | m  |                 |          |         |        |             |                                     |
|          | Fire Alarm Panel   | Entire Building | 1        | EA      | 7      | 6-10 years  |                                     |
|          | Fire Alarm Strobe Lights   | Entire Building | 142,911  | SF      | 6      | 6-10 years  |                                     |
|          | Fire Alarm_System  | Entire Building | 142,911  | SF      | 6      | 6-10 years  |                                     |
| _4       |  | -               | <b>.</b> |         |        | -           |                                     |
| atego    | ry : Mechanical  |                 | В        | uilding | : wain | Recommend   |                                     |
| roup     | Item - Type  | Location        | Quantity | UOM     | Rank   | Replacement | Comments                            |
|          | ling Systems   |                 |          |         |        |             |                                     |
| anu      | Air Handling Unit- Built Up-Multi Zone-                                      | Auditorium      | 1        | EA      | 6      | 6-10 years  |                                     |
|          | Double Delivery- Steam Coils - 45001 -                                       | Additorium      | '        |         | J      | 0-10 years  |                                     |
|          | 60000 cfm  |                 |          |         |        |             |                                     |
|          | Air Intake   | Auditorium      | 1        | EA      | 6      | 6-10 years  |                                     |
|          | Auxiliaries - 45001 - 60000 cfm  | Auditorium      | 1        | EA      | 5      | 6-10 years  |                                     |
|          | Return Duct Work - Indoor- Vertical Shaft                                    | Auditorium      | 100      | LF      | 6      | 6-10 years  |                                     |
|          | and Ducts  | Auditorium      | 100      | LF      | O      | 0-10 years  |                                     |
|          |  | Auditorium      | 40       | Ε.Λ     | 6      | 6-10 years  |                                     |
|          | Zone Dampers   |                 |          | EΑ      | 6      |             |                                     |
|          | Air Handling Unit- Built Up-Multi Zone-<br>Steam Coils - 25001 - 35000 cfm   | Mechanical Room | 1        | EA      | 5      | 6-10 years  |                                     |
|          | Air Intake   | Mechanical Room | 1        | EA      | 6      | 6-10 years  |                                     |
|          | Auxiliaries - 25001 - 35000 cfm  | Mechanical Room | 1        | EA      | 5      | 6-10 years  |                                     |
|          | Return Duct Work - Indoor- Vertical Shaft and Ducts                          | Mechanical Room | 100      | LF      | 6      | 6-10 years  |                                     |
|          | Zone Dampers   | Mechanical Room | 10       | EA      | 6      | 6-10 years  |                                     |
|          | Air Handling Unit- Built Up- Single Zone w/                                  | South West      | 1        | EA      | 6      | 6-10 years  |                                     |
|          | Air Tunnel- Steam Coils - Greater than 35000 cfm                             |                 |          |         |        |             |                                     |
|          |  | South West      | 4        | ⊏^      | e      | 6 10        |                                     |
|          | Air Intake   |                 | 1        | EΑ      | 6      | 6-10 years  |                                     |
|          | Auxiliaries - Greater than 35000 cfm   | South West      | 1        | EΑ      | 5      | 6-10 years  |                                     |
|          | Reheat Boxes - Reheat Boxes with Steam Coil                                  | South West      | 11       | EA      | 6      | 6-10 years  |                                     |
|          | Return Duct Work - Indoor- Vertical Shaft and Ducts                          | South West      | 100      | LF      | 7      | 6-10 years  |                                     |
|          | Zone Dampers   | South West      | 30       | EA      | 6      | 6-10 years  |                                     |
| oiler Sy | stems  |                 |          |         |        |             |                                     |
|          | Boiler Auxiliary- Scotch Marine- Steam Low<br>Pressure Boiler - 201 - 300 HP | Boiler Room     | 2        | EA      | 6      | 6-10 years  |                                     |



| Catodo     | y : Mechanical                                 |                 | D          | uilding | · Main    | 3711 W                                  | •                              |
|------------|--|-----------------|------------|---------|-----------|---|--------------------------------|
| Jalegoi    | y . Mechanical                                 |                 | В          | unung   | . IVIAIII | Recommend                               |                                |
| Group      | Item - Type                                    | Location        | Quantity   | UOM     | Rank      | Replacement                             | Comments                       |
| Group      | Chemical Feed System                           | Boiler Room     | Quantity 1 | EA      | 7         | 6-10 years                              | Comments                       |
|            | Combustion Dampers                             | Boiler Room     | 2          | EA      | 5         | 6-10 years                              |                                |
|            | Condensate Pump                                | Boiler Room     | 4          | EA      | 5         | •                                       | Tank deteriorating heavily     |
|            | Feed Water Pumps and Tank                      | Boiler Room     | 1          | EA      | 5<br>5    | 1-2 years                               | Tanks in poor shape, pumps ok. |
|            | Non Condensing- Fire Tube- Scotch Marine-      |                 | 2          | EA      | 5<br>6    | 1-2 years<br>6-10 years                 | ranks in poor snape, pumps ok. |
|            |  | Boiler Room     | 2          | EA      | О         | 6-10 years                              |                                |
|            | Steam- Low Pressure Boiler - 201 - 300 HP      | Dellas Desas    | 500        |         | •         | 0.40                                    |                                |
|            | Piping - Condensate Pipe- Steel                | Boiler Room     | 500        | LF      | 6         | 6-10 years                              |                                |
|            | Piping - Steam Pipe- Steel                     | Boiler Room     | 500        | LF      | 6         | 6-10 years                              |                                |
|            | Steam Traps                                    | Boiler Room     | 120        | EA      | 6         | 6-10 years                              |                                |
| Gas Boo    | ster   |                 |            |         |           |   |                                |
|            | Gas Booster                                    | Boiler Room     | 2          | EA      | 6         | 10+ years                               |                                |
| Heating [  | Devices  |                 |            |         |           |   |                                |
|            | Cabinet Heaters - With Electric Coil           | 1st Floor       | 2          | EA      | 6         | 6-10 years                              |                                |
|            | Radiators - Steam                              | Entire Building | 2          | EΑ      | 6         | 6-10 years                              |                                |
|            | Wall Heater - Electric                         | Entire Building | 5          | EΑ      | 6         | 6-10 years                              |                                |
|            | Unit Heater - Steam                            | Lunchroom       | 1          | EA      | 6         | 6-10 years                              |                                |
|            | Office Total Occurr                            | Landinoom       | '          | L/\     | O         | o ro years                              |                                |
| Tempera    | ture Control                                   |                 |            |         |           |   |                                |
|            | Electric Thermostat                            | Entire Building | 3          | EΑ      | 7         | 6-10 years                              |                                |
|            | Hybrid Pneumatic/DDC System                    | Entire Building | 142,911    | SF      | 5         | 6-10 years                              |                                |
|            | Thermostats - Pneumatic                        | Entire Building | 89         | EA      | 6         | 6-10 years                              |                                |
| Ventilatio | n  |                 |            |         |           |   |                                |
|            | Exhaust Fans- Indoor - 500 - 1500 CFM          | Entire Building | 1          | EA      | 6         | 6-10 years                              |                                |
|            | Exhaust Fans- Roof Mounted - 1501 - 8000       | Entire Building | 1          | ĒΑ      | 6         | 6-10 years                              |                                |
|            | CFM  | g               | •          |         | -         | - · · · · · · · · · · · · · · · · · · · |                                |
|            | Exhaust Fans- Roof Mounted - 1501 - 8000       | Entire Building | 1          | EA      | 6         | 6-10 years                              |                                |
|            | CFM  |                 | _          |         | _         |   |                                |
|            | Exhaust Fans- Roof Mounted - 500 - 1500<br>CFM | Entire Building | 7          | EA      | 6         | 6-10 years                              |                                |
|            | Exhaust Fans- Roof Mounted - 500 - 1500        | Entire Building | 2          | EA      | 6         | 6-10 years                              |                                |
|            | CFM  |                 |            |         |           |   |                                |
|            | Exhaust Fans- Roof Mounted - 500 - 1500<br>CFM | Entire Building | 3          | EA      | 6         | 6-10 years                              |                                |
|            | Roof Mounted Duct Work                         | Entire Building | 40         | LF      | 6         | 6-10 years                              |                                |
|            | Type II Exhaust Hood- Warming Kitchen          | Entire Building | 1          | ĒA      | 7         | 10+ years                               |                                |
| Categoi    | y : Plumbing                                   |                 | В          | uilding | : Main    |   |                                |
|            | •  |                 |            |         |           | Recommend                               |                                |
| Group      | Item - Type                                    | Location        | Quantity   | UOM     | Rank      | Replacement                             | Comments                       |



| Catego   | ry : Plumbing   |                 | В        | uilding | : Main |             |               |
|----------|---|-----------------|----------|---------|--------|-------------|---------------|
|          | <u>-</u>  |                 |          |         |        | Recommend   |               |
| Group    | Item - Type   | Location        | Quantity | UOM     | Rank   | Replacement | Comments      |
|          | Gas Heater - 150000 - 300000 BTU/HR                             | Boiler Room     | 2        | EA      | 6      | 10+ years   |               |
|          | Hot Water Storage Tank_Gas - Less than 200 Gallons              | Boiler Room     | 1        | EA      | 7      | 10+ years   |               |
| _Piping_ |   |                 |          |         |        |             |               |
|          | Domestic Piping-Hot Water Return Lines                          | Entire Building | 142,911  | SF      | 6      | 6-10 years  |               |
|          | Domestic Piping-Hot Water Return Risers                         | Entire Building | 142,911  | SF      | 6      | 6-10 years  |               |
|          | Domestic Piping-Hot Water from Risers to Fixtures               | Entire Building | 142,911  | SF      | 6      | 6-10 years  |               |
|          | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)        | Entire Building | 142,911  | SF      | 6      | 6-10 years  |               |
|          | Domestic Piping-Hot/Cold Water Supply (Risers)                  | Entire Building | 142,911  | SF      | 6      | 6-10 years  |               |
|          | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 142,911  | SF      | 6      | 6-10 years  |               |
|          | Sanitary Piping   | Entire Building | 142,911  | SF      | 5      | 2-5 years   | 40+ years old |
|          | Storm Piping  | Entire Building | 142,911  | SF      | 5      | 2-5 years   | 40+ years old |
|          | Vent Piping   | Entire Building | 142,911  | SF      | 5      | 2-5 years   | 40+ years old |
| Pumps    |   |                 |          |         |        |             |               |
| •        | Pumps - Domestic Booster Pump-Duplex                            | Basement        | 1        | EA      | 6      | 6-10 years  |               |
|          | Pumps - Ejector-Duplex  | Basement        | 1        | EA      | 6      | 6-10 years  |               |

Category: Room **Building: Main** 

| Group | Item - Type                 | Location                        | Quantity | UOM | Rank | Recommend<br>Replacement | Comments |
|-------|-----------------------------|---------------------------------|----------|-----|------|--------------------------|----------|
| •     | trative Suites/Offices      | Location                        | Quantity | OOM | Rank | периссинен               | Comments |
|       | AC Unit                     | 1st Floor - 113 Kitchen Storage | 1        | EA  | 7    | 6-10 years               |          |
|       | Ceiling - Plaster/Drywall   | 1st Floor - 113 Kitchen Storage | 862      | SF  | 7    | 10+ years                |          |
|       | Doors - Wood Doors inclu hw | 1st Floor - 113 Kitchen Storage | 1        | EA  | 7    | 10+ years                |          |
|       | Floor - Tile                | 1st Floor - 113 Kitchen Storage | 862      | SF  | 6    | 10+ years                |          |
|       | Lighting - Pendent/Surface  | 1st Floor - 113 Kitchen Storage | 7        | EA  | 7    | 10+ years                |          |
|       | Power Distribution          | 1st Floor - 113 Kitchen Storage | 6        | EA  | 7    | 10+ years                |          |
|       | Storage/ Closet             | 1st Floor - 113 Kitchen Storage | 60       | SF  | 7    | 10+ years                |          |
|       | Walls - Concrete Block      | 1st Floor - 113 Kitchen Storage | 450      | SF  | 7    | 10+ years                |          |
|       | Walls - Plaster/Drywall     | 1st Floor - 113 Kitchen Storage | 1,242    | SF  | 7    | 10+ years                |          |
|       | AC Unit                     | 1st Floor - 119 Library         | 1        | EA  | 7    | 6-10 years               |          |
|       | Ceiling - Plaster/Drywall   | 1st Floor - 119 Library         | 318      | SF  | 7    | 10+ years                |          |
|       | Doors - Wood Doors inclu hw | 1st Floor - 119 Library         | 1        | EA  | 7    | 10+ years                |          |
|       | Floor - Tile                | 1st Floor - 119 Library         | 310      | SF  | 6    | 10+ years                |          |
|       | Floor - Tile                | 1st Floor - 119 Library         | 8        | SF  | 4    | 0-1 year                 | Cracked  |
|       | Lighting - Pendent/Surface  | 1st Floor - 119 Library         | 4        | EA  | 7    | 10+ years                |          |
|       | Power Distribution          | 1st Floor - 119 Library         | 6        | EA  | 7    | 10+ years                |          |



| Catego | ry : Room  |  | В        | uilding | : Main |             |          |
|--------|--|--|----------|---------|--------|-------------|----------|
|        |  |  |          |         |        | Recommend   |          |
| Group  | Item - Type                                      | Location                                     | Quantity | UOM     | Rank   | Replacement | Comments |
|        | Walls - Plaster/Drywall                          | 1st Floor - 119 Library                      | 1,069    | SF      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall                          | 1st Floor - 119 Library                      | 50       | SF      | 5      | 0-1 year    | Cracked  |
|        | AC Unit  | 1st Floor - Engineer                         | 1        | EA      | 7      | 6-10 years  |          |
|        | Ceiling - Plaster/Drywall                        | 1st Floor - Engineer                         | 150      | SF      | 7      | 10+ years   |          |
|        | Doors - Steel Doors incl hw                      | 1st Floor - Engineer                         | 1        | EA      | 7      | 10+ years   |          |
|        | Floor - Tile                                     | 1st Floor - Engineer                         | 146      | SF      | 6      | 10+ years   |          |
|        | Floor - Tile                                     | 1st Floor - Engineer                         | 4        | SF      | 5      | 0-1 year    | Cracked  |
|        | Lighting - Pendent/Surface                       | 1st Floor - Engineer                         | 2        | ĒΑ      | 7      | 10+ years   |          |
|        | Power Distribution                               | 1st Floor - Engineer                         | 4        | EA      | 7      | 10+ years   |          |
|        | Walls - Concrete Block                           | 1st Floor - Engineer                         | 368      | SF      | 7      | 10+ years   |          |
|        | Ceiling - Plaster/Drywall                        | 217C   | 143      | SF      | 7      | 10+ years   |          |
|        | Doors - Wood Doors inclu hw                      | 217C   | 1-13     | EA      | 7      | 10+ years   |          |
|        | Floor - Tile                                     | 217C   | 133      | SF      | 6      | 10+ years   |          |
|        | Floor - Tile                                     | 217C<br>217C                                 | 10       | SF      | 4      | 0-1 years   | Chipped  |
|        | Lighting - Pendent/Surface                       | 217C<br>217C                                 |          | EA      | 7      | ,           | Chipped  |
|        |  |  | 2        |         |        | 10+ years   |          |
|        | Power Distribution                               | 217C   | 6        | EA      | 7      | 10+ years   |          |
|        | Storage/ Closet                                  | 217C   | 8        | SF      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall                          | 217C   | 634      | SF      | 6      | 10+ years   |          |
|        | Ceiling - Plaster/Drywall                        | 244  | 416      | SF      | 7      | 10+ years   |          |
|        | Doors - Wood Doors inclu hw                      | 244  | 1        | EA      | 7      | 10+ years   |          |
|        | Floor - Tile                                     | 244  | 410      | SF      | 6      | 10+ years   |          |
|        | Floor - Tile                                     | 244  | 6        | SF      | 4      | 0-1 year    | Damaged  |
|        | Lighting - Pendent/Surface                       | 244  | 5        | EA      | 7      | 10+ years   |          |
|        | Power Distribution                               | 244  | 12       | EA      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall                          | 244  | 1,164    | SF      | 7      | 10+ years   |          |
|        | AC Unit  | 2nd Floor - 211A Teacher's Lounge            | 1        | EA      | 7      | 6-10 years  |          |
|        | Ceiling - Plaster/Drywall                        | 2nd Floor - 211A Teacher's Lounge            | 655      | SF      | 7      | 10+ years   |          |
|        | Doors - Transom Window                           | 2nd Floor - 211A Teacher's Lounge            | 10       | SF      | 7      | 10+ years   |          |
|        | Doors - Wood Doors inclu hw                      | 2nd Floor - 211A Teacher's Lounge            | 1        | EA      | 7      | 10+ years   |          |
|        | Floor - Tile                                     | 2nd Floor - 211A Teacher's Lounge            | 655      | SF      | 7      | 10+ years   |          |
|        | Lighting - Pendent/Surface                       | 2nd Floor - 211A Teacher's Lounge            | 18       | ĒΑ      | 7      | 10+ years   |          |
|        | Power Distribution                               | 2nd Floor - 211A Teacher's Lounge            | 10       | EΑ      | 7      | 10+ years   |          |
|        | Storage/ Closet                                  | 2nd Floor - 211A Teacher's Lounge            | 30       | SF      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall                          | 2nd Floor - 211A Teacher's Lounge            | 1,600    | SF      | 7      | 10+ years   |          |
|        | Ceiling - Plaster/Drywall                        | 2nd Floor - 217A Teacher's Lourige           | 76       | SF      | 7      | 10+ years   |          |
|        | Doors - Side-lite                                | 2nd Floor - 217A Gym<br>2nd Floor - 217A Gym | 10       | SF      | 7      | 10+ years   |          |
|        |  | 2nd Floor - 217A Gym<br>2nd Floor - 217A Gym | -        | EA      | 7      |             |          |
|        | Doors - Wood Doors inclu hw                      |  | 1        |         |        | 10+ years   |          |
|        | Floor - Tile                                     | 2nd Floor - 217A Gym                         | 76       | SF      | 6      | 10+ years   |          |
|        | Lighting - Pendent/Surface                       | 2nd Floor - 217A Gym                         | 1        | EA      | 7      | 10+ years   |          |
|        | Power Distribution                               | 2nd Floor - 217A Gym                         | 3        | EA      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall                          | 2nd Floor - 217A Gym                         | 485      | SF      | 6      | 10+ years   |          |
|        | AC Unit  | 2nd Floor - 226 Principal                    | 1        | EA      | 7      | 6-10 years  |          |
|        | Coiling Blooter/Dravell                          | 2nd Floor - 226 Principal                    | 348      | SF      | 7      | 10+ years   |          |
|        | Ceiling - Plaster/Drywall Doors - Transom Window | 2nd Floor - 226 Principal                    | 100      | SF      | 7      | 10+ years   |          |



| Catego | ry : Room                   |   | В        | uilding | : Main |             | _        |
|--------|-----------------------------|---|----------|---------|--------|-------------|----------|
| _      |                             |   |          |         |        | Recommend   |          |
| Group  | Item - Type                 | Location                                      | Quantity | UOM     | Rank   | Replacement | Comments |
|        | Doors - Wood Doors inclu hw | 2nd Floor - 226 Principal                     | 2        | EA      | 7      | 10+ years   |          |
|        | Floor - Carpet              | 2nd Floor - 226 Principal                     | 348      | SF      | 7      | 6-10 years  |          |
|        | Lighting - Pendent/Surface  | 2nd Floor - 226 Principal                     | 6        | EA      | 7      | 10+ years   |          |
|        | Power Distribution          | 2nd Floor - 226 Principal                     | 12       | EA      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall     | 2nd Floor - 226 Principal                     | 554      | SF      | 7      | 10+ years   |          |
|        | AC Unit                     | 2nd Floor - 230 Main Office                   | 1        | EA      | 7      | 6-10 years  |          |
|        | Ceiling - Plaster/Drywall   | 2nd Floor - 230 Main Office                   | 348      | SF      | 7      | 10+ years   |          |
|        | Doors - Transom Window      | 2nd Floor - 230 Main Office                   | 110      | SF      | 7      | 10+ years   |          |
|        | Doors - Wood Doors inclu hw | 2nd Floor - 230 Main Office                   | 1        | EA      | 7      | 10+ years   |          |
|        | Floor - Carpet              | 2nd Floor - 230 Main Office                   | 348      | SF      | 7      | 6-10 years  |          |
|        | Lighting - Pendent/Surface  | 2nd Floor - 230 Main Office                   | 10       | EA      | 7      | 10+ years   |          |
|        | Power Distribution          | 2nd Floor - 230 Main Office                   | 20       | EA      | 7      | 10+ years   |          |
|        | Storage/ Closet             | 2nd Floor - 230 Main Office                   | 120      | SF      | 7      | 10+ years   |          |
|        | Storage/ Closet             | 2nd Floor - 230 Main Office                   | 40       | SF      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall     | 2nd Floor - 230 Main Office                   | 991      | SF      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall     | 2nd Floor - 230 Main Office                   | 5        | SF      | 5      | 0-1 year    | Cracked  |
|        | Ceiling - Plaster/Drywall   | 2nd Floor - Main Office Copy Room             | 125      | SF      | 7      | 10+ years   |          |
|        | Doors - Wood Doors inclu hw | 2nd Floor - Main Office Copy Room             | 1        | EA      | 7      | 10+ years   |          |
|        | Floor - Carpet              | 2nd Floor - Main Office Copy Room             | 125      | SF      | 7      | 6-10 years  |          |
|        | Lighting - Pendent/Surface  | 2nd Floor - Main Office Copy Room             | 2        | EA      | 7      | 10+ years   |          |
|        | Power Distribution          | 2nd Floor - Main Office Copy Room             | 6        | EA      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall     | 2nd Floor - Main Office Copy Room             | 250      | SF      | 7      | 10+ years   |          |
|        | AC Unit                     | 3rd Floor-309 Main Office                     | 1        | EA      | 7      | 6-10 years  |          |
|        | Ceiling - Plaster/Drywall   | 3rd Floor-309 Main Office                     | 516      | SF      | 7      | 10+ years   |          |
|        | Doors - Transom Window      | 3rd Floor-309 Main Office                     | 12       | SF      | 7      | 10+ years   |          |
|        | Doors - Wood Doors inclu hw | 3rd Floor-309 Main Office                     | 1        | EA      | 7      | 10+ years   |          |
|        | Floor - Tile                | 3rd Floor-309 Main Office                     | 516      | SF      | 7      | 6-10 years  |          |
|        | Lighting - Pendent/Surface  | 3rd Floor-309 Main Office                     | 7        | EA      | 7      | 6-10 years  |          |
|        | Power Distribution          | 3rd Floor-309 Main Office                     | 12       | EA      | 7      | 10+ years   |          |
|        | Storage/ Closet             | 3rd Floor-309 Main Office                     | 15       | SF      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall     | 3rd Floor-309 Main Office                     | 1,189    | SF      | 7      | 10+ years   |          |
|        | AC Unit                     | 3rd Floor-309A Head of School, in<br>Room 309 | 1        | EA      | 7      | 6-10 years  |          |
|        | Ceiling - Plaster/Drywall   | 3rd Floor-309A Head of School, in             | 354      | SF      | 7      | 10+ years   |          |
|        |                             | Room 309                                      |          |         |        |             |          |
|        | Doors - Wood Doors inclu hw | 3rd Floor-309A Head of School, in Room 309    | 1        | EA      | 7      | 10+ years   |          |
|        | Floor - Tile                | 3rd Floor-309A Head of School, in             | 354      | SF      | 7      | 6-10 years  |          |
|        | Lighting - Pendent/Surface  | Room 309<br>3rd Floor-309A Head of School, in | 4        | EA      | 7      | 10+ years   |          |
|        |                             | Room 309                                      |          |         |        |             |          |
|        | Power Distribution          | 3rd Floor-309A Head of School, in Room 309    | 10       | EA      | 7      | 10+ years   |          |
|        | Walls - Plaster/Drywall     | 3rd Floor-309A Head of School, in             | 1,012    | SF      | 7      | 10+ years   |          |

Campus Name: Herzl Page : 10 of 47 Assessment Date: 04/18/2022



| Catego     | ory : Room   |   | В        | uilding | : Main |   |          |
|------------|--|---|----------|---------|--------|---|----------|
|            |  |   |          | _       |        | Recommend                               |          |
| Group      | Item - Type  | Location                                      | Quantity | UOM     | Rank   | Replacement                             | Comments |
|            |  | Room 309                                      |          |         |        |   |          |
|            | AC Unit  | 3rd Floor-309B Office Manager, in             | 1        | EA      | 7      | 6-10 years                              |          |
|            |  | Room 309                                      |          |         | _      |   |          |
|            | Ceiling - Plaster/Drywall  | 3rd Floor-309B Office Manager, in             | 119      | SF      | 7      | 10+ years                               |          |
|            | D W 1D : 11  | Room 309                                      | 4        | _^      | _      | 40                                      |          |
|            | Doors - Wood Doors inclu hw  | 3rd Floor-309B Office Manager, in             | 1        | EA      | 7      | 10+ years                               |          |
|            | Floor - Tile   | Room 309<br>3rd Floor-309B Office Manager, in | 119      | SF      | 7      | 6-10 years                              |          |
|            | Floor - Tile   | Room 309                                      | 119      | SF      | 1      | 6-10 years                              |          |
|            | Lighting - Pendent/Surface   | 3rd Floor-309B Office Manager, in             | 2        | EA      | 7      | 6-10 years                              |          |
|            | Lighting - Fendent/Surface   | Room 309                                      | 2        | LA      | ,      | 0-10 years                              |          |
|            | Power Distribution   | 3rd Floor-309B Office Manager, in             | 8        | EA      | 7      | 10+ years                               |          |
|            |  | Room 309                                      | · ·      |         | •      | .o. you.o                               |          |
|            | Walls - Plaster/Drywall  | 3rd Floor-309B Office Manager, in             | 498      | SF      | 7      | 10+ years                               |          |
|            | <b>,</b>   | Room 309                                      |          |         |        | , |          |
|            | AC Unit  | 3rd Floor-311 Copy Room                       | 1        | EA      | 7      | 6-10 years                              |          |
|            | Ceiling - Plaster/Drywall  | 3rd Floor-311 Copy Room                       | 860      | SF      | 7      | 10+ years                               |          |
|            | Doors - Wood Doors inclu hw  | 3rd Floor-311 Copy Room                       | 1        | EA      | 7      | 10+ years                               |          |
|            | Floor - Tile 3rd Floor-311 Copy Roc<br>Floor - Tile 3rd Floor-311 Copy Roc | 3rd Floor-311 Copy Room                       | 855      | SF      | 7      | 6-10 years                              |          |
|            |  | 3rd Floor-311 Copy Room                       | 5        | SF      | 4      | 0-1 year                                | Chipped  |
|            | Lighting - Pendent/Surface   | 3rd Floor-311 Copy Room                       | 20       | EA      | 7      | 6-10 years                              |          |
|            | Power Distribution   | 3rd Floor-311 Copy Room                       | 12       | EA      | 7      | 10+ years                               |          |
|            | Walls - Plaster/Drywall  | 3rd Floor-311 Copy Room                       | 1,400    | SF      | 7      | 10+ years                               |          |
|            | Ceiling - Plaster/Drywall  | 3rd Floor-315D Staff Work Room                | 178      | SF      | 7      | 10+ years                               |          |
|            | Doors - Wood Doors inclu hw  | 3rd Floor-315D Staff Work Room                | 1        | EA      | 7      | 10+ years                               |          |
|            | Floor - Tile   | 3rd Floor-315D Staff Work Room                | 178      | SF      | 7      | 6-10 years                              |          |
|            | Lighting - Pendent/Surface   | 3rd Floor-315D Staff Work Room                | 2        | EA      | 7      | 6-10 years                              |          |
|            | Power Distribution   | 3rd Floor-315D Staff Work Room                | 6        | EA      | 7      | 10+ years                               |          |
|            | Walls - Plaster/Drywall  | 3rd Floor-315D Staff Work Room                | 652      | SF      | 7      | 10+ years                               |          |
|            | Ceiling - Plaster/Drywall  | 3rd Floor-330A Gym Teacher's                  | 160      | SF      | 7      | 10+ years                               |          |
|            | ,  | Office  |          |         |        | ,                                       |          |
|            | Doors - Wood Doors inclu hw  | 3rd Floor-330A Gym Teacher's                  | 1        | EA      | 7      | 10+ years                               |          |
|            |  | Office  |          |         |        | •                                       |          |
|            | Floor - Tile   | 3rd Floor-330A Gym Teacher's                  | 160      | SF      | 7      | 6-10 years                              |          |
|            |  | Office  |          |         |        | ·                                       |          |
|            | Lighting - Pendent/Surface   | 3rd Floor-330A Gym Teacher's                  | 2        | EA      | 7      | 6-10 years                              |          |
|            |  | Office  |          |         |        |   |          |
|            | Power Distribution   | 3rd Floor-330A Gym Teacher's                  | 4        | EA      | 7      | 10+ years                               |          |
|            |  | Office  |          |         |        | ·                                       |          |
|            | Walls - Plaster/Drywall  | 3rd Floor-330A Gym Teacher's                  | 550      | SF      | 7      | 10+ years                               |          |
|            |  | Office  |          |         |        |   |          |
|            |  |   |          |         |        |   |          |
| _Auditoriu | um & Theater   |   |          |         |        |   |          |
|            | Ceiling - Splined  | 1st Floor                                     | 6,441    | SF      | 7      | 10+ years                               |          |
|            |  |   |          |         |        |   |          |



| Catego   | ry : Room                   |                        | В        | uilding | : Main |             |          |
|----------|-----------------------------|------------------------|----------|---------|--------|-------------|----------|
|          |                             |                        |          |         |        | Recommend   |          |
| Group    | Item - Type                 | Location               | Quantity | UOM     | Rank   | Replacement | Comments |
|          | Doors - Steel Doors incl hw | 1st Floor              | 10       | EA      | 7      | 10+ years   |          |
|          | Doors - Wood Doors inclu hw | 1st Floor              | 2        | EA      | 7      | 10+ years   |          |
|          | Floor - Carpet              | 1st Floor              | 760      | SF      | 7      | 6-10 years  |          |
|          | Floor - Tile                | 1st Floor              | 1,908    | SF      | 7      | 10+ years   |          |
|          | Floor - Tile                | 1st Floor              | 33       | SF      | 4      | 0-1 year    | Chipped  |
|          | Floor - Wood                | 1st Floor              | 3,740    | SF      | 7      | 10+ years   |          |
|          | Lighting - Pendent/Surface  | 1st Floor              | 20       | EA      | 7      | 10+ years   |          |
|          | Lighting - Wall Mounted     | 1st Floor              | 16       | EA      | 7      | 10+ years   |          |
|          | Main Floor Seating          | 1st Floor              | 650      | EA      | 7      | 10+ years   |          |
|          | Sound System                | 1st Floor              | 1        | EA      | 7      | 10+ years   |          |
|          | Stage                       | 1st Floor              | 1,071    | SF      | 7      | 10+ years   |          |
|          | Stage Curtain               | 1st Floor              | 8        | EA      | 7      | 10+ years   |          |
|          | Stage Lift                  | 1st Floor              | 1        | EA      | 7      | 10+ years   |          |
|          | Stage Lighting System       | 1st Floor              | 1        | EA      | 7      | 10+ years   |          |
|          | Stage-Stairs - Wood         | 1st Floor              | 42       | LF      | 7      | 10+ years   |          |
|          | Stairs - Asphalt            | 1st Floor              | 128      | LF      | 7      | 10+ years   |          |
|          | Walls - Plaster/Drywall     | 1st Floor              | 9,784    | SF      | 7      | 10+ years   |          |
| _Gymnas  | ia                          |                        |          |         |        |             |          |
| •        | Ceiling - Plaster/Drywall   | 2nd Floor - 217 Girl's | 2,970    | SF      | 7      | 10+ years   |          |
|          | Doors - Transom Window      | 2nd Floor - 217 Girl's | 30       | SF      | 7      | 10+ years   |          |
|          | Doors - Wood Doors inclu hw | 2nd Floor - 217 Girl's | 4        | EA      | 7      | 10+ years   |          |
|          | Floor - Wood                | 2nd Floor - 217 Girl's | 2,970    | SF      | 7      | 10+ years   |          |
|          | Lighting - Pendent/Surface  | 2nd Floor - 217 Girl's | 15       | EA      | 7      | 10+ years   |          |
|          | Walls - Plaster/Drywall     | 2nd Floor - 217 Girl's | 5,020    | SF      | 7      | 10+ years   |          |
|          | Ceiling - Plaster/Drywall   | Room 330, Boy's Gym    | 4,806    | SF      | 7      | 10+ years   |          |
|          | Doors - Transom Window      | Room 330, Boy's Gym    | 40       | SF      | 7      | 10+ years   |          |
|          | Doors - Wood Doors inclu hw | Room 330, Boy's Gym    | 4        | EA      | 7      | 10+ years   |          |
|          | Floor - Wood                | Room 330, Boy's Gym    | 4,806    | SF      | 6      | 6-10 years  |          |
|          | Lighting - Pendent/Surface  | Room 330, Boy's Gym    | 36       | EA      | 7      | 6-10 years  |          |
|          | Walls - Plaster/Drywall     | Room 330, Boy's Gym    | 5,564    | SF      | 7      | 10+ years   |          |
| _Kitchen |                             |                        |          |         |        |             |          |
|          | Ceiling - Plaster/Drywall   | 1st Floor              | 915      | SF      | 7      | 10+ years   |          |
|          | Doors - Wood Doors inclu hw | 1st Floor              | 3        | EA      | 7      | 10+ years   |          |
|          | Floor - Tile Quarry         | 1st Floor              | 915      | SF      | 7      | 10+ years   |          |
|          | Lighting - Pendent/Surface  | 1st Floor              | 16       | EA      | 7      | 10+ years   |          |
|          | Serving Line                | 1st Floor              | 18       | LF      | 7      | 10+ years   |          |
|          | Walls - Metal Panel         | 1st Floor              | 934      | SF      | 7      | 10+ years   |          |
|          | Walls - Plaster/Drywall     | 1st Floor              | 623      | SF      | 7      | 10+ years   |          |
| Library  |                             |                        |          |         |        |             |          |
| <u> </u> | AC Unit                     | 118                    | 3        | EA      | 7      | 6-10 years  |          |
|          |                             |                        |          |         |        |             |          |



| Catego  | Category : Room              |                         | В        | uilding | : Main |             |                        |
|---------|------------------------------|-------------------------|----------|---------|--------|-------------|------------------------|
|         |                              |                         |          |         |        | Recommend   |                        |
| Group   | Item - Type                  | Location                | Quantity | UOM     | Rank   | Replacement | Comments               |
|         | Casework                     | 118                     | 42       | LF      | 7      | 10+ years   |                        |
|         | Ceiling - Plaster/Drywall    | 118                     | 1,402    | SF      | 7      | 10+ years   |                        |
|         | Doors - Transom Window       | 118                     | 18       | SF      | 7      | 10+ years   |                        |
|         | Doors - Wood Doors inclu hw  | 118                     | 2        | EA      | 7      | 10+ years   |                        |
|         | Floor - Tile                 | 118                     | 1,402    | SF      | 7      | 10+ years   |                        |
|         | Lighting - Pendent/Surface   | 118                     | 22       | EA      | 7      | 10+ years   |                        |
|         | Storage/ Closet              | 118                     | 20       | SF      | 7      | 10+ years   |                        |
|         | Walls - Plaster/Drywall      | 118                     | 2,181    | SF      | 7      | 10+ years   |                        |
|         | Walls - Plaster/Drywall      | 118                     | 10       | SF      | 5      | 0-1 year    | Cracked                |
| Lunch & | Multipurpose Room            |                         |          |         |        |             |                        |
|         | AC Unit                      | 109/110                 | 3        | EA      | 7      | 6-10 years  |                        |
|         | Ceiling - Plaster/Drywall    | 109/110                 | 2,759    | SF      | 7      | 10+ years   |                        |
|         | Doors - Transom Window       | 109/110                 | 2,739    | SF      | 7      | 10+ years   |                        |
|         | Doors - Wood Doors inclu hw  |                         |          | EA      | 7      | -           |                        |
|         |                              | 109/110                 | 3        |         |        | 10+ years   |                        |
|         | Floor - Tile                 | 109/110                 | 2,759    | SF      | 5      | 2-5 years   |                        |
|         | Lighting - Pendent/Surface   | 109/110                 | 42       | EΑ      | 7      | 10+ years   |                        |
|         | Serving Line                 | 109/110                 | 20       | LF      | 7      | 10+ years   |                        |
|         | Walls - Plaster/Drywall      | 109/110                 | 4,375    | SF      | 7      | 10+ years   |                        |
|         | AC Unit                      | 114A                    | 1        | EA      | 7      | 6-10 years  |                        |
|         | Ceiling - Plaster/Drywall    | 114A                    | 906      | SF      | 7      | 10+ years   |                        |
|         | Doors - Steel Doors incl hw  | 114A                    | 1        | EA      | 7      | 10+ years   |                        |
|         | Doors - Transom Window       | 114A                    | 9        | SF      | 7      | 10+ years   |                        |
|         | Doors - Wood Doors inclu hw  | 114A                    | 1        | EA      | 7      | 10+ years   |                        |
|         | Floor - Tile                 | 114A                    | 906      | SF      | 6      | 6-10 years  |                        |
|         | Lighting - Pendent/Surface   | 114A                    | 14       | ĒΑ      | 7      | 10+ years   |                        |
|         | Market Board                 | 114A                    | 24       | LF      | 7      | 6-10 years  |                        |
|         | Student Lockers - Three Tier | 114A                    | 100      | EA      | 7      | 10+ years   |                        |
|         | Walls - Plaster/Drywall      | 114A                    | 1,570    | SF      | 7      | 10+ years   |                        |
|         | vvalis - Flastel/Diywali     | 1144                    | 1,570    | SF      | ,      | 10+ years   |                        |
| MDF_ID  |                              | Ond Floor months Com    |          | ΓΛ      | 7      | 10:         |                        |
|         | Doors - Wood Doors inclu hw  | 2nd Floor - next to Gym | 1        | EA      | 7      | 10+ years   |                        |
|         | Finishes                     | 2nd Floor - next to Gym | 246      | SF      | 7      | 10+ years   |                        |
|         | Other Cooling Unit           | 2nd Floor - next to Gym | 1        | EA      | 7      | 6-10 years  | Ductless split system. |
|         | Doors - Wood Doors inclu hw  | 3rd Floor               | 1        | EA      | 7      | 10+ years   |                        |
|         | Finishes                     | 3rd Floor               | 155      | SF      | 5      | 10+ years   | Water damage to wall.  |
|         | Other Cooling Unit           | 3rd Floor               | 1        | EA      | 7      | 10+ years   | Ductless split system. |
| Mechan  | ical/ Service Rooms          |                         |          |         |        |             |                        |
|         | Air Intake Plenums           | 1st Floor               | 450      | SF      | 7      | 10+ years   |                        |
|         | Air Intake Plenums           | 1st Floor               | 650      | SF      | 7      | 10+ years   |                        |
|         | Air Tunnel                   | 1st Floor               | 9,531    | SF      | 7      | 10+ years   |                        |
|         | Auditorium Plenums           | 1st Floor               | 4,661    | SF      | 7      | 10+ years   |                        |
|         |                              |                         | .,001    | σ.      | •      | ,           |                        |



| Catego   | ry : Room                       |           | В        |     |      |             |  |
|----------|---------------------------------|-----------|----------|-----|------|-------------|--|
|          |                                 |           |          |     |      | Recommend   |  |
| Group    | Item - Type                     | Location  | Quantity | UOM | Rank | Replacement | Comments   |
|          | Boiler Room                     | 1st Floor | 1,061    | SF  | 5    | 10+ years   | Water damage to ceiling, paint chipping and peeling really bad on walls. |
|          | Janitor's Closet                | 1st Floor | 140      | SF  | 7    | 10+ years   |  |
|          | Janitor's Closet                | 1st Floor | 48       | SF  | 5    | 10+ years   |  |
|          | Mechanical/ Service Rooms       | 1st Floor | 40       | SF  | 7    | 10+ years   |  |
|          | Mechanical/ Service Rooms       | 1st Floor | 270      | SF  | 7    | 10+ years   |  |
|          | Mechanical/ Service Rooms       | 1st Floor | 1,845    | SF  | 5    | 10+ years   |  |
|          | Mechanical/ Service Rooms       | 1st Floor | 50       | SF  | 5    | 6-10 years  | No damage observed   |
|          | Storage Room                    | 1st Floor | 64       | SF  | 7    | 10+ years   |  |
|          | Storage Room                    | 1st Floor | 690      | SF  | 5    | 10+ years   |  |
|          | Janitor's Closet                | 2nd Floor | 10       | SF  | 7    | 10+ years   |  |
|          | Janitor's Closet                | 2nd Floor | 10       | SF  | 7    | 10+ years   |  |
|          | Janitor's Closet                | 2nd Floor | 10       | SF  | 5    | 10+ years   | Water damage to wall.  |
|          | Mechanical/ Service Rooms       | 2nd Floor | 10       | SF  | 7    | 10+ years   |  |
|          | Mechanical/ Service Rooms       | 2nd Floor | 26       | SF  | 7    | 10+ years   |  |
|          | Vaults                          | 2nd Floor | 50       | SF  | 7    | 10+ years   |  |
|          | Janitor's Closet                | 3rd Floor | 10       | SF  | 7    | 10+ years   |  |
|          | Janitor's Closet                | 3rd Floor | 10       | SF  | 7    | 10+ years   |  |
|          | Janitor's Closet                | 3rd Floor | 10       | SF  | 5    | 10+ years   | Damage to wall.  |
|          | Storage Room                    | 3rd Floor | 396      | SF  | 7    | 10+ years   |  |
| _Restroo | m                               |           |          |     |      |             |  |
|          | Accessories                     | 115       | 72       | SF  | 7    | 6-10 years  |  |
|          | Ceiling - Plaster/Drywall       | 115       | 72       | SF  | 7    | 10+ years   |  |
|          | Doors - Wood Doors inclu hw     | 115       | 1        | EA  | 7    | 10+ years   |  |
|          | Floor - Tile                    | 115       | 72       | SF  | 7    | 10+ years   |  |
|          | Floor Drain                     | 115       | 1        | EA  | 7    | 10+ years   |  |
|          | Hand Dryer                      | 115       | 1        | EA  | 7    | 6-10 years  |  |
|          | Lavatory                        | 115       | 1        | EA  | 7    | 10+ years   |  |
|          | Lighting - Pendent/Surface      | 115       | 1        | EA  | 7    | 10+ years   |  |
|          | Walls - Plaster/Drywall         | 115       | 220      | SF  | 7    | 10+ years   |  |
|          | Walls - Tile Ceramic/ Porcelain | 115       | 40       | SF  | 7    | 10+ years   |  |
|          | Water Closet                    | 115       | 1        | EA  | 7    | 10+ years   |  |
|          | Accessories                     | 1st Floor | 201      | SF  | 7    | 6-10 years  |  |
|          | Ceiling - Plaster/Drywall       | 1st Floor | 186      | SF  | 7    | 10+ years   |  |
|          | Ceiling - Plaster/Drywall       | 1st Floor | 15       | SF  | 6    | 10+ years   |  |
|          | Doors - Transom Window          | 1st Floor | 18       | SF  | 7    | 10+ years   |  |
|          | Doors - Wood Doors inclu hw     | 1st Floor | 1        | EA  | 7    | 10+ years   |  |
|          | Floor - Tile Ceramic/ Porcelain | 1st Floor | 196      | SF  | 7    | 10+ years   |  |
|          | Floor - Tile Ceramic/ Porcelain | 1st Floor | 5        | SF  | 4    | 0-1 year    | Chipped  |
|          | Floor Drain                     | 1st Floor | 1        | EA  | 7    | 10+ years   |  |
|          | Hand Dryer                      | 1st Floor | 2        | EA  | 7    | 6-10 years  |  |
|          | Lavatory                        | 1st Floor | 4        | EA  | 7    | 10+ years   |  |
|          |                                 |           |          |     |      |             |  |

Campus Name: Herzl Page : 14 of 47 Assessment Date: 04/18/2022



| Group | Item - Type Lighting - Pendent/Surface | Location                                   |           | _   |      | Recommend   |          |
|-------|--|--|-----------|-----|------|-------------|----------|
| Group |  | Location                                   |           |     |      |             |          |
|       | Lighting - Pendent/Surface             |  | Quantity  | UOM | Rank | Replacement | Comments |
|       |  | 1st Floor                                  | 6         | EA  | 7    | 10+ years   |          |
|       | Partitions                             | 1st Floor                                  | 3         | EA  | 7    | 10+ years   |          |
|       | Urinals                                | 1st Floor                                  | 3         | EΑ  | 7    | 10+ years   |          |
|       | Walls - Structural Glazed Tile         | 1st Floor                                  | 402       | SF  | 7    | 10+ years   |          |
|       | Water Closet                           | 1st Floor                                  | 3         | EA  | 7    | 10+ years   |          |
|       | Accessories                            | 1st Floor - Unisex                         | 89        | SF  | 7    | 6-10 years  |          |
|       | Ceiling - Exposed                      | 1st Floor - Unisex                         | 89        | SF  | 7    | 10+ years   |          |
|       | Doors - Wood Doors inclu hw            | 1st Floor - Unisex                         | 1         | EA  | 7    | 10+ years   |          |
|       | Floor - Tile Ceramic/ Porcelain        | 1st Floor - Unisex                         | 89        | SF  | 7    | 10+ years   |          |
|       | Floor Drain                            | 1st Floor - Unisex                         | 1         | EΑ  | 7    | 10+ years   |          |
|       | Hand Dryer                             | 1st Floor - Unisex                         | 1         | EA  | 7    | 6-10 years  |          |
|       | Lavatory                               | 1st Floor - Unisex                         | 1         | ΕA  | 7    | 10+ years   |          |
|       | Lighting - Pendent/Surface             | 1st Floor - Unisex                         | 1         | ΕA  | 7    | 10+ years   |          |
|       | Walls - Plaster/Drywall                | 1st Floor - Unisex                         | 455       | SF  | 7    | 10+ years   |          |
|       | Water Closet                           | 1st Floor - Unisex                         | 1         | EA  | 7    | 10+ years   |          |
|       | Accessories                            | 1st Floor - across from Room 110           | 271       | SF  | 7    | 6-10 years  |          |
|       | Ceiling - Plaster/Drywall              | 1st Floor - across from Room 110           | 271       | SF  | 7    | 10+ years   |          |
|       | Doors - Steel Doors incl hw            | 1st Floor - across from Room 110           | 1         | EA  | 7    | 10+ years   |          |
|       | Doors - Transom Window                 | 1st Floor - across from Room 110           | 20        | SF  | 7    | 10+ years   |          |
|       | Floor - Tile Ceramic/ Porcelain        | 1st Floor - across from Room 110           | 20<br>271 | SF  | 7    | ,           |          |
|       | Floor Drain                            | 1st Floor - across from Room 110           | 1         | EA  |      | 10+ years   |          |
|       |  |  |           |     | 7    | 10+ years   |          |
|       | Hand Dryer                             | 1st Floor - across from Room 110           | 2         | EΑ  | 7    | 6-10 years  |          |
|       | Lavatory                               | 1st Floor - across from Room 110           | 4         | EΑ  | 7    | 10+ years   |          |
|       | Lighting - Pendent/Surface             | 1st Floor - across from Room 110           | 6         | EΑ  | 7    | 10+ years   |          |
|       | Partitions                             | 1st Floor - across from Room 110           | 5         | EA  | 7    | 10+ years   |          |
|       | Walls - Structural Glazed Tile         | 1st Floor - across from Room 110           | 905       | SF  | 7    | 10+ years   |          |
|       | Water Closet                           | 1st Floor - across from Room 110           | 5         | EA  | 7    | 10+ years   |          |
|       | Accessories                            | 1st Floor - across from Room 118           | 269       | SF  | 7    | 6-10 years  |          |
|       | Ceiling - Plaster/Drywall              | 1st Floor - across from Room 118           | 269       | SF  | 7    | 10+ years   |          |
|       | Doors - Wood Doors inclu hw            | 1st Floor - across from Room 118           | 1         | EA  | 7    | 10+ years   |          |
|       | Floor - Tile Ceramic/ Porcelain        | 1st Floor - across from Room 118           | 269       | SF  | 6    | 10+ years   |          |
|       | Floor Drain                            | 1st Floor - across from Room 118           | 1         | EA  | 7    | 10+ years   |          |
|       | Hand Dryer                             | 1st Floor - across from Room 118           | 2         | EA  | 7    | 6-10 years  |          |
|       | Lavatory                               | 1st Floor - across from Room 118           | 6         | EA  | 7    | 10+ years   |          |
|       | Lighting - Pendent/Surface             | 1st Floor - across from Room 118           | 5         | EA  | 7    | 10+ years   |          |
|       | Partitions                             | 1st Floor - across from Room 118           | 7         | EA  | 7    | 10+ years   |          |
|       | Walls - Structural Glazed Tile         | 1st Floor - across from Room 118           | 905       | SF  | 7    | 10+ years   |          |
|       | Water Closet                           | 1st Floor - across from Room 118           | 7         | EA  | 7    | 10+ years   |          |
|       | Accessories                            | 2nd Floor - Single Unisex, in Room         | 115       | SF  | 7    | 6-10 years  |          |
|       |  | 211A                                       |           |     |      | •           |          |
|       | Ceiling - Plaster/Drywall              | 2nd Floor - Single Unisex, in Room 211A    | 115       | SF  | 7    | 10+ years   |          |
|       | Doors - Wood Doors inclu hw            | 2nd Floor - Single Unisex, in Room<br>211A | 1         | EA  | 7    | 10+ years   |          |



| Catego | Category : Room                 |  | В        | uilding | : Main |                        |                |
|--------|---------------------------------|--|----------|---------|--------|------------------------|----------------|
| Group  | Item - Type                     | Location   | Quantity | UOM     | Rank   | Recommend Replacement  | Comments       |
| Cicup  | Floor - Tile Ceramic/ Porcelain | 2nd Floor - Single Unisex, in Room<br>211A                           | 115      | SF      | 7      | 10+ years              | Commonto       |
|        | Hand Dryer                      | 2nd Floor - Single Unisex, in Room<br>211A                           | 1        | EA      | 7      | 6-10 years             |                |
|        | Lavatory                        | 2nd Floor - Single Unisex, in Room<br>211A                           | 1        | EA      | 7      | 10+ years              |                |
|        | Lighting - Lay-in               | 2nd Floor - Single Unisex, in Room<br>211A                           | 1        | EA      | 7      | 10+ years              |                |
|        | Lighting - Wall Mounted         | 2nd Floor - Single Unisex, in Room<br>211A                           | 1        | EA      | 7      | 10+ years              |                |
|        | Walls - Plaster/Drywall         | 2nd Floor - Single Unisex, in Room<br>211A                           | 125      | SF      | 7      | 10+ years              |                |
|        | Walls - Tile Ceramic/ Porcelain | 2nd Floor - Single Unisex, in Room<br>211A                           | 210      | SF      | 7      | 10+ years              |                |
|        | Water Closet                    | 2nd Floor - Single Unisex, in Room<br>211A                           | 1        | EA      | 7      | 10+ years              |                |
|        | Accessories                     | 2nd Floor - Unisex, in Room 211A                                     | 130      | SF      | 7      | 6-10 years             |                |
|        | Ceiling - Plaster/Drywall       | 2nd Floor - Unisex, in Room 211A                                     | 126      | SF      | 7      | 10+ years              |                |
|        | Ceiling - Plaster/Drywall       | 2nd Floor - Unisex, in Room 211A                                     | 4        | SF      | 4      | 0-1 year               | Hole           |
|        | Doors - Wood Doors inclu hw     | 2nd Floor - Unisex, in Room 211A                                     | 1        | EA      | 7      | 10+ years              | 11010          |
|        | Floor - Tile Ceramic/ Porcelain | 2nd Floor - Unisex, in Room 211A                                     | 130      | SF      | 7      | 10+ years              |                |
|        | Hand Dryer                      | 2nd Floor - Unisex, in Room 211A                                     | 1        | EA      | 7      | 6-10 years             |                |
|        | Lavatory                        | 2nd Floor - Unisex, in Room 211A                                     | 2        | EA      | 7      | 10+ years              |                |
|        | Lighting - Lay-in               | 2nd Floor - Unisex, in Room 211A                                     | 1        | EA      | 7      | 10+ years              |                |
|        | Lighting - Wall Mounted         | 2nd Floor - Unisex, in Room 211A                                     | 1        | EA      | 7      | 10+ years              |                |
|        | Partitions                      | 2nd Floor - Unisex, in Room 211A                                     | 2        | EA      | 7      | 10+ years              |                |
|        | Walls - Plaster/Drywall         | 2nd Floor - Unisex, in Room 211A                                     | 140      | SF      | 7      | 10+ years              |                |
|        | Walls - Tile Ceramic/ Porcelain | 2nd Floor - Unisex, in Room 211A                                     | 218      | SF      | 7      | 10+ years              |                |
|        | Walls - Tile Ceramic/ Porcelain | 2nd Floor - Unisex, in Room 211A                                     | 2        | SF      | 4      | 0-1 year               | Missing tiles  |
|        | Water Closet                    | 2nd Floor - Unisex, in Room 211A                                     | 2        | EA      | 7      | 10+ years              | Wildeling theo |
|        | Accessories                     | 2nd Floor - next to Electric Room                                    | 250      | SF      | 7      | 6-10 years             |                |
|        | Ceiling - Plaster/Drywall       | 2nd Floor - next to Electric Room                                    | 250      | SF      | 7      | 10+ years              |                |
|        | Doors - Transom Window          | 2nd Floor - next to Electric Room                                    | 20       | SF      | 7      | 10+ years              |                |
|        | Doors - Wood Doors inclu hw     | 2nd Floor - next to Electric Room                                    | 1        | EA      | 7      | 10+ years              |                |
|        | Floor - Tile Ceramic/ Porcelain | 2nd Floor - next to Electric Room                                    | 250      | SF      | 7      | 10+ years              |                |
|        | Floor Drain                     | 2nd Floor - next to Electric Room                                    | 1        | EA      | 7      | 10+ years              |                |
|        | Hand Dryer                      | 2nd Floor - next to Electric Room                                    | 2        | EA      | 7      | 6-10 years             |                |
|        | Lavatory                        | 2nd Floor - next to Electric Room                                    | 3        | EA      | 7      | 10+ years              |                |
|        | Lighting - Pendent/Surface      | 2nd Floor - next to Electric Room                                    | 5        | EA      | 7      | 10+ years              |                |
|        | Partitions                      | 2nd Floor - next to Electric Room                                    | 3        | EA      | 7      | 10+ years              |                |
|        | Urinals                         | 2nd Floor - next to Electric Room                                    | 5        | EA      | 7      | ,                      |                |
|        | Walls - Structural Glazed Tile  | 2nd Floor - next to Electric Room  2nd Floor - next to Electric Room | 837      | SF      | 7      | 10+ years<br>10+ years |                |
|        | Water Closet                    | 2nd Floor - next to Electric Room  2nd Floor - next to Electric Room | 3        | EA      | 7      | 10+ years<br>10+ years |                |
|        | Accessories                     | 2nd Floor - next to Room 215   | 269      | SF      | 7      | 6-10 years             |                |
|        | VOCESSOLIES                     | ZHU FIOOF HEXT TO ROUTH Z 13   | 209      | ЗF      | ,      | 0-10 years             |                |



| Catego | ry : Room                                    |                                       | В        | uilding | : Main |             |                 |
|--------|--|---------------------------------------|----------|---------|--------|-------------|-----------------|
|        |  |                                       |          |         |        | Recommend   |                 |
| Group  | Item - Type                                  | Location                              | Quantity | UOM     | Rank   | Replacement | Comments        |
|        | Ceiling - Plaster/Drywall                    | 2nd Floor - next to Room 215          | 269      | SF      | 7      | 10+ years   |                 |
|        | Doors - Transom Window                       | 2nd Floor - next to Room 215          | 20       | SF      | 7      | 10+ years   |                 |
|        | Doors - Wood Doors inclu hw                  | 2nd Floor - next to Room 215          | 1        | EA      | 7      | 10+ years   |                 |
|        | Floor - Tile Ceramic/ Porcelain              | 2nd Floor - next to Room 215          | 269      | SF      | 7      | 10+ years   |                 |
|        | Floor Drain                                  | 2nd Floor - next to Room 215          | 1        | EA      | 7      | 10+ years   |                 |
|        | Hand Dryer                                   | 2nd Floor - next to Room 215          | 1        | EA      | 7      | 6-10 years  |                 |
|        | Hand Dryer                                   | 2nd Floor - next to Room 215          | 1        | EA      | 5      | 0-1 year    | Out of service  |
|        | Lavatory                                     | 2nd Floor - next to Room 215          | 3        | EA      | 7      | 10+ years   |                 |
|        | Lighting - Lay-in                            | 2nd Floor - next to Room 215          | 4        | EΑ      | 7      | 10+ years   |                 |
|        | Lighting - Pendent/Surface                   | 2nd Floor - next to Room 215          | 2        | EA      | 7      | 10+ years   |                 |
|        | Partitions                                   | 2nd Floor - next to Room 215          | 8        | EA      | 7      | 10+ years   |                 |
|        | Walls - Structural Glazed Tile               | 2nd Floor - next to Room 215          | 905      | SF      | 7      | 10+ years   |                 |
|        | Water Closet                                 | 2nd Floor - next to Room 215          | 8        | EA      | 7      | 10+ years   |                 |
|        | Accessories                                  | 2nd Floor - next to Room 220          | 375      | SF      | 7      | 6-10 years  |                 |
|        | Ceiling - Plaster/Drywall                    | 2nd Floor - next to Room 220          | 375      | SF      | 7      | 10+ years   |                 |
|        | Floor - Tile Ceramic/ Porcelain              | 2nd Floor - next to Room 220          | 375      | SF      | 7      | 10+ years   |                 |
|        | Floor Drain                                  | 2nd Floor - next to Room 220          | 1        | ĒΑ      | 7      | 10+ years   |                 |
|        | Hand Dryer                                   | 2nd Floor - next to Room 220          | 1        | EA      | 7      | 6-10 years  |                 |
|        | Hand Dryer                                   | 2nd Floor - next to Room 220          | 1        | EA      | 5      | 0-1 year    | Out of service  |
|        | Lavatory                                     | 2nd Floor - next to Room 220          | 4        | EΑ      | 6      | 10+ years   | Cut 01 001 1100 |
|        | Lighting - Lay-in                            | 2nd Floor - next to Room 220          | 4        | EΑ      | 7      | 10+ years   |                 |
|        | Lighting - Pendent/Surface                   | 2nd Floor - next to Room 220          | 2        | EA      | 7      | 10+ years   |                 |
|        | Partitions                                   | 2nd Floor - next to Room 220          | 5        | EA      | 7      | 10+ years   |                 |
|        | Walls - Plaster/Drywall                      | 2nd Floor - next to Room 220          | 189      | SF      | 7      | 10+ years   |                 |
|        | Walls - Structural Glazed Tile               | 2nd Floor - next to Room 220          | 995      | SF      | 7      | 10+ years   |                 |
|        | Water Closet                                 | 2nd Floor - next to Room 220          | 5        | EA      | 7      | 10+ years   |                 |
|        | Accessories                                  | 2nd Floor - next to room 204          | 375      | SF      | 7      | 6-10 years  |                 |
|        | Ceiling - Plaster/Drywall                    | 2nd Floor - next to room 204          | 375      | SF      | 7      | 10+ years   |                 |
|        | Floor - Tile Ceramic/ Porcelain              | 2nd Floor - next to room 204          | 375      | SF      | 7      | 10+ years   |                 |
|        | Floor Drain                                  | 2nd Floor - next to room 204          | 1        | EA      | 7      | 10+ years   |                 |
|        | Hand Dryer                                   | 2nd Floor - next to room 204          | 2        | EA      | 7      | 6-10 years  |                 |
|        | Lavatory                                     | 2nd Floor - next to room 204          | 4        | EA      | 7      | 10+ years   |                 |
|        | Lighting - Lay-in                            | 2nd Floor - next to room 204          | 1        | EA      | 7      | 10+ years   |                 |
|        | Lighting - Lay-in Lighting - Pendent/Surface | 2nd Floor - next to room 204          | 4        | EA      | 7      | 10+ years   |                 |
|        | Partitions                                   | 2nd Floor - next to room 204          | 3        | EA      | 7      | 10+ years   |                 |
|        | Urinals                                      | 2nd Floor - next to room 204          | 3        | EA      | 7      | 10+ years   |                 |
|        | Walls - Plaster/Drywall                      | 2nd Floor - next to room 204          | 145      | SF      | 7      | 10+ years   |                 |
|        | Walls - Structural Glazed Tile               | 2nd Floor - next to room 204          | 865      | SF      | 7      | 10+ years   |                 |
|        | Water Closet                                 | 2nd Floor - next to room 204          | 3        | EA      | 7      | 10+ years   |                 |
|        | Accessories                                  | 3rd Floor Boy's Room next to room     | 375      | SF      | 7      | 6-10 years  |                 |
|        |  | 304                                   |          |         |        | •           |                 |
|        | Ceiling - Plaster/Drywall                    | 3rd Floor Boy's Room next to room 304 | 375      | SF      | 6      | 10+ years   |                 |
|        | Floor - Tile Ceramic/ Porcelain              | 3rd Floor Boy's Room next to room     | 375      | SF      | 6      | 6-10 years  |                 |



| Catego | ry : Room                       |  | Building : Main |       |       |                       |          |  |  |
|--------|---------------------------------|--|-----------------|-------|-------|-----------------------|----------|--|--|
| Group  | Item - Type                     | Location                                 | Quantity        | UOM   | Rank  | Recommend Replacement | Comments |  |  |
| Group  | item - Type                     | 304                                      | Quantity        | UOIVI | Kalik | Replacement           | Comments |  |  |
|        | Floor Drain                     | 3rd Floor Boy's Room next to room<br>304 | 1               | EA    | 7     | 10+ years             |          |  |  |
|        | Hand Dryer                      | 3rd Floor Boy's Room next to room 304    | 2               | EA    | 7     | 10+ years             |          |  |  |
|        | Lavatory                        | 3rd Floor Boy's Room next to room 304    | 4               | EA    | 7     | 10+ years             |          |  |  |
|        | Lighting - Lay-in               | 3rd Floor Boy's Room next to room 304    | 1               | EA    | 7     | 6-10 years            |          |  |  |
|        | Lighting - Pendent/Surface      | 3rd Floor Boy's Room next to room 304    | 4               | EA    | 7     | 6-10 years            |          |  |  |
|        | Partitions                      | 3rd Floor Boy's Room next to room 304    | 3               | EA    | 7     | 10+ years             |          |  |  |
|        | Urinals                         | 3rd Floor Boy's Room next to room 304    | 3               | EA    | 7     | 10+ years             |          |  |  |
|        | Walls - Plaster/Drywall         | 3rd Floor Boy's Room next to room 304    | 145             | SF    | 7     | 10+ years             |          |  |  |
|        | Walls - Structural Glazed Tile  | 3rd Floor Boy's Room next to room 304    | 865             | SF    | 7     | 10+ years             |          |  |  |
|        | Water Closet                    | 3rd Floor Boy's Room next to room 304    | 3               | EA    | 7     | 10+ years             |          |  |  |
|        | Accessories                     | 3rd Floor Girl's Room next to room 320   | 375             | SF    | 7     | 6-10 years            |          |  |  |
|        | Ceiling - Plaster/Drywall       | 3rd Floor Girl's Room next to room 320   | 375             | SF    | 7     | 10+ years             |          |  |  |
|        | Floor - Tile Ceramic/ Porcelain | 3rd Floor Girl's Room next to room 320   | 375             | SF    | 7     | 6-10 years            |          |  |  |
|        | Floor Drain                     | 3rd Floor Girl's Room next to room 320   | 1               | EA    | 7     | 10+ years             |          |  |  |
|        | Hand Dryer                      | 3rd Floor Girl's Room next to room 320   | 2               | EA    | 7     | 10+ years             |          |  |  |
|        | Lavatory                        | 3rd Floor Girl's Room next to room 320   | 4               | EA    | 7     | 10+ years             |          |  |  |
|        | Lighting - Lay-in               | 3rd Floor Girl's Room next to room 320   | 4               | EA    | 7     | 6-10 years            |          |  |  |
|        | Lighting - Pendent/Surface      | 3rd Floor Girl's Room next to room 320   | 2               | EA    | 7     | 6-10 years            |          |  |  |
|        | Partitions                      | 3rd Floor Girl's Room next to room 320   | 5               | EA    | 7     | 10+ years             |          |  |  |
|        | Walls - Plaster/Drywall         | 3rd Floor Girl's Room next to room 320   | 189             | SF    | 7     | 10+ years             |          |  |  |
|        | Walls - Structural Glazed Tile  | 3rd Floor Girl's Room next to room 320   | 995             | SF    | 7     | 10+ years             |          |  |  |
|        | Water Closet                    | 3rd Floor Girl's Room next to room       | 5               | EA    | 7     | 10+ years             |          |  |  |



| Catego | Category : Room                 |  | В        | uilding | : Main | 3711 W Douglas BOOLEVARD, Chicago, IL 60623 |               |  |
|--------|---------------------------------|--|----------|---------|--------|---|---------------|--|
|        |                                 |  | _        |         |        | Recommend                                   |               |  |
| Group  | Item - Type                     | Location                                 | Quantity | UOM     | Rank   | Replacement                                 | Comments      |  |
|        |                                 | 320                                      |          |         |        |   |               |  |
|        | Accessories                     | 3rd Floor-Staff Toilet, next to Room     | 136      | SF      | 7      | 6-10 years                                  |               |  |
|        | 0.11. D /D                      | 311                                      | 400      | 0=      | _      | 40  |               |  |
|        | Ceiling - Plaster/Drywall       | 3rd Floor-Staff Toilet, next to Room     | 136      | SF      | 7      | 10+ years                                   |               |  |
|        | Doors - Wood Doors inclu hw     | 311 3rd Floor-Staff Toilet, next to Room | 1        | EA      | 7      | 10+ years                                   |               |  |
|        | Doors - Wood Doors Inclu IIW    | 311                                      | '        | LA      | ,      | 10+ years                                   |               |  |
|        | Floor - Tile Ceramic/ Porcelain | 3rd Floor-Staff Toilet, next to Room     | 136      | SF      | 7      | 6-10 years                                  |               |  |
|        |                                 | 311                                      |          |         |        | ,   |               |  |
|        | Lavatory                        | 3rd Floor-Staff Toilet, next to Room     | 1        | EA      | 7      | 10+ years                                   |               |  |
|        |                                 | 311                                      | _        |         | _      |   |               |  |
|        | Lighting - Pendent/Surface      | 3rd Floor-Staff Toilet, next to Room     | 2        | EA      | 7      | 6-10 years                                  |               |  |
|        | Dortitions                      | 311                                      | 0        | Ε.      | 7      | 40  |               |  |
|        | Partitions                      | 3rd Floor-Staff Toilet, next to Room 311 | 2        | EA      | 7      | 10+ years                                   |               |  |
|        | Walls - Plaster/Drywall         | 3rd Floor-Staff Toilet, next to Room     | 234      | SF      | 7      | 10+ years                                   |               |  |
|        | vvalio i laotoi/Diywali         | 311                                      | 201      | O.      | •      | To Tyouro                                   |               |  |
|        | Walls - Tile Ceramic/ Porcelain | 3rd Floor-Staff Toilet, next to Room     | 234      | SF      | 7      | 10+ years                                   |               |  |
|        |                                 | 311                                      |          |         |        | ,   |               |  |
|        | Water Closet                    | 3rd Floor-Staff Toilet, next to Room     | 2        | EA      | 7      | 10+ years                                   |               |  |
|        |                                 | 311                                      |          |         |        |   |               |  |
|        | Accessories                     | Adjacent to Room 123                     | 88       | SF      | 7      | 6-10 years                                  |               |  |
|        | Ceiling - Plaster/Drywall       | Adjacent to Room 123                     | 88       | SF      | 7      | 10+ years                                   |               |  |
|        | Doors - Wood Doors inclu hw     | Adjacent to Room 123                     | 1        | EA      | 7      | 10+ years                                   |               |  |
|        | Floor - Tile Ceramic/ Porcelain | Adjacent to Room 123                     | 88       | SF      | 7      | 10+ years                                   |               |  |
|        | Floor Drain                     | Adjacent to Room 123                     | 1        | EA      | 7      | 10+ years                                   |               |  |
|        | Hand Dryer                      | Adjacent to Room 123                     | 1        | EA      | 7      | 6-10 years                                  |               |  |
|        | Lavatory                        | Adjacent to Room 123                     | 1        | EA      | 7      | 10+ years                                   |               |  |
|        | Lighting - Pendent/Surface      | Adjacent to Room 123                     | 1        | EA      | 7      | 10+ years                                   |               |  |
|        | Walls - Plaster/Drywall         | Adjacent to Room 123                     | 180      | SF      | 7      | 10+ years                                   |               |  |
|        | Walls - Tile Ceramic/ Porcelain | Adjacent to Room 123                     | 170      | SF      | 7      | 10+ years                                   |               |  |
|        | Water Closet                    | Adjacent to Room 123                     | 1        | ĒΑ      | 7      | 10+ years                                   |               |  |
|        | Accessories                     | Boiler Room                              | 69       | SF      | 7      | 6-10 years                                  |               |  |
|        | Ceiling - Plaster/Drywall       | Boiler Room                              | 69       | SF      | 6      | 10+ years                                   |               |  |
|        | Doors - Wood Doors inclu hw     | Boiler Room                              | 1        | EA      | 6      | 10+ years                                   |               |  |
|        | Floor - Concrete                | Boiler Room                              | 69       | SF      | 7      | ,   |               |  |
|        |                                 |  |          |         |        | 10+ years                                   |               |  |
|        | Lavatory                        | Boiler Room                              | 1        | EA      | 7      | 10+ years                                   |               |  |
|        | Lighting - Pendent/Surface      | Boiler Room                              | 1        | EΑ      | 7      | 10+ years                                   |               |  |
|        | Showers                         | Boiler Room                              | 1        | EA      | 7      | 10+ years                                   |               |  |
|        | Walls - Plaster/Drywall         | Boiler Room                              | 405      | SF      | 4      | 0-1 year                                    | Water damage. |  |
|        | Water Closet                    | Boiler Room                              | 1        | EA      | 7      | 10+ years                                   |               |  |
|        | Accessories                     | Restroom next to room 315D               | 160      | SF      | 7      | 6-10 years                                  |               |  |
|        | Ceiling - Plaster/Drywall       | Restroom next to room 315D               | 160      | SF      | 7      | 10+ years                                   |               |  |
|        | Doors - Wood Doors inclu hw     | Restroom next to room 315D               | 1        | EA      | 7      | 10+ years                                   |               |  |



|          | ry : Room                                  |                            | R           | uilding  | · Main  | 3711 W                   | Douglas BOULEVARD, Chicago, IL 60623 |
|----------|--|----------------------------|-------------|----------|---------|--------------------------|--------------------------------------|
| Outego   | 1    |                            |             | ananig   | . Maiii | Recommend                |                                      |
| Group    | Item - Type                                | Location                   | Quantity    | UOM      | Rank    | Replacement              | Comments                             |
| 0.00.0   | Floor - Tile Ceramic/ Porcelain            | Restroom next to room 315D | 160         | SF       | 7       | 6-10 years               |                                      |
|          | Floor Drain                                | Restroom next to room 315D | 1           | EΑ       | 7       | 10+ years                |                                      |
|          | Lavatory                                   | Restroom next to room 315D | 1           | EA       | 7       | 10+ years                |                                      |
|          | Lighting - Pendent/Surface                 | Restroom next to room 315D | 2           | EA       | 7       | 6-10 years               |                                      |
|          | Walls - Plaster/Drywall                    | Restroom next to room 315D | 485         | SF       | 7       | 10+ years                |                                      |
|          | Walls - Tile Ceramic/ Porcelain            | Restroom next to room 315D | 250         | SF       | 7       | •                        |                                      |
|          |  |                            |             |          | 7       | 10+ years                |                                      |
|          | Water Closet                               | Restroom next to room 315D | 1           | EA       | /       | 10+ years                |                                      |
| Catego   | ry : Classroom                             |                            | В           | uilding  | : Main  |                          |                                      |
| Group    | Item - Type                                | Location                   | Quantity    | UOM      | Rank    | Recommend<br>Replacement | Comments                             |
|          | om #101 (Pre School)                       | Location                   | Quantity    | 00111    | Kank    | Nopidocilicit            | - Commonto                           |
| SIGOSIO  | AC Units                                   | 1st Floor                  | 1           | EA       | 7       | 6-10 years               |                                      |
|          | Casework                                   | 1st Floor                  | 24          | LF       | 7       | 10+ years                |                                      |
|          | Ceiling - Plaster/Drywall                  | 1st Floor                  | 870         | SF       | 7       | •                        |                                      |
|          |  |                            | 9           | SF       | 7       | 10+ years                |                                      |
|          | Doors - Transom Window                     | 1st Floor                  | -           |          |         | 10+ years                |                                      |
|          | Doors - Wood Doors inclu hw                | 1st Floor                  | 1           | EA       | 7       | 10+ years                |                                      |
|          | Floor - Tile                               | 1st Floor                  | 865         | SF       | 7       | 6-10 years               |                                      |
|          | Floor - Tile                               | 1st Floor                  | 5           | SF       | 4       | 0-1 year                 | Cracked                              |
|          | Lighting - Pendent/Surface                 | 1st Floor                  | 14          | EA       | 7       | 6-10 years               |                                      |
|          | Marker Board                               | 1st Floor                  | 28          | LF       | 7       | 6-10 years               |                                      |
|          | Storage/ Closet                            | 1st Floor                  | 20          | SF       | 7       | 10+ years                |                                      |
|          | Walls - Plaster/Drywall                    | 1st Floor                  | 1,539       | SF       | 7       | 10+ years                |                                      |
| Classroo | om #102 (Pre School)                       |                            |             |          |         |                          |                                      |
|          | AC Units                                   | 1st Floor                  | 1           | EA       | 7       | 6-10 years               |                                      |
|          | Casework                                   | 1st Floor                  | 6           | LF       | 7       | 10+ years                |                                      |
|          | Ceiling - Plaster/Drywall                  | 1st Floor                  | 870         | SF       | 7       | 10+ years                |                                      |
|          | Doors - Transom Window                     | 1st Floor                  | 9           | SF       | 7       | 10+ years                |                                      |
|          | Doors - Wood Doors inclu hw                | 1st Floor                  | 1           | EA       | 7       | 10+ years                |                                      |
|          | Floor - Tile                               | 1st Floor                  | 870         | SF       | 7       | 6-10 years               |                                      |
|          | Lighting - Pendent/Surface                 | 1st Floor                  | 14          | EA       | 7       | 6-10 years               |                                      |
|          | Marker Board                               |                            | 28          | LF       | 7       | 6-10 years<br>6-10 years |                                      |
|          |  | 1st Floor                  |             |          |         | •                        |                                      |
|          | Storage/ Closet<br>Walls - Plaster/Drywall | 1st Floor                  | 20<br>1,539 | SF<br>SF | 7<br>7  | 10+ years                |                                      |
|          | walls - Plaster/Drywall                    | 1st Floor                  | 1,539       | SF       | /       | 10+ years                |                                      |
| Classroo | om #103 (Regular Classroom)                |                            |             |          |         |                          |                                      |
|          | AC Units                                   | 1st Floor                  | 2           | EA       | 7       | 6-10 years               |                                      |
|          | Ceiling - Plaster/Drywall                  | 1st Floor                  | 870         | SF       | 7       | 10+ years                |                                      |
|          | Doors - Transom Window                     | 1st Floor                  | 9           | SF       | 7       | 10+ years                |                                      |
|          | Doors - Wood Doors inclu hw                | 1st Floor                  | 1           | ĒΑ       | 7       | 10+ years                |                                      |
|          | Floor - Tile                               | 1st Floor                  | 870         | SF       | 7       | 6-10 years               |                                      |
|          | Lighting - Pendent/Surface                 | 1st Floor                  | 14          | EA       | 7       | 6-10 years               |                                      |
|          | gg   |                            | • • •       | _, .     | •       | o .o you.o               |                                      |
|          |  |                            |             |          |         |                          |                                      |

Campus Name: Herzl Page : 20 of 47 Assessment Date: 04/18/2022



| Catego    | ry : Classroom              |           | В        | uilding | : Main |             | · ·      |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
|           |                             |           |          |         |        | Recommend   |          |
| Group     | Item - Type                 | Location  | Quantity | UOM     | Rank   | Replacement | Comments |
|           | Marker Board                | 1st Floor | 40       | LF      | 7      | 6-10 years  |          |
|           | Storage/ Closet             | 1st Floor | 20       | SF      | 7      | 10+ years   |          |
|           | Walls - Plaster/Drywall     | 1st Floor | 1,539    | SF      | 7      | 10+ years   |          |
|           | Wireless System             | 1st Floor | 1        | EA      | 7      | 10+ years   |          |
| Classroo  | om #104 (Regular Classroom) |           |          |         |        |             |          |
|           | AC Units                    | 1st Floor | 1        | EA      | 7      | 6-10 years  |          |
|           | Casework                    | 1st Floor | 6        | LF      | 7      | 10+ years   |          |
|           | Ceiling - Plaster/Drywall   | 1st Floor | 870      | SF      | 7      | 10+ years   |          |
|           | Doors - Wood Doors inclu hw | 1st Floor | 2        | ĒΑ      | 7      | 10+ years   |          |
|           | Floor - Tile                | 1st Floor | 870      | SF      | 7      | 6-10 years  |          |
|           | Lighting - Pendent/Surface  | 1st Floor | 14       | ĒΑ      | 7      | 6-10 years  |          |
|           | Marker Board                | 1st Floor | 28       | LF      | 7      | 6-10 years  |          |
|           | Storage/ Closet             | 1st Floor | 20       | SF      | 7      | 10+ years   |          |
|           | Walls - Plaster/Drywall     | 1st Floor | 1,539    | SF      | 7      | 10+ years   |          |
| Classroo  | om #105 (Regular Classroom) |           |          |         |        |             |          |
|           | AC Units                    | 1st Floor | 1        | EA      | 7      | 6-10 years  |          |
|           | Casework                    | 1st Floor | 6        | LF      | 7      | 10+ years   |          |
|           | Ceiling - Plaster/Drywall   | 1st Floor | 870      | SF      | 7      | 10+ years   |          |
|           | Doors - Wood Doors inclu hw | 1st Floor | 1        | ĒΑ      | 7      | 10+ years   |          |
|           | Floor - Tile                | 1st Floor | 865      | SF      | 7      | 6-10 years  |          |
|           | Floor - Tile                | 1st Floor | 5        | SF      | 4      | 0-1 year    | Cracked  |
|           | Lighting - Pendent/Surface  | 1st Floor | 14       | EΑ      | 7      | 6-10 years  | 0.46.164 |
|           | Marker Board                | 1st Floor | 28       | LF      | 7      | 6-10 years  |          |
|           | Storage/ Closet             | 1st Floor | 20       | SF      | 7      | 10+ years   |          |
|           | Walls - Plaster/Drywall     | 1st Floor | 1,529    | SF      | 7      | 10+ years   |          |
|           | Walls - Plaster/Drywall     | 1st Floor | 10       | SF      | 5      | 0-1 year    | Cracked  |
| Classroo  | om #107 (Store Room)        |           |          |         |        |             |          |
|           | AC Units                    | 1st Floor | 1        | EA      | 7      | 6-10 years  |          |
|           | Casework                    | 1st Floor | 6        | LF      | 7      | 10+ years   |          |
|           | Ceiling - Plaster/Drywall   | 1st Floor | 870      | SF      | 7      | 10+ years   |          |
|           | Doors - Wood Doors inclu hw | 1st Floor | 1        | EA      | 7      | 10+ years   |          |
|           | Floor - Tile                | 1st Floor | 870      | SF      | 7      | 6-10 years  |          |
|           | Lighting - Pendent/Surface  | 1st Floor | 14       | EA      | 7      | 6-10 years  |          |
|           | Marker Board                | 1st Floor | 28       | LF      | 7      | 6-10 years  |          |
|           | Storage/ Closet             | 1st Floor | 20       | SF      | 7      | 10+ years   |          |
|           | Walls - Plaster/Drywall     | 1st Floor | 1,539    | SF      | 7      | 10+ years   |          |
| _Classroo | om #108 (Regular Classroom) |           |          |         |        |             |          |
|           | AC Units                    | 1st Floor | 1        | EA      | 7      | 6-10 years  |          |
|           | Casework                    | 1st Floor | 6        | LF      | 7      | 10+ years   |          |
|           | Cacomoni                    | 1001      | O        | _1      | ,      | ioi youis   |          |



| Catego    | ry : Classroom              |           | В        | uilding | : Main |             |              |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|--------------|
| _         |                             |           |          | _       |        | Recommend   |              |
| Group     | Item - Type                 | Location  | Quantity | UOM     | Rank   | Replacement | Comments     |
|           | Ceiling - Plaster/Drywall   | 1st Floor | 870      | SF      | 7      | 10+ years   |              |
|           | Doors - Wood Doors inclu hw | 1st Floor | 1        | EA      | 7      | 10+ years   |              |
|           | Floor - Tile                | 1st Floor | 870      | SF      | 7      | 6-10 years  |              |
|           | Lighting - Pendent/Surface  | 1st Floor | 14       | EA      | 7      | 6-10 years  |              |
|           | Marker Board                | 1st Floor | 28       | LF      | 7      | 6-10 years  |              |
|           | Storage/ Closet             | 1st Floor | 20       | SF      | 7      | 10+ years   |              |
|           | Walls - Plaster/Drywall     | 1st Floor | 1,539    | SF      | 7      | 10+ years   |              |
| Classroo  | ım #115 (Regular Classroom) |           |          |         |        |             |              |
|           | AC Units                    | 1st Floor | 1        | EA      | 7      | 6-10 years  |              |
|           | Ceiling - Plaster/Drywall   | 1st Floor | 870      | SF      | 7      | 10+ years   |              |
|           | Doors - Transom Window      | 1st Floor | 8        | SF      | 7      | 10+ years   |              |
|           | Doors - Wood Doors inclu hw | 1st Floor | 1        | EA      | 7      | 10+ years   |              |
|           | Floor - Tile                | 1st Floor | 870      | SF      | 7      | 6-10 years  |              |
|           | Lighting - Pendent/Surface  | 1st Floor | 14       | EA      | 7      | 6-10 years  |              |
|           | Marker Board                | 1st Floor | 28       | LF      | 7      | 6-10 years  |              |
|           | Walls - Plaster/Drywall     | 1st Floor | 1,539    | SF      | 7      | 10+ years   |              |
|           | Work Sink                   | 1st Floor | 1        | EA      | 7      | 10+ years   |              |
| _Classroo | m #116 (Store Room)         |           |          |         |        |             |              |
|           | AC Units                    | 1st Floor | 2        | EA      | 7      | 6-10 years  |              |
|           | Ceiling - Plaster/Drywall   | 1st Floor | 1,039    | SF      | 7      | 10+ years   |              |
|           | Doors - Wood Doors inclu hw | 1st Floor | 1        | ĒΑ      | 7      | 10+ years   |              |
|           | Floor - Tile                | 1st Floor | 1,039    | SF      | 7      | 6-10 years  |              |
|           | Lighting - Pendent/Surface  | 1st Floor | . 14     | EΑ      | 7      | 6-10 years  |              |
|           | Marker Board                | 1st Floor | 28       | LF      | 7      | 6-10 years  |              |
|           | Walls - Plaster/Drywall     | 1st Floor | 1,509    | SF      | 7      | 10+ years   |              |
|           | Walls - Plaster/Drywall     | 1st Floor | 30       | SF      | 5      | 0-1 year    | Water damage |
| _Classroc | m #120 (Regular Classroom)  |           |          |         |        |             |              |
|           | AC Units                    | 1st Floor | 1        | EA      | 7      | 6-10 years  |              |
|           | Casework                    | 1st Floor | 6        | LF      | 7      | 10+ years   |              |
|           | Ceiling - Plaster/Drywall   | 1st Floor | 871      | SF      | 7      | 10+ years   |              |
|           | Doors - Wood Doors inclu hw | 1st Floor | 1        | EA      | 7      | 10+ years   |              |
|           | Floor - Tile                | 1st Floor | 871      | SF      | 6      | 6-10 years  |              |
|           | Lighting - Pendent/Surface  | 1st Floor | 14       | EA      | 7      | 6-10 years  |              |
|           | Marker Board                | 1st Floor | 40       | LF      | 7      | 6-10 years  |              |
|           | Storage/ Closet             | 1st Floor | 20       | SF      | 7      | 10+ years   |              |
|           | Walls - Plaster/Drywall     | 1st Floor | 1,357    | SF      | 7      | 10+ years   |              |
| _Classroo | m #121 (Regular Classroom)  |           |          |         |        |             |              |
|           | AC Units                    | 1st Floor | 1        | EA      | 7      | 6-10 years  |              |
|           | Casework                    | 1st Floor | 6        | LF      | 7      | 10+ years   |              |
|           | 223                         | 1001      | O .      |         | •      | .o. youro   |              |



| Catego    | Category : Classroom                               |           | В                                     | uilding  | : Main | 1                     |                 |  |
|-----------|--|-----------|---------------------------------------|----------|--------|-----------------------|-----------------|--|
|           |  |           |                                       | Ĭ        |        | Recommend             |                 |  |
| Group     | Item - Type  | Location  | Quantity                              | UOM      | Rank   | Replacement           | Comments        |  |
| -         | Ceiling - Plaster/Drywall                          | 1st Floor | 871                                   | SF       | 7      | 10+ years             |                 |  |
|           | Doors - Transom Window                             | 1st Floor | 9                                     | SF       | 7      | 10+ years             |                 |  |
|           | Doors - Wood Doors inclu hw                        | 1st Floor | 2                                     | ĒΑ       | 7      | 10+ years             |                 |  |
|           | Floor - Tile                                       | 1st Floor | 871                                   | SF       | 6      | 6-10 years            |                 |  |
|           | Lighting - Pendent/Surface                         | 1st Floor | 14                                    | EA       | 7      | 6-10 years            |                 |  |
|           | Marker Board                                       | 1st Floor | 40                                    | LF       | 7      | 6-10 years            |                 |  |
|           | Storage/ Closet                                    | 1st Floor | 20                                    | SF       | 7      | 10+ years             |                 |  |
|           | Walls - Plaster/Drywall                            | 1st Floor | 1,357                                 | SF       | 7      | 10+ years             |                 |  |
| Classroo  | om #122 (Store Room)                               |           |                                       |          |        |                       |                 |  |
| Cidoorox  | AC Units   | 1st Floor | 1                                     | EA       | 7      | 6-10 years            |                 |  |
|           | Casework   | 1st Floor | 18                                    | LF       | 7      | 10+ years             |                 |  |
|           | Casework Ceiling - Plaster/Drywall                 | 1st Floor | 871                                   | SF       | 7      | 10+ years             |                 |  |
|           | Doors - Transom Window                             | 1st Floor | 9                                     | SF       | 7      | 10+ years             |                 |  |
|           |  | 1st Floor | 1                                     | EA       | 7      | -                     |                 |  |
|           | Doors - Wood Doors inclu hw                        |           | · · · · · · · · · · · · · · · · · · · | SF       |        | 10+ years             |                 |  |
|           | Floor - Tile                                       | 1st Floor | 871                                   |          | 7      | 6-10 years            |                 |  |
|           | Lighting - Pendent/Surface                         | 1st Floor | 14                                    | EA       | 7      | 6-10 years            |                 |  |
|           | Marker Board                                       | 1st Floor | 26                                    | LF       | 7      | 6-10 years            |                 |  |
|           | Storage/ Closet                                    | 1st Floor | 20                                    | SF       | 7      | 10+ years             |                 |  |
|           | Walls - Plaster/Drywall                            | 1st Floor | 1,357                                 | SF       | 7      | 10+ years             |                 |  |
| Classroo  | om #123 (Regular Classroom)                        |           |                                       |          |        |                       |                 |  |
|           | AC Units   | 1st Floor | 1                                     | EA       | 7      | 6-10 years            |                 |  |
|           | AC Units   | 1st Floor | 1                                     | EA       | 4      | 0-1 year              | Out of service  |  |
|           | Ceiling - Plaster/Drywall                          | 1st Floor | 871                                   | SF       | 7      | 10+ years             |                 |  |
|           | Doors - Wood Doors inclu hw                        | 1st Floor | 1                                     | EA       | 7      | 10+ years             |                 |  |
|           | Floor - Tile                                       | 1st Floor | 871                                   | SF       | 7      | 6-10 years            |                 |  |
|           | Lighting - Pendent/Surface                         | 1st Floor | 14                                    | EA       | 7      | 6-10 years            |                 |  |
|           | Marker Board                                       | 1st Floor | 20                                    | LF       | 7      | 6-10 years            |                 |  |
|           | Storage/ Closet                                    | 1st Floor | 20                                    | SF       | 7      | 10+ years             |                 |  |
|           | Walls - Plaster/Drywall                            | 1st Floor | 1,357                                 | SF       | 7      | 10+ years             |                 |  |
|           | Work Sink  | 1st Floor | 1                                     | EA       | 7      | 10+ years             |                 |  |
| _Classroo | om #149 (Regular Classroom)                        |           |                                       |          |        |                       |                 |  |
|           | AC Units   | 1st Floor | 1                                     | EA       | 7      | 6-10 years            |                 |  |
|           | Ceiling - Exposed                                  | 1st Floor | 655                                   | SF       | 7      | 10+ years             |                 |  |
|           | Doors - Transom Window                             | 1st Floor | 9                                     | SF       | 7      | 10+ years             |                 |  |
|           | Doors - Wood Doors inclu hw                        | 1st Floor | 1                                     | EA       | 7      | 10+ years             |                 |  |
|           | Floor - Tile                                       | 1st Floor | 655                                   | SF       | 7      | 6-10 years            |                 |  |
|           | Lighting - Pendent/Surface                         | 1st Floor | 10                                    | EA       | 7      | 6-10 years            |                 |  |
|           | Marker Board                                       | 1st Floor | 24                                    | LF       | 7      | 6-10 years            |                 |  |
|           |  | 1st Floor |                                       | SF       |        |                       |                 |  |
|           | Walls - Plaster/Drywall<br>Walls - Plaster/Drywall | 1st Floor | 1,335<br>40                           | SF<br>SF | 7<br>4 | 10+ years<br>0-1 year | Peeling/damaged |  |
|           |  |           |                                       |          |        |                       |                 |  |



| Catego      | ry : Classroom              |                        | В        | uilding | : Main |             |          |
|-------------|-----------------------------|------------------------|----------|---------|--------|-------------|----------|
|             | <del></del>                 |                        | 0        |         |        | Recommend   | •        |
| Group       | Item - Type                 | Location               | Quantity | UOM     | Rank   | Replacement | Comments |
| Classroo    | om #201 (Regular Classroom) |                        |          |         |        |             |          |
| _ CIGOOI OX | AC Units                    | 2nd Floor              | 1        | EA      | 7      | 6-10 years  |          |
|             | Casework                    | 2nd Floor              | 6        | LF      | 7      | 10+ years   |          |
|             | Ceiling - Plaster/Drywall   | 2nd Floor              | 795      | SF      | 7      | 10+ years   |          |
|             | Doors - Transom Window      | 2nd Floor              | 9        | SF      | 7      | 10+ years   |          |
|             | Doors - Wood Doors inclu hw |                        | 1        | EA      | 7      | •           |          |
|             |                             | 2nd Floor              |          |         |        | 10+ years   |          |
|             | Floor - Tile                | 2nd Floor              | 795      | SF      | 7      | 10+ years   |          |
|             | Lighting - Pendent/Surface  | 2nd Floor              | 14       | EA      | 7      | 10+ years   |          |
|             | Marker Board                | 2nd Floor              | 34       | LF      | 7      | 6-10 years  |          |
|             | Walls - Plaster/Drywall     | 2nd Floor              | 1,455    | SF      | 7      | 10+ years   |          |
| Classroo    | om #202 (Regular Classroom) |                        |          |         |        |             |          |
|             | AC Units                    | 2nd Floor              | 1        | EA      | 7      | 6-10 years  |          |
|             | Ceiling - Plaster/Drywall   | 2nd Floor              | 795      | SF      | 7      | 10+ years   |          |
|             | Doors - Transom Window      | 2nd Floor              | 9        | SF      | 7      | 10+ years   |          |
|             | Doors - Wood Doors inclu hw | 2nd Floor              | 1        | EA      | 7      | 10+ years   |          |
|             | Floor - Tile                | 2nd Floor              | 795      | SF      | 7      | 10+ years   |          |
|             | Lighting - Pendent/Surface  | 2nd Floor              | 14       | EA      | 7      | 10+ years   |          |
|             | Marker Board                | 2nd Floor              | 18       | LF      | 7      | •           |          |
|             |                             |                        |          | SF      |        | 6-10 years  |          |
|             | Walls - Plaster/Drywall     | 2nd Floor              | 1,430    | SF      | 7      | 10+ years   |          |
| Classroo    | om #203 (Science)           |                        |          |         |        |             |          |
|             | AC Units                    | 2nd Floor              | 1        | EA      | 7      | 6-10 years  |          |
|             | Casework                    | 2nd Floor              | 40       | LF      | 7      | 10+ years   |          |
|             | Ceiling - Plaster/Drywall   | 2nd Floor              | 795      | SF      | 7      | 10+ years   |          |
|             | Doors - Transom Window      | 2nd Floor              | 9        | SF      | 7      | 10+ years   |          |
|             | Doors - Wood Doors inclu hw | 2nd Floor              | 1        | ĒΑ      | 7      | 10+ years   |          |
|             | Floor - Tile                | 2nd Floor              | 795      | SF      | 7      | 10+ years   |          |
|             | Lighting - Pendent/Surface  | 2nd Floor              | 14       | EA      | 7      | 10+ years   |          |
|             | Marker Board                | 2nd Floor              | 20       | LF      | 7      | 6-10 years  |          |
|             | Walls - Plaster/Drywall     | 2nd Floor              | 1,430    | SF      | 7      | 10+ years   |          |
|             | Work Sink                   | 2nd Floor<br>2nd Floor | 1,430    | EA      | 7      | ,           |          |
|             | Work Silik                  | 211d F1001             | ა        | EA      | ,      | 10+ years   |          |
| Classroo    | om #204 (Regular Classroom) |                        |          |         |        |             |          |
|             | AC Units                    | 2nd Floor              | 1        | EA      | 7      | 6-10 years  |          |
|             | Casework                    | 2nd Floor              | 6        | LF      | 7      | 10+ years   |          |
|             | Ceiling - Plaster/Drywall   | 2nd Floor              | 795      | SF      | 7      | 10+ years   |          |
|             | Doors - Transom Window      | 2nd Floor              | 9        | SF      | 7      | 10+ years   |          |
|             | Doors - Wood Doors inclu hw | 2nd Floor              | 1        | ĒΑ      | 6      | 10+ years   |          |
|             | Floor - Tile                | 2nd Floor              | 795      | SF      | 6      | 10+ years   |          |
|             | Lighting - Pendent/Surface  | 2nd Floor              | 14       | EA      | 7      | 10+ years   |          |
|             | Marker Board                | 2nd Floor              | 34       | LF      | 7      | 6-10 years  |          |
|             | Marker Dualu                | 2110 1 1001            | 34       | LF      | ,      | 0-10 years  |          |
|             |                             |                        |          |         |        |             |          |



| Catego    | ry : Classroom              |           | В        | uilding | : Main |             |          |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
|           |                             |           |          |         |        | Recommend   |          |
| Group     | Item - Type                 | Location  | Quantity | UOM     | Rank   | Replacement | Comments |
|           | Walls - Plaster/Drywall     | 2nd Floor | 1,430    | SF      | 7      | 10+ years   |          |
|           | Work Sink                   | 2nd Floor | 1        | EA      | 7      | 10+ years   |          |
| Classroc  | om #205 (Regular Classroom) |           |          |         |        |             |          |
|           | AC Units                    | 2nd Floor | 1        | EA      | 7      | 6-10 years  |          |
|           | Casework                    | 2nd Floor | 6        | LF      | 7      | 10+ years   |          |
|           | Ceiling - Plaster/Drywall   | 2nd Floor | 795      | SF      | 7      | 10+ years   |          |
|           | Doors - Transom Window      | 2nd Floor | 9        | SF      | 7      | 10+ years   |          |
|           | Doors - Wood Doors inclu hw | 2nd Floor | 1        | EA      | 7      | 10+ years   |          |
|           | Floor - Tile                | 2nd Floor | 795      | SF      | 6      | 10+ years   |          |
|           | Lighting - Pendent/Surface  | 2nd Floor | 14       | EA      | 7      | 10+ years   |          |
|           | Marker Board                | 2nd Floor | 34       | LF      | 7      | 6-10 years  |          |
|           | Walls - Plaster/Drywall     | 2nd Floor | 1,430    | SF      | 7      | 10+ years   |          |
| Classroc  | om #206 (Regular Classroom) |           |          |         |        |             |          |
|           | AC Units                    | 2nd Floor | 1        | EA      | 7      | 6-10 years  |          |
|           | Casework                    | 2nd Floor | 6        | LF      | 7      | 10+ years   |          |
|           | Ceiling - Plaster/Drywall   | 2nd Floor | 795      | SF      | 7      | 10+ years   |          |
|           | Doors - Transom Window      | 2nd Floor | 9        | SF      | 7      | 10+ years   |          |
|           | Doors - Wood Doors inclu hw | 2nd Floor | 1        | EA      | 7      | 10+ years   |          |
|           | Floor - Tile                | 2nd Floor | 795      | SF      | 7      | 10+ years   |          |
|           | Lighting - Pendent/Surface  | 2nd Floor | 14       | EA      | 7      | 10+ years   |          |
|           | Marker Board                | 2nd Floor | 26       | LF      | 7      | 6-10 years  |          |
|           | Walls - Plaster/Drywall     | 2nd Floor | 1,455    | SF      | 7      | 10+ years   |          |
| Classroc  | om #207 (Regular Classroom) |           |          |         |        |             |          |
|           | AC Units                    | 2nd Floor | 1        | EA      | 7      | 6-10 years  |          |
|           | Ceiling - Plaster/Drywall   | 2nd Floor | 915      | SF      | 7      | 10+ years   |          |
|           | Doors - Transom Window      | 2nd Floor | 9        | SF      | 7      | 10+ years   |          |
|           | Doors - Wood Doors inclu hw | 2nd Floor | 1        | EA      | 7      | 10+ years   |          |
|           | Floor - Tile                | 2nd Floor | 915      | SF      | 7      | 10+ years   |          |
|           | Lighting - Pendent/Surface  | 2nd Floor | 14       | EA      | 7      | 10+ years   |          |
|           | Marker Board                | 2nd Floor | 36       | LF      | 7      | 6-10 years  |          |
|           | Walls - Plaster/Drywall     | 2nd Floor | 1,570    | SF      | 7      | 10+ years   |          |
| _Classroc | om #208 (Regular Classroom) |           |          |         |        |             |          |
|           | AC Units                    | 2nd Floor | 1        | EA      | 7      | 6-10 years  |          |
|           | Ceiling - Plaster/Drywall   | 2nd Floor | 915      | SF      | 7      | 10+ years   |          |
|           | Doors - Transom Window      | 2nd Floor | 9        | SF      | 7      | 10+ years   |          |
|           | Doors - Wood Doors inclu hw | 2nd Floor | 1        | EA      | 7      | 10+ years   |          |
|           | Floor - Tile                | 2nd Floor | 912      | SF      | 7      | 10+ years   |          |
|           | Floor - Tile                | 2nd Floor | 3        | SF      | 4      | 0-1 year    | Cracked  |
|           | Lighting - Pendent/Surface  | 2nd Floor | 14       | EA      | 7      | 10+ years   | Ordoned  |
|           |                             | ZHU FIUUI | 14       | ĽA      | ,      | IUT VEAIS   |          |



| Catego   | ry : Classroom                     |           | В        | uilding  | : Main |             |           |
|----------|------------------------------------|-----------|----------|----------|--------|-------------|-----------|
|          |                                    |           |          |          |        | Recommend   |           |
| Group    | Item - Type                        | Location  | Quantity | UOM      | Rank   | Replacement | Comments  |
|          | Marker Board                       | 2nd Floor | 36       | LF       | 7      | 6-10 years  |           |
|          | Walls - Plaster/Drywall            | 2nd Floor | 1,560    | SF       | 7      | 10+ years   |           |
|          | Walls - Plaster/Drywall            | 2nd Floor | 10       | SF       | 5      | 0-1 year    | Cracked   |
| Classroo | m #209 (Regular Classroom)         |           |          |          |        |             |           |
|          | AC Units                           | 2nd Floor | 1        | EA       | 7      | 6-10 years  |           |
|          | Ceiling - Plaster/Drywall          | 2nd Floor | 915      | SF       | 7      | 10+ years   |           |
|          | Doors - Transom Window             | 2nd Floor | 9        | SF       | 7      | 10+ years   |           |
|          | Doors - Wood Doors inclu hw        | 2nd Floor | 1        | ĒA       | 7      | 10+ years   |           |
|          | Floor - Tile                       | 2nd Floor | 915      | SF       | 6      | 10+ years   |           |
|          | Lighting - Pendent/Surface         | 2nd Floor | 14       | ĒA       | 7      | 10+ years   |           |
|          | Marker Board                       | 2nd Floor | 36       | LF       | 7      | 6-10 years  |           |
|          | Walls - Plaster/Drywall            | 2nd Floor | 1,570    | SF       | 7      | 10+ years   |           |
| Classroo | m #210 (Regular Classroom)         |           |          |          |        |             |           |
|          | AC Units                           | 2nd Floor | 1        | EA       | 7      | 6-10 years  |           |
|          | Ceiling - Plaster/Drywall          | 2nd Floor | 915      | SF       | 7      | 10+ years   |           |
|          | Doors - Transom Window             | 2nd Floor | 9        | SF       | 7      | 10+ years   |           |
|          | Doors - Wood Doors inclu hw        | 2nd Floor | 1        | EA       | 7      | 10+ years   |           |
|          | Floor - Tile                       | 2nd Floor | 915      | SF       | 6      | 10+ years   |           |
|          | Lighting - Pendent/Surface         | 2nd Floor | 14       | EA       | 7      | 10+ years   |           |
|          | Marker Board                       | 2nd Floor | 36       | LF       | 7      | 6-10 years  |           |
|          | Walls - Plaster/Drywall            | 2nd Floor | 1,568    | SF       | 7      | 10+ years   |           |
|          | Walls - Plaster/Drywall            | 2nd Floor | 2        | SF       | 6      | 10+ years   |           |
| Classroo | m #211 (Regular Classroom)         |           |          |          |        |             |           |
| JIUSSIOC | AC Units                           | 2nd Floor | 1        | EA       | 7      | 6-10 years  |           |
|          | Casework                           | 2nd Floor | 20       | LF       | 7      | 10+ years   |           |
|          | Casework Ceiling - Plaster/Drywall | 2nd Floor | 915      | SF       | 7      | 10+ years   |           |
|          | Doors - Transom Window             | 2nd Floor | 913      | SF       | 7      | •           |           |
|          |                                    |           | 1        | SF<br>EA | 7      | 10+ years   |           |
|          | Doors - Wood Doors inclu hw        | 2nd Floor | •        |          | 7      | 10+ years   |           |
|          | Floor - Tile                       | 2nd Floor | 915      | SF       |        | 10+ years   |           |
|          | Lighting - Pendent/Surface         | 2nd Floor | 14       | EA       | 7      | 10+ years   |           |
|          | Marker Board                       | 2nd Floor | 18       | LF       | 7      | 6-10 years  |           |
|          | Walls - Plaster/Drywall            | 2nd Floor | 1,540    | SF       | 7      | 10+ years   |           |
| Classroo | m #212 (Regular Classroom)         | 0.15      |          |          |        | 0.40        |           |
|          | AC Units                           | 2nd Floor | 1        | EA       | 7      | 6-10 years  |           |
|          | Casework                           | 2nd Floor | 12       | LF       | 7      | 10+ years   |           |
|          | Ceiling - Plaster/Drywall          | 2nd Floor | 910      | SF       | 7      | 10+ years   |           |
|          | Ceiling - Plaster/Drywall          | 2nd Floor | 5        | SF       | 5      | 0-1 year    | Cracking. |
|          | Doors - Transom Window             | 2nd Floor | 9        | SF       | 7      | 10+ years   |           |
|          | Doors - Wood Doors inclu hw        | 2nd Floor | 1        | EA       | 7      | 10+ years   |           |



| Category : Classroom |                                   | Building : Main |          |     |      |             |                            |
|----------------------|-----------------------------------|-----------------|----------|-----|------|-------------|----------------------------|
|                      |                                   |                 |          |     |      | Recommend   |                            |
| Group                | Item - Type                       | Location        | Quantity | UOM | Rank | Replacement | Comments                   |
|                      | Floor - Tile                      | 2nd Floor       | 915      | SF  | 6    | 10+ years   |                            |
|                      | Lighting - Pendent/Surface        | 2nd Floor       | 14       | EA  | 7    | 10+ years   |                            |
|                      | Marker Board                      | 2nd Floor       | 30       | LF  | 7    | 6-10 years  |                            |
|                      | Walls - Plaster/Drywall           | 2nd Floor       | 1,540    | SF  | 7    | 10+ years   |                            |
| Classroo             | m #213 (Regular Classroom)        |                 |          |     |      |             |                            |
|                      | AC Units                          | 2nd Floor       | 1        | EΑ  | 7    | 6-10 years  |                            |
|                      | Casework                          | 2nd Floor       | 6        | LF  | 7    | 10+ years   |                            |
|                      | Ceiling - Plaster/Drywall         | 2nd Floor       | 905      | SF  | 7    | 10+ years   |                            |
|                      | Ceiling - Plaster/Drywall         | 2nd Floor       | 10       | SF  | 6    | 10+ years   |                            |
|                      | Doors - Transom Window            | 2nd Floor       | 10       | SF  | 7    | 10+ years   |                            |
|                      | Doors - Wood Doors inclu hw       | 2nd Floor       | 1        | ĒA  | 7    | 10+ years   |                            |
|                      | Floor - Tile                      | 2nd Floor       | 915      | SF  | 7    | 10+ years   |                            |
|                      | Lighting - Pendent/Surface        | 2nd Floor       | 14       | EA  | 7    | 10+ years   |                            |
|                      | Marker Board                      | 2nd Floor       | 36       | LF  | 7    | 6-10 years  |                            |
|                      | Walls - Plaster/Drywall           | 2nd Floor       | 1,540    | SF  | 7    | 10+ years   |                            |
|                      | Walls - Flastel/Drywall           | 2110 1 1001     | 1,540    | Oi  | ,    | 10+ years   |                            |
| Classroo             | m #214 (Regular Classroom)        |                 |          |     |      |             |                            |
|                      | AC Units                          | 2nd Floor       | 1        | EA  | 7    | 6-10 years  |                            |
|                      | Casework                          | 2nd Floor       | 12       | LF  | 7    | 10+ years   |                            |
|                      | Ceiling - Plaster/Drywall         | 2nd Floor       | 830      | SF  | 7    | 10+ years   |                            |
|                      | Doors - Transom Window            | 2nd Floor       | 18       | SF  | 7    | 10+ years   |                            |
|                      | Doors - Wood Doors inclu hw       | 2nd Floor       | 2        | EA  | 7    | 10+ years   |                            |
|                      | Floor - Tile                      | 2nd Floor       | 830      | SF  | 7    | 10+ years   |                            |
|                      | Lighting - Pendent/Surface        | 2nd Floor       | 14       | EA  | 7    | 10+ years   |                            |
|                      | Marker Board                      | 2nd Floor       | 18       | LF  | 7    | 6-10 years  |                            |
|                      | Walls - Plaster/Drywall           | 2nd Floor       | 1,410    | SF  | 7    | 10+ years   |                            |
| Classroo             | m #215 (Regular Classroom)        |                 |          |     |      |             |                            |
|                      | AC Units                          | 2nd Floor       | 1        | EA  | 7    | 6-10 years  |                            |
|                      | Ceiling - Plaster/Drywall         | 2nd Floor       | 780      | SF  | 7    | 10+ years   |                            |
|                      | Doors - Transom Window            | 2nd Floor       | 9        | SF  | 7    | 10+ years   |                            |
|                      | Doors - Wood Doors inclu hw       | 2nd Floor       | 1        | EA  | 7    | 10+ years   |                            |
|                      | Floor - Tile                      | 2nd Floor       | 772      | SF  | 7    | 10+ years   |                            |
|                      | Floor - Tile                      | 2nd Floor       | 8        | SF  | 4    | 0-1 year    | Chipped                    |
|                      |                                   |                 |          | EA  |      | •           | Спіррец                    |
|                      | Lighting - Lay-in<br>Marker Board | 2nd Floor       | 14       |     | 7    | 10+ years   |                            |
|                      |                                   | 2nd Floor       | 40       | LF  | 7    | 6-10 years  |                            |
|                      | Walls - Plaster/Drywall           | 2nd Floor       | 1,420    | SF  | 7    | 10+ years   |                            |
|                      | Wireless System                   | 2nd Floor       | 1        | EA  | 7    | 10+ years   |                            |
| Classroo             | m #216 (Regular Classroom)        |                 |          |     |      |             |                            |
|                      | AC Units                          | 2nd Floor       | 2        | EA  | 7    | 6-10 years  |                            |
|                      | Ceiling - Plaster/Drywall         | 2nd Floor       | 870      | SF  | 7    | 10+ years   | Changed due to observation |



| Catego    | Category : Classroom        |             | В        | uilding | : Main |             |               |  |
|-----------|-----------------------------|-------------|----------|---------|--------|-------------|---------------|--|
|           |                             |             |          |         |        | Recommend   |               |  |
| Group     | Item - Type                 | Location    | Quantity | UOM     | Rank   | Replacement | Comments      |  |
|           | Doors - Transom Window      | 2nd Floor   | 9        | SF      | 7      | 10+ years   |               |  |
|           | Doors - Wood Doors inclu hw | 2nd Floor   | 1        | EA      | 7      | 10+ years   |               |  |
|           | Floor - Tile                | 2nd Floor   | 870      | SF      | 7      | 10+ years   |               |  |
|           | Lighting - Pendent/Surface  | 2nd Floor   | 5        | EA      | 7      | 10+ years   |               |  |
|           | Marker Board                | 2nd Floor   | 8        | LF      | 7      | 6-10 years  |               |  |
|           | Walls - Plaster/Drywall     | 2nd Floor   | 1,208    | SF      | 7      | 10+ years   |               |  |
|           | Walls - Plaster/Drywall     | 2nd Floor   | 10       | SF      | 5      | 0-1 year    | Water damage. |  |
| _Classroo | om #218 (Regular Classroom) |             |          |         |        |             |               |  |
|           | AC Units                    | 2nd Floor   | 1        | EA      | 7      | 6-10 years  |               |  |
|           | Casework                    | 2nd Floor   | 6        | LF      | 7      | 10+ years   |               |  |
|           | Ceiling - Plaster/Drywall   | 2nd Floor   | 795      | SF      | 7      | 10+ years   |               |  |
|           | Doors - Transom Window      | 2nd Floor   | 9        | SF      | 7      | 10+ years   |               |  |
|           | Doors - Wood Doors inclu hw | 2nd Floor   | 1        | EA      | 7      | 10+ years   |               |  |
|           | Floor - Tile                | 2nd Floor   | 795      | SF      | 7      | 10+ years   |               |  |
|           | Lighting - Pendent/Surface  | 2nd Floor   | 14       | EA      | 7      | 10+ years   |               |  |
|           | Marker Board                | 2nd Floor   | 38       | LF      | 7      | 6-10 years  |               |  |
|           | Walls - Plaster/Drywall     | 2nd Floor   | 1,455    | SF      | 7      | 10+ years   |               |  |
| Classroo  | om #219 (Regular Classroom) |             |          |         |        |             |               |  |
|           | AC Units                    | 2nd Floor   | 1        | EA      | 7      | 6-10 years  |               |  |
|           | Casework                    | 2nd Floor   | 6        | LF      | 7      | 10+ years   |               |  |
|           | Ceiling - Plaster/Drywall   | 2nd Floor   | 795      | SF      | 7      | 10+ years   |               |  |
|           | Doors - Transom Window      | 2nd Floor   | 9        | SF      | 7      | 10+ years   |               |  |
|           | Doors - Wood Doors inclu hw | 2nd Floor   | 1        | EA      | 7      | 10+ years   |               |  |
|           | Floor - Tile                | 2nd Floor   | 791      | SF      | 6      | 10+ years   |               |  |
|           | Floor - Tile                | 2nd Floor   | 4        | SF      | 4      | 0-1 year    | Chipped       |  |
|           | Lighting - Pendent/Surface  | 2nd Floor   | 14       | EA      | 7      | 10+ years   |               |  |
|           | Marker Board                | 2nd Floor   | 34       | LF      | 7      | 6-10 years  |               |  |
|           | Walls - Plaster/Drywall     | 2nd Floor   | 1,430    | SF      | 7      | 10+ years   |               |  |
| Classroo  | om #220 (Regular Classroom) |             |          |         |        |             |               |  |
|           | AC Units                    | 2nd Floor   | 1        | EA      | 7      | 6-10 years  |               |  |
|           | Casework                    | 2nd Floor   | 6        | LF      | 7      | 10+ years   |               |  |
|           | Ceiling - Plaster/Drywall   | 2nd Floor   | 795      | SF      | 7      | 10+ years   |               |  |
|           | Doors - Transom Window      | 2nd Floor   | 9        | SF      | 7      | 10+ years   |               |  |
|           | Doors - Wood Doors inclu hw | 2nd Floor   | 1        | ĒΑ      | 7      | 10+ years   |               |  |
|           | Floor - Tile                | 2nd Floor   | 795      | SF      | 7      | 10+ years   |               |  |
|           | Lighting - Pendent/Surface  | 2nd Floor   | 14       | EΑ      | 7      | 10+ years   |               |  |
|           | Marker Board                | 2nd Floor   | 20       | LF      | 7      | 6-10 years  |               |  |
|           | Walls - Plaster/Drywall     | 2nd Floor   | 1,426    | SF      | 7      | 10+ years   |               |  |
|           | Walls - Plaster/Drywall     | 2nd Floor   | 4        | SF      | 6      | 10+ years   |               |  |
|           |                             | 2.13 . 100. | •        | Ο.      | Ŭ      | ,           |               |  |



| Category : Classroom |                             | R         | uilding  | · Main | 3711 00   | Douglas BOULEVARD, Chicago, IL 60623 |          |
|----------------------|-----------------------------|-----------|----------|--------|-----------|--------------------------------------|----------|
| Jaiegu               | ı y . Olassi Oolii          |           | В        | unung  | . Iviaiii | Recommend                            |          |
| Group                | Item - Type                 | Location  | Quantity | UOM    | Rank      | Replacement                          | Comments |
|                      | om #221 (Regular Classroom) | <b></b>   | Quality  | •      | rtann     | rtopiacomont                         |          |
| Ciassion             | AC Units                    | 2nd Floor | 1        | EA     | 7         | 6-10 years                           |          |
|                      | Casework                    | 2nd Floor | 6        | LF     | 7         | 10+ years                            |          |
|                      | Ceiling - Plaster/Drywall   | 2nd Floor | 795      | SF     | 7         | 10+ years                            |          |
|                      | Doors - Transom Window      | 2nd Floor | 9        | SF     | 7         | 10+ years                            |          |
|                      | Doors - Wood Doors inclu hw | 2nd Floor | 1        | EA     | 7         | 10+ years                            |          |
|                      | Floor - Tile                | 2nd Floor | 795      | SF     | 7         | 10+ years                            |          |
|                      | Lighting - Pendent/Surface  | 2nd Floor | 14       | EA     | 7         | 10+ years                            |          |
|                      | Marker Board                | 2nd Floor | 34       | LF     | 7         | 6-10 years                           |          |
|                      | Walls - Plaster/Drywall     | 2nd Floor | 1,430    | SF     | 7         | 10+ years                            |          |
| Classroo             | om #222 (Regular Classroom) |           |          |        |           |                                      |          |
|                      | AC Units                    | 2nd Floor | 1        | EA     | 7         | 6-10 years                           |          |
|                      | Casework                    | 2nd Floor | 6        | LF     | 7         | 10+ years                            |          |
|                      | Ceiling - Plaster/Drywall   | 2nd Floor | 795      | SF     | 7         | 10+ years                            |          |
|                      | Doors - Transom Window      | 2nd Floor | 9        | SF     | 7         | 10+ years                            |          |
|                      | Doors - Wood Doors inclu hw | 2nd Floor | 1        | ĒΑ     | 7         | 10+ years                            |          |
|                      | Floor - Tile                | 2nd Floor | 795      | SF     | 6         | 10+ years                            |          |
|                      | Lighting - Pendent/Surface  | 2nd Floor | 14       | ĒΑ     | 7         | 10+ years                            |          |
|                      | Marker Board                | 2nd Floor | 36       | LF     | 7         | 6-10 years                           |          |
|                      | Walls - Plaster/Drywall     | 2nd Floor | 1,430    | SF     | 7         | 10+ years                            |          |
| Classroo             | om #223 (Regular Classroom) |           |          |        |           |                                      |          |
|                      | AC Units                    | 2nd Floor | 1        | EA     | 7         | 6-10 years                           |          |
|                      | Casework                    | 2nd Floor | 6        | LF     | 7         | 10+ years                            |          |
|                      | Ceiling - Plaster/Drywall   | 2nd Floor | 780      | SF     | 7         | 10+ years                            |          |
|                      | Ceiling - Plaster/Drywall   | 2nd Floor | 15       | SF     | 6         | 10+ years                            |          |
|                      | Doors - Transom Window      | 2nd Floor | 9        | SF     | 7         | 10+ years                            |          |
|                      | Doors - Wood Doors inclu hw | 2nd Floor | 1        | ĒA     | 7         | 10+ years                            |          |
|                      | Floor - Tile                | 2nd Floor | 795      | SF     | 7         | 10+ years                            |          |
|                      | Lighting - Pendent/Surface  | 2nd Floor | 14       | EA     | 7         | 10+ years                            |          |
|                      | Marker Board                | 2nd Floor | 34       | LF     | 7         | 6-10 years                           |          |
|                      | Walls - Plaster/Drywall     | 2nd Floor | 1,455    | SF     | 7         | 10+ years                            |          |
| Classroo             | om #301 (Weight)            |           |          |        |           |                                      |          |
|                      | AC Units                    | 3rd Floor | 1        | EA     | 7         | 6-10 years                           |          |
|                      | Ceiling - Plaster/Drywall   | 3rd Floor | 871      | SF     | 7         | 10+ years                            |          |
|                      | Doors - Transom Window      | 3rd Floor | 9        | SF     | 7         | 10+ years                            |          |
|                      | Doors - Wood Doors inclu hw | 3rd Floor | 1        | EA     | 7         | 10+ years                            |          |
|                      | Floor - Tile                | 3rd Floor | 871      | SF     | 7         | 6-10 years                           |          |
|                      | Lighting - Pendent/Surface  | 3rd Floor | 14       | EA     | 7         | 6-10 years                           |          |
|                      | Marker Board                | 3rd Floor | 40       | LF     | 7         | 6-10 years                           |          |
|                      | Storage/ Closet             | 3rd Floor | 15       | SF     | 7         | 10+ years                            |          |
|                      |                             |           |          |        |           |                                      |          |



| Category : Classroom |  |                        | В        | uilding  | : Main |                         | Douglas Double VAIND, Officago, IE 00020 |
|----------------------|--|------------------------|----------|----------|--------|-------------------------|--|
| Juliage              | .,   |                        | _        | u        | ····   | Recommend               |  |
| Group                | Item - Type                                | Location               | Quantity | UOM      | Rank   | Replacement             | Comments                                 |
|                      | Walls - Plaster/Drywall                    | 3rd Floor              | 1,357    | SF       | 7      | 10+ years               |  |
|                      | ·  |                        |          |          |        | ·                       |  |
| Classroo             | om #302 (Vacant)                           |                        |          |          |        |                         |  |
|                      | AC Units                                   | 3rd Floor              | 1        | EA       | 7      | 6-10 years              |  |
|                      | Ceiling - Plaster/Drywall                  | 3rd Floor              | 871      | SF       | 6      | 10+ years               |  |
|                      | Doors - Transom Window                     | 3rd Floor              | 9        | SF       | 7      | 10+ years               |  |
|                      | Doors - Wood Doors inclu hw                | 3rd Floor              | 1        | EA       | 7      | 10+ years               |  |
|                      | Floor - Tile                               | 3rd Floor              | 871      | SF       | 7      | 6-10 years              |  |
|                      | Lighting - Pendent/Surface                 | 3rd Floor              | 14       | EA       | 6      | 6-10 years              |  |
|                      | Marker Board                               | 3rd Floor              | 38       | LF       | 7      | 6-10 years              |  |
|                      | Walls - Plaster/Drywall                    | 3rd Floor              | 1,356    | SF       | 6      | 10+ years               |  |
| Classro              | om #303 (Science Lab Level 1)              |                        |          |          |        |                         |  |
| _Cia55i00            | AC Units                                   | 3rd Floor              | 1        | EA       | 7      | 6-10 years              |  |
|                      | Ceiling - Plaster/Drywall                  | 3rd Floor              | 871      | SF       | 7      | 10+ years               |  |
|                      | Doors - Transom Window                     | 3rd Floor              | 12       | SF       | 7      | 10+ years               |  |
|                      | Doors - Wood Doors inclu hw                | 3rd Floor              | 12       | EA       | 7      |                         |  |
|                      |  | 3rd Floor              | 1<br>1   | EA       | 7      | 10+ years               |  |
|                      | Eye Wash Station<br>Floor - Tile           | 3rd Floor              | 871      | SF       | 7      | 10+ years<br>6-10 years |  |
|                      |  | 3rd Floor              | _        | EA       |        |                         |  |
|                      | Lighting - Pendent/Surface<br>Marker Board | 3rd Floor              | 14<br>38 | LF       | 7<br>7 | 6-10 years              |  |
|                      |  |                        |          | SF       |        | 6-10 years              |  |
|                      | Walls - Plaster/Drywall<br>Work Sink       | 3rd Floor<br>3rd Floor | 1,343    | SF<br>EA | 7<br>7 | 10+ years               |  |
|                      | WORK SINK                                  | 31d F1001              | ı        | EA       | ,      | 10+ years               |  |
| Classroo             | om #304 (Vacant)                           |                        |          |          |        |                         |  |
|                      | AC Units                                   | 3rd Floor              | 1        | EA       | 7      | 6-10 years              |  |
|                      | Ceiling - Plaster/Drywall                  | 3rd Floor              | 871      | SF       | 7      | 10+ years               |  |
|                      | Doors - Transom Window                     | 3rd Floor              | 12       | SF       | 7      | 10+ years               |  |
|                      | Doors - Wood Doors inclu hw                | 3rd Floor              | 1        | EA       | 7      | 10+ years               |  |
|                      | Floor - Tile                               | 3rd Floor              | 871      | SF       | 7      | 6-10 years              |  |
|                      | Lighting - Pendent/Surface                 | 3rd Floor              | 14       | EA       | 7      | 6-10 years              |  |
|                      | Marker Board                               | 3rd Floor              | 38       | LF       | 7      | 6-10 years              |  |
|                      | Storage/ Closet                            | 3rd Floor              | 15       | SF       | 7      | 10+ years               |  |
|                      | Walls - Plaster/Drywall                    | 3rd Floor              | 1,343    | SF       | 7      | 10+ years               |  |
| Classro              | om #305 (Vacant)                           |                        |          |          |        |                         |  |
|                      | AC Units                                   | 3rd Floor              | 1        | EA       | 7      | 6-10 years              |  |
|                      | Ceiling - Plaster/Drywall                  | 3rd Floor              | 871      | SF       | 7      | 10+ years               |  |
|                      | Doors - Transom Window                     | 3rd Floor              | 12       | SF       | 7      | 10+ years               |  |
|                      | Doors - Wood Doors inclu hw                | 3rd Floor              | 1        | EA       | 7      | 10+ years               |  |
|                      | Floor - Tile                               | 3rd Floor              | 871      | SF       | 7      | 6-10 years              |  |
|                      | Lighting - Pendent/Surface                 | 3rd Floor              | 14       | EA       | 7      | 6-10 years              |  |
|                      | Marker Board                               | 3rd Floor              | 38       | LF       | 7      | 6-10 years              |  |
|                      |  | -                      |          |          |        | <b>,</b>                |  |
|                      |  |                        |          |          |        |                         |  |



| Catego    | ory : Classroom             |           | В        | uilding | : Main |             | Bouglas Boole VAIND, Officago, IE 00023 |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|---|
| _         |                             |           |          |         |        | Recommend   |   |
| Group     | Item - Type                 | Location  | Quantity | UOM     | Rank   | Replacement | Comments                                |
|           | Storage/ Closet             | 3rd Floor | 15       | SF      | 7      | 10+ years   |   |
|           | Walls - Plaster/Drywall     | 3rd Floor | 1,343    | SF      | 7      | 10+ years   |   |
| _Classro  | om #306 (Vacant)            |           |          |         |        |             |   |
|           | AC Units                    | 3rd Floor | 2        | EA      | 7      | 6-10 years  |   |
|           | Ceiling - Plaster/Drywall   | 3rd Floor | 889      | SF      | 7      | 10+ years   |   |
|           | Doors - Transom Window      | 3rd Floor | 12       | SF      | 7      | 10+ years   |   |
|           | Doors - Wood Doors inclu hw | 3rd Floor | 1        | EA      | 7      | 10+ years   |   |
|           | Floor - Tile                | 3rd Floor | 889      | SF      | 7      | 6-10 years  |   |
|           | Lighting - Pendent/Surface  | 3rd Floor | 14       | EA      | 7      | 6-10 years  |   |
|           | Marker Board                | 3rd Floor | 40       | LF      | 7      | 6-10 years  |   |
|           | Storage/ Closet             | 3rd Floor | 15       | SF      | 7      | 10+ years   |   |
|           | Walls - Plaster/Drywall     | 3rd Floor | 1,425    | SF      | 7      | 10+ years   |   |
| _Classro  | om #307 (Vacant)            |           |          |         |        |             |   |
|           | AC Units                    | 3rd Floor | 1        | EA      | 7      | 6-10 years  |   |
|           | Ceiling - Plaster/Drywall   | 3rd Floor | 871      | SF      | 7      | 10+ years   |   |
|           | Doors - Transom Window      | 3rd Floor | 12       | SF      | 7      | 10+ years   |   |
|           | Doors - Wood Doors inclu hw | 3rd Floor | 1        | ĒΑ      | 7      | 10+ years   |   |
|           | Floor - Tile                | 3rd Floor | 871      | SF      | 7      | 6-10 years  |   |
|           | Lighting - Pendent/Surface  | 3rd Floor | 14       | ĒΑ      | 7      | 6-10 years  |   |
|           | Marker Board                | 3rd Floor | 35       | LF      | 7      | 6-10 years  |   |
|           | Storage/ Closet             | 3rd Floor | 15       | SF      | 7      | 10+ years   |   |
|           | Walls - Plaster/Drywall     | 3rd Floor | 1,357    | SF      | 7      | 10+ years   |   |
| _Classro  | om #308 (Vacant)            |           |          |         |        |             |   |
|           | AC Units                    | 3rd Floor | 1        | EA      | 7      | 6-10 years  |   |
|           | Ceiling - Plaster/Drywall   | 3rd Floor | 871      | SF      | 7      | 10+ years   |   |
|           | Doors - Transom Window      | 3rd Floor | 12       | SF      | 7      | 10+ years   |   |
|           | Doors - Wood Doors inclu hw | 3rd Floor | 1        | EA      | 7      | 10+ years   |   |
|           | Floor - Tile                | 3rd Floor | 871      | SF      | 7      | 6-10 years  |   |
|           | Lighting - Pendent/Surface  | 3rd Floor | 14       | EΑ      | 7      | 10+ years   |   |
|           | Marker Board                | 3rd Floor | 30       | LF      | 7      | 6-10 years  |   |
|           | Storage/ Closet             | 3rd Floor | 15       | SF      | 7      | 10+ years   |   |
|           | Walls - Plaster/Drywall     | 3rd Floor | 1,356    | SF      | 7      | 10+ years   |   |
| _Classroo | om #310 (Vacant)            |           |          |         |        |             |   |
|           | AC Units                    | 3rd Floor | 1        | EA      | 7      | 6-10 years  |   |
|           | Ceiling - Plaster/Drywall   | 3rd Floor | 870      | SF      | 7      | 10+ years   |   |
|           | Doors - Transom Window      | 3rd Floor | 12       | SF      | 7      | 10+ years   |   |
|           | Doors - Wood Doors inclu hw | 3rd Floor | 1        | EA      | 7      | 10+ years   |   |
|           | Floor - Tile                | 3rd Floor | 870      | SF      | 7      | 6-10 years  |   |
|           | Lighting - Pendent/Surface  | 3rd Floor | 14       | EA      | 7      | 6-10 years  |   |
|           |                             | 5.555.    | 11       |         | •      | c .c jouro  |   |
|           |                             |           |          |         |        |             |   |



| Catego   | ory : Classroom             |           | R        | uilding | · Main  | 0           | Douglas BOOLE VAIND, Officago, IE 00020 |
|----------|-----------------------------|-----------|----------|---------|---------|-------------|---|
| Oatogo   | ny . Olassi ooni            |           |          | ananig  | . Maiii | Recommend   |   |
| Group    | Item - Type                 | Location  | Quantity | UOM     | Rank    | Replacement | Comments                                |
| 0.00.0   | Marker Board                | 3rd Floor | 38       | LF      | 7       | 6-10 years  |   |
|          | Walls - Plaster/Drywall     | 3rd Floor | 1,357    | SF      | 7       | 10+ years   |   |
|          | Wallo Tiaston/Drywall       | 0.4.1.001 | 1,007    | O.      | •       | To Tyouro   |   |
| _Classro | om #315 (Vacant)            |           |          |         |         |             |   |
|          | AC Units                    | 3rd Floor | 1        | EA      | 7       | 6-10 years  |   |
|          | Ceiling - Plaster/Drywall   | 3rd Floor | 871      | SF      | 7       | 10+ years   |   |
|          | Doors - Transom Window      | 3rd Floor | 12       | SF      | 7       | 10+ years   |   |
|          | Doors - Wood Doors inclu hw | 3rd Floor | 1        | EA      | 7       | 10+ years   |   |
|          | Floor - Tile                | 3rd Floor | 871      | SF      | 7       | 6-10 years  |   |
|          | Lighting - Pendent/Surface  | 3rd Floor | 14       | ĒΑ      | 7       | 6-10 years  |   |
|          | Marker Board                | 3rd Floor | 30       | LF      | 7       | 6-10 years  |   |
|          | Walls - Plaster/Drywall     | 3rd Floor | 1,357    | SF      | 7       | 10+ years   |   |
|          | vvalio i laotoi/Brywaii     | 0.4.1.001 | 1,007    | O.      | •       | 101 youro   |   |
| _Classro | om #316 (Vacant)            |           |          |         |         |             |   |
|          | AC Units                    | 3rd Floor | 2        | EA      | 7       | 6-10 years  |   |
|          | Ceiling - Plaster/Drywall   | 3rd Floor | 860      | SF      | 7       | 10+ years   |   |
|          | Ceiling - Plaster/Drywall   | 3rd Floor | 10       | SF      | 4       | 0-1 year    | Water damage                            |
|          | Doors - Transom Window      | 3rd Floor | 12       | SF      | 7       | 10+ years   | Ğ                                       |
|          | Doors - Wood Doors inclu hw | 3rd Floor | 1        | ĒΑ      | 7       | 10+ years   |   |
|          | Floor - Tile                | 3rd Floor | 870      | SF      | 7       | 6-10 years  |   |
|          | Lighting - Pendent/Surface  | 3rd Floor | 14       | ĒΑ      | 7       | 6-10 years  |   |
|          | Marker Board                | 3rd Floor | 30       | LF      | 7       | 6-10 years  |   |
|          | Walls - Plaster/Drywall     | 3rd Floor | 1,357    | SF      | 7       | 10+ years   |   |
|          |                             |           |          |         |         |             |   |
| _Classro | om #317 (Vacant)            |           |          |         |         |             |   |
|          | AC Units                    | 3rd Floor | 2        | EA      | 7       | 6-10 years  |   |
|          | Ceiling - Plaster/Drywall   | 3rd Floor | 871      | SF      | 7       | 10+ years   |   |
|          | Doors - Transom Window      | 3rd Floor | 12       | SF      | 7       | 10+ years   |   |
|          | Doors - Wood Doors inclu hw | 3rd Floor | 1        | EΑ      | 7       | 10+ years   |   |
|          | Floor - Tile                | 3rd Floor | 871      | SF      | 7       | 6-10 years  |   |
|          | Lighting - Pendent/Surface  | 3rd Floor | 14       | EA      | 7       | 6-10 years  |   |
|          | Marker Board                | 3rd Floor | 30       | LF      | 7       | 6-10 years  |   |
|          | Walls - Plaster/Drywall     | 3rd Floor | 1,357    | SF      | 7       | 10+ years   |   |
| Classes  | om #318 (Vacant)            |           |          |         |         |             |   |
| _Ciassio | ,                           | 2nd Ele   |          | Г^      | 7       | 0.40        |   |
|          | AC Units                    | 3rd Floor | 1        | EA      | 7       | 6-10 years  |   |
|          | Ceiling - Plaster/Drywall   | 3rd Floor | 871      | SF      | 7       | 10+ years   |   |
|          | Doors - Transom Window      | 3rd Floor | 12       | SF      | 7       | 10+ years   |   |
|          | Doors - Wood Doors inclu hw | 3rd Floor | 1        | EA      | 7       | 10+ years   |   |
|          | Floor - Tile                | 3rd Floor | 871      | SF      | 7       | 6-10 years  |   |
|          | Lighting - Pendent/Surface  | 3rd Floor | 14       | EA      | 7       | 6-10 years  |   |
|          | Marker Board                | 3rd Floor | 38       | LF      | 7       | 6-10 years  |   |
|          | Storage/ Closet             | 3rd Floor | 15       | SF      | 7       | 10+ years   |   |
|          |                             |           |          |         |         |             |   |



| Catego   | ry : Classroom                             |                        | В           | uilding  | : Main | -                      | Douglas DOULE VAILD, Officago, IE 00025 |
|----------|--|------------------------|-------------|----------|--------|------------------------|---|
| Julioge  | , Classicon                                |                        |             | anamg    | · Wani | Recommend              |   |
| Group    | Item - Type                                | Location               | Quantity    | UOM      | Rank   | Replacement            | Comments                                |
|          | Walls - Plaster/Drywall                    | 3rd Floor              | 1,357       | SF       | 7      | 10+ years              |   |
|          | •  |                        |             |          |        | •                      |   |
| Classro  | om #319 (Vacant)                           |                        |             |          |        |                        |   |
|          | AC Units                                   | 3rd Floor              | 1           | EA       | 7      | 6-10 years             |   |
|          | Ceiling - Plaster/Drywall                  | 3rd Floor              | 871         | SF       | 7      | 10+ years              |   |
|          | Doors - Transom Window                     | 3rd Floor              | 12          | SF       | 7      | 10+ years              |   |
|          | Doors - Wood Doors inclu hw                | 3rd Floor              | 1           | EA       | 7      | 10+ years              |   |
|          | Floor - Tile                               | 3rd Floor              | 871         | SF       | 7      | 6-10 years             |   |
|          | Lighting - Pendent/Surface                 | 3rd Floor              | 14          | EA       | 7      | 6-10 years             |   |
|          | Marker Board                               | 3rd Floor              | 40          | LF       | 7      | 6-10 years             |   |
|          | Storage/ Closet                            | 3rd Floor              | 15          | SF       | 7      | 10+ years              |   |
|          | Walls - Plaster/Drywall                    | 3rd Floor              | 1,357       | SF       | 7      | 10+ years              |   |
| Classro  | om #320 (Vacant)                           |                        |             |          |        |                        |   |
|          | AC Units                                   | 3rd Floor              | 1           | EA       | 7      | 6-10 years             |   |
|          | Ceiling - Plaster/Drywall                  | 3rd Floor              | 871         | SF       | 7      | 10+ years              |   |
|          | Doors - Transom Window                     | 3rd Floor              | 12          | SF       | 7      | 10+ years              |   |
|          | Doors - Wood Doors inclu hw                | 3rd Floor              | 1           | EA       | 7      | 10+ years              |   |
|          | Floor - Tile                               | 3rd Floor              | 871         | SF       | 7      | 6-10 years             |   |
|          | Lighting - Pendent/Surface                 | 3rd Floor              | 14          | EA       | 7      | 6-10 years             |   |
|          | Marker Board                               | 3rd Floor              | 38          | LF       | 7      | 6-10 years             |   |
|          | Storage/ Closet                            | 3rd Floor              | 15          | SF       | 7      | 10+ years              |   |
|          | Walls - Plaster/Drywall                    | 3rd Floor              | 1,357       | SF       | 7      | 10+ years              |   |
| 01       | 11004 () (a a a a a)                       |                        |             |          |        |                        |   |
| _Classro | om #321 (Vacant)                           | 0.151                  |             | Ε.       |        | 0.40                   |   |
|          | AC Units                                   | 3rd Floor              | 1           | EA       | 7      | 6-10 years             |   |
|          | Ceiling - Plaster/Drywall                  | 3rd Floor              | 871         | SF       | 7      | 10+ years              |   |
|          | Doors - Transom Window                     | 3rd Floor              | 12          | SF       | 7      | 10+ years              |   |
|          | Doors - Wood Doors inclu hw                | 3rd Floor              | 1           | EA       | 7      | 10+ years              |   |
|          | Floor - Tile                               | 3rd Floor              | 871         | SF       | 7      | 6-10 years             |   |
|          | Lighting - Pendent/Surface<br>Marker Board | 3rd Floor              | 14          | EA       | 7      | 6-10 years             |   |
|          | Storage/ Closet                            | 3rd Floor<br>3rd Floor | 30          | LF<br>SF | 7      | 6-10 years             |   |
|          | Walls - Plaster/Drywall                    | 3rd Floor              | 45<br>1,357 | SF<br>SF | 7<br>7 | 10+ years<br>10+ years |   |
|          | vvalis - i lastei/Drywali                  | 310 1 1001             | 1,307       | OI .     | ,      | 10+ years              |   |
| _Classro | om #322 (Vacant)                           |                        |             |          |        |                        |   |
|          | AC Units                                   | 3rd Floor              | 1           | EA       | 7      | 6-10 years             |   |
|          | Ceiling - Lay-in                           | 3rd Floor              | 871         | SF       | 6      | 10+ years              |   |
|          | Doors - Wood Doors inclu hw                | 3rd Floor              | 1           | EA       | 7      | 10+ years              |   |
|          | Floor - Tile                               | 3rd Floor              | 871         | SF       | 7      | 6-10 years             |   |
|          | Lighting - Pendent/Surface                 | 3rd Floor              | 14          | EA       | 7      | 6-10 years             |   |
|          | Marker Board                               | 3rd Floor              | 38          | LF       | 7      | 6-10 years             |   |
|          | Storage/ Closet                            | 3rd Floor              | 55          | SF       | 7      | 10+ years              |   |
|          |  |                        |             |          |        |                        |   |



| Category : Classroom |  |                                | В        | uilding | : Main |             |          |
|----------------------|--|--------------------------------|----------|---------|--------|-------------|----------|
|                      | _  |                                |          |         |        | Recommend   |          |
| Group                | Item - Type                              | Location                       | Quantity | UOM     | Rank   | Replacement | Comments |
|                      | Walls - Plaster/Drywall                  | 3rd Floor                      | 1,357    | SF      | 6      | 10+ years   |          |
| Classroo             | om #323 (Regular Classroom)              |                                |          |         |        |             |          |
| 01400100             | AC Units                                 | 3rd Floor                      | 1        | EA      | 7      | 6-10 years  |          |
|                      | Ceiling - Lay-in                         | 3rd Floor                      | 871      | SF      | 7      | 10+ years   |          |
|                      | Doors - Transom Window                   | 3rd Floor                      | 12       | SF      | 7      | 10+ years   |          |
|                      | Doors - Wood Doors inclu hw              | 3rd Floor                      | 1        | EA      | 7      | 6-10 years  |          |
|                      | Floor - Tile                             | 3rd Floor                      | 871      | SF      | 7      | 6-10 years  |          |
|                      | Lighting - Pendent/Surface               | 3rd Floor                      | 14       | EA      | 7      | 6-10 years  |          |
|                      | Marker Board                             | 3rd Floor                      | 38       | LF      | 7      | 6-10 years  |          |
|                      | Storage/ Closet                          | 3rd Floor                      | 15       | SF      | 7      | 10+ years   |          |
|                      | Walls - Plaster/Drywall                  | 3rd Floor                      | 1,357    | SF      | 6      | 10+ years   |          |
|                      | vvalio i lastei/Diywali                  | 314 1 1001                     | 1,007    | O.      | O      | 101 years   |          |
| Catego               | ry : Interior                            |                                | В        | uilding | : Main |             |          |
|                      |  |                                |          |         |        | Recommend   |          |
| Group                | Item - Type                              | Location                       | Quantity | UOM     | Rank   | Replacement | Comments |
| Corridor             |  |                                |          |         |        |             |          |
|                      | Ceiling - Plaster/Drywall                | 1st Floor                      | 13,458   | SF      | 7      | 10+ years   |          |
|                      | Doors - Wood Doors include hw            | 1st Floor                      | 18       | EA      | 7      | 10+ years   |          |
|                      | Drinking Fountains - Triple Fountain     | 1st Floor                      | 3        | EA      | 7      | 10+ years   |          |
|                      | Floor - Tile/Sheet                       | 1st Floor                      | 13,458   | SF      | 7      | 6-10 years  |          |
|                      | Lighting - Pendent/Surface               | 1st Floor                      | 142      | EA      | 7      | 10+ years   |          |
|                      | Lighting - Wall Mounted                  | 1st Floor                      | 4        | EA      | 7      | 6-10 years  |          |
|                      | Stairs - Concrete Stairs                 | 1st Floor                      | 6        | LF      | 7      | 10+ years   |          |
|                      | Walls - Plaster/Drywall                  | 1st Floor                      | 17,725   | SF      | 7      | 10+ years   |          |
|                      | Walls - Structural Glazed Tile           | 1st Floor                      | 922      | SF      | 7      | 10+ years   |          |
|                      | Ceiling - Plaster/Drywall                | 2nd Floor                      | 8,266    | SF      | 7      | 10+ years   |          |
|                      | Drinking Fountains - Single Fountain     | 2nd Floor                      | 6        | EA      | 7      | 10+ years   |          |
|                      | Drinking Fountains - Single Water Cooler | 2nd Floor                      | 2        | EA      | 7      | 10+ years   |          |
|                      | Floor - Asphalt Floor                    | 2nd Floor                      | 8,266    | SF      | 6      | 10+ years   |          |
|                      | Lighting - Pendent/Surface               | 2nd Floor                      | 124      | EA      | 7      | 10+ years   |          |
|                      | Walls - Plaster/Drywall                  | 2nd Floor                      | 18,550   | SF      | 7      | 10+ years   |          |
|                      | Ceiling - Plaster/Drywall                | 2nd Floor - around Main Office | 890      | SF      | 7      | 10+ years   |          |
|                      | Floor - Asphalt Floor                    | 2nd Floor - around Main Office | 890      | SF      | 6      | 10+ years   |          |
|                      | Lighting - Pendent/Surface               | 2nd Floor - around Main Office | 9        | EA      | 7      | 10+ years   |          |
|                      | Walls - Plaster/Drywall                  | 2nd Floor - around Main Office | 3,766    | SF      | 7      | 10+ years   |          |
|                      | Ceiling - Plaster/Drywall                | 3rd Floor                      | 8,138    | SF      | 7      | 10+ years   |          |
|                      | Drinking Fountains - Triple Fountain     | 3rd Floor                      | 2        | EA      | 7      | 10+ years   |          |
|                      | Floor - Asphalt Floor                    | 3rd Floor                      | 8 138    | SF.     | 7      | 6-10 years  |          |

Safety

Floor - Asphalt Floor

Lighting - Pendent/Surface Walls - Plaster/Drywall

8,138

19,120

120

SF

EΑ

SF

7

6

6-10 years

6-10 years

10+ years

3rd Floor

3rd Floor

3rd Floor



| Catego   | ry : Interior                 |             | В        | uilding | : Main |                        |                                  |
|----------|-------------------------------|-------------|----------|---------|--------|------------------------|----------------------------------|
|          |                               |             | <b>.</b> |         |        | Recommend              |                                  |
| roup     | Item - Type                   | Location    | Quantity | UOM     | Rank   | Replacement            | Comments                         |
|          | Camera Viewing Station        | 1st Floor   | 1        | EA      | 7      | 6-10 years             |                                  |
|          | Security Cameras              | 1st Floor   | 8        | EA      | 7      | 6-10 years             |                                  |
| tairs    |                               |             |          |         |        |                        |                                  |
|          | Ceiling - Plaster/Drywall     | #1 NW Stair | 725      | SF      | 7      | 10+ years              |                                  |
|          | Floor - Asphalt               | #1 NW Stair | 646      | SF      | 6      | 10+ years              |                                  |
|          | Handrails                     | #1 NW Stair | 150      | LF      | 7      | 10+ years              |                                  |
|          | Lighting - Pendent/Surface    | #1 NW Stair | 5        | EA      | 7      | 10+ years              |                                  |
|          | Stairs - Asphalt              | #1 NW Stair | 528      | LF      | 7      | 10+ years              |                                  |
|          | Walls - Plaster/Drywall       | #1 NW Stair | 2,910    | SF      | 7      | 10+ years              |                                  |
|          | Ceiling - Plaster/Drywall     | #2 W Stair  | 745      | SF      | 7      | 10+ years              |                                  |
|          | Floor - Asphalt               | #2 W Stair  | 545      | SF      | 6      | 10+ years              |                                  |
|          | Handrails                     | #2 W Stair  | 242      | LF      | 7      | 10+ years              |                                  |
|          | Lighting - Pendent/Surface    | #2 W Stair  | 3        | ĒΑ      | 7      | 10+ years              |                                  |
|          | Stairs - Asphalt              | #2 W Stair  | 540      | LF      | 7      | 10+ years              |                                  |
|          | Walls - Plaster/Drywall       | #2 W Stair  | 3,020    | SF      | 7      | 10+ years              |                                  |
|          | Ceiling - Plaster/Drywall     | #3 S Stair  | 380      | SF      | 7      | 10+ years              |                                  |
|          | Floor - Asphalt               | #3 S Stair  | 172      | SF      | 7      | 6-10 years             |                                  |
|          | Handrails                     | #3 S Stair  | 64       | LF      | 7      | •                      |                                  |
|          | Lighting - Pendent/Surface    | #3 S Stair  | 2        | EA      | 6      | 10+ years<br>10+ years |                                  |
|          | Stairs - Asphalt              | #3 S Stair  |          | LF      |        | ,                      |                                  |
|          |                               |             | 28       | SF      | 7      | 10+ years              |                                  |
|          | Walls - Plaster/Drywall       | #3 S Stair  | 1,770    |         | 7      | 10+ years              | \\/                              |
|          | Walls - Plaster/Drywall       | #3 S Stair  | 50       | SF      | 4      | 0-1 year               | Water damage                     |
|          | Ceiling - Plaster/Drywall     | #4 SE Stair | 695      | SF      | 7      | 10+ years              |                                  |
|          | Floor - Asphalt               | #4 SE Stair | 440      | SF      | 7      | 6-10 years             |                                  |
|          | Handrails                     | #4 SE Stair | 254      | LF      | 7      | 10+ years              |                                  |
|          | Lighting - Pendent/Surface    | #4 SE Stair | 4        | EA      | 7      | 6-10 years             |                                  |
|          | Stairs - Asphalt              | #4 SE Stair | 65       | LF      | 7      | 10+ years              |                                  |
|          | Walls - Plaster/Drywall       | #4 SE Stair | 3,010    | SF      | 7      | 10+ years              |                                  |
|          | Ceiling - Plaster/Drywall     | #5 NE Stair | 646      | SF      | 7      | 10+ years              |                                  |
|          | Floor - Asphalt               | #5 NE Stair | 646      | SF      | 7      | 6-10 years             |                                  |
|          | Handrails                     | #5 NE Stair | 150      | LF      | 7      | 10+ years              |                                  |
|          | Lighting - Pendent/Surface    | #5 NE Stair | 7        | EA      | 6      | 6-10 years             |                                  |
|          | Stairs - Asphalt              | #5 NE Stair | 66       | LF      | 7      | 10+ years              |                                  |
|          | Walls - Plaster/Drywall       | #5 NE Stair | 2,910    | SF      | 7      | 10+ years              |                                  |
|          | Ceiling - Plaster/Drywall     | #6 E Stair  | 426      | SF      | 7      | 10+ years              |                                  |
|          | Floor - Asphalt               | #6 E Stair  | 426      | SF      | 6      | 10+ years              |                                  |
|          | Handrails                     | #6 E Stair  | 140      | LF      | 7      | 10+ years              |                                  |
|          | Lighting - Pendent/Surface    | #6 E Stair  | 5        | EΑ      | 7      | 10+ years              |                                  |
|          | Stairs - Asphalt              | #6 E Stair  | 432      | LF      | 7      | 10+ years              |                                  |
|          | Walls - Plaster/Drywall       | #6 E Stair  | 2,875    | SF      | 7      | 10+ years              |                                  |
| /ortical | Conveyance                    |             |          |         |        |                        |                                  |
| erneal   | •                             | 1et Floor   | 4        | ГΛ      | 6      | 10                     | Flooring chinning and are direct |
|          | Elevator - Hydraulic Elevator | 1st Floor   | 1        | EA      | 6      | 10+ years              | Flooring chipping and cracking.  |

Campus Name: Herzl Page : 35 of 47 Assessment Date: 04/18/2022



**Building: Main Category: Interior** 

Recommend Item - Type Location UOM Group Quantity Rank Replacement Comments Elevator - Lula 1st Floor EΑ 10+ years 6

Campus Name: Herzl Page : 36 of 47 Assessment Date: 04/18/2022





Category : Exterior **Building: Branch-CPC** 

|            |  |  |          |     |      | Recommend   |   |
|------------|--|--|----------|-----|------|-------------|---|
| oup Item · | - Type   | Location                               | Quantity | UOM | Rank | Replacement | Comments  |
| rance      |  |  |          |     |      |             |   |
| Exter      | or Doors - Exterior Steel Door   | Entrance 2 - East                      | 2        | EA  | 5    | 0-1 year    | Dented.   |
| Exter      | ior Doors - Side lite  | Entrance 2 - East                      | 2        | EA  | 6    | 10+ years   | Paint peeling.  |
| Exter      | ior Doors - Transom Lite   | Entrance 2 - East                      | 2        | EA  | 6    | 10+ years   |   |
| Exter      | Exterior Doors - Exterior Steel Door Entrance 3 - East - Yard S building |  | 2        | EA  | 5    | 0-1 year    | Denting   |
|            | ior Doors - Exterior Steel Door  | Entrance 4                             | 1        | EA  | 6    | 10+ years   |   |
|            | ior Doors - Side lite  | Entrance 4                             | 2        | EA  | 6    | 10+ years   | Paint peeling.  |
|            | ior Doors - Transom Lite   | Entrance 4                             | 1        | EA  | 6    | 10+ years   |   |
|            | nce Control - Audio and Video  | Main Entrance 1 - North                | 1        | EA  | 5    | 6-10 years  |   |
|            | ior Doors - Exterior Steel Door  | Main Entrance 1 - North                | 2        | EA  | 5    | 0-1 year    | Denting and corroded around edg   |
|            | ior Doors - Side lite  | Main Entrance 1 - North                | 2        | EA  | 5    | 0-1 year    | Corroded around edges.  |
| Exter      | ior Doors - Transom Lite   | Main Entrance 1 - North                | 2        | EA  | 6    | 10+ years   |   |
| undation   |  |  |          |     |      |             |   |
|            | dation - Concrete  | Entire Building                        | 400      | LF  | 7    | 10+ years   |   |
| Supe       | rstructure - Steel   | Entire Building                        | 8,525    | SF  | 7    | 10+ years   |   |
| hting      |  |  |          |     |      |             |   |
|            | ior Lighting - Wall Mounted  | Entire Building                        | 2        | EA  | 6    | 6-10 years  |   |
| Exter      | ior Lighting - Wall Mounted  | Entire Building                        | 2        | EA  | 5    | 6-10 years  |   |
| of System  |  |  |          |     |      |             |   |
| Copir      | ng - Metal   | Roof 14                                | 400      | LF  | 6    | 10+ years   |   |
| Down       | spouts - Interior Downspouts   | Roof 14                                | 60       | LF  | 5    | 2-5 years   | No access   |
|            | - Asphalt Gravel Ballast   | Roof 14                                | 8,525    | SF  | 4    | 0-1 year    | Roof was not accessible during si visit, per Building Engineer roof le reported. Ranking of this roof is ranked based on Building Engineer and previous assessment. |
|            | Structure - Steel / Metal Deck/<br>rete Topping                          | Roof 14                                | 8,525    | SF  | 7    | 10+ years   |   |
|            | ng - Metal   | Yard Storage Building - North of annex | 50       | LF  | 6    | 10+ years   |   |
| Roof       | - Asphalt Gravel Ballast   | Yard Storage Building - North of annex | 125      | SF  | 4    | 0-1 year    | During the site visit this roof was inaccessible. Ranking of this roof ranked based on Building Engine and previous assessment.                                     |
| Roof       | Structure - Concrete   | Yard Storage Building - North of annex | 125      | SF  | 7    | 10+ years   | promote accomment   |



| Catego    | ry : Exterior  |  | Building : Branch-CPC |         |         |             |                              |  |  |
|-----------|--|--|-----------------------|---------|---------|-------------|------------------------------|--|--|
| _         |  |  |                       | _       |         | Recommend   |                              |  |  |
| Group     | Item - Type  | Location                               | Quantity              | UOM     | Rank    | Replacement | Comments                     |  |  |
| _         | Exterior Walls - Prefabricated Metal Panel Wall        | Entire Building                        | 1,000                 | SF      | 5       | 2-5 years   |                              |  |  |
|           | Exterior Walls - Prefabricated Metal Panel Wall        | Entire Building                        | 2,415                 | SF      | 5       | 2-5 years   | Paint peeling throughout.    |  |  |
|           | Exterior Walls - Concrete Block                        | Yard Storage Building - North of annex | 355                   | SF      | 7       | 10+ years   |                              |  |  |
| Windows   | 3  |  |                       |         |         |             |                              |  |  |
|           | Lintels - Steel  | Entire Building                        | 6                     | LF      | 6       | 6-10 years  |                              |  |  |
|           | Windows - Sash Lexan/ Glass Double-pane                | Entire Building                        | 1,080                 | SF      | 6       | 6-10 years  |                              |  |  |
| Catego    | ry : Electrical  |  | В                     | uilding | : Branc | h-CPC       |                              |  |  |
|           |  |  |                       |         |         | Recommend   |                              |  |  |
| Group     | Item - Type  | Location                               | Quantity              | UOM     | Rank    | Replacement | Comments                     |  |  |
| Emerger   | ncy System   |  |                       |         |         |             |                              |  |  |
|           | Automatic Transfer Switch                              | Electrical Room                        | 1                     | EA      | 6       | 6-10 years  |                              |  |  |
|           | Exit Signs - Corridors and Stairs                      | Entire Building                        | 3                     | EA      | 4       | 0-1 year    | Outdated, incandescent bulbs |  |  |
|           | Security System - Intrusion Detection                  | Entire Building                        | 8,525                 | SF      | 6       | 6-10 years  |                              |  |  |
| Main Sei  | vice   |  |                       |         |         |             |                              |  |  |
|           | PA System  | 1st Floor                              | 8,525                 | SF      | 4       | 1-2 years   | Outdated                     |  |  |
|           | Main Electrical Service - 1000 A<br>120/208/3PH        | Electrical Room                        | 1                     | EA      | 6       | 6-10 years  |                              |  |  |
|           | Independent Electrical Service for<br>emergency power  | Electrical Room                        | 1                     | EA      | 6       | 10+ years   |                              |  |  |
| Power D   | istribution  |  |                       |         |         |             |                              |  |  |
|           | Lighting and Power Panels - 100 A                      | Electrical Room                        | 1                     | EA      | 7       | 6-10 years  |                              |  |  |
|           | Lighting and Power Panels - 100 A                      | Electrical Room                        | 1                     | EA      | 6       | 6-10 years  |                              |  |  |
|           | Lighting and Power Panels - Above 100 A                | Electrical Room                        | 2                     | EA      | 6       | 6-10 years  |                              |  |  |
| Catego    | ry : Mechanical  |  | В                     | uilding | : Branc | h-CPC       |                              |  |  |
| _         |  |  |                       |         |         | Recommend   |                              |  |  |
| Group     | Item - Type  | Location                               | Quantity              | UOM     | Rank    | Replacement | Comments                     |  |  |
| Heating I | Devices  |  |                       |         |         |             |                              |  |  |
| ŭ         | Cabinet Heaters - With Electric Coil                   | Entire Building                        | 3                     | EA      | 6       | 6-10 years  |                              |  |  |
|           | Wall Heater - Electric                                 | Entire Building                        | 4                     | EA      | 6       | 6-10 years  |                              |  |  |
| Unit Ven  | tilation   |  |                       |         |         |             |                              |  |  |
| CIII VOII | Unit Ventilators- Floor Mounted- Electric              | Entire Building                        | 6                     | EA      | 5       | 2-5 years   |                              |  |  |
|           | Heating & DX Cooling Coil W/ Self Contained Compressor | Januariy                               | Ü                     | _, .    | ŭ       | 20 ,0010    |                              |  |  |



| Catego      | ry : Mechanical  |                                 | В        | uilding  |        |                          |   |
|-------------|--|---------------------------------|----------|----------|--------|--------------------------|---|
| Group       | Item - Type  | Location                        | Quantity | UOM      | Rank   | Recommend<br>Replacement | Comments  |
| _Ventilatio |  |                                 |          |          |        |                          |   |
|             | Exhaust Fans- Indoor - 500 - 1500 CFM<br>Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building Entire Building | 5<br>2   | EA<br>EA | 5<br>3 | 2-5 years<br>0-1 year    | Does not turn on  |
|             | Exhaust Fans- Roof Mounted - 500 - 1500<br>CFM                                 | Entire Building                 | 1        | EA       | 6      | 6-10 years               | Roof was no accessible during site visit, components ranked based on Building Engineer and previous assessment. |

Category : Plumbing **Building: Branch-CPC** 

| Group    | Item - Type                            | Location        | Quantity | UOM | Rank | Recommend<br>Replacement | Comments |
|----------|--|-----------------|----------|-----|------|--------------------------|----------|
| Hot Wate | er                                     |                 |          |     |      |                          |          |
|          | Electric Heater - Less than 20 KW      | Electrical Room | 1        | EA  | 6    | 6-10 years               |          |
|          |  |                 |          |     |      |                          |          |
| _Piping  |  |                 |          |     |      |                          |          |
|          | Domestic Piping-Hot Water Return Lines | Entire Building | 8,525    | SF  | 6    | 6-10 years               |          |
|          | Domestic Piping-Hot/Cold Water Supply  | Entire Building | 8,525    | SF  | 6    | 6-10 years               |          |
|          | (Horizontal Lines)                     |                 |          |     |      |                          |          |
|          | Sanitary Piping                        | Entire Building | 8,525    | SF  | 6    | 6-10 years               |          |

Category : Room **Building: Branch-CPC** 

|         |                             |                            |          |     |      | Recommend   |          |
|---------|-----------------------------|----------------------------|----------|-----|------|-------------|----------|
| Group   | Item - Type                 | Location                   | Quantity | UOM | Rank | Replacement | Comments |
| Adminis | trative Suites/Offices      |                            |          |     |      |             |          |
|         | Ceiling - Lay-in            | 1st Floor - Break Room     | 140      | SF  | 7    | 10+ years   |          |
|         | Doors - Steel Doors incl hw | 1st Floor - Break Room     | 1        | EA  | 7    | 10+ years   |          |
|         | Floor - Carpet              | 1st Floor - Break Room     | 130      | SF  | 7    | 6-10 years  |          |
|         | Floor - Carpet              | 1st Floor - Break Room     | 10       | SF  | 4    | 0-1 year    | Torn     |
|         | Lighting - Lay-in           | 1st Floor - Break Room     | 3        | EA  | 7    | 10+ years   |          |
|         | Power Distribution          | 1st Floor - Break Room     | 4        | EA  | 7    | 10+ years   |          |
|         | Walls - Metal Panel         | 1st Floor - Break Room     | 615      | SF  | 7    | 10+ years   |          |
|         | Ceiling - Lay-in            | 1st Floor - Lounge/Kitchen | 210      | SF  | 7    | 10+ years   |          |
|         | Doors - Steel Doors incl hw | 1st Floor - Lounge/Kitchen | 1        | EA  | 7    | 10+ years   |          |
|         | Floor - Tile                | 1st Floor - Lounge/Kitchen | 210      | SF  | 7    | 10+ years   |          |
|         | Lighting - Lay-in           | 1st Floor - Lounge/Kitchen | 3        | EA  | 7    | 10+ years   |          |
|         | Power Distribution          | 1st Floor - Lounge/Kitchen | 6        | EA  | 7    | 10+ years   |          |
|         | Walls - Metal Panel         | 1st Floor - Lounge/Kitchen | 530      | SF  | 7    | 10+ years   |          |
|         | Walls - Plaster/Drywall     | 1st Floor - Lounge/Kitchen | 160      | SF  | 7    | 10+ years   |          |
|         | Work SInk                   | 1st Floor - Lounge/Kitchen | 1        | EA  | 7    | 10+ years   |          |
|         | Ceiling - Lay-in            | Main Office                | 205      | SF  | 7    | 10+ years   |          |
|         | Doors - Steel Doors incl hw | Main Office                | 1        | EA  | 7    | 10+ years   |          |
|         | Floor - Carpet              | Main Office                | 195      | SF  | 7    | 6-10 years  |          |

Campus Name: Herzl Page : 39 of 47 Assessment Date: 04/18/2022



| Catego   | ry : Room                   | -                       | В        | uilding | : Branc | h-CPC         | -                                     |
|----------|-----------------------------|-------------------------|----------|---------|---------|---------------|---------------------------------------|
|          |                             |                         |          |         |         | Recommend     |                                       |
| Group    | Item - Type                 | Location                | Quantity | UOM     | Rank    | Replacement   | Comments                              |
|          | Floor - Carpet              | Main Office             | 10       | SF      | 4       | 0-1 year      | Torn                                  |
|          | Lighting - Lay-in           | Main Office             | 5        | EA      | 7       | 10+ years     |                                       |
|          | Power Distribution          | Main Office             | 8        | EΑ      | 7       | 10+ years     |                                       |
|          | Storage/ Closet             | Main Office             | 55       | SF      | 7       | 10+ years     |                                       |
|          | Walls - Metal Panel         | Main Office             | 675      | SF      | 7       | 10+ years     |                                       |
|          | Ceiling - Lay-in            | Main Office - Director  | 75       | SF      | 7       | 10+ years     |                                       |
|          | Doors - Steel Doors incl hw | Main Office - Director  | 1        | EA      | 7       | 10+ years     |                                       |
|          | Floor - Carpet              | Main Office - Director  | 75       | SF      | 7       | 6-10 years    |                                       |
|          | Lighting - Lay-in           | Main Office - Director  | 2        | EA      | 7       | 10+ years     |                                       |
|          | Power Distribution          | Main Office - Director  | 6        | EA      | 7       | 10+ years     |                                       |
|          | Walls - Metal Panel         | Main Office - Director  | 335      | SF      | 7       | 10+ years     |                                       |
|          | Ceiling - Lay-in            | Main Office - Principal | 120      | SF      | 7       | 10+ years     |                                       |
|          | Doors - Steel Doors incl hw | Main Office - Principal | 1        | ĒΑ      | 7       | 10+ years     |                                       |
|          | Floor - Carpet              | Main Office - Principal | 114      | SF      | 7       | 6-10 years    |                                       |
|          | Floor - Carpet              | Main Office - Principal | 6        | SF      | 4       | 0-1 year      | Torn                                  |
|          | Lighting - Lay-in           | Main Office - Principal | 2        | EA      | 7       | 10+ years     | 10111                                 |
|          | Power Distribution          | Main Office - Principal | 6        | EA      | 7       | 10+ years     |                                       |
|          | Walls - Metal Panel         | Main Office - Principal | 570      | SF      | 7       | 10+ years     |                                       |
|          | Ceiling - Lay-in            | Parent Room             | 750      | SF      | 7       | •             |                                       |
|          |                             |                         |          |         | 7       | 10+ years     |                                       |
|          | Doors - Wood Doors inclu hw | Parent Room             | 1        | EA      |         | 10+ years     |                                       |
|          | Floor - Carpet              | Parent Room             | 750      | SF      | 7       | 6-10 years    |                                       |
|          | Lighting - Lay-in           | Parent Room             | 6        | EA      | 7       | 6-10 years    |                                       |
|          | Power Distribution          | Parent Room             | 8        | EA      | 7       | 10+ years     |                                       |
|          | Walls - Plaster/Drywall     | Parent Room             | 600      | SF      | 7       | 10+ years     |                                       |
| _MDF_ID  | F                           |                         |          |         |         |               |                                       |
| _        | Doors - Steel Doors incl hw | 1st Floor               | 1        | EA      | 7       | 10+ years     |                                       |
|          | Finishes                    | 1st Floor               | 75       | SF      | 7       | 10+ years     |                                       |
|          | Other Cooling Unit          | 1st Floor               | 1        | ĒΑ      | 5       | 6-10 years    | Missing cover. Ductless split system. |
|          | outer coaming of the        | 101.100.                | ·        | _, ,    | · ·     | 5 . 5 y 5 a 5 | oog oo oo 2 donooo op oyoto           |
| Mechani  | cal/ Service Rooms          |                         |          |         |         |               |                                       |
|          | Janitor's Closet            | 1st Floor               | 38       | SF      | 7       | 10+ years     |                                       |
|          | Mechanical/ Service Rooms   | 1st Floor               | 140      | SF      | 7       | 10+ years     |                                       |
|          | Storage Room                | 1st Floor               | 95       | SF      | 7       | 10+ years     |                                       |
| Prep Ro  | om                          |                         |          |         |         |               |                                       |
|          | Ceiling - Lay-in            | 1st Floor               | 185      | SF      | 7       | 10+ years     |                                       |
|          | Doors - Steel Doors incl hw | 1st Floor               | 1        | EA      | 7       | 10+ years     |                                       |
|          | Floor - Tile                | 1st Floor               | 185      | SF      | 6       | 10+ years     |                                       |
|          | Lighting - Lay-in           | 1st Floor               | 4        | EA      | 7       | 10+ years     |                                       |
|          | Walls - Metal Panel         | 1st Floor               | 575      | SF      | 7       | 10+ years     |                                       |
|          | vvans - metai i anel        | 13(1100)                | 575      | J.      | ,       | TOT years     |                                       |
| Restroor | n                           |                         |          |         |         |               |                                       |
|          |                             |                         |          |         |         |               |                                       |

Campus Name: Herzl Page : 40 of 47 Assessment Date: 04/18/2022



| Catego | ry : Room                       |                        | В        | uilding | : Branc | h-CPC       |  |
|--------|---------------------------------|------------------------|----------|---------|---------|-------------|--|
| _      |                                 |                        |          | _       |         | Recommend   |  |
| Group  | Item - Type                     | Location               | Quantity | UOM     | Rank    | Replacement | Comments   |
|        | Accessories                     | 1st Floor - Break Room | 30       | SF      | 7       | 10+ years   |  |
|        | Ceiling - Lay-in                | 1st Floor - Break Room | 30       | SF      | 7       | 10+ years   |  |
|        | Floor - Tile Ceramic/ Porcelain | 1st Floor - Break Room | 30       | SF      | 7       | 10+ years   |  |
|        | Lavatory                        | 1st Floor - Break Room | 1        | EA      | 7       | 10+ years   |  |
|        | Lighting - Pendent/Surface      | 1st Floor - Break Room | 1        | EA      | 7       | 10+ years   |  |
|        | Walls - Metal Panel             | 1st Floor - Break Room | 195      | SF      | 7       | 10+ years   |  |
|        | Water Closet                    | 1st Floor - Break Room | 1        | EA      | 7       | 10+ years   |  |
|        | Accessories                     | 1st Floor - Unisex     | 50       | SF      | 7       | 6-10 years  |  |
|        | Ceiling - Lay-in                | 1st Floor - Unisex     | 50       | SF      | 7       | 10+ years   |  |
|        | Doors - Steel Doors incl hw     | 1st Floor - Unisex     | 1        | EA      | 7       | 10+ years   |  |
|        | Floor - Tile Ceramic/ Porcelain | 1st Floor - Unisex     | 50       | SF      | 7       | 10+ years   |  |
|        | Floor Drain                     | 1st Floor - Unisex     | 1        | EA      | 7       | 10+ years   |  |
|        | Lavatory                        | 1st Floor - Unisex     | 1        | EA      | 7       | 10+ years   |  |
|        | Lighting - Pendent/Surface      | 1st Floor - Unisex     | 1        | EA      | 7       | 10+ years   |  |
|        | Walls - Metal Panel             | 1st Floor - Unisex     | 270      | SF      | 7       | 10+ years   |  |
|        | Water Closet                    | 1st Floor - Unisex     | 1        | EA      | 7       | 10+ years   |  |
|        | Accessories                     | 401A                   | 73       | SF      | 7       | 6-10 years  |  |
|        | Ceiling - Lay-in                | 401A                   | 73       | SF      | 7       | 10+ years   |  |
|        | Doors - Wood Doors inclu hw     | 401A                   | 1        | EA      | 7       | 10+ years   |  |
|        | Floor - Tile Ceramic/ Porcelain | 401A                   | 73       | SF      | 7       | 10+ years   |  |
|        | Lavatory                        | 401A                   | 1        | EA      | 7       | 10+ years   |  |
|        | Lighting - Pendent/Surface      | 401A                   | 1        | EA      | 7       | 10+ years   |  |
|        | Walls - Metal Panel             | 401A                   | 222      | SF      | 7       | 10+ years   |  |
|        | Water Closet                    | 401A                   | 1        | ĒΑ      | 7       | 10+ years   |  |
|        | Accessories                     | 402B                   | 38       | SF      | 7       | 6-10 years  |  |
|        | Ceiling - Lay-in                | 402B                   | 38       | SF      | 7       | 10+ years   |  |
|        | Doors - Wood Doors inclu hw     | 402B                   | 1        | EA      | 7       | 10+ years   |  |
|        | Floor - Tile Ceramic/ Porcelain | 402B                   | 38       | SF      | 7       | 10+ years   |  |
|        | Lavatory                        | 402B                   | 1        | EA      | 7       | 10+ years   |  |
|        | Lighting - Pendent/Surface      | 402B                   | 1        | EΑ      | 7       | 10+ years   |  |
|        | Walls - Metal Panel             | 402B                   | 222      | SF      | 7       | 10+ years   |  |
|        | Water Closet                    | 402B                   | 1        | EA      | 7       | 10+ years   |  |
|        | Accessories                     | 403C                   | 38       | SF      | 7       | 6-10 years  |  |
|        | Ceiling - Lay-in                | 403C                   | 38       | SF      | 7       | 10+ years   |  |
|        | Doors - Wood Doors inclu hw     | 403C                   | 1        | ĒΑ      | 7       | 10+ years   |  |
|        | Floor - Tile Ceramic/ Porcelain | 403C                   | 38       | SF      | 7       | 10+ years   |  |
|        | Lavatory                        | 403C                   | 1        | ĒΑ      | 7       | 10+ years   |  |
|        | Lighting - Pendent/Surface      | 403C                   | 1        | EA      | 7       | 10+ years   |  |
|        | Walls - Metal Panel             | 403C                   | 222      | SF      | 7       | 10+ years   |  |
|        | Water Closet                    | 403C                   | 1        | ĒΑ      | 7       | 10+ years   |  |
|        | Accessories                     | 404D                   | 73       | SF      | 7       | 6-10 years  |  |
|        | Ceiling - Lay-in                | 404D                   | 65       | SF      | 7       | 10+ years   |  |
|        | Ceiling - Lay-in                | 404D                   | 8        | SF      | 3       | 0-1 year    | Active water leak with water dripping.   |
|        | Doors - Wood Doors inclu hw     | 404D                   | 1        | EA      | 7       | 10+ years   | and a second sec |
|        |                                 |                        | ·        |         | •       | ,           |  |



| Recommend Quantity UOM Rank Replacement Comments 73 SF 7 10+ years 1 EA 7 10+ years |
|---|
| 73 SF 7 10+ years   |
|   |
| 1 FA 7 10+ vears  |
| 1 L/C / 101 years   |
| 1 EA 7 10+ years  |
| 276 SF 7 10+ years  |
| 1 EA 7 10+ years  |
| 52 SF 7 6-10 years  |
| 46 SF 7 10+ years   |
| 6 SF 4 0-1 year Water damage  |
| 1 EA 7 10+ years  |
| 52 SF 6 10+ years   |
| 1 EA 7 10+ years  |
| 1 EA 7 6-10 years   |
| 1 EA 7 10+ years  |
| 1 EA 7 10+ years  |
| 238 SF 7 10+ years  |
| 30 SF 7 10+ years   |
| 1 EA 7 10+ years  |
|   |

Building : Branch-CPC Category : Classroom

|           |                             |           |          |     |      | Recommend   |               |
|-----------|-----------------------------|-----------|----------|-----|------|-------------|---------------|
| Group     | Item - Type                 | Location  | Quantity | UOM | Rank | Replacement | Comments      |
| Classroo  | om #401A (Pre School)       |           |          |     |      |             |               |
|           | Casework                    | 1st Floor | 4        | LF  | 7    | 10+ years   |               |
|           | Ceiling - Lay-in            | 1st Floor | 745      | SF  | 7    | 10+ years   |               |
|           | Ceiling - Lay-in            | 1st Floor | 8        | SF  | 4    | 0-1 year    | Water damage. |
|           | Chalk Board                 | 1st Floor | 20       | LF  | 4    | 2-5 years   |               |
|           | Doors - Wood Doors inclu hw | 1st Floor | 1        | EA  | 7    | 10+ years   |               |
|           | Floor - Tile                | 1st Floor | 753      | SF  | 6    | 10+ years   |               |
|           | Lighting - Lay-in           | 1st Floor | 10       | EΑ  | 7    | 10+ years   |               |
|           | Walls - Metal Panel         | 1st Floor | 870      | SF  | 6    | 10+ years   |               |
|           | Work Sink                   | 1st Floor | 1        | EΑ  | 7    | 10+ years   |               |
|           |                             |           |          |     |      |             |               |
| _Classroo | om #402B (Pre School)       |           |          |     |      |             |               |
|           | Ceiling - Lay-in            | 1st Floor | 829      | SF  | 7    | 10+ years   |               |
|           | Chalk Board                 | 1st Floor | 20       | LF  | 4    | 2-5 years   |               |
|           | Doors - Wood Doors inclu hw | 1st Floor | 1        | EΑ  | 7    | 10+ years   |               |
|           | Floor - Tile                | 1st Floor | 829      | SF  | 7    | 10+ years   |               |
|           | Lighting - Lay-in           | 1st Floor | 11       | EΑ  | 7    | 10+ years   |               |
|           | Walls - Metal Panel         | 1st Floor | 939      | SF  | 7    | 10+ years   |               |
|           | Work Sink                   | 1st Floor | 1        | EA  | 7    | 10+ years   |               |
|           |                             |           |          |     |      |             |               |
| _Classroo | om #403C (Pre School)       |           |          |     |      |             |               |
|           | Ceiling - Lay-in            | 1st Floor | 737      | SF  | 7    | 10+ years   |               |
|           |                             |           |          |     |      |             |               |

Campus Name: Herzl Page : 42 of 47 Assessment Date: 04/18/2022



Lighting - Lay-in Walls - Metal Panel

#### Theodore Herzl Elementary School 3711 W Douglas BOULEVARD, Chicago, IL 60623

| Catego   | ry : Classroom                       |           | В        | Building : Branch-CPC |         |             |  |  |  |
|----------|--------------------------------------|-----------|----------|-----------------------|---------|-------------|--|--|--|
|          |                                      |           |          |                       |         | Recommend   |  |  |  |
| Group    | Item - Type                          | Location  | Quantity | UOM                   | Rank    | Replacement | Comments   |  |  |
|          | Ceiling - Lay-in                     | 1st Floor | 16       | SF                    | 4       | 0-1 year    | Water damage   |  |  |
|          | Chalk Board                          | 1st Floor | 35       | LF                    | 4       | 2-5 years   |  |  |  |
|          | Doors - Wood Doors inclu hw          | 1st Floor | 1        | EA                    | 7       | 10+ years   |  |  |  |
|          | Floor - Tile                         | 1st Floor | 753      | SF                    | 6       | 10+ years   |  |  |  |
|          | Lighting - Lay-in                    | 1st Floor | 10       | EA                    | 7       | 10+ years   |  |  |  |
|          | Walls - Metal Panel                  | 1st Floor | 870      | SF                    | 7       | 10+ years   |  |  |  |
|          | Work Sink                            | 1st Floor | 1        | EA                    | 7       | 10+ years   |  |  |  |
| Classroo | om #404D (Pre School)                |           |          |                       |         |             |  |  |  |
|          | Casework                             | 1st Floor | 4        | LF                    | 7       | 10+ years   |  |  |  |
|          | Ceiling - Lay-in                     | 1st Floor | 741      | SF                    | 7       | 10+ years   |  |  |  |
|          | Ceiling - Lay-in                     | 1st Floor | 15       | SF                    | 4       | 0-1 year    | Water damage   |  |  |
|          | Chalk Board                          | 1st Floor | 24       | LF                    | 4       | 2-5 years   | <del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> - <del>-</del> - <del>-</del> |  |  |
|          | Doors - Wood Doors inclu hw          | 1st Floor | 1        | ĒΑ                    | 7       | 10+ years   |  |  |  |
|          | Floor - Tile                         | 1st Floor | 756      | SF                    | 6       | 10+ years   |  |  |  |
|          | Lighting - Lay-in                    | 1st Floor | 10       | ĒΑ                    | 7       | 10+ years   |  |  |  |
|          | Walls - Metal Panel                  | 1st Floor | 880      | SF                    | 7       | 10+ years   |  |  |  |
|          | Work Sink                            | 1st Floor | 1        | ĒΑ                    | 7       | 10+ years   |  |  |  |
| Classroo | om #405E (Store Room)                |           |          |                       |         |             |  |  |  |
|          | Ceiling - Lay-in                     | 1st Floor | 652      | SF                    | 7       | 10+ years   |  |  |  |
|          | Chalk Board                          | 1st Floor | 15       | LF                    | 4       | 2-5 years   |  |  |  |
|          | Doors - Wood Doors inclu hw          | 1st Floor | 1        | EA                    | 7       | 10+ years   |  |  |  |
|          | Floor - Tile                         | 1st Floor | 652      | SF                    | 6       | 10+ years   |  |  |  |
|          | Lighting - Lay-in                    | 1st Floor | 10       | EΑ                    | 7       | 10+ years   |  |  |  |
|          | Walls - Metal Panel                  | 1st Floor | 820      | SF                    | 7       | 10+ years   |  |  |  |
| Catego   | ory : Interior                       |           | В        | uilding               | : Branc | h-CPC       |  |  |  |
|          |                                      |           |          |                       |         | Recommend   |  |  |  |
| Group    | Item - Type                          | Location  | Quantity | UOM                   | Rank    | Replacement | Comments   |  |  |
| Corridor |                                      |           |          |                       |         |             |  |  |  |
|          | Ceiling - Lay-in                     | 1st Floor | 1,310    | SF                    | 7       | 10+ years   |  |  |  |
|          | Ceiling - Lay-in                     | 1st Floor | 14       | SF                    | 4       | 0-1 year    | Water damage.  |  |  |
|          | Doors - Steel Doors incl hw          | 1st Floor | 8        | EA                    | 7       | 10+ years   | -  |  |  |
|          | Drinking Fountains - Double Fountain | 1st Floor | 1        | EA                    | 7       | 6-10 years  |  |  |  |
|          | Drinking Fountains - Single Fountain | 1st Floor | 1        | EA                    | 7       | 6-10 years  |  |  |  |
|          | Floor - Concrete                     | 1st Floor | 104      | SF                    | 7       | 10+ years   |  |  |  |
|          | Floor - Tile/Sheet                   | 1st Floor | 1,220    | SF                    | 7       | 6-10 years  |  |  |  |
|          | Lighting - Lay-in                    | 1st Floor | 17       | ĒΑ                    | 7       | 10+ years   |  |  |  |
|          | Wells Motel Bonel                    | 1st Floor | 2.655    | SE.                   | 7       | 10. voore   |  |  |  |

10+ years

2,655 SF

1st Floor



Category : Site Building : Site

| atego      | ry : Site                         |                   |          | ullaing | . 0  |                        |                               |
|------------|-----------------------------------|-------------------|----------|---------|------|------------------------|-------------------------------|
|            |                                   |                   |          |         |      | Recommend              |                               |
| roup       | Item - Type                       | Location          | Quantity | UOM     | Rank | Replacement            | Comments                      |
| hletic     |                                   |                   |          |         |      |                        |                               |
|            | Surface - Asphalt                 | Main              | 9,380    | SF      | 4    | 0-1 year               | Cracking                      |
|            |                                   |                   |          |         |      |                        |                               |
| Civil/Drai | nage                              |                   |          |         |      |                        |                               |
|            | Civil/ Drainage - Site Manhole    | Branch - CPC site | 3        | EA      | 6    | 6-10 years             |                               |
|            | Civil/ Drainage - Site Manhole    | Branch - CPC site | 1        | EA      | 6    | 6-10 years             |                               |
|            | Civil/ Drainage - Catch Basin     | Main              | 6        | EA      | 6    | 10+ years              |                               |
|            | Civil/ Drainage - Site Drain      | Main              | 1        | EA      | 6    | 10+ years              |                               |
|            | Civil/ Drainage - Site Manhole    | Main              | 11       | EA      | 6    | 10+ years              |                               |
|            | Civil/ Drainage - Site Manhole    | Main              | 1        | EΑ      | 5    | 6-10 years             |                               |
|            | Š                                 |                   |          |         |      |                        |                               |
| encing     |                                   |                   |          |         |      |                        |                               |
|            | Fencing - Chain Link              | Branch - CPC site | 800      | LF      | 5    | 2-5 years              |                               |
|            | Fencing - Chain Link              | Branch - CPC site | 60       | LF      | 4    | 0-1 year               | Bent / leaning                |
|            | Fencing - Chain Link              | Main              | 200      | LF      | 6    | 10+ years              |                               |
|            | Fencing - Guard Rail              | Main              | 45       | LF      | 6    | 10+ years              |                               |
|            | Fencing - New Standard Ornamental | Main              | 440      | LF      | 6    | 6-10 years             |                               |
|            | Fencing - Old Standard Ornamental | Main              | 1,835    | LF      | 4    | 0-1 year               | Rusted                        |
|            | Fencing - Old Standard Ornamental | Main              | 15       | LF      | 4    | 0-1 year               | Bent                          |
|            | -                                 |                   |          |         |      | -                      |                               |
| andsca     |                                   |                   |          |         |      |                        |                               |
|            | Landscape - Grass                 | Branch - CPC site | 20,000   | SF      | 6    | 10+ years              | Missed in prior assessment    |
|            | Parkway trees                     | Branch - CPC site | 8        | EA      | 6    | 10+ years              | Missed in prior               |
|            | Planting Beds/ Area               | Branch - CPC site | 300      | SF      | 6    | 6-10 years             | Area added to grass line item |
|            | Play Area - Hardscape- Concrete   | Branch - CPC site | 1,000    | SF      | 4    | 0-1 year               | Crumbling,                    |
|            | Play Area - Hardscape- Concrete   | Branch - CPC site | 6,000    | SF      | 4    | 0-1 year               | Concrete heaving, cracking    |
|            |                                   |                   | -,       | -       |      | 5 · <b>,</b> 5 · · ·   | throughout.                   |
|            | Trash Receptacles                 | Branch - CPC site | 2        | EA      | 6    | 10+ years              | 3                             |
|            | Benches                           | Main              | 7        | ΕA      | 7    | 10+ years              |                               |
|            | Landscape - Grass                 | Main              | 17,540   | SF      | 6    | 6-10 years             |                               |
|            | Landscape - Hardscape- Asphalt    | Main              | 2,755    | SF      | 6    | 6-10 years             |                               |
|            | Landscape - Hardscape- Asphalt    | Main              | 2,125    | SF      | 4    | 0-10 years<br>0-1 year | Cracking and potholes         |
|            |                                   |                   |          |         |      |                        | Cracking and politicles       |
|            | Landscape - Hardscape- Concrete   | Main              | 5,950    | SF      | 6    | 6-10 years             |                               |
|            | Parkway trees                     | Main              | 31       | EA      | 6    | 6-10 years             |                               |
|            | Planting Beds/ Area               | Main              | 3,490    | SF      | 7    | 10+ years              |                               |
|            | Play Area - Hardscape- Asphalt    | Main              | 500      | SF      | 6    | 2-5 years              |                               |
|            | Play Area - Hardscape- Asphalt    | Main              | 12,880   | SF      | 5    | 6-10 years             | Cracking and uneven surface   |
|            | Trash Receptacles                 | Main              | 3        | EA      | 6    | 10+ years              |                               |
|            | ot                                |                   |          |         |      |                        |                               |
| Parking I  | -VI                               |                   |          |         |      |                        |                               |
| Parking I  | Trash Enclosure - Chain Links     | Branch - CPC site | 200      | SF      | 6    | 6-10 years             |                               |

Campus Name: Herzl Page : 44 of 47 Assessment Date: 04/18/2022



#### **Theodore Herzl Elementary School**

3711 W Douglas BOULEVARD, Chicago, IL 60623

| Category : Site |   |                          | В        | Building : Site |      |             | bodgido boole vitto, omodgo, le ocozo         |
|-----------------|---|--------------------------|----------|-----------------|------|-------------|---|
|                 |   |                          | _        |                 |      | Recommend   |   |
| Group           | Item - Type                                 | Location                 | Quantity | UOM             | Rank | Replacement | Comments                                      |
|                 | Surface - Asphalt                           | Main - East              | 800      | SF              | 4    | 0-1 year    | Cracking / potholes                           |
|                 | Trash Enclosure - Chain Links               | Main - East              | 450      | SF              | 6    | 6-10 years  |   |
|                 | Concrete Curbs                              | Main - NE corner of site | 85       | LF              | 7    | 10+ years   |   |
|                 | Surface - Asphalt                           | Main - NE corner of site | 3,245    | SF              | 6    | 10+ years   | Minor cracking in the middle                  |
|                 | Surface - Asphalt                           | Main - NW                | 10,000   | SF              | 6    | 6-10 years  | Missed in prior assessment. Cracking observed |
| Playgrou        | ınd   |                          |          |                 |      |             |   |
|                 | Equipment - Combo 3-12                      | Main - SE                | 1        | EA              | 6    | 6-10 years  |   |
|                 | Surface - Poured Surface                    | Main - SE                | 2,185    | SF              | 5    | 2-5 years   | Minor holes                                   |
|                 | Equipment - Combo 3-12                      | Main - West              | 1        | EA              | 6    | 6-10 years  |   |
|                 | Surface - Poured Surface                    | Main - West              | 1,945    | SF              | 5    | 2-5 years   | Minor holes.                                  |
| Sidewall        | (S  |                          |          |                 |      |             |   |
|                 | Sidewalks - Internal Walks                  | Branch - CPC site        | 470      | LF              | 6    | 6-10 years  |   |
|                 | Sidewalks - Perimeter Sidewalks             | Branch - CPC site        | 1,000    | SF              | 6    | 6-10 years  |   |
|                 | Sidewalks - Internal Walks                  | Main                     | 30       | LF              | 6    | 6-10 years  |   |
|                 | Sidewalks - Internal Walks                  | Main                     | 710      | LF              | 6    | 6-10 years  |   |
|                 | Sidewalks - Perimeter Sidewalks             | Main                     | 17,400   | SF              | 6    | 6-10 years  |   |
|                 | Sidewalks - Perimeter Sidewalks             | Main                     | 100      | SF              | 4    | 0-1 year    | Cracked near door 2                           |
| Signage         |   |                          |          |                 |      |             |   |
|                 | Monument - Sign                             | Branch - CPC site        | 2        | EA              | 6    | 6-10 years  |   |
|                 | Flag Pole - Flag Pole                       | Main                     | 1        | EA              | 6    | 6-10 years  |   |
|                 | Marquee - Free Standing Back Lighted        | Main                     | 1        | EA              | 6    | 6-10 years  |   |
|                 | Marquee - Free Standing Back Lighted        | Main                     | 1        | EA              | 6    | 6-10 years  |   |
|                 | Monument - Building Mounted Cut Letter Sign | Main                     | 1        | EA              | 6    | 10+ years   |   |

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Herzl Page : 45 of 47 Assessment Date: 04/18/2022

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

| Classroom Summary   |                   |               |        | Floor Plan |       | Glazed | Operable |        |        |
|---------------------|-------------------|---------------|--------|------------|-------|--------|----------|--------|--------|
|                     |                   |               | Room   | Room       | Area  | Window | Window   | Window | Smart- |
| Current Usage       | Intended Usage    | Room Location | Number | Number     | (SF)  | Area   | Area     | Stop   | Board  |
| Building : Main     |                   | ·             |        |            |       |        |          |        |        |
| Pre School          | Regular Classroom | 1st Floor     | 101    | 101        | 870   | 210    | 84       | N      | N      |
| Pre School          | Regular Classroom | 1st Floor     | 102    | 102        | 870   | 210    | 84       | N      | N      |
| Regular Classroom   | Computer Lab      | 2nd Floor     | 215    | 215        | 780   | 180    | 90       | N      | N      |
| Regular Classroom   | Kindergarten      | 1st Floor     | 123    | 123        | 871   | 175    | 70       | N      | N      |
| Regular Classroom   | Regular Classroom | 1st Floor     | 103    | 103        | 870   | 210    | 84       | N      | Y      |
| Regular Classroom   | Regular Classroom | 1st Floor     | 104    | 104        | 870   | 210    | 126      | N      | N      |
| Regular Classroom   | Regular Classroom | 1st Floor     | 105    | 105        | 870   | 210    | 84       | N      | N      |
| Regular Classroom   | Regular Classroom | 1st Floor     | 108    | 108        | 870   | 210    | 84       | N      | N      |
| Regular Classroom   | Regular Classroom | 1st Floor     | 115    | 115        | 870   | 252    | 126      | N      | N      |
| Regular Classroom   | Regular Classroom | 1st Floor     | 120    | 120        | 871   | 210    | 90       | N      | N      |
| Regular Classroom   | Regular Classroom | 1st Floor     | 121    | 121        | 871   | 210    | 84       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 201    | 201        | 795   | 125    | 62       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 202    | 202        | 795   | 150    | 75       | N      | Υ      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 204    | 204        | 795   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 205    | 205        | 795   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 206    | 206        | 795   | 125    | 62       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 207    | 207        | 915   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 208    | 208        | 915   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 209    | 209        | 915   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 210    | 210        | 915   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 211    | 211        | 915   | 180    | 90       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 212    | 212        | 915   | 180    | 90       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 213    | 213        | 915   | 180    | 90       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 214    | 214        | 830   | 180    | 90       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 216    | 216        | 870   | 180    | 90       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 218    | 218        | 795   | 125    | 62       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 219    | 219        | 795   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 220    | 220        | 795   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 221    | 221        | 795   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 222    | 222        | 795   | 150    | 75       | N      | N      |
| Regular Classroom   | Regular Classroom | 2nd Floor     | 223    | 223        | 795   | 125    | 62       | N      | N      |
| Regular Classroom   | Regular Classroom | 3rd Floor     | 323    | 323        | 871   | 180    | 90       | N      | N      |
| Regular Classroom   | Store Room        | 1st Floor     | 149    | Store room | 655   | 35     | 14       | N      | N      |
| Science             | Regular Classroom | 2nd Floor     | 203    | 203        | 795   | 150    | 75       | N      | N      |
| Science Lab Level 1 | Regular Classroom | 3rd Floor     | 303    | 303        | 871   | 180    | 90       | N      | N      |
| Store Room          | Kindergarten      | 1st Floor     | 107    | 107        | 870   | 210    | 84       | N      | N      |
| Store Room          | Kindergarten      | 1st Floor     | 116    | 116        | 1,039 | 245    | 147      | N      | N      |
| Store Room          | Regular Classroom | 1st Floor     | 122    | 122        | 871   | 210    | 84       | N      | N      |



**Classroom Summary** 

|               |                   |               | Room   | Floor Plan<br>Room | Area | Glazed<br>Window | Operable<br>Window | Window | Smart- |
|---------------|-------------------|---------------|--------|--------------------|------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage    | Room Location | Number | Number             | (SF) | Area             | Area               | Stop   | Board  |
| Vacant        | Regular Classroom | 3rd Floor     | 302    | 302                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 304    | 304                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 305    | 305                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 306    | 306                | 889  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 307    | 307                | 871  | 180              | 90                 | N      | Y      |
| Vacant        | Regular Classroom | 3rd Floor     | 308    | 308                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 310    | 310                | 870  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 315    | 315                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 316    | 316                | 870  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 317    | 317                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 318    | 318                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 319    | 319                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 320    | 320                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 321    | 321                | 871  | 180              | 90                 | N      | N      |
| Vacant        | Regular Classroom | 3rd Floor     | 322    | 322                | 871  | 180              | 90                 | N      | N      |
| Weight        | Regular Classroom | 3rd Floor     | 301    | 301                | 871  | 180              | 90                 | N      | N      |

| Building : Branch-CPC |            |           |      |     |     |     |    |   |   |
|-----------------------|------------|-----------|------|-----|-----|-----|----|---|---|
| Pre School            | Pre School | 1st Floor | 401A | 103 | 753 | 100 | 10 | N | N |
| Pre School            | Pre School | 1st Floor | 402B | 102 | 829 | 100 | 10 | N | N |
| Pre School            | Pre School | 1st Floor | 403C | 101 | 753 | 100 | 10 | N | N |
| Pre School            | Pre School | 1st Floor | 404D | 104 | 756 | 100 | 10 | N | N |
| Store Room            | Pre School | 1st Floor | 405E | 111 | 652 | 100 | 10 | N | N |

Campus Name: Herzl Page : 47 of 47 Assessment Date: 04/18/2022