

8905 S Crandon AVENUE, Chicago, IL 60617

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1955	1	17,859
Addition	1998	1	10,125
Campus Total			27,984

Catego	Category : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#10	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#10	10	LF	7	10+ years	
	Ramps - Concrete	#10	22	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#2	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2	6	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#3	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#3	10	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#8	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Main Entry #1	1	EA	7	10+ years	Missing enclosure/case
	Exterior Doors - Exterior Steel Door	Main Entry #1	2	EA	6	10+ years	-
	Exterior Doors - Side lite	Main Entry #1	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Main Entry #1	3	EA	6	10+ years	
oundat	on						
	Foundation - Concrete	Entire Building	760	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	10	SF	4	1-2 years	Room 102 west wall - Stepped Crac in CMU wall with major separation a juncture of wall and floor slab



Categor	y : Exterior		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Superstructure - Metal Deck/ Concrete	Entire Building	17,859	SF	7	10+ years	
	Topping						
Lighting							
Lighting	Exterior Lighting - Lighting	Entire Building	1	EA	5	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	5	6-10 years	
D (0							
Roof Sys		A Main	2	ΓΛ	7	10	
	Access Ladder - Metal	A Main	2	EA	7	10+ years	
	Chimney - Brick Chimney- Stainless Steel Liner	A Main	15	LF	7	10+ years	
	Chimney - Metal Flue	A Main	60	LF	6	10+ years	
	Coping - Metal	A Main	583	LF	7	10+ years	
	Coping - Stone	A Main	102	LF	7	10+ years	
	Downspouts - Interior Downspouts	A Main	46	LF	7	10+ years	
	Downspouts - Interior Downspouts	A Main	8	LF	6	10+ years	
	Parapet - 16" - 30" Height	A Main	102	LF	7	10+ years	
	Parapet - Parapet < 16" Height	A Main	583	LF	7	10+ years	Does not exist
	Roof - Asphalt Gravel Ballast	A Main	17,859	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	A Main	17,859	SF	7	10+ years	
	Concrete Topping	7	,000	О.	-	. o . y ca. c	
Walls							
walls	Canopy - Concrete/ Stucco	Entire Building	160	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	6,366	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	170	SF	4	0-1 year	Cracked bricks and mortar
	Exterior Walls - Blick	Entire Building	170	SF	4	0-1 year	Cracked bricks and mortar
Vindows							
	Guard - Guards perforated	Entire Building	2,264	SF	7	10+ years	
	Lintels - Steel	Entire Building	409	LF	7	10+ years	
	Windows - Louver	Entire Building	106	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,264	SF	6	10+ years	
Categor	y : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	OOW	IVALIK	Replacement	Comments
⊏mergen	cy System Emergency A/C Power - Corridors and	Entire Building	3,030	SF	6	6-10 years	
	Stairs - Corndors and	Entire building	3,030	SF	0	o-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years	

Campus Name: Hoyne Page : 2 of 22 Assessment Date: 04/19/2022



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - Intrusion Detection	Entire Building	27,984	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	9	EA	2	0-1 year	No battery packs, no AC generator
_Main Sei	vice						
	PA System	Main Office	27,984	SF	6	6-10 years	Connected to addition building
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	Served from addition building
	Main Distribution Panels - 400 - 600 amp	Entire Building	i	EA	7	10+ years	Functional panels rated 7, served from addition building
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Also serves addition building
	Fire Alarm Strobe Lights	Entire Building	17,859	SF	6	10+ years	
	Fire Alarm_System	Entire Building	27,984	SF	6	6-10 years	Connected to addition building
	- ,	S	,			,	S
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	UOIVI	Naiik	Replacement	Comments
_Boiler Sy		D " D					
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	2	EA	5	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	Manual feed
	Combustion Dampers	Boiler Room	1	EA	5	10+ years	1 for 2 boilers
	Glycol Feed System	Boiler Room	1	EA	5	10+ years	Manual feed
	Hot Water Pump	Boiler Room	2	EA	5	6-10 years	Serve boiler
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001	Boiler Room	2	EA	5	10+ years	Serves main building, 1998 installation
	- 2000 MBH						
	Water Fill System	Boiler Room	1	EA	6	6-10 years	Previously not assessed
Gas Boo	ster						
	Gas Booster	Boiler Room	1	EA	5	6-10 years	1998 Installation, not used, not needed
Heating	Devices						
3	Wall Heater - Electric	1st Floor	1	EA	6	10+ years	
	Wall Heater - Electric	1st Floor	1	EA	5	6-10 years	Recently repaired and cleaned
						•	• •
			•				Recently repaired and cleaned

Campus Name: Hoyne Page : 3 of 22 Assessment Date: 04/19/2022



	schools					89	05 S Crandon AVENUE, Chicago, IL 60617
Catego	ry : Mechanical		В	uilding	: Main		
		1	0			Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wall Heater - Electric	1st Floor	2	EΑ	5	6-10 years	Recently serviced
	Cabinet Heaters - With Hot Water Coil	1st Floor	5	EA	5	6-10 years	
	Fin Tube - Hot Water	Entire Building	190	LF	6	6-10 years	
Machan	ical Blumbing						
IVIECHALI	ical Plumbing Hydronic Supply and Return - Steel	Entire Building	200	LF	5	10+ years	1955 installation, minor leaks
	Hydronic Supply and Return - Steel	Entire Building	200	LF	5	10+ years	occasionally repaired
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	7	10+ years	1 Recently replaced, 1 being
	Hot Water Fullip - Less than 10	Mechanical Room	2	EA	,	10+ years	replaced, serve univents and cabinet
							heaters, 2022 installation
							neaters, 2022 installation
Tempera	ature Control						
	Electric Controls	Entire Building	27,984	SF	5	6-10 years	In univents. No DDC, no pneumatic
		9	_,,,,,,		•	5 . c , c c	system
							,
Unit Ver							
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	8	EA	5	6-10 years	Recently replaced many blower
	Heating Coils Only						motors
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	2	EA	4	2-5 years	Require frequentrepair
	Heating Coils Only						
_Ventilati	on Exhaust Fans- Roof Mounted - 1501 - 8000	Doof	2	EA	6	10	
	CFM	Roof	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	2	EA	4	2-5 years	Noisy, not ballanced
	CFM	Rooi	۷	LA	7	2-5 years	Noisy, not ballanced
	Exhaust Fans- Roof Mounted - Less than	Roof	1	EA	6	10+ years	1998 installation
	500 CFM	. 100.	•		· ·	. o · you.o	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves main building
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	17,859	SF	6	10+ years	Minor leaks occasionally repaired,
					_		1955 installation
	Domestic Piping-Hot/Cold Water Supply	Entire Building	17,859	SF	6	10+ years	1955 installation
	(Horizontal Lines)	F 0 B 110		6 -	_	40	1055 1 1 11 11
	Sanitary Piping	Entire Building	17,859	SF	6	10+ years	1955 installation
	Storm Piping	Entire Building	17,859	SF	6	10+ years	



Building: Main Category : Plumbing

Recommend Location UOM Group Item - Type Quantity Rank Replacement Comments

Vent Piping **Entire Building** 17,859 SF 10+ years 6

Category: Room **Building: Main**

Jaiego	ry . Room		U	unung	. IVIAIII	_	
	_					Recommend	_
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
minist	rative Suites/Offices						
	Ceiling - Splined	111-Teacher's Resource Room	188	SF	6	10+ years	
	Doors - Wood Doors inclu hw	111-Teacher's Resource Room	1	EA	6	10+ years	
	Floor - Tile	111-Teacher's Resource Room	188	SF	6	10+ years	
	Lighting - Pendent/Surface	111-Teacher's Resource Room	8	EA	7	6-10 years	
	Walls - Concrete Block	111-Teacher's Resource Room	396	SF	7	10+ years	
	Walls - Plaster/Drywall	111-Teacher's Resource Room	132	SF	7	10+ years	
	Work SInk	111-Teacher's Resource Room	1	EA	7	6-10 years	
	AC Unit	111A	1	EA	5	2-5 years	
	Ceiling - Splined	111A	94	SF	6	10+ years	
	Doors - Wood Doors inclu hw	111A	1	ĒΑ	7	10+ years	
	Floor - Tile	111A	94	SF	6	10+ years	
	Lighting - Pendent/Surface	111A	2	ĒΑ	7	6-10 years	
	Walls - Concrete Block	111A	180	SF	7	10+ years	
	AC Unit	Assistant Principal's Office	1	ĒΑ	5	2-5 years	
	Ceiling - Lay-in	Assistant Principal's Office	113	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal's Office	1	EΑ	7	10+ years	
	Floor - Tile	Assistant Principal's Office	113	SF	5	6-10 years	
	Lighting - Lay-in	Assistant Principal's Office	2	ĒΑ	7	6-10 years	
	Walls - Concrete Block	Assistant Principal's Office	192	SF	7	10+ years	
	Walls - Plaster/Drywall	Assistant Principal's Office	192	SF	7	10+ years	
	AC Unit	Main Office	1	EΑ	5	2-5 years	
	Ceiling - Lay-in	Main Office	285	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	ĒΑ	6	10+ years	
	Floor - Tile/Sheet	Main Office	285	SF	7	10+ years	
	Lighting - Lay-in	Main Office	6	EA	7	6-10 years	
	Storage/ Closet	Main Office	52	SF	7	10+ years	
	Walls - Concrete Block	Main Office	654	SF	7	10+ years	
	AC Unit	Principals Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principals Office	210	SF	6	10+ years	
	Doors - Steel Doors incl hw	Principals Office	1	ĒΑ	7	10+ years	
	Floor - Tile	Principals Office	210	SF	7	6-10 years	
	Lighting - Lay-in	Principals Office	4	EΑ	7	6-10 years	
	Walls - Concrete Block	Principals Office	210	SF	7	10+ years	
	20000	50	2.0	٥.	•	. o . youro	
hani	cal/ Service Rooms						
цаш	Boiler Room	1st Floor	740	SF	7	10+ years	
	Janitor's Closet	1st Floor	45	SF	7	10+ years	
	Storage Room	1st Floor	59	SF	7	10+ years	
	Otorage Nooni	1311 1001	59	OI.	,	IUT years	



Catego	ry : Room		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	1st Floor	31	SF	7	10+ years	
estroo							
	Accessories	102A	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	102A	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102A	1	EA	6	6-10 years	Door knob missing
	Floor - Tile	102A	30	SF	7	6-10 years	
	Lavatory	102A	1	EA	7	10+ years	
	Lighting - Lay-in	102A	1	EA	7	6-10 years	
	Walls - Concrete Block	102A	165	SF	7	10+ years	
	Water Closet	102A	1	EA	7	10+ years	
	Accessories	103A	23	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103A	23	SF	7	10+ vears	
	Doors - Wood Doors inclu hw	103A	1	ĒΑ	7	10+ years	
	Floor - Tile	103A	23	SF	6	6-10 years	
	Lavatory	103A	1	EA	7	10+ years	
	Lighting - Lay-in	103A	1	EA	7	10+ years	
	Walls - Concrete Block	103A	142	SF	7	10+ years	
	Water Closet	103A	1	EA	7	10+ years	
	Accessories	103A 104A	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	104A 104A	30	SF	7	10+ years	
				EA			
	Doors - Wood Doors inclu hw	104A	1		7	10+ years	
	Floor - Tile	104A	30	SF	7	6-10 years	
	Lavatory	104A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	104A	1	EA	7	6-10 years	
	Walls - Concrete Block	104A	198	SF	7	10+ years	
	Water Closet	104A	1	EA	7	10+ years	
	Accessories	105A	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105A	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105A	1	EA	7	10+ years	
	Floor - Tile	105A	30	SF	7	6-10 years	
	Lavatory	105A	1	EA	6	10+ years	
	Lighting - Lay-in	105A	1	EA	7	6-10 years	
	Walls - Concrete Block	105A	165	SF	7	10+ years	
	Water Closet	105A	1	EA	7	10+ years	
	Accessories	106A	17	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	106A	17	SF	7	10+ years	
	Doors - Wood Doors inclu hw	106A	1	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	106A	17	SF	7	6-10 years	
	Lighting - Lay-in	106A	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	106A	119	SF	7	10+ years	
	Water Closet	106A	1	EA	7	10+ years	
	Accessories	100A 107A	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	107A 107A	30	SF	7	•	
	Gening - Flaster/Drywall	IUIA	30	SF	′	10+ years	



Category : Room Building :		: Main					
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	107A	1	EA	7	10+ years	
	Floor - Tile	107A	30	SF	7	6-10 years	
	Lavatory	107A	1	EA	7	10+ years	
	Lighting - Lay-in	107A	1	EA	7	6-10 years	
	Walls - Concrete Block	107A	165	SF	7	10+ years	
	Water Closet	107A	1	EA	7	10+ years	
	Accessories	108A	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	108A	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108A	1	EA	7	10+ years	
	Floor - Tile	108A	27	SF	7	6-10 years	
	Lavatory	108A	1	EA	7	10+ years	
	Lighting - Lay-in	108A	1	EA	7	6-10 years	
	Walls - Concrete Block	108A	156	SF	7	10+ years	
	Water Closet	108A	1	EA	7	10+ years	
	Accessories	110A	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	110A	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	110A	1	EA	7	10+ years	
	Floor - Tile/Sheet	110A	30	SF	7	6-10 years	
	Lavatory	110A	1	EA	6	10+ years	
	Lighting - Lay-in	110A	1	EA	6	6-10 years	
	Walls - Concrete Block	110A	165	SF	7	10+ years	
	Water Closet	110A	1	EA	7	10+ years	
	Accessories	112A	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	112A	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	112A	1	EA	6	10+ years	
	Floor - Tile	112A	28	SF	6	6-10 years	
	Lavatory	112A	1	EA	7	6-10 years	
	Lighting - Lay-in	112A	1	EA	7	6-10 years	
	Walls - Concrete Block	112A	159	SF	6	10+ years	
	Water Closet	112A	1	ĒΑ	6	10+ years	
	Accessories	Boiler Room	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boiler Room	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boiler Room	1	ĒΑ	7	10+ years	
	Floor - Concrete	Boiler Room	70	SF	5	1-2 years	Cracked concrete
	Lavatory	Boiler Room	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	7	6-10 years	
	Walls - Concrete Block	Boiler Room	252	SF	7	10+ years	
	Water Closet	Boiler Room	1	EΑ	7	10+ years	
	Accessories	Boys Toilet	207	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys Toilet	207	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys Toilet	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys Toilet	207	SF	7	10+ years	
	Floor Drain	Boys Toilet	1	EA	7	10+ years	
	Lavatory	Boys Toilet	2	EA	7	6-10 years	
		20,0 101101	_	_, .	•	o io youio	



Catego	ry : Room		В	uilding	: Main	·	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Boys Toilet	2	EA	7	6-10 years	
	Partitions	Boys Toilet	1	EA	7	10+ years	
	Urinals	Boys Toilet	2	EA	7	10+ years	
	Walls - Concrete Block	Boys Toilet	25	SF	5	1-2 years	Large crack
	Walls - Concrete Block	Boys Toilet	488	SF	5	10+ years	
	Water Closet	Boys Toilet	1	EA	7	10+ years	
	Accessories	Girls Toilet	238	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls Toilet	238	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Girls Toilet	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Toilet	238	SF	7	10+ years	
	Floor Drain	Girls Toilet	1	EA	4	10+ years	Missing drain grill
	Lavatory	Girls Toilet	2	EA	7	10+ years	-
	Lighting - Lay-in	Girls Toilet	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Girls Toilet	2	EA	7	6-10 years	
	Partitions	Girls Toilet	3	EA	7	10+ years	
	Walls - Concrete Block	Girls Toilet	576	SF	7	10+ years	
	Water Closet	Girls Toilet	3	EA	7	10+ years	
	Accessories	Staff Toilet @ Principals Office	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff Toilet @ Principals Office	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff Toilet @ Principals Office	1	EA	7	10+ years	
	Floor - Tile	Staff Toilet @ Principals Office	27	SF	7	10+ years	
	Lavatory	Staff Toilet @ Principals Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Staff Toilet @ Principals Office	1	EA	7	6-10 years	
	Partitions	Staff Toilet @ Principals Office	1	EA	7	10+ years	
	Walls - Concrete Block	Staff Toilet @ Principals Office	161	SF	7	10+ years	
	Water Closet	Staff Toilet @ Principals Office	1	EA	7	10+ years	

Category : Classroom **Building: Main**

on Quantity	UOM	D I-		
- Cultility	OOW	Rank	Replacement	Comments
oor 633	SF	7	10+ years	
oor 1	EΑ	7	10+ years	
oor 633	SF	7	6-10 years	
oor 9	EA	7	6-10 years	
oor 24	LF	7	6-10 years	
oor 9	EA	7	10+ years	
oor 869	SF	7	10+ years	
oor 1	EA	7	6-10 years	
oor 1	EA	5	1-2 years	Missing cover
oor 40	LF	7	10+ years	-
oor 869	SF	7	10+ years	
	poor 633 poor 633 poor 633 poor 99 poor 24 poor 99 poor 869	Door 633 SF Door 1 EA Door 633 SF Door 9 EA Door 24 LF Door 9 EA Door 869 SF Door 1 EA Door 1 EA Door 40 LF	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	633 SF 7 10+ years foor 1 EA 7 10+ years foor 633 SF 7 6-10 years foor 9 EA 7 6-10 years foor 24 LF 7 6-10 years foor 9 EA 7 10+ years foor 9 EA 7 10+ years foor 1 EA 7 10+ years foor 1 EA 7 6-10 years foor 1 EA 7 10+ years foor 1 EA 7 10+ years



Catego	ry : Classroom		R	uilding	· Main		505 S Claridon Avenue, Chicago, il 60617
Calego	iy . Glassioolii			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cicap	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	869	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	11	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	870	SF	7	10+ years	
Classroo	om #103 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	896	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	896	SF	7	6-10 vears	
	Lighting - Lay-in	1st Floor	11	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	11	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,091	SF	7	10+ years	
Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	21	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	869	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	869	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	11	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	978	SF	7	10+ years	
Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	38	LF	6	10+ years	
	Ceiling - Splined	1st Floor	944	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	944	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	11	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	1,055	SF	7	10+ years	
Classroo	om #106 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	



Catego	ry : Classroom		R	uilding	· Main		05 S Clandon AVENUE, Chicago, IL 60617
Guiogo			_	anamg	· Maii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Splined	1st Floor	1,141	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,141	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	[′] 21	ĒA	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,169	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	38	LF	6	10+ years	
	Ceiling - Splined	1st Floor	954	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	954	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	11	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	792	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	264	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #108 (Regular Classroom)						
	Casework	1st Floor	21	LF	7	10+ years	
	Ceiling - Splined	1st Floor	821	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	821	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	25	LF	7	6-10 years	
	Storage/ Closet	1st Floor	18	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	11	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	482	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	482	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Gasework	13.1 1001	9	LI	1	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Splined	1st Floor	575	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	575	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Student Lockers - One Tier	1st Floor	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	190	SF	7	10+ years	
lassroc	om #110 (Regular Classroom)						
	Casework	1st Floor	43	LF	6	10+ years	
	Ceiling - Splined	1st Floor	963	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	953	SF	7	6-10 years	
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Tile damage
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	7	6-10 years	9-
	Storage/ Closet	1st Floor	16	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	11	ĒΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	1,019	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
Classroc	om #112 (Other Instructional Use)						
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Splined	1st Floor	344	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	344	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	7	EΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	16	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	171	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	171	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroc	om #113 (Computer Lab)						
	Casework	1st Floor	48	LF	6	10+ years	
	Ceiling - Splined	1st Floor	636	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	636	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years	
	Ligiting - i chacilizatilace						



Catego	Category : Classroom			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	651	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	217	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	m #114 (Regular Classroom)						
	Casework	1st Floor	74	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	870	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	870	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	979	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	

Category: Interior **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	North Corridor	93	SF	6	10+ years	
	Ceiling - Splined	North Corridor	1,649	SF	6	10+ years	
	Doors - Steel Doors incl hw	North Corridor	4	EA	7	10+ years	
	Doors - Wood Doors include hw	North Corridor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	North Corridor	2	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	North Corridor	84	SF	7	10+ years	
	Floor - Tile/Sheet	North Corridor	1,658	SF	7	10+ years	
	Lighting - Pendent/Surface	North Corridor	19	EA	7	6-10 years	
	Walls - Concrete Block	North Corridor	1,904	SF	7	10+ years	
	Walls - Masonry	North Corridor	180	SF	7	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	5	EA	7	6-10 years	



Category : Exterior Building : Addition

ategory : Exterior			Building : Addition					
	Hans True	Lagation	0	LICA	Devil	Recommend	Comm.===1=	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
trance								
	Exterior Doors - Exterior Steel Door	#4	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#5	2	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#6	2	EA	7	10+ years		
	Entrance Control - Audio	#7	1	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	#7	2	EA	7	10+ years		
	Power Door Operator and Controls	#7	1	EA	7	6-10 years		
oundati	on							
	Foundation - Concrete	Entire Building	421	LF	7	10+ years		
	Superstructure - Metal Deck/ Concrete	Entire Building	10,125	SF	7	10+ years		
	Topping	Litting Building	10,120	O.	•	io. you.o		
ghting								
Junia.	Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	6-10 years		
		Ü				•		
of Sys								
	Access Ladder - Metal	Roof B	1	EA	7	10+ years		
	Chimney - Metal Flue	Roof B	70	LF	6	10+ years		
	Coping - Stone	Roof B	251	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof B	42	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof B	176	LF	7	10+ years		
	Parapet - Parapet > 30"	Roof B	75	LF	7	10+ years		
	Roof - Modified Bitumen	Roof B	6,500	SF	6	6-10 years		
	Roof - Modified Bitumen	Roof B	100	SF	5	2-5 years		
	Roof Hatch - Metal	Roof B	1	EA	7	10+ years		
	Roof Structure - Steel / Metal Deck/	Roof B	6,600	SF	7	10+ years		
	Concrete Topping	NOOI D	0,000	Ji	,	ioi yeais		
	Access Ladder - Metal	Roof C	1	EA	7	10+ years		
	Coping - Stone	Roof C	244	LF	7	10+ years		
	Downspouts - Interior Downspouts	Roof C	44	LF	7	•		
			244	LF LF	-	10+ years		
	Parapet - Parapet > 30"	Roof C		LF SF	7	10+ years		
	Roof - Modified Bitumen	Roof C	3,375		7	6-10 years		
	Roof - Modified Bitumen	Roof C	150	SF	5	2-5 years		
	Roof Structure - Steel / Metal Deck/	Roof C	3,525	SF	7	10+ years		
	Concrete Topping							
Valls								
	Canopy - Metal	Entire Building	30	SF	7	10+ years		
	Exterior Walls - Brick	Entire Building	5,695	SF	7	10+ years		
	Exterior Walls - Stone-Cast	Entire Building	516	SF	7	10+ years		



Catego	ry : Exterior		В	uilding	: Additi	on	
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
/indows							
	Clerestory - Glass Double-Pane	Entire Building	54	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	315	SF	7	10+ years	
	Lintels - Steel	Entire Building	120	LF	7	10+ years	
	Windows - Decorative	Entire Building	180	SF	6	10+ years	
	Windows - Louver	Entire Building	63	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	315	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Additi	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Security System - CCTV	1st Floor	10,125	SF	5	6-10 years	Exterior cameras only
	Security System - Intrusion Detection	1st Floor	10,125	SF	5	6-10 years	Previously not assessed
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Serves additionbuilding
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,225	SF	6	10+ years	
	Emergency A/C Power - Multipurpose	Entire Building	3,098	SF	6	10+ years	
	Room	Entire building	3,090	Si	Ü	10+ years	
	Emergency Battery Packs - Corridors and	Entire Building	4	EA	6	6-10 years	1998 installation
	Stairs						
	Emergency Battery Packs - Multipurpose	Entire Building	2	EA	6	6-10 years	
	Room						
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	1998 installation
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	With batteries
lain Se	rvice						
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	Served by ATS and second electric
	emergency power						meter, previously not assessed
	Main Electrical Service - 1000 A 120/240/3PH	Electrical Room	1	EA	6	10+ years	Serves addition and main building,
	120/240/3111						
ower D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	1998 installation
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Functional panel rated 7, also serving main building
atego	ry : Fire Protection		В	uilding	: Additi	on	
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						



Categor	y : Fire Protection		Building : Addition							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Fire Alarm Strobe Lights	Entire Building	10,125	SF	6	10+ years	1998 installation			
Sprinkler	System									
•	Sprinkler Heads	Entire Building	10,125	SF	7	10+ years	1998 installation			
	Sprinkler Piping	Entire Building	10,125	SF	7	10+ years	1998 installation			
	Wet Sprinkler System	Entire Building	10,125	SF	7	10+ years	Using city water pressure			
Categor	y : Mechanical		В	uilding	: Additi					
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Air Condi	tioning									
	Condensing Unit- Roof Mounted - 31-50 tons	Roof	1	EA	5	6-10 years	Serviced, functional, 1998 installation only 1 on lower roof			
Air Hand	ing Systems									
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 8001-12000 cfm	Boiler Room	1	EA	5	6-10 years	1998 installation			
	Air Intake	Boiler Room	1	EA	5	6-10 years	1998 installation			
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	4	EA	5	6-10 years	Located above ceilings, 1998 installation			
	Fan Power Box - Fan Power Box with No Coil	Entire Building	4	EA	6	10+ years	In. Addition only, located above ceilings			
	Make Up Air Unit- Roof Mounted- Gas Heating - 6000 - 10,000 cfm	Gym Roof	1	EA	5	6-10 years	1998 installation, located between 2 roof top units			
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating Coil - 5 - 10 tons	Gym Roof	2	EA	5	6-10 years	Recently serviced, tuned up, functional, 1998 installation, serve gym,			
Boiler Sy	stems									
Í	Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH	Boiler Room	2	EA	5	10+ years				
	Chemical Pot Feeder	Boiler Room	1	EA	5	6-10 years	Not painted, functional			
	Combustion Dampers	Boiler Room	1	EA	6	10+ years	- · · · · · · · · · · · · · · · · · · ·			
	Glycol Feed System	Boiler Room	1	EA	5	6-10 years	Manually fed			
	Hot Water Pump	Boiler Room	2	EA	5	6-10 years	Older, not reliable			
	Non Condensing- Flexible Tube-	Boiler Room	2	EA	5	10+ years	Serves addition, 1998 installation			
	Atmospheric- Hot Water Boiler - 500 - 1000 MBH					•				
	Water Fill System	Boiler Room	1	EA	5	6-10 years				
Gas Boos	ster									
Gas boo										

Campus Name: Hoyne Page : 15 of 22 Assessment Date: 04/19/2022



Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hooting	Devices						
пеашу	Radiator Panels - Hot Water	1st Floor	2	EA	6	10+ years	In restrooms, 1998 installation
	Cabinet Heaters - With Hot Water Coil	1st Floor	1	EA	6	10+ years	1998 installation, ceiling mounted
	Unit Heater - Hot Water	Mechanical Room	1	EA	5	6-10 years	1998 installation
	Offit Heater - Hot Water	Mechanical Room	1	EA	5	6-10 years	1990 IIIStaliation
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Mechanical Room	100	LF	6	10+ years	1998 installation
Tempera	ature Control						
	DDC System	Entire Building	10,125	SF	6	6-10 years	Software recently upgraded, only in
	Thermostats - DDC	Entire Building	8	EA	6	6-10 years	addition building
	memosiais - DDC	Entire building	0	EA	b	6-10 years	
Ventilation							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	5	6-10 years	1998 installation
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	2	EA	5	6-10 years	Not painted, previously not assesse
	CFM	1.00.	_	_, 、	Ŭ	o lo youlo	ret painted, providedly not access
	Roof Mounted Duct Work	Roof	50	LF	5	6-10 years	Not painted, functional, previously rassessed
Catego	ry : Plumbing		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	7	10+ years	Serves addition building, 2020 installation
	Gas Heater - Less than 150000 BTU/HR	Kitchen- 1st Floor	1	EA	6	6-10 years	Serves kitchen
	200 man 100000 210/1110	Tatonon Totaloo	·		Ü	o ro youro	COLVED INICIANT
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	10,125	SF	6	10+ years	1 story building, no risers
	Domestic Piping-Hot/Cold Water Supply	Entire Building	10,125	SF	6	10+ years	1998 installation, no leaks
	(Horizontal Lines)	· ·					
	Sanitary Piping	Entire Building	10,125	SF	7	10+ years	1998 installation
	Storm Piping	Entire Building	10,125	SF	7	10+ years	
	Vent Piping	Entire Building	10,125	SF	7	10+ years	
Catego	ry : Room		В	uilding	: Additi	on	
		Lastin				Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	trative Suites/Offices					-	



Catego	Category : Room		В	uildina	: Additi	on	
			_	_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	Gym Office/Gym Storage 123	562	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gym Office/Gym Storage 123	2	EA	7	10+ years	
	Floor - Tile	Gym Office/Gym Storage 123	562	SF	7	10+ years	
	Lighting - Pendent/Surface	Gym Office/Gym Storage 123	6	EA	7	6-10 years	
	Power Distribution	Gym Office/Gym Storage 123	6	EΑ	7	10+ years	
	Walls - Concrete Block	Gym Office/Gym Storage 123	1,124	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Office	68	SF	7	10+ years	
	Doors - Side-lite	Kitchen Office	30	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Office	1	EΑ	7	10+ years	
	Floor - Tile	Kitchen Office	68	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Office	1	EA	7	6-10 years	
	Walls - Concrete Block	Kitchen Office	279	SF	7	10+ years	
_Gvmnasi	a						
,	Ceiling - Exposed	1st Floor	3,189	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	
	Floor - Tile	1st Floor	3,174	SF	7	10+ years	
	Floor - Tile	1st Floor	15	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	3
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	600	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,447	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor	756	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	756	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	996	SF	7	10+ years	
_MDF_IDI	=						
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	150	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	Using central air
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	33	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	751	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	145	SF	7	10+ years	
Restroor	1						
	Accessories	1st Floor	67	SF	7	6-10 years	



Catego	Category: Room			uilding	: Addition	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	67	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	67	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	290	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	Boys Toilet	183	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys Toilet	223	SF	7	10+ years	
	Floor - Tile	Boys Toilet	30	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys Toilet	193	SF	7	10+ years	
	Floor Drain	Boys Toilet	1	EA	7	10+ years	
	Lavatory	Boys Toilet	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys Toilet	2	EA	7	6-10 years	
	Partitions	Boys Toilet	1	EA	7	10+ years	
	Urinals	Boys Toilet	2	EA	7	10+ years	
	Walls - Concrete Block	Boys Toilet	520	SF	7	10+ years	
	Water Closet	Boys Toilet	1	EA	7	10+ years	
	Accessories	Girls Toilet	265	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls Toilet	295	SF	7	10+ years	
	Floor - Tile	Girls Toilet	30	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Toilet	265	SF	7	10+ years	
	Floor Drain	Girls Toilet	2	EA	7	10+ years	
	Lavatory	Girls Toilet	2	EA	7	10+ years	
	Lighting - Lay-in	Girls Toilet	3	EA	7	6-10 years	
	Partitions	Girls Toilet	6	EA	7	10+ years	
	Walls - Concrete Block	Girls Toilet	630	SF	7	10+ years	
	Water Closet	Girls Toilet	6	EA	7	10+ years	
0-1	m Classes and		ь	!! -!!	. A al al!4!.		

Category : Classroom **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	m #115 (Regular Classroom)						
	Casework	1st Floor	29	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	860	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	860	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,033	SF	7	10+ years	



Catego	ry : Classroom		Building : Addition							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Classroc	om #116 (Regular Classroom)									
	Casework	1st Floor	30	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	861	SF	7	10+ years				
	Chalk Board	1st Floor	12	LF	4	2-5 years				
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years				
	Floor - Tile	1st Floor	861	SF	7	6-10 years				
	Lighting - Lay-in	1st Floor	9	EΑ	7	6-10 years				
	Marker Board	1st Floor	12	LF	7	6-10 years				
	Storage/ Closet	1st Floor	20	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	1,033	SF	7	10+ years				

Building: Addition Category : Interior

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	-					<u> </u>	
	Ceiling - Lay-in	1st Floor	1,112	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	77	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EΑ	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,112	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,458	SF	7	10+ years	



Category : Site	Building
Category : Site	Building

Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	10+ years	
_Fencing							
	Fencing - Chain Link	Entire Site	282	LF LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	255	LF	7	10+ years	
Landsca	pe						
	Benches	Entire Site	7	EA	7	10+ years	
	Landscape - Grass	Entire Site	10,674	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	680	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,150	SF	7	10+ years	
	Parkway trees	Entire Site	16	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	3,445	SF	7	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	2,288	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	800	SF	7	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	6-10 years	
Parking	_ot						
	Concrete Curbs	East	203	LF	7	10+ years	
	Surface - Asphalt	East	5,606	SF	7	10+ years	
	Trash Enclosure - Chain Links	East	192	SF	7	10+ years	
	Vehicular Screening	East	120	LF	7	10+ years	
Playgrou	nd						
	Equipment - School Age 5-12	East	1	EA	7	10+ years	
	Surface - Poured Surface	East	1,950	SF	7	10+ years	
	Equipment - School Age 5-12	West	1	EA	7	6-10 years	
	Surface - Poured Surface	West	1,435	SF	7	6-10 years	
Sidewalk	rs.						
Cidowalli	Sidewalks - Internal Walks	Entire Site	850	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	5,131	SF	7	10+ years	
			2,.0.	====	-	- ,	
Signage							
	Flag Pole - Flag Pole	Northwest	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Northwest	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter	Northwest	1	EA	7	10+ years	
	Sign						



1 It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-			
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board			
Building : Main												
Computer Lab	Computer Lab	1st Floor	113	112	636	120	60	N	N			
Kindergarten	Kindergarten	1st Floor	106	106	1,181	180	70	N	N			
Other Instructional Use	Office	1st Floor	112	112	360	60	30	N	N			
Regular Classroom	Kindergarten	1st Floor	105	105	963	180	70	N	Υ			
Regular Classroom	Kindergarten	1st Floor	108	108	839	140	70	N	N			
Regular Classroom	Kindergarten	1st Floor	110	110	979	180	90	N	Υ			
Regular Classroom	Regular Classroom	1st Floor	101	101	633	120	60	N	N			
Regular Classroom	Regular Classroom	1st Floor	102	102	869	180	90	N	N			
Regular Classroom	Regular Classroom	1st Floor	103	103	896	120	60	N	N			
Regular Classroom	Regular Classroom	1st Floor	104	104	869	180	90	N	N			
Regular Classroom	Regular Classroom	1st Floor	107	107	982	180	70	N	Υ			
Regular Classroom	Regular Classroom	1st Floor	109	109	575	120	50	N	N			
Regular Classroom	Regular Classroom	1st Floor	114	114	870	180	90	N	Υ			
Building : Addition												
Regular Classroom	Regular Classroom	1st Floor	115	115	860	120	60	N	Υ			
Regular Classroom	Regular Classroom	1st Floor	116	116	861	120	60	N	N			