

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1969	3	75,510
Campus Total			75,510

Category : Exterior Building : Main

	.y . =xtorio.					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance			•			•	
	Exterior Doors - Exterior FRP Door	#1 - SW	3	EA	7	10+ years	
	Exterior Stairs - Concrete	#1 - SW	48	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 - SW	2	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#10 Exit - NW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#10 Exit - NW	7	LF	7	10+ years	
	Stair Handrail - Steel Stair Handrail	#10 Exit - NW	4	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#11 Exit - SW	1	EA	7	10+ years	
	Exterior Stairs - Concrete	#11 Exit - SW	14	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#11 Exit - SW	8	LF	7	10+ years	
	Entrance Control - Audio and Video	#2 - S	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#2 - S	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 - S	32	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#2 - S	80	LF	6	10+ years	
	Ramps - Concrete	#2 - S	40	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#2 - S	14	LF	6	10+ years	
	Entrance Control - Audio	#3 - SE	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#3 - SE	3	EA	7	10+ years	
	Exterior Stairs - Concrete	#3 - SE	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 Exit - SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 Exit - SE	4	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	#5 SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 SE	25	LF	5	2-5 years	
	Stair Handrail - Steel_Stair Handrail	#5 SE	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 NE	1	EA	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main	5050	-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramp Handrail - Steel_Ramp Handrail	#6 NE	8	LF	6	10+ years	
	Ramps - Concrete	#6 NE	16	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6.5 NE Exit	1	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#6.5 NE Exit	20	LF	6	10+ years	
	Ramps - Concrete	#6.5 NE Exit	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7 Exit - NE	1	EA	7	10+ years	
	Exterior Stairs - Concrete	#7 Exit - NE	16	LF	5	2-5 years	
	Stair Handrail - Steel_Stair Handrail	#7 Exit - NE	18	LF	6	10+ years	
	Entrance Control - Audio and Video	#8 - N	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#8 - N	2	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#8 - N	36	LF	6	10+ years	
	Ramps - Concrete	#8 - N	18	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	#9 - N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 - N	12	LF	7	10+ years	
	Exterior ctairs controls	110	12	_1	,	101 youro	
Foundati							
	Foundation - Concrete	Entire Building	1,141	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	75,510	SF	7	10+ years	
	ropping						
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	15	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	26	EA	6	6-10 years	
Roof Svs	stem						
,	Coping - Metal	East Lower Roof	143	LF	6	10+ years	
	Downspouts - Interior Downspouts	East Lower Roof	24	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	East Lower Roof	2,312	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	East Lower Roof	2,312	SF	7	10+ years	
	Concrete Topping		_,	-		, , , , , , , , , , , , , , , , , , , ,	
	Coping - Metal	East Lowest Roof	305	LF	6	10+ years	
	Downspouts - Interior Downspouts	East Lowest Roof	28	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	East Lowest Roof	5,175	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	East Lowest Roof	5,175	SF	7	10+ years	
	Concrete Topping	Eddt Edwoot 11001	0,170	O.	•	101 youro	
	Access Ladder - Metal	Main Roof	3	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	47	LF	7	10+ years	
	Liner		.,		•	,	
	Coping - Metal	Main Roof	839	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	216	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Main Roof	19,149	SF	5	0-1 year	Cracking along edges pretty badly.
	Roof - Modified Bitumen	Main Roof	25	SF	5	2-5 years	Cracking along cages pretty badiy.
	Roof Hatch - Metal	Main Roof	3	EA	7	10+ years	

Campus Name: Kellman Page : 2 of 28 Assessment Date: 01/11/2022



Catego	ry : Exterior		В	uilding	: Main		
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Roof Structure - Steel / Metal Deck/	Main Roof	19,174	SF	7	10+ years	
	Concrete Topping					•	
	Coping - Metal	West Low Roof	274	LF	6	10+ years	
	Downspouts - Interior Downspouts	West Low Roof	28	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	West Low Roof	5,862	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	West Low Roof	5,862	SF	7	10+ years	
	Concrete Topping					•	
Nalls							
	Canopy - Metal	Entire Building	355	SF	5	2-5 years	
	Cheek-Wall - Concrete	Entire Building	82	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	24,450	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	25	SF	4	0-1 year	Chipped / cracking at corner of th
		_				-	building near door 10
	Exterior Walls - Concrete Block	Entire Building	140	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	886	SF	7	10+ years	
Windows	S						
	Curtain wall - Glazed Double Pane	Entire Building	7,490	SF	7	10+ years	
	Curtain wall - Insulated Panel	Entire Building	2,420	SF	7	10+ years	
	Curtain wall - Louver	Entire Building	369	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	3,160	SF	7	10+ years	
	Lintels - Steel	Entire Building	785	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	445	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergei	ncy System						
_	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Security System - CCTV	Entire Building	75,510	SF	6	6-10 years	
	On available Overtains	Fasting Duitaling	75.540	0.5	_	0.40	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
· ·	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Security System - CCTV	Entire Building	75,510	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	75,510	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	6	6-10 years	Quantity changed to match current
	Exit Signs - Gym	Entire Building	6	EA	6	6-10 years	observations.
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	32	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	6	EA	6	6-10 years	Quantity changed to match current observations
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	There is one in each of the six student toilets. Quantity changed to

Campus Name: Kellman Page : 3 of 28 Assessment Date: 01/11/2022



atego	ry : Electrical		В	uilding	: Main		
	Name Tame	Lagation	0	HOM	Danila	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,214	SF	6	6-10 years	match current observations.
	Emergency A/C Power - Gym	Entire Building	4,285	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,987	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,722	SF	6	6-10 years	
lain Sei	rvice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	75,510	SF	5	6-10 years	The "Press To Talk" push button cap is broken although it is still operable
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	Item Type changed to match curren observations
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	Quantity changed to match current observations
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Deteriorated; missing breaker with exposed live conductors.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	•
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	Item Type and quantity changed to match current observations.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	10+ years	
atego	ry : Fire Protection		В	uilding	: Main		
	_					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar							
	Fire Alarm Panel	Boiler Room	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Boiler Room	75,510	SF	7	10+ years	
	Fire Alarm_System	Boiler Room	75,510	SF	6	10+ years	



Catego	ry : Mechanical		В	uilding	: Main		
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 12001-20000 cfm	Basement	1	EA	5	6-10 years	AHU-1, serves gym
	Air Intake	Basement	1	EA	4	0-1 year	Severely corroded and deteriorated. Dampers must be manually adjusted.
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Boiler Room	1	EA	5	6-10 years	AHU-2, serves kitchen. Ceiling- mounted in boiler room area.
	Air Intake	Boiler Room	1	EA	4	1-2 years	Not directly accessible in a safe manner at the time of assessment due to snow/ice, high wind, and secure means of gaining access to the lower roof. Dampers are rusted and are manually adjusted.
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Gym Basement	1	EA	6	10+ years	Tagged "Exhaust Fan #11"
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	1	EA	6	10+ years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	One pump needs repair
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	6	10+ years	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	10+ years	Minor insulation repairs needed
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	10+ years	Minor insulation repairs needed
	Steam Traps	Boiler Room	103	EA	7	6-10 years	All traps replaced in 2021.
	Vacuum Pump	Boiler Room	1	EA	6	6-10 years	
Heating							
	Radiators - Steam	Boiler Room	3	EA	5	6-10 years	
	Unit Heater - Gas	Boiler Room	1	EA	5	2-5 years	
	Cabinet Heaters - With Steam Coil	Entire Building	33	EA	6	10+ years	
	Fin Tube - Steam	Entire Building	25	LF	6	6-10 years	Paint required.
Tempera	ature Control						
	DDC System	Entire Building	75,510	SF	5	6-10 years	System has been upgraded and a software update was actively being performed at the time of assessment.
	Thermostats - DDC	Entire Building	61	EA	6	6-10 years	parametric and an accomment

Campus Name: Kellman Page : 5 of 28 Assessment Date: 01/11/2022



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Unit Ver	ntilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	15	EA	5	6-10 years	
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	44	EA	5	6-10 years	
Ventilati	on						
v Critilati	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	Fan motor is in stalled-rotor condition
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	6	EA	5	6-10 years	Units on lower roof were not directly accessible in a safe manner at the time of assessment due to snow/ice, high wind, and secure means of gaining access to the lower roof.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	6	EA	5	6-10 years	Units on lower roof were not directly accessible in a safe manner at the time of assessment due to snow/ice, high wind, and secure means of gaining access to the lower roof.
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	gaming access to me terms con-
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	4	1-2 years	Older units operating as intended in service; signs of corrosion on exterior
Pining							shell with no visible leaks.
Piping_	Domestic Piping-Hot Water Return Lines	Entire Building	75,510	SF	6	6-10 years	snell with no visible leaks.
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Entire Building Entire Building	75,510 75,510	SF SF	6 6	6-10 years 6-10 years	snell with no visible leaks.
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures	Entire Building Entire Building Entire Building	75,510 75,510 75,510	SF SF SF	6 6 6	6-10 years 6-10 years 6-10 years	snell with no visible leaks.
Piping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply	Entire Building	75,510	SF	6	6-10 years	snell with no visible leaks.
Piping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures	Entire Building Entire Building	75,510 75,510	SF SF	6 6	6-10 years 6-10 years	snell with no visible leaks.
Piping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building Entire Building	75,510 75,510 75,510	SF SF	6 6	6-10 years 6-10 years 6-10 years	Corrosion/leaks repaired since last assessment.
Piping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	75,510 75,510 75,510 75,510 75,510 75,510	SF SF SF SF SF	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Corrosion/leaks repaired since last
Piping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building Entire Building Entire Building Entire Building Entire Building	75,510 75,510 75,510 75,510 75,510	SF SF SF SF	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Corrosion/leaks repaired since last



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							assessment.
<u>Pumps</u>							
	Pumps - Domestic Booster Pump-Simplex	Basement, Boiler Room	1	EA	2	0-1 year	Nonfunctional. Has not been in service for at least five years. The city water pressure is sufficient for this building and a domestic water booster pump is not needed.
	Pumps - Sump-Duplex	Basement, Boiler Room	1	EA	6	6-10 years	Item Type changed to match current observations.
	Pumps - Sump-Simplex	Basement, Boiler Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement, Boiler Room	1	EA	6	6-10 years	Bottom of elevator pit. Inaccessible at the time of assessment.

Category: Room **Building: Main** Recommend Item - Type Location Replacement Comments Group Quantity UOM Rank _Adminis

o itelii - Type	Location	Quantity	CON	Italik	Replacement	Comments
nistrative Suites/Offices						
Ceiling - Plaster/Drywall	1st Floor Conference Room 107A	149	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor Conference Room 107A	1	EA	6	10+ years	
Floor - Tile	1st Floor Conference Room 107A	149	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor Conference Room 107A	2	EA	6	6-10 years	
Power Distribution	1st Floor Conference Room 107A	6	EA	6	10+ years	
Walls - Concrete Block	1st Floor Conference Room 107A	186	SF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor Gym Office	152	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor Gym Office	2	EA	6	10+ years	
Floor - Tile	1st Floor Gym Office	152	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor Gym Office	2	EA	6	6-10 years	
Power Distribution	1st Floor Gym Office	2	EA	6	10+ years	
Walls - Concrete Block	1st Floor Gym Office	190	SF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor Library Office	127	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor Library Office	1	EA	6	10+ years	
Floor - Tile	1st Floor Library Office	127	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor Library Office	2	EA	6	6-10 years	
Power Distribution	1st Floor Library Office	4	EA	6	6-10 years	
Walls - Concrete Block	1st Floor Library Office	158	SF	6	10+ years	
AC Unit	1st Floor Principal's Office	1	EA	5	6-10 years	
Ceiling - Plaster/Drywall	1st Floor Principal's Office	171	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor Principal's Office	1	EA	6	10+ years	
Floor - Tile	1st Floor Principal's Office	171	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor Principal's Office	4	EA	6	6-10 years	
Power Distribution	1st Floor Principal's Office	8	EA	6	6-10 years	
Walls - Concrete Block	1st Floor Principal's Office	213	SF	6	10+ years	
AC Unit	1st Floor Room 107, Main Office	1	EA	5	6-10 years	

Campus Name: Kellman Page: 7 of 28 Assessment Date: 01/11/2022



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor Room 107, Main Office	378	SF	6	10+ years	
	Doors - Side-lite	1st Floor Room 107, Main Office	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor Room 107, Main Office	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Room 107, Main Office	1	EA	6	10+ years	
	Floor - Tile	1st Floor Room 107, Main Office	378	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Room 107, Main Office	6	EA	6	6-10 years	
	Power Distribution	1st Floor Room 107, Main Office	8	EA	6	10+ years	
	Storage/ Closet	1st Floor Room 107, Main Office	12	SF	5	10+ years	
	Walls - Concrete Block	1st Floor Room 107, Main Office	472	SF	6	10+ years	
	AC Unit	1st Floor Room 111, Faculty Lounge	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Room 111, Faculty Lounge	750	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Room 111, Faculty Lounge	1	EA	6	10+ years	
	Floor - Tile	1st Floor Room 111, Faculty Lounge	750	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Room 111, Faculty Lounge	16	EA	6	6-10 years	
	Power Distribution	1st Floor Room 111, Faculty Lounge	14	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Room 111, Faculty Lounge	900	SF	6	10+ years	
	Work SInk	1st Floor Room 111, Faculty Lounge	1	EA	5	6-10 years	
	AC Unit	1st floor Work Room	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st floor Work Room	188	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor Work Room	1	EA	6	10+ years	
	Floor - Tile	1st floor Work Room	188	SF	6	10+ years	
	Lighting - Pendent/Surface	1st floor Work Room	2	EA	6	6-10 years	
	Power Distribution	1st floor Work Room	2	EA	6	10+ years	
	Walls - Concrete Block	1st floor Work Room	235	SF	6	10+ years	
_Gymnas							
	Ceiling - Plaster/Drywall	1st Floor Room 100	4,285	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor Room 100	2	EA	6	10+ years	
	Floor - Wood	1st Floor Room 100	4,285	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor Room 100	12	EA	6	6-10 years	
	Scoreboards	1st Floor Room 100	1	EA	5	6-10 years	
	Sound System	1st Floor Room 100	_ 1	EA	5	6-10 years	
	Stage	1st Floor Room 100	942	SF	6	10+ years	
	Stage Curtain	1st Floor Room 100	2	EA	5	10+ years	
	Stage Lift	1st Floor Room 100	1	EA	5	10+ years	
	Stage Lighting System	1st Floor Room 100	1	EA	5	6-10 years	
	Stage-Stairs - Wood	1st Floor Room 100	4	LF	6	10+ years	
	Walls - Concrete Block	1st Floor Room 100	2,590	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Room 100	2,590	SF	6	10+ years	
	AC Unit	Fitness Center Rm 212	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	Fitness Center Rm 212	575	SF	6	10+ years	
	Doors - Transom Window	Fitness Center Rm 212	108	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Fitness Center Rm 212	1	EA	6	10+ years	
	Floor - Tile	Fitness Center Rm 212	575	SF	5	10+ years	



Catego	ry : Room		В	uilding	: Main	0000	5 W Armington STREET, Chicago, IL 60612
Guiogo	. y . 1.00			anamg	· mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Pendent/Surface	Fitness Center Rm 212	12	EA	6	6-10 years	
	Walls - Concrete Block	Fitness Center Rm 212	634	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	1,121	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	. 2	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	1,121	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Serving Line	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	100	SF	5	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,401	SF	6	10+ years	
Library							
	Casework	Room 101	76	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Room 101	1,458	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 101	2	EA	6	10+ years	
	Floor - Tile	Room 101	1,458	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 101	32	ĒΑ	6	6-10 years	
	Walls - Concrete Block	Room 101	1,312	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 101	439	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	1st Floor	2,987	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	2,987	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	50	ĒΑ	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,866	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,866	SF	6	10+ years	
MDF ID	F						
	Doors - Wood Doors inclu hw	3rd floor Room 314A	1	EA	6	10+ years	
	Finishes	3rd floor Room 314A	225	SF	5	6-10 years	
	Window AC Unit	3rd floor Room 314A	1	EA	5	6-10 years	
Mechan	cal/ Service Rooms						
	Janitor's Closet	1st Floor	26	SF	5	10+ years	Ceiling is damaged.
	Storage Room	1st Floor	73	SF	5	10+ years	5 5
	Storage Room	1st Floor	68	SF	5	10+ years	
	Vaults	1st Floor	59	SF	5	10+ years	
	Vaults	1st Floor	30	SF	5	10+ years	
	Janitor's Closet	2nd Floor	26	SF	5	10+ years	Water damage and hole in ceiling.
	Janitor's Closet	3rd Floor	26	SF	5	10+ years	Floor separating/missing. Ceiling has a board covering hole.



Catego	ategory: Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Room	Basement	1,623	SF	5	10+ years	
	Crawl Space - Unfinished	Basement	25,580	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	600	SF	5	10+ years	
Restroo	m						
	Accessories	1st Floor	46	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	46	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	46	SF	6	10+ years	
	Lavatory	1st Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	66	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	6-10 years	
			-	SF	-		
	Accessories	1st Floor	275	SF SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	275		6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	275	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	
	Partitions	1st Floor	7	EA	5	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	343	SF	6	10+ years	
	Water Closet	1st Floor	7	EA	6	6-10 years	
	Accessories	1st Floor	299	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	299	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	299	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	
	Partitions	1st Floor	4	ĒΑ	5	6-10 years	
	Urinals	1st Floor	3	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	374	SF	6	10+ years	
	Water Closet	1st Floor	4	EA	6	10+ years	
	Accessories	1st Floor Room 115A	46	SF	5	6-10 years	
	Ceiling - Lay-in	1st Floor Room 115A	46	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor Room 115A	1	EA	6	6-10 years	
	Floor - Tile		· · · · · · · · · · · · · · · · · · ·	SF	6	•	
		1st Floor Room 115A	46 1	SF EA	6 7	10+ years	
	Floor Drain	1st Floor Room 115A	· ·			10+ years	
	Lavatory	1st Floor Room 115A	1	EΑ	6	6-10 years	
	Lighting - Lay-in	1st Floor Room 115A	1	EA	6	6-10 years	
	Walls - Metal Panel	1st Floor Room 115A	57	SF	6	10+ years	
	Water Closet	1st Floor Room 115A	1	EA	6	6-10 years	
	Accessories	1st floor In the Principal's Office	46	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st floor In the Principal's Office	46	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor In the Principal's Office	1	EΑ	6	10+ years	



Catego	Category : Room		В	uilding	: Main		-
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st floor In the Principal's Office	46	SF	6	10+ years	
	Lavatory	1st floor In the Principal's Office	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st floor In the Principal's Office	1	EA	6	10+ years	
	Walls - Concrete Block	1st floor In the Principal's Office	66	SF	6	10+ years	
	Water Closet	1st floor In the Principal's Office	1	EA	6	10+ years	
	Accessories	2nd Floor	46	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	46	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	46	SF	6	10+ years	
	Lavatory	2nd Floor	1	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	66	SF	6	10+ years	
	Water Closet	2nd Floor	1	ĒΑ	6	10+ years	
	Accessories	2nd Floor	275	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	275	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	275	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	
	Partitions	2nd Floor	7	EA	5	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	343	SF	6	10+ years	
	Water Closet	2nd Floor	7	EA	6	6-10 years	
	Accessories	2nd Floor	299	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	299	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	299	SF	6		
	Floor Drain	2nd Floor	299	EA	7	10+ years	
	Lavatory	2nd Floor	3	EA	6	10+ years 6-10 years	
	,	2nd Floor	3	EA	6		
	Lighting - Pendent/Surface Partitions	2nd Floor	3	EA	5	6-10 years	
	Urinals	2nd Floor	•	EA	5 6	6-10 years	
	Walls - Concrete Block	2nd Floor	3 374	SF		6-10 years	
			_	Sr EA	6	10+ years	
	Water Closet	2nd Floor	4		6	6-10 years	
	Accessories	3rd Floor	46	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	46	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	46	SF	6	10+ years	
	Lavatory	3rd Floor	1	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	66	SF	6	10+ years	
	Water Closet	3rd Floor	1	EA	6	6-10 years	
	Accessories	3rd Floor	275	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	275	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	275	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	



Catego	Category : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	3rd Floor	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	3	EA	6	6-10 years	
	Partitions	3rd Floor	7	EA	5	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor	343	SF	6	10+ years	
	Water Closet	3rd Floor	7	EA	6	6-10 years	
	Accessories	3rd Floor	299	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	299	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	299	SF	6	10+ years	
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years	
	Lavatory	3rd Floor	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	3	EA	6	6-10 years	
	Partitions	3rd Floor	4	EΑ	5	6-10 years	
	Urinals	3rd Floor	3	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	374	SF	6	10+ years	
	Water Closet	3rd Floor	4	EA	6	10+ years	
		In the Main Office	46	SF	5		
	Accessories	In the Main Office	46	SF		6-10 years	
	Ceiling - Plaster/Drywall				5	10+ years	
	Doors - Wood Doors inclu hw	In the Main Office	1	EA	6	10+ years	
	Floor - Tile	In the Main Office	46	SF	6	10+ years	
	Lavatory	In the Main Office	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	In the Main Office	1	EA	6	6-10 years	
	Walls - Concrete Block	In the Main Office	66	SF	6	10+ years	
	Water Closet	In the Main Office	1	EA	6	6-10 years	
	Accessories	Room 106	36	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Room 106	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 106	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 106	36	SF	6	10+ years	
	Lavatory	Room 106	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Room 106	1	EA	6	6-10 years	
	Walls - Concrete Block	Room 106	57	SF	6	10+ years	
	Water Closet	Room 106	1	EA	6	6-10 years	
	Accessories	Room 108	36	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Room 108	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 108	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 108	36	SF	6	10+ years	
	Lavatory	Room 108	1	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	Room 108	1	EA	6	6-10 years	
	Walls - Concrete Block	Room 108	52	SF	6	10+ years	
	Water Closet	Room 108	1	EA	6	6-10 years	
	Accessories	Room 110	36	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Room 110	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 110	1	EA		•	
					6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 110	36	SF EA	6	10+ years	
	Lavatory	Room 110	1	ĽΑ	6	6-10 years	

Campus Name: Kellman Page : 12 of 28 Assessment Date: 01/11/2022



Catego	ry : Room		В	uilding	: Main			
	_					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	Room 110	1	EA	6	6-10 years		
	Walls - Concrete Block	Room 110	52	SF	6	10+ years		
	Water Closet	Room 110	1	EA	6	6-10 years		
Catego	ry : Classroom		В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	om #102 (Regular Classroom)		4.4.4					
Oldssion	AC Units	1st Floor	1	EA	5	6-10 years		
	Casework	1st Floor	15	LF	6	6-10 years		
	Casework Ceiling - Plaster/Drywall	1st Floor	750	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6			
	Floor - Tile	1st Floor		SF	6	10+ years		
		1st Floor	750		-	10+ years		
	Lighting - Pendent/Surface		16	EA	6	6-10 years		
	Marker Board	1st Floor	32	LF	6	6-10 years		
	Walls - Concrete Block	1st Floor	809	SF	6	10+ years		
Classroo	om #103 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	30	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years		
	Floor - Tile	2nd Floor	810	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years		
	Marker Board	2nd Floor	12	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	745	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	248	SF	6	10+ years		
Classroo	om #104 (Store Room)							
	AC Units	1st Floor	1	EA	5	6-10 years		
	Casework	1st Floor	15	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	750	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years		
	Floor - Tile	1st Floor	750	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years		
	Marker Board	1st Floor	32	LF	6	6-10 years		
	Walls - Concrete Block	1st Floor	2	SF	6	10+ years		
	Walls - Concrete Block	1st Floor	809	SF	6	10+ years		
Classro	om #105 (Regular Classroom)							
Classiul	AC Units	1st Floor	4	ΕΛ	E	6-10 years		
			1 30	EA LF	5	•		
	Casework Ceiling - Plaster/Drywall	1st Floor 1st Floor	30 810	SF	6 6	10+ years 10+ years		
	<u> </u>				-	- ,		

Campus Name: Kellman Page: 13 of 28 Assessment Date: 01/11/2022



Catego	ategory : Classroom			uilding			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	810	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	745	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	248	SF	6	10+ years	
Classroo	om #106 (Kindergarten)						
	AC Units	1st Floor	2	EA	5	6-10 years	
	Casework	1st Floor	15	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,125	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	5	10+ years	
	Floor - Tile	1st Floor	1,125	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor		EA	6	•	
		1st Floor	21	LF	6	6-10 years	
	Marker Board		8	SF	_	6-10 years	
	Storage/ Closet	1st Floor	25	SF SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,184		6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #108 (Kindergarten)						
	AC Units	1st Floor	2	EA	5	6-10 years	
	Casework	1st Floor	15	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,125	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,125	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	50	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,184	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #109 (Play Room)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Casework	1st Floor	30	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	810	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	810	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	-	
	Marker Board	1st Floor	12	LF	6	6-10 years	
				SF	_	6-10 years	
	Walls - Concrete Block	1st Floor	745		6	10+ years	
	Walls - Plaster/Drywall	1st Floor	248	SF	6	10+ years	

Campus Name: Kellman Page : 14 of 28 Assessment Date: 01/11/2022



Catego	ry : Classroom		В	uilding	: Main		5 W Arthington OTIVEET, Onicago, IE 00012
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #110 (Pre School)						
	AC Units	1st Floor	2	EA	5	6-10 years	
	Casework	1st Floor	15	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,125	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,125	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	50	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,184	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #200 (Office)	0.15				0.40	
	Casework	2nd Floor	15	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	809	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	30	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	810	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	745	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	248	SF	6	10+ years	
0.1	(1000 /D 1 0)						
Classro	om #202 (Regular Classroom)	0.15	-			0.10	
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	15	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	25	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	



Category : Classroom			R	Building : Main				
				ananig	. Maiii	Recommend		
Proup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
лоцр	Marker Board	2nd Floor	32	LF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	809	SF	6	10+ years		
	rraile i lacter, 2 ly trail			О.	· ·	.o. you.o		
lassroc	om #203 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	30	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years		
	Chalk Board	2nd Floor	16	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	810	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years		
	Marker Board	2nd Floor	12	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	745	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	248	SF	6	10+ years		
lassroo	om #204 (Office)							
COOLOR	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	15	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years		
	Chalk Board	2nd Floor	16	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	740	SF	6	10+ years		
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Missing	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	3	
	Marker Board	2nd Floor	16	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	809	SF	6	10+ years		
lassroc	om #205 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	5	6-10 years		
	Casework	2nd Floor	30	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years		
	Chalk Board	2nd Floor	16	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	810	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years		
	Marker Board	2nd Floor	12	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	745	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	248	SF	6	10+ years		
laceron	om #206 (Regular Classroom)							
ussiuc	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor 2nd Floor	15	LF	<i>7</i> 6			
	Casework Ceiling - Plaster/Drywall			SF	6 7	10+ years		
	Ceiling - Flastel/Drywall	2nd Floor	750	SF	′	10+ years		



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	809	SF	7	10+ years	
Classroo	om #207 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	•	
	Walls - Concrete Block	2nd Floor 2nd Floor	745	SF	7	10+ years	
		2nd Floor 2nd Floor	145	EA	7	10+ years	
	Wireless System	2110 F1001	1	EA	1	6-10 years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	. 1	EΑ	7	6-10 years	
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	Water damage.
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	809	SF	7	10+ years	
Classroo	om #209 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	248	SF	7	•	
	vvalis - riastei/Diywali	ZIIU FIUUI	240	3F	,	10+ years	

Campus Name: Kellman Page : 17 of 28 Assessment Date: 01/11/2022



Category : Classroom			В	uilding	: Main		
		•	0		.	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	560	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	15	SF	5	0-1 year	Water damage.
	Chalk Board	2nd Floor	16	LF	4	2-5 years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	575	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	634	SF	7	10+ years	
Classroo	om #211 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	795	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	15	SF	6	10+ years	Not painted
	Chalk Board	2nd Floor	16	LF	4	2-5 years	rtot paintou
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	248	SF	7	10+ years	
Classroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Cracking.
	Chalk Board	2nd Floor	16	LF	4	2-5 years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	248	SF	7	10+ years	
Classroo	om #214 (Faculty Lounge)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	575	SF	7	- ,	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	575	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	634	SF	7	10+ years	
Classroo	m #215 (Faculty Lounge)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	248	SF	7	10+ years	
	walls - Flastel/Drywall	2110 1 1001	240	OI .	,	10+ years	
Classroo	m #216 (Science Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	70	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,764	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	1,764	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	46	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	11	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	1,383	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	461	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	7	6-10 years	
Classroo	m #300 (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	675	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	675	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	734	SF	7	10+ years	
	walls concrete block	314 1 1001	734	Oi.	,	10+ years	
Classroo	m #301 (Regular Classroom)						

Campus Name: Kellman Page : 19 of 28 Assessment Date: 01/11/2022



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	248	SF	7	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	809	SF	7	10+ years	
				-	-	, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	248	SF	7	10+ years	
lassroc	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	



Category : Classroom			В	uilding	: Main		
July	. ,			uiig		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Огоар	Walls - Concrete Block	3rd Floor	809	SF	7	10+ years	
	Trails Correlate Blook	0.01.001	000	O.	•	io. youro	
lassroo	om #305 (Regular Classroom)						
21433100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	810	SF	7	10+ years	
	Chalk Board	3rd Floor		LF	4	,	
	Doors - Wood Doors inclu hw		16	EA		2-5 years	
		3rd Floor	1		6	10+ years	
	Floor - Tile	3rd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	_12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	248	SF	7	10+ years	
Jassroc	om #306 (Office) AC Units	3rd Floor	1	EA	7	6-10 years	
						•	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	809	SF	7	10+ years	
laceron	om #307 (Regular Classroom)						
JIASSIUC	AC Units	3rd Floor	1	EA	7	6-10 years	
		3rd Floor		LF		10+ years	
	Casework	3rd Floor 3rd Floor	30 810	SF	6 7		
	Ceiling - Plaster/Drywall	3rd Floor 3rd Floor		SF LF		10+ years	
	Chalk Board		16		4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	248	SF	7	10+ years	
lassroo	om #308 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
		31U I 1001		$\vdash \land$	U	IUT years	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	809	SF	7	10+ years	
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6		
				SF	-	6-10 years	
	Walls - Concrete Block	3rd Floor	745		7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	248	SF	7	10+ years	
Classroo	om #310 (Store Room)						
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	809	SF	7	10+ years	
Classroo	om #311 (Art Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,620	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1,020	EA	6	10+ years	
	Floor - Tile		1,620	SF	7	•	
		3rd Floor				10+ years	
	Lighting - Pendent/Surface	3rd Floor	32	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	84	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,308	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	436	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	6-10 years	
Classroo	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	575	SF	7	10+ years	
		5.5.	0.0		•	,	



Catego	ry : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	575	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	634	SF	7	10+ years	
Classroo	m #313 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	248	SF	7	10+ years	
Classroo	m #314 (Regular Classroom)						
Classico	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	575	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
	Floor - Tile	3rd Floor	575	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	634	SF	7	10+ years	
0-1	ma dataman		5		B.	•	
Catego	ry : Interior		В	uilding	: wain	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	1,924	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	5	10+ years	
	Floor - Tile/Sheet	1st Floor	1,924	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	40	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	2,134	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,848	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	ĒΑ	5	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,848	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	40	EA	6	6-10 years	



Category : Interior			Building : Main					•
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Walls - Concrete Block	2nd Floor	1,878	SF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	1,848	SF	6	10+ years		
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	5	2-5 years		
	Floor - Tile/Sheet	3rd Floor	1,848	SF	5	10+ years		
	Lighting - Pendent/Surface	3rd Floor	40	EA	6	6-10 years		
	Walls - Concrete Block	3rd Floor	1,878	SF	6	10+ years		
Cofoty								
Safety	Company Viewing Station	Fating Duilding	2	ΕΛ		C 40		
	Camera Viewing Station	Entire Building	3	EA EA	5	6-10 years		
	Security Cameras	Entire Building	· · · · · · · · · · · · · · · · · · ·		5	6-10 years		
	Security Cameras	Entire Building	3	EΑ	5	6-10 years		
	Security Cameras	Entire Building	6	EA	5	6-10 years		
	Security Cameras	Entire Building	1	EA	5	6-10 years		
Stairs								
	Ceiling - Plaster/Drywall	South	198	SF	6	10+ years		
	Floor - Tile	South	198	SF	6	10+ years		
	Handrails	South	402	LF	5	10+ years		
	Lighting - Pendent/Surface	South	12	EA	6	6-10 years		
	Stairs - Terrazzo	South	774	LF	6	10+ years		
	Walls - Plaster/Drywall	South	252	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Southeast	198	SF	6	10+ years		
	Floor - Tile	Southeast	198	SF	6	10+ years		
	Handrails	Southeast	402	LF	5	10+ years		
	Lighting - Pendent/Surface	Southeast	12	EA	6	6-10 years		
	Stairs - Terrazzo	Southeast	774	LF	6	10+ years		
	Walls - Plaster/Drywall	Southeast	252	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Southwest	198	SF	6	10+ years		
	Floor - Tile	Southwest	198	SF	6	10+ years		
	Handrails	Southwest	402		5	10+ years		
	Lighting - Pendent/Surface	Southwest	12		6	6-10 years		
	Stairs - Terrazzo	Southwest	774	LF	6	10+ years		
	Walls - Plaster/Drywall	Southwest	252		6	10+ years		
Vertical	Conveyance							
VEITICAL	Elevator - Elevator- Roped Holeless	1st Floor	1	EA	7	10+ years		
	Hydraulic							





Category: Site **Building: Site**

Catego	ry : Site	Building : Site							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Civil/Dra	- 5								
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	7	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	7	10+ years			
Fencing									
J	Fencing - Chain Link	Entire Site	905	LF	6	10+ years			
	Fencing - Chain Link	Entire Site	100	LF	4	0-1 year	Missing top portion of fence.		
	Fencing - New Standard Ornamental	Entire Site	1,080	LF	6	10+ years	•		
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	328	LF	7	6-10 years			
Landsca	pe								
	Benches	Entire Site	6	EA	4	0-1 year	Worn out, falling apart.		
	Landscape - Grass	Entire Site	7,020	SF	6	10+ years	, 3 1		
	Landscape - Hardscape- Concrete	Entire Site	200	SF	7	10+ years			
	Landscape - Hardscape- Concrete	Entire Site	175	SF	6	10+ years			
	Parkway trees	Entire Site	25	EA	6	10+ years			
	Play Area - Synthetic Turf	Entire Site	11,520	SF	7	10+ years			
	Trash Receptacles	Entire Site	2	ĒΑ	6	10+ years			
Parking	Lot								
J	Surface - Asphalt	North Courtyard	16,500	SF	4	0-1 year	Cracking and holes.		
	Trash Enclosure - Chain Links	North Courtyard	825	SF	6	10+ years	ŭ		
Playgrou	ind								
, g	Equipment - School Age 5-12	North Courtyard	1	EA	6	6-10 years			
	Surface - Poured Surface	North Courtyard	1,520	SF	5	0-1 year	Holes.		
Sidewalk	S.S.								
	Sidewalks - Internal Walks	Entire Site	65	LF	6	10+ years			
	Sidewalks - Perimeter Sidewalks	Entire Site	11,600	SF	7	10+ years			
Signage									
5	Flag Pole - Flag Pole	South Courtyard	1	EA	7	10+ years			
	Marquee - Free Standing Back Lighted	South Courtyard	1	EA	7	6-10 years			

Campus Name: Kellman Page: 25 of 28 Assessment Date: 01/11/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Kellman Page : 26 of 28 Assessment Date: 01/11/2022





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			1101111001		(0.7	7	7.1.00	0.00	
Art Room	Regular Classroom	3rd Floor	311	311	1,620	312	104	Y	Υ
Computer Lab	Regular Classroom	2nd Floor	207	207	810	148	52	Y	N
Faculty Lounge	Regular Classroom	2nd Floor	214	214	575	108	42	Y	N
Faculty Lounge	Regular Classroom	2nd Floor	215	215	810	156	52	Y	N
Kindergarten	Kindergarten	1st Floor	106	106	1,125	288	84	Y	Υ
Kindergarten	Kindergarten	1st Floor	108	108	1,125	288	84	Υ	Υ
Office	Regular Classroom	2nd Floor	200	200	750	144	49	Υ	N
Office	Regular Classroom	2nd Floor	204	204	750	156	52	Υ	N
Office	Regular Classroom	2nd Floor	209	209	810	156	52	Υ	N
Office	Regular Classroom	3rd Floor	306	306	750	144	49	Υ	N
Office	Regular Classroom	3rd Floor	308	308	750	144	49	Υ	N
Office	Regular Classroom	3rd Floor	313	313	810	156	52	Υ	N
Play Room	Regular Classroom	1st Floor	109	109	810	120	20	Υ	N
Pre School	Pre School	1st Floor	110	110	1,125	288	84	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	750	144	49	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	105	107	810	115	20	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	103	105	810	115	20	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	810	156	52	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	750	144	49	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	810	156	52	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	810	156	52	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	750	144	49	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	750	144	49	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	575	108	42	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	810	156	52	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	810	156	52	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	302	750	140	42	Υ	Ζ
Regular Classroom	Regular Classroom	3rd Floor	303	303	810	156	52	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	750	144	49	Υ	Ζ
Regular Classroom	Regular Classroom	3rd Floor	305	305	810	156	52	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	810	156	52	Υ	Ν
Regular Classroom	Regular Classroom	3rd Floor	309	309	810	156	52	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	575	108	42	Y	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	575	108	42	Υ	N
Science Classroom	Science Classroom	2nd Floor	216	216	1,764	261	72	N	N
Store Room	Regular Classroom	1st Floor	104	104	750	144	49	Υ	Υ
Store Room	Regular Classroom	2nd Floor	211	211	810	156	52	Υ	N
Store Room	Regular Classroom	3rd Floor	300	300	675	108	42	Υ	Ν



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Store Room	Regular Classroom	3rd Floor	310	310	750	144	49	Υ	N

Campus Name: Kellman Page : 28 of 28 Assessment Date: 01/11/2022