

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1937	2	18,315
Addition	1954	2	8,328
Modular 1 (4-Classroom)	2001	1	4,200
Campus Total			30,843

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	<u>,</u>						
	Entrance Control - Audio and Video	#1 - West	1	EA	7	10+ years	
	Exterior Doors - Store Front	#1 - West	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#1 - West	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#1 - West	54	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#2 - NorthWest	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - NorthWest	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 - NorthWest	60	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#3 Basement	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 Basement	44	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 Basement	50	LF	4	1-2 years	Corroded
Foundati	ion						
	Foundation - Concrete	Entire Building	365	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	18,315	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	5	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	А	2	EA	7	10+ years	



Catego	ory : Exterior		В	uilding	: Main		
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Chimney - Brick Chimney- Concrete/ Mortar	A	20	LF	6	10+ years	
	Liner					2	
	Coping - Stone	А	414	LF	6	10+ years	
	Downspouts - Interior Downspouts	A	68	LF	7	10+ years	
	Parapet - 16" - 30" Height	А	56	LF	7	10+ years	
	Parapet - Parapet < 16" Height	A	242	LF	6	10+ years	
	Parapet - Parapet > 30"	A	116	LF	6	10+ years	
	Roof - Metal	A	144	SF	6	10+ years	
	Roof - Modified Bitumen	A	7,326	SF	6	10+ years	
	Roof Hatch - Metal	A	1,520	EA	7	10+ years	
			-		6		
	Roof Structure - Steel with Clay Tile Arch	A	7,326	SF	6	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	240	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	6,835	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	412	SF	6	10+ years	
Window	2						
VVIIIGOV	Guard - Guards perforated	Entire Building	1,584	SF	7	10+ years	
	Lintels - Steel	Entire Building	133	LF	6	10+ years	
	Lintels - Stone	Entire Building	123	LF	7	10+ years	
	Windows - Louver	Entire Building	21	SF	6	10+ years	
	Windows - Couver Windows - Sash Aluminum Double-pane	Entire Building	3,000	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane Windows - Sash Aluminum Double-pane	•	3,000 72	SF	6	•	
	Windows - Sash Aluminum Double-parle	Entire Building	12	ЗГ	0	10+ years	
Catego	ory : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	ncy System	Location	Quantity		Nank	Replacement	Commenta
Lineige	Automatic Transfer Switch	Boiler Room	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	2,546	SF	6	10+ years	
	Stairs		_,5 .0		-	,	
						10	
		Entire Building	2 876	SF	7	10+ vears	
	Emergency A/C Power - Students Toilets	Entire Building	2,876 4	SF FA	7 6	10+ years 6-10 years	
	Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and	Entire Building Entire Building	2,876 4	SF EA	7 6	10+ years 6-10 years	
	Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	
	Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Students Toilets	Entire Building	4	EA EA	6 7	6-10 years 6-10 years	No battery backup por backup
	Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	No battery backup nor backup generator
	Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Security System - CCTV	Entire Building	4 2 5 18,315	EA EA	6 7	6-10 years 6-10 years	No battery backup nor backup generator
	Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building	4 2 5	EA EA EA	6 7 2	6-10 years 6-10 years 0-1 year	, i i
Main Se	Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Security System - CCTV Security System - Intrusion Detection	Entire Building Entire Building Entire Building Entire Building	4 2 5 18,315	EA EA EA SF	6 7 2 6	6-10 years 6-10 years 0-1 year 6-10 years	, i i
Main Se	Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Security System - CCTV Security System - Intrusion Detection	Entire Building Entire Building Entire Building Entire Building	4 2 5 18,315	EA EA EA SF	6 7 2 6	6-10 years 6-10 years 0-1 year 6-10 years	, i i



9241 S Leavitt STREET, Chicago, IL 60643 **Category : Electrical Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments emergency power Main Electrical Service - 1000 A ΕA Boiler Room 4 Still functional but beyond its useful 1 2-5 years 120/240/3PH life SF 6 PA System Entire Building 18.315 6-10 years Power Distribution Lighting and Power Panels - 100 A Entire Building FΑ 6 6-10 years 1 Lighting and Power Panels - Above 100 A Entire Building 4 FΑ 6 6-10 years The panel has been repaired 3 Lighting and Power Panels - Above 100 A Entire Building ΕA 6 6-10 vears Lighting and Power Panels - Above 100 A Entire Building 1 ΕA 4 2-5 years Beyond service life Main Distribution Panels - Less than 400 3 ΕA Entire Building 4 1-2 years Beyond service life amp ΕA Transformers - 120/240 - 120/208 Entire Building 1 6 2-5 years **Category : Fire Protection Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Fire Alarm FΑ 7 Fire Alarm Panel Entire Building 1 10+ vears SF Fire Alarm Strobe Lights Entire Building 18.315 6 6-10 years SF Fire Alarm\_System Entire Building 18.315 6 6-10 years Category : Mechanical **Building : Main** Recommend Location Quantity UOM Rank **Replacement** Comments Group Item - Type Air Handling Systems Air Handling Unit- Built Up- Multi Zone- Hot ΕA Boiler Room 1 5 6-10 years Water Coils - 25001 - 35000 cfm Air Intake Boiler Room ΕA 5 1 6-10 years **Boiler Room** ΕA 5 Auxiliaries - 25001 - 35000 cfm 1 2-5 years The filters are installed LF 5 Return Duct Work - Indoor- Vertical Shaft Boiler Room 100 10+ years and Ducts Zone Dampers Boiler Room 16 ΕA 5 6-10 years Boiler Systems Boiler Auxiliary- Non Condensing Hot Water Boiler Room 3 FΑ 5 6-10 years - 1001 - 2000 MBH **Chemical Pot Feeder** Boiler Room 1 ΕA 4 1-2 years Corroded 6 **Combustion Dampers** Boiler Room 3 ΕA 10+ years Non Condensing- Water Tube- Flexible Boiler Room 3 ΕA 5 6-10 years Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH ΕA Water Fill System **Boiler Room** 1 6 10+ years



**Building : Main** Category : Mechanical Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Heating Devices Wall Heater - Electric Engineer's Office 1 ΕA 4 0-1 year Non functional Mechanical Plumbing Hot Water Pump - Less than 10 Boiler Room 2 ΕA 6 6-10 years Hydronic Supply and Return - Steel Entire Building 200 LF 4 1-2 years Temperature Control Pneumatic System Entire Building 18.315 SF 6 10+ vears Thermostats - Pneumatic Entire Building 10 FΑ 7 6-10 years Ventilation Exhaust Fans- Indoor - 1501 - 8000 CFM 1 ΕA 4 Attic 0-1 year Inoperable **Category : Plumbing Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Hot Water Gas Heater - 150000 - 300000 BTU/HR ΕA 7 Boiler Room 1 10+ years Piping Domestic Piping-Hot Water Return Lines Entire Building 18,315 SF 6 6-10 years Domestic Piping-Hot Water Return Risers SF Entire Building 18,315 6 6-10 years SF Domestic Piping-Hot Water from Risers to Entire Building 18.315 6 6-10 years Fixtures Domestic Piping-Hot/Cold Water Supply SF Entire Building 18.315 6 6-10 years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply SF Entire Building 18,315 6 6-10 years (Risers) Domestic Piping-Hot/Cold Water Supply Entire Building 18,315 SF 6 6-10 years (from Risers to Fixtures) Sanitary Piping Entire Building 18.315 SF 5 6-10 years Storm Piping Entire Building 18,315 SF 6 6-10 years Vent Piping Entire Building 18.315 SF 6 6-10 years Pumps ΕA Pumps - Ejector-Duplex Boiler Room 2 6 6-10 years



Group

**Building : Main** Category : Room Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Administrative Suites/Offices Ceiling - Exposed Basement - Staff Office 152 SF 6 10+ years Doors - Wood Doors inclu hw **Basement - Staff Office** 1 ΕA 5 10+ years Floor - Epoxy/ Painted Basement - Staff Office 152 SF 4 10+ years Lighting - Pendent/Surface Basement - Staff Office ΕA 4 0-1 year 3 Storage/ Closet 36 SF Basement - Staff Office 5 10+ years Walls - Masonry Basement - Staff Office 394 SF 6 10+ years Work SInk Basement - Staff Office 1 FΑ 7 10+ years SF Ceiling - Plaster/Drvwall Faculty Lounge 288 7 10+ vears SF Doors - Transom Window Faculty Lounge 9 6 10+ years Doors - Wood Doors inclu hw Faculty Lounge 1 EΑ 6 10+ years Floor - Tile Faculty Lounge 288 SF 6 10+ years Lighting - Pendent/Surface Faculty Lounge ΕA 7 6-10 years 6 Power Distribution Faculty Lounge 7 ΕA 7 10+ years 705 SF 7 Walls - Plaster/Drvwall Faculty Lounge 10+ vears Work SInk Faculty Lounge FΑ 7 10+ years 1 Main Office SF Ceiling - Plaster/Drywall 143 7 10+ vears Doors - Transom Window SF Main Office 9 7 10+ years 7 Doors - Wood Doors inclu hw Main Office 1 EΑ 10+ years Floor - Carpet Main Office 143 SF 7 6-10 years Lighting - Pendent/Surface Main Office 2 ΕA 7 6-10 years Power Distribution Main Office 8 ΕA 7 10+ vears SF Storage/ Closet Main Office 3 7 10+ vears Walls - Plaster/Drvwall Main Office 513 SF 7 10+ vears AC Unit Principal's Office 1 EΑ 7 6-10 years Ceiling - Plaster/Drywall Principal's Office 135 SF 7 10+ years Doors - Wood Doors inclu hw Principal's Office 1 EA 6 10+ years SF Floor - Carpet Principal's Office 135 6 6-10 years Lighting - Pendent/Surface FΑ 6-10 years Principal's Office 3 6 Power Distribution Principal's Office 8 ΕA 7 10+ years SF Walls - Plaster/Drywall Principal's Office 345 7 10+ years 102A-MDF/Copy room Doors - Wood Doors inclu hw 2 ΕA 6 10+ years Quantity changed to match current observations SF Finishes 102A-MDF/Copy room 154 5 10+ vears Some chipped flooring tiles 102A-MDF/Copy room ΕA 7 6-10 vears Ductless split system Other Cooling Unit 1 Window AC Unit 102A-MDF/Copy room 0 FΑ 7 6-10 years Mechanical/ Service Rooms SF 16 5 10+ years

MDF IDF

18

1.485

SF

SF

5

5

10+ years

10+ years



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	Basement Storage	556	SF	5	10+ years	
Restroor	n						
	Accessories	1st Flr - Boys Restroom	224	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Flr - Boys Restroom	224	SF	7	10+ years	
	Doors - Transom Window	1st Flr - Boys Restroom	36	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr - Boys Restroom	224	SF	7	6-10 years	
	Floor Drain	1st Flr - Boys Restroom	1	EA	7	10+ years	
	Lavatory	1st Flr - Boys Restroom	3	EA	7	10+ years	Changed to match current observations
	Lighting - Pendent/Surface	1st Flr - Boys Restroom	4	EA	7	6-10 years	
	Partitions	1st Flr - Boys Restroom	3	EA	7	10+ years	
	Urinals	1st Flr - Boys Restroom	3	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr - Boys Restroom	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FIr - Boys Restroom	554	SF	7	10+ years	Newly remodeled/changed to mate current observations
	Water Closet	1st Flr - Boys Restroom	3	EA	7	10+ years	Newly remodeled/changed to mate
	Accessories	1st Flr - Girls Restroom	224	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Flr - Girls Restroom	224	SF	7	10+ years	
	Doors - Transom Window	1st Flr - Girls Restroom	36	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr - Girls Restroom	224	SF	7	10+ years	
	Floor Drain	1st Flr - Girls Restroom	1	EA	7	10+ years	
	Lavatory	1st Flr - Girls Restroom	3	EA	7	10+ years	Newly remodeled/changed to mate current observations
	Lighting - Pendent/Surface	1st Flr - Girls Restroom	4	EA	7	6-10 years	
	Partitions	1st Fir - Girls Restroom	5	EA	7	10+ years	Newly remodeled/changed to mate
	Walls - Plaster/Drywall	1st Fir - Girls Restroom	80	SF	7	-	current observations
	Walls - Tile Ceramic/ Porcelain	1st Fir - Girls Restroom	554	SF	7	10+ years	Changed to motch surrent
						10+ years	Changed to match current observations
	Water Closet	1st Flr - Girls Restroom	5	EA	7	10+ years	Newly remodeled/changed to mat current observations
	Accessories	2nd Flr- Girls Restroom	224	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd FIr- Girls Restroom	224	SF	6	10+ years	
	Doors - Transom Window	2nd Flr- Girls Restroom	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd FIr- Girls Restroom	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr- Girls Restroom	224	SF	6	10+ years	
	Floor Drain	2nd Flr- Girls Restroom	1	EA	7	10+ years	
	Hand Dryer	2nd Flr- Girls Restroom	2	EA	7	6-10 years	
	Lavatory	2nd Flr- Girls Restroom	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd FIr- Girls Restroom	3	EA	7	6-10 years	
	Partitions	2nd FIr- Girls Restroom	5	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Fir- Girls Restroom	80	SF	6	10+ years	



Catego	ry : Room		B	uilding	· Main		
outogo				anang	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	2nd Flr- Girls Restroom	554	SF	6	10+ years	
	Water Closet	2nd Flr- Girls Restroom	5	EA	7	10+ years	
	Accessories	2nd Flr-Boy's Toilet	224	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Flr-Boy's Toilet	224	SF	6	10+ years	
	Doors - Transom Window	2nd Flr-Boy's Toilet	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr-Boy's Toilet	3	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr-Boy's Toilet	224	SF	6	10+ years	
	Floor Drain	2nd Flr-Boy's Toilet	1	EA	7	10+ years	
	Hand Dryer	2nd Flr-Boy's Toilet	2	EA	7	6-10 years	
	Lavatory	2nd Flr-Boy's Toilet	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Flr-Boy's Toilet	3	EA	7	6-10 years	
	Partitions	2nd Flr-Boy's Toilet	3	EA	7	10+ years	
	Urinals	2nd Flr-Boy's Toilet	3	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Flr-Boy's Toilet	80	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Flr-Boy's Toilet	554	SF	6	10+ years	
	Water Closet	2nd Flr-Boy's Toilet	3	EA	7	10+ years	
	Accessories	Basement Staff Toilet	42	SF	5	2-5 years	
	Ceiling - Exposed	Basement Staff Toilet	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Staff Toilet	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	Basement Staff Toilet	42	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement Staff Toilet	1	EA	6	6-10 years	Broken/
	Walls - Masonry	Basement Staff Toilet	218	SF	6	10+ years	
	Water Closet	Basement Staff Toilet	1	EA	4	0-1 year	Not in use
	Accessories	Faculty Lounge	53	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Faculty Lounge	53	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Faculty Lounge	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Faculty Lounge	53	SF	6	10+ years	
	Lavatory	Faculty Lounge	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Faculty Lounge	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Faculty Lounge	285	SF	7	10+ years	
	Water Closet	Faculty Lounge	1	EA	6	10+ years	
	Accessories	Main Office Toilet	17	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office Toilet	17	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office Toilet	17	SF	7	10+ years	
	Lavatory	Main Office Toilet	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Main Office Toilet	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Main Office Toilet	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Main Office Toilet	148	SF	7	10+ years	
	Water Closet	Main Office Toilet	1	EA	7	10+ years	



**Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #100 (Regular Classroom) AC Units 1 ΕA 7 6-10 years 1st Floor Casework 1st Floor 9 LF 7 10+ years Ceiling - Plaster/Drywall 693 SF 7 10+ years 1st Floor Doors - Transom Window 9 SF 7 10+ years 1st Floor Doors - Wood Doors inclu hw FΑ 7 1st Floor 1 10+ years Floor - Tile 1st Floor 693 SF 7 10+ years Lighting - Pendent/Surface 1st Floor 12 FΑ 7 6-10 years LF Marker Board 1st Floor 50 7 6-10 years SF Walls - Plaster/Drywall 1st Floor 1,260 7 10+ years Classroom #101 (Kindergarten) AC Units 1st Floor 1 ΕA 7 6-10 years LF Casework 1st Floor 9 7 10+ vears Ceiling - Plaster/Drywall 693 SF 1st Floor 7 10+ years Doors - Transom Window 1st Floor 9 SF 7 10+ years Doors - Wood Doors inclu hw 7 1st Floor 1 EΑ 10+ years Floor - Tile SF 7 10+ years 1st Floor 693 Lighting - Pendent/Surface FΑ 7 1st Floor 12 6-10 years Marker Board 20 LF 7 6-10 years 1st Floor SF Walls - Plaster/Drywall 1st Floor 1,260 7 10+ years Classroom #102 (Computer Lab) AC Units 1st Floor 1 ΕA 7 6-10 years LF Casework 1st Floor 8 7 10+ vears SF Ceiling - Plaster/Drywall 1st Floor 812 7 10+ years Doors - Transom Window SF 7 1st Floor 18 10+ vears Doors - Wood Doors inclu hw 1st Floor 2 ΕA 7 10+ years Floor - Tile 1st Floor 812 SF 7 10+ years 7 Lighting - Pendent/Surface 1st Floor 16 EΑ 6-10 years Storage/ Closet 70 SF 7 1st Floor 10+ years SF Walls - Plaster/Drywall 1st Floor 6 7 10+ years Classroom #103 (Regular Classroom) AC Units 7 1st Floor 1 EA 6-10 years Casework 1st Floor 9 LF 7 10+ years Ceiling - Plaster/Drywall SF 1st Floor 693 7 10+ years LF Chalk Board 1st Floor 11 4 2-5 years SF Doors - Transom Window 1st Floor 9 7 10+ years ΕA Doors - Wood Doors inclu hw 1st Floor 1 7 10+ vears Floor - Tile 1st Floor 693 SF 7 10+ vears Lighting - Pendent/Surface 1st Floor 12 ΕA 7 6-10 years Marker Board LF 7 1st Floor 20 6-10 years



Kate S Kellogg Elementary School 9241 S Leavitt STREET, Chicago, IL 60643

Catego	ry : Classroom		В	uilding	: Main		
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,260	SF	7	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	693	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	693	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	693	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	693	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroo	om #201A (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	340	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	340	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	813	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	693	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	



Catego	ry : Classroom		R	uilding	· Main		
Calego			J	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Floor - Tile	2nd Floor	693	SF	6	10+ years	Comments
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	693	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	693	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	7	10+ years	
atego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•							
-		1st Floor		SF		10+ vears	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw	1st Floor 1st Floor	1,248 2	SF EA	7 7	10+ years 10+ years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw	1st Floor	1,248 2	EA	7 7	10+ years	Quantity changed to match curren observations
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain	1st Floor 1st Floor	1,248 2 3	EA EA	7 7 7	10+ years 10+ years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor	1,248 2 3 1,248	EA EA SF	7 7 7 7	10+ years 10+ years 10+ years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor	1,248 2 3 1,248 18	EA EA SF EA	7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,248 2 3 1,248 18 71	EA EA SF EA EA	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,248 2 3 1,248 18 71 1,108	EA SF EA EA SF	7 7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,248 2 3 1,248 18 71 1,108 1,108	EA SF EA SF SF SF	7 7 7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,248	EA SF EA SF SF SF	7 7 7 7 7 7 7 7 6	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,108 1,248 1	EA SF EA SF SF SF EA	7 7 7 7 7 7 7 7 6 7	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,108 1,248 1 1	EA EA SF EA SF SF EA EA	7 7 7 7 7 7 7 7 6 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,108 1,248 1 1 1,248	EA SF EA SF SF EA SF SF SF	7 7 7 7 7 7 7 7 6 7 7 5	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
•	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,248 1 1 1,248 1 1	EA EA EA SF EA SF EA SF EA SF EA	7 7 7 7 7 7 7 7 6 7 5 7	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,108 1,248 1 1 1,248 16 90	EA EA SF EA SF EA SF EA SF EA EA EA	7 7 7 7 7 7 7 7 6 7 7 5 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,108 1,248 1 1 1,248 16 90 1,108	EA EA SF EA SF EA SF EA SF EA SF SF	7 7 7 7 7 7 7 7 6 7 5 7 6	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
-	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,108 1,248 1 1 1,248 16 90	EA EA SF EA SF EA SF EA SF EA EA EA	7 7 7 7 7 7 7 7 6 7 7 5 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
Corridor	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,248 1 1 1,248 16 90 1,108 1,108	EA EA SFA EA SFF EA SF EA SF SF SF	7 7 7 7 7 7 7 7 7 6 7 7 5 7 7 6 6	10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	
Corridor	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,248 1 1 1,248 16 90 1,108 1,108	EA EA SF EA SF EA SF EA SF EA	7 7 7 7 7 7 7 6 7 7 6 6 6	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
Safety	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - Two Tiers Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,248 2 3 1,248 18 71 1,108 1,108 1,248 1 1 1,248 16 90 1,108 1,108	EA EA SFA EA SFF EA SF EA SF SF SF	7 7 7 7 7 7 7 7 7 6 7 7 5 7 7 6 6	10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	Quantity changed to match current observations



# Kate S Kellogg Elementary School 9241 S Leavitt STREET, Chicago, IL 60643

Category : Interior				uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Stairs							
	Ceiling - Exposed	Basement Stairs	90	SF	6	10+ years	
	Floor - Epoxy/ Painted	Basement Stairs	90	SF	4	6-10 years	
	Handrails	Basement Stairs	18	LF	7	10+ years	
	Lighting - Wall Mounted	Basement Stairs	2	EA	7	6-10 years	
	Stairs - Concrete	Basement Stairs	52	LF	6	10+ years	
	Walls - Masonry	Basement Stairs	737	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North Stairs	392	SF	7	10+ years	
	Floor - Terrazzo	North Stairs	315	SF	6	10+ years	
	Handrails	North Stairs	69	LF	7	10+ years	
	Lighting - Pendent/Surface	North Stairs	6	EA	7	6-10 years	
	Lighting - Wall Mounted	North Stairs	2	EA	7	6-10 years	
	Stairs - Terrazzo	North Stairs	172	LF	6	10+ years	
	Walls - Plaster/Drywall	North Stairs	731	SF	6	10+ years	
	Walls - Structural Glazed Tile	North Stairs	731	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South Stairs	392	SF	7	10+ years	
	Floor - Terrazzo	South Stairs	315	SF	6	10+ years	
	Handrails	South Stairs	69	LF	7	10+ years	
	Lighting - Pendent/Surface	South Stairs	8	EA	7	6-10 years	
	Stairs - Terrazzo	South Stairs	172	LF	6	10+ years	
	Walls - Plaster/Drywall	South Stairs	731	SF	6	10+ years	
	Walls - Structural Glazed Tile	South Stairs	731	SF	7	10+ years	



**Category : Exterior Building : Addition** Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Entrance FΑ 7 Entrance Control - Audio and Video #4 - Southeast 1 10+ years 2 ΕA Exterior Doors - Exterior Steel Door #4 - Southeast 6 10+ years 2 Exterior Doors - Transom Lite #4 - Southeast EΑ 6 10+ years Exterior Stairs - Concrete #4 - Southeast 14 LF 6 10+ years LF Ramp Handrail - Steel Ramp Handrail #4 - Southeast 41 6 10+ years Ramps - Steel or Aluminum LF #4 - Southeast 42 6 10+ years Entrance Control - Audio and Video #5 - Southwest 1 EΑ 7 10+ years Exterior Doors - Exterior Steel Door #5 - Southwest 2 ΕA 7 10+ vears Exterior Doors - Transom Lite #5 - Southwest 2 ΕA 6 10+ years LF 7 10+ years Exterior Stairs - Concrete #5 - Southwest 144 Power Door Operator and Controls #5 - Southwest 1 EA 7 10+ years Ramp Handrail - Steel\_Ramp Handrail 40 LF 7 #5 - Southwest 10+ years Ramps - Concrete #5 - Southwest 20 LF 7 10+ years LF Stair Handrail - Steel Stair Handrail #5 - Southwest 22 7 10+ years Foundation Foundation - Concrete Entire Building 333 LF 7 10+ years SF Superstructure - Steel with Clay Tile Arch Entire Building 8,328 7 10+ years Liahtina Exterior Lighting - Parapet or Roof Mounted Entire Building 3 ΕA 7 10+ years Exterior Lighting - Wall Mounted Entire Building 5 ΕA 6 10+ years Roof System Access Ladder - Metal В 1 ΕA 7 10+ years В LF Coping - Stone 137 6 10+ years Downspouts - Interior Downspouts В 62 LF 6 10+ vears Parapet - Parapet < 16" Height В LF 120 6 10+ years Parapet - Parapet < 16" Height В LF 6 10+ years 17 в Roof - Modified Bitumen 2,345 SF 6 10+ years В 7 Roof Hatch - Metal 1 ΕA 10+ years В 2.345 SF Roof Structure - Steel / Metal Deck/ 7 10+ years Concrete Toppina Access Ladder - Metal С 1 EΑ 7 10+ years С LF Coping - Stone 216 6 10+ vears С **Downspouts - Interior Downspouts** 28 LF 6 10+ years Parapet - Parapet < 16" Height С LF 6 10+ years 216 Roof - Modified Bitumen С SF 3,638 6 10+ years С Roof Structure - Steel / Metal Deck/ 3,638 SF 7 10+ years Concrete Topping



### Kate S Kellogg Elementary School

Catego	ory : Exterior		В	uilding	: Additio	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Valls							
	Exterior Walls - Brick	Entire Building	6,911	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	124	SF	6	10+ years	
Vindow	s						
maom	Guard - Guards perforated	Entire Building	495	SF	7	10+ years	
	Guard - Guards wire guard	Entire Building	360	SF	6	10+ years	
	Lintels - Steel	Entire Building	96	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,179	SF	6	10+ years	
Category : Electrical Building : Addition							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merge	ncy System						
	Emergency Battery Packs - Corridors and Stairs	Corridor	1	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Corridor	1	EA	7	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	562	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	2,413	SF	6	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	· 1	EA	2	0-1 year	No battery backup
	Exit Signs - Gym	Entire Building	3	EA	2	0-1 vear	No battery backup
	Security System - CCTV	Entire Building	8,328	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	8,328	SF	6	6-10 years	
∕lain Se	rvice						
	PA System	Entire Building	8,328	SF	6	6-10 years	Connected with the main building
ower D	Distribution						
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	6-10 years	
atego	bry : Fire Protection		В	uilding	: Additie	on	
-				Ŭ		Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Fire AlarmFire Alarm Strobe LightsEntire Building8,328SF66-10 yearsFire Alarm\_SystemEntire Building8,328SF66-10 years



#### Kate S Kellogg Elementary School

<b>AT</b>	Schools	Kate S Kellogg Elementary Schoo 9241 S Leavitt STREET, Chicago, IL 6064					
Catego	ry : Mechanical		В	uilding	: Additi	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
leating	Devices Wall Heater - Electric	Gym	2	EA	5	2-5 years	
empera	ature Control						
	Pneumatic System	Entire Building	8,328	SF	6	10+ years	
	Thermostats - Pneumatic	Entire Building	6	EA	7	2-5 years	Thermostats are new
/entilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Attic	2	EA	4	0-1 year	Non functional
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Attic	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additi	on	
••••	H		Owentites		Daula	Recommend	Original
<b>Group</b> Piping	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
siping	Domestic Piping-Hot Water Return Lines	Entire Building	8,328	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	8,328	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	8,328	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	8,328	SF	6	6-10 years	
	Sanitary Piping	Entire Building	8,328	SF	6	6-10 years	
	Storm Piping	Entire Building	8,328	SF	6	6-10 years	
	Vent Piping	Entire Building	8,328	SF	6	6-10 years	
Catego	ry : Room		В	uilding	: Additi	on	
Crours	Itom Tuno	Location	Ouentitu	UOM	Rank	Recommend	Commonto
Group	Item - Type rative Suites/Offices	LUCATION	Quantity		Rank	Replacement	Comments
Administ		105 Adjustment Deem	000	0	7	10	
	Ceiling - Plaster/Drywall Doors - Transom Window	105 - Adjustment Room 105 - Adjustment Room	323 9	SF SF	7 7	10+ years 10+ years	
	Doors - Wood Doors inclu hw	105 - Adjustment Room	9	EA	7	10+ years	
	Floor - Tile	105 - Adjustment Room	323	SF	7	10+ years	
	Lighting - Pendent/Surface	105 - Adjustment Room	6	EA	7	6-10 years	
			0		-	10 yourd	

Power Distribution

Floor - Tile

Walls - Plaster/Drywall

Ceiling - Plaster/Drywall

Doors - Wood Doors inclu hw

Lighting - Pendent/Surface

105 - Adjustment Room

105 - Adjustment Room

Library Office

Library Office

Library Office

Library Office

ΕA

SF

SF

ΕA

SF

ΕA

7

7

7

6

6

7

10+ years

10+ years

10+ years

10+ years

10+ years

6-10 years

8

850

86

86

2

2



Category : Room

alego			D	unung	. Auun		
			<b>•</b>			Recommend	<b>.</b> .
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Library Office	8	EA	7	10+ years	
	Storage/ Closet	Library Office	3	SF	5	10+ years	
	Walls - Plaster/Drywall	Library Office	291	SF	6	10+ years	
	Work SInk	Library Office	1	EA	7	10+ years	
iymnas	ia						
	Ceiling - Lay-in	1st Floor	2,800	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	4	SF	5	0-1 year	Missing tile
	Ceiling - Plaster/Drywall	1st Floor	399	SF	7	10+ years	C C
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	10+ years	
	Floor - Tile	1st Floor	85	SF	7	10+ years	
	Floor - Tile	1st Floor	304	SF	7	10+ years	
	Floor - Wood	1st Floor	2,814	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	10+ years	
		1st Floor	414	SF			
	Stage				7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage-Stairs - Tile	1st Floor	41	LF	7	10+ years	
	Storage/ Closet	1st Floor	154	SF	5	6-10 years	Changed to match current observations
	Walls - Plaster/Drywall	1st Floor	990	SF	7	10+ years	observations
	Walls - Structural Glazed Tile	1st Floor	3,589	SF	7	10+ years	
			0,000	0.	•	i e i yeare	
ibrary							
2	AC Unit	204	1	EA	7	6-10 years	
	Casework	204	66	LF	6	10+ years	
	Ceiling - Splined	204	693	SF	6	10+ years	
	Doors - Transom Window	204	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	204	1	EA	6	10+ years	
	Floor - Tile	204	693	SF	6	6-10 years	
	Lighting - Pendent/Surface	204	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	204	1,260	SF	6	10+ years	
		204	1,200	5	0	IUT years	
lechani	cal/ Service Rooms						
	Storage Room	Storage near library	10	SF	7	10+ years	
			.0	0,	,	is: youro	
estroor	n						
	Ceiling - Plaster/Drywall	Gymnasium - Men's (Used as	58	SF	7	10+ years	
	÷ ,						
		Storage)					
	Doors - Wood Doors inclu hw	Storage) Gymnasium - Men's (Used as	1	EA	7	10+ years	

**Building : Addition** 



Catego	ry : Room		В	uilding	: Additi	on	,,,,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Gymnasium - Men's (Used as Storage)	58	SF	7	10+ years	
	Lighting - Pendent/Surface	Gymnasium - Men's (Used as Storage)	1	EA	7	6-10 years	
	Partitions	Gymnasium - Men's (Used as Storage)	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Gymnasium - Men's (Used as Storage)	275	SF	7	10+ years	Newly remodeled
	Accessories	Gymnasium - Unisex	58	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gymnasium - Unisex	58	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gymnasium - Unisex	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gymnasium - Unisex	58	SF	7	10+ years	
	Lavatory	Gymnasium - Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Gymnasium - Unisex	7	EA	7	6-10 years	
	Partitions	Gymnasium - Unisex	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Gymnasium - Unisex	60	SF	7	10+ years	Newly remodeled/changed to match current observations
	Walls - Tile Ceramic/ Porcelain	Gymnasium - Unisex	215	SF	7	10+ years	Newly remodeled/changed to match current observations
	Water Closet	Gymnasium - Unisex	1	EA	7	10+ years	-

### Category : Classroom

Catego	ry : Classroom		Building : Addition					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Classroo	om #104 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	10	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	691	SF	7	10+ years		
	Doors - Transom Window	1st Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	691	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years		
	Marker Board	1st Floor	40	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,260	SF	7	10+ years		
Classroo	om #205 (Science Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	24	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	706	SF	7	10+ years		
	Chalk Board	2nd Floor	5	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	706	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years		



Catego	ry : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	11	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	72	SF	5	10+ years	
	Storage/ Closet	2nd Floor	6	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,229	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	

**Building : Addition** 

#### **Category : Interior**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1sr Floor - S + SE Corridor	591	SF	7	10+ years	
	Doors - Transom Window	1sr Floor - S + SE Corridor	18	SF	7	10+ years	
	Doors - Wood Doors include hw	1sr Floor - S + SE Corridor	2	EA	7	10+ years	Changed to match current observations
	Floor - Tile/Sheet	1sr Floor - S + SE Corridor	591	SF	5	10+ years	
	Lighting - Pendent/Surface	1sr Floor - S + SE Corridor	8	EA	7	6-10 years	
	Student Lockers - Two Tiers	1sr Floor - S + SE Corridor	65	EA	7	10+ years	
	Walls - Plaster/Drywall	1sr Floor - S + SE Corridor	708	SF	7	10+ years	
	Walls - Structural Glazed Tile	1sr Floor - S + SE Corridor	666	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor S Corridor	264	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor S Corridor	264	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor S Corridor	2	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor S Corridor	36	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor S Corridor	264	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor S Corridor	201	SF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Modul	ar 1 (4-Classro Recommend	om )
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
Entrance							
	Entrance Control - Audio and Video	#6 West	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#6 West	2	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#7 East	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#7 East	12	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#7 East	26	LF	6	10+ years	
Foundati	on						
	Foundation - Concrete	Entire Building	250	LF	7	10+ years	
	Foundation - Masonry	Entire Building	10	LF	6	10+ years	
	Superstructure - Slab on Grade	Entire Building	4,200	SF	7	10+ years	
Lighting							
-0 0	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	10+ years	
Roof Sys	stem						
-	Coping - Metal	D	60	LF	6	10+ years	
	Coping - Metal	D	200	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	D	4,200	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	D	4,200	SF	7	10+ years	
Walls							
	Exterior Walls - Hardie Board	Entire Building	2,670	SF	6	10+ years	
	Exterior Walls - Hardie Board	Entire Building	450	SF	4	1-2 years	Cracked, spalling
Windows	3						
	Guard - Guards wire guard	Entire Building	260	SF	7	10+ years	
	Lintels - Steel	Entire Building	48	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	240	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (4-Classro	om )
0	Here The	Lesster	•		<b>D</b> . 1	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	nev Svetem						
Emergen	, ,		-		_	<b>A</b> 4 <b>A</b>	
Emerger	Exit Signs - Corridors and Stairs	Entire Building	2	EA	7	6-10 years	
Emerger	, ,	Entire Building Entire Building	2 2	EA EA	7 6	6-10 years 6-10 years	



9241 S Leavitt STREET, Chicago, IL 60643 Building : Modular 1 (4-Classroom ) **Category : Electrical** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Main Service Main Electrical Service - 800 A and Less 2 ΕA 6 West Facade 10+ years than 120/208/3PH Power Distribution Lighting and Power Panels - Above 100 A Entire Building 1 ΕA 7 10+ years Building : Modular 1 (4-Classroom) **Category : Fire Protection** Recommend **Replacement** Comments Group Item - Type Location Quantity UOM Rank Sprinkler System SF 7 Sprinkler Heads Entire Building 4,200 6-10 years Sprinkler Piping Entire Building 4,200 SF 7 10+ years Wet Sprinkler System Entire Building 4,200 SF 7 6-10 years Building : Modular 1 (4-Classroom ) **Category : Mechanical** Recommend Item - Type Location Quantity UOM **Replacement** Comments Group Rank Temperature Control Electric Controls Entire Building 4.200 SF 6 6-10 vears Electric Thermostat Entire Building 4 ΕA 6 6-10 years Unit Ventilation Unit Ventilators - Vertical Package Electric ΕA Entire Building 4 6 6-10 years Heat & Self Contained Cooling Ventilation Exhaust Fans- Roof Mounted - Less than Roof 6 ΕA 6 6-10 years 500 CFM **Category : Plumbing** Building : Modular 1 (4-Classroom ) Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Hot Water Electric Heater - Less than 20 KW Mechanical Room 1 ΕA 7 10+ years Piping Domestic Piping-Hot Water Return Lines Entire Building 4,200 SF 6 10+ years Domestic Piping-Hot Water from Risers to SF Entire Building 4,200 6 10+ years Fixtures Domestic Piping-Hot/Cold Water Supply 4.200 SF Entire Building 6 10+ years



Catego	ry : Plumbing		В	Building : Modular 1 (4-Classroom )					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	(Horizontal Lines)								
	Domestic Piping-Hot/Cold Water Supply	Entire Building	4,200	SF	6	10+ years			
	(from Risers to Fixtures)								
	Sanitary Piping	Entire Building	4,200	SF	6	10+ years			
	Storm Piping	Entire Building	4,200	SF	6	10+ years			
	Vent Piping	Entire Building	4,200	SF	6	10+ years			

Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	om )
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroc	m #A-2nd Grade (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	643	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	603	SF	6	10+ years	
	Floor - Tile	1st Floor	40	SF	4	0-1 year	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	46	SF	5	10+ years	
	Walls - Metal Panel	1st Floor	769	SF	7	10+ years	
assroc	m #B-1st Grade (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	643	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	599	SF	6	10+ years	
	Floor - Tile	1st Floor	44	SF	4	0-1 year	Cracking
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	5
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	46	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	769	SF	7	10+ years	
assroo	m #C-Kindergarten (Kindergarten)						
	Ceiling - Lay-in	1st Floor	635	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	0-1 year	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	586	SF	6	10+ years	
	Floor - Tile	1st Floor	57	SF	4	0-1 year	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	769	SF	7	10+ years	
lassroo	m #D-3rd Grade (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	643	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	pom )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	627	SF	7	10+ years	
	Floor - Tile	1st Floor	16	SF	4	0-1 year	Cracking
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	46	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	769	SF	7	10+ years	
Catego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	oom )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	60	SF	5	10+ years	
Restroor	n						
	Accessories	1st Floor	138	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	138	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	138	SF	5	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Partitions	1st Floor	1	EA	5	10+ years	
	Urinals	1st Floor	3	EA	6	10+ years	
	Walls - Metal Panel	1st Floor	390	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	170	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	167	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	170	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	435	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	7	10+ years	



# Kate S Kellogg Elementary School 9241 S Leavitt STREET, Chicago, IL 60643

Catego	ry : Interior		Building : Modular 1 (4-Classroom )					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	k Replacement	Comments	
Corridor								
	Ceiling - Lay-in	1st Floor	679	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years		
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	679	SF	4	1-2 years	Cracking throughout the entire corridor	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years		
	Walls - Metal Panel	1st Floor	1,138	SF	7	10+ years		



Catego	ry : Site		В	uilding	: Site		
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic				~-			
	Surface - Natural	northeast	5,625	SF	6	10+ years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	7	10+ years	
encing				. –			
	Fencing - Chain Link	Entire Site	111	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site Entire Site	180 1,801	LF LF	6	10+ years	
	Fencing - New Standard Ornamental Fencing - New Standard Ornamental	Entire Site	20	LF	7 5	10+ years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	5	2-5 years	
andsca	be						
	Benches	Entire Site	4	EA	7	10+ years	
	Landscape - Grass	Entire Site	84,500	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	212	SF	6	10+ years	
	Parkway trees	Entire Site	55	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	2,100	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	168	SF	6	10+ years	
	Trash Receptacles	Entire Site	1	EA	6	10+ years	
Parking L	ot						
<u></u>	Surface - Asphalt	North	14,160	SF	6	6-10 years	Recent repairs
	Trash Enclosure - Chain Links	North	765	SF	6	10+ years	·
Playgrou	nd						
aygiou	Equipment - Combo 3-12	West	1	EA	6	10+ years	
	Equipment - Pre K 3-5	West	1	EA	6	10+ years	
	Equipment - Swingset	West	1	EA	6	10+ years	
	Surface - Poured Surface	West	2,525	SF	5	1-2 years	Holes throughout
Sidewalk	6						
	Sidewalks - Internal Walks	Entire Site	400	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	129,756	SF	6	10+ years	
Signage							
nginaye	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	7	10+ years	Building
	Sign				-	,	



Catego	ry : Site		В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Monument - Sign	Entire Site	1	EA	7	10+ years	

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



#### **Classroom Summary**

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					_				
Computer Lab	Kindergarten	1st Floor	102	102	812	150	60	Y	Y
Kindergarten	Regular Classroom	1st Floor	101	101	693	150	60	Y	Y
Regular Classroom	Regular Classroom	1st Floor	100	100	693	150	60	Y	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	693	150	60	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	200	200	693	150	60	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	693	150	60	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	693	150	48	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	693	150	60	Y	Y
Regular Classroom	Store Room	2nd Floor	201A	N/A	340	60	24	Y	N

Building : Modular 1 (4-0	lassroom)								
Kindergarten	Regular Classroom	1st Floor	C- Kindergarte	-	643	60	30	Y	Y
Regular Classroom	Regular Classroom	1st Floor	A-2nd Grade	-	643	60	30	Y	N
Regular Classroom	Regular Classroom	1st Floor	B-1st Grade	-	643	60	30	Y	N
Regular Classroom	Regular Classroom	1st Floor	D-3rd Grade	-	643	60	30	Y	N

Building : Addition									
Regular Classroom	Regular Classroom	1st Floor	104	104	691	150	60	Y	N
Science Classroom	Regular Classroom	2nd Floor	205	205	706	150	60	Y	Y