

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	2000	3	218,126
Campus Total			218,126

Category: Exterior **Building: Main** Recommend Item - Type Location Quantity **UOM** Rank Replacement Comments Group Entrance Exterior Doors - Store Front Entrance 2-SW 3 EΑ 7 10+ years Exterior Doors - Transom Lite Entrance 2-SW 3 EΑ 7 10+ years Exterior Doors - Store Front Entrance 3-NW 3 FΑ 10+ years 6 3 Exterior Doors - Transom Lite Entrance 3-NW FΑ 7 10+ years Entrance Control - Audio and Video **Entrance 4-East** 1 EΑ 7 10+ years Exterior Doors - Store Front **Entrance 4-East** 3 FΑ 7 10+ years 3 Exterior Doors - Transom Lite **Entrance 4-East** EΑ 7 10+ years 2 Exterior Doors - Exterior Steel Door Entrance 5A-SE - Outside yard EΑ 6 10+ years storage Exterior Doors - Exterior Steel Door Entrance 6-SW - Electrical 1 FΑ 6 10+ years Exterior Doors - Exterior Steel Door 2 FΑ Entrance 7-E 6 10+ years Exterior Doors - Exterior Steel Door Entrance 9-SW - Kitchen 1 FΑ 5 0-1 year Rust at frame 2 Exterior Doors - Exterior Steel Door Exit 5-S FΑ 6 10+ years Exterior Doors - Exterior Steel Door Exit 8-N - Lunchroom 2 FΑ 6 6-10 years Entrance Control - Audio and Video Main Entrance 1 - West 1 EΑ 7 10+ years Exterior Doors - Side lite 4 EΑ 7 10+ years Main Entrance 1 - West Exterior Doors - Store Front Main Entrance 1 - West 4 EΑ 6 6-10 years Exterior Doors - Transom Lite Main Entrance 1 - West 2 FΑ 7 10+ years Foundation LF Foundation - Concrete **Entire Building** 1,150 7 10+ years **Entire Building** SF 7 Superstructure - Metal Deck/ Concrete 218.126 10+ years Topping



Catego	ry : Exterior		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Lighting	Evilia Boro Boro	E (0.5			0.40			
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	25	EΑ	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	15	EΑ	7 4	6-10 years	Draken lene		
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	0-1 year	Broken lens		
Roof Sys	tem								
	Access Ladder - Metal	Roof 1 - Main	1	EA	7	10+ years			
	Coping - Stone	Roof 1 - Main	800	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof 1 - Main	900	LF	7	10+ years			
	Parapet - Parapet > 30"	Roof 1 - Main	800	LF	6	10+ years			
	Roof - Modified Bitumen	Roof 1 - Main	25,625	SF	5	0-1 year	Granule loss, cracking.		
	Roof Hatch - Metal	Roof 1 - Main	1	EA	5	0-1 year	Loose hatch door		
	Roof Structure - Steel / Metal Deck/	Roof 1 - Main	25,625	SF	7	10+ years			
	Concrete Topping					•			
	Coping - Stone	Roof 2 - South	260	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof 2 - South	125	LF	7	10+ years			
	Downspouts - Interior Downspouts	Roof 2 - South	25	LF	7	10+ years			
	Parapet - 16" - 30" Height	Roof 2 - South	260	LF	7	10+ years			
	Roof - Modified Bitumen	Roof 2 - South	6,820	SF	5	0-1 year	Bubbling		
	Roof Structure - Steel / Metal Deck/	Roof 2 - South	6,820	SF	7	10+ years	•		
	Concrete Topping		-,-			, , , , ,			
	Coping - Stone	Roof 3 - West	270	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof 3 - West	160	LF	6	10+ years			
	Parapet - Parapet < 16" Height	Roof 3 - West	270	LF	6	10+ years			
	Roof - Modified Bitumen	Roof 3 - West	2,055	SF	6	6-10 years			
	Roof Structure - Steel / Metal Deck/	Roof 3 - West	2,055	SF	7	10+ years			
	Concrete Topping		_,000	О.	-	. o . y ca. c			
	Chimney - Metal Flue	Roof 4 - North	60	LF	6	10+ years			
	Coping - Stone	Roof 4 - North	260	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof 4 - North	125	LF	7	10+ years			
	Downspouts - Interior Downspouts	Roof 4 - North	25	LF	7	10+ years			
	Parapet - 16" - 30" Height	Roof 4 - North	260	LF	7	10+ years			
	Roof - Modified Bitumen	Roof 4 - North	6,820	SF	6	6-10 years			
	Roof Structure - Steel / Metal Deck/	Roof 4 - North	6,820	SF	7	10+ years			
	Concrete Topping	rtoor r rtorur	0,020	O.	,	101 youro			
Valls									
valis	Canopy - Metal	Entire Building	800	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	29.050	SF	6	10+ years			
	Exterior Walls - Stone-Cast	Entire Building	6,030	SF	7	10+ years			
	Extendi Wans - Otone-Cast	Litale building	0,030	OI.	1	10+ years			
Vindows									
	Clerestory - Glass Double-Pane	Entire Building	720	SF	7	10+ years			



Category : Exterior

William K New Sullivan Elementary School 8331 S Mackinaw AVENUE, Chicago, IL 60617

Recommend

Building: Main

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Guard - Guards perforated	Entire Building	2,720	SF	6	6-10 years	
	Lintels - Steel	Entire Building	1,490	LF	7	10+ years	
	Windows - Louver	Entire Building	610	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,820	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	320	SF	3	0-1 year	Windows access to west roof, window
	Wildows Cash, Wallington Boasie parie	Zitaro Banamig	020	O.	Ü	o i youi	not staying open
Catego	ry : Electrical		R	uilding	· Main		
Calego	ry . Liectricai			unung	. IVICIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Security System - CCTV	Entire Building	218,126	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	218,126	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	22,406	SF	7	10+ years	
	Emergency A/C Power - Gym	Entire Building	4,153	SF	7	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	4,112	SF	7	10+ years	
	Emergency Battery Packs - Corridors and	Entire Building	18	ĒΑ	6	6-10 years	
	Stairs	Entire Duilding	6	ГΛ	6	6.10 vooro	
	Emergency Battery Packs - Gym	Entire Building	6 6	EA EA	6 6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building				6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA EA	6	6-10 years	No bottom chapture man bookure
	Exit Signs - Corridors and Stairs	Entire Building	23		2	0-1 year	No battery backup nor backup generator
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	2	0-1 year	No battery backup nor backup generator
	Exit Signs - Gym	Entire Building	8	EA	2	0-1 year	No battery backup nor backup generator
	Exit Signs - Lunchroom	Entire Building	7	EA	2	0-1 year	No battery backup nor backup generator
	Exit Signs - Lunchroom	Entire Building	1	EA	2	0-1 year	No battery backup nor backup generator
_Main Sei	rvice						
	Main Electrical Service - 2000 A 277/480/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	
	emergency power PA System	Entire Building	218,126	SF	6	6-10 years	
Dower D	intribution						
_Power D	istribution	Floatrical Dears	4		7	40	
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	7	10+ years	

Campus Name: New Sullivan Page : 3 of 35 Assessment Date: 04/13/2022



	y : Electrical		R	uilding	· Main		
Calegory	y . Electrical		В	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Electrical Room	5	EA	7	10+ years	Commonio
	Lighting and Power Panels - Above 100 A	Electrical Room	2	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Electrical Room	14	EΑ	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Electrical Room	1	EA	7	10+ years	
	amp	Electrical (Com	'	L/ \	,	101 years	
	Main Distribution Panels - Greater than 600	Electrical Room	1	EA	7	10+ years	
	amp	Electrical (Com	'	L/ \	,	101 years	
	Transformers - 277/480 - 120/208	Electrical Room	2	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Electrical Room	2	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	6	10+ years	
	Transformers - 277/400 - 120/200	Liectifical Nooili	'	LA	U	10+ years	
Category	y : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarm	1						
	Fire Alarm Panel	Mechanical Room	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Mechanical Room	218,126	SF	7	10+ years	
	Fire Alarm_System	Mechanical Room	218,126	SF	7	10+ years	
	Fire Pump Controller	Mechanical Room	1	EA	6	10+ years	
	The Famp Controller	West amount toom	·	_, 、	Ŭ	io. youro	
Pump Roc	om Assembly						
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	10+ years	
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	
	, ,					,	
Sprinkler							
	Sprinkler Heads	Entire Building	218,126	SF	7	10+ years	
	Sprinkler Piping	Entire Building	218,126	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	218,126	SF	6	10+ years	
Category	y : Mechanical		В	uilding	: Main		
Craun	Itam Tuna	Location	Ouantitu	LIOM	Donk	Recommend	Comments
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Condit							
	Chemical Pot Feeder	Roof	1	EA	7	6-10 years	
	Chiller-Air Cooled- Recipricating-Roof	Roof	1	EA	6	6-10 years	Serves 1st floor and gym.
	Mounted - 201 - 300 tons						
	Chiller-Air Cooled- Recipricating-Roof	Roof	1	EA	6	6-10 years	Serves second and third floors, north
	Mounted - 50 - 100 tons						chiller.
	Pipes - Chilled Water Pipe- Copper	Roof	500	LF	6	10+ years	
	Pipes - Chilled Water Pipe- Steel	Roof	100	LF	6	10+ years	
	Pressure Fill System	Roof	1	EA	6	10+ years	



Category : Mechanical		В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	ling Systems						
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	6	EA	6	10+ years	Above ceilings, served by AHU 3.
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	15	EA	6	10+ years	Above ceilings, served by AHU 4.
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	5	EA	6	10+ years	Above ceilings, served by AHU 1.
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	25	EA	6	10+ years	Above ceilings, served by AHU 2.
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF3
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	2	EA	6	10+ years	RF 4 and 1
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF2
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room	1	EA	6	10+ years	AHU 2, serves second and third floors.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	6	10+ years	AHU 4, serves gym.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room	1	EA	6	10+ years	AHU 3 Serves Cafeteria.
	Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room	1	EA	6	10+ years	AHU 1, serves first floor.
	Air Intake	Mechanical Room	1	EA	7	10+ years	
	Air Intake	Mechanical Room	1	EA	7	10+ years	
	VAV Box	Mechanical Room	24	EA	6	10+ years	Above ceilings, second and third floors.
	VAV Box	Mechanical Room	16	EA	6	10+ years	Above ceilings, first floor.
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Roof	1	EA	5	2-5 years	Serves kitchen, MAU-1. Rusting.
Boiler Sy	stems						
	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Boiler Room	3	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	3	EA	6	10+ years	
	Combustion Dampers	Boiler Room	3	EA	6	10+ years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH	Boiler Room	3	EA	6	10+ years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Fill System	Boiler Room	1	EA	6	10+ years	
_							
Gas Boo							
	Gas Booster	Boiler Room	1	EA	6	10+ years	
Heating	Devices						
Ü	Cabinet Heaters - With Hot Water Coil	Entire Building	21	EA	6	6-10 years	
	Radiator Panels - Hot Water	Entire Building	12	EA	6	6-10 years	
	Unit Heater - Electric	Mechanical Room	3	EA	6	10+ years	
	Unit Heater - Hot Water	Mechanical Room	6	EA	6	10+ years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	1,500	LF	7	10+ years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	2	EA	6	6-10 years	In North Mechanical Room
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	2	EA	6	6-10 years	In South Mechanical Room
	Hot Water Pump - 10 - 20 HP	Mechanical Room	4	EA	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	4	EA	5	2-5 years	Recirculating pumps.
Tempera	ature Control						
	DDC System	Entire Building	218,126	SF	5	6-10 years	
	Electric Controls	Entire Building	218,126	SF	6	10+ years	
	Electric Thermostat	Entire Building	10	EA	6	10+ years	
	Thermostats - DDC	Entire Building	113	EA	6	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof, 1st floor, Facade SE	3	EA	6	10+ years	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof, 1st floor, Facade SE	2	EA	6	10+ years	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof, 1st floor, Facade SE	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof, 1st floor, Facade SE	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Roof, 1st floor, Facade SE	2	EA	5	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof, 1st floor, Facade SE	1	EA	7	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Roof, 1st floor, Facade SE	1	EA	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Electric Heater - Greater than 50 KW	Kitchen	1	EA	6	6-10 years	For dishwasher.
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	7	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping							
ping	Domestic Piping-Hot Water Return Lines	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	218,126	SF	7	10+ years	
	Sanitary Piping	Entire Building	218,126	SF	7	10+ years	
	Storm Piping	Entire Building	218,126	SF	7	10+ years	
	Vent Piping	Entire Building	218,126	SF	7	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	10+ years	Under elevator.
Catego	ry : Room		В	uilding	: Main		

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	rative Suites/Offices						
	Ceiling - Lay-in	109A gym office	55	SF	6	10+ years	
	Ceiling - Lay-in	109A gym office	48	SF	4	0-1 year	Water damage.
	Doors - Side-lite	109A gym office	9	SF	6	10+ years	•
	Doors - Wood Doors inclu hw	109A gym office	1	EΑ	6	10+ years	
	Floor - Tile	109A gym office	103	SF	6	10+ years	
	Lighting - Lay-in	109A gym office	1	EA	7	6-10 years	
	Power Distribution	109A gym office	4	EΑ	7	6-10 years	
	Walls - Concrete Block	109A gym office	380	SF	7	10+ years	
	Ceiling - Lay-in	113 counselor	121	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113 counselor	1	EA	7	10+ years	
	Floor - Tile	113 counselor	121	SF	7	10+ years	
	Lighting - Lay-in	113 counselor	2	EΑ	7	6-10 years	
	Power Distribution	113 counselor	4	EA	7	6-10 years	
	Walls - Concrete Block	113 counselor	225	SF	7	10+ years	
	Ceiling - Lay-in	116 # 1-44	125	SF	6	10+ years	
	Doors - Wood Doors inclu hw	116 # 1-44	1	EA	6	10+ years	
	Floor - Tile	116 # 1-44	125	SF	6	10+ years	
	Lighting - Lay-in	116 # 1-44	2	EA	7	6-10 years	
	Power Distribution	116 # 1-44	3	EA	7	6-10 years	

Campus Name: New Sullivan Page : 7 of 35 Assessment Date: 04/13/2022



Catego	Category : Room			uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	116 # 1-44	410	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor Engineers Office	144	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor Engineers Office	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor Engineers Office	8	SF	7	10+ years	
	Floor - Tile	1st Floor Engineers Office	144	SF	6	10+ years	
	Lighting - Lay-in	1st Floor Engineers Office	2	EA	7	10+ years	
	Power Distribution	1st Floor Engineers Office	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Engineers Office	454	SF	6	10+ years	
	Ceiling - Lay-in	214 Office # 2-28	215	SF	6	10+ years	
	Doors - Wood Doors inclu hw	214 Office # 2-28	1	EA	6	10+ years	
	Floor - Tile	214 Office # 2-28	215	SF	6	10+ years	
	Lighting - Lay-in	214 Office # 2-28	6	EA	7	6-10 years	
	Power Distribution	214 Office # 2-28	10	EA	7	6-10 years	
	Storage/ Closet	214 Office # 2-28	180	SF	7	10+ years	
	Walls - Concrete Block	214 Office # 2-28	94	SF	6	10+ years	
	Walls - Plaster/Drywall	214 Office # 2-28	557	SF	6	10+ years	
	Work SInk	214 Office # 2-28	1	EA	7	10+ years	
	Ceiling - Exposed	317 Office #3-26	147	SF	7	10+ years	
	Doors - Wood Doors inclu hw	317 Office #3-26	1	EA	6	10+ years	
	Floor - Tile	317 Office #3-26	147	SF	6	10+ years	
	Lighting - Pendent/Surface	317 Office #3-26	3	EA	7	6-10 years	
	Walls - Concrete Block	317 Office #3-26	225	SF	6	10+ years	
	Walls - Plaster/Drywall	317 Office #3-26	327	SF	6	10+ years	
	Ceiling - Lay-in	Kitchen office	63	SF	6	10+ years	
	Ceiling - Lay-in	Kitchen office	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	Kitchen office	16	SF	6	10+ years	3
	Doors - Steel Doors incl hw	Kitchen office	1	ĒΑ	6	10+ years	
	Doors - Transom Window	Kitchen office	8	SF	7	10+ years	
	Floor - Tile	Kitchen office	71	SF	6	10+ years	
	Lighting - Lay-in	Kitchen office	1	ĒΑ	7	6-10 years	
	Power Distribution	Kitchen office	4	ΕA	7	6-10 years	
	Walls - Concrete Block	Kitchen office	344	SF	6	10+ years	
	Ceiling - Lay-in	Office 117 in room 107	83	SF	6	10+ years	
	Ceiling - Lay-in	Office 117 in room 107	8	SF	4	0-1 year	Missing
	Doors - Wood Doors inclu hw	Office 117 in room 107	1	ĒΑ	6	10+ years	9
	Floor - Tile	Office 117 in room 107	91	SF	6	10+ years	
	Lighting - Lay-in	Office 117 in room 107	1	ĒΑ	7	10+ years	
	Power Distribution	Office 117 in room 107	4	EA	7	10+ years	
	Walls - Concrete Block	Office 117 in room 107	141	SF	6	10+ years	
	Walls - Plaster/Drywall	Office 117 in room 107	237	SF	6	10+ years	
	Ceiling - Lay-in	Practice room 2 In room 107	61	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice room 2 In room 107	1	EA	6	10+ years	
	Floor - Tile	Practice room 2 In room 107	61	SF	6	10+ years	
	Lighting - Lay-in	Practice room 2 In room 107	1	EA	7	10+ years	
	gg,	. 100000 1001112 111100111 101		_, .	•	10. 300.0	



Catego	Category : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Power Distribution	Practice room 2 In room 107	4	EA	7	10+ years		
	Walls - Plaster/Drywall	Practice room 2 In room 107	122	SF	6	10+ years		
	Ceiling - Lay-in	Practice room 3. In room 107	61	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Practice room 3. In room 107	1	EA	6	10+ years		
	Floor - Tile	Practice room 3. In room 107	61	SF	6	10+ years		
	Lighting - Lay-in	Practice room 3. In room 107	1	EA	7	10+ years		
	Power Distribution	Practice room 3. In room 107	4	EA	7	10+ years		
	Walls - Plaster/Drywall	Practice room 3. In room 107	122	SF	6	10+ years		
	Ceiling - Lay-in	Practice room 4 in room 107	64	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Practice room 4 in room 107	1	EA	6	10+ years		
	Floor - Tile	Practice room 4 in room 107	64	SF	6	10+ years		
	Lighting - Lay-in	Practice room 4 in room 107	1	EA	7	10+ years		
	Power Distribution	Practice room 4 in room 107	4	EA	7	10+ years		
	Walls - Concrete Block	Practice room 4 in room 107	113	SF	6	10+ years		
	Walls - Plaster/Drywall	Practice room 4 in room 107	212	SF	6	10+ years		
	Ceiling - Lay-in	Practice room 6 in room 107	76	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Practice room 6 in room 107	1	EA	6	10+ years		
	Floor - Tile	Practice room 6 in room 107	76	SF	6	10+ years		
	Lighting - Lay-in	Practice room 6 in room 107	1	EA	7	10+ years		
	Power Distribution	Practice room 6 in room 107	4	EA	7	10+ years		
	Walls - Concrete Block	Practice room 6 in room 107	360	SF	6	10+ years		
	Ceiling - Lay-in	Rm101 Principal's Office	292	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Rm101 Principal's Office	1	EA	6	10+ years		
	Floor - Carpet	Rm101 Principal's Office	292	SF	6	6-10 years		
	Lighting - Lay-in	Rm101 Principal's Office	4	EA	7	10+ years		
	Power Distribution	Rm101 Principal's Office	12	EA	7	10+ years		
	Walls - Concrete Block	Rm101 Principal's Office	84	SF	6	10+ years		
	Walls - Plaster/Drywall	Rm101 Principal's Office	536	SF	6	10+ years		
	Ceiling - Lay-in	Rm102 Dean of students	148	SF	6	10+ years		
	Ceiling - Lay-in	Rm102 Dean of students	8	SF	4	0-1 year	Water damage.	
	Doors - Wood Doors inclu hw	Rm102 Dean of students	1	EA	6	10+ years	G	
	Floor - Carpet	Rm102 Dean of students	156	SF	6	6-10 years		
	Lighting - Lay-in	Rm102 Dean of students	2	EA	7	10+ years		
	Power Distribution	Rm102 Dean of students	12	EA	7	10+ years		
	Walls - Concrete Block	Rm102 Dean of students	86	SF	6	10+ years		
	Walls - Plaster/Drywall	Rm102 Dean of students	336	SF	6	10+ years		
	Ceiling - Lay-in	Rm103 Asst Principal	152	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Rm103 Asst Principal	1	ĒA	6	10+ years		
	Floor - Carpet	Rm103 Asst Principal	152	SF	6	6-10 years		
	Lighting - Lay-in	Rm103 Asst Principal	2	EA	7	10+ years		
	Power Distribution	Rm103 Asst Principal	12	EA	7	6-10 years		
	Walls - Concrete Block	Rm103 Asst Principal	87	SF	6	10+ years		
	Walls - Plaster/Drywall	Rm103 Asst Principal	339	SF	6	10+ years		
	Ceiling - Lay-in	Rm105 main office	680	SF	6	10+ years	Quantity changed to match current	
	3 -7		230		-	- ,		



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations
	Doors - Side-lite	Rm105 main office	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm105 main office	2	EA	6	10+ years	Quantity changed to match current
						Ž	observations
	Floor - Carpet	Rm105 main office	546	SF	6	6-10 years	Quantity changed to match current
	•					•	observations
	Floor - Terrazzo	Rm105 main office	134	SF	7	10+ years	
	Lighting - Lay-in	Rm105 main office	10	EA	7	10+ years	Quantity changed to match current
	5 5 7					,	observations
	Power Distribution	Rm105 main office	14	EA	7	10+ years	
	Storage/ Closet	Rm105 main office	12	SF	7	10+ years	
	Walls - Concrete Block	Rm105 main office	380	SF	6	10+ years	Quantity changed to match current
				-	•	, , , , , , , , , , , , , , , , , , , ,	observations
	Walls - Plaster/Drywall	Rm105 main office	450	SF	6	10+ years	Quantity changed to match current
	Trane Tractor, 21, Trans	· ····································	.00	٠.	•	.o. youro	observations
	Walls - Structural Glazed Tile	Rm105 main office	586	SF	6	10+ years	
	Ceiling - Lay-in	Rm110	131	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm110	1	EA	6	10+ years	
	Floor - Tile	Rm110	131	SF	6	10+ years	
	Lighting - Lay-in	Rm110	2	EA	7	10+ years	
	Power Distribution	Rm110	12	EΑ	7	10+ years	
	Walls - Concrete Block	Rm110	135	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm110	331	SF	6	10+ years	
	Work Sink	Rm110	1	EA	7	10+ years	
	Work on ik	Tallitio	ı	L/\	,	101 years	
Gvmnasi	ia						
	Bleacher Seating	1st Floor	82	EA	6	10+ years	
	Ceiling - Exposed	1st Floor	4,153	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	4,153	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	16	EA	6	6-10 years	
	Scoreboards	1st Floor	1	EΑ	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	180	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	7,762	SF	6	10+ years	
	Walls - Concrete block	13(1100)	7,702	Oi	O	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor	1,612	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	ĒΑ	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,612	SF	7	10+ years	Changed to match current
			.,012	٠.	•	,	observations
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	1	EΑ	7	6-10 years	
					•	J . J J J J J J J J J J J J J J J J J J	
	Storage/ Closet	1st Floor	130	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	4,032	SF	6	10+ years	
Library							
<u></u>	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,600	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Carpet	2nd Floor	3,600	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	46	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,100	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,200	SF	6	10+ years	
Lunch 8	Multipurpose Room						
LUIICII X	Ceiling - Exposed	1st Floor	3,155	SF	7	10+ years	
	Ceiling - Exposed Ceiling - Lay-in	1st Floor	957	SF	6	10+ years	
		1st Floor					Quantity shanged to match surrent
	Doors - Wood Doors inclu hw	1St Floor	4	EA	6	10+ years	Quantity changed to match current observations
	Floor - Tile/Sheet	1st Floor	4,106	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	6	SF	4	0-1 year	Chipped
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	6-10 years	
	Serving Line	1st Floor	54	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	7,166	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,237	SF	6	10+ years	
MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Finishes	2nd Floor	123	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	ĒΑ	7	10+ years	Ductless split system.
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	12	SF	7	10+ years	
	Janitor's Closet	1st Floor	15	SF	7	10+ years	
	Janitor's Closet	1st Floor	29	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years	Quantity changed to match current observations
	Mechanical/ Service Rooms	1st Floor	271	SF	7	10+ years	observations
	Mechanical/ Service Rooms	1st Floor	406	SF	5	10+ years	
	Storage Room	1st Floor	194	SF	7	10+ years	
	Storage Room	1st Floor	140	SF	7	10+ years	
	Storage Room	1st Floor	451	SF	7	10+ years	
	Vaults	1st Floor		SF SF	7 7	,	
	Boiler Room	2nd Floor	248 2,019	SF SF	7	10+ years 10+ years	



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	2nd Floor	12	SF	7	10+ years	
	Janitor's Closet	2nd Floor	12	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	85	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	1,850	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	69	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	28	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	28	SF	7	10+ years	
	Storage Room	2nd Floor	1,121	SF	7	10+ years	
	Janitor's Closet	3rd Floor	11	SF	7	10+ years	
	Janitor's Closet	3rd Floor	11	SF	7	10+ years	
	Storage Room	3rd Floor	82	SF	7	10+ years	
Restroor	n						
	Accessories	1st Fl Boys North	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl Boys North	194	SF	6	10+ years	
	Floor - Terrazzo	1st FI Boys North	194	SF	7	10+ years	
	Floor Drain	1st FI Boys North	2	EA	7	10+ years	
	Lavatory	1st FI Boys North	3	EA	7	10+ years	
	Lighting - Lay-in	1st Fl Boys North	4	EΑ	7	10+ years	
	Partitions	1st Fl Boys North	2	EA	7	10+ years	
	Urinals	1st Fl Boys North	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Fl Boys North	696	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl Boys North	810	SF	6	10+ years	
	Water Closet	1st Fl Boys North	2	EA	7	10+ years	
	Accessories	1st Fl Boys South	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl Boys South	194	SF	6	10+ years	
	Floor - Terrazzo	1st Fl Boys South	194	SF	5	10+ years	Cracking
	Floor Drain	1st Fl Boys South	2	EA	7	10+ years	Cracking
	Lavatory	1st Fl Boys South	3	EA	7		
			3 4	EA	7	10+ years	
	Lighting - Lay-in	1st Fl Boys South	-			10+ years	
	Partitions	1st Fl Boys South	2	EΑ	7	10+ years	
	Urinals	1st Fl Boys South	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Fl Boys South	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl Boys South	810	SF	6	10+ years	
	Water Closet	1st Fl Boys South	2	EA	6	10+ years	
	Accessories	1st Fl Girls North	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl Girls North	192	SF	6	10+ years	
	Floor - Terrazzo	1st Fl Girls North	192	SF	7	10+ years	
	Floor Drain	1st Fl Girls North	2	EA	7	10+ years	
	Lavatory	1st Fl Girls North	3	EA	7	10+ years	
	Lighting - Lay-in	1st Fl Girls North	4	EA	7	10+ years	
	Partitions	1st Fl Girls North	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Fl Girls North	789	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl Girls North	810	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Fl Girls North	4	EA	6	10+ years	
	Accessories	1st Fl Girls South	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl Girls South	192	SF	6	10+ years	
	Floor - Terrazzo	1st Fl Girls South	182	SF	6	10+ years	
	Floor - Terrazzo	1st Fl Girls South	10	SF	4	0-1 year	Cracking
	Floor Drain	1st Fl Girls South	2	EA	7	10+ years	
	Lavatory	1st Fl Girls South	3	EΑ	7	10+ years	
	Lighting - Lay-in	1st Fl Girls South	4	EA	7	10+ years	
	Partitions	1st Fl Girls South	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Fl Girls South	516	SF	7	10+ years	
	Water Closet	1st Fl Girls South	4	EA	7	10+ years	
	Accessories	1st Fl Men's North	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl Men's North	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl Men's North	1	EA	6	10+ years	
	Floor - Terrazzo	1st Fl Men's North	60	SF	6	10+ years	
	Floor Drain	1st Fl Men's North	1	EA	7	10+ years	
	Lavatory	1st Fl Men's North	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fl Men's North	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl Men's North	256	SF	6	10+ years	
	Water Closet	1st Fl Men's North	1	EA	6	10+ years	
	Accessories	1st Fl Room 119 Restroom	33	SF	7	6-10 years	
	Ceiling - Lay-in	1st Fl Room 119 Restroom	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl Room 119 Restroom	1	EΑ	6	10+ years	
	Floor - Tile	1st Fl Room 119 Restroom	33	SF	6	10+ years	
	Floor Drain	1st Fl Room 119 Restroom	1	EA	7	10+ years	
	Lavatory	1st Fl Room 119 Restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fl Room 119 Restroom	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Fl Room 119 Restroom	206	SF	6	10+ years	
	Water Closet	1st Fl Room 119 Restroom	1	ĒΑ	6	10+ years	
	Accessories	1st Fl South	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl South	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl South	1	ĒA	6	10+ years	
	Floor - Terrazzo	1st Fl South	52	SF	7	10+ years	
	Floor Drain	1st Fl South	1	ĒΑ	7	10+ years	
	Lavatory	1st Fl South	1	EΑ	6	10+ years	
	Lighting - Lay-in	1st Fl South	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl South	271	SF	6	10+ years	
	Water Closet	1st Fl South	1	EA	6	10+ years	
	Accessories	1st Fl Women's North	74	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI Women's North	74	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl Women's North	1	EA	6	10+ years	
	Floor - Terrazzo	1st Fl Women's North	74	SF	7	10+ years	
	Floor Drain	1st FI Women's North	1	EA	7	10+ years	
	Lavatory	1st FI Women's North	1	EA	7	10+ years	
	Lavatory	Total Women's Note:	•	_/ \	,	ioi youis	



Catego	ry : Room		В	uilding	: Main		. 5 .
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Fl Women's North	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Fl Women's North	6	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl Women's North	324	SF	6	10+ years	
	Water Closet	1st Fl Women's North	1	EA	7	10+ years	
	Accessories	1st FI inside Main Office	37	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI inside Main Office	37	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI inside Main Office	1	EA	6	10+ years	
	Floor - Tile	1st FI inside Main Office	37	SF	6	10+ years	
	Floor Drain	1st FI inside Main Office	1	EA	7	10+ years	
	Lavatory	1st FI inside Main Office	1	EA	7	10+ years	
	Lighting - Lay-in	1st FI inside Main Office	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st FI inside Main Office	219	SF	6	10+ years	
	Water Closet	1st FI inside Main Office	1	ĒΑ	7	10+ years	
	Accessories	1st FI, Rm 114 restroom	33	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI, Rm 114 restroom	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI, Rm 114 restroom	1	EA	6	10+ years	
	Floor - Tile	1st FI, Rm 114 restroom	33	SF	6	10+ years	
	Floor Drain	1st Fl, Rm 114 restroom	1	EA	7	10+ years	
	Lavatory	1st FI, Rm 114 restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fl, Rm 114 restroom	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st FI, Rm 114 restroom	206	SF	6	10+ years	
	Water Closet	1st Fl, Rm 114 restroom	1	EA	6	10+ years	
	Accessories	1st FI, Rm 117 restroom	33	SF	7	6-10 years	
	Ceiling - Lay-in	1st Fl, Rm 117 restroom	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl, Rm 117 restroom	1	EA	6	10+ years	
	Floor - Tile	1st FI, Rm 117 restroom	33	SF	7	10+ years	
	Floor Drain	1st FI, Rm 117 restroom	33 1	EA	7	10+ years	
		•	1	EA	6		
	Lavatory	1st Fl, Rm 117 restroom	· ·	EA	7	10+ years	
	Lighting - Lay-in	1st Fl, Rm 117 restroom	1	SF		6-10 years	
	Walls - Tile Ceramic/ Porcelain Water Closet	1st FI, Rm 117 restroom	206	Sr EA	6	10+ years	
		1st Fl, Rm 117 restroom	1 33	SF	6 7	10+ years	
	Accessories	1st Fl, Rm 118 restroom		SF SF		6-10 years	
	Ceiling - Lay-in	1st Fl, Rm 118 restroom	33		6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl, Rm 118 restroom	1	EA SF	6	10+ years	
	Floor - Tile	1st Fl, Rm 118 restroom	33		6	10+ years	
	Floor Drain	1st Fl, Rm 118 restroom	1	EΑ	7	10+ years	
	Lighting - Lay-in	1st FI, Rm 118 restroom	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Fl, Rm 118 restroom	206	SF	6	10+ years	
	Water Closet	1st Fl, Rm 118 restroom	1	EA	6	10+ years	
	Accessories	1st Fl, Rm 120 restroom	33	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI, Rm 120 restroom	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI, Rm 120 restroom	1	EA	6	10+ years	
	Floor - Tile	1st FI, Rm 120 restroom	33	SF	6	10+ years	
	Floor Drain	1st Fl, Rm 120 restroom	1	EA	7	10+ years	

Campus Name: New Sullivan Page : 14 of 35 Assessment Date: 04/13/2022



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st FI, Rm 120 restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st FI, Rm 120 restroom	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl, Rm 120 restroom	206	SF	6	10+ years	
	Water Closet	1st FI, Rm 120 restroom	1	EA	6	10+ years	
	Accessories	2nd Fl Boys South	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Fl Boys South	194	SF	6	10+ years	
	Floor - Terrazzo	2nd Fl Boys South	194	SF	7	10+ years	
	Floor Drain	2nd Fl Boys South	2	EA	7	10+ years	
	Lavatory	2nd Fl Boys South	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Fl Boys South	4	EΑ	7	6-10 years	
	Partitions	2nd Fl Boys South	2	EA	7	10+ years	
	Urinals	2nd Fl Boys South	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Fl Boys South	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Fl Boys South	810	SF	6	10+ years	
	Water Closet	2nd Fl Boys South	2	ĒΑ	7	10+ years	
	Accessories	2nd Fl Girls North	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Fl Girls North	192	SF	6	10+ years	
	Floor - Terrazzo	2nd Fl Girls North	192	SF	7	10+ years	
	Floor Drain	2nd Fl Girls North	2	ĒΑ	7	10+ years	
	Lavatory	2nd Fl Girls North	3	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Fl Girls North	4	EA	7	6-10 years	
	Partitions	2nd Fl Girls North	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Fl Girls North	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Fl Girls North	810	SF	6	10+ years	
	Water Closet	2nd Fl Girls North	4	ĒΑ	7	10+ years	
	Accessories	2nd Fl North	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Fl North	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Fl North	1	ĒΑ	6	10+ years	
	Floor - Terrazzo	2nd Fl North	60	SF	7	10+ years	
	Floor Drain	2nd Fl North	1	ĒΑ	7	10+ years	
	Lavatory	2nd Fl North	1	ΕA	7	10+ years	
	Lighting - Lay-in	2nd Fl North	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Fl North	256	SF	6	10+ years	
	Water Closet	2nd Fl North	1	ĒΑ	6	10+ years	
	Accessories	2nd Fl South	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Fl South	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Fl South	1	EΑ	6	10+ years	
	Floor - Terrazzo	2nd Fl South	52	SF	7	10+ years	
	Floor Drain	2nd Fl South	1	EA	7	10+ years	
	Lavatory	2nd Fl South	1	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Fl South	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Fl South	271	SF	6	10+ years	
	Water Closet	2nd Fl South	1	EA	7	10+ years	
	Accessories	2nd Fir boys south 2	192	SF	7	6-10 years	
	. 1000001100	2/10 / 11 20/0 000012	102	0.	•	3 10 ,00.0	



Catego	ry : Room		В	uilding	: Main		. 5
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Flr boys south 2	192	SF	6	10+ years	
	Floor - Terrazzo	2nd Flr boys south 2	192	SF	7	10+ years	
	Floor Drain	2nd Flr boys south 2	2	EA	7	10+ years	
	Lavatory	2nd Flr boys south 2	3	EA	7	10+ years	
	Lighting - Lay-in	2nd FIr boys south 2	4	EA	7	6-10 years	
	Partitions	2nd Flr boys south 2	2	EA	7	10+ years	
	Urinals	2nd FIr boys south 2	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd FIr boys south 2	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd FIr boys south 2	810	SF	6	10+ years	
	Water Closet	2nd Flr boys south 2	2	EA	7	10+ years	
	Accessories	2nd Flr girls North 2	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Flr girls North 2	194	SF	6	10+ years	
	Floor - Terrazzo	2nd Flr girls North 2	194	SF	7	10+ years	
	Floor Drain	2nd Flr girls North 2	2	EA	7	10+ years	
	Lavatory	2nd Flr girls North 2	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Flr girls North 2	4	EA	7	6-10 years	
	Partitions	2nd Flr girls North 2	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Flr girls North 2	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Flr girls North 2	810	SF	6	10+ years	
	Water Closet	2nd Flr girls North 2	4	EA	7	10+ years	
	Accessories	3rd Fl Boys North #3-16	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl Boys North #3-16	194	SF	6	10+ years	
	Floor - Terrazzo	3rd Fl Boys North #3-16	194	SF	7	10+ years	
	Floor Drain	3rd Fl Boys North #3-16	2	EA	7	10+ years	
	Lavatory	3rd Fl Boys North #3-16	3	EA	6	10+ years	
	Lighting - Lay-in	3rd Fl Boys North #3-16	4	EA	7	6-10 years	
	Partitions	3rd Fl Boys North #3-16	2	EA	7	10+ years	
	Urinals	3rd Fl Boys North #3-16	2	EA	6	10+ years	
	Walls - Structural Glazed Tile	3rd Fl Boys North #3-16	516	SF	6	10+ years	
	Water Closet	3rd Fl Boys North #3-16	2	EA	6	10+ years	
	Accessories	3rd Fl Boys South #3-15	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl Boys South #3-15	194	SF	6	10+ years	
	Floor - Terrazzo	3rd Fl Boys South #3-15	194	SF	7	10+ years	
	Floor Drain	3rd Fl Boys South #3-15	2	ĒΑ	7	10+ years	
	Lavatory	3rd Fl Boys South #3-15	3	EA	6	10+ years	
	Lighting - Lay-in	3rd Fl Boys South #3-15	4	EA	7	6-10 years	
	Partitions	3rd Fl Boys South #3-15	2	EA	7	10+ years	
	Urinals	3rd Fl Boys South #3-15	2	EA	6	10+ years	
	Walls - Structural Glazed Tile	3rd Fl Boys South #3-15	516	SF	6	6-10 years	
	Water Closet	3rd Fl Boys South #3-15	2	ĒΑ	6	10+ years	
	Accessories	3rd Fl Girls North #3-02	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl Girls North #3-02	192	SF	6	10+ years	
	Floor - Terrazzo	3rd Fl Girls North #3-02	192	SF	7	10+ years	
	Floor Drain	3rd Fl Girls North #3-02	2	ĒΑ	7	10+ years	
			_			- ,	



Category: Room			В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	3rd FI Girls North #3-02	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Fl Girls North #3-02	4	EA	7	6-10 years	
	Partitions	3rd Fl Girls North #3-02	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Fl Girls North #3-02	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Fl Girls North #3-02	810	SF	6	10+ years	
	Water Closet	3rd Fl Girls North #3-02	4	EΑ	7	10+ years	
	Accessories	3rd Fl Girls South #3-01	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl Girls South #3-01	192	SF	6	10+ years	
	Floor - Terrazzo	3rd Fl Girls South #3-01	192	SF	7	10+ years	
	Floor Drain	3rd Fl Girls South #3-01	2	EΑ	7	10+ years	
	Lavatory	3rd Fl Girls South #3-01	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Fl Girls South #3-01	4	EA	7	6-10 years	
	Partitions	3rd Fl Girls South #3-01	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Fl Girls South #3-01	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Fl Girls South #3-01	810	SF	6	10+ years	
	Water Closet	3rd Fl Girls South #3-01	4	ĒΑ	7	10+ years	
	Accessories	3rd Fl North #3-18	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl North #3-18	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Fl North #3-18	1	EΑ	6	10+ years	
	Floor - Terrazzo	3rd Fl North #3-18	60	SF	7	10+ years	
	Floor Drain	3rd Fl North #3-18	1	EΑ	7	10+ years	
	Lavatory	3rd Fl North #3-18	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Fl North #3-18	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd Fl North #3-18	256	SF	6	10+ years	
	Water Closet	3rd Fl North #3-18	1	EΑ	7	10+ years	
	Accessories	3rd Fl South #3-04	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl South #3-04	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Fl South #3-04	1	EA	6	10+ years	
	Floor - Terrazzo	3rd FI South #3-04	52	SF	6	10+ years	
	Floor Drain	3rd Fl South #3-04	1	EA	7	10+ years	
	Lavatory	3rd FI South #3-04	1	EA	6	10+ years	
	Lighting - Lay-in	3rd Fl South #3-04	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd FI South #3-04	271	SF	6	10+ years	
	Water Closet	3rd FI South #3-04	1	EA	6	10+ years	
	Trailor Glocot	ora i i ocalii no c i	·	_, .	Ü	101 youro	
•go	ry : Classroom		В	uilding	: Main		
	W T	Lagadian	0	11614	D- 1	Recommend	0
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
sroo	m #107 (Band Room)						
	Casework	1st Floor	46	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	2,075	SF	6	10+ years	
	Doors - Side-lite	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	2,065	SF	6	10+ years	



Category : Classroom			В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Cracking
	Instrument Storage Casework	1st Floor	24	LF	6	10+ years	
	Lighting - Lay-in	1st Floor	34	EA	7	10+ years	
	Risers	1st Floor	16	LF	6	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	134	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	959	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	788	SF	6	10+ years	
lassroc	om #112 (Regular Classroom)						
	Casework	1st Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Side-lite Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	895	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7		
				LF		10+ years	
	Marker Board	1st Floor	24	SF	7	6-10 years	
	Storage/ Closet	1st Floor	6		7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	520	SF	6	10+ years	
lassroc	om #114 (Pre School)						
	Casework	1st Floor	60	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,052	SF	7	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,052	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	Quantity changed to match current
	Walls - Concrete Block	1st Floor	581	SF	6	10+ years	observations
	Walls - Plaster/Drywall	1st Floor	710	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
lassroc	om #115 (Kindergarten)						
	Casework	1st Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	895	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	ואמות בו שטמוט	1301 1001	24	LF	1	0-10 years	



Category : Classroom		В	uilding	Building : Main				
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage/ Closet	1st Floor	6	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	560	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	520	SF	6	10+ years		
lassroo	m #117 (Regular Classroom)							
	Casework	1st Floor	60	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	1,104	SF	7	10+ years		
	Doors - Side-lite	1st Floor	8	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	1,104	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	1,104	EA	7	•		
				LF		6-10 years		
	Marker Board	1st Floor	12		7	6-10 years	O	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	Quantity changed to match curren observations	
	Walls - Concrete Block	1st Floor	581	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	710	SF	6	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
lassroo	m #118 (Regular Classroom)							
	Casework	1st Floor	60	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	1,104	SF	7	10+ years		
	Doors - Side-lite	1st Floor	8	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	Quantity changed to match curren	
					-	-	observations	
	Floor - Tile	1st Floor	1,104	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	60	SF	7	10+ years	Quantity changed to match current observations	
	Walls - Concrete Block	1st Floor	581	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	710	SF	6	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years	Drinking fountain	
lassroo	m #119 (Kindergarten)							
	Casework	1st Floor	60	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	1,104	SF	6	10+ years		
	Doors - Side-lite	1st Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	Quantity changed to match curren	
						•	observations	
	Floor - Tile	1st Floor	1,104	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years		
	5 5 7	1st Floor	12	LF	7	6-10 years		



Catego	ry : Classroom		В	uilding	: Main		-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	72	SF	5	10+ years	Falling ceiling tiles
	Walls - Concrete Block	1st Floor	581	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	710	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	Drinking fountain
Classroo	om #120 (Regular Classroom)						
	Casework	1st Floor	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,080	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,080	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	EΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	71	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	936	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	355	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
	Casework Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Concrete Block Walls - Plaster/Drywall	1st Floor	43 873 8 1 873 12 24 6 539 520	LF SF SF EA SF EA LF SF SF SF	6 6 6 6 7 7 7 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	
Classroo	om #124 (Faculty Lounge)						
	Casework	1st Floor	80	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	875	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	875	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	459	SF	6	10+ years	
		1st Floor	472	SF	6	10+ years	
	Walls - Plaster/Drywall	151 [100]	417	O.	U	IOT VEGIS	



Category : Classroom			В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
-		Location	Quantity	OCIVI	Naiik	Replacement	Comments	
Classroo	m #133 (Regular Classroom)	=				10		
	Casework	1st Floor	58	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years		
	Doors - Side-lite	1st Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	895	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Storage/ Closet	1st Floor	107	SF	7	10+ years	Quantity changed to match current observations	
	Walls - Concrete Block	1st Floor	560	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	520	SF	6	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years	Quantity changed to match current observations	
							observations	
Classroo	m #201 (Regular Classroom)							
	Casework	2nd Floor	58	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	871	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	8	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	785	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	244	SF	6	10+ years		
Classroo	m #202 (Regular Classroom)							
	Casework	2nd Floor	58	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	915	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	915	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
				LF	7	-		
	Marker Board	2nd Floor	24	SF		6-10 years		
	Storage/ Closet	2nd Floor	6		7	10+ years		
	Walls - Concrete Block	2nd Floor	856	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	243	SF	6	10+ years		
Classroo	m #203 (Regular Classroom)							
	Casework	2nd Floor	58	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	915	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		



Catego	ry : Classroom		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	915	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	243	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	867	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Buckled tile
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	Buokiou ino
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	871	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	•	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
		2nd Floor 2nd Floor	6	SF		6-10 years	
	Storage/ Closet			SF SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	785		6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	244	SF	6	10+ years	
Classroo	om #205 (Office)						
	Casework	2nd Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	456	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	456	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	340	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	123	SF	6	10+ years	
Classroo	om #206 (Counseling Room)						
	Casework	2nd Floor	23	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	543	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	543	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	309	SF SF	, 6	10+ years 10+ years	
	walls - Concrete Block	∠πα πιοθί	309	or-	О	iu+ years	



Catego	ory : Classroom		В	uilding	: Main	300	1 6 Mackillaw Avenue, Gilleage, 12 00017
Julioge	i y i Giacol Com		_	anamg	· Wani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	518	SF	6	10+ years	
	·					•	
Classro	om #207 (Office)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	539	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	543	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	309	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	518	SF	6	10+ years	
Classro	om #208 (Regular Classroom)						
Ciassio	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	895	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	520	SF	6	10+ years	
Classro	om #209 (Regular Classroom)						
Classion	Casework	2nd Floor	56	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	871	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	550	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	482	SF	6	10+ years	
01	·					,	
_Classro	om #210 (Regular Classroom)						
	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	915	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	915	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	243	SF	6	10+ years	
Classroc	om #211 (Science Classroom)						
	Casework	2nd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,192	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6		
	Floor - Tile	2nd Floor		SF	6	10+ years	
			1,200		-	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	120	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	778	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	484	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroc	om #216 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,185	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,197	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	[′] 19	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	878	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	506	SF	6	10+ years	
Classroo	om #217 (Regular Classroom)						
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	456	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	456	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor 2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	24	LF	7 7	6-10 years	
	Storage/ Closet		24 6	SF	7	•	
	Sturage/ Cluser	2nd Floor	б	or −	1	10+ years	



Category : Classroom			В				
				_		Recommend	
	tem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Valls - Concrete Block	2nd Floor	530	SF	6	10+ years	
V	Valls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
Classroom :	#218 (Regular Classroom)						
C	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	456	SF	6	10+ years	
D	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
D	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
F	loor - Tile	2nd Floor	456	SF	6	10+ years	
L	ighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Valls - Concrete Block	2nd Floor	530	SF	6	10+ years	
	Valls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
:lassroom	#219 (Regular Classroom)						
	Casework	2nd Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	456	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	loor - Tile	2nd Floor	456	SF	6	10+ years	
	ighting - Lay-in	2nd Floor	10	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Valls - Concrete Block	2nd Floor	800	SF	6	10+ years	
	Valls - Plaster/Drywall	2nd Floor	270	SF	6	10+ years	
:lassroom	#301 (Regular Classroom)						
	Casework	3rd Floor	56	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	869	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	4	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	Trate: damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	loor - Tile	3rd Floor	873	SF	6	10+ years	
	ighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Valls - Concrete Block	3rd Floor	539	SF	6	10+ years	
	Valls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
lassroom :	#302 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
C	John S Lay III	010 1 1001	093	Oi.	J	ioi yeais	



Catego	ry : Classroom		В	uilding	: Main	333	TO Mackinaw AVENOE, Officago, 12 00017
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
_OIGOOI OI	Casework	3rd Floor	58	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	•	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
				SF	_	10+ years	
	Floor - Tile	3rd Floor	895		6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
_Classroo	om #304 (Vacant)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	890	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	890	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	845	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	243	SF	6	10+ years	
Classroo	om #305 (Store Room)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	3rd Floor	0	SF EA	6	-	
			· · · · · · · · · · · · · · · · · · ·		_	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		1 o Mackinaw Avenue, Officago, 12 00017
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classroo	om #306 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
	·					•	
_Classroo	om #307 (Regular Classroom)	3rd Floor				40	
	Casework		58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
_Classroo	om #308 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	865	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classroo	om #309 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	915	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
			·		-	,	



	: Main		
		Recommend	
Group Item - Type Location Quantity UOM	Rank	Replacement	Comments
Floor - Tile 3rd Floor 915 SF	6	10+ years	
Lighting - Lay-in 3rd Floor 12 EA	7	6-10 years	
Marker Board 3rd Floor 24 LF	7	6-10 years	
Storage/ Closet 3rd Floor 6 SF	7	10+ years	
Walls - Concrete Block 3rd Floor 856 SF	6	10+ years	
Walls - Plaster/Drywall 3rd Floor 243 SF	6	10+ years	
Classroom #310 (Regular Classroom)			
Casework 3rd Floor 58 LF	6	10+ years	
Ceiling - Lay-in 3rd Floor 895 SF	6	10+ years	
Doors - Side-lite 3rd Floor 8 SF	6	10+ years	
Doors - Wood Doors inclu hw 3rd Floor 1 EA	6	10+ years	
Floor - Tile 3rd Floor 895 SF	6	10+ years	
Lighting - Lay-in 3rd Floor 12 EA	7	6-10 years	
Marker Board 3rd Floor 24 LF	7	6-10 years	
Storage/ Closet 3rd Floor 6 SF	7	10+ years	
Walls - Concrete Block 3rd Floor 560 SF	6	10+ years	
Walls - Plaster/Drywall 3rd Floor 520 SF	6	10+ years	
Classroom #311 (Regular Classroom)			
Casework 3rd Floor 58 LF	6	10+ years	
Ceiling - Lay-in 3rd Floor 895 SF	6	10+ years	
Doors - Side-lite 3rd Floor 8 SF	6	10+ years	
Doors - Wood Doors inclu hw 3rd Floor 1 EA	6	10+ years	
Floor - Tile 3rd Floor 895 SF	6	10+ years	
Lighting - Lay-in 3rd Floor 12 EA	7	6-10 years	
Marker Board 3rd Floor 24 LF	7	6-10 years	
Storage/ Closet 3rd Floor 6 SF	7	10+ years	
Walls - Concrete Block 3rd Floor 560 SF	6	10+ years	
Walls - Plaster/Drywall 3rd Floor 520 SF	6	10+ years	
Classroom #312 (Art Room)			
Casework 3rd Floor 36 LF	6	10+ years	
Ceiling - Lay-in 3rd Floor 1,143 SF	6	10+ years	
Ceiling - Lay-in 3rd Floor 20 SF	4	0-1 year	Water damage.
Doors - Side-lite 3rd Floor 8 SF	6	10+ years	
Doors - Wood Doors inclu hw 3rd Floor 1 EA	6	10+ years	
Floor - Tile 3rd Floor 1,163 SF	6	10+ years	
Lighting - Lay-in 3rd Floor 16 EA	7	6-10 years	
Marker Board 3rd Floor 24 LF	7	6-10 years	
Storage/ Closet 3rd Floor 122 SF	7	10+ years	
Walls - Concrete Block 3rd Floor 778 SF	6	10+ years	
Walls - Plaster/Drywall 3rd Floor 484 SF	6	10+ years	
valie i laston brywaii ola i looi 404 Ol	U	101 yours	



Calegor	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	3rd Floor	2	EA	7	10+ years	
Classroo	m #313 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	1	SF	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classroo	m #314 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Olasaus a	m #245 (Basilar Classica)						
Classioo	m #315 (Regular Classroom) Casework	3rd Floor	50	LF		40	
		3rd Floor 3rd Floor	58	SF	6	10+ years	
	Ceiling - Lay-in		890		6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	890	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF 0F	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classroo	m #316 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	907	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	Trator damage
				OI.	U	IVI VEGIO	



Catego	ry : Classroom		В	uilding	: Main		1 S Mackinaw Avenue, Chicago, it 60617
Juligo	.y. Gladorodiii			anamg	· Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	ΕA	6	10+ years	
	Floor - Tile	3rd Floor	915	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	243	SF	6	10+ years	
Classroo	om #918 (Kindergarten)						
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	745	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	743	SF	6	10+ years	
	Floor - Tile	1st Floor	2	SF	4	0-1 year	Chipped
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	Спіррец
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	576	SF	6	10+ years	
		1st Floor	514	SF	6	•	
	Walls - Plaster/Drywall	1St Flooi	314	SF	b	10+ years	
Catego	ry : Interior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Camidan			-			•	
Corridor							
_Corridor		1st Floor	7 840	SF	6	10+ vears	
Corridor	Ceiling - Lay-in	1st Floor	7,840 28	SF SF	6	10+ years	
Corridor	Ceiling - Lay-in Doors - Side-lite	1st Floor	28	SF	6	10+ years	
Corridor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw	1st Floor 1st Floor	28 6	SF EA	6 6	10+ years 10+ years	
Corridor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front	1st Floor 1st Floor 1st Floor	28 6 4	SF EA EA	6 6 6	10+ years 10+ years 10+ years	
Comdor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window	1st Floor 1st Floor 1st Floor 1st Floor	28 6 4 18	SF EA EA SF	6 6 6	10+ years 10+ years 10+ years 10+ years	
Comdor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	28 6 4 18 4	SF EA EA SF EA	6 6 6 7	10+ years 10+ years 10+ years 10+ years 10+ years	Cracking throughout
Comoor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	28 6 4 18 4 7,340	SF EA EA SF EA SF	6 6 6 7 4	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year	Cracking throughout.
Comdor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet	1st Floor	28 6 4 18 4 7,340 500	SF EA SF EA SF SF	6 6 6 7 4 5	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years	Cracking throughout.
Comoor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in	1st Floor	28 6 4 18 4 7,340 500 190	SF EA SF EA SF SF EA	6 6 6 7 4 5 7	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years 10+ years	Cracking throughout.
Comoor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface	1st Floor	28 6 4 18 4 7,340 500 190 8	SF EA SF EA SF SF EA	6 6 6 7 4 5 7	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years 10+ years	Cracking throughout.
Comoor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Structural Glazed Tile	1st Floor	28 6 4 18 4 7,340 500 190 8 9,639	SF EA SF EA SF EA EA SF	6 6 6 7 4 5 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years	Cracking throughout.
Comoor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Structural Glazed Tile Ceiling - Lay-in	1st Floor	28 6 4 18 4 7,340 500 190 8 9,639 6,580	SF EA SF EA SF EA SF SF	6 6 6 7 4 5 7 7 6	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years	Cracking throughout.
Comain	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Structural Glazed Tile Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor 2nd Floor 2nd Floor	28 6 4 18 4 7,340 500 190 8 9,639 6,580 6	SF EA SF SF EA SF EA SF EA	6 6 6 7 4 5 7 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Cracking throughout.
Comain	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Structural Glazed Tile Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain	1st Floor 2nd Floor 2nd Floor 2nd Floor	28 6 4 18 4 7,340 500 190 8 9,639 6,580 6	SF EA SF EA SF EA SF EA EA	6 6 6 7 4 5 7 6 6 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years	Cracking throughout.
Comain	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Structural Glazed Tile Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Terrazzo	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	28 6 4 18 4 7,340 500 190 8 9,639 6,580 6 4 6,580	SF EA SF EA SF EA SF EA SF EA SF	6 6 6 7 4 5 7 6 6 6 7 6	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years	Cracking throughout.
Comoor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Structural Glazed Tile Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in	1st Floor 2nd Floor	28 6 4 18 4 7,340 500 190 8 9,639 6,580 6 4 6,580	SF EA SF EA SF EA SF EA SF EA	6 6 6 7 4 5 7 6 6 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years	Cracking throughout.
Comoor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Structural Glazed Tile Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Walls - Concrete Block	1st Floor 2st Floor 2nd Floor	28 6 4 18 4 7,340 500 190 8 9,639 6,580 6 4 6,580 170 7,654	SF EA SF EA SF EA SF EA SF EA SF	6 6 6 7 4 5 7 6 6 6 7 6	10+ years	Cracking throughout.
Comaor	Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Structural Glazed Tile Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in	1st Floor 2nd Floor	28 6 4 18 4 7,340 500 190 8 9,639 6,580 6 4 6,580	SF EA SF EA SF EA SF EA SF EA	6 6 6 7 4 5 7 6 6 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 0-1 year 10+ years	Cracking throughout. Water damage



Catego	egory : Interior		В	uilding	: Main	<u> </u>	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Doors - Steel Doors incl hw	3rd Floor	6	EΑ	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EΑ	7	10+ years	
	Floor - Terrazzo	3rd Floor	6,580	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	170	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	7,654	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EΑ	7	6-10 years	
	Security Cameras	Entire Building	16	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	Stair#1	314	SF	6	10+ years	
	Floor - Terrazzo	Stair#1	520	SF	7	10+ years	
	Handrails	Stair#1	112	LF	7	10+ years	
	Lighting - Lay-in	Stair#1	6	EΑ	6	6-10 years	
	Stairs - Terrazzo	Stair#1	448	LF	7	10+ years	
	Walls - Concrete Block	Stair#1	860	SF	6	10+ years	
	Ceiling - Lay-in	Stair#2	219	SF	6	10+ years	
	Floor - Terrazzo	Stair#2	420	SF	7	10+ years	
	Handrails	Stair#2	112	LF	7	10+ years	
	Lighting - Lay-in	Stair#2	6	EA	6	6-10 years	
	Stairs - Terrazzo	Stair#2	448	LF	7	10+ years	
	Walls - Structural Glazed Tile	Stair#2	760	SF	6	6-10 years	
	Ceiling - Lay-in	Stair#3	302	SF	6	10+ years	
	Ceiling - Lay-in	Stair#3	12	SF	4	0-1 year	Water damage
	Floor - Terrazzo	Stair#3	520	SF	7	10+ years	Ğ
	Handrails	Stair#3	112	LF	7	10+ years	
	Lighting - Lay-in	Stair#3	6	EA	6	6-10 years	
	Stairs - Terrazzo	Stair#3	448	LF	7	10+ years	
	Walls - Concrete Block	Stair#3	860	SF	6	10+ years	
Vertical (Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	Flooring cracking and buckling.





Category : Site **Building: Site**

outogo.	ry . Site		ь	unung	. Oile		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EΑ	6	10+ years	
	Givii, Brainago Gito Marinolo	Litting Gite	•		O	101 youro	
-anaina							
encing	Fencing - New Standard Ornamental	Entire Site	2.005	LF		40	
	Fencing - New Standard Ornamental	Entire Site	3,005	LF	6	10+ years	
andsca							
	Benches	Entire Site	19	EA	6	10+ years	
	Landscape - Grass	Entire Site	51,475	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	60	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	5,355	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	4	EA	6	6-10 years	
	Parkway trees	Entire Site	44	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	5,005	SF	6	10+ years	
	Trash Receptacles	Entire Site	1	EA	6	10+ years	
Parking I	ot						
	Concrete Curbs	East	1,158	LF	7	10+ years	
	Interior Plantings	East	1,100	LF	6	6-10 years	
	Lighting - Pole Mounted	East	5	EA	6	6-10 years	
	Surface - Asphalt	East	29,885	SF	4	0-1 year	Cracking and holes throughout.
	Trash Compactor	East	1	EA	6	10+ years	
	Trash Enclosure - Masonry	East	3,150	SF	7	10+ years	
	•					-	
Playgrou	ınd						
	Equipment - Pre K 3-5	SE Site	1	EA	6	10+ years	
	Equipment - School Age 5-12	SE Site	1	EA	6	10+ years	
	Surface - Poured Surface	SE Site	5,000	SF	6	10+ years	
			,			•	
Sidewalk	XS.						
	Sidewalks - Internal Walks	Entire Site	1,215	LF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	13,020	SF	6	6-10 years	
			, - = •		-	,	
Signage							
990	Flag Pole - Flag Pole	NW corner of site	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted	NW corner of site	1	EA	7	10+ years	
				EA	7		
	Marquee - Building Mounted Back Lighted	NW corner of site	1	HΑ	/	10+ years	



William K New Sullivan Elementary School

8331 S Mackinaw AVENUE, Chicago, IL 60617

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: New Sullivan Page : 33 of 35 Assessment Date: 04/13/2022



Classroom Summary

Band RoomBand Room1Computer LabComputer Lab2Counseling RoomRegular Classroom2	3rd Floor 1st Floor 2nd Floor	312 107	Number 3-24	(SF)	Area		Stop	Board
Art RoomArt Room3Band Room1Computer LabComputer Lab2Counseling RoomRegular Classroom2	1st Floor 2nd Floor		0.04			Area	Оюр	Dourd
Band Room1Computer LabComputer LabCounseling RoomRegular Classroom	1st Floor 2nd Floor		3-24	1,163	119	23	Υ	N
Computer LabComputer Lab2Counseling RoomRegular Classroom2	2nd Floor		1-13	2,075	360	26	Ý	N
Counseling Room Regular Classroom 2		216	2-31	1,197	119	23	Ý	Y
	2nd Floor	206	2-10	543	80	8	Ý	N
L COVIO CATE ROOM REQUIAL CIASSIOOM	1st Floor	123	1-79	873	120	12	Ý	N
	1st Floor	124	1-60	875	120	12	Ý	N
	1st Floor	119	1-53	1,104	120	12	Ý	N
	1st Floor	115	1-42	895	89	17	Ý	N
	1st Floor	918	1-18	745	120	8	Ý	N
	2nd Floor	205	2-10	456	80	8	Ý	N
	2nd Floor	207	2-12	543	80	8	Ý	N
	1st Floor	114	1-39	1,052	89	17	Ý	N
	1st Floor	133	1-33	895	89	17	Ý	N
	1st Floor	112	1-36	895	89	17	Ý	N
	1st Floor	117	1-47	1,104	89	17	Ý	N
	1st Floor	118	1-50	1,104	89	17	Ý	N
	1st Floor	120	1-56	1,080	120	8	Ý	N
	2nd Floor	201	2-06	871	120	12	Ý	N
	2nd Floor	202	2-07	915	120	12	Ý	N
	2nd Floor	203	2-08	915	120	12	Ý	N
	2nd Floor	204	2-09	871	120	12	Ý	N
	2nd Floor	208	2-13	895	120	12	Ý	N
O O	2nd Floor	209	2-14	871	120	12	Ý	N
0	2nd Floor	210	2-22	915	89	17	Ý	N
	2nd Floor	217	2-33	456	59	11	Ý	N
	2nd Floor	218	2-35	456	59	11	Ý	N
0	2nd Floor	219	2-37	456	59	11	Ý	N
	3rd Floor	301	3-07	873	89	17	Ý	N
	3rd Floor	302	3-08	895	89	17	Ý	N
	3rd Floor	303	3-09	895	89	17	Ý	Y
	3rd Floor	306	3-12	895	89	17	Ý	N
	3rd Floor	307	3-13	895	89	17	Ý	N
	3rd Floor	308	3-14	865	89	17	Ý	N
	3rd Floor	309	3-21	915	89	17	Ý	N
	3rd Floor	310	3-22	895	89	17	Ý	N
	3rd Floor	311	3-23	895	89	17	Ý	N
U	3rd Floor	313	3-27	895	89	17	Ý	N
	3rd Floor	314	3-28	895	89	17	Ý	N



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	315	3-29	890	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	316	3-30	915	89	17	Υ	N
Science Classroom	Science Classroom	2nd Floor	211	2-24	1,200	119	23	Υ	N
Store Room	Regular Classroom	3rd Floor	305	3-11	895	89	17	Y	N
Vacant	Regular Classroom	3rd Floor	304	3-10	890	89	17	Y	Υ

Campus Name: New Sullivan Page : 35 of 35 Assessment Date: 04/13/2022