

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1956	3	20,650
Leased-Branch	1956	2	22,322
Campus Total			42,972

n - Type						
ypc	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
rance Control - Audio and Video	1 - East	1	EA	7	10+ years	
erior Doors - Store Front	1 - East	4	EΑ	6	10+ years	
erior Doors - Transom Lite	1 - East	3	EA	6	10+ years	
ver Door Operator and Controls	1 - East	1	EΑ	7	6-10 years	Not previously assessed
erior Doors - Exterior Steel Door	2 - SW	2	EA	6	10+ years	
ndation - Concrete	Entire Building	355	LF	7	10+ vears	
erstructure - Steel	Entire Building	19,861	SF	7	10+ years	
erior Lighting - Wall Mounted	East Facade	6	EA	6	10+ vears	
erior Lighting - Wall Mounted	East Façade	2	EA	4	0-1 year	Does not work, damaged.
ess Ladder - Metal	Entire Building	1	EA	7	10+ years	
mney - Brick Chimney- Concrete/ Mortar		40	LF	6	10+ years	
er	3				,	
ing - Metal	Entire Building	450	LF	6	10+ years	
		180	LF	6	10+ years	
of - Modified Bitumen		7.113	SF	6	,	
of Hatch - Metal		1	ĒΑ	7	•	Not previously assessed
e e e e e e e e e e e e e e e e e e e	rior Doors - Exterior Steel Door Indation - Concrete Perstructure - Steel Prior Lighting - Wall Mounted Prior Lighting - Wall Mounted Pess Ladder - Metal Penney - Brick Chimney- Concrete/ Mortar Penney - Metal Penney - Metal Penney - Interior Downspouts Penney - Modified Bitumen	rior Doors - Exterior Steel Door 2 - SW Indation - Concrete Entire Building Entire Building Prior Lighting - Wall Mounted East Façade Fior Lighting - Wall Mounted East Façade Pess Ladder - Metal Entire Building Entire B	rior Doors - Exterior Steel Door 2 - SW 2 Indation - Concrete Entire Building 355 Indation - Concrete Entire Building 19,861 Indation - Concrete Entire Building 19,861 Indicate From From Parish From From Parish From Par	rior Doors - Exterior Steel Door 2 - SW 2 EA Indiation - Concrete Entire Building 355 LF Perstructure - Steel Entire Building 19,861 SF Prior Lighting - Wall Mounted East Façade 6 EA Prior Lighting - Wall Mounted East Façade 2 EA Personal Entire Building 1 EA Personal Entire Building 1 EA Personal Entire Building 40 LF Personal Entire Building 450 LF Personal Entire Building 180 LF Personal Entire Building 1	rior Doors - Exterior Steel Door 2 - SW 2 EA 6 Indation - Concrete Entire Building 355 LF 7 Indexerstructure - Steel Entire Building 19,861 SF 7 Indication - Concrete Entire Building 19,861 SF 6 Indication - Concrete Entire Building 19,861 SF 7 Indication - Concrete Entire Building 180 LF 6 Indication - Concrete Entire Building 1	rior Doors - Exterior Steel Door 2 - SW 2 EA 6 10+ years Indation - Concrete Entire Building 19,861 SF 7 10+ years Perstructure - Steel Entire Building 19,861 SF 7 10+ years Prior Lighting - Wall Mounted East Façade 6 EA 6 10+ years Prior Lighting - Wall Mounted East Façade 2 EA 4 0-1 years Pers Ladder - Metal Entire Building 1 EA 7 10+ years Pers Ladder - Metal Entire Building 1 EN 6 10+ years Pers Ladder - Metal Entire Building 10+ years

Page: 1 of 30





Category : Exterior

4946 S Paulina STREET, Chicago, IL 60609

	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Entire Building	7,113	SF	7	10+ years	
Nalls							
	Exterior Walls - Brick	Entire Building	4,655	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	500	SF	5	10+ years	Deteriorating mortar
	Exterior Walls - Precast Panel Wall	Entire Building	45	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	1,737	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	217	SF	5	10+ years	
Windows	3						
	Curtain wall - Glazed Double Pane	Entire Building	2,583	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	288	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	742	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	745	SF	6	10+ years	
	Lintels - Steel	Entire Building	726	LF	6	10+ years	
	Windows - Louver	Entire Building	50	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	48	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,724	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Commonto
meraer			4.00				
- Emerger	ncy System Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	Serves independent service. Serves
- merger	ncy System		•		6	·	
Emerger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs	Electrical Room Entire Building	1 2,203	EA SF		6-10 years	Serves independent service. Serves main building
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and	Electrical Room	1	EA	6	6-10 years 10+ years	Serves independent service. Serves
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs	Electrical Room Entire Building Entire Building Entire Building	1 2,203 1,200 5	EA SF SF EA	6 6 6	6-10 years 10+ years 10+ years 6-10 years	Serves independent service. Serves main building
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose	Electrical Room Entire Building Entire Building	1 2,203 1,200	EA SF SF	6 6	6-10 years 10+ years 10+ years	Serves independent service. Serves main building
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose Room	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building	1 2,203 1,200 5 2 2	EA SF SF EA EA	6 6 6 6	6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Serves independent service. Serves main building
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 2,203 1,200 5 2 2 2	EA SF SF EA EA	6 6 6 6	6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years	Serves independent service. Serves main building Building has EM panel
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose Room	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building	1 2,203 1,200 5 2 2	EA SF SF EA EA	6 6 6 6	6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Serves independent service. Serves main building
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym	Electrical Room Entire Building	1 2,203 1,200 5 2 2 2 4 5 1	EA SF SF EA EA EA EA	6 6 6 6 6 2 2	6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 0-1 year	Serves independent service. Serves main building Building has EM panel No battery pack, no AC generator No battery pack, previously not assessed
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom	Electrical Room Entire Building Entire Building	1 2,203 1,200 5 2 2 2 4 5 1	EA SF SF EA EA EA EA	6 6 6 6 6 2 2	6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 0-1 year	Serves independent service. Serves main building Building has EM panel No battery pack, no AC generator No battery pack, previously not assessed No battery pack
- merger	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym	Electrical Room Entire Building	1 2,203 1,200 5 2 2 2 4 5 1	EA SF SF EA EA EA EA	6 6 6 6 6 2 2	6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 0-1 year	Serves independent service. Serves main building Building has EM panel No battery pack, no AC generator No battery pack, previously not assessed

Building: Main

Recommend





Catego	ry : Electrical		В	uilding	: Main	·	946 3 Faulilla STREET, Chicago, IL 60609
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Main Se	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	Serves main building
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	6-10 years	Serves main building. Building has an ATS and an additional meter
	PA System	Entire Building	20,650	SF	5	6-10 years	Serves main building
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	10+ years	
Catego	ry : Fire Protection		B	uilding	· Main		
Jaiogo	.,			anding	· waiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves main building
	Fire Alarm Strobe Lights	Entire Building	20,650	SF	6	10+ years	Including horns
	Fire Alarm_System	Entire Building	20,650	SF	5	6-10 years	Serves main building
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	ling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 2 serves cafeteria in basement
	Air Intake	Mechanical Room	1	EA	5	10+ years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 8001-12000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-1 Serves Gym.
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 1000 - 2000 MBH	Boiler Room	1	EA	6	6-10 years	Only 1 boiler. No back-up boiler
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	1	EA	6	10+ years	
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	Manually fed
	Non Condensing- Scotch Marine- Hot Water Boiler - 1000 - 2000 MBH	Boiler Room	1	EA	6	6-10 years	Serves main building
	Water Fill System	Boiler Room	1	EA	6	10+ years	Manually fed

Page: 3 of 30

Peace & Education Coalition HS

Catego	ry : Mechanical		В		. 3,		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
	Fin Tube - Hot Water	Entire Building	420	LF	5	6-10 years	Mostly in gym area
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	5	6-10 years	Near entrance doors
Mechan	ical Plumbing						
IVICCHAIL	Hot Water Pump - Less than 10	Boiler Room	2	EA	5	6-10 years	Serve air handlers
	Hot Water Pump - Less than 10	Boiler Room	2	EA	5	6-10 years	Serve boiler
	Hot Water Pump - Less than 10	Boiler Room	_ 1	EA	5	6-10 years	Circulating pump
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	10+ years	1956 installation
Temper	ature Control						
_теттрен	Electric Controls	Entire Building	20,650	SF	5	6-10 years	No DDC system, no pneumatic
		g	_0,000	٠.	· ·	0 .0 ,00.0	system. Using a programmable
							controller, using individual dedicated
							temperature control. Univents have
							internal thermostats.
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	Serves boiler, controls for hot water
		_				-	temperature
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Serves 2 air handlers
Unit Ver	ntilation						
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	8	EA	4	1-2 years	Deteriorated, requiring frequent
	Heating Coils Only	_				•	repairs, more than 30 years old. With
							internal thermostats.
Ventilati	on						
_venillati	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	5	6-10 years	Through wall axial fans, larger fans
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EA	6	10+ years	Located above ceilings
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EA	5	6-10 years	Behind grill, above ceiling in
		_				•	restrooms, turns on when light in
							restroom is turned on
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	10+ years	
	CFM				_		
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	4	0-1 year	Noisy, worn, missing cover, serves restrooms.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	Older, functional, with a centrifugal
	,,		•		-	2 . 2 , 2 2 2	exhaust fan





Catego	ry : Plumbing		Building : Main					
_	<u> </u>			_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Hot Wat	er							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves main building, 2018 installation	
Piping								
	Domestic Piping-Hot Water Return Lines	Entire Building	20,650	SF	6	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	20,650	SF	6	10+ years		
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	20,650	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	20,650	SF	6	10+ years	1956 installation	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	20,650	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	20,650	SF	6	10+ years	Minor leaks are occasionally repaired	
	Sanitary Piping	Entire Building	20,650	SF	6	10+ years	1956 installation	
	Storm Piping	Entire Building	20,650	SF	6	10+ years	Jet water cleaned in 2020	
	Vent Piping	Entire Building	20,650	SF	6	10+ years		
Pumps								
	Pumps - Ejector-Duplex	Boiler Room	1	EA	5	6-10 years		

Category : Room Building : Main

						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
minist	rative Suites/Offices						
	Ceiling - Plaster/Drywall	1-B	218	SF	7	10+ years	
	Doors - Steel Doors incl hw	1-B	1	EA	7	10+ years	
	Floor - Tile	1-B	218	SF	7	10+ years	
	Lighting - Pendent/Surface	1-B	2	EA	7	10+ years	
	Power Distribution	1-B	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1-B	392	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1-C	110	SF	7	10+ years	
	Doors - Steel Doors incl hw	1-C	1	EΑ	7	10+ years	
	Floor - Tile	1-C	110	SF	7	10+ years	
	Lighting - Pendent/Surface	1-C	1	EA	7	10+ years	
	Power Distribution	1-C	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1-C	280	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1.5 Floor - Office 2-I	230	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1.5 Floor - Office 2-I	1	EA	7	10+ years	
	Floor - Tile	1.5 Floor - Office 2-I	230	SF	7	10+ years	
	Lighting - Pendent/Surface	1.5 Floor - Office 2-I	2	EA	7	10+ years	
	Power Distribution	1.5 Floor - Office 2-I	8	EA	7	10+ years	





tegory : Room			В	uilding	: Main		
			•			Recommend	
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1.5 Floor - Office 2-I	451	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Counselor's Office 2D	204	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Counselor's Office 2D	2	EA	7	10+ years	
	Floor - Tile	1st Floor - Counselor's Office 2D	184	SF	7	10+ years	Quantity and rank changed to mat current observation
	Floor - Tile	1st Floor - Counselor's Office 2D	20	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	1st Floor - Counselor's Office 2D	2	EΑ	7	10+ years	
	Power Distribution	1st Floor - Counselor's Office 2D	8	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor - Counselor's Office 2D	224	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Counselor's Office 2D	224	SF	7	10+ years	
	AC Unit	2-B 1st floor principals office	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	2-B 1st floor principals office	204	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2-B 1st floor principals office	1	EA	7	10+ years	
	Floor - Tile	2-B 1st floor principals office	204	SF	6	10+ years	
	Lighting - Pendent/Surface	2-B 1st floor principals office	4	EA	7	10+ years	
	Power Distribution	2-B 1st floor principals office	8	EA	7	10+ years	
	Walls - Masonry	2-B 1st floor principals office	224	SF	7	10+ years	
	Walls - Masority Walls - Plaster/Drywall	2-B 1st floor principals office	124	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Teacher's Lounge	228	SF	7	-	
	Doors - Wood Doors inclu hw	Basement - Teacher's Lounge	220	EA	7	10+ years	
	Floor - Tile		-	SF	7	10+ years	
		Basement - Teacher's Lounge	228			10+ years	
	Lighting - Pendent/Surface	Basement - Teacher's Lounge	2	EΑ	7	10+ years	
	Power Distribution	Basement - Teacher's Lounge	8	EA	7	10+ years	
	Storage/ Closet	Basement - Teacher's Lounge	170	SF	7	10+ years	
	Walls - Concrete Block	Basement - Teacher's Lounge	240	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - Teacher's Lounge	280	SF	7	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	361	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Tile	Main Office	361	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office	5	EA	7	10+ years	
	Power Distribution	Main Office	4	EA	7	10+ years	
	Storage/ Closet	Main Office	60	SF	7	10+ years	
	Walls - Masonry	Main Office	174	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office	240	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Next to principal 2C	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Next to principal 2C	1	ĒΑ	7	10+ years	
	Floor - Tile	Next to principal 2C	100	SF	7	10+ years	
	Lighting - Pendent/Surface	Next to principal 2C	1	EA	7	6-10 years	
	Power Distribution	Next to principal 2C	4	EA	7	10+ years	
	Walls - Concrete Block	Next to principal 2C	140	SF	7	10+ years	
	Walls - Masonry	Next to principal 2C	80	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		oro or admia orrect, orneago, it occor
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	3,050	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	7	10+ years	
	Floor - Wood	1st Floor	3,050	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	10+ years	
	Stage	1st Floor	774	SF	6	10+ years	
	Stage Curtain	1st Floor	7	EA	7	10+ years	
	Stage-Stairs - Asphalt	1st Floor	16	LF	7	10+ years	
	Walls - Masonry	1st Floor	990	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,970	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	Basement	400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	400	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	4	EA	7	10+ years	
	Serving Line	Basement	20	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement	800	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement	3,652	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	4	ĒΑ	7	10+ years	
	Floor - Tile	Basement	3,652	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	22	EA	7	10+ years	
	Serving Line	Basement	20	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement	5,360	SF	7	10+ years	
_MDF_ID	F						
<u>-</u>	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Finishes	1st Floor	258	SF	5	0-1 year	Damaged ceiling plaster and missing floor tiles throughout.
_Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	36	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years	
	Boiler Room	Basement	325	SF	7	10+ years	
	Janitor's Closet	Basement	42	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	700	SF	7	10+ years	
_Restroo	m						
	Accessories	1.5 Floor - Boys	225	SF	7	6-10 years	
	Ceiling - Lay-in	1.5 Floor - Boys	225	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 Floor - Boys	1	EA	7	10+ years	
	Floor - Terrazzo	1.5 Floor - Boys	225	SF	6	10+ years	
		20,0	220	٥.	Ŭ	,	





Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Floor Drain 1.5 Floor - Bovs EΑ 10+ vears 7 EΑ 7 Lavatory 1.5 Floor - Bovs 4 10+ years Lighting - Pendent/Surface 1.5 Floor - Bovs 2 FΑ 7 10+ years Partitions 3 EΑ 7 1.5 Floor - Boys 10+ years 5 Urinals 1.5 Floor - Boys EΑ 7 10+ years SF Walls - Concrete Block 480 7 1.5 Floor - Boys 10+ years Water Closet 1.5 Floor - Boys EΑ 7 10+ years 3 SF Accessories 1.5 Floor - Girls 241 7 6-10 years SF Ceiling - Plaster/Drywall 1.5 Floor - Girls 241 7 10+ years Doors - Wood Doors inclu hw 1.5 Floor - Girls FΑ 7 10+ years Floor - Terrazzo 1.5 Floor - Girls 241 SF 7 10+ years Floor Drain 1.5 Floor - Girls 1 EΑ 7 10+ years 1.5 Floor - Girls 3 EΑ 7 Lavatory 10+ years Lighting - Pendent/Surface 2 EΑ 7 1.5 Floor - Girls 10+ years **Partitions** 1.5 Floor - Girls 6 EΑ 7 10+ years Walls - Concrete Block SF 1.5 Floor - Girls 510 7 10+ years EΑ Water Closet 1.5 Floor - Girls 6 7 10+ years 1st Floor - Principal toilet SF Accessories 64 7 6-10 years Ceiling - Plaster/Drywall SF 1st Floor - Principal toilet 64 7 10+ vears Doors - Wood Doors inclu hw 1st Floor - Principal toilet 1 EΑ 7 10+ years Floor - Tile 1st Floor - Principal toilet 64 SF 7 10+ years Floor Drain 7 10+ years 1st Floor - Principal toilet 1 EΑ 7 Lavatory 1st Floor - Principal toilet 1 EΑ 10+ years 7 Lighting - Pendent/Surface 1st Floor - Principal toilet 1 FΑ 10+ years Walls - Plaster/Drywall 1st Floor - Principal toilet 128 SF 7 10+ years Water Closet 1st Floor - Principal toilet 1 EΑ 7 10+ years SF Accessories At Main Entry - Men 195 7 6-10 years Ceiling - Plaster/Drywall At Main Entry - Men 195 SF 7 10+ years Doors - Wood Doors inclu hw At Main Entry - Men EΑ 1 7 10+ years Floor - Terrazzo At Main Entry - Men 195 SF 6 10+ years Floor Drain At Main Entry - Men FΑ 7 10+ years 1 Lavatory At Main Entry - Men 3 EΑ 7 10+ years Lighting - Pendent/Surface 2 7 At Main Entry - Men FΑ 10+ years **Partitions** At Main Entry - Men 2 FΑ 7 10+ years 7 Urinals At Main Entry - Men 4 EΑ 10+ years Walls - Concrete Block At Main Entry - Men SF 7 400 10+ years Water Closet At Main Entry - Men 2 EΑ 7 10+ years At Main Entry - Women SF 6-10 years Accessories 224 7 SF Ceiling - Plaster/Drywall At Main Entry - Women 224 7 10+ years Doors - Wood Doors inclu hw At Main Entry - Women EΑ 1 7 10+ years SF Floor - Terrazzo At Main Entry - Women 224 7 10+ years Floor Drain At Main Entry - Women FΑ 7 10+ years 1 Lavatory At Main Entry - Women 3 EΑ 7 10+ years 2 Lighting - Pendent/Surface At Main Entry - Women EΑ 7 10+ years





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	At Main Entry - Women	4	EΑ	7	10+ years	
	Walls - Concrete Block	At Main Entry - Women	458	SF	7	10+ years	
	Water Closet	At Main Entry - Women	4	EA	7	10+ years	
	Accessories	Basement	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	42	SF	7	10+ years	
	Floor Drain	Basement	1	EΑ	7	10+ years	
	Lavatory	Basement	1	EΑ	7	10+ years	
	Lighting - Wall Mounted	Basement	1	EA	7	10+ years	
	Walls - Concrete Block	Basement	92	SF	7	10+ years	
	Water Closet	Basement	1	EA	7	10+ years	
	Accessories	Basement	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	7	10+ years	
	Floor - Tile	Basement	42	SF	7	10+ years	
	Lavatory	Basement	1	EA	7	10+ years	
	Lighting - Wall Mounted	Basement	1	EA	7	6-10 years	
	Walls - Concrete Block	Basement	92	SF	7	10+ years	
	Water Closet	Basement	1	EA	7	10+ years	
	Accessories	Stage left	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Stage left	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Stage left	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Stage left	30	SF	7	10+ years	
	Lavatory	Stage left	1	EA	7	10+ years	
	Lighting - Wall Mounted	Stage left	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Stage left	60	SF	7	10+ years	
	Water Closet	Stage left	1	EA	7	10+ years	

Category : Classroom Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	m #1 (Art Room)		•			•	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	768	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EΑ	7	10+ years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	659	SF	7	10+ years	
	Walls - Masonry	2nd Floor	659	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	45	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	



Catego	ry : Classroom		R	uilding	: Main	·	1946 S Paulina STREET, Chicago, IL 6060
Jalogo				anamg	· maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #2 (Regular Classroom)					•	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	645	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	645	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	536	SF	7	10+ years	
	Walls - Masonry	2nd Floor	53	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	256	SF	7	10+ years	
Classroo	m #303 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	645	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	645	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	536	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	120	SF	7	10+ years	
Classroo	m #304 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	620	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	620	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	26	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	384	SF	7	10+ years	
	Walls - Masonry	2nd Floor	384	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	42	SF	7	10+ years	
Classroo	m #305 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	620	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	620	SF	7	10+ years	
	-		323	= -	-	- ,	

Page : 10 of 30



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	384	SF	7	10+ years	
	Walls - Masonry	2nd Floor	384	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	42	SF	7	10+ years	
						,	
Classroo	m #306 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	645	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	645	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	800	SF	7	10+ years	
	Walls - Masonry	2nd Floor	72	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	48	SF	7	10+ years	
			.0	О.	•	.o. you.o	
Classroo	m #7 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	645	SF	7	10+ years	
	Chalk Board	2nd Floor	16	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	645	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	26	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	600	SF	7	10+ years	
	Walls - Masonry	2nd Floor	200	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	48	SF	7	10+ years	
			.0	О.	•	.o. you.o	
Classroo	m #8 (Science Lab Level 1)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	752	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	752	SF	7	10+ years	
	Gas Line	2nd Floor	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	752	SF	7	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	33.3.100 Edb 31101101	2110 1 1001	'	_, .	•	io. youro	





Category : Classroom			Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Masonry	2nd Floor	432	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	432	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	52	SF	7	10+ years		
	Work Sink	2nd Floor	3	EA	7	10+ years		
Catego	ry : Interior		В	uilding	: Main			
Jatogo	y			unung	· Wani	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Plaster/Drywall	1.5 Floor	78	SF	7	10+ years		
	Doors - Steel Doors incl hw	1.5 Floor	1	EA	7	10+ years		
	Floor - Terrazzo	1.5 Floor	78	SF	7	10+ years		
	Lighting - Pendent/Surface	1.5 Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1.5 Floor	156	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	774	SF	6	10+ years		
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years		
	Floor - Tile/Sheet	2nd Floor	774	SF	7	10+ years	Rank changed to match current	
	11001 1110/011001	2110 1 1001	• • •	O.	•	io. youro	observation	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years		
	Student Lockers - One Tier	2nd Floor	139	ΕA	6	10+ years		
	Walls - Concrete Block	2nd Floor	81	SF	7	10+ years		
	Walls - Masonry	2nd Floor	54	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	216	SF	7	10+ years		
Cafatu	·					•		
Safety	Camera Viewing Station	Entire building	1	EA	7	6-10 years		
	Metal Dedector	Entire building	1	EA	7	6-10 years		
	Security Cameras	Entire building Entire building	10	EA	7	•		
	Security Carrieras	Entire building	10	EA	1	6-10 years		
Stairs								
	Ceiling - Plaster/Drywall	Main Entrance	150	SF	7	10+ years		
	Floor - Terrazzo	Main Entrance	40	SF	7	10+ years		
	Floor - Tile	Main Entrance	375	SF	7	10+ years		
	Handrails	Main Entrance	280	LF	7	10+ years	Rank changed to match current observation	
	Lighting - Pendent/Surface	Main Entrance	10	EA	7	10+ years		
	Stairs - Terrazzo	Main Entrance	120	LF	7	10+ years		
	Walls - Plaster/Drywall	Main Entrance	1,296	SF	7	10+ years		
	Ceiling - Plaster/Drywall	South	96	SF	7	10+ years		
	Floor - Concrete	South	120	SF	7	10+ years		
	Handrails	South	144	LF	7	10+ years	Rank changed to match current observation	
	Lighting - Pendent/Surface	South	6	EA	7	10+ years	ODSCIVATION	





Category : Interior			В	Building : Main					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Stairs - Concrete	South	72	LF	7	10+ years			
	Walls - Masonry	South	1,296	SF	7	10+ years			



Category : Exterior	Building : Leased-Branch
	_

ategory . Exterior			anamg	. <u>_</u>	Recommend	
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance	20041011	Quantity	COM	rwin	Ropidoomon	Comments
Entrance Control - Audio and Video	1 - West	1	EA	6	10	Locked.
Exterior Doors - Exterior Steel Door	1 - West	1	EA	6	10+ years	Locked.
		1		6	10+ years	
Exterior Doors - Side lite	1 - West	· ·	EA	6	10+ years	
Exterior Stairs - Concrete	1 - West	24	LF	6	10+ years	
Stair Handrail - Steel_Stair Handrail	1 - West	12	LF	7	10+ years	
Entrance Control - Audio	2 - SE	1	EA	7	10+ years	
Exterior Doors - Exterior Steel Door	2 - SE	1	EA	6	10+ years	
Exterior Doors - Side lite	2 - SE	1	EA	6	10+ years	
Exterior Stairs - Concrete	2 - SE	40	LF	5	10+ years	
Stair Handrail - Steel_Stair Handrail	2 - SE	20	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	3 - East	1	EA	6	10+ years	
Exterior Doors - Side lite	3 - East	1	EA	6	10+ years	
Exterior Stairs - Concrete	3 - East	40	LF	6	10+ years	
Stair Handrail - Steel_Stair Handrail	3 - East	20	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	4 - NE	2	EΑ	6	10+ years	
Exterior Stairs - Concrete	4 - NE	40	LF	5	10+ years	
Power Door Operator and Controls	4 - NE	1	EA	7	10+ years	
Ramp Handrail - Steel_Ramp Handrail	4 - NE	50	LF	5	10+ years	Corrected quantity
Ramps - Concrete	4 - NE	23	LF	7	10+ years	Divided out quantities
Ramps - Concrete	4 - NE	2	LF	5	0-1 year	Spalling at posts
Stair Handrail - Steel_Stair Handrail	4 - NE	10	LF	5	0-1 year	Rusted posts
Entrance Control - Audio and Video	5 - NW	1	EA	7	10+ years	·
Exterior Doors - Exterior Steel Door	5 - NW	1	EA	6	10+ years	
Exterior Doors - Side lite	5 - NW	1	EA	6	10+ years	
Exterior Stairs - Concrete	5 - NW	32	LF	7	10+ years	
Ramp Handrail - Steel_Ramp Handrail	5 - NW	46	LF	6	10+ years	
Ramps - Concrete	5 - NW	2	LF	6	10+ years	
Ramps - Concrete	5 - NW	21	LF	6	10+ years	
Stair Handrail - Steel_Stair Handrail	5 - NW	3	LF	6	10+ years	
Stair Handrail - Steel_Stair Handrail	5 - NW	9	LF	6	10+ years	
otali Harididii Otoci_otali Harididii	3 1444	9		O	101 years	
undation						
Foundation - Concrete	Entire Building	750	LF	7	10+ years	No basement
Superstructure - Steel	Entire Building	33,484	SF	7	10+ years	No exposed structure
Superotructure Stock	Zitti o Dalianig	55,70 1	٥.	•	ioi youis	110 OAPOOOG GERGERE
phting						
Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	7	10+ years	
Exterior Lighting - Wall Mounted	Entire Building	19	EA	7	10+ years	New LED lighting
Ç Ç	Ÿ				-	5 5
oof System						
Access Ladder - Metal	Roof	1	EA	7	10+ years	No issues observed

Page : 14 of 30





Catego	ry : Exterior		В	uilding	: Lease	d-Branch	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chimney - Brick Chimney- Concrete/ Mortar	Roof	40	LF	7	10+ years	
	Liner						
	Chimney - Metal Flue	Roof	70	LF	7	10+ years	
	Coping - Stone	Roof	795	LF	6	10+ years	Combined quantities
	Downspouts - Exterior Downspouts	Roof	293	LF	6	10+ years	•
	Parapet - 16" - 30" Height	Roof	232	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof	545	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof	2	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof	20	LF	4	0-1 year	Displaced masonry, failed repair
	Roof - Asphalt Gravel Ballast			SF		-	Displaced masonly, falled repair
		Roof	13,742		7	10+ years	Manatation months and in a
	Roof - Asphalt Gravel Ballast	Roof	3,000	SF	5	0-1 year	Vegetation growth, ponding, and
	Destiletel Metal	Doort	4	^	7	40	trees growing onto roof.
	Roof Hatch - Metal	Roof	10.740	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof	16,742	SF	7	10+ years	
	Concrete Topping						
Valls							
	Exterior Walls - Brick	Entire Building	12,356	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	400	SF	3	0-1 year	At parapet. Damaged, shifting
		3				, ,	masonry
	Exterior Walls - Stone-Cast	Entire Building	2,060	SF	5	10+ years	,
	Exterior Walls - Stone-Cut	Entire Building	1,335	SF	5	10+ years	
	Exterior Walls - Stucco	Entire Building	2,835	SF	5	10+ years	
	Exterior Wallo Cladeo	Zittire Ballating	2,000	O.	Ü	Tot youro	
Vindows	3						
	Guard - Guards perforated	Entire Building	1,578	SF	6	10+ years	
	Lintels - Steel	Entire Building	795	LF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	3,310	SF	6	6-10 years	
	pane	J	·			•	
	Windows - Decorative	Entire Building	12	SF	6	6-10 years	
	Windows - Louver	Entire Building	24	SF	6	6-10 years	
	Windows - Louver	Entire Building	28	SF	5	6-10 years	
					-	, ,	
Catego	ry : Electrical		В	uilding	: Lease	d-Branch	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	7.1	Location	Quantity	UOIVI	Naiik	Replacement	Comments
merger	ncy System	Entire Building	7 550	SF	6	10 L VOORO	
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,550	SF	б	10+ years	
	Emergency A/C Power - Multipurpose	Entire Building	4,500	SF	6	10+ years	Building has an EM panel
	Room						
	Emergency Battery Packs - Corridors and	Entire Building	28	EA	6	6-10 years	
	Stairs						

Page : 15 of 30





Catogo	ry : Electrical		P	uildina	· I 0260	d-Branch	
Salego	ry . Electrical		Building : Leased-Branch Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	Comments
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	23	EA	6	6-10 years	
	Security System - CCTV	Entire Building	33,484	SF	6	6-10 years	
	Security System - Corv Security System - Intrusion Detection	Entire Building	33,484	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	33,404	SF	O	0-10 years	
/lain Sei	rvice						
	Main Electrical Service - 1200 A	Electrical Room	1	EA	6	10+ years	Serves leased building
	120/208/3PH						
	PA System	Entire Building	33,484	SF	6	6-10 years	Serves leased building
Power D	istribution						
<u> </u>	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	ĒΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Less than 400	Entire Building	2	EA	7	10+ years	
	amp	Little Building	2	L/\	,	101 years	
Catego	ry : Fire Protection		В	uildina	· Lease	d-Branch	
oulogo	19 11 110 110 10 10 10 11			unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Serves leased building, older,
							functional
	Fire Alarm Strobe Lights	Entire Building	33,484	SF	6	10+ years	
	Fire Alarm_System	Entire Building	33,484	SF	6	10+ years	Serves leased building
Snrinklar	System						
	Sprinkler Heads	Entire Building	33,484	SF	7	10+ years	
	Sprinkler Piping	Entire Building	33,484	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	33,484	SF	6	10+ years	1956 installation, using city water
		g	22,121		-	, , , , , , , , , , , , , , , , , , ,	pressure
Catego	ry : Mechanical		R	uildina	· I ease	d-Branch	
Jacogo	. jcomamoui			anamg	. =5456	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
<u></u>	Condensing Unit- Roof Mounted - 5-10	Roof	1	EA	6	10+ years	Johnson Control unitary Products, (1. serves north side, first floor, shar

Page : 16 of 30



Peace & Education Coalition HS

Catego	ry : Mechanical		В	Building : Leased-Branch				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	6-10 years	Johnson Controls, CU 5, serves center portion of building	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	6-10 years	Carrier, Gemini CU 2, serves north side, first floor, shared with Precious Blood tenant	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	10+ years	Johnson Control Unitary Products, CU 4, serves center portion, first floor	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	10+ years	Goodman, CU 10, serves south portion of building	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	10+ years	Carrier, CU 7, serves south portion of building	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	10+ years	CU 9, serves south portion of building	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Johnson Control, CU 8, serves south portion of building	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Carrier CU 3,serves north side, first floor, shared with Precious Blood tenant	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	4	10+ years	Carrier, CU 6, serves center portion of building, not mounted on base, contractor is scheduled to reinstall, reposition the unit	
_Air Hand	lling Systems							
	Fan Coil Unit- Floor Mounted - Electric	Entire Building	2	EA	6	10+ years	Serves north portion of building. Domestic style gas furnace with a DX coil.	
	Fan Coil Unit- Floor Mounted - Electric	Entire Building	6	EA	6	10+ years	Serves center and south portion of building, gas domestic style furnace with a DX coil	
	Fan Coil Unit- Floor Mounted - Electric	Entire Building	2	EA	6	10+ years	Serves north end, gas domestic style furnace with a DX coil	
Heating	Devices							
-0	Cabinet Heaters - With Electric Coil	1st Floor	4	EA	5	6-10 years		
	Wall Heater - Electric	Entire Building	4	EA	6	10+ years		
	High Efficiency Condensing Furnace - Less than 100 MBH	Entire Building	2	EA	5	6-10 years	In closets, next to room 101, 201, previously not assessed	
Tempera	ature Control							
-	Electric Controls	Electrical Room	33,484	SF	5	6-10 years	Control individual split system HVAC	
	Electric Thermostat	Electrical Room	10	EA	5	6-10 years	Serves fan coil units	



Peace & Education Coalition HS

Category : Mechanical			Building : Leased-Branch					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Ventilatio								
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	6	EA	5	6-10 years		
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	3	EA	6	10+ years		
	CFM							
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	4	EA	5	6-10 years		
	CFM	F 6 B 76	00		•	40		
	Roof Mounted Duct Work	Entire Building	30	LF	6	10+ years	Vertically mounted against the wall	
	Type I Exhaust Hood- Kitchen	Entire Building	1 2	EA EA	5 6	6-10 years	With fire suppression	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	б	10+ years	Stove is removed, not used in a kitchen anymore, functional, may have been part of culinary arts class.	
Catego	ry : Plumbing		В	uilding	: Lease	d-Branch		
	•					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Hot Wate	er							
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	6	6-10 years	Serves south portion of leased building	
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	Serves north portion of leased building, 2015 installation, 75k Btu/hr	
Dinin a								
Piping	Domestic Piping-Hot Water Return Lines	Entire Duilding	22.404	SF	6	10	Water pressure is good without a	
	Domestic Piping-not Water Return Lines	Entire Building	33,484	SF	6	10+ years	Water pressure is good, without a pressure booster pump	
	Domestic Piping-Hot Water Return Risers	Entire Building	33,484	SF	6	10+ years	There are no pipe clamps	
	Domestic Piping-Hot Water from Risers to	Entire Building	33,484	SF	6	10+ years	There are no pipe damps	
	Fixtures	Zitine Bananig	33, 13 1	O.	Ü	io. youro		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	33,484	SF	6	10+ years	1956 installation	
	(Horizontal Lines)	-				-		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	33,484	SF	6	10+ years		
	(Risers)				_			
	Domestic Piping-Hot/Cold Water Supply	Entire Building	33,484	SF	6	10+ years	Minor leaks are occasionally repaired	
	(from Risers to Fixtures)	Fating Desilations	20.404	0.5	0	40		
	Sanitary Piping	Entire Building	33,484	SF SF	6	10+ years		
	Storm Piping Vent Piping	Entire Building Entire Building	33,484 33,484	SF SF	6 6	10+ years		
	vent riping	Entire Building	33,404	SF	O	10+ years		
Catego	ry : Room		В	uilding	: Lease	d-Branch		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Administ	rative Suites/Offices							
	Ceiling - Plaster/Drywall	1st Floor - 102B	104	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - 102B	1	EΑ	7	10+ years		
	200.0 11000 200.0 110.0 111					,		





Category : Room			В	uilding	: Lease	d-Branch	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor - 102B	104	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - 102B	2	EA	7	10+ years	
	Power Distribution	1st Floor - 102B	6	EA	6	10+ years	
	Storage/ Closet	1st Floor - 102B	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - 102B	160	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - 102B	72	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - ADMIN 102	295	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - ADMIN 102	1	EA	7	10+ years	
	Floor - Tile	1st Floor - ADMIN 102	295	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - ADMIN 102	6	EA	7	6-10 years	
	Power Distribution	1st Floor - ADMIN 102	8	EA	6	10+ years	
	Storage/ Closet	1st Floor - ADMIN 102	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - ADMIN 102	612	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Conference Room	130	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Conference Room	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Conference Room	130	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Conference Room	2	EA	7	10+ years	
	Power Distribution	1st Floor - Conference Room	8	EA	6	10+ years	
	Walls - Concrete Block	1st Floor - Conference Room	24	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Conference Room	252	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - DIRECTOR 102A	176	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - DIRECTOR 102A	1	EA	7	10+ years	
	Floor - Tile	1st Floor - DIRECTOR 102A	176	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - DIRECTOR 102A	2	EA	7	10+ years	
	Power Distribution	1st Floor - DIRECTOR 102A	6	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - DIRECTOR 102A	468	SF	6	10+ years	
	Ceiling - Exposed	1st Floor - Engineer's Office	296	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Engineer's Office	2	EΑ	7	10+ years	
	Floor - Tile	1st Floor - Engineer's Office	296	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Engineer's Office	3	ĒΑ	7	10+ years	
	Power Distribution	1st Floor - Engineer's Office	8	ΕA	6	10+ years	
	Walls - Concrete Block	1st Floor - Engineer's Office	272	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Engineer's Office	272	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Engineer's Office	54	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Library Resource 116	240	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Library Resource 116	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Library Resource 116	240	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Library Resource 116	2	EA	7	10+ years	
	Power Distribution	1st Floor - Library Resource 116	8	EA	6	10+ years	
	Walls - Concrete Block	1st Floor - Library Resource 116	120	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Library Resource 116	380	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Library Resource 116	82	SF	6	10+ years	
	Ceiling - Exposed	1st Floor - Reception 100	98	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Reception 100	1	EA	7	•	
	DOOLS - MOOR DOOLS HIGH HM	15t Floor - Reception 100	ı	EA	,	10+ years	





Catego	ry : Room		В	uilding	: Lease	d-Branch	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor - Reception 100	98	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Reception 100	1	EA	6	10+ years	
	Power Distribution	1st Floor - Reception 100	2	EA	6	10+ years	
	Walls - Concrete Block	1st Floor - Reception 100	162	SF	6	10+ years	
	Ceiling - Plaster/Drywall	210 office	98	SF	6	10+ years	
	Doors - Wood Doors inclu hw	210 office	1	EA	7	10+ years	
	Floor - Carpet	210 office	98	SF	6	6-10 years	
	Lighting - Pendent/Surface	210 office	1	EA	7	10+ years	
	Power Distribution	210 office	8	EA	6	10+ years	
	Walls - Concrete Block	210 office	94	SF	6	10+ years	
	Walls - Plaster/Drywall	210 office	94	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - 212	850	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - 212	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor - 212	850	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - 212	6	EA	7	10+ years	
	Power Distribution	2nd Floor - 212	16	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor - 212	580	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - 212	580	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - 212	110	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Computer Technical Room 208	150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Computer Technical Room 208	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor - Computer Technical Room 208	150	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Computer Technical Room 208	1	EA	7	10+ years	
	Power Distribution	2nd Floor - Computer Technical Room 208	4	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor - Computer Technical Room 208	192	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Computer Technical Room 208	192	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - Computer Technical Room 208	42	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Office 124	117	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office 124	1	EA	6	10+ years	
	Floor - Tile	Office 124	117	SF	6	10+ years	
	Lighting - Pendent/Surface	Office 124	2	EA	7	10+ years	
	Walls - Concrete Block	Office 124	110	SF	6	10+ years	
	Walls - Plaster/Drywall	Office 124	98	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	190	SF	6	10+ years	





	Category : Room		Building : Leased-Branch					
Calego	iy. Kooni		ь	unung	. L c ase	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Огоир	Doors - Steel Doors incl hw	1st Floor	quantity 1	EA	6	10+ years	Comments	
	Floor - Tile	1st Floor	190	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	4	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	416	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	164	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	164	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	2	ĒΑ	7	10+ years		
	Storage/ Closet	2nd Floor	40	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	384	SF	6	10+ years		
Lunch &	Multipurpose Room							
	Ceiling - Plaster/Drywall	1st Floor	1,373	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	1,373	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	28	EA	7	10+ years		
	Market Board	1st Floor	16	LF	7	6-10 years		
	Serving Line	1st Floor	14	LF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	2,184	SF	6	10+ years		
_MDF_ID	E							
	Doors - Steel Doors incl hw	1st Floor - MDF Room 125	1	EA	7	10+ years		
	Finishes	1st Floor - MDF Room 125	98	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	IDF 119A	1	EA	7	10+ years		
	Finishes	IDF 119A	32	SF	7	6-10 years		
Maabaai	inal/ Coming Dooms							
_iviechani	cal/ Service Rooms	A - A Flancia	00	0.5	7	40		
	Janitor's Closet	1st Floor	82	SF SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	100	SF SF	7	10+ years		
	Mechanical/ Service Rooms Mechanical/ Service Rooms	1st Floor 1st Floor	130 110	SF SF	7 7	10+ years		
			-	SF SF	7 7	10+ years		
	Mechanical/ Service Rooms Storage Room	1st Floor 1st Floor	30 104	SF SF	7	10+ years		
	Storage Room	1st Floor	80	SF	7	10+ years 10+ years		
		1st Floor	60	SF SF	7			
	Storage Room			SF SF	7 7	10+ years		
	Mechanical/ Service Rooms Mechanical/ Service Rooms	2nd Floor 2nd Floor	150 15	SF SF	7	10+ years		
	Storage Room	2nd Floor	150	SF	7	10+ years 10+ years		
5.	-			-		- ,		
_Restroor		1at Floor Man 404	407		7	6.40		
	Accessories	1st Floor - Men 101	187	SF	7	6-10 years		
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	1st Floor - Men 101 1st Floor - Men 101	187 1	SF EA	6 7	10+ years		
	Doors - Wood Doors Inclu flw	15t Floor - Metr 101	.1	⊏A	′	10+ years		





Catego	Category : Room		В	, , , , , , , , , ,			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men 101	187	SF	6	10+ years	
	Floor Drain	1st Floor - Men 101	1	EΑ	7	10+ years	
	Lavatory	1st Floor - Men 101	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men 101	3	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men 101	2	EΑ	5	0-1 year	Missing diffuser
	Partitions	1st Floor - Men 101	2	EA	7	10+ years	
	Urinals	1st Floor - Men 101	3	EA	6	10+ years	
	Walls - Concrete Block	1st Floor - Men 101	208	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Men 101	208	SF	6	10+ years	
	Water Closet	1st Floor - Men 101	2	EA	6	10+ years	
	Accessories	1st Floor - Men 119	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Men 119	370	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Men 119	10	SF	5	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	1st Floor - Men 119	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men 119	380	SF	6	10+ years	
	Floor Drain	1st Floor - Men 119	1	EA	7	10+ years	
	Lavatory	1st Floor - Men 119	3	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men 119	6	EΑ	7	10+ years	
	Partitions	1st Floor - Men 119	6	EΑ	7	10+ years	
	Urinals	1st Floor - Men 119	5	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor - Men 119	342	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Men 119	342	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Men 119	62	SF	6	10+ years	
	Water Closet	1st Floor - Men 119	6	EA	7	10+ years	
	Accessories	1st Floor - Restroom 110A	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Restroom 110A	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Restroom 110A	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor - Restroom 110A	36	SF	6	10+ years	
	Floor Drain	1st Floor - Restroom 110A	1	EA	7	10+ years	
	Lavatory	1st Floor - Restroom 110A	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Restroom 110A	1	EA	5	0-1 year	Missing diffuser
	Walls - Concrete Block	1st Floor - Restroom 110A	192	SF	6	10+ years	5
	Walls - Structural Glazed Tile	1st Floor - Restroom 110A	24	SF	6	10+ years	
	Water Closet	1st Floor - Restroom 110A	1	EA	6	10+ years	
	Accessories	1st Floor - Restroom 131	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Restroom 131	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Restroom 131	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Restroom 131	36	SF	6	10+ years	
	Floor Drain	1st Floor - Restroom 131	1	EA	7	10+ years	
	Lavatory	1st Floor - Restroom 131	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Restroom 131	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Restroom 131	81	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - Restroom 131	81	SF	7	10+ years	
	Water Closet	1st Floor - Restroom 131	1	EA	6	10+ years	
	Tratal Global	TOUT INCOLLOCATION	!		U	ioi years	





Catego	ory : Room		В	Building : Leased-Branch					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	1st Floor - Women 105	380	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor - Women 105	380	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - Women 105	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women 105	380	SF	6	10+ years			
	Floor Drain	1st Floor - Women 105	1	EA	7	10+ years			
	Lavatory	1st Floor - Women 105	5	EA	6	10+ years			
	Lighting - Pendent/Surface	1st Floor - Women 105	8	EA	7	10+ years			
	Partitions	1st Floor - Women 105	9	EA	7	10+ years			
	Walls - Concrete Block	1st Floor - Women 105	226	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor - Women 105	304	SF	6	10+ years			
	Water Closet	1st Floor - Women 105	9	EA	6	10+ years			
	Accessories	2nd Floor - Bathroom 207	33	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor - Bathroom 207	33	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - Bathroom 207	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Bathroom 207	33	SF	6	10+ years			
	Lavatory	2nd Floor - Bathroom 207	1	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor - Bathroom 207	1	EA	6	10+ years			
	Partitions	2nd Floor - Bathroom 207	1	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor - Bathroom 207	39	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Bathroom 207	37	SF	6	10+ years			
	Water Closet	2nd Floor - Bathroom 207	1	EA	6	10+ years			
	Accessories	2nd Floor - Men 203	205	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor - Men 203	205	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - Men 203	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Men 203	205	SF	6	10+ years			
	Floor Drain	2nd Floor - Men 203	1	EA	7	10+ years			
	Lavatory	2nd Floor - Men 203	2	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor - Men 203	2	EA	7	10+ years			
	Partitions	2nd Floor - Men 203	2	EA	7	10+ years			
	Urinals	2nd Floor - Men 203	3	EA	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor - Men 203	378	SF	6	10+ years			
	Water Closet	2nd Floor - Men 203	2	EA	6	10+ years			
	Accessories	In room 104 daycare	37	SF	7	6-10 years			
	Ceiling - Lay-in	In room 104 daycare	37	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	In room 104 daycare	1	EA	7	10+ years			
	Floor - Tile	In room 104 daycare	37	SF	7	6-10 years			
	Lavatory	In room 104 daycare	1	EA	7	10+ years			
	Lighting - Lay-in	In room 104 daycare	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	In room 104 daycare	1	SF	7	10+ years			
	Water Closet	In room 104 daycare	1	EA	4	0-1 year	Does not work.		





Catego	ry : Classroom		Building : Leased-Branch						
Calogo	.,		_	aag	0000	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank		Comments		
Classroc	om #103 (Regular Classroom)		-			•			
	Casework	1st Floor	15	LF	7	10+ years			
	Ceiling - Exposed	1st Floor	815	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	10+ years			
	Floor - Tile	1st Floor	815	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	10	EA	7	10+ years			
	Marker Board	1st Floor	6	LF	7	6-10 years			
	Storage/ Closet	1st Floor	30	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	104	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	772	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	100	SF	7	10+ years			
Classroo	om #104 (Regular Classroom)								
0.000.00	Casework	1st Floor	15	LF	7	10+ years			
	Ceiling - Exposed	1st Floor	506	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	506	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	7	ĒΑ	7	10+ years			
	Marker Board	1st Floor	6	LF	7	6-10 years			
	Storage/ Closet	1st Floor	30	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	64	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	594	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	100	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classroo	om #115 (Regular Classroom)								
	Ceiling - Exposed	1st Floor	850	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Floor - Tile	1st Floor	850	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	10+ years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Walls - Concrete Block	1st Floor	100	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	928	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor	102	SF	6	10+ years			
Classroo	om #117 (Regular Classroom)								
0.000.00	Ceiling - Plaster/Drywall	1st Floor	850	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	850	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	928	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor	98	SF	6	10+ years			
						,			





Catego	ry : Classroom		В	uilding	: Lease	d-Branch	·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classros	om #120 (Science Lab Level 1)						
Classion	Casework	1st Floor	24	LF	6	10+ years	
				SF		,	
	Ceiling - Plaster/Drywall	1st Floor	450		6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EΑ	7	10+ years	
	Marker Board	1st Floor	48	LF	7	6-10 years	
	Science Lab Elements	1st Floor	450	SF	7	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	42	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	336	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	336	SF	7	10+ years	
	Work Sink	1st Floor	4	EA	7	10+ years	
_Classroo	om #122 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	540	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	540	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	736	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	42	SF	7	10+ years	
Classroo	om #123 (Computer Lab)						
Classion		4-4-51	77.4			40	
	Ceiling - Plaster/Drywall	1st Floor	774	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	774	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	10+ years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	400	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	650	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	500	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
_Classroo	om #200 (Office)						
	Ceiling - Exposed	2nd Floor	130	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	130	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	



Building : Leased-Branch



Category : Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	24	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	225	SF	6	10+ years	
Classroo	m #205 (Weight)						
	Ceiling - Plaster/Drywall	2nd Floor	729	SF	6	10+ years	
	Chalk Board	2nd Floor	12	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	2nd Floor	729	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	550	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	550	SF	6	10+ years	
				_		,	
Classroo	m #215 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	535	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Carpet	2nd Floor	400	SF	6	6-10 years	
	Floor - Tile	2nd Floor	135	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EΑ	7	10+ years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	368	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	368	SF	6	10+ years	
	Work Sink	2nd Floor	1	EΑ	7	10+ years	
						,	
Catego	ry : Interior		В	Building	: Lease	d-Branch	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Exposed	1st Floor	2,856	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	8	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	2,856	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	26	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	104	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	848	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	848	SF	6	10+ years	
	Ceiling - Exposed	2nd Floor	890	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	3	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor	890	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	464	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	464	SF	6	10+ years	
						•	
Campus N	Name: Peace And Education HS		Page: 26 of 30				Assessment Date: 05/25/2022



Peace & Education Coalition HS

Catego	Category : Interior			Building : Leased-Branch					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Safety									
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years			
	Metal Dedector	Entire Building	1	EA	7	6-10 years			
	Security Cameras	Entire Building	16	EA	7	6-10 years			
_Stairs									
	Ceiling - Plaster/Drywall	South East	266	SF	7	10+ years			
	Floor - Terrazzo	South East	225	SF	6	10+ years			
	Handrails	South East	52	LF	7	10+ years			
	Lighting - Pendent/Surface	South East	5	EA	7	10+ years			
	Stairs - Terrazzo	South East	26	LF	6	10+ years			
	Walls - Concrete Block	South East	62	SF	7	10+ years			
	Walls - Plaster/Drywall	South East	576	SF	7	10+ years			
	Walls - Structural Glazed Tile	South East	576	SF	7	10+ years			





Category: Site **Building: Site** Recommend Location Replacement Item - Type Quantity **UOM** Comments Group Rank Athletic Metal Bleachers Leased South LF 7 80 10+ years 4.000 SF 7 Surface - Asphalt Leased South 10+ years Civil/Drainage Civil/ Drainage - Catch Basin 5 FΑ Leased 6 10+ years 3 Civil/ Drainage - Site Manhole FΑ 6 Leased 10+ years Fencina Fencing - Chain Link LF 7 Leased 1,210 10+ years LF Fencing - Chain Link Leased 30 6 6-10 years Assessed based on current condition LF Fencing - New Standard Ornamental Leased 400 7 10+ years Fencing - Chain Link Main 142 LF 6 10+ years LF Fencing - Chain Link Main 46 0-1 year Worn, falling apart. Landscape Landscape - Grass Leased 59.587 SF 6 10+ years SF Landscape - Hardscape- Asphalt Leased 415 5 6-10 years Landscape - Hardscape- Concrete 725 SF 6 10+ years Leased SF Landscape - Hardscape- Pavers Leased 355 10+ years Parkway trees 17 EΑ 6 10+ years Leased Planting Beds/ Area Leased 20,870 SF 7 10+ years SF Play Area - Hardscape- Asphalt Leased 9,817 0-1 year Cracking and vegetation growth. Walking Path - Crushed Stone SF 7 10+ years Leased 450 Landscape - Grass SF 1.775 0-1 year Worn, damaged Main Landscape - Hardscape- Concrete Main 780 SF 6 2-5 years SF Planting Beds/ Area Main 1.075 5 10+ years Parking Lot Concrete Curbs Leased - NW LF 7 30 10+ years LF Interior Plantings Leased - NW 18 6 10+ years SF Surface - Asphalt Leased - NW 29.435 4 0-1 year Potholes, sinkholes, extensive cracking and raveling throughout. SF Surface - Concrete Leased - NW 1.300 Potholes, sinkholes, extensive 0-1 year cracking and spalling throughout. Sidewalks Sidewalks - Internal Walks LF Leased 50 6 10+ years Sidewalks - Perimeter Sidewalks Leased 2.000 SF 7 10+ years SF Sidewalks - Perimeter Sidewalks Leased 10,895 6 10+ years Sidewalks - Internal Walks LF 7 Main 74 10+ years

Page: 28 of 30



Peace & Education Coalition HS

4946 S Paulina STREET, Chicago, IL 60609

Catego	ry : Site		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Main	26	LF	4	0-1 year	Cracked/broken.
	Sidewalks - Perimeter Sidewalks	Main	840	SF	7	10+ years	
Signage							
0 0	Marquee - Building Mounted Back Lighted	Leased	1	EA	7	10+ years	
	w/ LĖD					,	
	Monument - Building Mounted Cut Letter	Main	1	EA	6	10+ years	
	Sign					•	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Page: 29 of 30

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

-				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	2nd Floor	1	301	768	168	45	Ν	N
Music Room	Regular Classroom	2nd Floor	303	303	645	183	60	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	2	302	645	183	60	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	304	304	620	128	35	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	305	305	620	128	35	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	306	306	645	128	35	Ν	N
Regular Classroom	Regular Classroom	2nd Floor	7	307	645	128	35	Ν	N
Science Lab Level 1	Regular Classroom	2nd Floor	8	308	752	78	28	Ν	N

Building : Leased-Branch									
Computer Lab	Computer Lab	1st Floor	123	123	774	72	24	Υ	N
Office	Computer Lab	2nd Floor	200	200	130	48	24	N	N
Regular Classroom	Exclusively Used by Outside Organization	1st Floor	103	Daycare	815	12	30		
Regular Classroom	Exclusively Used by Outside Organization	1st Floor	104	Daycare	506	12	21		
Regular Classroom	Regular Classroom	1st Floor	115	115	850	96	48	Υ	Ν
Regular Classroom	Regular Classroom	1st Floor	117	117	850	96	48	Υ	N
Regular Classroom	Regular Classroom	1st Floor	122	122	540	72	36	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	209	535	96	48	N	N
Science Lab Level 1	Regular Classroom	1st Floor	120	120	450	72	36	Υ	N
Weight	Art Room	2nd Floor	205	205	729	184	144	Υ	N

Page : 30 of 30