

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1907	3	158,325
Campus Total			158,325

Category: Exterior **Building: Main** Recommend Item - Type Location Quantity **UOM** Rank Replacement Comments Group Cell Equipment Cell Equipment - Antenna **Entire Building** 3 EΑ 7 10+ years Cell Equipment - Cabinets **Entire Building** 3 EΑ 7 10+ years Entrance Exterior Doors - Exterior Steel Door 7 4.3 West Courtyard Basement 1 EΑ 10+ years Exterior Doors - Transom Lite 4.3 West Courtyard Basement 1 EΑ 7 10+ years 4.3 West Courtyard Basement 5 LF Exterior Stairs - Concrete 7 10+ years Entrance Control - Audio and Video Door 1 - East center 1 EΑ 6 10+ years 7 Exterior Doors - Exterior FRP Door Door 1 - East center 3 FΑ 10+ years Exterior Stairs - Concrete Door 1 - East center 66 LF 6 10+ years Entrance Control - Audio and Video Door 1.5 - East courtvard north 1 FΑ 6 10+ years Exterior Doors - Store Front Door 1.5 - East courtyard north EΑ 6 10+ years 1 Exterior Doors - Transom Lite Door 1.5 - East courtyard north 1 EΑ 6 10+ years Door 1.5 - East courtyard north LF 6 Ramp Handrail - Steel Ramp Handrail 84 10+ years ΙF Ramps - Concrete Door 1.5 - East courtyard north 42 6 10+ years Exterior Doors - Exterior FRP Door Door 10 - east courtvard, south FΑ 6 10+ years 1 Exterior Doors - Transom Lite Door 10 - east courtyard, south 1 FΑ 6 10+ years Exterior Doors - Exterior FRP Door Door 2 - Southeast 3 EΑ 6 10+ years Exterior Stairs - Concrete Door 2 - Southeast 58 LF 6 10+ years LF 5 Exterior Stairs - Concrete Door 2 - Southeast 10 0-1 year Cracking/missing. Entrance Control - Audio and Video Door 3 - South 1 EΑ 6 10+ years Exterior Doors - Exterior FRP Door 3 EΑ 6 10+ years Door 3 - South Door 3 - South LF 6 10+ years Ramp Handrail - Steel Ramp Handrail 36 LF Ramps - Concrete Door 3 - South 18 6 10+ years



Catego	Category : Exterior		В	uilding	: Main		: J :
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	Door 3.3 - Chiller South	2	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 3.5 - Chiller north	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Door 4 - West Boiler Rm	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 4 - West Boiler Rm	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	Door 4 - West Boiler Rm	1	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 4.1 - West, Courtyard Engineer	1	EΑ	6	10+ years	
	Exterior Stairs - Stone	Door 4.1 - West, Courtyard Engineer	4	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 4.2 - Auditorium South	2	EΑ	5	2-5 years	
	Exterior Stairs - Concrete	Door 4.2 - Auditorium South	6	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 5 - West, north	1	EA	6	10+ years	
	Exterior Doors - Side lite	Door 5 - West, north	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	Door 5 - West, north	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	Door 5 - West, north	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 5.2 - Fire escape	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 5.2 - Fire escape	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 5.5 - Auditorium North	2	EΑ	5	2-5 years	
	Exterior Stairs - Concrete	Door 5.5 - Auditorium North	6	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 6 - Northwest	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 7 - North	3	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 7 - North	24	LF	6	10+ years	
	Ramps - Concrete	Door 7 - North	12	LF	6	10+ years	
	Entrance Control - Audio and Video	Door 8 - Northeast	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 8 - Northeast	3	EΑ	6	10+ years	
	Exterior Stairs - Concrete	Door 8 - Northeast	71	LF	6	10+ years	
	Exterior Stairs - Concrete	Door 8 - Northeast	5	LF	5	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 9 - East courtyard north	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 9 - East courtyard north	1	EA	6	10+ years	
_Fire Esc	ape						
	Fire Escape	Façade- NW	80	LF	6	6-10 years	
	Fire Escape	Façade- NW	5	LF	4	0-1 year	Tread broken
_Foundat	ion						
_i ouiluat	Foundation - Concrete	Entire Building	155	LF	7	10+ years	
	Foundation - Concrete Foundation - Masonry	Entire Building Entire Building	1,414	LF LF	7 7	10+ years 10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building Entire Building	158,325	SF	7	10+ years	
	Caparatidatare Clost with Olay The Alon	Entire ballating	100,020	01	,	ioi yeais	
_Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	7	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	2,033	LF	6	10+ years	
	·		•			Í	



Catego	ry : Exterior	-	В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Asphalt Shingle	Roof 1	36,668	SF	7	10+ years	Replaced 2020.
	Roof Structure - Steel with Clay Tile Arch	Roof 1	36,668	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	5	EA	7	10+ years	
	Access Ladder - Wood	Roof 2	3	EA	4	0-1 year	Not properly secured, access unsafe
	Coping - Stone	Roof 2	332	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 2	100	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 2	192	LF	7	10+ years	Replaced 2020.
	Parapet - Parapet < 16" Height	Roof 2	140	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 2	6,692	SF	7	10+ years	Replaced 2020.
	Roof Hatch - Metal	Roof 2	2	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	6,692	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	2	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 3	100	LF	6	10+ years	
	Liner	D (0			_	40	
	Coping - Stone	Roof 3	214	LF	7	10+ years	
	Coping - Stone	Roof 3	149	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	95	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 3	363	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	1,066	SF	7	10+ years	B 10000
	Roof - Modified Bitumen	Roof 3	2,412	SF	7	10+ years	Replaced 2020.
	Roof Structure - Steel with Clay Tile Arch	Roof 3	3,478	SF	7	10+ years	
	Coping - Stone	Roof 4	60	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4	60	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 4	60	LF	7	10+ years	D I I 0000
	Roof - Modified Bitumen	Roof 4	239	SF	7	10+ years	Replaced 2020.
	Roof Structure - Steel / Metal Deck/	Roof 4	239	SF	7	10+ years	
	Concrete Topping	Doof 5	00		7	10	
	Coping - Stone	Roof 5	62	LF	7 7	10+ years	
	Downspouts - Exterior Downspouts	Roof 5	60	LF	=	10+ years	
	Parapet - 16" - 30" Height Roof - Modified Bitumen	Roof 5	62 83	LF SF	7 7	10+ years	Danlaged 2020
		Roof 5		SF SF		10+ years	Replaced 2020.
	Roof - Modified Bitumen	Roof 5	280 63	SF SF	7	10+ years	Replaced 2020.
	Roof - Modified Bitumen	Roof 5 Roof 5	426	SF SF	6 7	6-10 years	Replaced 2020.
	Roof Structure - Steel with Clay Tile Arch	K001 5	420	SF	/	10+ years	
147 11							
_Walls	Charle Wall Chara	Fatina Divilalia a			7	40	
	Cheek-Wall - Stone	Entire Building	80	SF	7	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	3,400	LF	7	10+ years	B 1
	Cornice - Metal Projecting	Entire Building	3,300	LF	7	10+ years	Replacement in progress
	Exterior Walls - Brick	Entire Building	39,943	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	2,805	SF	6	6-10 years	
	Exterior Walls - Stone-Cast	Entire Building	1,080	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	1,320	SF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
oroup	item - Type	Location	Qualitity	OOW	Naiik	Replacement	Comments
/indows	3						
	Curtain wall - Glazed Double Pane	Entire Building	774	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	8,087	SF	6	10+ years	
	Lintels - Brick	Entire Building	40	LF	6	10+ years	
	Lintels - Brick	Entire Building	70	LF	6	10+ years	
	Lintels - Steel	Entire Building	1,265	LF	6	10+ years	
	Lintels - Stone	Entire Building	260	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	190	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,840	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Main		
	_					Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System	EL .: 15				40	
	Automatic Transfer Switch	Electrical Room	2	EA	7	10+ years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	4,850	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	25,350	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,366	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,515	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,250	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	2	EA	7	6-10 years	The damaged units have been replaced
	Exit Signs - Auditoium	Entire Building	7	EA	6	6-10 years	Торійови
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	7	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	38	EA	2	0-1 year	Many signs have no backup or no light source
	Exit Signs - Gym	Entire Building	1	EA	7	6-10 years	The units are new
	Exit Signs - Lunchroom	Entire Building	3	ĒĀ	2	0-1 year	Exit sign missing at one exit (pape sign), another missing battery bac up and last one is not illuminated.
	Security System - CCTV	Entire Building	158,325	SF	5	2-5 years	ap and last one is not murimated.
	Security System - Intrusion Detection	Entire Building	158,325	SF	6	6-10 years	
	Emergency Generator- Outdoor- Diesel - 60 - 100 KW	Site West	1	EA	5	2-5 years	Repaired

Campus Name: Penn Page : 4 of 37 Assessment Date: 10/27/2021



Indoor Return Fans- Centrifugal Squirrel

Air Handling Unit- Built Up- Multi Zone- Hot

Cage - Greater than 20000 ČFM

Attic

Mechanical Room

William Penn Elementary School 1616 S Avers AVENUE, Chicago, IL 60623

3 units serve the AHU # 1, 2 and 3

Serves gym and auditorium.

	SCHOOIS						1616 S Avers AVENUE, Chicago, IL 60
Catego	ry : Electrical		В	Building	: Main		
			0			Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	7	10+ years	
	120/208/3PH	Entire Duilding	450.005	C.E.	_	0.40	Night feell governmen
	PA System	Entire Building	158,325	SF	5	6-10 years	Not full coverage
Power D	vistribution						
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Electrical Room	5	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Electrical Room	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Electrical Room	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	4	1-2 years	Old and deteriorated, auditorium
	Lighting and Power Panels - Above 100 A	Electrical Room	14	EA	6	6-10 years	,
	Lighting and Power Panels - Above 100 A	Electrical Room	13	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	1	EΑ	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	3	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600	Electrical Room	3	EA	7	10+ years	
	amp					,	
Catego	ry : Fire Protection		B	Building	· Main		
Juligo	19111011000000		_	anamg	· Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building	158,325	SF	7	10+ years	
	Fire Alarm_System	Entire Building	158,325	SF	7	10+ years	
	·	g				.o. you.o	
Catego	ry : Mechanical		В	uilding	: Main	D	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Conc			•			•	
	Chemical Pot Feeder	Site South	1	EA	7	10+ years	
	Chiller-Air Cooled-Screw Type-Ground	Site South	1	EA	7	10+ years	
	Mounted - 201 - 300 tons					•	
	Glycol Feed	Site South	1	EA	7	10+ years	
	Pipes - Dual Temperature Pipe- Copper	Site South	200	LF	7	10+ years	
	Pressure Fill System	Site South	1	EA	7	10+ years	
Air Hand	lling Systems						
	Indoor Return Fans- Centrifugal Squirrel	Attic	1	EA	6	10+ years	Serves the gymnasium and
	Cage - 10001 - 20000 CFM	A 44: -	0	- ^	^	40	auditorium ,AHU #4

Campus Name: Penn Page : 5 of 37 Assessment Date: 10/27/2021

10+ years

2-5 years

EΑ

EΑ



Catego		Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water and Chilled Water Coils - 15001 -						
	25000 cfm	Machanical Dages	4	Ε.	0	0.40	
	Air Intake Auxiliaries - 15001 - 25000 cfm	Mechanical Room Mechanical Room	1	EA EA	6 6	6-10 years 6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	200	LF	6	6-10 years	
	and Ducts	Wechanical Room	200	LF	O	0-10 years	
	Zone Dampers	Mechanical Room	7	EA	6	6-10 years	
	Air Handling Unit- Built Up- Multi Zone- Hot	Mechanical Room	1	EA	5	2-5 years	Serves the north wing classrooms
	Water and Chilled Water Coils - 15001 -	Wednamear Room	•	_, 、	Ū	20 you.o	Corves and moral wing diagonound
	25000 cfm						
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	200	LF	6	6-10 years	
	Missing or Existing Shaft					, , ,	
	Zone Dampers	Mechanical Room	20	EA	6	6-10 years	
	Air Handling Unit- Built Up- Multi Zone- Hot	Mechanical Room	1	EA	5	2-5 years	Serves south wing classrooms and
	Water and Chilled Water Coils - 15001 -					-	corridors
	25000 cfm						
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	200	LF	6	6-10 years	
	and Ducts						
	Zone Dampers	Mechanical Room	20	EA	6	6-10 years	
	Air Handling Unit- Built Up- Multi Zone-	Mechanical Room	1	EA	5	2-5 years	Serves north and south classrooms
	Double Delivery- Hot Water and Chilled						
	Water Coils - 45001 - 60000 cfm				_		
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 45001 - 60000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	20	LF	6	6-10 years	
	and Ducts	Machanical Dages	40	Ε.	0	0.40	
	Zone Dampers	Mechanical Room	40	EA	6	6-10 years	
Boiler Sy	rstems						
	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	6	10+ years	
	- 3001 - 4000 MBH	_ = = = = = = = = = = = = = = = = = = =	_		Ü	,	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	ĒΑ	6	2-5 years	Minor corrosion on frame
	Non Condensing- Water Tube- Flexible	Boiler Room	2	EA	6	10+ years	
	Tube- Force Draft- Hot Water Boiler - 3001				-	,	
	- 4000 MBH						
	Water Fill System	Boiler Room	1	EA	6	10+ years	
Gas Boo	otor						
<u>Gas B00</u>	Gas Booster	Basement	2	EA	6	6-10 years	
	230 20000		2	_, 、	J	o lo youlo	



Catego	ry : Mechanical		В	uilding	: Main		
Croun	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group	item - Type	Location	Quantity	UOW	Kank	Replacement	Comments
Heating	Devices						
·	Unit Heater - Gas	Boiler Room	1	EA	7	10+ years	
	Unit Heater - Electric	Entire Building	4	EA	5	2-5 years	
	Unit Heater - Hot Water	Entire Building	6	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	18	EA	6	6-10 years	4 of these were electric unit heaters previously misidentified.
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Only one unit left, non functional
	Fin Tube - Hot Water	Entire Building	50	LF	6	6-10 years	,
Mechan	ical Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	400	LF	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	2	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	3	EA	6	6-10 years	
	Dual Temperature Pump - 10 - 20 HP	Mechanical Room	2	EA	6	6-10 years	
Tempera	ature Control						
•	DDC System	Entire Building	158,325	SF	6	6-10 years	
	Thermostats - DDC	Entire Building	90	EA	6	6-10 years	
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	7	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression system, hood too small for equipment
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	small for equipment
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	5	2-5 years	
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	158,325	SF	4	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	158,325	SF	4	2-5 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	158,325	SF	4	2-5 years	



Catego	ry : Plumbing		В	uilding	: Main		_
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	158,325	SF	4	2-5 years	Majority of piping is galvanized. No leaks report but 5 pipe clamps are being used.
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	158,325	SF	4	2-5 years	•
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	158,325	SF	4	2-5 years	
	Sanitary Piping	Entire Building	158,325	SF	6	10+ years	
	Storm Piping	Entire Building	158,325	SF	6	10+ years	
	Vent Piping	Entire Building	158,325	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Boiler Room	2	EA	6	6-10 years	Elevator pit pump and boiler room

Category: Room **Building: Main**

categoi	y . 1100111		Bulluling : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
dministr	ative Suites/Offices									
	AC Unit	1st Floor-100 Main Office	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor-100 Main Office	400	SF	6	10+ years				
	Doors - Side-lite	1st Floor-100 Main Office	20	SF	6	6-10 years				
	Doors - Transom Window	1st Floor-100 Main Office	10	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st Floor-100 Main Office	1	EΑ	6	6-10 years				
	Floor - Carpet	1st Floor-100 Main Office	140	SF	6	6-10 years				
	Floor - Tile	1st Floor-100 Main Office	260	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st Floor-100 Main Office	6	EΑ	6	10+ years				
	Power Distribution	1st Floor-100 Main Office	10	EΑ	6	6-10 years				
	Storage/ Closet	1st Floor-100 Main Office	24	SF	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor-100 Main Office	2,000	SF	6	10+ years				
	AC Unit	1st Floor-102 Conference Room	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor-102 Conference Room	440	SF	6	10+ years				
	Doors - Transom Window	1st Floor-102 Conference Room	10	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st Floor-102 Conference Room	1	EA	6	6-10 years				
	Floor - Carpet	1st Floor-102 Conference Room	440	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st Floor-102 Conference Room	6	EA	6	10+ years				
	Power Distribution	1st Floor-102 Conference Room	16	EA	6	10+ years				
	Walls - Plaster/Drywall	1st Floor-102 Conference Room	1,170	SF	6	10+ years				
	AC Unit	1st Floor-Nurse's Office Suite	2	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor-Nurse's Office Suite	390	SF	6	6-10 years				
	Doors - Side-lite	1st Floor-Nurse's Office Suite	80	SF	6	6-10 years				
	Doors - Transom Window	1st Floor-Nurse's Office Suite	30	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st Floor-Nurse's Office Suite	3	EA	6	6-10 years				
	Floor - Tile	1st Floor-Nurse's Office Suite	390	SF	6	10+ years				

Campus Name: Penn Page : 8 of 37 Assessment Date: 10/27/2021





Catego	ry : Room		В	uilding	: Main		Toto o Avers Avervoe, officago, le 00025
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor-Nurse's Office Suite	6	EA	6	10+ years	
	Power Distribution	1st Floor-Nurse's Office Suite	10	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Nurse's Office Suite	1,940	SF	6	10+ years	
	AC Unit	1st Floor-Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Principal's Office	150	SF	6	10+ years	
	Doors - Side-lite	1st Floor-Principal's Office	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office	2	EΑ	6	6-10 years	
	Floor - Carpet	1st Floor-Principal's Office	150	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Principal's Office	1	EA	6	10+ years	
	Power Distribution	1st Floor-Principal's Office	8	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Principal's Office	580	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Kitchen Office	120	SF	6	10+ years	Portion of duct tape hanging off of
	, , , , , , , , , , , , , , , , , , ,					, , , , , ,	vent.
	Doors - Wood Doors inclu hw	Basement-Kitchen Office	1	EA	6	6-10 years	
	Floor - Tile	Basement-Kitchen Office	105	SF	7	6-10 years	
	Floor - Tile	Basement-Kitchen Office	15	SF	4	0-1 year	Missing
	Lighting - Pendent/Surface	Basement-Kitchen Office	2	ĒΑ	6	6-10 years	3
	Power Distribution	Basement-Kitchen Office	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement-Kitchen Office	428	SF	6	10+ years	
_Auditoriu	ım & Theater Balcony Seating	1st Floor	95	EA	7	6.10 years	
		1st Floor 1st Floor		SF		6-10 years	
	Ceiling - Plaster/Drywall		4,165		6	10+ years	
	Doors - Steel Doors incl hw Doors - Wood Doors inclu hw	1st Floor 1st Floor	3 8	EA EA	6 6	6-10 years	
		1st Floor 1st Floor		SF	_	6-10 years	
	Floor - Concrete Epoxy/ Painted Floor - Wood		1,036	SF SF	7	10+ years	
	Floor - Wood Floor - Wood	1st Floor 1st Floor	165	SF SF	6	10+ years	
			2,964		6	10+ years	
	Lighting - Pendent/Surface	1st Floor	25	EΑ	6	10+ years	
	Lighting - Wall Mounted	1st Floor	8	EΑ	6 7	10+ years	
	Main Floor Seating	1st Floor	576	EΑ	=	10+ years	
	Sound System	1st Floor 1st Floor	1 535	EA SF	7 6	10+ years	
	Stage Stage Curtain				_	6-10 years	
	Stage Curtain	1st Floor	10	EΑ	7	6-10 years	
	Stage Lighting System	1st Floor	1	EΑ	7	6-10 years	Drokon
	Stage Stairs Torrozza	1st Floor	1	EA LF	5 6	0-1 year	Broken.
	Stage-Stairs - Terrazzo	1st Floor	5	LF LF		10+ years	
	Stage-Stairs - Wood	1st Floor	10	LF LF	6	10+ years	
	Stairs - Asphalt	1st Floor	32		6	10+ years	
	Walls - Concrete Block	1st Floor	110	SF SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	9,180	5F	6	10+ years	
_Gymnas	ia						
,	Ceiling - Plaster/Drywall	3rd Floor	4,366	SF	6	10+ years	





Catego	ry : Room		В	uilding	: Main		Toto o Avers Avenoe, officago, le 60025
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	20	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	4,366	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	24	EA	7	10+ years	
	Scoreboards	3rd Floor	1	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	50	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5,203	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	020 - Basement warming kitchen	875	SF	6	10+ years	
	Doors - Wood Doors inclu hw	020 - Basement warming kitchen	1	EA	6	6-10 years	
	Floor - Tile	020 - Basement warming kitchen	875	SF	6	6-10 years	
	Lighting - Pendent/Surface	020 - Basement warming kitchen	20	EA	6	6-10 years	
	Walls - Masonry	020 - Basement warming kitchen	436	SF	6	10+ years	
	Walls - Plaster/Drywall	020 - Basement warming kitchen	1,000	SF	6	10+ years	
Library							
	AC Unit	1st Floor-117 Library	1	EA	7	6-10 years	
	Casework	1st Floor-117 Library	154	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-117 Library	1,500	SF	6	10+ years	
	Doors - Transom Window	1st Floor-117 Library	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor-117 Library	10	EA	6	6-10 years	
	Floor - Carpet	1st Floor-117 Library	1,500	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-117 Library	24	EA	6	10+ years	
	Storage/ Closet	1st Floor-117 Library	25	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-117 Library	2,210	SF	6	10+ years	
	Walls - Hastel/Diywall	13t 1001-117 Library	2,210	OI .	O	10+ years	
_Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement-014 Warming Kitchen/Lunchroom	2,106	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-014 Warming Kitchen/Lunchroom	2	EA	6	6-10 years	
	Floor - Tile	Basement-014 Warming	2,106	SF	6	6-10 years	
	Lighting - Pendent/Surface	Kitchen/Lunchroom Basement-014 Warming	40	EA	6	6-10 years	
		Kitchen/Lunchroom				-	
	Serving Line	Basement-014 Warming Kitchen/Lunchroom	16	LF	6	6-10 years	
	Walls - Concrete Block	Basement-014 Warming Kitchen/Lunchroom	100	SF	6	10+ years	
	Walls - Masonry	Basement-014 Warming Kitchen/Lunchroom	3,275	SF	6	10+ years	

Campus Name: Penn Page : 10 of 37 Assessment Date: 10/27/2021



Category : Room Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Basement-014 Warming Kitchen/Lunchroom	366	SF	6	10+ years	
_MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor-213 MDF Room	1	EA	6	6-10 years	
	Finishes	2nd Floor-213 MDF Room	212	SF	5	6-10 years	Flooring needs to be cleaned.
	Window AC Unit	2nd Floor-213 MDF Room	1	ĒΑ	7	6-10 years	3
						•	
_Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	15	SF	7	10+ years	
	Janitor's Closet	1st Floor	20	SF	5	10+ years	Water damage to walls around wall sink.
	Janitor's Closet	1st Floor	15	SF	5	10+ years	Painting required, insulation replacement required.
	Storage Room	1st Floor	10	SF	7	10+ years	
	Storage Room	1st Floor	25	SF	7	10+ years	
	Storage Room	1st Floor	30	SF	5	10+ years	
	Janitor's Closet	2nd Floor	48	SF	7	6-10 years	
	Janitor's Closet	2nd Floor	24	SF	5	6-10 years	Paint required.
	Mechanical/ Service Rooms	2nd Floor	94	SF	7	6-10 years	•
	Mechanical/ Service Rooms	2nd Floor	24	SF	7	6-10 years	
	Storage Room	2nd Floor	135	SF	7	6-10 years	
	Storage Room	2nd Floor	24	SF	7	6-10 years	
	Janitor's Closet	3rd Floor	15	SF	5	10+ years	Paint cracking and peeling throughout.
	Janitor's Closet	3rd Floor	15	SF	5	10+ years	Water damage to walls.
	Janitor's Closet	3rd Floor	15	SF	5	10+ years	Water damage to walls.
	Janitor's Closet	3rd Floor	15	SF	5	10+ years	Water damage to walls.
	Air Tunnel	Basement	150	SF	7	10+ years	<u> </u>
	Air Tunnel	Basement	210	SF	7	10+ years	
	Air Tunnel	Basement	1,500	SF	7	10+ years	
	Boiler Room	Basement	1,322	SF	7	10+ years	
	Coal Room	Basement	550	SF	7	10+ years	
	Janitor's Closet	Basement	8	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	159	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	560	SF	5	10+ years	2 SF of damage to floor.
	Storage Room	Basement	1,079	SF	7	6-10 years	
	Storage Room	Basement	490	SF	7	6-10 years	
	Storage Room	Basement	110	SF	7	6-10 years	
	Storage Room	Basement	430	SF	7	6-10 years	
	Storage Room	Basement	110	SF	5	6-10 years	Paint chipping and peeling.
Restroo	m						
	••						



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor-117 Library Restroom- Closed Unuseable	110	SF	5	0-1 year	Closed - unuseable.
	Ceiling - Plaster/Drywall	1st Floor-117 Library Restroom- Closed Unuseable	110	SF	6	0-1 year	Closed - unuseable.
	Doors - Wood Doors inclu hw	1st Floor-117 Library Restroom- Closed Unuseable	1	EA	6	0-1 year	Closed - unuseable.
	Floor - Terrazzo	1st Floor-117 Library Restroom- Closed Unuseable	110	SF	6	0-1 year	Closed - unuseable.
	Hand Dryer	1st Floor-117 Library Restroom- Closed Unuseable	1	EA	5	0-1 year	
	Lavatory	1st Floor-117 Library Restroom- Closed Unuseable	1	EA	6	0-1 year	
	Lighting - Pendent/Surface	1st Floor-117 Library Restroom- Closed Unuseable	1	EA	6	0-1 year	
	Partitions	1st Floor-117 Library Restroom- Closed Unuseable	2	EA	5	0-1 year	
	Walls - Plaster/Drywall	1st Floor-117 Library Restroom- Closed Unuseable	220	SF	6	0-1 year	
	Water Closet	1st Floor-117 Library Restroom- Closed Unuseable	2	EA	6	0-1 year	
	Accessories	1st Floor-Classroom 107 Restroom	115	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 107 Restroom	115	SF	6	10+ years	
	Doors - Side-lite	1st Floor-Classroom 107 Restroom	28	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 107 Restroom	1	EA	6	6-10 years	
	Floor - Tile	1st Floor-Classroom 107 Restroom	115	SF	6	6-10 years	
	Lavatory	1st Floor-Classroom 107 Restroom	113	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Classroom 107 Restroom	1	EA	6	6-10 years	
	Partitions	1st Floor-Classroom 107 Restroom	2	EA	7		
	Walls - Plaster/Drywall	1st Floor-Classroom 107 Restroom	350	SF	6	6-10 years	
	Water Closet	1st Floor-Classroom 107 Restroom		EA		10+ years	
		1st Floor-Classroom 107 Restroom	2 60	SF	6 7	6-10 years	
	Accessories		60	SF SF	7 7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 109 Restroom		EA		10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 109 Restroom	1		7	10+ years	
	Floor - Tile	1st Floor-Classroom 109 Restroom	60	SF	6	6-10 years	
	Lavatory	1st Floor-Classroom 109 Restroom	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Classroom 109 Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Classroom 109 Restroom	310	SF	7	10+ years	
	Water Closet	1st Floor-Classroom 109 Restroom	1	EA	7	6-10 years	
	Accessories	1st Floor-Classroom 115 Restroom	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 115 Restroom	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 115 Restroom	1	EA	6	6-10 years	
	Floor - Tile	1st Floor-Classroom 115 Restroom	45	SF	4	0-1 year	Cracking and separating.
	Lavatory	1st Floor-Classroom 115 Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Classroom 115 Restroom	2	EA	6	6-10 years	



	Category : Room			В	uilding	: Main		
Walls - Piaster/Drywall 1st Floor-Classroom 115 Restroom 165 SF 6 10+ years Waller Closel 1st Floor-Classroom 115 Restroom 1 EA 6 6-10 years Accessories 1st Floor-Classroom 115 Restroom 20 SF 7 6-10 years Ceiling - Plaster/Drywall 1st Floor-Main Office Restroom 20 SF 6 10+ years Floor - Tile 1st Floor-Main Office Restroom 1 EA 6 6-10 years Floor - Tile 1st Floor-Main Office Restroom 1 EA 6 6-10 years Lavatory 1st Floor-Main Office Restroom 1 EA 6 6-10 years Lighting - Wall Mounted 1st Floor-Main Office Restroom 1 EA 6 6-10 years Accessories 1st Floor-Main Office Restroom 165 SF 6 10+ years Accessories 1st Floor-Women's Staff Restroom 215 SF 6 10+ years Accessories 1st Floor-Women's Staff Restroom 1 EA 6 6-10 years					_			
Walls - Plaster/Drywall 1st Floor-Classroom 115 Restroom 50 SF 5 0-1 years Water Closel 1st Floor-Classroom 1 EA 6 6-10 years Accessories 1st Floor-Main Office Restroom 20 SF 7 6-10 years Doors - Wood Doors inclu hw 1st Floor-Main Office Restroom 1 EA 6 6-10 years Floor - Tille 1st Floor-Main Office Restroom 1 EA 6 6-10 years Lavatory 1st Floor-Main Office Restroom 1 EA 6 6-10 years Lavatory 1st Floor-Main Office Restroom 1 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor-Main Office Restroom 165 SF 6 10+ years Celling - Plaster/Drywall 1st Floor-Worner's Staff Restroom 216 SF 6 10+ years Celling - Plaster/Drywall 1st Floor-Worner's Staff Restroom 216 SF 6 10+ years Doors - Transom Window 1st Floor-Worner's Staff Restroom 15 SF 6	Group			Quantity		Rank		Comments
Water Closes			1st Floor-Classroom 115 Restroom					
Accessories 1st Floor-Main Office Restroom 20 SF 6 10 + years		Walls - Plaster/Drywall	1st Floor-Classroom 115 Restroom	50		5	0-1 year	Water damage and holes.
Ceiling - Plaster/Dywall		Water Closet	1st Floor-Classroom 115 Restroom	1			6-10 years	
Doors - Wood Doors inclu hw 1st Floor-Main Office Restroom		Accessories	1st Floor-Main Office Restroom	20		7	6-10 years	
Doors - Wood Doors inclu hw		Ceiling - Plaster/Drywall	1st Floor-Main Office Restroom	20	SF	6	10+ years	
Floor - Tile			1st Floor-Main Office Restroom	1	EA	6		
Lighting - Wall Mounted 1st Floor-Main Office Restroom 16 EA 6 10+ years		Floor - Tile	1st Floor-Main Office Restroom	20	SF	6		
Lighting - Wall Mounted 1st Floor-Main Office Restroom 165 SF 6 10+ years		Lavatory	1st Floor-Main Office Restroom	1	EA	6	6-10 years	
Walls - Plaster/Dywall		Lighting - Wall Mounted	1st Floor-Main Office Restroom	1	EA	6		
Accessories 1st Floor-Women's Staff Restroom 215 SF 7 6-10 years		Walls - Plaster/Drywall	1st Floor-Main Office Restroom	165	SF	6		
Ceiling - Plaster/Drywall 1st Floor-Women's Staff Restroom 215 SF 6 6-10 years 1-10 years 1-1			1st Floor-Women's Staff Restroom	215	SF			
Doors - Transom Window 1st Floor-Women's Staff Restroom 1		Ceiling - Plaster/Drywall	1st Floor-Women's Staff Restroom	215	SF	6		
Doors - Wood Doors inclu hw			1st Floor-Women's Staff Restroom					
Floor - Carpet								
Floor - Terrazzo							-	Fraving and not secured.
Layatory Lighting - Pendent/Surface 1st Floor-Women's Staff Restroom 2 EA 7 6-10 years Partitions 1st Floor-Women's Staff Restroom 2 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor-Women's Staff Restroom 1,135 SF 6 10+ years Water Closet 1st Floor-Women's Staff Restroom 1,135 SF 6 10+ years Water Closet 1st Floor-Women's Staff Restroom 2 EA Accessories 2 EA 6 6-10 years Accessories 2 Ind Floor-S Boy's Restroom 400 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-S Boy's Restroom 10 SF 6 6-10 years Doors - Transom Window 2nd Floor-S Boy's Restroom 10 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-S Boy's Restroom 10 SF 6 6-10 years Ploor - Tile Ceramic/ Porcelain 2nd Floor-S Boy's Restroom 1 EA 6 6-10 years Floor Drain 2nd Floor-S Boy's Restroom 1 EA 7 6-10 years Hand Dryer 2nd Floor-S Boy's Restroom 1 EA 7 6-10 years Layatory 2nd Floor-S Boy's Restroom 2 EA 7 6-10 years Layatory 2nd Floor-S Boy's Restroom 2 EA 7 6-10 years Layatory 2nd Floor-S Boy's Restroom 2 EA 7 6-10 years Dors - Wood Doors inclu hy 2nd Floor-S Boy's Restroom 2 EA 7 6-10 years Layatory 2nd Floor-S Boy's Restroom 2 EA 7 6-10 years Dors - Transom Window 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Dors - Volumen's Staff Restroom 3 EA 6 6-10 years Dors - Volumen's Staff Restroom 3 EA 6 6-10 years Dors - Volumen's Staff Restroom 3 EA 6 6-10 years Dors - Volumen's Staff Restroom 3 EA 6 6-10 years Doors - Transom Window 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years Doors - Transom Window 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Doors - Transom Window 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Ploor - Tile 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Ploor - Tile 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Ploor - Tile 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Ploor - Tile								· · · · · · · · · · · · · · · · · · ·
Lighting - Pendent/Surface								
Partitions 1st Floor-Women's Staff Restroom 2 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor-Women's Staff Restroom 1,135 SF 6 10+ years Accessories 2nd Floor-S Boy's Restroom 400 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-S Boy's Restroom 400 SF 7 6-10 years Doors - Transom Window 2nd Floor-S Boy's Restroom 10 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-S Boy's Restroom 1 EA 6 6-10 years Floor - Tile Ceramic/ Porcelain 2nd Floor-S Boy's Restroom 1 EA 7 6-10 years Floor Drain 2nd Floor-S Boy's Restroom 1 EA 7 6-10 years Hand Dryer 2nd Floor-S Boy's Restroom 2 EA 7 6-10 years Layatory 2nd Floor-S Boy's Restroom 2 EA 6 6-10 years Lighting - Pendent/Surface 2nd Floor-S Boy's Restroom 3 EA 6 6-10 year								
Walls - Plaster/Drywall 1st Floor-Women's Staff Restroom 2 EA 6 6-10 years Accessories 2nd Floor-S Boy's Restroom 400 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-S Boy's Restroom 400 SF 6 10+ years Doors - Transom Window 2nd Floor-S Boy's Restroom 10 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-S Boy's Restroom 10 SF 6 6-10 years Ploor - Tile Ceramic/ Porcelain 2nd Floor-S Boy's Restroom 1 EA 6 6-10 years Floor Drain 2nd Floor-S Boy's Restroom 1 EA 7 6-10 years Ploor Drain 2nd Floor-S Boy's Restroom 1 EA 7 6-10 years Ploor Drain 2nd Floor-S Boy's Restroom 1 EA 7 6-10 years Lavatory 2nd Floor-S Boy's Restroom 2 EA 7 6-10 years Lavatory 2nd Floor-S Boy's Restroom 2 EA 6 6-10 years Lighting - Pendent/Surface 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Urinals 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Urinals 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Urinals 2nd Floor-S Boy's Restroom 526 SF 6 10+ years Walls - Plaster/Drywall 2nd Floor-S Boy's Restroom 526 SF 6 10+ years Walls - Structural Glazed Tile 2nd Floor-S Boy's Restroom 738 SF 6 10+ years Accessories 2nd Floor-S Boy's Restroom 190 SF 7 6-10 years Accessories 2nd Floor-Women's Staff Restroom 190 SF 7 6-10 years Doors - Transom Window 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Plaster/Drywall 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 70 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 70 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 10 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 10 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 10 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 10 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 10 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 10 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 10 SF 6 6-10 years Ploor - Terrazzo 2nd Floor-Women's Staff Restroom 10 SF 6 6-10 years Ploor - Terra								
Water Closet1st Floor-Women's Staff Restroom2EA66-10 yearsAccessories2nd Floor-S Boy's Restroom400SF76-10 yearsCeiling - Plaster/Drywall2nd Floor-S Boy's Restroom400SF610+ yearsDoors - Wood Doors inclu hw2nd Floor-S Boy's Restroom10SF66-10 yearsPoor - Wood Doors inclu hw2nd Floor-S Boy's Restroom1EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor-S Boy's Restroom400SF66-10 yearsFloor Drain2nd Floor-S Boy's Restroom1EA76-10 yearsHand Dryer2nd Floor-S Boy's Restroom2EA76-10 yearsLayatory2nd Floor-S Boy's Restroom2EA66-10 yearsLighting - Pendent/Surface2nd Floor-S Boy's Restroom3EA66-10 yearsPartitions2nd Floor-S Boy's Restroom3EA66-10 yearsUrinals2nd Floor-S Boy's Restroom3EA66-10 yearsWalls - Plaster/Drywall2nd Floor-S Boy's Restroom526SF610+ yearsWater Closet2nd Floor-S Boy's Restroom3EA66-10 yearsAccessories2nd Floor-Women's Staff Restroom190SF76-10 yearsDoors - Transom Window2nd Floor-Women's Staff Restroom20SF66-10 yearsPoors - Tile2nd Floor-Women's Staff Restroom10SF <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>								
Accessories 2nd Floor-S Boy's Restroom 400 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-S Boy's Restroom 400 SF 6 10+ years Doors - Transom Window 2nd Floor-S Boy's Restroom 10 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-S Boy's Restroom 11 EA 6 6 6-10 years Floor - Tile Ceramic/ Porcelain 2nd Floor-S Boy's Restroom 400 SF 6 6-10 years Floor Drain 2nd Floor-S Boy's Restroom 1 EA 7 6-10 years Hand Dryer 2nd Floor-S Boy's Restroom 2 EA 6 6-10 years Lavatory 2nd Floor-S Boy's Restroom 2 EA 6 6-10 years Lighting - Pendent/Surface 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Partitions 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Urinals 2nd Floor-S Boy's Restroom 8 EA 6 6-10 years Walls - Plaster/Drywall 2nd Floor-S Boy's Restroom 8 EA 6 6-10 years Walls - Structural Glazed Tile 2nd Floor-S Boy's Restroom 738 SF 6 10+ years Water Closet 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Walter Closet 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Water Closet 2nd Floor-S Boy's Restroom 9 EA 6 6-10 years Accessories 2nd Floor-Women's Staff Restroom 190 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Floor - Terrazzo 2nd Floor-Women's Staff Restroom 70 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory is not functioning.				•				
Ceiling - Plaster/Drywall2nd Floor-S Boy's Restroom400SF610+ yearsDoors - Transom Window2nd Floor-S Boy's Restroom10SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor-S Boy's Restroom1EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor-S Boy's Restroom400SF66-10 yearsFloor Drain2nd Floor-S Boy's Restroom1EA76-10 yearsHand Dryer2nd Floor-S Boy's Restroom2EA66-10 yearsLavatory2nd Floor-S Boy's Restroom2EA66-10 yearsLighting - Pendent/Surface2nd Floor-S Boy's Restroom3EA66-10 yearsPartitions2nd Floor-S Boy's Restroom3EA76-10 yearsWalls - Plaster/Drywall2nd Floor-S Boy's Restroom3EA66-10 yearsWalls - Plaster/Drywall2nd Floor-S Boy's Restroom526SF610+ yearsWalls - Structural Glazed Tile2nd Floor-S Boy's Restroom3EA66-10 yearsAccessories2nd Floor-Women's Staff Restroom3EA66-10 yearsCeiling - Plaster/Drywall2nd Floor-Women's Staff Restroom190SF76-10 yearsDoors - Wood Doors inclu hw2nd Floor-Women's Staff Restroom2SF66-10 yearsFloor - Tile2nd Floor-Women's Staff Restroom12SF66-10 yearsLavatory2nd Floor-Wo								
Doors - Transom Window2nd Floor-S Boy's Restroom10SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor-S Boy's Restroom1EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor-S Boy's Restroom400SF66-10 yearsFloor Drain2nd Floor-S Boy's Restroom1EA76-10 yearsHand Dryer2nd Floor-S Boy's Restroom2EA76-10 yearsLavatory2nd Floor-S Boy's Restroom2EA66-10 yearsLighting - Pendent/Surface2nd Floor-S Boy's Restroom3EA66-10 yearsPartitions2nd Floor-S Boy's Restroom3EA76-10 yearsPartitions2nd Floor-S Boy's Restroom3EA76-10 yearsUrinals2nd Floor-S Boy's Restroom8EA66-10 yearsWalls - Plaster/Drywall2nd Floor-S Boy's Restroom738SF610+ yearsWalls - Structural Glazed Tile2nd Floor-S Boy's Restroom3EA66-10 yearsAccessories2nd Floor-Women's Staff Restroom3EA66-10 yearsCeiling - Plaster/Drywall2nd Floor-Women's Staff Restroom190SF610+ yearsDoors - Wood Doors inclu hw2nd Floor-Women's Staff Restroom20SF66-10 yearsFloor - Terrazzo2nd Floor-Women's Staff Restroom120SF66-10 yearsFloor - Tile2nd Floor-Women's Staff Restroom <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Doors - Wood Doors inclu hw2nd Floor-S Boy's Restroom1EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor-S Boy's Restroom400SF66-10 yearsFloor Drain2nd Floor-S Boy's Restroom1EA76-10 yearsHand Dryer2nd Floor-S Boy's Restroom2EA76-10 yearsLavatory2nd Floor-S Boy's Restroom2EA66-10 yearsLighting - Pendent/Surface2nd Floor-S Boy's Restroom3EA66-10 yearsPartitions2nd Floor-S Boy's Restroom3EA76-10 yearsUrinals2nd Floor-S Boy's Restroom8EA66-10 yearsWalls - Plaster/Drywall2nd Floor-S Boy's Restroom526SF610+ yearsWalls - Structural Glazed Tile2nd Floor-S Boy's Restroom738SF610+ yearsWater Closet2nd Floor-S Boy's Restroom3EA66-10 yearsAccessories2nd Floor-Women's Staff Restroom190SF76-10 yearsCeiling - Plaster/Drywall2nd Floor-Women's Staff Restroom20SF66-10 yearsDoors - Transom Window2nd Floor-Women's Staff Restroom2SF66-10 yearsFloor - Terrazzo2nd Floor-Women's Staff Restroom2SF66-10 yearsFloor - Tile2nd Floor-Women's Staff Restroom1EA40-1 yearsLavatory2nd Floor-Women's Staff Restroom1<			2nd Floor-S Boy's Restroom					
Floor - Tile Ceramic/ Porcelain Floor Drain 2nd Floor-S Boy's Restroom 2nd Floor-Women's Staff R			2nd Floor-S Boy's Restroom	_				
Floor Drain Hand Dryer And Floor-S Boy's Restroom And Dryer And Floor-S Boy's Restroom And Dryer And Floor-S Boy's Restroom And F								
Hand Dryer Lavatory 2nd Floor-S Boy's Restroom 2 EA Lighting - Pendent/Surface 2nd Floor-S Boy's Restroom 2 EA Lighting - Pendent/Surface 2nd Floor-S Boy's Restroom 3 EA Partitions 2nd Floor-S Boy's Restroom 3 EA Urinals 2nd Floor-S Boy's Restroom 3 EA BEA 6 6-10 years BEA 6 6-10 years BEA 6 6-10 years BEA 6 6-10 years BEA								
Lavatory 2nd Floor-S Boy's Restroom 2 EA 6 6-10 years Lighting - Pendent/Surface 2nd Floor-S Boy's Restroom 3 EA 7 6-10 years Partitions 2nd Floor-S Boy's Restroom 3 EA 7 6-10 years Urinals 2nd Floor-S Boy's Restroom 8 EA 6 6-10 years Walls - Plaster/Drywall 2nd Floor-S Boy's Restroom 526 SF 6 10+ years Walls - Structural Glazed Tile 2nd Floor-S Boy's Restroom 738 SF 6 10+ years Water Closet 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Accessories 2nd Floor-Women's Staff Restroom 190 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-Women's Staff Restroom 190 SF 6 10+ years Doors - Transom Window 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-Women's Staff Restroom 2 EA 6 6-10 years Floor - Terrazzo 2nd Floor-Women's Staff Restroom 70 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning. Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning.								
Lighting - Pendent/Surface 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years 2nd Floor-S Boy's Restroom 3 EA 7 6-10 years 2nd Floor-S Boy's Restroom 8 EA 6 6-10 years 2nd Floor-S Boy's Restroom 8 EA 6 6-10 years 2nd Floor-S Boy's Restroom 526 SF 6 10+ years 3 EA 6 6-10 years 4 EA 6 6-10 years 4 EA 6 6-10 years 5 EA 6 6-10 years 6 EA 6 6-10 years 6 EA 6 E			2nd Floor-S Boy's Restroom					
Partitions 2nd Floor-S Boy's Restroom 3 EA 7 6-10 years Urinals 2nd Floor-S Boy's Restroom 8 EA 6 6-10 years Walls - Plaster/Drywall 2nd Floor-S Boy's Restroom 526 SF 6 10+ years Walls - Structural Glazed Tile 2nd Floor-S Boy's Restroom 738 SF 6 10+ years Water Closet 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Accessories 2nd Floor-Women's Staff Restroom 190 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-Women's Staff Restroom 190 SF 6 10+ years Doors - Transom Window 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-Women's Staff Restroom 2 EA 6 6-10 years Floor - Terrazzo 2nd Floor-Women's Staff Restroom 70 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning. Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years			2nd Floor-S Boy's Restroom			_		
Urinals Walls - Plaster/Drywall 2nd Floor-S Boy's Restroom 3nd Floor-S Boy'								
Walls - Plaster/Drywall 2nd Floor-S Boy's Restroom 738 SF 6 10+ years Water Closet 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Accessories 2nd Floor-Women's Staff Restroom 190 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-Women's Staff Restroom 20 SF 6 10+ years Doors - Transom Window 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Floor - Terrazzo 2nd Floor-Women's Staff Restroom 2 EA 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning. Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years							•	
Walls - Structural Glazed Tile 2nd Floor-S Boy's Restroom 3 EA 6 6-10 years Accessories 2nd Floor-Women's Staff Restroom 190 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor-Women's Staff Restroom 190 SF 6 10+ years 7 6-10 years 8 7 6-10 years 9 9 8 7 6-10 years 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9							•	
Water Closet Accessories Accessories Ceiling - Plaster/Drywall Doors - Transom Window Floor-Women's Staff Restroom Doors - Terrazzo Floor-Women's Staff Restroom Floor-Women's Staff Restroom Doors - Terrazzo Accessories Acc								
Accessories Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor-Women's Staff Restroom Floor-Women's Staff Restroom Doors - Terrazzo Floor - Terrazzo Floor - Tile Lavatory Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom								
Ceiling - Plaster/Drywall 2nd Floor-Women's Staff Restroom 20 SF 6 10+ years Doors - Transom Window 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-Women's Staff Restroom 2nd Floor-Women's Staff								
Doors - Transom Window 2nd Floor-Women's Staff Restroom 20 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor-Women's Staff Restroom 2 EA 6 6-10 years Floor - Terrazzo 2nd Floor-Women's Staff Restroom 70 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning. Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years							-	
Doors - Wood Doors inclu hw 2nd Floor-Women's Staff Restroom 2 EA 6 6-10 years Floor - Terrazzo 2nd Floor-Women's Staff Restroom 70 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning. Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years								
Floor - Terrazzo 2nd Floor-Women's Staff Restroom 70 SF 6 6-10 years Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning. Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years				-				
Floor - Tile 2nd Floor-Women's Staff Restroom 120 SF 6 6-10 years Lavatory 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning. Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years								
Lavatory 2nd Floor-Women's Staff Restroom 1 EA 4 0-1 year Lavatory is not functioning. Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years							•	
Lighting - Pendent/Surface 2nd Floor-Women's Staff Restroom 3 EA 6 6-10 years							•	Lavatany is not functioning
								Lavalory is not functioning.
rannons zinu riooi-womens sian reshoom z EA / 0-10 years		• •						
		i aiuuoiis	ZHU FIOOI-WOHIEHS SIAH RESHOOM	2	ĽA	1	0-10 years	

Campus Name: Penn Page: 13 of 37 Assessment Date: 10/27/2021





Category : Room		В	uilding	: Main			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor-Women's Staff Restroom	850	SF	6	10+ years	
	Water Closet	2nd Floor-Women's Staff Restroom	2	EA	6	6-10 years	
	Accessories	2nd Floors-N Girl's Restroom	400	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floors-N Girl's Restroom	400	SF	7	10+ years	
	Doors - Transom Window	2nd Floors-N Girl's Restroom	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floors-N Girl's Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floors-N Girl's Restroom	400	SF	7	6-10 years	
	Floor Drain	2nd Floors-N Girl's Restroom	1	EA	7	6-10 years	
	Hand Dryer	2nd Floors-N Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	2nd Floors-N Girl's Restroom	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floors-N Girl's Restroom	3	EA	7	6-10 years	
	Partitions	2nd Floors-N Girl's Restroom	6	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floors-N Girl's Restroom	1,215	SF	7	10+ years	
	Water Closet	2nd Floors-N Girl's Restroom	6	EA	7	6-10 years	
	Accessories	2nd Floors-W Girl's Restroom	212	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floors-W Girl's Restroom	212	SF	6	10+ years	
	Doors - Transom Window	2nd Floors-W Girl's Restroom	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floors-W Girl's Restroom	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floors-W Girl's Restroom	212	SF	6	6-10 years	
	Floor Drain	2nd Floors-W Girl's Restroom	1	EA	7	6-10 years	
	Hand Dryer	2nd Floors-W Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	2nd Floors-W Girl's Restroom	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floors-W Girl's Restroom	3	EA	6	6-10 years	
	Partitions	2nd Floors-W Girl's Restroom	5	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floors-W Girl's Restroom	544	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floors-W Girl's Restroom	260	SF	6	6-10 years	
	Water Closet	2nd Floors-W Girl's Restroom	5	ĒA	6	6-10 years	
	Accessories	3rd Floor-Men's Staff Restroom	130	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor-Men's Staff Restroom	130	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor-Men's Staff Restroom	1	ĒΑ	6	6-10 years	
	Floor - Concrete	3rd Floor-Men's Staff Restroom	130	SF	7	10+ years	
	Floor Drain	3rd Floor-Men's Staff Restroom	1	ĒΑ	7	10+ years	
	Lavatory	3rd Floor-Men's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor-Men's Staff Restroom	2	EA	6	10+ years	
	Partitions	3rd Floor-Men's Staff Restroom	2	ΕA	7	6-10 years	
	Urinals	3rd Floor-Men's Staff Restroom	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor-Men's Staff Restroom	500	SF	6	10+ years	
	Water Closet	3rd Floor-Men's Staff Restroom	1	EA	6	6-10 years	
	Accessories	3rd Floor-N Girl's Restroom	400	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor-N Girl's Restroom	400	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor-N Girl's Restroom	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor-N Girl's Restroom	400	SF	6	10+ years	
	Floor Drain	3rd Floor-N Girl's Restroom	1	EA	7	6-10 years	
	Hand Dryer	3rd Floor-N Girl's Restroom	2	EA	7	6-10 years	
	Tana Diyor	ora ricor it care recomboni	2	_/\	,	o to yours	





Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	3rd Floor-N Girl's Restroom	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor-N Girl's Restroom	3	EA	6	10+ years	
	Partitions	3rd Floor-N Girl's Restroom	6	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor-N Girl's Restroom	385	SF	6	10+ years	
	Walls - Concrete Block	3rd Floor-N Girl's Restroom	100	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor-N Girl's Restroom	520	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor-N Girl's Restroom	210	SF	6	10+ years	
	Water Closet	3rd Floor-N Girl's Restroom	6	EA	6	6-10 years	
	Accessories	3rd Floor-S Boy's Restroom	400	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor-S Boy's Restroom	400	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor-S Boy's Restroom	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor-S Boy's Restroom	400	SF	6	10+ years	
	Floor Drain	3rd Floor-S Boy's Restroom	1	EA	7	6-10 years	
	Hand Dryer	3rd Floor-S Boy's Restroom	2	EΑ	7	6-10 years	
	Lavatory	3rd Floor-S Boy's Restroom	3	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor-S Boy's Restroom	3	EΑ	7	10+ years	
	Partitions	3rd Floor-S Boy's Restroom	3	EA	7	6-10 years	
	Urinals	3rd Floor-S Boy's Restroom	8	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor-S Boy's Restroom	100	SF	6	10+ years	
	Walls - Concrete Block	3rd Floor-S Boy's Restroom	385	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor-S Boy's Restroom	520	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor-S Boy's Restroom	252	SF	6	10+ years	
	Water Closet	3rd Floor-S Boy's Restroom	3	EA	6	6-10 years	
	Accessories	3rd Floor-W Girl's Restroom	212	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor-W Girl's Restroom	212	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor-W Girl's Restroom	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor-W Girl's Restroom	212	SF	6	10+ years	
	Floor Drain	3rd Floor-W Girl's Restroom	1	EA	7	6-10 years	
	Hand Dryer	3rd Floor-W Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	3rd Floor-W Girl's Restroom	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor-W Girl's Restroom	3	EA	7	10+ years	
	Partitions	3rd Floor-W Girl's Restroom	4	EA	7	6-10 years	
	Partitions	3rd Floor-W Girl's Restroom	1	EA	4	0-1 year	Broken partition
	Walls - Plaster/Drywall	3rd Floor-W Girl's Restroom	784	SF	6	10+ years	Broken paration
	Water Closet	3rd Floor-W Girl's Restroom	5	EA	6	6-10 years	
	Accessories	3rd Floor-Women's Staff Restroom	130	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor-Women's Staff Restroom	130	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor-Women's Staff Restroom	130	EA	6	6-10 years	
	Floor - Concrete	3rd Floor-Women's Staff Restroom	130	SF	5	10+ years	
	Floor Drain	3rd Floor-Women's Staff Restroom	130	EA	7	6-10 years	
	Lavatory	3rd Floor-Women's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor-Women's Staff Restroom	2	EA	7	10+ years	
	Partitions	3rd Floor-Women's Staff Restroom	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor-Women's Staff Restroom	500	SF	6	10+ years	
	vvalis - i lasici/Diywali	Sid i looi-women's Stan Nestidoni	300	JI	U	10+ years	





Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	3rd Floor-Women's Staff Restroom	2	EA	6	6-10 years	
	Accessories	Basement-Boy's Toilet	510	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Boy's Toilet	510	SF	6	10+ years	
	Doors - Side-lite	Basement-Boy's Toilet	9	SF	6	6-10 years	
	Doors - Transom Window	Basement-Boy's Toilet	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement-Boy's Toilet	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement-Boy's Toilet	510	SF	6	10+ years	
	Floor Drain	Basement-Boy's Toilet	1	EA	7	6-10 years	
	Hand Dryer	Basement-Boy's Toilet	2	EA	7	6-10 years	
	Lavatory	Basement-Boy's Toilet	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Boy's Toilet	6	EA	6	10+ years	
	Partitions	Basement-Boy's Toilet	3	EA	7	6-10 years	
	Urinals	Basement-Boy's Toilet	13	EA	6	6-10 years	
	Walls - Concrete Block	Basement-Boy's Toilet	65	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement-Boy's Toilet	956	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement-Boy's Toilet	205	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement-Boy's Toilet	5	SF	4	0-1 year	Missing.
	Water Closet	Basement-Boy's Toilet	3	EA	6	6-10 years	
	Accessories	Basement-Girl's Restroom	500	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Girl's Restroom	500	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Girl's Restroom	4	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement-Girl's Restroom	500	SF	6	10+ years	
	Floor Drain	Basement-Girl's Restroom	1	EA	7	6-10 years	
	Hand Dryer	Basement-Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	Basement-Girl's Restroom	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Girl's Restroom	9	EΑ	6	6-10 years	
	Partitions	Basement-Girl's Restroom	2	EA	7	6-10 years	
	Partitions	Basement-Girl's Restroom	12	EA	7	6-10 years	
	Walls - Concrete Block	Basement-Girl's Restroom	125	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Girl's Restroom	1,115	SF	6	10+ years	
	Water Closet	Basement-Girl's Restroom	14	EA	6	6-10 years	
	Accessories	Basement-Teacher's Lounge/Restroom	225	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Teacher's Lounge/Restroom	225	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement-Teacher's Lounge/Restroom	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement-Teacher's Lounge/Restroom	225	SF	6	6-10 years	
	Floor Drain	Basement-Teacher's Lounge/Restroom	1	EA	7	6-10 years	
	Lavatory	Basement-Teacher's Lounge/Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Teacher's	2	EA	6	6-10 years	

Campus Name: Penn Page : 16 of 37 Assessment Date: 10/27/2021





Catego	ry : Room		В	uilding	: Main		1010 3 AVEIS AVENUE, CHICAGO, IL 00023
22.090						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Lounge/Restroom					
	Walls - Concrete Block	Basement-Teacher's	42	SF	6	10+ years	
		Lounge/Restroom					
	Walls - Plaster/Drywall	Basement-Teacher's	796	SF	6	10+ years	
	W (0)	Lounge/Restroom	•	_^	•	40	
	Water Closet	Basement-Teacher's	1	EA	6	10+ years	
		Lounge/Restroom					
Catego	ry : Classroom		В	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #007 (Store Room)						
	Casework	Basement	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	945	SF	6	10+ years	
	Chalk Board	Basement	45	LF	4	2-5 years	
	Doors - Steel Doors incl hw	Basement	2	EA	6	6-10 years	
	Floor - Wood	Basement	945	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement	21	EA	6	10+ years	
	Walls - Concrete Block	Basement	345	SF	6	10+ years	
	Walls - Masonry	Basement	875	SF	6	10+ years	
Classroo	om #008 (Regular Classroom)						
	Casework	Basement	20	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	950	SF	6	10+ years	
	Chalk Board	Basement	6	LF	4	2-5 years	
	Doors - Steel Doors incl hw	Basement	1	EA	6	6-10 years	
	Floor - Wood	Basement	950	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement	21	EA	6	6-10 years	
	Walls - Masonry	Basement	1,000	SF	6	10+ years	
	Walls - Masonly Walls - Plaster/Drywall	Basement	305	SF	6	10+ years	
01	•					•	
_Classroo	om #010 (Regular Classroom)	Decement				0.40	
	Casework	Basement	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	950	SF	6	10+ years	
	Chalk Board	Basement	45	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	6-10 years	
	Floor - Wood	Basement	950	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	21	EA	6	6-10 years	
	Walls - Masonry	Basement	1,300	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	175	SF	6	10+ years	
Classroo	om #011 (Regular Classroom)						
	Casework	Basement	8	LF	6	6-10 years	

Campus Name: Penn Page : 17 of 37 Assessment Date: 10/27/2021



Catego	ry : Classroom	_	В	uilding	: Main	-	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement	925	SF	6	10+ years	Paint chipping and peeling.
	Chalk Board	Basement	44	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	6-10 years	
	Floor - Wood	Basement	925	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	21	EA	6	10+ years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Walls - Masonry	Basement	1,310	SF	6	10+ years	
Classroo	om #015 (Computer Lab)						
	Ceiling - Plaster/Drywall	Basement	940	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	6	6-10 years	
	Floor - Tile	Basement	940	SF	4	0-1 year	Cracked tiles and bubbling flooring
	Lighting - Pendent/Surface	Basement	21	EA	6	10+ years	Gracitod thos and Sassing hosting
	Marker Board	Basement	8	LF	7	6-10 years	
	Walls - Masonry	Basement	455	SF	6	10+ years	Paint chipping and peeling.
	Walls - Plaster/Drywall	Basement	845	SF	6	10+ years	i aint chipping and peeiing.
	Walls - Plaster/Drywall	Basement	30	SF	5		Plantar panal missing, evaponed pipes
	·		30		-	0-1 year	Plaster panel missing, exposed pipes and wiring.
	Wireless System	Basement	1	EA	7	6-10 years	
Classroo	om #017 (Other Instructional Use)						
	Casework	Basement	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	915	SF	6	10+ years	
	Chalk Board	Basement	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	6-10 years	
	Floor - Wood	Basement	910	SF	6	10+ years	
	Floor - Wood	Basement	5	SF	4	0-1 year	Wood bubbling up, some pieces
	11001 11000	Dassinon	ŭ	0.		o i you.	completely loose.
	Lighting - Pendent/Surface	Basement	21	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,375	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	6-10 years	
Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,015	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	20	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,015	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	23	EA	6	6-10 years	
	Storage/ Closet	1st Floor	23 6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,405	SF SF	, 6	10+ years	
	vvaus - Piasiei/LityWall	ISLEIOOF	7 405	>-	n		

Campus Name: Penn Page : 18 of 37 Assessment Date: 10/27/2021





Catego	ry : Classroom		В	uilding	: Main		
0	H T		2	11011	D	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #103 (Regular Classroom)						
21000100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	805	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	6-10 years	
	Floor - Wood Doors inclu riw	1st Floor	805	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor		EA	6	6-10 years	
	Storage/ Closet	1st Floor	20 15	SF	7		
						6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,530	SF	6	10+ years	
lassroo	m #104 (Office)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	810	SF	6	10+ years	
	Chalk Board	1st Floor	25	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	810	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	10+ years	
	Storage/ Closet	1st Floor	15	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,530	SF	6	10+ years	
Classroo	m #105 (Regular Classroom)						
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,150	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	1,150	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	5	0-1 year	Cover falling off and lights do not
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	work.
	Walls - Plaster/Drywall	1st Floor	2,680	SF	6	10+ years	
	·		•			•	
Classroo	m #106 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,015	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	27	SF	6	6-10 years	





Catego	ry : Classroom		R	uilding	· Main		10 10 3 AVEIS AVENUE, Chicago, IL 00023
Calego	iy . Classioolii			unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	Comments
	Floor - Wood	1st Floor	1,015	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EA	6	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,405	SF	6	10+ years	
	Walls - Flaster/Drywall	13(1100)	2,403	Si	O	10+ years	
Classroo	om #107 (Kindergarten)						
	Casework	1st Floor	16	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	890	SF	6	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	890	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,650	SF	6	10+ years	
	walls Tlaster/Drywall	13(1100)	1,000	O.	O	101 years	
Classroo	om #108 (Regular Classroom)						
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,150	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,150	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EA	6	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,880	SF	6	10+ years	
Classroo	om #109 (Pre School)						
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	825	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	6-10 years	
	Floor - Wood	1st Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	_	SF	6		
	vvalis - Flastel/Diywall	12f LI00l	1,710	SF	O	10+ years	
Classroo	om #110 (Office)						
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	890	SF	6	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
						-	

Campus Name: Penn Page : 20 of 37 Assessment Date: 10/27/2021





Catego	ry : Classroom		В	uilding	: Main		1010 0 AVCIS AVENUE, Officago, IE 00025
Juligo	. ,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	890	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,650	SF	6	10+ years	
01							
_Classroc	om #111 (Pre School)	4-4-51				0.40	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	840	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,700	SF	6	10+ years	
Classroo	nm #112 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
	Chalk Board	1st Floor	12	ĹF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	1st Floor	870	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	10+ years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,760	SF	6	10+ years	
Classes							
_Ciassioc	om #114 (Office)	1st Floor	0	LF	6	6 10 40000	
	Casework	1st Floor 1st Floor	8	SF	6	6-10 years	
	Ceiling - Plaster/Drywall		935	SF LF	6	10+ years	
	Chalk Board	1st Floor	20		4	2-5 years	
	Doors - Transom Window	1st Floor 1st Floor	10	SF EA	6	6-10 years	
	Doors - Wood Doors inclu hw		•		6	6-10 years	
	Floor - Wood	1st Floor	935	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,760	SF	6	10+ years	





Catego	ry : Classroom		R	uilding	· Main		1616 S Avers AVENUE, Chicago, IL 60623
Calego	iy . Classiooni			unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	om #115 (Pre School)	Location	Quantity	OOM	Italik	Replacement	Comments
Classro	,	4 at Ela an	40			0.40	
	Casework	1st Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	890	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	890	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,750	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #118 (Regular Classroom)						
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	825	SF	6	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	6-10 years	
	Floor - Wood	1st Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,125	SF	6	10+ years	
	•		,			j	
Classro	om #120 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	26	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,650	SF	7	10+ years	
Classro	om #200 (Regular Classroom)						
OIGSSI (I	Casework	2nd Floor	6	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	Chalk Board	2nd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
				_			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	825	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	23	EA	6	6-10 years	





Recommend	Catego	ry : Classroom		В	uilding	: Main		•
	Ju.090	. ,					Recommend	
Walls - Plaster/Drywall 2nd Floor 1,242 SF 6 10+ years	Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	O. Cup							
Ceiling - Plaster/Dywall		Walle Flactor/Bry Wall	2110 1 1001	.,	O.	Ü	ioi youio	
Ceiling - Plaster/Dywall	Classroo	om #201 (Special Education)						
Chalk Board 2nd Floor 36 LF 4 2.5 years Doors - Steel Doors incl hw 2nd Floor 1 EA 6 6-10 years Doors - Transom Window 2nd Floor 20 SF 6 6-10 years Ploor - Wood Doors inclu hw 2nd Floor 20 SF 6 6-10 years Ploor - Wood Doors inclu hw 2nd Floor 22 SF 6 6-10 years Ploor - Wood 2nd Floor 23 EA 6 6-10 years Ploor - Wood 2nd Floor 23 EA 6 6-10 years Ploors Walls - Plaster/Drywall 2nd Floor 23 EA 6 6-10 years Plaster/Drywall 2nd Floor 23 EA 6 6-10 years Plaster/Drywall 2nd Floor 20 EA 2 SF 6 10+ years Plaster/Drywall 2nd Floor 3nd Floor			2nd Floor	825	SF	6	10+ vears	
Doors - Steel Doors ind hw					_		•	
Doors - Transom Window 2nd Floor 20 SF							,	
Doors - Wood Doors inclu hw 2nd Floor 1								
Floor - Wood 2nd Floor 825 SF 6 10+ years 1,242 SF 10+ years 1,				1	_	-		
Lighting - Pendent/Surface 2nd Floor 1,242 SF 6 10+ years Iassroom #203 (Regular Classroom)				825				
Section Sect								
Casework							•	
Casework				.,			, , , , , , , , , , , , , , , , , , , ,	
Ceiling - Plaster/Drywall	Classroo	om #203 (Regular Classroom)						
Chalk Board		Casework	2nd Floor	8	LF	6	6-10 years	
Doors - Transom Window		Ceiling - Plaster/Drywall	2nd Floor	675	SF	6	10+ years	
Doors - Wood Doors inclu hw		Chalk Board	2nd Floor	20		4	2-5 years	
Floor - Wood		Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
Lighting - Pendent/Surface 2nd Floor 21		Doors - Wood Doors inclu hw	2nd Floor			6	6-10 years	
Storage / Closet 2nd Floor 36 SF 7 6-10 years				675		6	10+ years	
Alassroom #204 (Regular Classroom)		Lighting - Pendent/Surface	2nd Floor	21		6	6-10 years	
Asstroom #204 (Regular Classroom)		Storage/ Closet	2nd Floor	36		7	6-10 years	
Casework 2nd Floor 8 LF 6 6-10 years Ceiling - Plaster/Drywall 2nd Floor 675 SF 6 10+ years Chalk Board 2nd Floor 16 LF 4 2-5 years Doors - Transom Window 2nd Floor 10 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 675 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 18 EA 6 6-10 years Walls - Plaster/Drywall 2nd Floor 1,236 SF 6 10+ years Ceiling - Splined 2nd Floor 1,150 SF 6 6-10 years Ceiling - Splined 2nd Floor 1 EA 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 1 EA 6 6-10 years Lighting - Pendent/Surface 2nd Floor 1,150 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 23 EA 6 6-10 years Marker Board 2nd Floor 16 LF 6 6-10 years <td></td> <td>Walls - Plaster/Drywall</td> <td>2nd Floor</td> <td>1,236</td> <td>SF</td> <td>6</td> <td>10+ years</td> <td></td>		Walls - Plaster/Drywall	2nd Floor	1,236	SF	6	10+ years	
Casework 2nd Floor 8 LF 6 6-10 years Ceiling - Plaster/Drywall 2nd Floor 675 SF 6 10+ years Chalk Board 2nd Floor 16 LF 4 2-5 years Doors - Transom Window 2nd Floor 10 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 675 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 18 EA 6 6-10 years Walls - Plaster/Drywall 2nd Floor 1,236 SF 6 10+ years Ceiling - Splined 2nd Floor 1,150 SF 6 6-10 years Ceiling - Splined 2nd Floor 1 EA 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 1 EA 6 6-10 years Lighting - Pendent/Surface 2nd Floor 1,150 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 23 EA 6 6-10 years Marker Board 2nd Floor 16 LF 6 6-10 years <td>Classins</td> <td>urs #204 (Barrular Classical)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Classins	urs #204 (Barrular Classical)						
Ceiling - Plaster/Drywall 2nd Floor 675 SF 6 10+ years	Classroc	` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `	2nd Floor	0			C 10	
Chalk Board 2nd Floor 16 LF 4 2-5 years Doors - Transom Window 2nd Floor 10 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 18 EA 6 6-10 years Lighting - Pendent/Surface 2nd Floor 18 EA 6 6-10 years Walls - Plaster/Drywall 2nd Floor 1,236 SF 6 10+ years Casework 2nd Floor 1,150 SF 6 6-10 years Ceiling - Splined 2nd Floor 1,150 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 1,150 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 1,150 SF 6 10+ years Marker Board 2nd Floor 23 EA 6 6-10 years								
Doors - Transom Window						-		
Doors - Wood Doors inclu hw Floor - Wood Floor - Wood Floor - Wood Lighting - Pendent/Surface Floor - Wolf - Plaster/Drywall Casework Ceiling - Splined Doors - Wood Doors inclu hw Floor - Wood Doors - Wood Doors inclu hw Floor - Wood Floor - Wood Doors inclu hw Floor - Wood Floor - Wood - You Floor Floor - Wood - You Floor Lighting - Pendent/Surface Marker Board Marker Board Walls - Plaster/Drywall Plaster/Drywall Plaster/Drywall Plaster/Drywall Plaster/Drywall Plaster/Drywall Plaster/Drywall Plack 6 6-10 years 6 6-10 years 6 6-10 years 6 6-10 years 7 1 EA 6 6-10 years 7 1 EA 6 6-10 years 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							•	
Floor - Wood					_	-		
Lighting - Pendent/Surface 2nd Floor 1,236 SF 6 10+ years Walls - Plaster/Drywall 2nd Floor 1,236 SF 6 10+ years Casework 2nd Floor 6 LF 6 6-10 years Ceiling - Splined 2nd Floor 1,150 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 1,150 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 23 EA 6 6-10 years Marker Board 2nd Floor 16 LF 6 6-10 years Walls - Plaster/Drywall 2nd Floor 2,880 SF 6 10+ years				•		-		
Walls - Plaster/Drywall 2nd Floor 1,236 SF 6 10+ years Classroom #205 (Regular Classroom) 2nd Floor 6 LF 6 6-10 years Casework 2nd Floor 1,150 SF 6 6-10 years Ceiling - Splined 2nd Floor 1 EA 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 1,150 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 23 EA 6 6-10 years Marker Board 2nd Floor 16 LF 6 6-10 years Walls - Plaster/Drywall 2nd Floor 2,880 SF 6 10+ years							•	
Casework 2nd Floor 6							,	
Casework 2nd Floor 6 LF 6 6-10 years Ceiling - Splined 2nd Floor 1,150 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 1,150 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 23 EA 6 6-10 years Marker Board 2nd Floor 16 LF 6 6-10 years Walls - Plaster/Drywall 2nd Floor 2,880 SF 6 10+ years		Walls - Plaster/Drywall	2nd Floor	1,236	SF	6	10+ years	
Casework 2nd Floor 6 LF 6 6-10 years Ceiling - Splined 2nd Floor 1,150 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 6-10 years Floor - Wood 2nd Floor 1,150 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 23 EA 6 6-10 years Marker Board 2nd Floor 16 LF 6 6-10 years Walls - Plaster/Drywall 2nd Floor 2,880 SF 6 10+ years	Classroo	om #205 (Regular Classroom)						
Ceiling - Splined2nd Floor1,150SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor1EA66-10 yearsFloor - Wood2nd Floor1,150SF610+ yearsLighting - Pendent/Surface2nd Floor23EA66-10 yearsMarker Board2nd Floor16LF66-10 yearsWalls - Plaster/Drywall2nd Floor2,880SF610+ years		` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `	2nd Floor	6	LF	6	6-10 years	
Doors - Wood Doors inclu hw2nd Floor1EA66-10 yearsFloor - Wood2nd Floor1,150SF610+ yearsLighting - Pendent/Surface2nd Floor23EA66-10 yearsMarker Board2nd Floor16LF66-10 yearsWalls - Plaster/Drywall2nd Floor2,880SF610+ years								
Floor - Wood 2nd Floor 1,150 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 23 EA 6 6-10 years Marker Board 2nd Floor 16 LF 6 6-10 years Walls - Plaster/Drywall 2nd Floor 2,880 SF 6 10+ years		Doors - Wood Doors inclu hw		1				
Lighting - Pendent/Surface 2nd Floor 23 EA 6 6-10 years Marker Board 2nd Floor 16 LF 6 6-10 years Walls - Plaster/Drywall 2nd Floor 2,880 SF 6 10+ years				1.150				
Marker Board 2nd Floor 16 LF 6 6-10 years Walls - Plaster/Drywall 2nd Floor 2,880 SF 6 10+ years								
Walls - Plaster/Drywall 2nd Floor 2,880 SF 6 10+ years								
lassroom #206 (Regular Classroom)								
lassroom #206 (Regular Classroom)		·					-	
	Classroc	om #206 (Regular Classroom)						





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	23	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
Classroo	m #207 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	6-10 years	
	Floor - Tile	2nd Floor	825	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
	walls - Flaster/Drywall	2110 1 1001	1,242	OI.	O	10+ years	
Classroo	m #208 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	900	SF	6	10+ years	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	800	SF	6	6-10 years	
	Floor - Tile	2nd Floor	100	SF	4	0-1 year	Missing tile
	Lighting - Pendent/Surface	2nd Floor	23	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,318	SF	6	10+ years	
Classroo	m #209 (Special Education)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	Chalk Board	2nd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	4	0-1 year	Missing glass
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	3 3.000
	Floor - Wood	2nd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	18	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
Classroo	m #210 (Regular Classroom)						
ClassiUU	Casework	2nd Floor	0	LF	6	6-10 years	
			8		6		
	Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	





Catego	ry : Classroom		R	uilding	· Main		1010 S Avers Avenue, Chicago, iL 00023
Juliogo	, , , , , , , , , , , , , , , , , , ,			anamg	· wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
_Classroo	om #211 (Special Education)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	900	SF	6	10+ years	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	6-10 years	
	Floor - Wood	2nd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,318	SF	6	10+ years	
_Classroo	om #212 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
_Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	900	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,318	SF	6	10+ years	
Classroo	om #215 (Science)						
	Casework	2nd Floor	34	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	825	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	6	6-10 years	





Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Eye Wash Station	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	6-10 years	
lassroc	m #217 (Computer Lab)						
JIGGGIOC	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	Chalk Board			LF	_		
	Doors - Steel Doors incl hw	2nd Floor	36		4	2-5 years	
		2nd Floor	1	EA	6	6-10 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Floor - Wood	2nd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroc	m #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
Classroc	m #220 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	825	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	6-10 years	
	Floor - Wood Books including	2nd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor		LF			
			16	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,242	SF	6	10+ years	
lassroc	m #300 (Regular Classroom)						

Campus Name: Penn Page : 26 of 37 Assessment Date: 10/27/2021





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
Classroo	m #301 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	6-10 years	
	Floor - Wood	3rd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EΑ	7	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
	·	014 1 1001	1,212	O.	Ü	101 youro	
Classroo	m #303 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	675	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	675	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	18	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,236	SF	6	10+ years	
Classroo	m #304 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	675	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	3rd Floor	675	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,236	SF	6	10+ years	
lacoroa	m #305 (Regular Classroom)						

Campus Name: Penn Page : 27 of 37 Assessment Date: 10/27/2021





Catego	ry : Classroom		R	uilding	· Main		1010 3 AVEIS AVENUE, CHICAGO, IL 00023
Outogo	1 y . Oldoor oom			ananig	· Wall	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	7	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	900	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	195	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,318	SF	6	10+ years	
Classroo	om #306 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	825	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
Classroo	om #307 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	6-10 years	
	Floor - Wood	3rd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	900	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,318	SF	6	10+ years	
_Classroo	om #309 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	3 <u> ,</u>	 -	3-0		-	- ,	





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
_Classroo	om #310 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	6-10 years	
	Floor - Wood	3rd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
Classroo	om #311 (Regular Classroom)						
Classice	Casework	3rd Floor	8	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	900	SF	6	•	
	Chalk Board	3rd Floor	12	LF	4	10+ years 2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	9	EA	6		
	Floor - Wood Doors Inclu hw	3rd Floor 3rd Floor	900	SF	6	6-10 years	
				EA	-	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	LF	7	10+ years	
	Marker Board	3rd Floor	16	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,318	5F	6	10+ years	
Classroo	om #312 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
Classroo	om #314 (Regular Classroom)						

Campus Name: Penn Page : 29 of 37 Assessment Date: 10/27/2021





			Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	16	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	900	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,318	SF	6	10+ years	
Classroc	om #315 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	•	
			•	SF	6	6-10 years	
	Floor - Wood	3rd Floor	825			10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
Classroc	om #317 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
	Wireless System	3rd Floor	1,242	EA	7	10+ years	
Classror	om #318 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	025	EA	6	6-10 years	
	Floor - Wood Doors inclu hw		825	SF	6	-	
		3rd Floor				10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years	
	om #320 (Regular Classroom)						

Campus Name: Penn Page : 30 of 37 Assessment Date: 10/27/2021



Catego	ry : Classroom		Building : Main						
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Casework	3rd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	825	SF	6	10+ years			
	Chalk Board	3rd Floor	8	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years			
	Floor - Wood	3rd Floor	825	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	7	10+ years			
	Marker Board	3rd Floor	16	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,242	SF	6	10+ years			

Category : Interior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	6,668	SF	6	10+ years	
	Doors - Hardware	1st Floor	4	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	6-10 years	
	Floor - Asphalt Floor	1st Floor	3,372	SF	6	10+ years	
	Floor - Terrazzo	1st Floor	1,200	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	2,096	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EΑ	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	17,000	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	6,668	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Asphalt Floor	2nd Floor	2,372	SF	6	10+ years	
	Floor - Terrazzo	2nd Floor	1,200	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,046	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	50	SF	4	0-1 year	Missing tiles
	Lighting - Lay-in	2nd Floor	2	EΑ	6	6-10 years	•
	Lighting - Pendent/Surface	2nd Floor	83	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	17,000	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	6,668	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	2	EΑ	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EΑ	7	6-10 years	
	Floor - Asphalt Floor	3rd Floor	2,372	SF	6	10+ years	
	Floor - Terrazzo	3rd Floor	1,200	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	3,096	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	27	EΑ	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	17,000	SF	6	10+ years	
	Ceiling - Exposed	Basement	3,445	SF	6	10+ years	
	Ceiling - Exposed	Basement	25	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	6	6-10 years	
	Doors - Wood Doors include hw	Basement	12	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	Basement	10	EA	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	Basement	3,172	SF	7	6-10 years	
	1 lost Controlo Epoxy/ I dilitod	Zadomont	5,172	0.	•	J 10 yours	

Campus Name: Penn Page : 31 of 37 Assessment Date: 10/27/2021





Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	Basement	86	SF	6	10+ years	
	Floor - Tile Quarry	Basement	212	SF	6	6-10 years	
	Lighting - Lay-in	Basement	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	54	EA	6	6-10 years	
	Stairs - Concrete Stairs	Basement	12	LF	6	6-10 years	
	Walls - Concrete Block	Basement	874	SF	6	10+ years	
	Walls - Masonry	Basement	3,176	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	2,593	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	3	SF	5	0-1 year	Hole through wall
	Walls - Structural Glazed Tile	Basement	525	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	35	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Assembly Hall Stair	165	SF	6	10+ years	
	Floor - Concrete	Assembly Hall Stair	66	SF	7	10+ years	
	Floor - Terrazzo	Assembly Hall Stair	45	SF	6	10+ years	
	Handrails	Assembly Hall Stair	32	LF	7	10+ years	
	Lighting - Pendent/Surface	Assembly Hall Stair	2	EA	6	1-2 years	
	Stairs - Concrete	Assembly Hall Stair	4	LF	6	10+ years	
	Stairs - Terrazzo	Assembly Hall Stair	10	LF	6	10+ years	
	Walls - Plaster/Drywall	Assembly Hall Stair	1,150	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Central Stair	250	SF	6	10+ years	
	Floor - Asphalt	Central Stair	16	SF	6	10+ years	
	Handrails	Central Stair	18	LF	7	6-10 years	
	Lighting - Pendent/Surface	Central Stair	2	EA	6	6-10 years	
	Lighting - Wall Mounted	Central Stair	2	EA	6	6-10 years	
	Stairs - Asphalt	Central Stair	145	LF	6	6-10 years	
	Walls - Plaster/Drywall	Central Stair	900	SF	6	10+ years	
	Ceiling - Plaster/Drywall	NE Stair	710	SF	6	10+ years	
	Floor - Tile Quarry	NE Stair	60	SF	6	10+ years	
	Handrails	NE Stair	270	LF	7	6-10 years	
	Lighting - Lay-in	NE Stair	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	NE Stair	4	EA	6	6-10 years	
	Lighting - Wall Mounted	NE Stair	2	EA	6	6-10 years	
	Stairs - Concrete	NE Stair	24	LF	6	10+ years	
	Stairs - Terrazzo	NE Stair	432	LF	6	10+ years	
	Walls - Plaster/Drywall	NE Stair	1,300	SF	6	10+ years	
	Ceiling - Plaster/Drywall	NW Stair	710	SF	6	10+ years	
	Floor - Asphalt	NW Stair	432	SF	6	10+ years	
	Handrails	NW Stair	270	LF	7	6-10 years	
	Lighting - Lay-in	NW Stair	2	ĒΑ	6	6-10 years	
	· ·				-	,	



Catego	ry : Interior		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	NW Stair	4	EA	6	6-10 years	
	Lighting - Wall Mounted	NW Stair	2	EA	6	6-10 years	
	Stairs - Asphalt	NW Stair	84	LF	6	10+ years	
	Walls - Plaster/Drywall	NW Stair	3,000	SF	6	10+ years	
	Ceiling - Plaster/Drywall	SE Stair	710	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	SE Stair	144	SF	7	10+ years	
	Floor - Terrazzo	SE Stair	288	SF	6	10+ years	
	Floor - Tile Quarry	SE Stair	144	SF	6	10+ years	
	Handrails	SE Stair	270	LF	7	10+ years	
	Lighting - Lay-in	SE Stair	2	EA	6	10+ years	
	Lighting - Pendent/Surface	SE Stair	2	EA	6	10+ years	
	Lighting - Wall Mounted	SE Stair	2	EA	6	10+ years	
	Stairs - Asphalt	SE Stair	6	LF	6	10+ years	
	Stairs - Terrazzo	SE Stair	78	LF	6	10+ years	
	Walls - Plaster/Drywall	SE Stair	1,300	SF	6	10+ years	
	Ceiling - Plaster/Drywall	SW Stair	710	SF	6	10+ years	
	Floor - Asphalt	SW Stair	144	SF	6	10+ years	
	Floor - Asphalt	SW Stair	84	SF	6	10+ years	
	Handrails	SW Stair	270	LF	7	10+ years	
	Lighting - Lay-in	SW Stair	2	EA	6	10+ years	
	Lighting - Pendent/Surface	SW Stair	2	EA	6	10+ years	
	Lighting - Wall Mounted	SW Stair	8	EA	6	10+ years	
	Stairs - Asphalt	SW Stair	288	LF	6	10+ years	
	Walls - Plaster/Drywall	SW Stair	3,000	SF	6	10+ years	
<u>Vertical</u>	Conveyance						
	Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	1	EA	6	10+ years	Flooring needs to be repaired, missing.

Campus Name: Penn Page: 33 of 37 Assessment Date: 10/27/2021



Category : Site Building : Site

Catego	ry : Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	6	10+ years	
						, , , , , ,	
Fencing							
	Fencing - Chain Link	Entire Site	100	LF	6	10+ years	Does not exist, construction fencing
	Fencing - New Standard Ornamental	Entire Site	1,525	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	28	LF	4	0-1 year	temporary removal for construction
Landsca	na						
_andsca	Benches	Entire Site	3	EA	7	10+ years	
	Landscape - Grass	Entire Site	5,410	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,405	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	1,400	SF	6	10+ years	
	Planting Beds/ Area	Entire Site	532	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	10,000	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	3,000	SF	4	0-1 year	Cracking and holes.
	Retaining Wall - Concrete	Entire Site	80	SF	6	10+ years	erasamig and mores
Parking I	ot						
	Surface - Asphalt	Parking Lot- North	2,952	SF	7	10+ years	Repaired.
	Vehicular Screening	Parking Lot- North	20	LF	6	10+ years	. topaou.
	Surface - Asphalt	Parking Lot- South	8,985	SF	6	10+ years	
	Surface - Concrete	Parking Lot- West	2,280	SF	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- West	800	SF	7	10+ years	
Playgrou	nd						
riaygiou	Equipment - School Age 5-12	North	1	EA	7	10+ years	Repaired.
	Surface - Poured Surface	North	2,200	SF	7	10+ years	Repaired.
	Equipment - Pre K 3-5	West	1	ĒΑ	7	10+ years	Repaired.
	Surface - Poured Surface	West	1,200	SF	7	10+ years	Repaired.
Sidewalk							
Sidewair	Sidewalks - Internal Walks	Entire Site	720	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	15,400	SF	7	10+ years	Replacement in progress.
O:							
Signage	Flag Pole - Flag Pole	North	1	EA	6	10+ years	Missing flag
	Marquee - Free Standing Back lighted w/	North	1 1	EA EA	6 7		iviissii iy ilay
	LED	INOLUL	1	EA	1	10+ years	

 Campus Name: Penn
 Page : 34 of 37
 Assessment Date: 10/27/2021



William Penn Elementary School

1616 S Avers AVENUE, Chicago, IL 60623

Category : Site Building : Site

Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Penn Page : 35 of 37 Assessment Date: 10/27/2021





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Computer Lab	Regular Classroom	2nd Floor	217	217	825	64	32	Υ	N
Computer Lab	Regular Classroom	Basement	015	015	940	64	32	Y	N
Kindergarten	Kindergarten	1st Floor	107	107	890	200	100	Y	N
Office	Regular Classroom	1st Floor	104	104	810	200	100	Y	N
Office	Regular Classroom	1st Floor	110	110	890	200	100	N	N
Office	Regular Classroom	1st Floor	114	114	935	200	100	Υ	N
Office	Regular Classroom	1st Floor	120	120	850	175	85	N	N
Other Instructional Use	Regular Classroom	Basement	017	017	915	180	90	Υ	N
Pre School	Kindergarten	1st Floor	111	111	840	175	85	N	Υ
Pre School	Regular Classroom	1st Floor	109	109	825	175	85	N	N
Pre School	Regular Classroom	1st Floor	115	115	890	175	85	N	N
Regular Classroom	Computer Lab	3rd Floor	317	317	825	136	104	Υ	N
Regular Classroom	Kindergarten	1st Floor	101	101	1,015	175	85	N	N
Regular Classroom	Kindergarten	1st Floor	108	108	1,150	200	100	N	Υ
Regular Classroom	Library	2nd Floor	207	207	825	104	54	Υ	N
Regular Classroom	Regular Classroom	1st Floor	103	103	805	200	100	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	1,150	200	100	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	1,015	175	85	N	Υ
Regular Classroom	Regular Classroom	1st Floor	112	112	870	200	100	Υ	N
Regular Classroom	Regular Classroom	1st Floor	118	118	825	200	100	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	825	104	54	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	675	104	54	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	675	104	54	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	1,150	104	54	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	825	150	45	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	900	164	84	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	825	104	54	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	825	136	104	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	900	112	82	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	825	136	104	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	220	220	825	136	104	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	825	74	39	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	825	150	45	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	675	104	54	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	675	104	54	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	900	104	54	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	825	150	45	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	825	104	54	Υ	N

Campus Name: Penn Page : 36 of 37 Assessment Date: 10/27/2021





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	3rd Floor	308	308	900	164	84	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	825	104	54	Y	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	825	104	54	Y	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	900	112	82	Y	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	825	112	82	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	900	112	82	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	315	315	825	136	104	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	825	136	104	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	825	136	104	Υ	N
Regular Classroom	Regular Classroom	Basement	800	800	950	40	20	N	N
Regular Classroom	Regular Classroom	Basement	010	010	950	80	24	Y	N
Regular Classroom	Regular Classroom	Basement	011	011	925	180	90	N	N
Science	Regular Classroom	2nd Floor	215	215	825	136	104	Y	N
Special Education	Regular Classroom	2nd Floor	201	201	825	150	45	Υ	N
Special Education	Regular Classroom	2nd Floor	209	209	825	104	54	Y	N
Special Education	Regular Classroom	2nd Floor	211	211	900	112	82	Y	N
Store Room	Regular Classroom	Basement	007	007	945	180	90	N	N