



#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1963	3	64,558
Campus Total			64,558

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1- Main Accessible- SE	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#1- Main Accessible- SE	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1- Main Accessible- SE	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1- Main Accessible- SE	80	LF	6	10+ years	
	Power Door Operator and Controls	#1- Main Accessible- SE	2	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	#1- Main Accessible- SE	110	LF	6	10+ years	
	Ramps - Concrete	#1- Main Accessible- SE	50	LF	6	6-10 years	Foundation of raft is starting to crap, possibly from rust at the handrail post
	Stair Handrail - Steel_Stair Handrail	#1- Main Accessible- SE	27	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2- SE	1	EΑ	4	2-5 years	Old door with rotting wood frame
	Exterior Stairs - Concrete	#2- SE	7	LF	5	6-10 years	
	Exterior Stairs - Stone	#2- SE	3	LF	5	2-5 years	Repair to stone is beginning to fall apart with several cracks
	Exterior Doors - Exterior Steel Door	#3- SW	1	EA	4	2-5 years	·
	Exterior Stairs - Concrete	#3- SW	7	LF	5	0-1 year	Failed concrete repair
	Exterior Stairs - Stone	#3- SW	3	LF	5	6-10 years	·
	Exterior Doors - Exterior Steel Door	#4- SW	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#4- SW	15	LF	3	1-2 years	
	Exterior Doors - Exterior Steel Door	#5- SW	2	EA	6	6-10 years	
	Exterior Doors - Side lite	#5- SW	2	EA	4	1-2 years	Bottom of frame has rusted and the rust is also beginning to encroach onto the panels
	Exterior Stairs - Concrete	#5- SW	10	LF	5	1-2 years	
	Ramps - Concrete	#5- SW	12	LF	6	6-10 years	



tegory : Exterior		Building : Main				
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		1		6		
		•		-		
		•			6-10 years	
Ramps - Concrete	#9- NE	50	LF	5	10+ years	Concrete is generally in good shape but the tops of the ramp's foundation wall are spalling
Stair Handrail - Steel Stair Handrail	#9- NE	18	LF	6	10+ years	. 3
Exterior Doors - Exterior Steel Door	10- Low SW Roof	1	EA	6	10+ years	
					•	
	Entire Building	1.060	LF	6	10+ years	
			SF	7		
	3	- ,			, , , , ,	
Exterior Lighting Descript or Deef Mounted	Entire Building	10	ΕΛ	7	6.10 voore	New fixtures to be installed
		_				
						New fixtures to be installed
Exterior Lighting - Wall Mounted						New fixtures to be installed Damaged Obsolete light
Exterior Lighting - wall Mounted	Entire building	2	EA	4	0-1 year	Damaged Obsolete light
, •	Elevator roof				-	New coping to be installed at new roof
	Elevator roof					
Parapet - Parapet < 16" Height	Elevator roof	31		7		
Roof - Modified Bitumen	Elevator roof	144	SF	7	10+ years	New roof, ponding, not yet received modified bitumen
Roof Structure - Steel / Metal Deck/ Concrete Topping	Elevator roof	144	SF	7	10+ years	
	Low NW roof	19	LF	7	6-10 years	New coping to be installed
						Roof to receive new downspouts
Roof - Modified Bitumen	Low NW roof					New roof being installed
Roof Structure - Steel / Metal Deck/	Low NW roof	56	SF	7	10+ years	
	Low SW roof	18	LF	6	10+ vears	
				_		
Coping - Metal	Low SW roof	308	LF	7	10+ years	New coping to be installed
	Low SW roof	200	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Exterior FRP Door Exterior Doors - Exterior FRP Door Exterior Stairs - Concrete Ramp Concrete Ramp Handrail - Steel_Ramp Handrail Ramps - Concrete  Stair Handrail - Steel_Stair Handrail Exterior Doors - Exterior Steel Door  On	Exterior Doors - Exterior Steel Door	Exterior Doors - Exterior Steel Door	Location	Location	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Low SW roof	5,942	SF	7	10+ years	New roofing to be installed
	Roof Structure - Concrete	Low SW roof	5,942	SF	7	10+ years	-
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Metal	Main Roof	624	LF	7	10+ years	New roof in process
	Downspouts - Interior Downspouts	Main Roof	180	LF	6	10+ years	·
	Roof - Modified Bitumen	Main Roof	17,976	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	New hatch to be installed
	Roof Structure - Concrete	Main Roof	17,976	SF	7	10+ years	
	Access Ladder - Metal	Mid S roof	. 1	EA	7	10+ years	
	Coping - Metal	Mid S roof	267	LF	7	10+ years	
	Coping - Metal	Mid S roof	5	LF	7	10+ years	on going renovation / replacement
	Downspouts - Interior Downspouts	Mid S roof	75	LF	6	6-10 years	on going ronoranon, replacement
	Roof - Modified Bitumen	Mid S roof	6,051	SF	7	6-10 years	
	Roof Structure - Concrete	Mid S roof	6,051	SF	7	10+ years	
	Troof chactare controls	Wild C 1001	0,001	O.	•	101 youro	
alls	2		4.000				
	Canopy - Concrete/ Stucco	Entire Building	4,362	SF	7	10+ years	All concrete canopies are being repaired, seen today in process August 11, 2021
	Canopy - Concrete/ Stucco	Entire Building	285	SF	5	2-5 years	Canopy columns are rusting
	Canopy - Metal	Entire Building	205	SF	6	10+ years	3
	Cheek-Wall - Concrete	Entire Building	175	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	14,313	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	40	SF	7	10+ years	All masonry is being repaired today August 11, 2021
	Exterior Walls - Precast Panel Wall	Entire Building	1,080	SF	6	10+ years	7.ugust 11, 2021
'indows							
11111111111	Curtain wall - Glazed Double Pane	Entire Building	56	SF	6	10+ years	
	Curtain wall - Glazed Single Pane	Entire Building	138	SF	6	6-10 years	
	Curtain wall - Insulated Panel	Entire Building	3,230	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	170	SF	5	2-5 years	
	Curtain wall - Louver	Entire Building	204	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	3,410	SF	6	6-10 years	
	Lintels - Steel	Entire Building	86	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	8,382	SF	6	2-5 years	
atego	ry : Electrical		В	uilding	: Main		
_		Logotion		_		Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	Basement	2	EA	6	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	4	2-5 years	



Category : Electrical Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Corridors and Stairs	Entire Building	38	EA	4	2-5 years	
	Exit Signs - Gym	Entire Building	6	EA	4	2-5 years	
	Exit Signs - Gym	Entire Building	1	EA	4	2-5 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	4	2-5 years	
	Security System - CCTV	Entire Building	64,558	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	64,558	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,232	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,596	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,000	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	2	SF	2	0-1 year	failed
	Emergency A/C Power - Students Toilets	Entire Building	1,845	SF	6	10+ years	
	Emergency Generator- Outdoor- Diesel - 101 - 150 KW	Site West	1	EA	6	10+ years	
Main Ser	vice						
	Main Electrical Service - 1600 A 120/208/3PH	Basement	1	EA	4	1-2 years	
	PA System	Entire Building	64,558	SF	6	6-10 years	
Power Di							
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	4	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	8	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	12	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	6	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years	
Cotons	•		5		. Mein		
Catego	ry : Fire Protection		В	uilding	. wain	Doggmand	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Aları		Location	Qualitity	COIVI	IVALIA	Replacement	Ounillelits
_riie Alafi	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	64,558	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	64,558	SF	4	2-5 years	
Catego	ry : Mechanical		В	uilding	: Main		
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
	71						



					Replacement	
Air Conditioning					•	
Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	5	2-5 years	
Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons	Site West	1	EA	6	10+ years	
_Air Handling Systems						
Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Less than 4000 cfm	1st Floor	1	EA	6	6-10 years	
Air Intake	1st Floor	1	EA	6	6-10 years	
Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 10001-	Basement	1	EA	7	10+ years	
15000 cfm Air Intake	Basement	1	EA	6	10+ years	
Fan Coil Unit- Floor Mounted - Dual Temperature Coil	Entire Building	39	EA	6	6-10 years	
Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Fan Room 220	1	EA	6	10+ years	
Air Handling Unit- Built Up- Multi Zone- Hot Water Coils - 15001 - 25000 cfm	Fan Room 220	1	EA	5	10+ years	
Air Intake	Fan Room 220	1	EΑ	6	6-10 years	
Auxiliaries - 15001 - 25000 cfm	Fan Room 220	1	EA	5	6-10 years	
Return Duct Work - Indoor- Vertical Shaft and Ducts	Fan Room 220	100	LF	6	10+ years	
Zone Dampers	Fan Room 220	10	EA	6	10+ years	
Fan Coil Unit- Celing Mounted - Electric	Kitchen	1	EA	5	6-10 years	
Boiler Systems						
Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	2	EA	7	10+ years	
Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
Combustion Dampers	Boiler Room	1	EA	6	10+ years	replaced w new.
Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	7	10+ years	•
Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	7	10+ years	
Glycol Feed System	Boiler Room	1	EA	6	10+ years	
_Gas Booster						
Gas Booster	Boiler Room	3	EA	6	6-10 years	
Heating Devices						
Cabinet Heaters - With Hot Water Coil	Entire Building	16	EA	6	6-10 years	
Unit Heater - Hot Water	Entire Building	3	EA	6	6-10 years	



							0000 O Lillo AVEINOE, Officago, IE 00007
						Replacement	
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	4	0-1 year	
	Duct Heater - Hot Water	Entire Building	8		6	10+ years	
Mechanio	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	6-10 years	
	Chilled Water Pump - 21 - 50 HP	Boiler Room	2	EA	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	1,500	LF	6	10+ years	
Tempera	ture Control						
	DDC System	Entire Building	64,558	SF	6	6-10 years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	51	EA	6	6-10 years	
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Main Roof and Kitchen	8	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Main Roof and Kitchen	1	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Main Roof and Kitchen	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Main Roof and Kitchen	1	EA	4	2-5 years	
Categoi	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate		Location	Quantity	00141	Rank	Nopidocinent	Commonto
I IOL WALE	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Cas   leater - 300001 - 000000 b10/11K	Doller Mooni	ı	LA	U	0-10 years	
Piping							
. 5	B (1 B) 1 11 (1M (1 B (1 1)	F (1 B 11 P	04.550	0-	-	0.40	

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er -						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	64,558	SF	7	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	64,558	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	64,558	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	64,558	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	64,558	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	64,558	SF	6	6-10 years	
	Sanitary Piping	Entire Building	64,558	SF	6	6-10 years	
	Storm Piping	Entire Building	64,558	SF	6	6-10 years	
	Vent Piping	Entire Building	64,558	SF	6	6-10 years	

Campus Name: Wadsworth Page : 6 of 28 Assessment Date: 08/11/2021



**Building: Main** Category : Plumbing Recommend Location Quantity UOM Rank Replacement Comments Item - Type Group Pumps Pumps - Sump-Duplex Basement 1 EΑ 6 6-10 years

Building: Main Category: Room

- 4.090	y:Room	Building : Main						
<b>0</b>	Name Trans	Lagation	0	LIOM	Danila	Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Administ	rative Suites/Offices							
	Ceiling - Plaster/Drywall	104B Parent Room	231	SF	6	10+ years		
	Doors - Wood Doors inclu hw	104B Parent Room	1	EA	6	6-10 years		
	Floor - Tile	104B Parent Room	231	SF	6	10+ years		
	Lighting - Pendent/Surface	104B Parent Room	4	EA	6	6-10 years		
	Power Distribution	104B Parent Room	6	EA	6	10+ years		
	Walls - Concrete Block	104B Parent Room	576	SF	6	10+ years		
	Ceiling - Plaster/Drywall	112A	231	SF	6	10+ years		
	Doors - Wood Doors inclu hw	112A	1	EA	6	6-10 years		
	Floor - Tile	112A	231	SF	6	6-10 years		
	Lighting - Pendent/Surface	112A	4	EA	7	6-10 years		
	Power Distribution	112A	6	EA	6	6-10 years		
	Storage/ Closet	112A	20	SF	7	6-10 years		
	Walls - Concrete Block	112A	576	SF	7	10+ years		
	AC Unit	142 - Principal's Office	1	EA	5	6-10 years		
	Ceiling - Plaster/Drywall	142 - Principal's Office	168	SF	6	10+ years		
	Doors - Wood Doors inclu hw	142 - Principal's Office	1	EA	6	6-10 years		
	Floor - Tile	142 - Principal's Office	168	SF	6	10+ years		
	Lighting - Pendent/Surface	142 - Principal's Office	2	EA	6	6-10 years		
	Power Distribution	142 - Principal's Office	6	EA	6	6-10 years		
	Walls - Concrete Block	142 - Principal's Office	307	SF	6	10+ years		
	Ceiling - Lay-in	1st floor inside boiler room,	91	SF	6	10+ years		
	3 ,	engineer's office				,		
	Doors - Wood Doors inclu hw	1st floor inside boiler room,	1	EA	6	6-10 years		
		engineer's office				,		
	Floor - Tile	1st floor inside boiler room,	91	SF	6	10+ years		
		engineer's office	-	_	_	, , , , ,		
	Lighting - Lay-in	1st floor inside boiler room,	1	EA	6	6-10 years		
	3 - 37	engineer's office				, , , , , , ,		
	Power Distribution	1st floor inside boiler room,	6	EA	6	6-10 years		
		engineer's office	-		•	- · · · · · · · · · · · · · · · · · · ·		
	Storage/ Closet	1st floor inside boiler room,	35	SF	7	6-10 years		
		engineer's office			-	, ,		
	Walls - Concrete Block	1st floor inside boiler room,	342	SF	6	10+ years		
	20.0.0.0	engineer's office	3.2	<b>.</b>	•	,		
	Ceiling - Plaster/Drywall	322 Teachers lounge	305	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	322 Teachers lounge	1	EA	6	6-10 years		
	Floor - Tile	322 Teachers lounge	305	SF	6	6-10 years		



Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	322 Teachers lounge	4	EA	7	6-10 years			
	Power Distribution	322 Teachers lounge	4	EA	6	6-10 years			
	Walls - Concrete Block	322 Teachers lounge	417	SF	7	6-10 years			
	AC Unit	Assistant Principal office 113	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Assistant Principal office 113	498	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Assistant Principal office 113	2	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	Assistant Principal office 113	498	SF	6	10+ years			
	Lighting - Pendent/Surface	Assistant Principal office 113	8	EA	7	6-10 years			
	Power Distribution	Assistant Principal office 113	12	EA	6	6-10 years			
	Walls - Concrete Block	Assistant Principal office 113	1,584	SF	7	10+ years			
	Work SInk	Assistant Principal office 113	1	EΑ	7	6-10 years			
	AC Unit	Room 146, Main Office	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Room 146, Main Office	374	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Room 146, Main Office	1	EA	6	6-10 years			
	Floor - Tile	Room 146, Main Office	374	SF EA	6	10+ years			
	Lighting - Pendent/Surface	Room 146, Main Office	6	EA	6	6-10 years			
	Power Distribution	Room 146, Main Office Room 146, Main Office	8	SF	6 7	6-10 years			
	Storage/ Closet Walls - Concrete Block	Room 146, Main Office	67 529	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	Room 159, Kitchen Manager's	529 57	SF	6	10+ years 10+ years			
	,	Office	57		O	•			
	Doors - Wood Doors inclu hw	Room 159, Kitchen Manager's Office	1	EA	6	6-10 years			
	Floor - Tile	Room 159, Kitchen Manager's Office	57	SF	6	10+ years			
	Lighting - Pendent/Surface	Room 159, Kitchen Manager's Office	1	EA	7	6-10 years			
	Power Distribution	Room 159, Kitchen Manager's Office	2	EA	6	10+ years			
	Walls - Concrete Block	Room 159, Kitchen Manager's Office	98	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Room 222, Teacher's Lounge	305	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Room 222, Teacher's Lounge	1	EA	6	6-10 years			
	Floor - Tile	Room 222, Teacher's Lounge	305	SF	6	10+ years			
	Lighting - Pendent/Surface	Room 222, Teacher's Lounge	4	EA	6	6-10 years			
	Power Distribution	Room 222, Teacher's Lounge	4	EA	6	6-10 years			
	Walls - Concrete Block	Room 222, Teacher's Lounge	417	SF	6	10+ years			
	Ceiling - Plaster/Drywall	lunchroom office	450	SF	6	10+ years			
	Doors - Wood Doors inclu hw	lunchroom office	1	EA	6	6-10 years			
	Floor - Tile	lunchroom office	450	SF	6	10+ years			
	Lighting - Pendent/Surface	lunchroom office	2	EA	7	6-10 years			
	Power Distribution	lunchroom office	8	EA	6	6-10 years			
	Walls - Concrete Block	lunchroom office	1,536	SF	7	10+ years			
	Ceiling - Plaster/Drywall	office 112	210	SF	6	10+ years			



Type - Wood Doors inclu hw - Tile	Location	Quantity	UOM		Recommend	
- Wood Doors inclu hw - Tile		Quantity				
- Tile		• • • • • • • •		Rank	Replacement	Comments
	office 112	1	EA	6	6-10 years	
	office 112	210	SF	6	6-10 years	
ng - Pendent/Surface	office 112	4	EA	7	6-10 years	
Distribution	office 112	6	EA	6	6-10 years	
- Concrete Block	office 112	555	SF	7	10+ years	
g - Plaster/Drywall	Room 151C, 1st Floor	3,596	SF	6	10+ years	
- Steel Doors incl hw	Room 151C, 1st Floor	4	EΑ	6	6-10 years	
- Tile	Room 151C, 1st Floor	3,596	SF	6	10+ years	
ng - Metal Halide/Sodium Vapor	Room 151C, 1st Floor	17	ĒΑ	6	6-10 years	
ig Motal Hando/Codiam Vapor	Room 151C, 1st Floor	530	SF	6	6-10 years	
Curtain	Room 151C, 1st Floor	4	EA	5	6-10 years	
Lift	Room 151C, 1st Floor	1	EA	5	6-10 years	
Lighting System	Room 151C, 1st Floor	1	EA	7	6-10 years	
-Stairs - Wood	Room 151C, 1st Floor	18	LF	7	10+ years	
ge/ Closet	Room 151C, 1st Floor	97	SF	7	6-10 years	
- Concrete Block	Room 151C, 1st Floor	2,231	SF	6	10+ years	
- Structural Glazed Tile	Room 151C, 1st Floor	2,231	SF	6	10+ years	
Structural Glazed The	10011 1010, 1311 1001	2,201	01	O	101 years	
g - Plaster/Drywall	Room 157	958	SF	6	10+ years	
- Wood Doors inclu hw	Room 157	2	EA	6	6-10 years	
- Tile	Room 157	958	SF	6	10+ years	
ng - Pendent/Surface	Room 157	18	EA	6	6-10 years	
ig Line	Room 157	18	LF	6	6-10 years	
ge/ Closet	Room 157	114	SF	7	6-10 years	
- Structural Glazed Tile	Room 157	1,242	SF	6	10+ years	
Room						
sories	1st floor inside boiler room	92	SF	7	6-10 years	
g - Plaster/Drywall	1st floor inside boiler room	92	SF	6	10+ years	
- Wood Doors inclu hw	1st floor inside boiler room	1	EA	6	6-10 years	
- Tile/Sheet	1st floor inside boiler room	92	SF	7	10+ years	
ory	1st floor inside boiler room	1	ĒΑ	6	6-10 years	
ng - Pendent/Surface	1st floor inside boiler room	2	EA	6	2-5 years	
ons	1st floor inside boiler room	1	EΑ	7	6-10 years	
nt Lockers - One Tier		4			•	
- Concrete Block		•				
						Cracked
						Cidolod
Closet	TOUR INDIGENOUS DOUBLE TOUTH	1		U	o io years	
nt L - C - C	ockers - One Tier concrete Block concrete Block	cockers - One Tier 1st floor inside boiler room 1st floor inside boiler room 2st floor inside boiler room 1st floor inside boiler room 2st floor inside boiler ro	cockers - One Tier1st floor inside boiler room4concrete Block1st floor inside boiler room508concrete Block1st floor inside boiler room5	cockers - One Tier1st floor inside boiler room4EAconcrete Block1st floor inside boiler room508SFconcrete Block1st floor inside boiler room5SF	cockers - One Tier1st floor inside boiler room4EA6concrete Block1st floor inside boiler room508SF6concrete Block1st floor inside boiler room5SF5	cockers - One Tier1st floor inside boiler room4EA66-10 yearsconcrete Block1st floor inside boiler room508SF610+ yearsconcrete Block1st floor inside boiler room5SF50-1 year



Catego	ry : Room		В	uilding	: Main		0000 0 Ellis AVENUE, Officago, IE 00007
3-			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Faculty Lunchroom Inside 222 Teachers Lounge	197	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty Lunchroom Inside 222 Teachers Lounge	1	EA	6	6-10 years	
	Floor - Tile	Faculty Lunchroom Inside 222 Teachers Lounge	197	SF	6	10+ years	
	Lighting - Pendent/Surface	Faculty Lunchroom Inside 222 Teachers Lounge	6	EA	7	6-10 years	
	Walls - Concrete Block	Faculty Lunchroom Inside 222 Teachers Lounge	304	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 155	3,000	SF	6	10+ years	
	Doors - Steel Doors incl hw	Room 155	2	EΑ	6	6-10 years	
	Floor - Tile	Room 155	3,000	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 155	60	EΑ	6	6-10 years	
	Walls - Concrete Block	Room 155	3,984	SF	6	10+ years	
_MDF_ID							
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Finishes	2nd Floor	358	SF	7	6-10 years	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	
_Mechan	ical/ Service Rooms						
	Boiler Room	1st flr west side	1,026	SF	5	6-10 years	
	Janitor's Closet	1st flr west side	37	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st flr west side	53	SF	5	6-10 years	
	Storage Room	1st flr west side	150	SF	5	6-10 years	
	Storage Room	1st flr west side	105	SF	5	6-10 years	
	Storage Room	1st flr west side	130	SF	5	6-10 years	
	Storage Room	1st flr west side	112	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	37	SF	5	10+ years	
	Storage Room	2nd Floor	84	SF	7	10+ years	
	Janitor's Closet	3rd Floor	37	SF	5	6-10 years	
	Storage Room	3rd Floor	325	SF	5	6-10 years	
	Storage Room	3rd Floor	66	SF	5	6-10 years	
	Crawl Space - Unfinished	Basement	1,500	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	879	SF	5	6-10 years	
	Mechanical/ Service Rooms	Fan Room	923	SF	5	10+ years	
_Restroo	m						
	Accessories	145 - In the Main Office	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	145 - In the Main Office	43	SF	6	10+ years	
	Doors - Wood Doors inclu hw	145 - In the Main Office	1	EA	6	6-10 years	
	Floor - Tile	145 - In the Main Office	43	SF	6	10+ years	



Company   Comp	Catego	ry : Room		В	uilding	: Main		· • •
Lavatory					_			
Lightling - Pendent/Surface   145 - In the Main Office   1	Group	Item - Type		Quantity		Rank		Comments
Water Closet         145 - In the Main Office         97         SF         6         10 years           Accessories         18 Floor         328         SF         7         6-10 years           Ceiling - Plaster/Dywall         1st Floor         328         SF         6         610 years           Doors - Steel Doors inch hw         1st Floor         1         EA         6-610 years           Floor - Tile Ceramic/Porcelain         1st Floor         1         EA         6-10 years           Floor Drain         1st Floor         1         EA         6-10 years           Lavatory         1st Floor         2         EA         6-10 years           Lighting - Pendent/Surface         1st Floor         2         EA         6-10 years           Walls - Structural Glazed Tile         1st Floor         421         SF         6         10 years           Walls - Structural Glazed Tile         1st Floor         20         SF         4 0-1 years         Small cracks           Water Closet         1st Floor         25         6         6-10 years         Small cracks           Ceiling - Plaster/Dywall         1st Floor         269         SF         6-10 years           Ceiling - Plaster/Dywall         1st Flo		,	145 - In the Main Office	1	EA	6		
Water Closet   145 - In the Main Office   1   EA   6   6-10 years		Lighting - Pendent/Surface	145 - In the Main Office	1	EA	6		
Accessories			145 - In the Main Office	97	_	_		
Ceiling - Pilaster/Dywall		Water Closet	145 - In the Main Office			6		
Doors - Steel Doors incl hw		Accessories	1st Floor				6-10 years	
Floor - Tile Ceramic/ Porcelain		Ceiling - Plaster/Drywall	1st Floor	328	SF	6	10+ years	
Floor Drain		Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
Layatory		Floor - Tile Ceramic/ Porcelain	1st Floor	328	SF	6	10+ years	
Lighting - Pendent/Surface   1st Floor   2		Floor Drain	1st Floor	1	EA	7	10+ years	
Lighting - Pendent/Surface   1st Floor   2		Lavatory	1st Floor	2	EA	6	6-10 years	
Partitions		Lighting - Pendent/Surface	1st Floor	2	EA	6	•	
Walls - Structural Glazed Tile         1st Floor         20         SF         4         0-1 year         Small cracks           Waler Closet         1st Floor         6         EA         6         6-10 years         Small cracks           Accessories         1st Floor         269         SF         7         6-10 years         6-10 years           Celling - Plaster/Drywall         1st Floor         269         SF         6         10+ years           Doors - Steel Doors inch bw         1st Floor         1         EA         6         6-10 years           Floor - Tile Ceramic/ Porcelain         1st Floor         1         EA         6         6-10 years           Floor Drain         1st Floor         3         EA         6         6-10 years           Layatory         1st Floor         3         EA         6         6-10 years           Lighting - Pendent/Surface         1st Floor         2         EA         6         6-10 years           Partitions         1st Floor         2         EA         6         6-10 years           Walls - Structural Glazed Tile         1st Floor         35         EA         6         6-10 years           Walls - Structural Glazed Tile         1st floor ins			1st Floor				6-10 years	
Walls - Structural Glazed Tile         1st Floor         20         SF         4         0-1 year         Small cracks           Water Closet         1st Floor         269         SF         7         6-10 years           Accessories         1st Floor         269         SF         6         10 years           Celling - Plaster/Drywall         1st Floor         269         SF         6         10 years           Floor - Tile Ceramic/ Porcelain         1st Floor         1         EA         6         6-10 years           Floor Drain         1st Floor         269         SF         6         10 years           Floor Drain         1st Floor         289         SF         6         10 years           Lavatory         1st Floor         3 EA         6         6-10 years           Partitions         1st Floor         2 EA         6         6-10 years           Partitions         1st Floor         2 EA         7         6-10 years           Wals - Structural Glazed Tile         1st Floor         2 EA         6         6-10 years           Water Closet         1st Floor inside engineer's office         31         SF         6         10 years           Celling - Plaster/Drywall		Walls - Structural Glazed Tile	1st Floor	421	SF	6	10+ years	
Water Closet			1st Floor		SF	4		Small cracks
Accessories					_			
Ceiling - Plaster/Drywall								
Doors - Steel Doors inch hw								
Floor Tile Ceramic/ Porcelain Floor Drain Ist Floor Ist								
Floor Drain Lavatory 1st Floor 3 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Partitions 1st Floor 2 EA 7 6-10 years Urinals 1st Floor 5 EA 6 6-10 years Urinals 1st Floor 5 EA 6 6-10 years Urinals Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Water Closet 1st Floor 2 EA 6 6-10 years Water Closet 1st Floor 325 SF 6 10+ years Water Closet 1st floor inside engineer's office 31 SF 7 6-10 years Ceiling - Plaster/Drywall 1st floor inside engineer's office 31 SF 6 10+ years Doors - Wood Doors inclu hw 1st floor inside engineer's office 31 SF 6 10+ years Doors - Wood Doors inclu hw 1st floor inside engineer's office 31 SF 6 10+ years Doors - Wood Doors inclu hw 1st floor inside engineer's office 31 SF 6 10+ years Floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years Uighting - Lay-in 1st floor inside engineer's office 31 SF 6 10+ years Uighting - Lay-in 1st floor inside engineer's office 1 EA 6 6-10 years Walls - Concrete Block 1st floor inside engineer's office 1 EA 6 6-10 years Accessories 1st floor inside engineer's office 1 EA 6 6-10 years Ceiling - Plaster/Drywall 1st floor inside engineer's office 1 EA 6 6-10 years Ceiling - Plaster/Drywall 1st fli inside parent room, woman's 1 SF 7 6-10 years Ceiling - Plaster/Drywall 1st fli inside parent room, woman's 1 SF 7 6-10 years Ceiling - Plaster/Drywall 1st fli inside parent room, woman's 1 EA 6 6-10 years Floor - Tile 1st fli inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st fli inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st fli inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st fli inside parent room, woman's 2 EA 7 6-10 years Valer Closet 1st fli inside parent room, woman's 2 EA 7 6-10 years Valer Closet 1st fli inside parent room, woman's 2 EA 6 6-10 years United States and the search and the searc								
Lavatory Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Partitions 1st Floor 2 EA 7 6-10 years Urinals Urinals 1st Floor 5 EA 6 6-10 years Urinals Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Water Closet 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 325 SF 6 10+ years Water Closet 1st Floor Accessories 1st floor inside engineer's office 31 SF 7 6-10 years Ceiling - Plaster/Drywall 1st floor inside engineer's office 31 SF 6 10+ years Doors - Wood Doors inclu hw 1st floor inside engineer's office 1 EA 6 6-10 years Floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years Urinals							•	
Lighting - Pendent/Surface 1st Floor 2 EA 7 6-10 years Partitions 1st Floor 2 EA 7 6-10 years Urinals 1st Floor 5 EA 6 6-10 years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Water Closet 1st Floor 2 EA 6 6-10 years St floor inside engineer's office 31 SF 7 6-10 years Ceiling - Plaster/Drywall 1st floor inside engineer's office 31 SF 6 10+ years St floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years St floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years St floor - Tile 1st floor inside engineer's office 1 EA 6 6-10 years St floor - Tile 1st floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside engineer's office 1 EA 6 6-10 years St floor inside parent room, woman's 1 SF 7 6-10 years SC eiling - Plaster/Drywall 1st flr inside parent room, woman's 1 SF 7 6-10 years SC eiling - Plaster/Drywall 1st flr inside parent room, woman's 1 EA 6 6-10 years SC eiling - Plaster/Drywall 1st flr inside parent room, woman's 1 EA 6 6-10 years SC eiling - Plaster/Drywall 1st flr inside parent room, woman's 1 EA 6 6-10 years SC eiling - Plaster/Drywall 1st flr inside parent room, woman's 1 EA 6 6-10 years SC eiling - Plaster/Drywall 1st flr inside parent room, woman's 1 EA 6 6-10 years SC eiling - Plaster/Drywall 1st flr inside parent room, woman's 1 EA 6 6-10 years SC eiling - Plaster/Drywall 1st flr inside parent room, woman's 1 EA 6 6-10 years SC eiling - Plaster/Drywall SC encorate Block 1st flr inside parent room, woman's 2							•	
Partitions Urinals Urinals 1st Floor 1st Floor 315 FA 6 6-10 years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet Mater Closet 1st Floor 325 SF 6 10+ years Water Closet Accessories 1st floor inside engineer's office 31 SF 7 6-10 years Ceiling - Plaster/Drywall 1st floor inside engineer's office 31 SF 6 10+ years Doors - Wood Doors inclu hw 1st floor inside engineer's office 1 EA 6 6-10 years Floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years Floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years Floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years Floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years Floor - Tile 1st floor inside engineer's office 1 EA 6 6-10 years Walls - Concrete Block 1st floor inside engineer's office 1 EA 6 6-10 years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Accessories 1st flr inside parent room, woman's Ceiling - Plaster/Drywall 1st flr inside parent room, woman's Doors - Wood Doors inclu hw 1st flr inside parent room, woman's Floor - Tile 1st flr inside parent room, woman's 1 EA 6 6-10 years Floor - Tile 1st flr inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Lighting - Pendent/Surface 1st flr inside parent room, woman's 1 EA 6 6-10 years Valls - Concrete Block 1st flr inside parent room, woman's 2 EA 7 6-10 years Walls - Concrete Block 1st flr inside parent room, woman's 2 EA 7 6-10 years Valls - Concrete Block Vater Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years								
Urinals Walls - Structural Glazed Tile Walts - Structural Glazed Tile Walts - Structural Glazed Tile Walts - Structural Glazed Tile Structural Glazed Genomes's office Structural Stru		•					•	
Walls - Structural Glazed Tile1st Floor325SF610+ yearsWater Closet1st Floor2EA66-10 yearsAccessories1st floor inside engineer's office31SF76-10 yearsCeiling - Plaster/Drywall1st floor inside engineer's office31SF610+ yearsDoors - Wood Doors inclu hw1st floor inside engineer's office1EA66-10 yearsFloor - Tile1st floor inside engineer's office31SF610+ yearsLavatory1st floor inside engineer's office1EA66-10 yearsLighting - Lay-in1st floor inside engineer's office1EA66-10 yearsWalls - Concrete Block1st floor inside engineer's office1EA66-10 yearsWater Closet1st floor inside engineer's office1EA66-10 yearsAccessories1st flr inside parent room, woman's1SF76-10 yearsCeiling - Plaster/Drywall1st flr inside parent room, woman's1SF76-10 yearsDoors - Wood Doors inclu hw1st flr inside parent room, woman's1EA66-10 yearsFloor - Tile1st flr inside parent room, woman's1EA66-10 yearsLighting - Pendent/Surface1st flr inside parent room, woman's1EA66-10 yearsWalls - Concrete Block1st flr inside parent room, woman's2EA76-10 years<								
Water Closet Accessories 1st Floor inside engineer's office 31 SF 7 6-10 years Ceiling - Plaster/Drywall 1st floor inside engineer's office Doors - Wood Doors inclu hw 1st floor inside engineer's office 1 EA 6 6-10 years Floor - Tile 1st floor inside engineer's office 1 EA 6 6-10 years Lavatory 1st floor inside engineer's office 1 EA 6 6-10 years Lighting - Lay-in 1st floor inside engineer's office 1 EA 6 6-10 years Lighting - Concrete Block 1st floor inside engineer's office 1 EA 6 6-10 years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Ceiling - Plaster/Drywall 1st flr inside parent room, woman's 1 SF 7 6-10 years Ceiling - Plaster/Drywall 1st flr inside parent room, woman's 1 EA 6 6-10 years Floor - Tile 1st flr inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st flr inside parent room, woman's 2 EA 7 6-10 years Walls - Concrete Block 1st flr inside parent room, woman's 2 EA 7 6-10 years Walls - Concrete Block 1st flr inside parent room, woman's 2 EA 7 6-10 years Water Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years						_		
Accessories 1st floor inside engineer's office 31 SF 7 6-10 years Ceiling - Plaster/Drywall 1st floor inside engineer's office 31 SF 6 10+ years Doors - Wood Doors inclu hw 1st floor inside engineer's office 1 EA 6 6-10 years Floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years Lavatory 1st floor inside engineer's office 1 EA 6 6-10 years Lighting - Lay-in 1st floor inside engineer's office 1 EA 6 6-10 years Walls - Concrete Block 1st floor inside engineer's office 216 SF 6 10+ years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Accessories 1st flor inside engineer's office 1 EA 6 6-10 years Ceiling - Plaster/Drywall 1st flr inside parent room, woman's 1 SF 7 6-10 years Ceiling - Plaster/Drywall 1st flr inside parent room, woman's 82 SF 6 10+ years Floor - Tile 1st flr inside parent room, woman's 1 EA 6 6-10 years Lighting - Pendent/Surface 1st flr inside parent room, woman's 1 EA 6 6-10 years Lighting - Pendent/Surface 1st flr inside parent room, woman's 1 EA 6 6-10 years Walls - Concrete Block 1st flr inside parent room, woman's 2 EA 7 6-10 years Walls - Concrete Block 1st flr inside parent room, woman's 2 EA 7 6-10 years Water Closet 1st flr inside parent room, woman's 324 SF 6 10+ years Water Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years					_	_		
Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw 1st floor inside engineer's office 1 EA 6 6-10 years Floor - Tile 1st floor inside engineer's office 1 EA 6 6-10 years Lavatory 1st floor inside engineer's office 1 EA 6 6-10 years Lighting - Lay-in 1st floor inside engineer's office 1 EA 6 6-10 years Lighting - Concrete Block 1st floor inside engineer's office 1 EA 6 6-10 years Walls - Concrete Block 1st floor inside engineer's office 216 SF 6 10+ years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Water Closet 1st flr inside parent room, woman's 1 SF 7 6-10 years Ceiling - Plaster/Drywall 1st flr inside parent room, woman's Doors - Wood Doors inclu hw 1st flr inside parent room, woman's 1 EA 6 6-10 years Floor - Tile 1st flr inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Partitions 1st flr inside parent room, woman's 1 EA 6 6-10 years Walls - Concrete Block 1st flr inside parent room, woman's 2 EA 7 6-10 years Water Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years								
Doors - Wood Doors inclu hw Floor - Tile 1st floor inside engineer's office 2st floor			•				•	
Floor - Tile 1st floor inside engineer's office 31 SF 6 10+ years Lavatory 1st floor inside engineer's office 1 EA 6 6-10 years Lighting - Lay-in 1st floor inside engineer's office 1 EA 6 6-10 years Walls - Concrete Block 1st floor inside engineer's office 216 SF 6 10+ years Water Closet 1st floor inside engineer's office 1 EA 6 6-10 years Accessories 1st flr inside parent room, woman's 1 SF 7 6-10 years Ceiling - Plaster/Drywall 1st flr inside parent room, woman's 82 SF 6 10+ years Doors - Wood Doors inclu hw 1st flr inside parent room, woman's 1 EA 6 6-10 years Floor - Tile 1st flr inside parent room, woman's 82 SF 6 10+ years Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Lighting - Pendent/Surface 1st flr inside parent room, woman's 1 EA 6 6-10 years Partitions 1st flr inside parent room, woman's 2 EA 7 6-10 years Walls - Concrete Block 1st flr inside parent room, woman's 324 SF 6 10+ years Water Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years							,	
Lavatory Lighting - Lay-in St floor inside engineer's office Lighting - Lay-in St floor inside engineer's office Lighting - Lay-in St floor inside engineer's office Lighting - Concrete Block St floor inside engineer's office Lighting - Concrete Block L								
Lighting - Lay-in  1st floor inside engineer's office  1 EA 6 6-10 years  Walls - Concrete Block  1st floor inside engineer's office  216 SF 6 10+ years  Water Closet  1st floor inside engineer's office  1 EA 6 6-10 years  Accessories  1st flr inside parent room, woman's  1 SF 7 6-10 years  Ceiling - Plaster/Drywall  1st flr inside parent room, woman's  Doors - Wood Doors inclu hw  1st flr inside parent room, woman's  Floor - Tile  1st flr inside parent room, woman's  Layatory  1st flr inside parent room, woman's  Lighting - Pendent/Surface  1st flr inside parent room, woman's  Partitions  1st flr inside parent room, woman's  1st flr inside parent room, woman's  1st flr inside parent room, woman's  2st flr inside parent room, woman's								
Walls - Concrete Block  Water Closet Accessories Accessories Ceiling - Plaster/Drywall Ist flr inside parent room, woman's Lavatory Lighting - Pendent/Surface Ist flr inside parent room, woman's Lighting - Pendent/Surface Ist flr inside parent room, woman's Ist flr inside parent ro								
Water Closet Accessories 1st flor inside engineer's office 1			•	-				
Accessories Ceiling - Plaster/Drywall 1st flr inside parent room, woman's Doors - Wood Doors inclu hw 1st flr inside parent room, woman's Floor - Tile 1st flr inside parent room, woman's Lavatory Lighting - Pendent/Surface Partitions 1st flr inside parent room, woman's Nat flr insi								
Ceiling - Plaster/Drywall 1st flr inside parent room, woman's Doors - Wood Doors inclu hw 1st flr inside parent room, woman's Floor - Tile 1st flr inside parent room, woman's Lavatory 1st flr inside parent room, woman's Lighting - Pendent/Surface 1st flr inside parent room, woman's 1 EA 6 6-10 years 2 EA 7 6-10 years 4 Floor - Tile 1 EA 7 6-10 years 2 EA 7 6-10 years 3 SF 6 10+ years 4 SF 7 6-10 years 4 SF 7 6-10 years 4 SF 8								
Doors - Wood Doors inclu hw 1st flr inside parent room, woman's Floor - Tile 1st flr inside parent room, woman's Lavatory 1st flr inside parent room, woman's 1 EA 6 6-10 years Lighting - Pendent/Surface 1st flr inside parent room, woman's 1 EA 6 6-10 years 1 EA 6 6-10 years 1 EA 6 6-10 years 2 EA 7 6-10 years 3 EA 7 6-10 years 3 EA 7 6-10 years 4 Flr inside parent room, woman's 4 EA 6 6-10 years 5 EA 7 6-10 years 6 EA 7 6-10 years 7 EA 6 6-10 years 8 EA 7 6-10 years 8 EA 8 6 6-10 years 8 EA 8 EA 8 6 6-10 years								
Floor - Tile Lavatory Lavatory Lighting - Pendent/Surface Partitions Substitute of the state of						_		
Lavatory Lighting - Pendent/Surface 1st flr inside parent room, woman's 1 EA 6 6-10 years 1 EA 6 6-10 years 1 EA 6 6-10 years 2 EA 7 6-10 years 324 SF 6 10+ years 4 Valls - Concrete Block 4 SF 6 10+ years 4 Valls - Concrete Block 5 SF 6 10+ years 8 Valls - Concrete Block 8 SF 6 10+ years 9 SF 6 10+ years							•	
Lighting - Pendent/Surface 1st flr inside parent room, woman's 1 EA 6 6-10 years Partitions 1st flr inside parent room, woman's 2 EA 7 6-10 years Walls - Concrete Block 1st flr inside parent room, woman's 324 SF 6 10+ years Water Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years						_		
Partitions 1st flr inside parent room, woman's 2 EA 7 6-10 years  Walls - Concrete Block 1st flr inside parent room, woman's 324 SF 6 10+ years  Water Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years								
Walls - Concrete Block 1st flr inside parent room, woman's 324 SF 6 10+ years Water Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years		•						
Water Closet 1st flr inside parent room, woman's 2 EA 6 6-10 years								
						_		
Accessories 1st iii restroom 145 112 SF / 6-10 years			·					
		Accessories	151 111 1621100111 143	112	SF	1	o- to years	



Catego	Category : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st flr restroom 145	112	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr restroom 145	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st flr restroom 145	112	SF	6	10+ years	
	Lavatory	1st flr restroom 145	2	EA	7	6-10 years	
	Lighting - Wall Mounted	1st flr restroom 145	2	EA	7	6-10 years	
	Partitions	1st flr restroom 145	2	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st flr restroom 145	187	SF	6	10+ years	
	Water Closet	1st flr restroom 145	2	EA	7	10+ years	
	Accessories	1st flr unisex restroom	112	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr unisex restroom	112	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st flr unisex restroom	1	EA	6	6-10 years	
	Floor - Tile	1st flr unisex restroom	112	SF	6	6-10 years	
	Lavatory	1st flr unisex restroom	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st flr unisex restroom	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st flr unisex restroom	187	SF	6	6-10 years	
	Water Closet	1st flr unisex restroom	1	EA	7	6-10 years	
	Accessories	2nd Floor	328	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	328	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	328	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	
	Partitions	2nd Floor	6	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	441	SF	6	10+ years	
	Water Closet	2nd Floor	6	EA	6	6-10 years	
	Accessories	2nd Floor	269	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	269	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	269	SF	6	10+ years	
	Floor Drain	2nd Floor	1	ĒΑ	7	10+ years	
	Lavatory	2nd Floor	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	
	Partitions	2nd Floor	2	EA	7	6-10 years	
	Urinals	2nd Floor	5	ĒΑ	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	325	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	6-10 years	
	Accessories	3rd Floor	328	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	328	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	328	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	6	6-10 years	
	Lighting 1 ondone oundoo	014 1 1001	2	_/\	J	o io youis	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	3rd Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	441	SF	6	10+ years	
	Water Closet	3rd Floor	6	EA	6	6-10 years	
	Accessories	3rd Floor	269	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	269	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	269	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	6	6-10 years	
	Partitions	3rd Floor	2	EA	7	6-10 years	
	Urinals	3rd Floor	5	EA	6	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor	325	SF	6	10+ years	
	Water Closet	3rd Floor	2	EA	6	6-10 years	
	Accessories	3rd Flr Faculty Unisex restroom	95	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Flr Faculty Unisex restroom	95	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Flr Faculty Unisex restroom	1	ĒΑ	6	6-10 years	
	Floor - Tile	3rd Flr Faculty Unisex restroom	95	SF	6	6-10 years	
	Lavatory	3rd Flr Faculty Unisex restroom	1	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd Flr Faculty Unisex restroom	1	ĒΑ	7	6-10 years	
	Partitions	3rd Flr Faculty Unisex restroom	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd Flr Faculty Unisex restroom	159	SF	7	6-10 years	
	Water Closet	3rd Flr Faculty Unisex restroom	1	EA	7	6-10 years	
	Accessories	Faculty Men's, 1st Floor	95	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Faculty Men's, 1st Floor	95	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty Men's, 1st Floor	1	EA	6	6-10 years	
	Floor - Tile	Faculty Men's, 1st Floor	95	SF	6	10+ years	
	Lavatory	Faculty Men's, 1st Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Faculty Men's, 1st Floor	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Faculty Men's, 1st Floor	1	EA	6	6-10 years	
	Partitions	Faculty Men's, 1st Floor	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Faculty Men's, 1st Floor	159	SF	6	10+ years	
	Water Closet	Faculty Men's, 1st Floor	1	EA	6	6-10 years	
	Accessories	Faculty Restroom in Room 107	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Faculty Restroom in Room 107	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty Restroom in Room 107	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Faculty Restroom in Room 107	32	SF	6	10+ years	
	Lavatory	Faculty Restroom in Room 107	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Faculty Restroom in Room 107	1	EA	7	6-10 years	
	Walls - Concrete Block	Faculty Restroom in Room 107	68	SF	6	10+ years	
	Water Closet	Faculty Restroom in Room 107	1	EA	6	6-10 years	
	Accessories	Faculty Women's, 2nd Floor	95	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Faculty Women's, 2nd Floor	95 95	SF SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty Women's, 2nd Floor	95	EA	6	6-10 years	
	Doors - Wood Doors Illou IIW	i acuity violineirs, zhu riooi	1	ĽA	U	U-10 years	



Catego	ry : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Faculty Women's, 2nd Floor	95	SF	6	10+ years	
	Lavatory	Faculty Women's, 2nd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Faculty Women's, 2nd Floor	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Faculty Women's, 2nd Floor	1	EA	6	6-10 years	
	Partitions	Faculty Women's, 2nd Floor	2	EA	7	6-10 years	
	Walls - Concrete Block	Faculty Women's, 2nd Floor	159	SF	6	10+ years	
	Water Closet	Faculty Women's, 2nd Floor	2	EA	6	6-10 years	
	Accessories	In Kitchen Manager's Office	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Kitchen Manager's Office	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Kitchen Manager's Office	1	EA	6	6-10 years	
	Floor - Tile	In Kitchen Manager's Office	20	SF	6	10+ years	
	Lavatory	In Kitchen Manager's Office	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	In Kitchen Manager's Office	1	EA	6	6-10 years	
	Walls - Concrete Block	In Kitchen Manager's Office	67	SF	6	10+ years	
	Water Closet	In Kitchen Manager's Office	1	EA	6	6-10 years	
	Accessories	In Room 109	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 109	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Room 109	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	In Room 109	54	SF	6	10+ years	
	Floor Drain	In Room 109	1	EA	7	10+ years	
	Lavatory	In Room 109	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	In Room 109	1	EA	6	6-10 years	
	Walls - Concrete Block	In Room 109	89	SF	6	10+ years	
	Water Closet	In Room 109	1	EA	6	6-10 years	
	Accessories	Unisex restroom 3rd Floor	95	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex restroom 3rd Floor	95	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex restroom 3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	Unisex restroom 3rd Floor	94	SF	6	2-5 years	
	Floor - Tile	Unisex restroom 3rd Floor	1	SF	4	0-1 year	Missing tile
	Lavatory	Unisex restroom 3rd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Unisex restroom 3rd Floor	1	EA	6	2-5 years	
	Lighting - Wall Mounted	Unisex restroom 3rd Floor	1	EA	6	2-5 years	
	Partitions	Unisex restroom 3rd Floor	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Unisex restroom 3rd Floor	159	SF	6	10+ years	
	Water Closet	Unisex restroom 3rd Floor	1	EA	6	6-10 years	
	Accessories	Women Rest Room, 2nd Floor	95	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women Rest Room, 2nd Floor	95	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women Rest Room, 2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	Women Rest Room, 2nd Floor	95	SF	6	10+ years	
	Floor Drain	Women Rest Room, 2nd Floor	1	EA	7	10+ years	
	Lavatory	Women Rest Room, 2nd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Women Rest Room, 2nd Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	Women Rest Room, 2nd Floor	159	SF	6	10+ years	
	Water Closet	Women Rest Room, 2nd Floor	1	EA	6	6-10 years	
						-	



Juiculi	ry : Room		Building : Main					
				ananig	. IVICIII	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
O. Cup	Accessories	restroom in 113	40	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	restroom in 113	40	SF	6	10+ years		
	Doors - Wood Doors inclu hw	restroom in 113	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	restroom in 113	40	SF	7	10+ years		
	Lavatory	restroom in 113	1	EA	7	10+ years		
	•		1		7			
	Lighting - Lay-in	restroom in 113	1	EA		6-10 years		
	Walls - Concrete Block	restroom in 113	280	SF	7	10+ years		
	Water Closet	restroom in 113	1	EA	7	10+ years		
Catego	ry : Classroom		В	uilding	: Main			
0	Name Tama	Iti	0	LIOM	Danila	Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #101 (Counseling Room)	4-4-51	700			40		
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years		
	Doors - Transom Window	1st Floor	1	SF	6	6-10 years		
	Floor - Tile	1st Floor	720	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	6	2-5 years		
	Marker Board	1st Floor	12	LF	6	6-10 years		
	Walls - Concrete Block	1st Floor	986	SF	6	10+ years		
Classros	m #102 (Laboratory/Shop)							
Classiuu		4 of Eleca	4	ГΛ	7	C 40		
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	22	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	1,122	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years		
	Floor - Tile	1st Floor	1,122	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	24	EA	6	6-10 years		
	Marker Board	1st Floor	16	LF	6	6-10 years		
	Storage/ Closet	1st Floor	72	SF	7	6-10 years		
	Walls - Concrete Block	1st Floor	1,009	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	5	6-10 years		
Classroo	m #103 (Store Room)							
	Ceiling - Plaster/Drywall	1st Floor	558	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Floor - Tile	1st Floor	558	SF	6	10+ years		
		1st Floor		EA				
	Lighting - Pendent/Surface		7		6	6-10 years		
	Marker Board	1st Floor	12	LF	6	6-10 years		
	Storage/ Closet	1st Floor	36	SF	7	6-10 years		
	Walls - Concrete Block	1st Floor	750	SF	6	10+ years		
Classroo	m #105 (Computer Lab)							
	AC Units	1st Floor	2	EA	7	6-10 years		



Category : Classroom			В				
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Doors - Store Front	1st Floor	1	EΑ	6	6-10 years	
	Floor - Tile	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EΑ	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	986	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
_Classroo	m #106 (Regular Classroom)						
	Casework	1st Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	1st Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	866	SF	6	10+ years	
	Work Sink	1st Floor	1	EΑ	5	6-10 years	
Classroo	m #107 (Kindergarten)						
<u> </u>	Casework	1st Floor	56	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	960	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	960	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,107	SF	6	10+ years	
	Work Sink	1st Floor	1,107	EA	5	6-10 years	
Classroo	m #108 (Regular Classroom)						
<u></u>	Casework	1st Floor	30	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	SF EA	6	6-10 years	
	Floor - Tile	1st Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	SF EA	6	6-10 years	
	Marker Board	1st Floor 1st Floor	16	LF	6	6-10 years 6-10 years	
	Storage/ Closet	1st Floor	52	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	52 866	SF			
	Work Sink	1st Floor	1	SF EA	6 5	10+ years	
	VVOIR SIIIK	181 11001	1	EA	5	6-10 years	
_Classroo	m #109 (Pre School)						

Campus Name: Wadsworth Page : 16 of 28 Assessment Date: 08/11/2021



Catego	Category : Classroom		В	uilding	: Main		6000 & Ellis AVENOE, Glileago, IE 60007
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	56	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	960	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	6-10 years	
	Floor - Tile	1st Floor	960	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EΑ	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	960	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
Classroo	nm #110 (Regular Classroom)						
	Casework	1st Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	52	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	866	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
Oldooroc	Casework	2nd Floor	24	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	•	
	Storage/ Closet			SF	7	6-10 years	
		2nd Floor	42	SF SF	·=	6-10 years	
	Walls - Concrete Block	2nd Floor	864	51	6	10+ years	
Classroo	om #203/201 (Library)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	66	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,430	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	1,430	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	37	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,544	SF	6	10+ years	
Classroo	nm #204 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	813	SF	6	10+ years	
	gac.c., 21,a		310	٥.	Ü	. o . youro	



Catego	ry : Classroom		В	uilding	: Main		6050 & Ellis AVENOE, Officago, IE 60657
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	42	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	864	SF	6	10+ years	
_Classroo	om #205 (Regular Classroom)						
	Casework	2nd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block			SF SF	6		
	Walls - Concrete block	2nd Floor	986	SF	0	10+ years	
Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	42	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	864	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	Casework	2nd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	6-10 years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
				_	-		
	Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor	16	EA	6	6-10 years	
			16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	986	SF	6	10+ years	
Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	813	SF	6	10+ years	
	,					,	



Catego	ry : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	42	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	864	SF	6	10+ years	
Classroo	om #209 (Counseling Room)						
	Casework	2nd Floor	16	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	348	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	348	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	6		
			o 12	LF	_	6-10 years	
	Marker Board	2nd Floor			6	6-10 years	
	Walls - Concrete Block	2nd Floor	712	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	42	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	864	SF	6	10+ years	
Classroo	om #211 (Regular Classroom)						
	Casework	2nd Floor	16	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	6-10 years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	•	
					_	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	986	SF	6	10+ years	
Classroo	om #212 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		6630 S Ellis AVENUE, Chicago, IL 60637
J.						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	42	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	864	SF	6	10+ years	
Classroo	om #213 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	720	SF	6	10+ years	
Classroo	om #214 (Special Education)						
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	577	SF	6	10+ years	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	577	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	486	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	243	SF	6	10+ years	
Classro	om #301 (Regular Classroom)						
Classion	Casework	3rd Floor	28	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall		720	SF		•	
		3rd Floor		LF	6	10+ years	
	Chalk Board Doors - Wood Doors inclu hw	3rd Floor	16	EA	4	2-5 years	
		3rd Floor	1		6	6-10 years	
	Floor - Tile	3rd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	2-5 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	986	SF	6	10+ years	
Classroo	om #302 (Regular Classroom)						
	Casework	3rd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	813	SF	6	10+ years	
	Chalk Board	3rd Floor	25	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	



	pry : Classroom		R	uilding	· Main		6030 3 EIIIS AVENUE, CHICAGO, IL 60637
Catego	ny . Glassicom			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
О.О	Storage/ Closet	3rd Floor	42	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	864	SF	6	10+ years	
						, , , , , ,	
_Classro	om #303 (Science Classroom)						
	Casework	3rd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	3rd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	986	SF	6	10+ years	
01	#004 (Off:)						
_Classroo	om #304 (Office)  Casework	3rd Floor	24	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	813	SF	6	10+ years	
			1			•	
	Doors - Wood Doors inclu hw Floor - Tile	3rd Floor 3rd Floor	813	EA SF	6 6	6-10 years 10+ years	
		3rd Floor	16				
	Lighting - Pendent/Surface	3rd Floor	32	EA LF	6 6	6-10 years	
	Marker Board		32 42	SF	-	6-10 years	
	Storage/ Closet	3rd Floor	42 864	SF SF	7 6	6-10 years	
	Walls - Concrete Block	3rd Floor	004	SF	О	10+ years	
Classro	om #305 (Regular Classroom)						
	Casework	3rd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	3rd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	986	SF	6	10+ years	
01.	#200 (Demules Classes)						
Liassro	om #306 (Regular Classroom)	Ond Ele				0.40	
	Casework	3rd Floor	30	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	42	SF	7	6-10 years	



Catego	ory : Classroom		В	uilding	: Main		0000 0 Ellis AVENOE, Chicago, le 00007
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor	864	SF	6	10+ years	
Classro	om #307 (Regular Classroom)						
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	6-10 years	
	Floor - Tile	3rd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	986	SF	6	10+ years	
	201101010 210011	0.0.1.00.		О.	· ·	.o. you.o	
_Classro	om #308 (Regular Classroom)						
	Casework	3rd Floor	26	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	42	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	864	SF	6	10+ years	
Classro	om #309 (Regular Classroom)						
	Casework	3rd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	3rd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	986	SF	6	10+ years	
Classro	om #310 (Art Room)						
CidaalU	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	813	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	6-10 years	
	Floor - Tile	3rd Floor		SF	6	10+ years	
	Instructional Surface		813 8	SF LF	6	,	
		3rd Floor	16	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	О	6-10 years	



Catego	Category : Classroom		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	42	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	864	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	5	6-10 years	
Classroc	om #311 (Regular Classroom)						
	Casework	3rd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	700	SF	6	10+ years	
	Floor - Tile	3rd Floor	20	SF	5	1-2 years	Water damage
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	vvator damago
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	986	SF	6	10+ years	
	Walls - Coliciete Block	Sid Floor	900	Si	O	10+ years	
Classroc	om #312 (Computer Lab)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	813	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	864	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
Classroc	om #313 (Music Room)						
	Casework	3rd Floor	28	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	986	SF	6	10+ years	
Classras	om #314 (Office)						
CIGSSIUC	• •	2rd Floor	24	1.5		6.10 years	
	Casework	3rd Floor	24	LF CF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	558	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	558	SF	6	10+ years	



Catego	ry : Classroom		В				
	_					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	484	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	242	SF	6	10+ years	
atego	ry : Interior		В	uilding	: Main		
	<del></del>	•	0			Recommend	•
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	3,304	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	5	EA	6	6-10 years	
	Doors - Store Front	1st Floor	2	EA	6	6-10 years	
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	684	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	3,304	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	42	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,662	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,224	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,464	SF	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	2,464	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	28	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,225	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,449	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,464	SF	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	1	ĒΑ	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	2,464	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	28	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,225	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	2,449	SF	6	10+ years	
	Walle Structural Glazea File	014 1 1001	2,110	O.	Ü	io. you.o	
afety							
	Camera Viewing Station	Entire building	2	EA	7	6-10 years	
	Metal Dedector	Entire building	1	EA	7	6-10 years	
	Security Cameras	Entire building	8	EA	7	6-10 years	
	Security Cameras	Entire building	4	EA	7	6-10 years	
tairs							
	Ceiling - Plaster/Drywall	North	356	SF	6	10+ years	
	Floor - Terrazzo	North	310	SF	6	10+ years	
	Handrails	North	128	LF	7	6-10 years	
	Lighting - Pendent/Surface	North	4	ĒΑ	6	6-10 years	
	Stairs - Terrazzo	North	60	LF	6	10+ years	
	Stand Fortuzzo	110101	00	_1	0	101 yours	



Category : Interior			В	uilding				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	North	980	SF	6	10+ years		
	Walls - Structural Glazed Tile	North	980	SF	6	10+ years		
	Ceiling - Plaster/Drywall	South	238	SF	6	10+ years		
	Floor - Terrazzo	South	180	SF	6	10+ years		
	Handrails	South	128	LF	7	6-10 years		
	Lighting - Pendent/Surface	South	3	EA	6	6-10 years		
	Lighting - Wall Mounted	South	1	EA	6	6-10 years		
	Stairs - Terrazzo	South	60	LF	6	10+ years		
	Walls - Structural Glazed Tile	South	1,832	SF	6	10+ years		
_Vertical (	Conveyance							
	Elevator - Elevator- Roped Holeless Hydraulic		1	EA	6	6-10 years		
	Wheelchair Lift - Chair Lift		1	EA	7	6-10 years		

Campus Name: Wadsworth Page : 25 of 28 Assessment Date: 08/11/2021





Category : Site **Building: Site** 

						Recommend	
<b>Group</b> Athletic	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Amienc_	Surface - Asphalt	North	3,938	SF	7	10+ years	
	Surface - Synthetic including exc & retention	North	16,268	SF	7	10+ years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	10+ years	
encing							
	Fencing - Chain Link	Entire Site	200	LF	4	1-2 years	Fence is old, rusted and damaged
	Fencing - Chain Link	Entire Site	878	LF	4	0-1 year	
	Fencing - Iron and Concrete Post	Entire Site	120	LF	7	10+ years	This is a tall mesh with steel posts, good condition
	Fencing - New Standard Ornamental	Entire Site	250	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	5	1-2 years	(2)10 foot lengths of damaged area
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	289	LF	7	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	20	LF	5	1-2 years	Wood fence is missing several slats See engineer survey, vandalism
Landscar	De .						
	Landscape - Grass	Entire Site	5,259	SF	6	6-10 years	
	Landscape - Hardscape- Asphalt	Entire Site	6,959	SF	5	2-5 years	
	Landscape - Mulch	Entire Site	1,000	SF	5	2-5 years	Only weeds Grow here
	Parkway trees	Entire Site	24	EA	6	10+ years	•
	Parkway trees	Entire Site	1	EA	6	1-2 years	Tree is pushing the building
	Parkway trees	Entire Site	3	EA	4	2-5 years	Missing Parkway trees
	Planting Beds/ Area	Entire Site	5,815	SF	6	6-10 years	•
	Play Area - Hardscape- Asphalt	Entire Site	3,609	SF	7	10+ years	
	Trash Receptacles	Entire Site	3	EA	7	6-10 years	
Parking L	ot						
· ·	Surface - Asphalt	Parking Lot- South	5,000	SF	4	2-5 years	Parking lot surface is not draining properly with areas of ponding, alligator surface and sunken areas with potholes
	Surface - Asphalt	Parking Lot- West	2,000	SF	7	6-10 years	•
	Surface - Asphalt	Parking Lot- West	2,993	SF	5	2-5 years	Alligatored surfsce
	Trash Enclosure - Chain Links	Parking Lot- West	500	SF	6	6-10 years	-
	Trash Enclosure - Chain Links	Parking Lot- West	80	SF	5	1-2 years	Broken hinge at chain-link fence



Catego	ry : Site	В	uilding	,			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Equipment - Pre K 3-5	North	1	EA	7	10+ years	
	Equipment - School Age 5-12	North	1	EA	7	10+ years	
	Surface - Poured Surface	North	6,208	SF	7	10+ years	
Sidewall	KS						
	Sidewalks - Internal Walks	Entire Site	254	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	15	LF	4	1-2 years	Sidewalk is a key and it does not meet the perimeter sidewalk at the same level
	Sidewalks - Perimeter Sidewalks	Entire Site	852	SF	6	10+ years	partially fixed
	Sidewalks - Perimeter Sidewalks	Entire Site	14,333	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,000	SF	4	1-2 years	Buckling and cracked sidewalks
_Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	6-10 years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Classiconi Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	3rd Floor	310	310	813	176	56	Υ	N
Computer Lab	Regular Classroom	1st Floor	105	105	720	103	56	Υ	N
Computer Lab	Regular Classroom	3rd Floor	312	312	813	176	56	Υ	N
Counseling Room	Regular Classroom	1st Floor	101	101	720	110	56	Υ	Υ
Counseling Room	Regular Classroom	2nd Floor	209	209	348	55	28	Υ	N
Kindergarten	Kindergarten	1st Floor	107	107	960	330	168	N	N
Laboratory/Shop	Regular Classroom	1st Floor	102	102 + 104	1,122	264	84	Y	N
Library	Regular Classroom	2nd Floor	203/201	203	1,430	205	116	Y	N
Music Room	Regular Classroom	3rd Floor	313	313	720	110	56	Y	N
Office	Regular Classroom	3rd Floor	304	304	813	176	56	Y	N
Office	Regular Classroom	3rd Floor	314	314	558	176	56	Υ	N
Other Instructional Use	Other Instructional Use	2nd Floor	213	213	720	110	56	Υ	N
Pre School	Kindergarten	1st Floor	109	109	960	330	168	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	813	176	56	Y	N
Regular Classroom	Regular Classroom	1st Floor	108	108	813	176	56	Y	N
Regular Classroom	Regular Classroom	1st Floor	110	110	813	176	56	Y	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	813	176	56	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	813	176	56	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	720	110	56	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	813	176	56	Y	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	720	110	56	Y	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	813	176	56	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	813	176	56	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	720	110	56	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	813	176	56	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	720	110	56	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	302	813	176	56	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	305	720	110	56	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	306	813	176	56	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	720	110	56	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	813	176	56	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	720	110	56	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	720	110	56	Υ	N
Science Classroom	Regular Classroom	3rd Floor	303	303	720	110	56	Υ	Υ
Special Education	Regular Classroom	2nd Floor	214	214	577	176	56	Υ	N
Store Room	Regular Classroom	1st Floor	103	103	558	69	18	Υ	N