

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1896	3	68,500
Addition	1961	3	58,800
Linked Addition	1998	1	18,000
Campus Total			145,300

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	- ·		•				
	Exterior Doors - Exterior Steel Door	1 W	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	1 W	1	EA	6	6-10 years	
	Exterior Stairs - Stone	1 W	46	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	1.5 S	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	10.5 Coal Room	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	11 E	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	11 E	1	EA	5	2-5 years	Corroded
	Exterior Doors - Exterior Steel Door	12 east	1	EA	6	6-10 years	
	Exterior Doors - Side lite	12 east	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	13 N	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	13 N	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	14	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	14	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	14	63	LF	6	10+ years	
	Entrance Control - Audio and Video	15 Main Entrance	1	EA	7	2-5 years	
	Exterior Doors - Exterior Steel Door	15 Main Entrance	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	15 Main Entrance	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	15 Main Entrance	63	LF	6	10+ years	Reaggregated quantities
	Exterior Doors - Exterior Steel Door	2nd & 3rd Floor Fire Escape	1	EA	5	0-1 year	Vines overgrown, door doesn't open
	Exterior Doors - Exterior Steel Door	2nd & 3rd Floor Fire Escape	1	EA	5	0-1 year	Vines overgrown, door doesn't open
	Exterior Doors - Transom Lite	2nd & 3rd Floor Fire Escape	2	EA	6	6-10 years	
		·				•	



Catego	ry : Exterior		В	uilding	: Main				
	_					Recommend			
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
re Esca									
	Fire Escape	Coutyard, east facade	114	LF	6	6-10 years			
oundati		Fating Duilding	700	LF	7	10			
	Foundation - Masonry	Entire Building	780	LF LF	7	10+ years			
	Foundation - Masonry	Entire Building	15		6	10+ years			
	Superstructure - Heavy Timber	Entire Building	68,500	SF	7	10+ years			
ighting									
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	22	EA	6	6-10 years			
oof Sys	etem								
oor oy.	Coping - Stone	#1 N Courtyard SE Roof	21	LF	6	6-10 years			
	Downspouts - Interior Downspouts	#1 N Courtyard SE Roof	15	LF	6	6-10 years			
	Parapet - 16" - 30" Height	#1 N Courtyard SE Roof	21	LF	6	10+ years			
	Roof - Modified Bitumen	#1 N Courtyard SE Roof	113	SF	6	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	#1 N Courtyard SE Roof	113	SF	7	10+ years			
	Coping - Stone	#11 Roof	26	LF	6	10+ years			
	Downspouts - Interior Downspouts	#11 Roof	24	LF	6	6-10 years			
	Parapet - 16" - 30" Height	#11 Roof	26	LF	6	10+ years			
	Roof - Modified Bitumen	#11 Roof	251	SF	6	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	#11 Roof	251	SF	7	10+ years			
	Coping - Stone	#12 Roof	13	LF	6	10+ years			
	Downspouts - Interior Downspouts	#12 Roof	15	LF	6	6-10 years			
	Parapet - 16" - 30" Height	#12 Roof	13	LF	6	6-10 years			
	Roof - Modified Bitumen	#12 Roof	518	SF	6	,			
	Roof Structure - Steel with Clay Tile Arch		518	SF	7	6-10 years			
	•	#12 Roof				10+ years			
	Access Ladder - Metal	#13 S Upper Roof	1	EA	7	6-10 years			
	Coping - Terra Cotta	#13 S Upper Roof	285	LF	6	10+ years			
	Downspouts - Exterior Downspouts	#13 S Upper Roof	216	LF	6	6-10 years			
	Parapet - Parapet > 30"	#13 S Upper Roof	285	LF	6	10+ years			
	Roof - Modified Bitumen	#13 S Upper Roof	4,732	SF	6	6-10 years			
	Roof Hatch - Metal	#13 S Upper Roof	1	EA	7	6-10 years			
	Roof Structure - Heavy Timber	#13 S Upper Roof	4,732	SF	7	10+ years			
	Access Ladder - Metal	#14 Upper Middle Roof	2	EA	7	10+ years			
	Access Ladder - Wood	#14 Upper Middle Roof	1	EA	3	2-5 years	In attic		
	Coping - Terra Cotta	#14 Upper Middle Roof	282	LF	6	10+ years			
	Downspouts - Exterior Downspouts	#14 Upper Middle Roof	40	LF	6	6-10 years			
	Parapet - 16" - 30" Height	#14 Upper Middle Roof	30	LF	6	6-10 years			
	Parapet - Parapet > 30"	#14 Upper Middle Roof	252	LF	6	6-10 years			
	Roof - Modified Bitumen	#14 Upper Middle Roof	4,954	SF	6	6-10 years			
	Roof Hatch - Metal	#14 Upper Middle Roof	1	EA	7	10+ years	Reassessed		



tegor	y : Exterior		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Heavy Timber	#14 Upper Middle Roof	4,954	SF	7	10+ years	
	Access Ladder - Metal	#15 N Upper Roof	1	EA	7	10+ years	Functional, just not used much
	Coping - Terra Cotta	#15 N Upper Roof	216	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#15 N Upper Roof	216	LF	6	6-10 years	
	Parapet - Parapet > 30"	#15 N Upper Roof	216	LF	6	10+ years	
	Roof - Modified Bitumen	#15 N Upper Roof	5,214	SF	6	10+ years	
	Roof Hatch - Metal	#15 N Upper Roof	1	EA	7	10+ years	Functional, just not used much
	Roof Structure - Heavy Timber	#15 N Upper Roof	5,214	SF	7	10+ years	
	Coping - Stone	#16 Low NE Roof	30	LF	6	10+ years	
	Coping - Terra Cotta	#16 Low NE Roof	30	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#16 Low NE Roof	12	LF	6	6-10 years	
	Parapet - 16" - 30" Height	#16 Low NE Roof	60	LF	6	10+ years	
	Roof - Modified Bitumen	#16 Low NE Roof	718	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	#16 Low NE Roof	718	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	#17 Low E Boiler Room Roof	70	LF	6	10+ years	
	Coping - Terra Cotta	#17 Low E Boiler Room Roof	256	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#17 Low E Boiler Room Roof	12	LF	5	2-5 years	
	Parapet - 16" - 30" Height	#17 Low E Boiler Room Roof	256	LF	6	10+ years	
	Roof - Modified Bitumen	#17 Low E Boiler Room Roof	3,106	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	#17 Low E Boiler Room Roof	3,106	SF	7	10+ years	
	Coping - Stone	#18 Low N Roof	31	LF	6	10+ years	
	Parapet - Parapet > 30"	#18 Low N Roof	31	LF	6	10+ years	
	Roof - Modified Bitumen	#18 Low N Roof	120	SF	5	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	#18 Low N Roof	120	SF	7	10+ years	
	Coping - Stone	#19 Mid N Roof	31	LF	6	6-10 years	
	Parapet - Parapet > 30"	#19 Mid N Roof	31	LF	6	10+ years	
	Roof - Modified Bitumen	#19 Mid N Roof	120	SF	5	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	#19 Mid N Roof	120	SF	7	10+ years	
	Coping - Stone	#4 Roof	12	LF	6	10+ years	
	Downspouts - Interior Downspouts	#4 Roof	15	LF	4	0-1 year	Not draining
	Parapet - 16" - 30" Height	#4 Roof	12	LF	6	10+ years	
	Roof - Modified Bitumen	#4 Roof	120	SF	5	0-1 year	Worn and damaged surface. Pond
	Roof Structure - Steel / Metal Deck/	#4 Roof	120	SF	6	10+ years	Trom and damaged canader rem
	Concrete Topping	<i>"</i> 1100!		O.	Ū	ioi youlo	
	Coping - Stone	#6 Auditorium Roof	262	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#6 Auditorium Roof	10	LF	6	6-10 years	
	Downspouts - Interior Downspouts	#6 Auditorium Roof	25	LF	6	6-10 years	
	Parapet - 16" - 30" Height	#6 Auditorium Roof	30	LF	6	10+ years	
	Parapet - Parapet < 16" Height	#6 Auditorium Roof	232	LF	6	10+ years	
	Roof - Modified Bitumen	#6 Auditorium Roof	3,690	SF	6	6-10 years	
	Roof Structure - Heavy Timber	#6 Auditorium Roof	3,690	SF	7	10+ years	

Campus Name: Yates Page : 3 of 52 Assessment Date: 09/20/2021



Category : Exterior

Richard Yates Elementary School 1839 N Richmond STREET, Chicago, IL 60647

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oloup	Canopy - Concrete/ Stucco	Entire Building	120	SF	6	10+ years	Comments
	Cheek-Wall - Stone	Entire Building	102	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	19,975	SF	6	10+ years	Reaggregated quantities
	Exterior Walls - Stone-Cut	Entire Building	12,680	SF	6	10+ years	Reaggregated quantities
	Exterior trails Storie Sut	Zimio Bananig	12,000	O.	Ū	ioi youro	rtoaggrogatoa quartitioo
_Windows	3						
	Guard - Guards perforated	Entire Building	1,131	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	312	SF	6	6-10 years	
	Lintels - Brick	Entire Building	130	LF	6	10+ years	
	Lintels - Steel	Entire Building	12	LF	6	10+ years	
	Lintels - Stone	Entire Building	616	LF	6	10+ years	
	Windows - Louver	Entire Building	30	SF	6	6-10 years	Not previously assessed
	Windows - Sash Aluminum	Entire Building	312	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,011	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
				, i		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Emergency A/C Power - Auditoium and Aisle Lighting	1st Floor	3	SF	6	6-10 years	
	Security System - CCTV	Entire Building	68,500	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	68,500	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and	Entire Building	2	EA	6	6-10 years	
	Aisle Lighting	· ·				•	
	Emergency Battery Packs - Corridors and	Entire Building	7	EA	6	6-10 years	
	Stairs	3				,	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	8	EA	2	6-10 years	The exit lights have no batteries and
		g	•	_, ,	_	0 .0 ,00.0	no backup generator
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	2	0-1 year	The exit lights have no batteries and no backup generator
	Exit Signs - Gym	Entire Building	2	EA	2	6-10 years	The exit lights have no batteries and no backup generator
	Exit Signs - Gym	Entire Building	6	EA	2	0-1 year	One of the units is missing the battery and the light source
_Main Se	vice						
	PA System	Entire Building	68,500	SF	5	10+ years	
_Power D	istribution						
_ OWELD	Lighting and Power Panels - 100 A	Entire Building	16	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	6-10 years	
	Lighting and Fower Fallets - Above 100 A	Little building	I	EA	′	o-10 years	

Building: Main



ALL S						183	9 N Richmond STREET, Chicago, IL 60647
Catego	ry : Electrical		В	uilding	: Main		
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	4	1-2 years	Old
	amp						
_							
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	68,500	SF	6	10+ years	
	Fire Alarm_System	Entire Building	68,500	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	4	0-1 year	Fire pump controller works but needs
							frequent maintenance
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Mechanical room	1	EA	4	1-2 years	Beyond service life
	тист этр 2000 гр		·		·	,	_ , , , , , , , , , , , , , , , , , , ,
Sprinkler	System						
_оринист	Dry Sprinkler System	Entire Building	68,500	SF	5	10+ years	
	Sprinkler Heads	Entire Building	68,500	SF	4	1-2 years	Beyond service life
	Sprinkler Piping	Entire Building	68,500	SF	5	10+ years	Boyona dorvido ino
	op.m.nor r ip.m.g	Zitano Banamg	00,000	O.	Ū	ioi youlo	
Catego	ry : Mechanical		В	uilding	: Main		
ou.ogo	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ling Systems						
_/\li_i i idid	Indoor Return Fans- Centrifugal Squirrel	1st Floor	1	EA	5	2-5 years	
	Cage - Greater than 20000 CFM	131 1 1001	'	LA	3	2-5 years	
	Air Handling Unit- Built Up- Single Zone-	Basement	1	EA	5	10+ years	
	Steam Coils - 15001 - 25000 cfm	Dasement	'	LA	3	10+ years	
	Air Intake	Basement	1	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Basement	5	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Basement	150	LF	6	10+ years	
	and Ducts	23011011	100		J	io. youro	
	Air Handling Unit- Built Up-Multi Zone-	Fan Room 1 & 2	1	EA	5	6-10 years	
	Double Delivery- Steam Coils - 30001 -			_, .	Ü	3 10 ,0010	
	45000 cfm						
	Air Intake	Fan Room 1 & 2	1	EA	6	10+ years	
	Auxiliaries - 30001 - 45000 cfm	Fan Room 1 & 2	1	EΑ	6	10+ years	
	Return Duct Work - Masonry and Ducts-	Fan Room 1 & 2	200	LF	5	6-10 years	
	Missing or Existing Shaft		200		•	3 .0 ,00.0	
	Zone Dampers	Fan Room 1 & 2	29	EA	6	6-10 years	The zone dampers have relatively
	r				-	,	new actuators
	Iomo: Votos		Dogo : E of E2				Accomment Date: 00/20/2021

Campus Name: Yates Page : 5 of 52 Assessment Date: 09/20/2021



Catego	ry : Mechanical		В	uilding	: Main		
			<u> </u>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy	etame						
Doner Gy	Piping - Condensate Pipe- Steel	Entire Building	800	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Entire Building	800	LF	5	10+ years	
	Steam Traps	Entire Building	30	EA	5	6-10 years	
	Vacuum Pump	Entire Building	1	EA	6	6-10 years	
Heating I	Devices						
	Unit Heater - Electric	Entire Building	1	EA	5	2-5 years	
	Unit Heater - Steam	Entire Building	1	EA	5	6-10 years	
	Fin Tube - Steam	Entire Building	52	LF	5	10+ years	
	Radiators - Steam	Entire Building	2	EA	5	10+ years	
	Radiators - Steam	Entire Building	1	EA	5	10+ years	
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	The units are now functional
		Entire Building	1	EA		2-5 years	The units are now functional
	Wall Heater - Electric		-		5	•	
	Wall Heater - Electric	Entire Building	6	EA	5	6-10 years	
empera	ture Control						
	DDC System	Entire Building	68,500	SF	4	0-1 year	Non functional
	Electric Thermostat	Entire Building	6	EA	5	10+ years	
	Thermostats - DDC	Entire Building	29	EA	4	1-2 years	Non functional
/entilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	5	6-10 years	
Categoi	ry : Plumbing		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate		MankariasID				0.40	
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500	Mechanical Room	1	EA	6	10+ years	
	Gallons						
Dining							
Piping	Domestic Dining Hot Water Beturn Lines	Entire Building	60 500	- CE	6	10 L VOORS	
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Entire Building	68,500	SF	6	10+ years	
	LIOMASTIC PINING-HOT WATER RATIUM RISARS	Entire Building	68,500	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	68,500	SF	6	10+ years	



Catego	ry : Plumbing		В	uilding	: Main		•
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	68,500	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	68,500	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	68,500	SF	6	10+ years	
	Sanitary Piping	Entire Building	68,500	SF	6	10+ years	
	Storm Piping	Entire Building	68,500	SF	6	10+ years	
	Vent Piping	Entire Building	68,500	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	5	6-10 years	

Building · Main

Catego	ry : Room		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminis	rative Suites/Offices						
	AC Unit	1st - 106 Office	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - 106 Office	759	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - 106 Office	1	EΑ	6	10+ years	
	Floor - Wood	1st - 106 Office	759	SF	7	10+ years	
	Lighting - Pendent/Surface	1st - 106 Office	14	EA	6	6-10 years	
	Power Distribution	1st - 106 Office	15	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st - 106 Office	338	SF	6	10+ years	
	Walls - Plaster/Drywall	1st - 106 Office	1,031	SF	6	10+ years	
	AC Unit	1st Clerk Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Clerk Office	365	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Clerk Office	1	EA	6	10+ years	
	Floor - Tile	1st Clerk Office	365	SF	6	10+ years	
	Lighting - Lay-in	1st Clerk Office	4	EΑ	6	6-10 years	
	Power Distribution	1st Clerk Office	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Clerk Office	748	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd - Gym Office	168	SF	6	10+ years	
	Doors - Transom Window	3rd - Gym Office	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd - Gym Office	1	EA	6	10+ years	
	Floor - Tile	3rd - Gym Office	168	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd - Gym Office	5	EA	6	6-10 years	
	Power Distribution	3rd - Gym Office	2	EA	6	6-10 years	
	Storage/ Closet	3rd - Gym Office	5	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd - Gym Office	820	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd - Teachers Lounge	231	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd - Teachers Lounge	1	EA	6	10+ years	
	Floor - Tile	3rd - Teachers Lounge	231	SF	6	10+ years	

Campus Name: Yates Page : 7 of 52 Assessment Date: 09/20/2021



Catego	ry : Room		В	uilding	: Main		· • • ·
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd - Teachers Lounge	2	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	3rd - Teachers Lounge	5	EA	6	6-10 years	
	Power Distribution	3rd - Teachers Lounge	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd - Teachers Lounge	1,015	SF	6	10+ years	
	Work SInk	3rd - Teachers Lounge	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - 001 Teachers Lounge	447	SF	6	10+ years	
	Doors - Side-lite	Basement - 001 Teachers Lounge	3	SF	6	10+ years	
	Doors - Transom Window	Basement - 001 Teachers Lounge	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - 001 Teachers Lounge	1	EA	6	10+ years	
	Floor - Tile	Basement - 001 Teachers Lounge	447	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - 001 Teachers Lounge	8	EA	6	6-10 years	
	Power Distribution	Basement - 001 Teachers Lounge	6	EA	6	6-10 years	
	Walls - Masonry	Basement - 001 Teachers Lounge	867	SF	6	10+ years	
	Work Sink	Basement - 001 Teachers Lounge	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Room 003 social worker	320	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Room 003 social worker	1	EA	6	10+ years	
	Floor - Tile	Basement - Room 003 social worker	320	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - Room 003 social worker	5	EA	6	6-10 years	
	Power Distribution	Basement - Room 003 social worker	4	EA	6	6-10 years	
	Walls - Masonry	Basement - Room 003 social worker	519	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Room 003 social worker	135	SF	6	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main Office	196	SF	6	10+ years	
	Ceiling - Lay-in	Main Office	16	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Tile	Main Office	210	SF	6	10+ years	
	Lighting - Pendent/Surface	Main Office	2	EA	6	6-10 years	
	Power Distribution	Main Office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Main Office	639	SF	6	10+ years	
Auditoriu	ım & Theater						
	Ceiling - Lay-in	Basement	3,087	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	4	ĒΑ	6	10+ years	
	Floor - Tile	Basement	2,097	SF	6	10+ years	
	Floor - Wood	Basement	990	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	Basement	6	EA	7	6-10 years	
	Main Floor Seating	Basement	396	EA	7	10+ years	
	Sound System	Basement	1	EA	7	6-10 years	
	Stage	Basement	765	SF	6	10+ years	
	Stage Curtain	Basement	8	EA	7	6-10 years	
	Stage Lighting System	Basement	1	EA	7	6-10 years	
	Stage-Stairs - Wood	Basement	10	LF	6	10+ years	
	Stairs - Wood	Basement	10	LF	6	10+ years	
	Walls - Plaster/Drywall	Basement	4,708	SF	6	10+ years	
	,		,		-	,	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Basement	120	SF	5	1-2 years	Peeling
_Gymnas	ia						
	Ceiling - Splined	3rd Floor	6,291	SF	4	0-1 year	Missing and damaged
	Doors - Side-lite	3rd Floor	56	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	82	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Tile	3rd Floor	6,286	SF	6	6-10 years	
	Floor - Tile	3rd Floor	5	SF	4	0-1 year	Damaged missing
	Lighting - Pendent/Surface	3rd Floor	20	ĒA	6	6-10 years	3 3 3 3 3
	Storage/ Closet	3rd Floor	224	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,833	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,215	SF	4	0-1 year	Cracked / damage plaster
	,		, -			, , , , , ,	3.1
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement - 005 Parent's Room	694	SF	6	10+ years	
	Floor - Tile	Basement - 005 Parent's Room	694	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - 005 Parent's Room	16	EA	6	6-10 years	
	Storage/ Closet	Basement - 005 Parent's Room	251	SF	5	10+ years	
	Walls - Masonry	Basement - 005 Parent's Room	1,016	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - 005 Parent's Room	212	SF	6	10+ years	
	Ceiling - Exposed	Basement - Girls Playroom	806	SF	6	10+ years	
	Doors - Transom Window	Basement - Girls Playroom	24	SF	6	10+ years	
	Floor - Tile	Basement - Girls Playroom	806	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - Girls Playroom	20	EΑ	6	6-10 years	
	Storage/ Closet	Basement - Girls Playroom	256	SF	5	10+ years	
	Walls - Masonry	Basement - Girls Playroom	893	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Girls Playroom	214	SF	6	10+ years	
		2400		О.	· ·	.o. you.o	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	16	SF	5	10+ years	
	Storage Room	1st Floor	230	SF	7	10+ years	
	Janitor's Closet	2nd Floor	16	SF	5	10+ years	
	Janitor's Closet	3rd Floor	16	SF	5	10+ years	
	Storage Room	3rd Floor	325	SF	7	10+ years	
	Air Intake Plenums	Basement	1,093	SF	5	10+ years	
	Boiler Room	Basement	1,497	SF	5	6-10 years	
	Crawl Space - Unfinished	Basement	3,481	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	934	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	654	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	439	SF	5	10+ years	
	Storage Room	Basement	1,786	SF	5	10+ years	
	g- · · · · · · · · · · · · · · · ·	_ 200	.,. 00		ŭ	,	



Category : Room			В	uilding	: Main	183	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Restroon	n		_			_	
	Accessories	103	77	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	103	77	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103	2	EΑ	6	10+ years	
	Floor - Tile	103	38	SF	6	10+ years	
	Floor - Wood	103	37	SF	6	10+ years	
	Lavatory	103	1	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	103	1	EΑ	6	6-10 years	
	Partitions	103	1	EΑ	5	10+ years	
	Walls - Plaster/Drywall	103	50	SF	6	10+ years	
	Walls - Plaster/Drywall	103	416	SF	6	10+ years	
	Water Closet	103	1	EA	6	6-10 years	
	Accessories	2nd - Boys	111	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd - Boys	111	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd - Boys	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd - Boys	111	SF	6	10+ years	
	Floor Drain	2nd - Boys	1	EA	7	10+ years	
	Hand Dryer	2nd - Boys	1	EΑ	5	2-5 years	
	Lavatory	2nd - Boys	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd - Boys	2	EΑ	7	6-10 years	
	Partitions	2nd - Boys	2	EA	7	10+ years	
	Urinals	2nd - Boys	2	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd - Boys	119	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd - Boys	356	SF	6	10+ years	
	Water Closet	2nd - Boys	2	EA	6	6-10 years	
	Accessories	2nd - Girls	123	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	2nd - Girls	123	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd - Girls	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd - Girls	123	SF	6	10+ years	
	Floor Drain	2nd - Girls	1	EA	7	10+ years	
	Hand Dryer	2nd - Girls	1	EΑ	5	2-5 years	
	Lavatory	2nd - Girls	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd - Girls	3	EΑ	6	6-10 years	
	Partitions	2nd - Girls	3	EΑ	5	2-5 years	
	Walls - Plaster/Drywall	2nd - Girls	137	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd - Girls	271	SF	6	10+ years	
	Water Closet	2nd - Girls	3	EA	6	6-10 years	
	Accessories	3rd - Men inside Teachers lounge	24	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	3rd - Men inside Teachers lounge	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd - Men inside Teachers lounge	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd - Men inside Teachers lounge	24	SF	6	10+ years	
	Lavatory	3rd - Men inside Teachers lounge	1	EA	6	10+ years	
	Lighting - Wall Mounted	3rd - Men inside Teachers lounge	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd - Men inside Teachers lounge	49	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	3rd - Men inside Teachers lounge	108	SF	6	10+ years	
	Water Closet	3rd - Men inside Teachers lounge	1	EA	6	10+ years	
	Accessories	3rd - Women inside teachers lounge	24	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	3rd - Women inside teachers lounge	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd - Women inside teachers lounge	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd - Women inside teachers lounge	24	SF	6	10+ years	
	Lavatory	3rd - Women inside teachers lounge	1	EA	6	6-10 years	
	Lighting - Wall Mounted	3rd - Women inside teachers lounge	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd - Women inside teachers lounge	50	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd - Women inside teachers lounge	107	SF	6	10+ years	
	Water Closet	3rd - Women inside teachers lounge	1	EA	6	10+ years	
	Accessories	Assembly Hall	87	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Assembly Hall	87	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assembly Hall	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Assembly Hall	87	SF	6	10+ years	
	Lavatory	Assembly Hall	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Assembly Hall	1	EA	5	6-10 years	
	Partitions	Assembly Hall	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Assembly Hall	418	SF	5	10+ years	
	Water Closet	Assembly Hall	2	EA	6	6-10 years	
	Accessories	Assembly Hall	87	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Assembly Hall	87	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assembly Hall	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Assembly Hall	87	SF	6	10+ years	
	Floor Drain	Assembly Hall	1	EA	7	10+ years	
	Lavatory	Assembly Hall	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Assembly Hall	1	EA	5	6-10 years	
	Partitions	Assembly Hall	1	EA	5	10+ years	
	Urinals	Assembly Hall		EA	5	6-10 years	
	Walls - Plaster/Drywall	Assembly Hall	418	SF	5	10+ years	
	Water Closet	Assembly Hall	1	EA	6	6-10 years	
	Accessories	Basement - Boys Toilet	720	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Boys Toilet	720	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Boys Toilet	3	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement - Boys Toilet	720	SF	6	6-10 years	
	Floor Drain	Basement - Boys Toilet	2	EA	7	6-10 years	
	Hand Dryer	Basement - Boys Toilet	2	EΑ	5	6-10 years	
	Lavatory	Basement - Boys Toilet	4	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Basement - Boys Toilet	9	EΑ	6	6-10 years	
	Partitions	Basement - Boys Toilet	5	EΑ	5	10+ years	
	Urinals	Basement - Boys Toilet	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement - Boys Toilet	323	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement - Boys Toilet	752	SF	6	10+ years	
	Water Closet	Basement - Boys Toilet	5	EA	6	6-10 years	

Campus Name: Yates Page : 11 of 52 Assessment Date: 09/20/2021



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Basement - Girls Toilet	962	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Girls Toilet	962	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Girls Toilet	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - Girls Toilet	962	SF	6	10+ years	
	Floor Drain	Basement - Girls Toilet	2	EA	7	10+ years	
	Hand Dryer	Basement - Girls Toilet	2	EA	5	6-10 years	
	Lavatory	Basement - Girls Toilet	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement - Girls Toilet	8	EA	7	6-10 years	
	Partitions	Basement - Girls Toilet	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Girls Toilet	277	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement - Girls Toilet	644	SF	7	10+ years	
	Water Closet	Basement - Girls Toilet	12	EA	7	6-10 years	
	Accessories	Basement - Mens	151	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Mens	151	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Mens	2	EA	6	10+ years	
	Floor - Tile	Basement - Mens	151	SF	6	10+ years	
	Lavatory	Basement - Mens	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement - Mens	2	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement - Mens	1	EA	6	6-10 years	
	Partitions	Basement - Mens	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Mens	665	SF	6	10+ years	
	Water Closet	Basement - Mens	1	EA	6	6-10 years	
	Accessories	Basement - Women	190	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Women	190	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Women	2	EA	6	10+ years	
	Floor - Tile	Basement - Women	190	SF	6	10+ years	
	Lavatory	Basement - Women	1	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	Basement - Women	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement - Women	902	SF	6	10+ years	
	Water Closet	Basement - Women	1	ĒΑ	6	6-10 years	
	Accessories	Clerk Office	66	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Clerk Office	66	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Clerk Office	6	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Clerk Office	66	SF	6	10+ years	
	Lavatory	Clerk Office	1	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	Clerk Office	1	EA	6	6-10 years	
	Partitions	Clerk Office	1	EΑ	5	6-10 years	
	Walls - Plaster/Drywall	Clerk Office	359	SF	6	10+ years	
	Water Closet	Clerk Office	1	EA	6	6-10 years	
	Accessories	Restroom in 101	108	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in 101	108	SF	6	10+ years	
	Doors - Transom Window	Restroom in 101	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in 101	2	EA	6	10+ years	
	Floor - Tile	Restroom in 101	108	SF	6	10+ years	
	11001 1110	1.000.0011111101	100	J1	3	ioi youis	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Restroom in 101	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Restroom in 101	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Restroom in 101	506	SF	6	10+ years	
	Walls - Plaster/Drywall	Restroom in 101	85	SF	6	10+ years	
	Water Closet	Restroom in 101	1	EA	6	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
	-		0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #002 (Multi Purpose Room)						
	Ceiling - Plaster/Drywall	Basement	648	SF	6	10+ years	
	Chalk Board	Basement	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Tile	Basement	648	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	6	6-10 years	
	Walls - Masonry	Basement	819	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	230	SF	6	10+ years	
Classroo	om #004 (Other Instructional Use)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	744	SF	6	10+ years	
	Chalk Board	Basement	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Tile	Basement	744	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	13	EA	6	6-10 years	
	Walls - Masonry	Basement	754	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	333	SF	6	10+ years	
Classroo	om #006 (Other Instructional Use)						
	Ceiling - Plaster/Drywall	Basement	718	SF	6	10+ years	
	Chalk Board	Basement	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	2	ĒΑ	6	10+ years	
	Floor - Tile	Basement	718	SF	4	0-1 year	Damaged throughout
	Lighting - Pendent/Surface	Basement	11	EA	7	10+ years	
	Storage/ Closet	Basement	31	SF	5	10+ years	
	Walls - Masonry	Basement	764	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	248	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	20	SF	6	10+ years	
Classro	om #101 (Counseling Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	17	LF	6	•	
	Casework Ceiling - Plaster/Drywall	1st Floor	560	SF	6	10+ years 10+ years	
	· ·					•	
_							

Campus Name: Yates Page : 13 of 52 Assessment Date: 09/20/2021



	ry : Classroom		ь	uilding	: wain		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Ceiling - Plaster/Drywall	1st Floor	160	SF	5	0-1 year	Damaged
	Chalk Board	1st Floor	28	LF	4	2-5 years	•
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,150	SF	5	10+ years	
Classroo	om #102 (Store Room)						
	Casework	1st Floor	3	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	824	SF	5	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	824	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	90	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	280	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,094	SF	5	10+ years	
	Work Sink	1st Floor	1,004	EA	5	10+ years	
Classro	om #103 (Kindergarten)						
Classice	Casework	1st Floor	28	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	824	SF	5	•	
	Chalk Board	1st Floor	30	LF	4	10+ years	
	Doors - Transom Window	1st Floor	8	SF		2-5 years	
					6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	824	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	993	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	431	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
Classroo	om #104 (Regular Classroom)						
	Casework	1st Floor	3	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	824	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	824	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,014	SF	6	10+ years	

Campus Name: Yates Page : 14 of 52 Assessment Date: 09/20/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	360	SF	6	10+ years	
Classro	om #105 (Office)						
Classiu	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	3	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	824	SF	5	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood Books med hw	1st Floor	824	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	380	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,094	SF	6	10+ years	
	walis - i laster/brywali	131 1 1001	1,034	OI.	O	10+ years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	806	SF	6	6-10 years	
	Chalk Board	1st Floor	50	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	806	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	183	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	342	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,037	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	824	SF	5	0-1 year	Damaged, peeling throughout
	Chalk Board	1st Floor	43	LF	4	2-5 years	- amagaa, paamig amaagaaa
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	814	SF	5	10+ years	
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Chipped damaged
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	6	6-10 years	
	Storage/ Closet	1st Floor	172	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,070	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	346	SF	6	10+ years	
Classroo	om #109 (Regular Classroom)						
	,						

Campus Name: Yates Page : 15 of 52 Assessment Date: 09/20/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	11	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	762	SF	6	10+ years	
	Chalk Board	1st Floor	21	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	712	SF	5	10+ years	
	Floor - Tile	1st Floor	50	SF	4	0-1 year	Cracked and damaged floor tile
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	92	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,034	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	338	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	313	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	400	SF	5	0-1 year	Damaged, peeling throughout
	Chalk Board	2nd Floor	23	LF	4	2-5 years	- amagaa, pramig amaagaaa
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	713	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	6	6-10 years	
	Storage/ Closet	2nd Floor	87	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	907	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	323	SF	6	10+ years	
Classroo	m #202 (Computer Lab)						
Oldooloo	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	756	SF	6	10+ years	
	Chalk Board	2nd Floor	39	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	756	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	77	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,024	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	324	SF	6	10+ years	
Classus s	#202 (Basular Classes)						
Classroo	m #203 (Regular Classroom)	0 15				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	

Campus Name: Yates Page : 16 of 52 Assessment Date: 09/20/2021



atego	ry : Classroom		В	uilding	: Main		
_						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	822	SF	6	10+ years	
	Chalk Board	2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	822	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	218	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,061	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	346	SF	6	10+ years	
	nm #204 (Regular Classroom)					·	
199100	AC Units	2nd Floor	1	EA	7	6-10 years	
			1 5	LF			
	Casework	2nd Floor			6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	210	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	600	SF	5	0-1 year	Damaged, peeling throughout
	Chalk Board	2nd Floor	43	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	810	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	173	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	343	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	6	10+ years	
ssroo	nm #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	749	SF	5	0-1 year	Damaged, peeling throughout
	Chalk Board	2nd Floor	43	LF	4	2-5 years	Damagea, peemig imoughout
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor 2nd Floor	759	SF	6	10+ years	
					-		
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	155	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,022	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	338	SF	6	10+ years	
ssroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	762	SF	5	10+ years	
	,		30	LF	-	2-5 years	

Campus Name: Yates Page : 17 of 52 Assessment Date: 09/20/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	762	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	172	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	963	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	431	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	762	SF	5	6-10 years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood Bools inclu hw	2nd Floor	762	SF	6	10+ years	
					-		
	Lighting - Pendent/Surface	2nd Floor	14	EA SF	6 5	6-10 years	
	Storage/ Closet	2nd Floor	189			10+ years	
	Walls - Plaster/Drywall	2nd Floor	431	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	993	SF	6	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	3	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	824	SF	5	6-10 years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	824	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,070	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	431	SF	6	10+ years	
Classroo	om #209 (Regular Classroom)						
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	362	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	400	SF	5	0-1 year	Damaged, peeling throughout
	Chalk Board	2nd Floor	30	LF	4	2-5 years	Damagea, peeming unoughout
	Doors - Transom Window	2nd Floor	8	SF	6	-	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	0	Sr EA	6	10+ years	
						10+ years	
	Floor - Wood	2nd Floor	762	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	

Campus Name: Yates Page : 18 of 52 Assessment Date: 09/20/2021



Catego	ory : Classroom		В	uilding	: Main		The Michigan Control of Meeting of the Control of t
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	338	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,034	SF	6	10+ years	
Classroo	om #301 (Store Room)						
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	717	SF	6	10+ years	
	Chalk Board	3rd Floor	23	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	717	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	96	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	906	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	324	SF	6	10+ years	
	wane i lactor/21, wan	014 1 1001	021	O.	Ü	io: youro	
Classroo	om #302 (Vacant)						
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	765	SF	6	10+ years	
	Chalk Board	3rd Floor	34	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	765	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	86	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	339	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,024	SF	6	10+ years	
Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	742	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	30	SF	4	1-2 years	Water damage and pealing plaster/ paint
	Chalk Board	3rd Floor	43	LF	4	2-5 years	Panit
	Doors - Transom Window	3rd Floor	8	SF	5	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	10+ years	
	Floor - Tile	3rd Floor	750	SF	5	2-5 years	
	Floor - Tile	3rd Floor	20	SF	4	0-1 year	Damaged floor tile
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	178	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,523	SF	6	10+ years	
		3.350	1,020	٥.	Ü	.o. youro	

Campus Name: Yates Page : 19 of 52 Assessment Date: 09/20/2021



Outogo	ry : Classroom		В	uilding	: Main		9 N Richmond STREET, Chicago, IL 606
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #306 (Vacant)						
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	771	SF	5	10+ years	
	Chalk Board	3rd Floor	49	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	5	10+ years	
	Floor - Tile	3rd Floor	771	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	178	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,376	SF	6	10+ years	
Classroo	om #309 (Regular Classroom)						
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	772	SF	5	0-1 year	Damaged, peeling throughout
	Chalk Board	3rd Floor	16	LF	4	2-5 years	3 71 3 3
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	772	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	190	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,033	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
	uru i Intorior				· Main		
Catego	ry . Interior		В	uilding	. IVIAIII		
Catego	ry . Interior		В	uilding	. IVIAIII	Recommend	
	Item - Type	Location	B Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location		_			Comments
Group	Item - Type	Location 1st Floor		_			Comments
Group	Item - Type	2.200.2	Quantity	UOM	Rank	Replacement	Comments
Group	Item - Type Ceiling - Plaster/Drywall	1st Floor	Quantity 1,170	UOM	Rank 6	Replacement 10+ years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st Floor 1st Floor	Quantity 1,170 10	SF EA EA SF	Rank 6 6	10+ years 10+ years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler	1st Floor 1st Floor 1st Floor	1,170 10 3	SF EA EA SF EA	Rank 6 6 5	10+ years 10+ years 6-10 years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood	1st Floor 1st Floor 1st Floor 1st Floor	1,170 10 3 1,170	SF EA EA SF EA SF	6 6 5 6	10+ years 10+ years 6-10 years 10+ years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,170 10 3 1,170 16	SF EA EA SF EA	6 6 5 6	10+ years 10+ years 6-10 years 10+ years 6-10 years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,170 10 3 1,170 16 1,360	SF EA EA SF EA SF SF SF	6 6 5 6 6 6	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,170 10 3 1,170 16 1,360 41	SF EA EA SF EA SF SF	6 6 5 6 6 6 6	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Wood	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor	1,170 10 3 1,170 16 1,360 41 41	SF EA EA SF EA SF SF SF	6 6 5 6 6 6 6 6	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years 6-10 years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor	1,170 10 3 1,170 16 1,360 41 41 1	SF EA SF EA SF SF SF SF EA	6 6 6 6 6 6	10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years 6-10 years 10+ years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,170 10 3 1,170 16 1,360 41 41	SF EA SF EA SF SF SF SF EA SF	8 6 6 6 6 6 6 6 6 6	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years 6-10 years 10+ years 10+ years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor	1,170 10 3 1,170 16 1,360 41 41 1 274 2,103	SF EA SF EA SF SF SF SF SF SF	8 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years 6-10 years 10+ years 6-10 years	Comments
Group	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Wood	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor	1,170 10 3 1,170 16 1,360 41 41 1 274 2,103	SF EA SF EA SF SF SF EA SF EA	8 6 6 6 6 6 6 5 5	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
Catego Group Corridor	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Drinking Fountains - Single Water Cooler Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Wood Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor	1,170 10 3 1,170 16 1,360 41 41 2,74 2,103 4 2,103	SF EA SF EA SF SF SF EA SF SF EA SF	Rank 6 6 5 6 6 6 6 6 6 6 6 6 6	10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 2-5 years 10+ years 6-10 years 10+ years 6-10 years	Comments



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement	4,827	SF	6	10+ years	
	Floor - Concrete	Basement	1,420	SF	5	10+ years	
	Floor - Terrazzo	Basement	270	SF	6	10+ years	
	Floor - Tile/Sheet	Basement	3,137	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement	28	EA	6	6-10 years	
	Walls - Masonry	Basement	4,293	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	2,959	SF	6	10+ years	
Safety							
•	Camera Viewing Station	Entire Building	3	EA	7	6-10 years	
	Security Cameras	Entire Building	6	EA	7	6-10 years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	384	SF	6	10+ years	
	Floor - Tile	North	450	SF	6	10+ years	
	Handrails	North	180	LF	5	10+ years	
	Lighting - Pendent/Surface	North	4	EA	6	6-10 years	
	Stairs - Rubber	North	90	LF	6	10+ years	
	Stairs - Rubber	North	10	LF	4	0-1 year	Chipped broken
	Walls - Plaster/Drywall	North	2,016	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	384	SF	6	10+ years	
	Floor - Tile	South	450	SF	7	10+ years	
	Handrails	South	180	LF	5	10+ years	
	Lighting - Pendent/Surface	South	4	EA	6	6-10 years	
	Stairs - Rubber	South	90	LF	6	10+ years	
	Stairs - Rubber	South	15	LF	4	0-1 year	Broken missing
	Walls - Plaster/Drywall	South	2,016	SF	6	10+ years	-





Category: Exterior Building: Addition

Galegoi	ry : Exterior			ananig	: Additio	J11	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Exterior Doors - Exterior Steel Door	10 Courtyard	2	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	16 N Court Yard	1	EA	5	2-5 years	Delaminating
	Exterior Doors - Exterior Steel Door	2 W	2	EA	4	1-2 years	Rusting out door and framr
	Exterior Doors - Transom Lite	2 W	1	EA	6	6-10 years	rasting out door and nami
	Exterior Doors - Exterior Steel Door	2.5 N	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	3 south	2	EA	6	•	
	Exterior Doors - Exterior Steel Door	7 N	4	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door		4	EA	6	6-10 years	
		7 N	•	LF	-	6-10 years	
	Exterior Stairs - Stone	7 N	12		6	6-10 years	
	Exterior Doors - Exterior Steel Door	8 W Boiler Room	1	EΑ	6	6-10 years	Hardware has been replaced
	Exterior Doors - Transom Lite	8 W Boiler Room	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	9 W Yard Storage	2	EA	5	1-2 years	Missing hardware, warped
	Exterior Doors - Exterior Steel Door	Roof - lower	1	EA	6	6-10 years	Moved data from main building
Foundation	on						
	Foundation - Concrete	Entire Building	1,182	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	58,800	SF	7	10+ years	
ighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	2-5 years	
		g			· ·	_ 0 ,000	
Roof Sys							
	Coping - Metal	#10 Low NE Roof	15	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	#10 Low NE Roof	10	LF	6	6-10 years	
	Roof - Modified Bitumen	#10 Low NE Roof	225	SF	5	2-5 years	
	Roof Structure - Concrete	#10 Low NE Roof	225	SF	7	10+ years	
	Coping - Metal	#2 Low N Courtyard Roof	26	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	#2 Low N Courtyard Roof	12	LF	6	6-10 years	
	Downspouts - Interior Downspouts	#2 Low N Courtyard Roof	12	LF	6	6-10 years	
	Roof - Modified Bitumen	#2 Low N Courtyard Roof	270	SF	6	6-10 years	
	Roof Structure - Concrete	#2 Low N Courtyard Roof	270	SF	7	10+ years	
	Coping - Metal	#3 South Roof	78	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	#3 South Roof	10	LF	6	6-10 years	
	Roof - Modified Bitumen	#3 South Roof	296	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	#3 South Roof	296	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/					•	
	Concrete Topping Access Ladder - Metal	#5 L.R. Roof	1	EA	7	10+ years	Reassessed
	Concrete Topping Access Ladder - Metal			EA LF	7 6	10+ years 6-10 years	Reassessed
	Concrete Topping	#5 L.R. Roof #5 L.R. Roof #5 L.R. Roof	1 380 76			10+ years 6-10 years 6-10 years	Reassessed

Campus Name: Yates Page : 22 of 52 Assessment Date: 09/20/2021



atego	ry : Exterior		В	uilding	: Addition	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Hatch - Metal	#5 L.R. Roof	1	EA	7	10+ years	Reassed
	Roof Structure - Steel / Metal Deck/	#5 L.R. Roof	8,422	SF	7	10+ years	
	Concrete Topping				_		
	Access Ladder - Metal	#7 Roof	1	EA	7	6-10 years	
	Coping - Metal	#7 Roof	340	LF	6	6-10 years	
	Downspouts - Interior Downspouts	#7 Roof	50	LF	6	6-10 years	
	Roof - Modified Bitumen	#7 Roof	6,364	SF	6	6-10 years	
	Roof Structure - Concrete	#7 Roof	6,364	SF	7	10+ years	
	Access Ladder - Metal	#8 Main Roof	1	EA LF	7	6-10 years	
	Chimney - Brick Chimney- Stainless Steel Liner	#8 Main Roof	40	LF	6	10+ years	
	Coping - Metal	#8 Main Roof	565	LF	6	6-10 years	
	Downspouts - Interior Downspouts	#8 Main Roof	102	LF	6	6-10 years	
	Roof - Modified Bitumen	#8 Main Roof	10,285	SF	6	6-10 years	
	Roof - PVC Membrane	#8 Main Roof	3,675	SF	6	6-10 years	
	Roof Hatch - Metal	#8 Main Roof	1	EA	7	6-10 years	
	Roof Structure - Concrete	#8 Main Roof	13,960	SF	7	10+ years	
	Coping - Metal	#9 SE Low Roof	15	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	#9 SE Low Roof	10	LF	6	6-10 years	
	Roof - Modified Bitumen	#9 SE Low Roof	225	SF	6	6-10 years	
	Roof Structure - Concrete	#9 SE Low Roof	225	SF	7	10+ years	
alls							
	Canopy - Concrete/ Stucco	Entire Building	50	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	40,190	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	12	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	750	SF	6	10+ years	
indows							
	Curtain wall - Insulated Panel	Entire Building	4,255	SF	6	6-10 years	
	Curtain wall - Louver	Entire Building	108	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	2,530	SF	6	6-10 years	
	Lintels - Steel	Entire Building	30	LF	6	10+ years	
	Windows - Insulated Panel	Entire Building	240	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,347	SF	6	6-10 years	Aggregated quantities
atego	ry : Electrical		В	uilding	: Additio	on	
						Recommend	
roup	7.	Location	Quantity	UOM	Rank	Replacement	Comments
nerger	ncy System			F ^			
	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Security System - CCTV	Entire Building	58,800	SF	6	10+ years	
	Security System - Intrusion Detection	Entire Building	58,800	SF	5	6-10 years	



Fire Alarm Strobe Lights

Fire Alarm_System

Richard Yates Elementary School 1839 N Richmond STREET, Chicago, IL 60647

Catego	ry : Electrical		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Emergency A/C Power - Corridors and Stairs	Entire Building	7,255	SF	4	0-1 year	Some lights aren't working
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	2	0-1 year	No battery backup and no backup generator
	Exit Signs - Gym	Entire Building	6	EA	2	0-1 year	No battery backup and no backup generator
	Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	No battery backup and no backup generator
	Emergency Battery Packs - Corridors and Stairs	Entire Building	11	EA	6	10+ years	
	Emergency Battery Packs - Gym	Entire Building	3	EA	6	6-10 years	The non functional units have been replaced
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	6	10+ years	•
	Emergency Battery Packs - Students Toilets	Entire Building	1	EA	7	6-10 years	
lain Se							
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	2-5 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	2-5 years	The deficient panels have been replaced
	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	10+ years	·
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	8	EA	6	2-5 years	The deficient panel have been replaced
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	4	2-5 years	The deficient panel have been replaced
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	6	6-10 years	·
atego	ry : Fire Protection		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Cina Alama Ctraha Limbta	Cating Duilding	E0 000	CE	•	0.40	

Campus Name: Yates Page : 24 of 52 Assessment Date: 09/20/2021

SF

6

58,800

58,800

6-10 years

10+ years

Entire Building

Entire Building



Catego	Category : Mechanical			uilding	: Additi		
0	Harry Trans	Laatlan	0	11014	D'	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	ling Systems	Doof		Ε,		10	
	Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained	Roof	2	EA	6	10+ years	
	Compressor - 11 - 20 tons						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	
	Gas Heating and DX Cooling Coil - 21 - 30						
	tons						
Boiler Sy	retame						
_Doller O	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	6-10 years	
	Pressure Boiler - 101 - 150 HP	Bollet Room	2	LA	3	0-10 years	
	Chemical Feed System	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	5	2-5 years	
	Steam- Low Pressure Boiler - 101 - 150 HP	Dailer Daam	000	. –	4	2.5.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Come nines have alaman
	Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel	Boiler Room Boiler Room	800 800	LF LF	4 6	2-5 years 10+ years	Some pipes have clamps
	Steam Traps	Boiler Room	60	EA	6	6-10 years	
	Vacuum Pump	Boiler Room	1	EΑ	7	10+ years	
	·					,	
Heating	Devices						
	Wall Heater - Electric	Entire Building	4	EA	6	6-10 years	The rusted units have been replaced or repaired
	Wall Heater - Electric	Entire Building	1	EA	5	6-10 years	·
	Cabinet Heaters - With Steam Coil	Entire Building	9	EA	5	6-10 years	
Tempera	ture Control						
_тотпрои	DDC System	Entire Building	58,800	SF	4	1-2 years	Most manual control
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	42	EA	6	10+ years	
Unit Ven	tilation						
<u> Cint v GI</u>	Unit Ventilators- Floor Mounted- Steam	Entire Building	28	EA	5	6-10 years	
	Heating Coils Only	Ŭ					
	Unit Ventilators- Floor Mounted- Steam	Entire Building	10	EA	4	1-2 years	Frequently repaired
	Heating Coils Only						
_Ventilatio	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	5	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	6	EA	4	2-5 years	One of the fans is missing a motor and all other 3 are missing the basin

Campus Name: Yates Page : 25 of 52 Assessment Date: 09/20/2021



Catego	ry : Mechanical		В	uilding	: Additi	on		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	2	EA	6	6-10 years		
	Roof Mounted Duct Work	Entire Building	15	LF	6	2-5 years		
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	7	10+ years		
Catego	ry : Plumbing		В	uilding	: Additi	on		
				_		Decemmend		

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat	• • • • • • • • • • • • • • • • • • •						
	Electric Heater - Less than 20 KW	1st Floor	1	EA	5	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	58,800	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	58,800	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	58,800	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	58,800	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	58,800	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	58,800	SF	6	10+ years	
	Sanitary Piping	Entire Building	58,800	SF	6	10+ years	
	Storm Piping	Entire Building	58,800	SF	6	10+ years	
	Vent Piping	Entire Building	58,800	SF	6	10+ years	

Category : Room **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	110 Assistant Principal's Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	110 Assistant Principal's Office	336	SF	6	10+ years	
	Doors - Wood Doors inclu hw	110 Assistant Principal's Office	1	EA	6	10+ years	
	Floor - Tile	110 Assistant Principal's Office	336	SF	6	6-10 years	
	Lighting - Pendent/Surface	110 Assistant Principal's Office	8	EA	7	6-10 years	
	Power Distribution	110 Assistant Principal's Office	8	EA	6	10+ years	
	Storage/ Closet	110 Assistant Principal's Office	27	SF	7	10+ years	
	Walls - Concrete Block	110 Assistant Principal's Office	760	SF	6	10+ years	
	AC Unit	1st - Engineer's Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st - Engineer's Office	122	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	1st - Engineer's Office	122	SF	6	6-10 years	

Campus Name: Yates Page : 26 of 52 Assessment Date: 09/20/2021



Catego	ry : Room	-	Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	1st - Engineer's Office	4	EA	7	6-10 years		
	Lighting - Wall Mounted	1st - Engineer's Office	1	EA	7	6-10 years		
	Power Distribution	1st - Engineer's Office	14	EA	7	10+ years		
	Storage/ Closet	1st - Engineer's Office	18	SF	7	10+ years		
	Walls - Concrete Block	1st - Engineer's Office	484	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st- Gym office	153	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st- Gym office	2	EA	6	10+ years		
	Floor - Tile	1st- Gym office	153	SF	6	10+ years		
	Lighting - Pendent/Surface	1st- Gym office	2	EA	7	10+ years		
	Power Distribution	1st- Gym office	4	EA	6	10+ years		
	Storage/ Closet	1st- Gym office	27	SF	7	10+ years		
	Storage/ Closet	1st- Gym office	26	SF	7	6-10 years		
	Walls - Concrete Block	1st- Gym office	400	SF	6	10+ years		
	Ceiling - Splined	2nd Floor Women's Teacher Room	360	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor Women's Teacher Room	1	EA	6	10+ years		
	Floor - Tile	2nd Floor Women's Teacher Room	360	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor Women's Teacher Room	4	EA	6	6-10 years		
	Walls - Concrete Block	2nd Floor Women's Teacher Room	780	SF	6	10+ years		
	Ceiling - Splined	3rd Floor Women's Teacher Room	360	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor Women's Teacher Room	1	EA	6	10+ years		
	Floor - Tile	3rd Floor Women's Teacher Room	360	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor Women's Teacher Room	4	EA	6	6-10 years		
	Walls - Concrete Block	3rd Floor Women's Teacher Room	840	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Adjustment Office	375	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Adjustment Office	1	EA	6	10+ years		
	Floor - Tile	Adjustment Office	375	SF	6	10+ years		
	Lighting - Pendent/Surface	Adjustment Office	2	ĒA	7	6-10 years		
	Power Distribution	Adjustment Office	8	EA	6	10+ years		
	Walls - Concrete Block	Adjustment Office	810	SF	6	10+ years		
	Work SInk	Adjustment Office	2	ĒΑ	7	10+ years		
	Ceiling - Plaster/Drywall	Kitchen Office	375	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	6	10+ years		
	Floor - Tile	Kitchen Office	375	SF	6	6-10 years		
	Lighting - Pendent/Surface	Kitchen Office	5	ĒA	7	6-10 years		
	Power Distribution	Kitchen Office	8	EA	6	10+ years		
	Storage/ Closet	Kitchen Office	64	SF	7	10+ years		
	Walls - Concrete Block	Kitchen Office	760	SF	6	10+ years		
	Work SInk	Kitchen Office	2	ĒΑ	7	10+ years		
		Turonon omos	_		•	.o. youro		
_Gymnas	ia							
-	Ceiling - Plaster/Drywall	1st Floor	4,490	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years		
	Floor - Wood	1st Floor	4,490	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	17	EΑ	7	10+ years		
	- -					•		

Campus Name: Yates Page : 27 of 52 Assessment Date: 09/20/2021



Category : Room Building : Addition							
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Sound System	1st Floor	1	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	174	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,344	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,677	SF	6	10+ years	
Kitchen							
TRICTION	Ceiling - Plaster/Drywall	1st Floor	1,800	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	1,800	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	28	EA	7	6-10 years	
	Serving Line	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	276	SF	7	•	
	Walls - Concrete Block	1st Floor	1,700	SF SF	, 6	10+ years	
	vvalis - Concrete Block	1st Floor	1,700	SF	б	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	5,250	SF	6	10+ years	
	Floor - Tile	1st Floor	5,246	SF	6	10+ years	
	Floor - Tile	1st Floor	4	SF	4	0-1 year	Damaged tile
	Lighting - Pendent/Surface	1st Floor	57	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	5,303	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd- Rm 215- Teacher's Lunch Rm	663	SF	6	10+ years	
	Doors - Hardware	2nd- Rm 215- Teacher's Lunch Rm	1	EA	6	10+ years	
	Floor - Tile	2nd- Rm 215- Teacher's Lunch Rm	663	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd- Rm 215- Teacher's Lunch Rm	12	EΑ	7	10+ years	
	Walls - Concrete Block	2nd- Rm 215- Teacher's Lunch Rm	932	SF	6	10+ years	
MDF_ID	F						
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Finishes	1st Floor	100	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	
Machani	ical/ Service Rooms						
IMPCHALI	Boiler Room	1st Floor	1,279	SF	7	10+ years	
	Janitor's Closet	1st Floor	41	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	142	SF	5 7	10+ years	
	Janitor's Closet	2nd Floor	78	SF	7	6-10 years	
	Storage Room	2nd Floor 2nd Floor	435	SF SF	4	2-5 years	Damaged tile
	Janitor's Closet	3rd Floor	78	SF	7	6-10 years	Damaged tile
	Storage Room	3rd Floor	1,157	SF SF	7	•	
						10+ years	
	Crawl Space - Unfinished	Basement	9,789	SF	7	10+ years	
Restroor	m						
TOOLI OOL							

Campus Name: Yates Page : 28 of 52 Assessment Date: 09/20/2021



Category : Room			В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	116 Restroom	240	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	116 Restroom	240	SF	6	10+ years	
	Doors - Wood Doors inclu hw	116 Restroom	1	EA	6	6-10 years	
	Floor - Tile	116 Restroom	237	SF	6	10+ years	
	Floor - Tile	116 Restroom	3	SF	5	1-2 years	Damage tile
	Lavatory	116 Restroom	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	116 Restroom	2	EA	6	6-10 years	
	Partitions	116 Restroom	1	EA	7	6-10 years	
	Urinals	116 Restroom	1	EA	6	10+ years	
	Walls - Concrete Block	116 Restroom	680	SF	6	10+ years	
	Water Closet	116 Restroom	1	EA	6	10+ years	
	Accessories	1st - Boy's (by lunchroom)	143	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Boy's (by lunchroom)	143	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st - Boy's (by lunchroom)	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - Boy's (by lunchroom)	143	SF	6	6-10 years	
	Floor Drain	1st - Boy's (by lunchroom)	1	EA	7	10+ years	
	Lavatory	1st - Boy's (by lunchroom)	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st - Boy's (by lunchroom)	3	EA	7	6-10 years	
	Urinals	1st - Boy's (by lunchroom)	1	EA	6	10+ years	
	Walls - Concrete Block	1st - Boy's (by lunchroom)	497	SF	7	10+ years	
	Water Closet	1st - Boy's (by lunchroom)	1	EA	7	10+ years	
	Accessories	1st Floor	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	266	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	266	SF	6	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	532	SF	6	10+ years	
	Water Closet	1st Floor	7	EA	6	10+ years	
	Accessories	1st Floor Boy's Restroom	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boy's Restroom	266	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Boy's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boy's Restroom	266	SF	6	6-10 years	
	Floor Drain	1st Floor Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor Boy's Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor Boy's Restroom	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Boy's Restroom	2	EA	7	6-10 years	
	Partitions	1st Floor Boy's Restroom	3	EA	7	10+ years	
	Urinals	1st Floor Boy's Restroom	5	ΕA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boy's Restroom	640	SF	6	10+ years	
	Water Closet	1st Floor Boy's Restroom	3	EA	7	10+ years	
			· ·		-	,	



Category : Room		В	Building : Addition				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor Girls Restroom	360	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls Restroom	360	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Girls Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls Restroom	360	SF	6	10+ years	
	Hand Dryer	1st Floor Girls Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor Girls Restroom	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor Girls Restroom	2	EA	6	6-10 years	
	Partitions	1st Floor Girls Restroom	8	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor Girls Restroom	620	SF	6	10+ years	
	Water Closet	1st Floor Girls Restroom	8	EA	6	10+ years	
	Accessories	1st- Engineer Toilet	53	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Engineer Toilet	53	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Engineer Toilet	1	EA	6	10+ years	
	Floor - Tile	1st- Engineer Toilet	53	SF	6	10+ years	
	Lavatory	1st- Engineer Toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st- Engineer Toilet	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st- Engineer Toilet	1	EΑ	7	6-10 years	
	Partitions	1st- Engineer Toilet	1	EΑ	7	10+ years	
	Walls - Concrete Block	1st- Engineer Toilet	236	SF	6	10+ years	
	Water Closet	1st- Engineer Toilet	1	EA	7	10+ years	
	Accessories	2nd - 221 Teacher's restroom	69	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd - 221 Teacher's restroom	69	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd - 221 Teacher's restroom	1	EΑ	6	10+ years	
	Floor - Tile	2nd - 221 Teacher's restroom	69	SF	6	10+ years	
	Lavatory	2nd - 221 Teacher's restroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd - 221 Teacher's restroom	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd - 221 Teacher's restroom	2	EA	7	6-10 years	
	Partitions	2nd - 221 Teacher's restroom	2	EA	7	10+ years	
	Walls - Concrete Block	2nd - 221 Teacher's restroom	289	SF	6	10+ years	
	Water Closet	2nd - 221 Teacher's restroom	2	EA	7	10+ years	
	Accessories	2nd Floor	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	236	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	5	0-1 year	Damaged, peeling
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	266	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EΑ	7	6-10 years	
	Lavatory	2nd Floor	3	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
	Partitions	2nd Floor	7	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	620	SF	6	10+ years	
	Water Closet	2nd Floor	7	EA	6	6-10 years	
	Accessories	2nd floor boy's restroom	266	SF	7	6-10 years	

Campus Name: Yates Page : 30 of 52 Assessment Date: 09/20/2021



Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd floor boy's restroom	266	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor boy's restroom	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boy's restroom	266	SF	6	10+ years	
	Floor Drain	2nd floor boy's restroom	1	EA	7	10+ years	
	Hand Dryer	2nd floor boy's restroom	1	EA	7	6-10 years	
	Lavatory	2nd floor boy's restroom	3	EA	6	10+ years	
	Lighting - Lay-in	2nd floor boy's restroom	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd floor boy's restroom	2	EA	7	6-10 years	
	Partitions	2nd floor boy's restroom	3	EA	7	10+ years	
	Urinals	2nd floor boy's restroom	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor boy's restroom	620	SF	6	10+ years	
	Water Closet	2nd floor boy's restroom	3	EA	6	10+ years	
	Accessories	3rd Floor	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	266	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	266	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	10+ years	
	Partitions	3rd Floor	3	EA	7	10+ years	
	Urinals	3rd Floor	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	620	SF	6	10+ years	
	Water Closet	3rd Floor	3	EA	7	10+ years	
	Accessories	3rd girl's restroom	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd girl's restroom	266	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd girl's restroom	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd girl's restroom	266	SF	6	10+ years	
	Floor Drain	3rd girl's restroom	1	ĒΑ	7	10+ years	
	Hand Dryer	3rd girl's restroom	1	EA	7	6-10 years	
	Lavatory	3rd girl's restroom	3	EA	6	6-10 years	
	Lighting - Lay-in	3rd girl's restroom	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd girl's restroom	2	EA	7	6-10 years	
	Partitions	3rd girl's restroom	7	ĒΑ	7	6-10 years	
	Water Closet	3rd girl's restroom	7	EΑ	6	6-10 years	
	Accessories	3rd men's teacher room	69	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd men's teacher room	69	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd men's teacher room	1	EA	6	10+ years	
	Floor - Tile	3rd men's teacher room	69	SF	6	10+ years	
	Lavatory	3rd men's teacher room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd men's teacher room	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd men's teacher room	1	EA	7	10+ years	
	Partitions	3rd men's teacher room	1	EA	7	•	
	r artitions	ord men a reacher room	ı	EA	1	10+ years	

Campus Name: Yates Page : 31 of 52 Assessment Date: 09/20/2021



Catego	ry : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Urinals	3rd men's teacher room	1	EA	6	10+ years			
	Walls - Concrete Block	3rd men's teacher room	289	SF	6	10+ years			
	Water Closet	3rd men's teacher room	1	EA	7	10+ years			
	Accessories	Girl's 1st floor restroom near cafeteria	116	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Girl's 1st floor restroom near cafeteria	116	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Girl's 1st floor restroom near cafeteria	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Girl's 1st floor restroom near cafeteria	116	SF	6	10+ years			
	Floor Drain	Girl's 1st floor restroom near cafeteria	1	EA	7	10+ years			
	Lavatory	Girl's 1st floor restroom near cafeteria	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Girl's 1st floor restroom near cafeteria	2	EA	7	10+ years			
	Partitions	Girl's 1st floor restroom near cafeteria	2	EA	7	10+ years			
	Walls - Concrete Block	Girl's 1st floor restroom near cafeteria	387	SF	6	10+ years			
	Water Closet	Girl's 1st floor restroom near cafeteria	2	EA	6	10+ years			
	Accessories	Kitchen Office Restroom	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Kitchen Office Restroom	30	SF	6	10+ years			
	Doors - Steel Doors incl hw	Kitchen Office Restroom	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Kitchen Office Restroom	30	SF	7	10+ years			
	Lavatory	Kitchen Office Restroom	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Kitchen Office Restroom	1	EA	7	6-10 years			
	Walls - Concrete Block	Kitchen Office Restroom	200	SF	6	10+ years			
	Water Closet	Kitchen Office Restroom	1	EA	6	10+ years			
Catego	ry : Classroom		В	uilding	: Additi	on			

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #111 (Store Room)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	66	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	1,035	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Tile	1st Floor	1,025	SF	6	10+ years	
Floor - Tile	1st Floor	10	SF	5	1-2 years	Damaged tile
Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	-
Walls - Concrete Block	1st Floor	1,240	SF	6	10+ years	



Category : Classroom		Building : Addition					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	Work Sink	1st Floor	6	EA	7	10+ years	
Classro	om #112 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,025	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Damaged
	Chalk Board	1st Floor	24	LF	4	2-5 years	-
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	10+ years	
	Floor - Tile	1st Floor	1,035	SF	6	10+ years	
	Kiln	1st Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,240	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #113 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,035	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,035	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,240	SF	6	10+ years	
	Work Sink	1st Floor	1,210	EA	7	10+ years	
Classro	om #116 (Science)						
	Ceiling - Splined	1st Floor	360	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	360	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classro	om #117 (Counseling Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	36	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,080	SF	6	10+ years	



Category : Classroom			В	Building : Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	#### (D. O.)								
Classroo	m #118 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	36	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	730	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years			
	Storage/ Closet	1st Floor	27	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	1,080	SF	6	10+ years			
Classroo	m #119 (Library)								
	Casework	1st Floor	81	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,170	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years			
	Floor - Tile	1st Floor	1,170	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	32	ĒΑ	7	6-10 years			
	Walls - Concrete Block	1st Floor	1,420	SF	6	10+ years			
:lassroo	m #210 (Office)								
21000100	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	730	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	977	SF	6	10+ years			
Naceroo	m #211 (Regular Classroom)								
JIASSIUU	, ,	2nd Floor	4	ГΛ	7	6.10 veers			
	AC Units	2nd Floor	1	EA LF	7	6-10 years			
	Casework	2nd Floor	8		6	10+ years			
	Ceiling - Plaster/Dravell	2nd Floor	12	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	718	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	730	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	977	SF	6	10+ years			
Classroo	m #212 (Regular Classroom)								
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years			
	Floor - Tile	2nd Floor	730	SF	6	6-10 years			



Category : Classroom			Building : Addition					
_			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	977	SF	6	10+ years		
Classroo	om #213 (Other Instructional Use)							
Classicc	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor 2nd Floor	8	LF	6			
	Casework Ceiling - Plaster/Drywall		730	SF	6	10+ years		
		2nd Floor				10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	730	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	977	SF	6	10+ years		
Classroc	om #214 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years		
	Floor - Tile	2nd Floor	730	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	977	SF	6	10+ years		
	Walls Collete Block	2110 1 1001	017	O.	Ü	101 youro		
Classroc	om #216 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years		
	Chalk Board	2nd Floor	36	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years		
	Floor - Tile	2nd Floor	730	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	977	SF	6	10+ years		
01	#847 (B							
Classroc	om #217 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	730	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	977	SF	6	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
01	#040 (O : 151 · :)							
Jassroc	om #218 (Special Education)							

Campus Name: Yates Page : 35 of 52 Assessment Date: 09/20/2021



Category : Classroom			Building : Addition					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years		
	Chalk Board	2nd Floor	36	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	730	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	977	SF	6	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
Classroo	om #219 (Computer Lab)							
	AC Units	2nd Floor	2	EA	7	10+ years		
	Casework	2nd Floor	76	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	1,366	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years		
	Floor - Tile	2nd Floor	1,366	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	1,753	SF	6	10+ years		
	Wireless System	2nd Floor	1	EA	7	10+ years		
Classroo	om #310 (Regular Classroom)							
Ciassioc	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		
	Casework Ceiling - Splined	3rd Floor	730	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	730	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	,		
		3rd Floor		LF	7	6-10 years		
	Marker Board		16	SF		6-10 years		
	Walls - Concrete Block	3rd Floor	977	5F	6	10+ years		
Classroo	om #311 (Regular Classroom)	. —						
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	730	SF	6	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years		
	Marker Board	3rd Floor	8	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	976	SF	6	10+ years		
Classroo	om #312 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		

Campus Name: Yates Page : 36 of 52 Assessment Date: 09/20/2021



Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	977	SF	6	10+ years	
Classroo	m #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	730	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Lighting - Wall Mounted	3rd Floor	19	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	977	SF	6	10+ years	
	Walls - Collete block	310 1 1001	911	OI.	U	10+ years	
Classroo	m #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	977	SF	6	10+ years	
Classroo	m #316 (Science Lab Level 3)						
	Casework	3rd Floor	72	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,035	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,035	SF	6	10+ years	
	Gas Line	3rd Floor	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	24	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,242	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	100	SF	6	10+ years	
	Work Sink	3rd Floor	100	EA	7	10+ years	
	TOTA OFFICE	0.4.1.001		_/ \	,	ioi youis	
lassroo	m #317 (Regular Classroom)						

Campus Name: Yates Page : 37 of 52 Assessment Date: 09/20/2021



Catego	ry : Classroom			uildina	: Addition		9 N Richmond STREET, Chicago, IL 60647
Guiogo	ry i Glader delli			ananig	. / taarer	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	977	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #318 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Walls - Concrete Block	3rd Floor	977	SF	6	10+ years	
	Work Sink	3rd Floor	1	ĒΑ	7	10+ years	
Classroo	om #319 (Music Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	950	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	950	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	25	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,125	SF	6	10+ years	
	Work Sink	3rd Floor	1	ĒΑ	7	10+ years	
Catego	ry : Interior		В	uilding	: Additio	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	3,279	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	144	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,125	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	10	SF	4	0-1 year	Missing tile
	Lighting - Lay-in	1st Floor	10	EA	7	10+ years	-
	Lighting - Pendent/Surface	1st Floor	32	EA	7	10+ years	

Campus Name: Yates Page : 38 of 52 Assessment Date: 09/20/2021



Catego	ry : Interior		<u></u>	Building	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	1st Floor	137	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	6,140	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,888	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,888	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	142	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	4,880	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,888	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,888	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Student Lockers - One Tier	3rd Floor	142	EA	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	4,880	SF	6	10+ years	
Safety							
•	Security Cameras	Entire Building	6	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	7	6-10 years	
Stairs							
<u> </u>	Ceiling - Plaster/Drywall	North	192	SF	6	10+ years	
	Floor - Terrazzo	North	100	SF	6	10+ years	
	Handrails	North	112	LF	7	10+ years	
	Lighting - Pendent/Surface	North	2	EA	7	10+ years	
	Stairs - Terrazzo	North	56	LF	6	10+ years	
	Walls - Structural Glazed Tile	North	784	SF	6	10+ years	
	Ceiling - Splined	South	192	SF	6	10+ years	
	Floor - Terrazzo	South	100	SF	6	10+ years	
	Handrails	South	112	LF	7	10+ years	
	Lighting - Pendent/Surface	South	2	EA	6	10+ years	
	Stairs - Terrazzo	South	56	LF	6	10+ years	
	Walls - Structural Glazed Tile	South	784	SF	6	10+ years	
						-	





Catego	ry : Exterior		В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance	1						
	Entrance Control - Audio	4 W	1	EA	4	0-1 year	Broken
	Exterior Doors - Exterior Steel Door	4 W	2	EA	6	6-10 years	
	Entrance Control - Audio	5 S	1	EA	4	0-1 year	Broken
	Exterior Doors - Exterior Steel Door	5 S	2	EA	6	6-10 years	
	Entrance Control - Audio	6 E	1	EA	4	0-1 year	Broken
	Exterior Doors - Exterior Steel Door	6 E	4	EA	6	6-10 years	
	Power Door Operator and Controls	6 E	1	EA	7	2-5 years	
_Foundat	on						
	Foundation - Concrete	Entire Building	745	LF	7	10+ years	Foundation not exposed
	Superstructure - Metal Deck/ Concrete	Entire Building	18,000	SF	7	10+ years	Superstructure not exposed
	Topping						
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	6-10 years	
Roof Sys	stem						
•	Chimney - Metal Flue	Main Roof	36	LF	6	6-10 years	
	Coping - Metal	Main Roof	745	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	65	LF	6	1-2 years	Gutters clogged, vegetation growing
	Roof - Metal	Main Roof	18,000	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	18,000	SF	7	10+ years	
Walls							
	Canopy - Metal	Entire Building	623	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	745	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	9,685	SF	6	10+ years	
_Windows							
	Curtain wall - Louver	Entire Building	120	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	1,750	SF	6	6-10 years	
	Lintels - Steel	Entire Building	252	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,750	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Linked	l Addition	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System					•	
	Security System - CCTV	Entire Building	18,000	SF	5	6-10 years	

Page : 40 of 52 Campus Name: Yates Assessment Date: 09/20/2021



Group	Item - Type					Addition Recommend	
Group						Recommend	
		Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - Intrusion Detection	Entire Building	18,000	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
lain Ser	vice						
naiii Oci	PA System	Entire Building	18,000	SF	6	10+ years	Fed from the Main building
	ra System	Entire Building	10,000	SI	O	10+ years	red from the Main building
Power Dis	stribution						
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	
	amp						
Categor	y : Fire Protection		В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alarn	n						
	Fire Alarm Strobe Lights	Entire Building	18,000	SF	6	10+ years	
	Fire Alarm_System	Entire Building	18,000	SF	6	10+ years	
Sprinkler	System						
-	Sprinkler Heads	Entire Building	18,000	SF	7	10+ years	
	Sprinkler Piping	Entire Building	18,000	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	18,000	SF	6	10+ years	
		3				,	
Categor	y : Mechanical		В	uilding	: Linked	Addition	
	Name Time	Location	Overetite.	LIONA	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sys	stems Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	F	101.1/2272	
	- Less than 500 MBH	Bollet Room	2	EA	5	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	1	EΑ	5	10+ years	
	Non Condensing- Flexible Tube-	Boiler Room	2	EA	4	2-5 years	Leaky and unreliable
	Atmospheric- Hot Water Boiler - Less than	Donor Room	2		-7	2 0 years	Loany and unrollable
	500 MBH						
	Water Fill System	Boiler Room	1	EA	6	10+ years	
) D-							
as Boos		Poilor Poom		EA	6	101.1/2272	
	Gas Booster	Boiler Room	1	ĽΑ	6	10+ years	
leating D	Devices						



Catego	ory : Mechanical		В	uilding	: Linked	l Addition	•
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wall Heater - Electric	1st Floor	4	EΑ	6	6-10 years	Non existent
	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EΑ	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	2	EA	6	10+ years	
Mechan	ical Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	10+ years	
	Hydronic Supply and Return - Copper	Entire Building	200	LF	6	10+ years	
Tempera	ature Control						
•	DDC System	Entire Building	18,000	SF	5	6-10 years	
	Electric Thermostat	Entire Building	2	EA	6	10+ years	
	Thermostats - DDC	Entire Building	11	EA	6	10+ years	
Unit Ver	ntilation						
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	1st Floor	11	EA	5	6-10 years	
Ventilati	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	3	EA	6	10+ years	

Category: Plumbing Building: Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	OOW	ivalik	Replacement	Comments
Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Pump Room	1	EA	7	10+ years	
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	18,000	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	18,000	SF	6	10+ years	
	Fixtures	G				•	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	18,000	SF	6	10+ years	
	(Horizontal Lines)	· ·				•	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	18,000	SF	6	10+ years	
	(from Risers to Fixtures)	· ·				•	
	Sanitary Piping	Entire Building	18,000	SF	6	10+ years	
	Storm Piping	Entire Building	18,000	SF	6	10+ years	
	Vent Piping	Entire Building	18,000	SF	6	10+ years	



ry : Room		ь	ullaing	: Linked	d Addition	
_					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
rative Suites/Offices						
Ceiling - Lay-in	027 Office			7	6-10 years	
	027 Office	5	SF	4	0-1 year	
Doors - Steel Doors incl hw	027 Office	1	EA	6	10+ years	
Floor - Tile	027 Office	360	SF	7	10+ years	
Lighting - Lay-in	027 Office	4	EA	7	6-10 years	
Power Distribution	027 Office	10	EA	6	6-10 years	
Walls - Concrete Block	027 Office	840	SF	6	10+ years	
F						
Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
Finishes	1st Floor	635	SF	7		
Other Cooling Unit	1st Floor	1	EA	7	6-10 years	Ducted
cal/ Service Rooms						
Boiler Room	1st Floor	567	SF	7	10+ years	
Janitor's Closet						
Mechanical/ Service Rooms	1st Floor	27	SF	7	10+ years	
n						
Accessories	020 Children Toilet	70	SF	5	2-5 years	
	020 Children Toilet				•	
Doors - Steel Doors incl hw	020 Children Toilet	1	ĒA	6		
Floor - Tile Ceramic/ Porcelain	020 Children Toilet	70	SF	6		
Lavatory	020 Children Toilet	1	EA	6		
Lighting - Lay-in	020 Children Toilet	2	EA	6	•	
Walls - Concrete Block	020 Children Toilet	380	SF	6		
Water Closet	020 Children Toilet	1	EA	6		
Accessories	021 Children Toilet	70	SF	5		
Ceiling - Lay-in	021 Children Toilet	70	SF	6		
Doors - Steel Doors incl hw	021 Children Toilet	1	EA	6		
Floor - Tile Ceramic/ Porcelain	021 Children Toilet	70	SF	6	•	
	021 Children Toilet	1	EΑ	6		
	021 Children Toilet	2	EA	6		
Walls - Concrete Block	021 Children Toilet	380	SF	6		
Water Closet	021 Children Toilet	1	ĒΑ	6		
Accessories	022 Children Toilet	70	SF	5	•	
	022 Children Toilet	70	SF	6		
Doors - Steel Doors incl hw	022 Children Toilet	1	ĒΑ	6		
		70		6		
	022 Children Toilet	1	ĒΑ	6		
	022 Children Toilet	2	EA	6		
Walls - Concrete Block	022 Children Toilet	380	SF	6	•	
E	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block F Doors - Steel Doors incl hw Finishes Other Cooling Unit cal/ Service Rooms Boiler Room Janitor's Closet Mechanical/ Service Rooms Accessories Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Lay-in Walls - Concrete Block Water Closet Accessories Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Lay-in Doors - Steel Doors incl hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Lay-in Walls - Concrete Block Water Closet Accessories Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Lay-in Doors - Steel Doors incl hw Floor - Tile Ceramic/ Porcelain Lavatory Lighting - Lay-in	rative Suites/Offices Ceiling - Lay-in 027 Office Ceiling - Lay-in 027 Office Doors - Steel Doors incl hw 027 Office Floor - Tile 027 Office Lighting - Lay-in 027 Office Lighting - Lay-in 027 Office Walls - Concrete Block 027 Office Doors - Steel Doors incl hw 1st Floor Finishes 1st Floor Other Cooling Unit 1st Floor Call Service Rooms Boiler Room 1st Floor Mechanical/ Service Rooms 1st Floor Accessories 020 Children Toilet Ceiling - Lay-in 020 Children Toilet Layatory 020 Children Toilet Layatory 020 Children Toilet Layatory 020 Children Toilet Walls - Concrete Block 020 Children Toilet Walls - Concrete Block 020 Children Toilet Walls - Concrete Block 020 Children Toilet Ceiling - Lay-in 020 Children Toilet Walls - Concrete Block 020 Children Toilet Ceiling - Lay-in 020 Children Toilet Ceiling - Lay-in 020 Children Toilet Ceiling - Lay-in 021 Children Toilet Accessories 022 Children Toilet Accessories 021 Children Toilet Ceiling - Lay-in 021 Children Toilet Doors - Steel Doors incl hw 021 Children Toilet Layatory 021 Children Toilet Layatory 021 Children Toilet Layatory 021 Children Toilet Walls - Concrete Block 022 Children Toilet Ceiling - Lay-in 022 Children Toilet Ceiling - Cay-in 022 Children Toilet	Ceiling - Lay-in	Celiling - Lay-in	Tative Suites/Offices	Lent Type Location Quantity UOM Rank Replacement Patrice Suities/Offices Ceiling - Lay-in O27 Office 355 SF 7 6-10 years Ceiling - Lay-in O27 Office 5 SF 4 0-1 years Doors - Steel Doors incl hw O27 Office 1 EA 6 0-1 years Floor - Tile O27 Office 360 SF 7 10+ years Floor - Tile O27 Office 4 EA 7 6-10 years Power Distribution O27 Office 10 EA 6 6-10 years O27 Office 10 EA 6 6-10 years O27 Office Ceiling - Lay-in O27 Office 10 EA 6 6-10 years O27 Office O27 Of



Catego	ry : Room		В	uilding	: Linked	d Addition	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	022 Children Toilet	1	EA	6	10+ years	
	Accessories	023 Children Toilet	70	SF	7	6-10 years	
	Ceiling - Lay-in	023 Children Toilet	70	SF	6	6-10 years	
	Doors - Steel Doors incl hw	023 Children Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	023 Children Toilet	70	SF	6	10+ years	
	Lavatory	023 Children Toilet	1	EA	7	10+ years	
	Lighting - Lay-in	023 Children Toilet	2	EA	7	6-10 years	
	Walls - Concrete Block	023 Children Toilet	380	SF	7	10+ years	
	Water Closet	023 Children Toilet	1	EA	7	10+ years	
	Accessories	024 Children Toilet	70	SF	5	2-5 years	
	Ceiling - Lay-in	024 Children Toilet	70	SF	6	6-10 years	
	Doors - Steel Doors incl hw	024 Children Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	024 Children Toilet	70	SF	6	10+ years	
	Lavatory	024 Children Toilet	1	EA	6	10+ years	
	Lighting - Lay-in	024 Children Toilet	2	EA	6	6-10 years	
	Walls - Concrete Block	024 Children Toilet	380	SF	6	10+ years	
	Water Closet	024 Children Toilet	1	EA	6	10+ years	
	Accessories	025 Children Toilet	70	SF	7	6-10 years	
	Ceiling - Lay-in	025 Children Toilet	70	SF	6	6-10 years	
	Doors - Steel Doors incl hw	025 Children Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	025 Children Toilet	70	SF	6	10+ years	
	Lavatory	025 Children Toilet	1	EA	6	10+ years	
	Lighting - Lay-in	025 Children Toilet	2	EA	6	6-10 years	
	Walls - Concrete Block	025 Children Toilet	380	SF	6	10+ years	
	Water Closet	025 Children Toilet	1	EA	6	10+ years	
	Accessories	026 Children Toilet	70	SF	5	6-10 years	
	Ceiling - Lay-in	026 Children Toilet	70	SF	6	6-10 years	
	Doors - Steel Doors incl hw	026 Children Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	026 Children Toilet	70	SF	6	10+ years	
	Lavatory	026 Children Toilet	1	EA	6	10+ years	
	Lighting - Lay-in	026 Children Toilet	2	EA	6	6-10 years	
	Walls - Concrete Block	026 Children Toilet	380	SF	6	10+ years	
	Water Closet	026 Children Toilet	1	EA	6	10+ years	
	Accessories	1st Floor	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	44	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	44	SF	7	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	260	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	44	SF	6	10+ years	
						•	



Item - Type Doors - Steel Doors incl hw Floor - Tile Ceramic/ Porcelain Floor Drain Lavatory Lighting - Pendent/Surface Walls - Concrete Block Water Closet 7: Classroom Item - Type	Location 1st Floor	Quantity 1 44 1 1 260 1	EA SF EA EA EA SF EA	Rank 6 6 7 6 6 6 6	Recommend Replacement 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years	Comments
Doors - Steel Doors incl hw Floor - Tile Ceramic/ Porcelain Floor Drain Lavatory Lighting - Pendent/Surface Walls - Concrete Block Water Closet /: Classroom Item - Type	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 44 1 1 1 260	EA SF EA EA EA SF	6 6 7 6 6	10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years	Comments
Floor - Tile Ceramic/ Porcelain Floor Drain Lavatory Lighting - Pendent/Surface Walls - Concrete Block Water Closet /: Classroom Item - Type	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	44 1 1 1 260 1	SF EA EA EA SF	6 7 6 6	6-10 years 10+ years 10+ years 6-10 years 10+ years	
Floor Drain Lavatory Lighting - Pendent/Surface Walls - Concrete Block Water Closet /: Classroom Item - Type	1st Floor 1st Floor 1st Floor 1st Floor	1 1 1 260 1	EA EA EA SF	7 6 6 6	10+ years 10+ years 6-10 years 10+ years	
Lavatory Lighting - Pendent/Surface Walls - Concrete Block Water Closet /: Classroom Item - Type	1st Floor 1st Floor 1st Floor	1	EA EA SF	6 6 6	10+ years 6-10 years 10+ years	
Lighting - Pendent/Surface Walls - Concrete Block Water Closet : Classroom Item - Type	1st Floor 1st Floor	1	EA SF	6 6	6-10 years 10+ years	
Walls - Concrete Block Water Closet : Classroom Item - Type	1st Floor	1	SF	6	10+ years	
Water Closet /: Classroom Item - Type		1			-	
v : Classroom Item - Type	1st Floor	·	EA	6	10± vears	
Item - Type		В			10+ years	
• •		_	uilding	: Linked	I Addition	
• •					Recommend	
4000 (Kindonsomer)	Location	Quantity	UOM	Rank	Replacement	Comments
n #020 (Kindergarten)						
Casework	1st Floor	24	LF	6	10+ years	
		=				
		•			•	
					6-10 years	
					10+ years	
				6	10+ years	
Walls - Plaster/Drywall	1st Floor	310	SF	6	10+ years	
Work Sink	1st Floor	2	EA	7	6-10 years	
n #021 (Kindergarten)						
Casework	1st Floor	24	LF	6	10+ years	
Ceiling - Lay-in	1st Floor	860	SF		•	
		4			•	
		1			•	
Floor - Tile	1st Floor	860		7		
Lighting - Lav-in	1st Floor			7		
			LF	7		
				-		
				_		
Work Sink	1st Floor	2	EA	7	6-10 years	
n #022 (Kindergarten)						
` • · · · · · · · · · · · · · · · · · ·	1et Floor	24	1.5	6	10 L VOORS	
Dears Side lite						
		•				
		•			,	
FIOOT - THE	1St Floor	860	SF	1	10+ years	
	#021 (Kindergarten) Casework Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Concrete Block Walls - Plaster/Drywall	Doors - Side-lite Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Concrete Block Walls - Plaster/Drywall Work Sink #021 (Kindergarten) Casework Ceiling - Lay-in Doors - Steel Doors incl hw Floor Lighting - Lay-in Marker Board Storage/ Closet #081 (Kindergarten) Casework Ceiling - Lay-in Doors - Steel Doors incl hw Floor Marker Board Storage/ Closet Walls - Concrete Block Marker Board Storage/ Closet Marker Board Stelloor Marker	Doors - Side-lite	Doors - Side-lite	Doors - Side-lite	Doors - Side-lite



Catego	ry : Classroom		В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	78	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	930	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	310	SF	6	10+ years	
	Work Sink	1st Floor	2	EΑ	7	6-10 years	
Classroc	om #023 (Kindergarten)						
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	860	SF	6	10+ years	
	Doors - Side-lite	1st Floor	4	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	860	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor		LF	7		
			16			6-10 years	
	Storage/ Closet	1st Floor	78	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	930	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	310	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroc	om #024 (Kindergarten)						
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	860	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	4	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	860	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	78	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	930	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	310	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #025 (Kindergarten)						
2.000.00	Casework	1st Floor	24	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	860	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	4	SF			
					7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	860	SF	7	10+ years	
	Lighting - Lay-in Marker Board	1st Floor 1st Floor	14 16	EA LF	7 7	10+ years 6-10 years	



Catego	ry : Classroom		В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	78	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	930	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	310	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #026 (Special Education)						
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	860	SF	6	10+ years	
	Doors - Side-lite	1st Floor	4	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	860	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	14	LF	7	•	
	Storage/ Closet	1st Floor	78	SF	7	6-10 years	
						10+ years	
	Walls - Concrete Block	1st Floor	930	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	310	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #028/029 (Multi Purpose Room)						
	Casework	1st Floor	60	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,800	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒA	6	10+ years	
	Floor - Tile	1st Floor	1,800	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	22	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,350	SF	6	10+ years	
		1st Floor	450	SF	6	•	
	Walls - Plaster/Drywall	151 F1001	450	SF	O	10+ years	
Catego	ry : Interior		В	uilding	: Linked	Addition	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	nom · i ype	Location	Quantity	OOW	Maiik	Replacement	Comments
	Ceiling - Lay-in	1st Floor	3,050	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	10	SF	4	2-5 years	Water stain
	Doors - Steel Doors incl hw	1st Floor	10	ĒΑ	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EΑ	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	3,060	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	3,000	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	4,880	SF	6	10+ years	
	vvalis - Cultulete block	191 11001	4,000	ЭГ	O	10+ years	
Safetv							



Building: Linked Addition Category: Interior Recommend Item - Type Location UOM Group Quantity Rank Replacement Comments Security Cameras **Entire Building** 2 EΑ 6-10 years

Campus Name: Yates Page : 48 of 52 Assessment Date: 09/20/2021





Category : Site **Building: Site**

				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	Basketball NE	3,342	SF	5	6-10 years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	12	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	6	6-10 years	
Fencing							
	Fencing - Chain Link	Entire Site	274	LF	7	10+ years	
	Fencing - Chain Link	Entire Site	192	LF	5	2-5 years	
	Fencing - New Standard Ornamental	Entire Site	645	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	40	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	5	LF	4	0-1 year	Rusted, damaged
Landscaı	20						
Landsca	Landscape - Grass	Entire Site	13,200	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	15,150	SF	6	6-10 years	
	Parkway trees	Entire Site	38	ĒΑ	7	10+ years	
	Planting Beds/ Area	Entire Site	3,225	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	14,750	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	900	SF	5	1-2 years	Raveling pavement
	Retaining Wall - Concrete	Entire Site	300	SF	6	10+ years	31
	Trash Receptacles	Entire Site	7	EA	6	6-10 years	
Parking I	ot						
	Concrete Curbs	North Courtyard	60	LF	6	10+ years	
	Surface - Asphalt	North Courtyard	11,838	SF	5	2-5 years	Raveling, cracking, striping worn of
	Vehicular Screening	North Courtyard	70	LF	6	10+ years	5, 5, 1 5
	Concrete Curbs	Parking Lot- East	640	LF	7	10+ years	
	Lighting - Pole Mounted	Parking Lot- East	3	EA	6	6-10 years	
	Surface - Asphalt	Parking Lot- East	6,414	SF	5	2-5 years	Worn surface, cracking, uneven pavement
	Surface - Asphalt	Parking Lot- East	10	SF	4	0-1 year	Large pothole by drain
	Vehicular Screening	Parking Lot- East	20	LF	6	10+ years	<i>5</i> . ,
	Concrete Curbs	West	780	LF	6	10+ years	
	Lighting - Pole Mounted	West	7	EA	6	2-5 years	
	Surface - Concrete	West	14,400	SF	6	10+ years	
	Trash Enclosure - Chain Links	West	200	SF	6	6-10 years	
	Vehicular Screening	West	20	LF	6	10+ years	
Diam							
Playgrou	HQ						

Campus Name: Yates Page : 49 of 52 Assessment Date: 09/20/2021



Catego	ory : Site		Building : Site					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Equipment - Combo 3-12	South	1	EΑ	6	6-10 years		
	Surface - Poured Surface	South	2,765	SF	6	6-10 years		
	Equipment - Combo 3-12	South West	1	EA	6	6-10 years		
	Surface - Poured Surface	South West	2,185	SF	6	6-10 years		
Sidewall	ks							
	Sidewalks - Internal Walks	Entire Site	1,055	LF	6	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	23,325	SF	6	10+ years		
Signage								
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years		
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site	1	EA	6	6-10 years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years		

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Yates Page: 50 of 52 Assessment Date: 09/20/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary				l ei bi					
			Daam	Floor Plan	A	Glazed	Operable	VA/i	C
Command Haarra	luten de d Heere	Doom Location	Room	Room	Area (SF)	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(3F)	Area	Area	Stop	Board
Building : Main	D	01.51	1 000	000	750	400	00	N.	
Computer Lab	Regular Classroom	2nd Floor	202	202	756	136	68	N	Y
Counseling Room	Office	1st Floor	101	101	720	144	69	N	N
Kindergarten	Kindergarten	1st Floor	103	103	824	136	68	N	N
Multi Purpose Room	Regular Classroom	Basement	002	100	648	66	33	N	N
Office	Regular Classroom	1st Floor	105	105	824	136	68	N	N
Other Instructional Use	Regular Classroom	Basement	004	NA	744	78	35	Υ	N
Other Instructional Use	Regular Classroom	Basement	006	NA	718	130	55	Υ	N
Regular Classroom	Regular Classroom	1st Floor	104	104	824	136	68	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	806	136	68	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	824	136	68	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	762	136	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	713	204	102	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	822	136	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	810	136	68	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	759	136	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	762	136	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	762	136	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	824	136	68	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	762	136	68	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	305	772	136	68	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	772	136	68	N	N
Store Room	Kindergarten	1st Floor	102	102	824	141	530	Y	N
Store Room	Library	3rd Floor	301	301	717	204	102	N	N
Vacant	Regular Classroom	3rd Floor	302	302	765	136	68	N	N
Vacant	Regular Classroom	3rd Floor	306	306	771	136	68	N	N
Building : Addition									
Art Room	Laboratory/Shop	1st Floor	112	3	1,035	192	84	N	N
Computer Lab	Art Room	2nd Floor	219	119	1,366	192	84	N N	Y
Computer Lab Counseling Room	Regular Classroom	1st Floor	117	5	730	112	48	N N	N N
		1st Floor 1st Floor	117	7		192		N N	N N
Library Music Boom	Library		319	219	1,170		84 70		
Music Room Office	Music Room	3rd Floor	210		950	160 112		N	N
	Regular Classroom	2nd Floor		110	730		48	N	N
Other Instructional Use	Regular Classroom	2nd Floor	213	113	730	112	48	N	N
Pre School	Laboratory/Shop	1st Floor	113	4	1,035	192	84	N	N
Regular Classroom	Regular Classroom	1st Floor	118	6	730	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	111	730	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	112	730	112	48	N	N





Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	214	114	730	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	116	730	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	117	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	210	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	211	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	212	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	213	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	314	212	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	317	217	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	218	730	112	48	N	N
Science	Science	1st Floor	116	116	360	96	30	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	316	216	1,035	192	84	N	N
Special Education	Regular Classroom	2nd Floor	218	118	730	112	48	N	N
Store Room	Laboratory/Shop	1st Floor	111	2	1,035	192	84	N	N

Building: Linked Addition	1								
Kindergarten	Kindergarten	1st Floor	020	109	860	144	48	N	Υ
Kindergarten	Kindergarten	1st Floor	021	110	860	144	48	N	Y
Kindergarten	Kindergarten	1st Floor	022	111	860	144	48	N	Υ
Kindergarten	Kindergarten	1st Floor	023	112	860	144	48	N	Υ
Kindergarten	Kindergarten	1st Floor	024	113	860	144	48	N	Y
Kindergarten	Kindergarten	1st Floor	025	114	860	144	48	N	Y
Multi Purpose Room	Multi Purpose Room	1st Floor	028/029	NA	1,800	288	96	N	N
Special Education	Kindergarten	1st Floor	026	115	860	144	48	N	N

Campus Name: Yates Page : 52 of 52 Assessment Date: 09/20/2021