



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	2006	3	104,203
Campus Total			104,203

Category : Exterior Building : Main

					Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance						
Entrance Control - Audi	o and Video #1 W	1	EA	6	6-10 years	
Exterior Doors - Side lit		2	EA	6	10+ years	
Exterior Doors - Store F		4	EA	6	10+ years	
Power Door Operator a	nd Controls #1 W	2	EA	7	6-10 years	
Exterior Doors - Exterio		2	EA	6	10+ years	
Entrance Control - Audi		1	EA	7	6-10 years	
Exterior Doors - Side lit	e #3 N	1	EA	6	10+ years	
Exterior Doors - Store F	Front #3 N	2	EA	6	10+ years	
Exterior Doors - Transo	m Lite #3 N	1	EA	6	10+ years	
Power Door Operator a	nd Controls #3 N	1	EA	7	6-10 years	Fixed
Exterior Doors - Exterio	r Steel Door #3.1 E	2	EA	6	10+ years	
Entrance Control - Audi	o #4 E	1	EA	6	6-10 years	
Exterior Doors - Exterio	r Steel Door #4 E	2	EA	6	10+ years	
Entrance Control - Audi	o and Video #5 E	1	EA	6	2-5 years	
Exterior Doors - Exterio	r Steel Door #5 E	1	EA	6	10+ years	
Entrance Control - Audi	o and Video #6 E	1	EA	6	2-5 years	
Exterior Doors - Exterio	r Steel Door #6 E	2	EA	6	10+ years	
Exterior Doors - Exterio		2	EA	6	6-10 years	
Entrance Control - Audi		1	EA	5	2-5 years	
Exterior Doors - Side lit	e #7 S	1	EA	6	10+ years	
Exterior Doors - Store F		2	EA	6	10+ years	
Exterior Doors - Transo		1	EA	6	10+ years	
Power Door Operator a	nd Controls #7 S	1	EA	7	2-5 years	Fixed
Exterior Doors - Exterio		Enclosure 1	EA	6	10+ years	



Group Item - Type Location Quantity UOM Rank Exterior Doors - Exterior Steel Door 8 Chiller roof 2 EA 6 Exterior Doors - Exterior Steel Door 9 Green Roof 1 EA 6 Foundation Foundation - Concrete Entire Building 1,103 LF 7	Recommend Replacement 10+ years 10+ years 10+ years 10+ years	Comments
Exterior Doors - Exterior Steel Door 8 Chiller roof 2 EA 6 Exterior Doors - Exterior Steel Door 9 Green Roof 1 EA 6 Foundation	10+ years 10+ years 10+ years	Comments
Exterior Doors - Exterior Steel Door 9 Green Roof 1 EA 6	10+ years 10+ years	
oundation	10+ years	
Foundation - Concrete Entire Building 1.103 LF 7		
	10+ years	
Superstructure - Steel Entire Building 104,203 SF 7		
ighting		
Exterior Lighting - Lighting Entire Building 10 EA 6	6-10 years	
Exterior Lighting - Wall Mounted Entire Building 18 EA 6	6-10 years	
Exterior Lighting - Wall Mounted Entire Building 4 EA 6	6-10 years	
Roof System		
Access Ladder - Metal Roof #1 - Main Roof 1 EA 7	10+ years	
Chimney - Metal Flue Roof #1 - Main Roof 9 LF 7	10+ years	
Chimney - Metal Flue Roof #1 - Main Roof 1 LF 5	0-1 year	Missing cap
Coping - Metal Roof #1 - Main Roof 1,020 LF 6	10+ years	Quantity changed to match curren observations
Downspouts - Interior Downspouts Roof #1 - Main Roof 1,380 LF 6	10+ years	
Roof - Modified Bitumen Roof #1 - Main Roof 36,073 SF 6	10+ years	
Roof Hatch - Metal Roof #1 - Main Roof 1 EA 7	10+ years	
Roof Structure - Steel / Metal Deck/ Roof #1 - Main Roof 36,073 SF 7 Concrete Topping	10+ years	
Coping - Metal Roof #2 - Chiller Roof 125 LF 7	10+ years	Changed to match current
	.o. you.o	observations. Included in the mair roof
Downspouts - Interior Downspouts Roof #2 - Chiller Roof 124 LF 6	10+ years	1001
Roof - Modified Bitumen Roof #2 - Chiller Roof 3,317 SF 6	10+ years	
Roof Structure - Steel / Metal Deck/ Roof #2 - Chiller Roof 3,317 SF 7	10+ years	
Concrete Topping	io. youro	
Coping - Metal Roof #3 - Green Roof 140 LF 6	10+ years	
Downspouts - Interior Downspouts Roof #3 - Green Roof 124 LF 6	10+ years	
Parapet - 16" - 30" Height Roof #3 - Green Roof 140 LF 6	10+ years	
Roof - Asphalt Gravel Ballast Roof #3 - Green Roof 2,006 SF 6	10+ years	Asphalt Ballast roof with green roo
Roof - Green Roof Roof #3 - Green Roof 2,560 SF 6	10+ years	
Roof Structure - Steel / Metal Deck/ Roof #3 - Green Roof 4,566 SF 7	10+ years	
Concrete Topping	101 years	
Valls		
Canopy - Concrete/ Stucco Entire Building 861 SF 7	10+ years	
Exterior Walls - Brick Entire Building 44,419 SF 6	10+ years	
Exterior Walls - Concrete Block Entire Building 3,212 SF 5	10+ years	
Exterior Walls - Concrete Block Entire Building 132 SF 4	1-2 years	Stepped cracking. Quantity chang
	,	TITE SE GIACIMIS AGAINNY GIAIN



Category : Exterior

Albany Park Multicultural Academy 4929 N Sawyer AVENUE, Chicago, IL 60625

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	<u>, </u>		-				to match current observations
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	508	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,073	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	4,344	SF	5	6-10 years	
	Exterior Walls - Stone-Cast	Entire Building	20	SF	3	0-1 year	Displaced
		9				5 · , 5 · · ·	
_Windows	3						
	Curtain wall - Glazed Double Pane	Entire Building	4,620	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	610	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	1,240	SF	7	10+ years	
	Lintels - Steel	Entire Building	603	LF	7	10+ years	
	Windows - Decorative	Entire Building	314	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,220	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	3	EA	6	10+ years	
	Security System - CCTV	Entire Building	104,203	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	104,203	SF	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	47	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	1	EΑ	6	0-1 year	Screen, broken, glass plate missing
	Exit Signs - Gym	Entire Building	4	EΑ	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	8	EΑ	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	24,319	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,986	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	6,154	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	2,802	SF	6	10+ years	
	Emergency Generator- Outdoor- Natural Gas - 101 - 150 KW	Lower Roof	1	EA	7	6-10 years	
_Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	104,203	SF	7	6-10 years	
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	20	EA	7	10+ years	
		-				-	

Building : Main

Recommend

Campus Name: Albany Park Page : 3 of 31 Assessment Date: 05/15/2024



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	ΕA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	3	EA	7	10+ years	
	amp	Fatina Daildina	0	_^	7	40	
	Main Distribution Panels - Greater than 600	Entire Building	3	EA	7	10+ years	
	amp Transformers - 277/480 - 120/208	Entire Building	8	EA	6	10 L VOOR9	
	Transformers - 277/460 - 120/206	Entire Building	0	EA	O	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	Electrical Room	1	EA	7	6-10 years	
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Electrical Room	104,203	SF	6	10+ years	
	Fire Alarm_System	Electrical Room	104,203	SF	6	6-10 years	
	Fire Pump Controller	Electrical Room	1	EA	6	6-10 years	
Pump Re	oom Assembly						
Типрт	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	6-10 years	
	Jockey Pump	Mechanical Room	1	EA	6	6-10 years	
					-		
Sprinkle	r System						
	Sprinkler Heads	Entire Building	104,203	SF	7	10+ years	
	Sprinkler Piping	Entire Building	104,203	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	104,203	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
ge	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litionina					-	
	Chemical Pot Feeder	Lower Roof	1	EA	6	6-10 years	
	Chiller-Air Cooled-Screw Type-Roof	Lower Roof	1	EΑ	6	6-10 years	
	Mounted - 301 - 400 tons		•	== =	-	,	
	Glycol Feed	Lower Roof	1	EA	6	10+ years	Glycol is manually fed into the system
	•		•		-	- ,	through the pot feeder
	Pipes - Chilled Water Pipe- Steel	Lower Roof	1,000	LF	6	10+ years	
	Pressure Fill System	Lower Roof	1	EA	6	10+ years	Glycol is manually fed into the system
	 		•		ŭ	,	through the pressure fill system
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	Serves MDF room
	than 5 tons		•		ŭ	3 .0 ,00.0	



chen/lunchroom area,located in ling underneath tiles. NW located in ceiling underneath s SW located in ceiling underneath s I NW. Located in ceiling derneath tiles.
chen/lunchroom area,located in ling underneath tiles. NW located in ceiling underneath s SW located in ceiling underneath s NW. Located in ceiling derneath tiles.
ling underneath tiles. NW located in ceiling underneath s SW located in ceiling underneath s I NW. Located in ceiling derneath tiles.
ling underneath tiles. NW located in ceiling underneath s SW located in ceiling underneath s I NW. Located in ceiling derneath tiles.
s SW located in ceiling underneath s I NW. Located in ceiling derneath tiles.
s I NW. Located in ceiling derneath tiles.
NW. Located in ceiling derneath tiles.
U-1 serves first floor, southwest
cated in ceilings under tiles oughout building
U-2 serves 3rd floor, Northeast
U-3 serves gym
U-4 serves kitchen & lunchroom
cated in ceiling underneath tiles oughout building
U-5 serves 1st floor, Northwest
cated in ceilings under tiles through building



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Glycol Feed System	Mechanical Room	1	EA	6	6-10 years	Glycol is manually fed into the syste
	Water Fill System	Mechanical Room	1	EA	6	6-10 years	System is a pressure fill system of the hot water pumps
leating	Devices						
J	Fin Tube - Hot Water	Entire Building	200	LF	6	10+ years	
	Unit Heater - Electric	Entire Building	2	EA	6	10+ years	
	Unit Heater - Hot Water	Entire Building	8	EA	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	10	EA	6	10+ years	
	Radiator Panels - Hot Water	Entire Building	6	EA	6	10+ years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	800	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	10+ years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EΑ	6	6-10 years	
	Chilled Water Pump - 21 - 50 HP	Mechanical Room	1	EA	6	6-10 years	
	Chilled Water Pump - 21 - 50 HP	Mechanical Room	1	EA	6	6-10 years	
Tempera	ture Control						
	DDC System	Entire Building	104,203	SF	6	6-10 years	Software recently updated in 2023
	Electric Thermostat	Entire Building	12	EΑ	6	6-10 years	
	Thermostats - DDC	Entire Building	76	EA	7	10+ years	System updated. Thermostats installed in 2023.
/entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	8	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	3	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate							
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	2	EA	7	6-10 years	



Catego	ry : Plumbing		В	uilding	: Main		-
	<u> </u>			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	104,203	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	104,203	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	104,203	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	104,203	SF	7	10+ years	
	(Horizontal Lines)	Little Building	104,200	Oi.	,	101 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	104,203	SF	7	10+ years	
	(Risers)	S .	•			,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	104,203	SF	7	10+ years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	104,203	SF	7	10+ years	
	Storm Piping	Entire Building	104,203	SF	7	10+ years	
	Vent Piping	Entire Building	104,203	SF	7	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	5	0-1 year	Per engineer, pump leaking water. Currently shut off. There is a work
							order in for repair, but on hold
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	10+ years	
Catego	ory : Room		R	uilding	· Main		
Calogo	, , , , , , , , , , , , , , , , , , ,		_	aag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
A dminiat	tratice Cuitas/Offices						
Administ	trative Suites/Offices						
Auminisi	Ceiling - Lay-in	111a Assistant Principal	167	SF	7	10+ years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw	111a Assistant Principal	1	EA	7	10+ years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet	111a Assistant Principal 111a Assistant Principal	1 167	EA SF	7 7	10+ years 6-10 years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor	111a Assistant Principal 111a Assistant Principal 111a Assistant Principal	1 167 6	EA SF EA	7 7 7	10+ years 6-10 years 10+ years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution	111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal	1 167 6 4	EA SF EA EA	7 7 7 7	10+ years 6-10 years 10+ years 10+ years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block	111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal	1 167 6 4 75	EA SF EA EA SF	7 7 7 7 7	10+ years 6-10 years 10+ years 10+ years 10+ years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall	111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal	1 167 6 4 75 133	EA SF EA EA SF SF	7 7 7 7 7 7	10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	
Auminisi	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in	111a Assistant Principal 111k workroom	1 167 6 4 75 133 175	EA SF EA EA SF SF	7 7 7 7 7 7	10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
Auminisi	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw	111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal 111a Assistant Principal	1 167 6 4 75 133 175	EA SF EA SF SF SF EA	7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
Auminisi	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile	111a Assistant Principal 111k workroom 111k workroom 111k workroom	1 167 6 4 75 133 175 1	EA SF EA SF SF SF EA SF	7 7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Auminsi	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in	111a Assistant Principal 111k Workroom 111k workroom 111k workroom 111k workroom	1 167 6 4 75 133 175 1 175	EA SF EA SF SF EA SF EA	7 7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 6-10 years	
Auminisi	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet	111a Assistant Principal 111k workroom 111k workroom 111k workroom 111k workroom 111k workroom	1 167 6 4 75 133 175 1 175 3	EA SF EA SF SF EA SF EA SF	7 7 7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 6-10 years 10+ years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Plaster/Drywall	111a Assistant Principal 111k Workroom 111k workroom 111k workroom 111k workroom	1 167 6 4 75 133 175 1 175 3 100 540	EA SF EA SF SF EA SF EA SF	7 7 7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Plaster/Drywall Ceiling - Lay-in	111a Assistant Principal 111k workroom	1 167 6 4 75 133 175 1 175 3	EA SF EA SF SF EA SF EA SF	7 7 7 7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 6-10 years 10+ years 6-10 years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw	111a Assistant Principal 111k workroom 111k Table Principal	1 167 6 4 75 133 175 1 175 3 100 540 150	EA SF EA SF SF EA SF SF SF EA	7 7 7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years	
Administ	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Plaster/Drywall Ceiling - Lay-in	111a Assistant Principal 111k workroom	1 167 6 4 75 133 175 1 175 3 100 540 150	EA SF EA SF SF EA SF SF SF SF	7 7 7 7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 6-10 years 10+ years 6-10 years	
_Auminisi	Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Carpet Lighting - Metal Halide/Sodium Vapor Power Distribution Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Plaster/Drywall Ceiling - Lay-in Doors - Steel Doors incl hw	111a Assistant Principal 111k workroom 111k Table Principal	1 167 6 4 75 133 175 1 175 3 100 540 150	EA SF EA SF SF EA SF SF SF EA	7 7 7 7 7 7 7 7 7 7	10+ years 6-10 years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	114C	200	SF	7	10+ years	
	Ceiling - Lay-in	114D	150	SF	7	6-10 years	
	Doors - Steel Doors incl hw	114D	1	EA	7	10+ years	
	Floor - Carpet	114D	150	SF	7	6-10 years	
	Lighting - Lay-in	114D	3	EΑ	7	6-10 years	
	Walls - Concrete Block	114D	200	SF	7	10+ years	
	Walls - Plaster/Drywall	114D	200	SF	7	10+ years	
	Ceiling - Lay-in	122A Kitchen manager's office	94	SF	7	10+ years	
	Doors - Side-lite	122A Kitchen manager's office	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	122A Kitchen manager's office	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	122A Kitchen manager's office	94	SF	7	10+ years	
	Lighting - Lay-in	122A Kitchen manager's office	2	EA	7	10+ years	
	Power Distribution	122A Kitchen manager's office	6	EΑ	7	10+ years	
	Walls - Concrete Block	122A Kitchen manager's office	237	SF	7	10+ years	
	Ceiling - Lay-in	122F- Pantry	137	SF	6	10+ years	
	Doors - Steel Doors incl hw	122F- Pantry	1	EA	7	10+ years	
	Floor - Tile	122F- Pantry	137	SF	7	10+ years	
	Lighting - Lay-in	122F- Pantry	2	EA	7	10+ years	
	Power Distribution	122F- Pantry	4	EA	7	10+ years	
	Walls - Concrete Block	122F- Pantry	97	SF	7	10+ years	
	Walls - Plaster/Drywall	122F- Pantry	290	SF	7	10+ years	
	Ceiling - Lay-in	Building Engineer Room 128A(160)	235	SF	7	10+ years	
	Doors - Steel Doors incl hw	Building Engineer Room 128A(160)	1	EA	7	10+ years	
	Floor - Tile	Building Engineer Room 128A(160)	235	SF	7	10+ years	
	Lighting - Lay-in	Building Engineer Room 128A(160)	4	EA	7	10+ years	
	Power Distribution	Building Engineer Room 128A(160)	10	EA	7	10+ years	
	Walls - Concrete Block	Building Engineer Room 128A(160)	540	SF	7	10+ years	
	Ceiling - Lay-in	Gym office 101a	157	SF	6	10+ years	
	Doors - Side-lite	Gym office 101a	7	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gym office 101a	1	ĒΑ	7	10+ years	
	Floor - Tile	Gym office 101a	157	SF	7	10+ years	
	Lighting - Lay-in	Gym office 101a	2	ĒΑ	7	10+ years	
	Power Distribution	Gym office 101a	10	EA	7	10+ years	
	Walls - Concrete Block	Gym office 101a	406	SF	7	10+ years	
	Ceiling - Lay-in	Office 111E - Conference room	167	SF	7	10+ years	
	Doors - Steel Doors incl hw	Office 111E - Conference room	1	EΑ	7	10+ years	
	Floor - Carpet	Office 111E - Conference room	167	SF	7	6-10 years	
	Lighting - Lay-in	Office 111E - Conference room	6	EA	7	10+ years	
	Power Distribution	Office 111E - Conference room	6	EA	7	10+ years	
	Walls - Concrete Block	Office 111E - Conference room	208	SF	7	10+ years	
	Walls - Plaster/Drywall	Office 111E - Conference room	208	SF	7	10+ years	
	Ceiling - Lay-in	Principal's office 111B	341	SF	7	10+ years	
	Doors - Steel Doors incl hw	Principal's office 111B	1	EA	7	10+ years	
	Floor - Carpet	Principal's office 111B	341	SF	7	6-10 years	
	1 looi ouipot	i illopara olloc IIID	J + I	51	'	o io years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Principal's office 111B	4	EA	7	10+ years	
	Power Distribution	Principal's office 111B	12	EA	7	10+ years	
	Walls - Concrete Block	Principal's office 111B	298	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's office 111B	298	SF	6	10+ years	
	Ceiling - Lay-in	Rom 211A workroom in Library (206 on the plan)	275	SF	7	10+ years	
	Doors - Steel Doors incl hw	Rom 211A workroom in Library (206 on the plan)	1	EA	7	10+ years	
	Floor - Carpet	Rom 211A workroom in Library (206 on the plan)	275	SF	7	6-10 years	
	Lighting - Lay-in	Rom 211A workroom in Library (206 on the plan)	3	EA	7	10+ years	
	Power Distribution	Rom 211A workroom in Library (206 on the plan)	20	EA	7	10+ years	
	Storage/ Closet	Rom 211A workroom in Library (206 on the plan)	165	SF	7	10+ years	
	Walls - Concrete Block	Rom 211A workroom in Library (206 on the plan)	563	SF	7	10+ years	
	Work SInk	Rom 211A workroom in Library (206 on the plan)	1	EA	7	10+ years	
	Ceiling - Lay-in	Room 111 main office (office #101 on the plan)	518	SF	7	10+ years	
	Doors - Side-lite	Room 111 main office (office #101 on the plan)	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 111 main office (office #101 on the plan)	1	EA	7	10+ years	
	Floor - Terrazzo	Room 111 main office (office #101 on the plan)	518	SF	7	10+ years	
	Lighting - Lay-in	Room 111 main office (office #101 on the plan)	12	EA	7	10+ years	
	Power Distribution	Room 111 main office (office #101 on the plan)	12	EA	7	10+ years	
	Storage/ Closet	Room 111 main office (office #101 on the plan)	50	SF	7	10+ years	
	Walls - Concrete Block	Room 111 main office (office #101 on the plan)	808	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 111 main office (office #101 on the plan)	270	SF	7	10+ years	
	Ceiling - Lay-in	Room 111C, Principal	222	SF	6	10+ years	
	Doors - Steel Doors incl hw	Room 111C, Principal	1	EA	7	10+ years	
	Floor - Carpet	Room 111C, Principal	222	SF	6	6-10 years	
	Lighting - Lay-in	Room 111C, Principal	5	EA	6	10+ years	
	Power Distribution	Room 111C, Principal	8	EA	7		
	Walls - Concrete Block	Room 111C, Principal	246	SF	6	10+ years	
	vvalis - Culiciele bluck	Room Fire, Annapai	240	SF	Ö	10+ years	



Catego	ry : Room	-	В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Room 111D - Conference Room	167	SF	7	10+ years	
	Doors - Steel Doors incl hw	Room 111D - Conference Room	1	EA	7	10+ years	
	Floor - Carpet	Room 111D - Conference Room	167	SF	6	6-10 years	
	Lighting - Lay-in	Room 111D - Conference Room	6	EA	7	10+ years	
	Power Distribution	Room 111D - Conference Room	6	EA	7	10+ years	
	Walls - Concrete Block	Room 111D - Conference Room	208	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 111D - Conference Room	208	SF	7	10+ years	
	Ceiling - Lay-in	Room 309 staff lounge(303 on the plan)	656	SF	6	10+ years	
	Doors - Side-lite	Room 309 staff lounge(303 on the plan)	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 309 staff lounge(303 on the plan)	1	EA	7	10+ years	
	Floor - Tile	Room 309 staff lounge(303 on the plan)	656	SF	6	10+ years	
	Lighting - Lay-in	Room 309 staff lounge(303 on the plan)	8	EA	7	10+ years	
	Power Distribution	Room 309 staff lounge(303 on the plan)	8	EA	6	10+ years	
	Walls - Concrete Block	Room 309 staff lounge(303 on the plan)	825	SF	6	10+ years	
	Work SInk	Room 309 staff lounge(303 on the plan)	1	EA	7	10+ years	
	Ceiling - Lay-in	Room 328 APMA office	449	SF	6	10+ years	
	Ceiling - Lay-in	Room 328 APMA office	8	SF	5	0-1 year	Missing
	Doors - Side-lite	Room 328 APMA office	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 328 APMA office	1	EA	7	10+ years	
	Floor - Tile	Room 328 APMA office	457	SF	6	10+ years	
	Lighting - Lay-in	Room 328 APMA office	5	EA	7	10+ years	
	Lighting - Lay-in	Room 328 APMA office	1	EA	6	6-10 years	
	Power Distribution	Room 328 APMA office	6	EA	6	10+ years	
	Walls - Concrete Block	Room 328 APMA office	718	SF	7	6-10 years	
	Ceiling - Lay-in	Work Break Room in 111	210	SF	7	10+ years	
	Doors - Steel Doors incl hw	Work Break Room in 111	2	EA	7	10+ years	
	Floor - Tile	Work Break Room in 111	210	SF	7	10+ years	
	Lighting - Lay-in	Work Break Room in 111	4	EA	7	6-10 years	
	Power Distribution	Work Break Room in 111	8	EA	7	10+ years	
	Storage/ Closet	Work Break Room in 111	35	SF	7	10+ years	
	Walls - Plaster/Drywall	Work Break Room in 111	800	SF	7	10+ years	
	Work SInk	Work Break Room in 111	1	EA	7	6-10 years	
_Gymnas							
	Bleacher Seating	1st Floor Room 101	70	EA	6	10+ years	
	Ceiling - Exposed	1st Floor Room 101	3,896	SF	6	10+ years	



	ry : Room		D	uilding	· Main		929 N Sawyer Avenue, Chicago, ic 60625
Calego	ry . Room		ь	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Doors - Steel Doors incl hw	1st Floor Room 101	5	EA	7	10+ years	Comments
	Floor - Wood	1st Floor Room 101	3,796	SF	6	10+ years	
	Floor - Wood	1st Floor Room 101	100	SF	4	0-1 year	Damaged flooring
	Lighting - Metal Halide/Sodium Vapor	1st Floor Room 101	20	EA	7	10+ years	Damaged hooling
	Lighting - Pendent/Surface	1st Floor Room 101	1	EA	5	0-1 year	Damaged exit sign
	Scoreboards	1st Floor Room 101	1	EA	7	10+ years	Damaged exit sign
	Storage/ Closet	1st Floor Room 101	240	SF	7	10+ years	
	Walls - Concrete Block	1st Floor Room 101	6,110	SF	6	10+ years	
	Walls - Concrete Block	1st Floor Room 101	5	SF	5	•	Cracked masonry
	Walls - Concrete Block	IST FIOOT ROOM TOT	5	SF	5	1-2 years	Cracked masonry
_Kitchen							
	Ceiling - Lay-in	1st Floor	875	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	875	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	1,062	SF	6	10+ years	
Librani							
Library	Casework	Room 211 (201 # on the plan)	70	LF	7	10+ years	
	Casework Ceiling - Lay-in	Room 211 (201 # on the plan)	4,557	SF	6	10+ years	
	Ceiling - Lay-III Ceiling - Plaster/Drywall	Room 211 (201 # on the plan)	500	SF	6	•	
	Doors - Side-lite	Room 211 (201 # on the plan)	36	SF	7	10+ years 10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	Room 211 (201 # on the plan)	36	SF EA	7	•	
	Floor - Carpet	Room 211 (201 # on the plan)	5,057	SF	6	10+ years	
	Lighting - Lay-in	Room 211 (201 # on the plan)	5,057 56	EA	7	6-10 years 10+ years	
	Walls - Masonry	Room 211 (201 # on the plan)		SF		•	
			6,207	SF SF	6 6	10+ years	
	Walls - Plaster/Drywall	Room 211 (201 # on the plan)	300	SF	б	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	Dining Room 118 1st Floor	6,154	SF	6	10+ years	
	Doors - Steel Doors incl hw	Dining Room 118 1st Floor	5	EA	7	10+ years	
	Floor - Tile	Dining Room 118 1st Floor	6,154	SF	6	10+ years	
	Lighting - Lay-in	Dining Room 118 1st Floor	34	EA	7	10+ years	
	Serving Line	Dining Room 118 1st Floor	45	LF	6	10+ years	
	Storage/ Closet	Dining Room 118 1st Floor	81	SF	7	10+ years	
	Walls - Concrete Block	Dining Room 118 1st Floor	4,648	SF	6	10+ years	
	Walls - Plaster/Drywall	Dining Room 118 1st Floor	414	SF	6	10+ years	
	Walls - Structural Glazed Tile	Dining Room 118 1st Floor	1,135	SF	6	10+ years	
MDF ID	F						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	145	SF	7	6-10 years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Split unit
	55. 550mig 5.m.		'	_, 、	•	o lo youlo	ep dim



ateno	ry : Room	Building : Main				,	
Jaicgo	ry . Room						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ТОИР	item - Type	Location	Quantity	OOW	Italik	Replacement	Comments
aabani	cal/ Service Rooms						
echani		4 - t - Cl	400	0.5	7	40	
	Janitor's Closet	1st Floor	180	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,080	SF	7	10+ years	
	Storage Room	1st Floor	240	SF	7	10+ years	
	Janitor's Closet	2nd Floor	50	SF	7	10+ years	
	Janitor's Closet	2nd Floor	50	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	2,522	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	88	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	88	SF	7	10+ years	
	Storage Room	2nd Floor	160	SF	7	10+ years	
	Storage Room	2nd Floor	160	SF	7	10+ years	
	Storage Room	2nd Floor	366	SF	7	10+ years	
	Janitor's Closet	3rd Floor	50	SF	7	10+ years	
	Janitor's Closet	3rd Floor	50	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	1,636	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	88	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	1,242	SF	7	10+ years	
	Storage Room	3rd Floor	221	SF	7	10+ years	
						_	
estroor	n						
	Accessories	1st floor north boys' room	203	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor north boys' room	203	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor north boys' room	203	SF	6	10+ years	
	Floor Drain	1st floor north boys' room	1	EA	7	10+ years	
	Hand Dryer	1st floor north boys' room	2	EΑ	7	6-10 years	
	Lavatory	1st floor north boys' room	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor north boys' room	7	EA	6	10+ years	
	Partitions	1st floor north boys' room	2	EA	7	10+ years	
	Urinals	1st floor north boys' room	3	EA	7	,	
	Walls - Tile Ceramic/ Porcelain	1st floor north boys' room	451	SF	6	10+ years	
	Water Closet		451 2	EA	7	10+ years	
		1st floor north boys' room		SF		10+ years	
	Accessories	1st floor north girls' room	265		7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor north girls' room	265	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor north girls' room	265	SF	7	10+ years	
	Floor Drain	1st floor north girls' room	1	EA	7	10+ years	
	Hand Dryer	1st floor north girls' room	2	EA	7	6-10 years	
	Lavatory	1st floor north girls' room	1_	EA	7	10+ years	
	Lighting - Lay-in	1st floor north girls' room	7	EA	7	10+ years	
	Partitions	1st floor north girls' room	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor north girls' room	545	SF	7	10+ years	
	Water Closet	1st floor north girls' room	5	EA	7	10+ years	
	Accessories	1st floor north unisex restroom	62	SF	7	10+ years	
	Ceiling - Lay-in	1st floor north unisex restroom	62	SF	6	10+ years	



Catego	Category : Room			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	1st floor north unisex restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor north unisex restroom	62	SF	6	10+ years	
	Floor Drain	1st floor north unisex restroom	1	EA	7	10+ years	
	Lavatory	1st floor north unisex restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor north unisex restroom	2	EA	6	10+ years	
	Walls - Concrete Block	1st floor north unisex restroom	252	SF	6	10+ years	
	Water Closet	1st floor north unisex restroom	1	EA	7	6-10 years	
	Accessories	1st floor south boys' room	203	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor south boys' room	203	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor south boys' room	203	SF	7	10+ years	
	Floor Drain	1st floor south boys' room	1	EA	7	10+ years	
	Hand Dryer	1st floor south boys' room	2	EA	7	6-10 years	
	Lavatory	1st floor south boys' room	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor south boys' room	7	EA	7	10+ years	
	Partitions	1st floor south boys' room	2	EA	7	10+ years	
	Urinals	1st floor south boys' room	3	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor south boys' room	451	SF	6	10+ years	
	Water Closet	1st floor south boys' room	2	EA	6	10+ years	
	Accessories	1st floor south girls' room	265	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor south girls' room	265	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor south girls' room	265	SF	6	10+ years	
	Floor Drain	1st floor south girls' room	1	EA	7	10+ years	
	Hand Dryer	1st floor south girls' room	2	EA	7	6-10 years	
	Lavatory	1st floor south girls' room	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor south girls' room	7	EA	7	10+ years	
	Partitions	1st floor south girls' room	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor south girls' room	545	SF	7	10+ years	
	Water Closet	1st floor south girls' room	5	EΑ	7	10+ years	
	Accessories	1st floor south unisex restroom	62	SF	7	10+ years	
	Ceiling - Lay-in	1st floor south unisex restroom	62	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st floor south unisex restroom	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor south unisex restroom	62	SF	6	10+ years	
	Floor Drain	1st floor south unisex restroom	1	EA	7	10+ years	
	Lavatory	1st floor south unisex restroom	1	EΑ	6	10+ years	
	Lighting - Lay-in	1st floor south unisex restroom	2	EA	6	10+ years	
	Walls - Concrete Block	1st floor south unisex restroom	252	SF	6	10+ years	
	Water Closet	1st floor south unisex restroom	1	EA	6	10+ years	
	Accessories	2nd near 208 girls' room	265	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd near 208 girls' room	265	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd near 208 girls' room	265	SF	6	10+ years	
	Floor Drain	2nd near 208 girls' room	1	EA	7	10+ years	
	Hand Dryer	2nd near 208 girls' room	2	EA	7	6-10 years	
	Lavatory	2nd near 208 girls' room	1	EA	7	10+ years	
	Lighting - Lay-in	2nd near 208 girls' room	7	EA	7	10+ years	
		-				-	

Campus Name: Albany Park Page: 13 of 31 Assessment Date: 05/15/2024



Catego	ry : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Partitions	2nd near 208 girls' room	5	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd near 208 girls' room	545	SF	7	10+ years		
	Water Closet	2nd near 208 girls' room	5	EΑ	7	10+ years		
	Accessories	2nd near 208 unisex	62	SF	7	6-10 years		
	Ceiling - Lay-in	2nd near 208 unisex	62	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd near 208 unisex	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd near 208 unisex	62	SF	6	10+ years		
	Floor Drain	2nd near 208 unisex	1	EA	7	10+ years		
	Lavatory	2nd near 208 unisex	1	EΑ	7	10+ years		
	Lighting - Lay-in	2nd near 208 unisex	2	EA	7	10+ years		
	Walls - Concrete Block	2nd near 208 unisex	252	SF	6	10+ years		
	Water Closet	2nd near 208 unisex	1	EA	7	10+ years		
	Accessories	2nd near 210 north boys' room	203	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd near 210 north boys' room	203	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd near 210 north boys' room	203	SF	6	10+ years		
	Floor Drain	2nd near 210 north boys' room	1	ĒΑ	7	10+ years		
	Hand Dryer	2nd near 210 north boys' room	2	EA	7	6-10 years		
	Lavatory	2nd near 210 north boys' room	1	EA	7	10+ years		
	Lighting - Lay-in	2nd near 210 north boys' room	7	EA	7	10+ years		
	Partitions	2nd near 210 north boys' room	2	EA	7	10+ years		
	Urinals	2nd near 210 north boys' room	3	EΑ	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd near 210 north boys' room	451	SF	7	10+ years		
	Water Closet	2nd near 210 north boys' room	2	EA	7	10+ years		
	Accessories	2nd near 217 girls' room	265	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd near 217 girls room	265	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd near 217 girls room	265	SF	6	10+ years		
	Floor Drain	2nd near 217 girls room	1	EA	7	10+ years		
	Hand Dryer	2nd near 217 girls room	2	EA	7	6-10 years		
	Lavatory	2nd near 217 girls room	1	EA	7	10+ years		
	Lighting - Lay-in	2nd near 217 girls room	7	EA	7	10+ years		
	Partitions	2nd near 217 girls room 2nd near 217 girls' room	5	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd near 217 girls room	545	SF	7	10+ years		
	Water Closet	2nd near 217 girls room	5	EA	7	10+ years		
	Accessories	2nd near 217 girls 100m	62	SF	7	6-10 years		
	Ceiling - Lay-in	2nd near 217 unisex restroom	62	SF	4	1-2 years	Water stain throughout	
	Floor - Tile Ceramic/ Porcelain	2nd near 217 unisex restroom	62	SF	6	10+ years	Water stain throughout	
	Floor Drain	2nd near 217 unisex restroom 2nd near 217 unisex restroom	1	EA	7	6-10 years		
	Lavatory	2nd near 217 unisex restroom 2nd near 217 unisex restroom	1	EA	7	10+ years		
	Lavatory Lighting - Lay-in	2nd near 217 unisex restroom 2nd near 217 unisex restroom	2	EA	7	•		
	Walls - Concrete Block	2nd near 217 unisex restroom 2nd near 217 unisex restroom	252	SF		10+ years		
					6	10+ years		
	Water Closet	2nd near 217 unisex restroom	1	EA SF	7	10+ years		
	Accessories	2nd near 218 boys' room	203		7	6-10 years		
	Ceiling - Plaster/Drywall	2nd near 218 boys' room	203	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd near 218 boys' room	203	SF	6	10+ years		

Campus Name: Albany Park Page : 14 of 31 Assessment Date: 05/15/2024



F H L:	tem - Type Floor Drain Hand Dryer .avatory .ighting - Lay-in	Location 2nd near 218 boys' room	Quantity	UOM	Rank	Recommend	
Fi H Li Li	loor Drain Hand Dryer avatory	2nd near 218 boys' room		UOM	Donk	Daulasaus	•
H Li Li	Hand Dryer Lavatory				Kalik	Replacement	Comments
L: Li	avatory	0 1 0401 1	1	EΑ	7	10+ years	
Li		2nd near 218 boys' room	2	EA	7	10+ years	
	ighting Lay in	2nd near 218 boys' room	1	EΑ	7	10+ years	
	igning - Lay-in	2nd near 218 boys' room	7	EA	7	10+ years	
	Partitions	2nd near 218 boys' room	2	EA	7	10+ years	
U	Jrinals	2nd near 218 boys' room	3	EA	7	10+ years	
V	Valls - Tile Ceramic/ Porcelain	2nd near 218 boys' room	451	SF	7	10+ years	
	Vater Closet	2nd near 218 boys' room	2	ĒΑ	7	10+ years	
Α	Accessories	3rd boys' room south near 316	203	SF	7	10+ years	
С	Ceiling - Plaster/Drywall	3rd boys' room south near 316	203	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd boys' room south near 316	203	SF	6	10+ years	
	Floor Drain	3rd boys' room south near 316	1	ĒΑ	7	10+ years	
	Hand Dryer	3rd boys' room south near 316	2	ΕA	7	6-10 years	
	_avatory	3rd boys' room south near 316	1	EΑ	6	10+ years	
	ighting - Lay-in	3rd boys' room south near 316	7	EΑ	7	10+ years	
	Partitions	3rd boys' room south near 316	2	EA	7	10+ years	
	Jrinals	3rd boys' room south near 316	3	EA	7	10+ years	
_	Valls - Structural Glazed Tile	3rd boys' room south near 316	451	SF	7	10+ years	
	Vater Closet	3rd boys room south near 316	2	EA	7	10+ years	
	Accessories	3rd near 308 girls' room north	265	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd near 308 girls' room north	265	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd near 308 girls' room north	265	SF	6	10+ years	
	Floor Drain	3rd near 308 girls' room north	203	EA	7	,	
	avatory	3rd near 308 girls room north	1	EA	6	10+ years 10+ years	
		3rd near 308 girls room north	7	EA	7		
	ighting - Lay-in Partitions	3rd near 308 girls' room north	5	EA	7	10+ years	
-	Valls - Tile Ceramic/ Porcelain		5 545	SF	6	10+ years	
	Vater Closet	3rd near 308 girls' room north		EA	7	10+ years	
		3rd near 308 girls' room north	5	SF		10+ years	
	Accessories	3rd near 308 unisex restroom north	62		7	10+ years	
	Ceiling - Lay-in	3rd near 308 unisex restroom north	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd near 308 unisex restroom north	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd near 308 unisex restroom north	62	SF	6	10+ years	
	Floor Drain	3rd near 308 unisex restroom north	1	EΑ	7	10+ years	
	avatory	3rd near 308 unisex restroom north	1	EΑ	6	10+ years	
	Lighting - Lay-in	3rd near 308 unisex restroom north	2	EA	7	10+ years	
	Valls - Concrete Block	3rd near 308 unisex restroom north	252	SF	6	10+ years	
	Vater Closet	3rd near 308 unisex restroom north	1	EA	6	10+ years	
	Accessories	3rd near 310 north boys' room	203	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd near 310 north boys' room	203	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd near 310 north boys' room	203	SF	6	10+ years	
	Floor Drain	3rd near 310 north boys' room	1	EA	7	10+ years	
	land Dryer	3rd near 310 north boys' room	2	EA	7	6-10 years	
	avatory	3rd near 310 north boys' room	1	EA	6	10+ years	
Li	ighting - Lay-in	3rd near 310 north boys' room	7	EA	7	10+ years	

Campus Name: Albany Park Page : 15 of 31 Assessment Date: 05/15/2024



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	3rd near 310 north boys' room	2	EA	7	10+ years	
	Urinals	3rd near 310 north boys' room	3	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd near 310 north boys' room	451	SF	6	10+ years	
	Water Closet	3rd near 310 north boys' room	2	EA	7	10+ years	
	Accessories	3rd south girls' room near 317	265	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd south girls' room near 317	265	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd south girls' room near 317	265	SF	6	10+ years	
	Floor Drain	3rd south girls' room near 317	1	EA	7	10+ years	
	Hand Dryer	3rd south girls' room near 317	2	EA	7	6-10 years	
	Lavatory	3rd south girls' room near 317	1	EA	6	10+ years	
	Lighting - Lay-in	3rd south girls' room near 317	8	EA	7	10+ years	
	Partitions	3rd south girls' room near 317	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd south girls' room near 317	545	SF	6	10+ years	
	Water Closet	3rd south girls' room near 317	5	EA	7	10+ years	
	Accessories	3rd unisex restroom south near 317	62	SF	7	10+ years	
	Ceiling - Lay-in	3rd unisex restroom south near 317	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd unisex restroom south near 317	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd unisex restroom south near 317	62	SF	6	10+ years	
	Floor Drain	3rd unisex restroom south near 317	1	EA	7	10+ years	
	Lavatory	3rd unisex restroom south near 317	1	EA	6	10+ years	
	Lighting - Lay-in	3rd unisex restroom south near 317	1	EA	7	10+ years	
	Walls - Concrete Block	3rd unisex restroom south near 317	252	SF	6	10+ years	
	Water Closet	3rd unisex restroom south near 317	1	EA	7	10+ years	
	Accessories	In main office area	62	SF	7	6-10 years	
	Ceiling - Lay-in	In main office area	62	SF	6	10+ years	
	Doors - Steel Doors incl hw	In main office area	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In main office area	62	SF	6	10+ years	
	Floor Drain	In main office area	1	EA	7	10+ years	
	Lavatory	In main office area	1	EA	7	10+ years	
	Lighting - Lay-in	In main office area	1	EA	6	10+ years	
	Walls - Concrete Block	In main office area	252	SF	6	10+ years	
	Water Closet	In main office area	1	ĒΑ	7	10+ years	
	Accessories	In room 110 (131A)	70	SF	7	6-10 years	
	Ceiling - Lay-in	In room 110 (131A)	70	SF	7	10+ years	
	Doors - Steel Doors incl hw	In room 110 (131A)	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In room 110 (131A)	70	SF	7	10+ years	
	Floor Drain	In room 110 (131A)	1	EA	7	10+ years	
	Lavatory	In room 110 (131A)	1	EΑ	7	10+ years	
	Lighting - Lay-in	In room 110 (131A)	1	EΑ	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	In room 110 (131A)	315	SF	7	10+ years	
	Water Closet	In room 110 (131A)	1	EA	7	10+ years	
	Accessories	In room 106 (130A)	70	SF	7	6-10 years	
	Ceiling - Lay-in	In room 106 (130A)	70	SF	7	10+ years	
	Doors - Steel Doors incl hw	In room 106 (130A)	1	EA	7	10+ years	
	200.0 0.001 20010 III0I IIW	111100111 100 (100/1)	•	_/\	,	ioi youis	



Category : Room Building : Main Group Item - Type Location Quantity UOM Rank Replacement Floor - Tile Ceramic/ Porcelain In room 106 (130A) 70 SF 7 10+ years Floor Drain In room 106 (130A) 1 EA 7 10+ years Lavatory In room 106 (130A) 1 EA 7 10+ years Lighting - Lay-in In room 106 (130A) 315 SF 7 10+ years Water Closet In room 106 (130A) 1 EA 7 10+ years Accessories In room 115 70 SF 7 6-10 years Ceiling - Lay-in In room 115 70 SF 7 10+ years	Comments
Floor - Tile Ceramic/ Porcelain In room 106 (130A) 70 SF 7 10+ years Floor Drain In room 106 (130A) 1 EA 7 10+ years Lavatory In room 106 (130A) 1 EA 7 10+ years Lighting - Lay-in In room 106 (130A) 1 EA 7 10+ years Walls - Tile Ceramic/ Porcelain In room 106 (130A) 315 SF 7 10+ years Water Closet In room 106 (130A) 1 EA 7 10+ years Accessories In room 115 70 SF 7 6-10 years	Comments
Floor Drain In room 106 (130A) 1 EA 7 10+ years Lavatory In room 106 (130A) 1 EA 7 10+ years Lighting - Lay-in In room 106 (130A) 1 EA 7 10+ years Walls - Tile Ceramic/ Porcelain In room 106 (130A) 315 SF 7 10+ years Water Closet In room 106 (130A) 1 EA 7 10+ years Accessories In room 115 70 SF 7 6-10 years	
Lavatory In room 106 (130A) 1 EA 7 10+ years Lighting - Lay-in In room 106 (130A) 1 EA 7 10+ years Walls - Tile Ceramic/ Porcelain In room 106 (130A) 315 SF 7 10+ years Water Closet In room 106 (130A) 1 EA 7 10+ years Accessories In room 115 70 SF 7 6-10 years	
Lighting - Lay-in In room 106 (130A) 1 EA 7 10+ years Walls - Tile Ceramic/ Porcelain In room 106 (130A) 315 SF 7 10+ years Water Closet In room 106 (130A) 1 EA 7 10+ years Accessories In room 115 70 SF 7 6-10 years	
Walls - Tile Ceramic/ Porcelain In room 106 (130A) 315 SF 7 10+ years Water Closet In room 106 (130A) 1 EA 7 10+ years Accessories In room 115 70 SF 7 6-10 years	
Water Closet In room 106 (130A) 1 EA 7 10+ years Accessories In room 115 70 SF 7 6-10 years	
Accessories In room 115 70 SF 7 6-10 years	
Ceiling - Lav-in In room 115 70 SF 7 10+ vears	
, , , , , , , , , , , , , , , , , , ,	
Doors - Steel Doors incl hw In room 115 1 EA 7 10+ years	
Floor - Tile Ceramic/ Porcelain In room 115 70 SF 7 10+ years	
Floor Drain In room 115 1 EA 7 10+ years	
Lavatory In room 115 1 EA 7 10+ years	
Lighting - Lay-in In room 115 1 EA 7 10+ years	
Walls - Tile Ceramic/ Porcelain In room 115 315 SF 7 10+ years	
Water Closet In room 115 1 EA 7 10+ years	
Accessories In room 123 70 SF 7 10+ years	
Ceiling - Lay-in In room 123 70 SF 7 10+ years	
Doors - Steel Doors incl hw In room 123 1 EA 7 10+ years	
Floor - Tile Ceramic/ Porcelain In room 123 70 SF 7 10+ years	
Floor Drain In room 123 1 EA 7 10+ years	
Lavatory In room 123 1 EA 7 10+ years	
Lighting - Lay-in In room 123 1 EA 7 10+ years	
Walls - Tile Ceramic/ Porcelain In room 123 315 SF 6 10+ years	
Water Closet In room 123 1 EA 6 10+ years	
Accessories In room 127 70 SF 7 10+ years	
Ceiling - Lay-in In room 127 70 SF 7 10+ years	
Doors - Steel Doors incl hw In room 127 1 EA 7 10+ years	
Floor - Tile Ceramic/ Porcelain In room 127 70 SF 7 10+ years	
Floor Drain In room 127 1 EA 7 10+ years	
Lavatory In room 127 1 EA 7 10+ years	
Lighting - Lay-in In room 127 1 EA 6 10+ years	
Walls - Tile Ceramic/ Porcelain In room 127 315 SF 6 10+ years	
Water Closet In room 127 1 EA 6 10+ years Accessories Men's room in the kitchen area 55 SF 7 10+ years	
Doors - Steel Doors incl hw Men's room in the kitchen area 1 EA 7 10+ years Floor - Concrete Epoxy/ Painted Men's room in the kitchen area 55 SF 7 10+ years	
Floor Drain Men's room in the kitchen area 1 EA 7 10+ years	
Lavatory Men's room in the kitchen area 1 EA 7 10+ years	
Lighting - Lay-in Men's room in the kitchen area 1 EA 7 10+ years	
Student Lockers - One Tier Men's room in the kitchen area 7 EA 7 10+ years	
,	
· · · · · · · · · · · · · · · · · · ·	
Water Closet Men's room in the kitchen area 1 EA 6 10+ years Accessories Rooms 114A-2 & A-3 80 SF 7 6-10 years	
7.00000001100 110 years	

Campus Name: Albany Park Page: 17 of 31 Assessment Date: 05/15/2024



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Rooms 114A-2 & A-3	80	SF	6	10+ years	
	Doors - Steel Doors incl hw	Rooms 114A-2 & A-3	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Rooms 114A-2 & A-3	80	SF	6	10+ years	
	Floor Drain	Rooms 114A-2 & A-3	2	EA	7	10+ years	
	Lavatory	Rooms 114A-2 & A-3	1	EA	7	10+ years	
	Lighting - Lay-in	Rooms 114A-2 & A-3	1	EA	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	Rooms 114A-2 & A-3	1	EA	7	10+ years	
	Showers	Rooms 114A-2 & A-3	1	EA	7	10+ years	
	Walls - Concrete Block	Rooms 114A-2 & A-3	340	SF	7	10+ years	
	Water Closet	Rooms 114A-2 & A-3	1	EA	7	10+ years	
	Accessories	Women's room in kitchen area	55	SF	7	10+ years	
	Ceiling - Lay-in	Women's room in kitchen area	55	SF	7	10+ years	
	Doors - Steel Doors incl hw	Women's room in kitchen area	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Women's room in kitchen area	55	SF	7	10+ years	
	Floor Drain	Women's room in kitchen area	1	EA	7	10+ years	
	Lavatory	Women's room in kitchen area	1	EA	7	10+ years	
	Lighting - Lay-in	Women's room in kitchen area	1	EA	7	10+ years	
	Student Lockers - One Tier	Women's room in kitchen area	8	EA	7	10+ years	
	Walls - Concrete Block	Women's room in kitchen area	238	SF	7	10+ years	
	Water Closet	Women's room in kitchen area	1	EA	7	10+ years	

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #102 (Fitness Room)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor	890	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	490	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	7	10+ years	
Classroo	om #106 (Regular Classroom)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,175	SF	7	10+ years	
	Doors - Side-lite	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,165	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Damaged tiles
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	•
	Marker Board	1st Floor	12	LF	7	6-10 years	

Page : 18 of 31 Campus Name: Albany Park Assessment Date: 05/15/2024



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Storage/ Closet	1st Floor	63	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	740	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	530	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classroc	om #110 (Kindergarten)								
	Casework	1st Floor	50	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,175	SF	7	10+ years			
	Doors - Side-lite	1st Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	1,175	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	15	ĒΑ	7	10+ years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Storage/ Closet	1st Floor	63	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	740	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	530	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classroo	om #115 (Art Room)								
0.000.00	Casework	1st Floor	30	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,175	SF	7	10+ years			
	Doors - Side-lite	1st Floor	14	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years			
	Floor - Tile	1st Floor	1,175	SF	6	10+ years			
	Instructional Surface	1st Floor	8	LF	6	10+ years			
	Kiln	1st Floor	1	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	2	EA	6	10+ years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
			50	SF	7	,			
	Storage/ Closet Walls - Concrete Block	1st Floor		SF SF		10+ years			
	Work Sink	1st Floor 1st Floor	1,270 2	EA	7 7	10+ years 10+ years			
Classron	om #123 (Regular Classroom)								
<u> </u>	Casework	1st Floor	50	LF	7	10+ years			
	Casework Ceiling - Lay-in	1st Floor	1,175	SF	7	10+ years 10+ years			
	Doors - Side-lite	1st Floor	1,175	SF SF					
		1st Floor		SF EA	7	10+ years			
	Doors - Wood Doors inclu hw		2		7	10+ years			
	Floor - Tile	1st Floor	1,175	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Storage/ Closet	1st Floor	63	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	740	SF	7	10+ years			



Catogo	ategory : Classroom		P	uilding	· Main		929 N Sawyel AVENUE, Chicago, iL 60623
Calego	iy . Classioolii			unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Walls - Plaster/Drywall	1st Floor	530	SF	7	10+ years	Comments
	Work Sink	1st Floor	1	EA	7	10+ years	
	WOIR GITIR	131 1001	Į.	LA	,	10+ years	
Classroo	om #127 (Regular Classroom)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,175	SF	7	10+ years	
	Doors - Side-lite	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,175	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	63	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	700	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	20	SF	6	1-2 years	Mortar cracks
	Walls - Plaster/Drywall	1st Floor	530	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #202 (Special Education)						
Classice	Casework	2nd Floor	40	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	640	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	2nd Floor	12	EA	7	10+ years	
	Floor - Tile	2nd Floor	640	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	10+ years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	340	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	40	SF SF	6	,	
	Work Sink	2nd Floor	40	EA	7	10+ years 10+ years	
	WOIR SIIIR	2110 F1001	1	LA	,	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	890	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	490	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	550	SF	6	10+ years	
Classroo	om #206 (Regular Classroom)						
OIGSSIUL	Casework	2nd Floor	50	LF	7	10+ years	
	Casework	ZIIU FIUUI	50	LF	,	IUT YEAIS	



Catego	ry : Classroom		В	Building : Main					
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	2nd Floor	890	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	890	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	10+ years			
	Walls - Concrete Block	2nd Floor	490	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	550	SF	6	10+ years			
_Classroc	om #208 (Regular Classroom)								
	Casework	2nd Floor	5	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	890	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	890	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	•			
	Marker Board	2nd Floor	24	LF		10+ years			
	Walls - Concrete Block	2nd Floor 2nd Floor	490	SF	7	6-10 years			
					6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	550	SF	6	10+ years			
Classroc	om #210 (Regular Classroom)								
	Casework	2nd Floor	50	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	890	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	890	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	10	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	490	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	550	SF	6	10+ years			
Classroc	om #212 (Regular Classroom)								
	Casework	2nd Floor	50	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	890	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	890	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	10	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	490	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	550	SF	6	10+ years			
		Z1101 E10(O)1		· JE	n	IUT VEALS			



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #214 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	1,015	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,015	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	870	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	225	SF	6	10+ years	
`laceroo	m #215 (Science Lab Level 3)						
	Casework	2nd Floor	80	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	795	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	795	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	795	SF	7	10+ years	
	Science Lab Shower	2nd Floor	1			•	
			20	EA SF	7 7	10+ years	Looked and blooked
	Storage/ Closet	2nd Floor		SF SF		10+ years	Locked and blocked
	Walls - Concrete Block	2nd Floor	679		6	10+ years	
	Walls - Metal Panel	2nd Floor	226	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
assroc	m #217 (Regular Classroom)						
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	795	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	795	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	ĒΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	679	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	200	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
laaaus -	TO #202 (Paraller Classes)						
assroc	m #223 (Regular Classroom)	0.151				40	
	Casework	2nd Floor	30	LF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	875	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	875	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	712	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	237	SF	6	10+ years	
Classroc	om #227 (Science Lab Level 3)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,709	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,709	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,709	SF	7	6-10 years	
	Science Lab Shower	2nd Floor	1,700	EA	7	10+ years	
	Storage/ Closet	2nd Floor	198	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	912	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroc	om #302 (Special Education)						
<u> Jidoorot</u>	Casework	3rd Floor	23	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	640	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	640	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	8	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	340	SF	6	10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	3rd Floor	550	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years 10+ years	
Classron	om #304 (Regular Classroom)						
-1400100	Casework	3rd Floor	50	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	890	SF	6		
	Doors - Side-lite	3rd Floor	12	SF SF	7	10+ years	
		3rd Floor	12	EA		10+ years	
	Doors - Wood Doors inclu hw Floor - Tile	3rd Floor 3rd Floor	890	SF	7 6	10+ years	
	FIUUI - LIIE	วเน ฅเบปโ	890	or-	О	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	9	EΑ	7	10+ years	
	Lighting - Lay-in	3rd Floor	3	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	490	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	550	SF	6	10+ years	
Classroc	om #306 (Regular Classroom)						
Olaboloc	Casework	3rd Floor	50	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	890	SF	6	•	
	Doors - Side-lite	3rd Floor	12	SF SF		10+ years	
					7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	890	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	490	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	550	SF	6	10+ years	
Classroc	om #308 (Regular Classroom)						
	Casework	3rd Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	890	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	890	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	490	SF	6	10+ years	
		3rd Floor	550	SF	6		
	Walls - Plaster/Drywall	310 11001	550	SF	б	10+ years	
Classroc	om #310 (Regular Classroom)						
	Casework	3rd Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	890	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	890	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	8	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	4	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	490	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	550	SF	6	10+ years	
Classroo	om #311 (Regular Classroom)						
Cidooioc	Casework	3rd Floor	20	LF	6	10+ years	
	Casework	SIU FIUUI	20		O	TOT years	
	Ceiling - Lay-in	3rd Floor	925	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	925	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	823	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	274	SF	6	10+ years	
Classroo	om #312 (Regular Classroom)						
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	890	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	890	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
		3rd Floor		SF	-		
	Walls - Concrete Block		490	SF SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	550	SF	6	10+ years	
_Classroo	om #313 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	575	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	575	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	7	10+ years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	676	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #314 (Regular Classroom)						
	Casework	3rd Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,040	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	1,040	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EΑ	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	590	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	550	SF	6	10+ years	
Classroo	om #315 (Regular Classroom)						
	, ,						



Catego	ry : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	910	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	910	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	2	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	805	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	268	SF	6	10+ years	
Classroo	om #317 (Regular Classroom)						
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	910	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	910	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	805	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	268	SF	6	10+ years	
Classroo	om #323 (Regular Classroom)						
	Casework	3rd Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	910	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	7		
	Floor - Tile	3rd Floor	910	SF	6	6-10 years	
		3rd Floor		SF EA		10+ years	
	Lighting - Lay-in		10		7	10+ years	
	Lighting - Lay-in	3rd Floor	2	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	805	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	268	SF	6	10+ years	
Classroo	om #326 (Art Room)						
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2,170	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	2,170	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	36	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	479	SF	7	10+ years	
	- 3		•		-	- ,	



Catego	ry : Classroom		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Concrete Block	3rd Floor	2,580	SF	6	10+ years				
	Work Sink	3rd Floor	1	EA	7	10+ years				
Classroo	om #327 (Science Classroom)									
	Ceiling - Lay-in	3rd Floor	1,733	SF	6	10+ years				
	Doors - Side-lite	3rd Floor	24	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	7	10+ years				
	Eye Wash Station	3rd Floor	2	EΑ	7	10+ years				
	Floor - Tile	3rd Floor	1,733	SF	6	10+ years				
	Lighting - Lay-in	3rd Floor	24	EΑ	7	10+ years				
	Marker Board	3rd Floor	24	LF	7	6-10 years				
	Science Lab Elements	3rd Floor	1,733	SF	7	10+ years				
	Storage/ Closet	3rd Floor	218	SF	7	10+ years				
	Walls - Concrete Block	3rd Floor	2,041	SF	6	10+ years				
	Work Sink	3rd Floor	3	EA	7	10+ years				

Category : Interior **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	9,939	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	374	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	25	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Carpet	1st Floor	1,025	SF	6	6-10 years	
	Floor - Terrazzo	1st Floor	9,288	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	123	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	132	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	13,066	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,958	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	384	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	12	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	6	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	4,342	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	96	EA	6	10+ years	
	Student Lockers - One Tier	2nd Floor	138	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	5,864	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	7,803	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	9	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	6	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	7,803	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	107	EA	7	10+ years	

Campus Name: Albany Park Page : 27 of 31 Assessment Date: 05/15/2024



Catego	ry : Interior		В	uilding	: Main		oze w cawyor w zwez, omoage, iz oooze
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Wall Mounted	3rd Floor	5	EA	7	10+ years	
	Student Lockers - One Tier	3rd Floor	161	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	9,192	SF	6	10+ years	
Safety							
Calcry	Camera Viewing Station	1st Floor	4	EA	7	10+ years	
	Metal Detector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	84	EA	7	6-10 years	29 outdoor 55 indoor
Stairs							
Sidilo	Ceiling - Lay-in	Central stair tower	1,082	SF	6	10+ years	
	Floor - Terrazzo	Central stair tower	1,082	SF	6	10+ years	
	Handrails	Central stair tower	68	LF	7	10+ years	
	Lighting - Lay-in	Central stair tower	18	EA	7	6-10 years	Qty updated
	Lighting - Wall Mounted	Central stair tower	5	EA	7	6-10 years	,
	Rescue Panel	Central stair tower	2	EA	7	10+ years	
	Stairs - Terrazzo	Central stair tower	288	LF	6	10+ years	
	Walls - Structural Glazed Tile	Central stair tower	4,853	SF	6	10+ years	
	Ceiling - Lay-in	North stair	902	SF	7	10+ years	
	Floor - Terrazzo	North stair	902	SF	7	10+ years	
	Handrails	North stair	66	LF	7	10+ years	
	Lighting - Lay-in	North stair	6	EA	7	10+ years	
	Lighting - Wall Mounted	North stair	5	EA	7	10+ years	
	Rescue Panel	North stair	2	EA	7	10+ years	
	Stairs - Terrazzo	North stair	288	LF	7	10+ years	
	Walls - Structural Glazed Tile	North stair	4,480	SF	7	10+ years	
	Ceiling - Lay-in	South stair	902	SF	6	10+ years	
	Floor - Terrazzo	South stair	902	SF	6	10+ years	
	Handrails	South stair	66	LF	7	10+ years	
	Lighting - Lay-in	South stair	6	EA	7	10+ years	
	Lighting - Wall Mounted	South stair	4	EA	7	10+ years	Qty adjusted
	Rescue Panel	South stair	2	EA	7	10+ years	
	Stairs - Terrazzo	South stair	288	LF	6	10+ years	
	Walls - Structural Glazed Tile	South stair	4,480	SF	6	10+ years	
Vertical	Conveyance						
verilleal	Elevator - Hydraulic Elevator	North	1	EA	6	10+ years	
			·		-	,	



Category : Site Building : Site

Civil/Draina (((Fencing	tem - Type age Civil/ Drainage - Catch Basin Civil/ Drainage - Site Drain Civil/ Drainage - Site Manhole Fencing - New Standard Ornamental Fencing - New Standard Ornamental	Entire Site Entire Site Entire Site	Quantity 10 1 6	EA EA EA	Rank 7 7	Recommend Replacement	Comments
Civil/Draina (((Eencing	age Civil/ Drainage - Catch Basin Civil/ Drainage - Site Drain Civil/ Drainage - Site Manhole Fencing - New Standard Ornamental	Entire Site Entire Site Entire Site	10	EA EA	7	10+ years	Comments
(((Fencing	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Drain Civil/ Drainage - Site Manhole Fencing - New Standard Ornamental	Entire Site Entire Site	1	EA			
Fencing F	Civil/ Drainage - Site Drain Civil/ Drainage - Site Manhole Fencing - New Standard Ornamental	Entire Site Entire Site	1	EA			
Fencing F	Civil/ Drainage - Site Manhole Fencing - New Standard Ornamental	Entire Site	•		7		
Fencing F	Fencing - New Standard Ornamental		6	ĿΑ		10+ years	
F					7	10+ years	
		F 42 14 B 14 1 4					
F	Fencing - New Standard Ornamental	Entire site, Parking lot	1,023	LF	6	10+ years	
	oneing trem clandard emanionia.	Entire site, Parking lot	12	LF	4	1-2 years	Heavy rust, causing the fence to become loose
F	Fencing - Wood Fencing w/ Steel Frame	Entire site, Parking lot	113	LF	6	6-10 years	
Landscape							
	Benches	Entire Site	3	EA	6	10+ years	
L	_andscape - Hardscape- Concrete	Entire Site	2,475	SF	6	10+ years	
	ighting - Pole Mounted	Entire Site	11	EA	7	10+ years	
	ighting - Pole Mounted	Entire Site	3	EA	7	10+ years	
F	Parkway trees	Entire Site	12	EA	7	10+ years	
	Parkway trees	Entire Site	13	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	4,018	SF	5	10+ years	
7	Trash Receptacles	Entire Site	4	EA	6	6-10 years	
7	Frash Receptacles	Entire Site	1	EA	6	6-10 years	
Parking Lot	t						
(Concrete Curbs	Parking Lot- East	285	LF	6	10+ years	
E	EV Charge Station	Parking Lot- East	1	EA	6	6-10 years	
	nterior Plantings	Parking Lot- East	292	LF	6	6-10 years	Added to match current observations
	ighting - Pole Mounted	Parking Lot- East	4	EA	6	6-10 years	
	Surface - Asphalt	Parking Lot- East	6,296	SF	5	6-10 years	
7	Frash Compactor	Parking Lot- East	1	EΑ	6	6-10 years	
7	Frash Enclosure - Chain Links	Parking Lot- East	128	SF	7	10+ years	
7	Гrash Enclosure - Masonry	Parking Lot- East	764	SF	6	10+ years	
	Trash Enclosure - Masonry	Parking Lot- East	4	SF	5	1-2 years	Cracking
	Vehicular Screening	Parking Lot- East	282	LF	6	10+ years	•
\	Vehicular Screening	Parking Lot- East	10	LF	5	1-2 years	Displaced/bent
Playground	1						
E	Equipment - School Age 5-12	East	1	EA	6	10+ years	
9	Surface - Poured Surface	East	3,020	SF	7	6-10 years	Quantity adjusted
Sidewalks							
5	Sidewalks - Internal Walks	Entire Site	427	LF	7	10+ years	

Campus Name: Albany Park Page : 29 of 31 Assessment Date: 05/15/2024



Catego	Category : Site			uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	9,297	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	24	SF	4	0-1 year	Deteriorating/cracking
_Signage							
0 0	Flag Pole - Flag Pole	West	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter	West	2	EA	7	10+ years	
	Sign						
	Monument - Sign	West	2	EA	7	10+ years	Quantity adjusted

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Albany Park Page: 30 of 31 Assessment Date: 05/15/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classicom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Art Room	1st Floor	115	115(172)	1,175	120	12	Y	N
Art Room	Music Room	3rd Floor	326	323	2,170	500	0	N	N
Fitness Room	Regular Classroom	1st Floor	102	129	890	80	8	Y	N
Kindergarten	Regular Classroom	1st Floor	110	131	1,175	120	12	Y	Υ
Regular Classroom	Computer Lab	2nd Floor	214	219	1,015	80	8	Υ	N
Regular Classroom	Regular Classroom	1st Floor	106	130	1,175	120	12	Υ	N
Regular Classroom	Regular Classroom	1st Floor	123	165	1,175	120	12	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	127	166	1,175	120	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	214	890	80	8	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	215	890	80	8	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	216	890	80	8	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	217	890	80	8	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	218	890	80	8	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	222	795	88	16	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	223	241	875	88	16	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	312	890	80	8	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	306	313	890	80	8	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	308	314	890	80	8	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	310	315	890	80	8	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	311	302	925	234	0	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	316	890	80	8	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	313	301	575	204	0	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	314	317	1,040	80	8	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	315	NA	910	88	16	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	317	NA	910	88	16	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	323	NA	910	88	16	Υ	Υ
Science Classroom	Science Lab Level 3	3rd Floor	327	NA	1,733	44	8	N	Υ
Science Lab Level 3	Science Lab Level 3	2nd Floor	215	221	795	88	16	Υ	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	227	238	1,709	44	8	Υ	N
Special Education	Regular Classroom	2nd Floor	202	213	640	60	6	Υ	Υ
Special Education	Regular Classroom	3rd Floor	302	311	640	60	6	Υ	N