

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1893	3	117,104
Campus Total			117,104

Category : Exterior Building : Main

Calego	IY. EXICITOR		<u> </u>	unung	. IVIAIII		
Croun	Itom Type	Location	Quantitu	HOM	Donk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio	Entrance 1 W	1	EA	4	0-1 year	Missing unit
	Exterior Doors - Exterior FRP Door	Entrance 1 W	2	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 1 W	2	EA	6	10+ years	
	Exterior Stairs - Stone	Entrance 1 W	8	LF	5	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 10 W	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 10 W	4	EA	6	10+ years	
	Exterior Stairs - Stone	Entrance 10 W	10	LF	6	10+ years	
	Entrance Control - Audio and Video	Entrance 2 W	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 2 W	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 2 W	4	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 3 S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 3 S	4	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 4 S	3	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 5 SE	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 6 E	1	EA	5	6-10 years	
	Exterior Doors - Transom Lite	Entrance 6 E	1	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 6.5 E	1	EA	5	6-10 years	
	Entrance Control - Audio	Entrance 7 E	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 7 E	1	EA	5	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 7 E	1	EA	5	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 8 N	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 8 N	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 8 N	1	EA	5	10+ years	Repaired
	Exterior Doors - Exterior FRP Door	Entrance 9 W	3	EA	6	10+ years	•



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	Entrance 9 W	4	EA	6	10+ years	
	Exterior Stairs - Stone	Entrance 9 W	10	LF	5	6-10 years	
Fire Esc	ape						
	Exterior Doors - Exterior Steel Door	East Façade	2	EA	6	2-5 years	
	Fire Escape	East Façade	118	LF	6	10+ years	
	Paints	East Façade	118	LF	5	2-5 years	
oundat	ion						
oundat	Foundation - Masonry	Entire Building	982	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	43,904	SF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	73,200	SF	7	10+ years	
	Superstructure - Steel with Glay The Arch	Littile Building	73,200	OI.	,	10+ years	
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	6-10 years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	5	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	21	EA	6	6-10 years	
Roof Sys	stem						
•	Access Ladder - Metal	Roof 1	1	EA	7	6-10 years	
	Access Ladder - Wood	Roof 1	1	EA	3	0-1 year	Ladder-only access to attic - wood ladder poorly attached/designed. Rungs to close to wall.
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1	1	LF	5	2-5 years	J
	Coping - Clay Tile	Roof 1	76	LF	5	10+ years	
	Coping - Stone	Roof 1	290	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 1	232	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 1	290	LF	6	6-10 years	
	Roof - Modified Bitumen	Roof 1	6,965	SF	5	2-5 years	
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	6,965	SF	7	10+ years	
	Coping - Stone	Roof 10	22	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 10	15	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 10	22	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 10	90	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 10	90	SF	7	•	
	Chimney - Metal Flue	Roof 11	4	SF LF	6	10+ years 6-10 years	
			44	LF LF	_	•	
	Coping - Stone	Roof 11			6	6-10 years	
	Downspouts - Exterior Downspouts	Roof 11	15	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 11	10	LF	6	2-5 years	
	Parapet - Parapet > 30"	Roof 11	34	LF	5	6-10 years	
	Roof - Metal	Roof 11	170	SF	6	10+ years	



Catego	Category : Exterior		В	uilding			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Steel / Metal Deck/	Roof 11	170	SF	7	10+ years	
	Concrete Topping						
	Coping - Stone	Roof 12	25	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 12	15	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 12	25	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 12	75	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 12	75	SF	7	10+ years	
	Coping - Stone	Roof 13	12	LF	6	2-5 years	
	Parapet - Parapet < 16" Height	Roof 13	15	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 13	40	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 13	240	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 13	240	SF	7	10+ years	
	Coping - Stone	Roof 14	24	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 14	15	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 14	24	LF	5	6-10 years	
	Roof - Metal	Roof 14	72	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 14	72	SF	7	2-5 years	
	Coping - Stone	Roof 15	22	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 15	15	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 15	22	LF	5	6-10 years	
	Roof - Modified Bitumen	Roof 15	124	SF	5	2-5 years	
	Roof Structure - Heavy Timber	Roof 15	124	SF	7	10+ years	
	Coping - Metal	Roof 2	34	LF	5	6-10 years	
	Downspouts - Interior Downspouts	Roof 2	58	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 2	34	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	2,350	SF	5	2-5 years	
	Roof Structure - Heavy Timber	Roof 2	2,350	SF	7	10+ years	
	Coping - Metal	Roof 3	300	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	36	LF	6	10+ years	
	Roof - Asphalt Shingle	Roof 3	6,064	SF	5	2-5 years	
	Roof - Metal	Roof 3	50	SF	5	2-5 years	
	Roof Structure - Heavy Timber	Roof 3	6,064	SF	7	10+ years	
	Coping - Metal	Roof 4	34	LF	5	2-5 years	
	Downspouts - Interior Downspouts	Roof 4	58	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof 4	45	LF	6	6-10 years	
	Roof - Modified Bitumen	Roof 4	2,350	SF	5	2-5 years	
	Roof Structure - Heavy Timber	Roof 4	2,350	SF	7	10+ years	
	Coping - Clay Tile	Roof 5	160	LF	5	6-10 years	
	Coping - Stone	Roof 5	175	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Roof 5	15	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 5	6	LF	5	2-5 years	
	Parapet - 16" - 30" Height	Roof 5	160	LF	6	2-5 years	
	Parapet - Parapet < 16" Height	Roof 5	175	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 5	5,400	SF	5	2-5 years	
			2, 100		-	- ,	



Catego	ry : Exterior		D	uilding	· Main	21	23 N Fairfield AVENUE, Chicago, IE 00047
Calego	Ty . Exterior		O Company	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Roof Structure - Steel / Metal Deck/	Roof 5	5,400	SF	7	10+ years	Commonto
	Concrete Topping	. 135. 5	0, .00	٠.	-	,	
	Coping - Stone	Roof 6	62	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Roof 6	6	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 6	62	LF	6	6-10 years	
	Roof - Modified Bitumen	Roof 6	940	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 6	940	SF	7	10+ years	
	Access Ladder - Metal	Roof 7	1	ĒΑ	7	10+ years	
	Coping - Stone	Roof 7	154	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 7	100	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 7	154	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 7	3,935	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 7	3,935	SF	7	10+ years	
	Coping - Clay Tile	Roof 8a	102	LF	5	6-10 years	
	Downspouts - Exterior Downspouts	Roof 8a	15	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 8a	12	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 8a	80	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 8a	795	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 8a	795	SF	6	10+ years	
	Chimney - Brick Chimney- Stainless Steel	Roof 8b	58	LF	6	6-10 years	
	Liner					-	
	Coping - Clay Tile	Roof 8b	180	LF	5	6-10 years	
	Downspouts - Exterior Downspouts	Roof 8b	15	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 8b	12	LF	6	2-5 years	
	Parapet - Parapet < 16" Height	Roof 8b	180	LF	6	6-10 years	
	Roof - Metal	Roof 8b	160	SF	6	10+ years	
	Roof - Modified Bitumen	Roof 8b	3,360	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 8b	3,520	SF	7	10+ years	
	Coping - Clay Tile	Roof 8c	58	LF	5	6-10 years	
	Coping - Metal	Roof 8c	36	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 8c	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 8c	18	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 8c	46	LF	6	10+ years	
	Roof - Metal	Roof 8c	32	SF	6	10+ years	
	Roof - Modified Bitumen	Roof 8c	1,157	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 8c	1,157	SF	7	10+ years	
	Coping - Stone	Roof 9	32	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 9	15	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 9	32	LF	5	6-10 years	
	Roof - Modified Bitumen	Roof 9	124	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 9	124	SF	7	10+ years	
Malla							
_Walls	Cornice - Cast Stone	Entire Building	897	LF	7	10+ years	
	Confide - Cast Stone	Little building	097	LI	,	10+ years	

Campus Name: Brentano Page : 4 of 37 Assessment Date: 11/28/2023



Category: Exterior

Exit Signs - Lunchroom

Security System - CCTV

Emergency A/C Power - Gym

Aisle Lighting

Stairs

Emergency Battery Packs - Auditoium and

Emergency Battery Packs - Students Toilets

Security System - Intrusion Detection

Emergency A/C Power - Corridors and

Lorenz Brentano Math & Science Academy ES

Building: Main

2723 N Fairfield AVENUE, Chicago, IL 60647

Calego	IY. LAICHOI		<u>_</u>	ununig	. IVIAIII		
	-	1	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	50	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	51,918	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	500	SF	5	2-5 years	
	Exterior Walls - Brick	Entire Building	540	SF	5	2-5 years	
	Exterior Walls - Stone-Cast	Entire Building	4,896	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	20	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	3	SF	4	1-2 years	Broken/Cracked
	Exterior Walls - Stone-Cut	Entire Building	210	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	4,548	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	5	SF	5	2-5 years	
	Exterior Walls - Terra Cotta	Entire Building	28	SF	6	10+ years	
Vindows	3						
	Guard - Guards perforated	Entire Building	1,806	SF	6	6-10 years	
	Lintels - Brick	Entire Building	492	LF	6	10+ years	
	Lintels - Steel	Entire Building	6	LF	4	1-2 years	
	Lintels - Stone	Entire Building	804	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	115	SF	5	2-5 years	
	Skylite - Glass Single-Pane	Entire Building	100	SF	5	2-5 years	
	Windows - Decorative	Entire Building	280	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	2,352	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,676	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,950	SF	5	6-10 years	
atego	ry : Electrical		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	2-5 years	
	Exit Signs - Auditoium	Entire Building	6	EA	4	2-5 years	Over 20 years old with incandescer bulbs
	Exit Signs - Corridors and Stairs	Entire Building	38	EA	4	2-5 years	Over 20 years old with incandescer bulbs
	Exit Signs - Gym	Entire Building	3	EA	4	2-5 years	Over 20 years old with incandescer bulbs
			_		_		Daibo

2

5

2

117,104

117,104

14,778

4,371

EΑ

EΑ

EA SF

SF

SF

SF

6

6

7

5

6

6

6

6-10 years

6-10 years

10+ years

6-10 years

6-10 years

6-10 years

6-10 years

Entire Building

Entire Building

Entire Building

Entire Building

Entire Building

Entire Building

Entire Building



	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Lunchrooms	Entire Building	1,784	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	2-5 years	
	PA System	Entire Building	117,104	SF	5	6-10 years	
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	2-5 years	For fire
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	15	EΑ	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	3	0-1 year	Corroded due to being rained or
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
						•	
	m						
•		Entire Buildina	1	EA	3	1-2 years	Obsolete parts
	m Fire Alarm Panel Fire Alarm_System	Entire Building Entire Building	1 117,104	EA SF	3 4	1-2 years 0-1 year	Obsolete parts Dated system and devices, no
	Fire Alarm Panel						
Fire Alar	Fire Alarm Panel Fire Alarm_System	Entire Building	117,104	SF	4	0-1 year	Dated system and devices, no
Fire Alar	Fire Alarm Panel Fire Alarm_System Fire Pump Controller	Entire Building	117,104	SF	4	0-1 year	Dated system and devices, no
Fire Alar	Fire Alarm Panel Fire Alarm_System Fire Pump Controller oom Assembly	Entire Building Entire Building	117,104	SF EA	6	0-1 year 6-10 years	Dated system and devices, no
Fire Alar	Fire Alarm Panel Fire Alarm_System Fire Pump Controller oom Assembly Fire Pump - 25-50 hp r System	Entire Building Entire Building Mechanical Room	117,104	SF EA EA	6	0-1 year 6-10 years 6-10 years	Dated system and devices, no
Fire Alar	Fire Alarm Panel Fire Alarm_System Fire Pump Controller oom Assembly Fire Pump - 25-50 hp	Entire Building Entire Building	117,104	SF EA	6	0-1 year 6-10 years	Dated system and devices, no



Catego	ry : Mechanical		В	uilding	: Main		
0	Mana Tuma	Lassian	Output!ter	HOM	Doub	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	0						
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years	Not found
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Center Basement - AHU3	1	EA	5	2-5 years	Old motor, chipping paint, coils damaged
	Air Intake	Center Basement - AHU3	1	EΑ	5	6-10 years	-
	Auxiliaries - 8001 - 15000 cfm	Center Basement - AHU3	1	EΑ	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Center Basement - AHU3	100	LF	4	2-5 years	No return fan installed, fresh air intake on roof
	Zone Dampers	Center Basement - AHU3	12	EA	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Center Basement - AHU4	1	EA	5	2-5 years	Old motor, chipping paint, coils damaged
	Air Intake	Center Basement - AHU4	1	EA	5	6-10 years	Serves AHU 3&4
	Auxiliaries - 8001 - 15000 cfm	Center Basement - AHU4	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Center Basement - AHU4	100	LF	4	2-5 years	No return fan installed, fresh air intake on roof
	Zone Dampers	Center Basement - AHU4	12	EA	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	East Basement - AHU1	1	EA	5	2-5 years	Belts vibrating, deteriorating walls, ol motor
	Air Intake	East Basement - AHU1	1	EA	5	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	East Basement - AHU1	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	East Basement - AHU1	100	LF	4	2-5 years	No return fan installed, fresh air intake on roof
	Zone Dampers	East Basement - AHU1	2	EA	5	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	5	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	5	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	5	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	5	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	5	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EΑ	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	North Basement - AHU2	1	EA	5	2-5 years	Old motor, bypass damper corroded
	Air Intake	North Basement - AHU2	1	EΑ	6	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	North Basement - AHU2	1	EΑ	5	6-10 years	Plenum door screwed shut
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	North Basement - AHU2	100	LF	5	6-10 years	

Campus Name: Brentano Page : 7 of 37 Assessment Date: 11/28/2023



Catego	ry : Mechanical		В	uilding	: Main		•
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Zone Dampers	North Basement - AHU2	24	EΑ	5	6-10 years	
	·					•	
Boiler S	ystems						
	Boiler Auxiliary- Scotch Marine- Steam Low	Entire Building	2	EA	5	6-10 years	
	Pressure Boiler - 201 - 300 HP	•				·	
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	
	Combustion Dampers	Entire Building	2	EA	6	6-10 years	
	Condensate Pump	Entire Building	1	EA	5	2-5 years	
	Condensate Pump	Entire Building	1	EA	5	2-5 years	
	Feed Water Pumps and Tank	Entire Building	1	EA	5	2-5 years	
	Feed Water Pumps and Tank	Entire Building	1	EA	5	2-5 years	
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	6-10 years	
	Steam- Low Pressure Boiler - 201 - 300 HP	-				-	
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	6-10 years	
	Steam- Low Pressure Boiler - 201 - 300 HP						
	Piping - Condensate Pipe- Steel	Entire Building	400	LF	5	2-5 years	
	Piping - Steam Pipe- Steel	Entire Building	400	LF	5	2-5 years	
	Steam Traps	Entire Building	60	EA	5	6-10 years	
	Vacuum Pump	Entire Building	2	EA	5	1-2 years	Tank leaking
_Heating							
	Fin Tube - Steam	1st Floor	20	LF	5	6-10 years	
	Radiators - Steam	Entire Building	8	EA	5	6-10 years	
	Unit Heater - Electric	Entire Building	9	EA	5	2-5 years	
	Unit Heater - Steam	Entire Building	1	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	7	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	5	2-5 years	
_Tempera	ature Control						
	Electric Thermostat	Entire Building	8	EA	5	6-10 years	For FCUs
	Electric Thermostat	Entire Building	1	EA	4	1-2 years	Not fully operational, for unit heaters
	Pneumatic System	Entire Building	117,104	SF	4	1-2 years	Compressor constantly running
	Thermostats - Pneumatic	Entire Building	54	EA	5	2-5 years	
<u>Ventilati</u>							
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	7	10+ years	New
	CFM						
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	6	6-10 years	
	500 CFM						



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR	Auditorium Restrooms Boiler Room	2 2	EA EA	6 6	6-10 years 6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	117,104	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	117,104	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	117,104	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	117,104	SF	6	6-10 years	Recently renovated
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	117,104	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	117,104	SF	6	6-10 years	
	Sanitary Piping	Entire Building	117,104	SF	5	6-10 years	
	Storm Piping	Entire Building	117,104	SF	5	6-10 years	
	Vent Piping	Entire Building	117,104	SF	5	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	6	6-10 years	

Category : Room **Building: Main**

	. ,			۳ه			
iroup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices					•	
	AC Unit	007 Basement - Engineer's work shop	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	007 Basement - Engineer's work shop	503	SF	7	10+ years	
	Doors - Wood Doors inclu hw	007 Basement - Engineer's work shop	1	EA	7	10+ years	
	Floor - Concrete	007 Basement - Engineer's work shop	503	SF	7	10+ years	
	Lighting - Pendent/Surface	007 Basement - Engineer's work shop	9	EA	7	6-10 years	
	Power Distribution	007 Basement - Engineer's work shop	8	EA	7	10+ years	
	Walls - Masonry	007 Basement - Engineer's work shop	499	SF	7	10+ years	
	Walls - Plaster/Drywall	007 Basement - Engineer's work shop	500	SF	7	10+ years	
	AC Unit	1st - Asst Principal 112	1	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st - Asst Principal 112	237	SF	7	10+ years	
	Doors - Transom Window	1st - Asst Principal 112	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - Asst Principal 112	1	EA	7	10+ years	
	Floor - Wood	1st - Asst Principal 112	237	SF	7	10+ years	
	Lighting - Pendent/Surface	1st - Asst Principal 112	3	EA	7	6-10 years	
	Power Distribution	1st - Asst Principal 112	8	EA	7	10+ years	
	Storage/ Closet	1st - Asst Principal 112	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - Asst Principal 112	823	SF	7	10+ years	
	AC Unit	1st - Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Main Office	489	SF	7	10+ years	
	Doors - Side-lite	1st - Main Office	40	SF	7	10+ years	
	Doors - Transom Window	1st - Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - Main Office	1	EA	7	10+ years	
	Floor - Wood	1st - Main Office	489	SF	7	10+ years	
	Lighting - Pendent/Surface	1st - Main Office	7	EA	7	6-10 years	
	Power Distribution	1st - Main Office	14	EA	7	10+ years	
	Storage/ Closet	1st - Main Office	108	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - Main Office	1,350	SF	7	10+ years	
	AC Unit	1st - Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Principal's Office	467	SF	7	10+ years	
	Doors - Transom Window	1st - Principal's Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - Principal's Office	2	EA	7	10+ years	
	Floor - Wood	1st - Principal's Office	467	SF	7	10+ years	
	Lighting - Pendent/Surface	1st - Principal's Office	6	EA	7	6-10 years	
	Power Distribution	1st - Principal's Office	8	EA	7	10+ years	
	Storage/ Closet	1st - Principal's Office	24	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - Principal's Office	1,195	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor - 108 teachers' lounge	413	SF	7	10+ years	
	Doors - Side-lite	1st floor - 108 teachers' lounge	84	SF	7	10+ years	
	Doors - Transom Window	1st floor - 108 teachers' lounge	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor - 108 teachers' lounge	1	EA	7	10+ years	
	Floor - Wood	1st floor - 108 teachers' lounge	413	SF	7	10+ years	
	Lighting - Pendent/Surface	1st floor - 108 teachers' lounge	11	EA	7	6-10 years	
	Power Distribution	1st floor - 108 teachers' lounge	18	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor - 108 teachers' lounge	1,432	SF	7	10+ years	
	Work SInk	1st floor - 108 teachers' lounge	1	EA	7	10+ years	
	AC Unit	1st floor - Assistant Principal's Office	1	EA	7	6-10 years	
		in Main Office					
	Ceiling - Plaster/Drywall	1st floor - Assistant Principal's Office	297	SF	7	10+ years	
		in Main Office					
	Doors - Transom Window	1st floor - Assistant Principal's Office	9	SF	7	10+ years	
		in Main Office					
	Doors - Wood Doors inclu hw	1st floor - Assistant Principal's Office	1	EA	7	10+ years	
		in Main Office					



Category : Room		Building : Main			n		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st floor - Assistant Principal's Office in Main Office	297	SF	7	10+ years	
	Lighting - Pendent/Surface	1st floor - Assistant Principal's Office in Main Office	6	EA	7	6-10 years	
	Power Distribution	1st floor - Assistant Principal's Office in Main Office	16	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor - Assistant Principal's Office in Main Office	1,167	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - 208 used as teachers' lounge	413	SF	7	10+ years	
	Doors - Side-lite	2nd Floor - 208 used as teachers' lounge	84	SF	7	10+ years	
	Doors - Transom Window	2nd Floor - 208 used as teachers' lounge	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - 208 used as teachers' lounge	1	EA	7	10+ years	
	Floor - Tile	2nd Floor - 208 used as teachers' lounge	413	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - 208 used as teachers' lounge	11	EA	7	6-10 years	
	Storage/ Closet	2nd Floor - 208 used as teachers' lounge	312	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - 208 used as teachers' lounge	385	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - 208 used as teachers' lounge	1,432	SF	7	10+ years	
	AC Unit	2nd Floor - 209 Adjustment Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - 209 Adjustment Office	742	SF	7	10+ years	
	Doors - Side-lite	2nd Floor - 209 Adjustment Office	108	SF	7	10+ years	
	Doors - Transom Window	2nd Floor - 209 Adjustment Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - 209 Adjustment Office	1	EA	7	10+ years	
	Floor - Tile	2nd Floor - 209 Adjustment Office	742	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - 209 Adjustment Office	9	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - 209 Adjustment Office	1	EA	6	6-10 years	Relamp
	Power Distribution	2nd Floor - 209 Adjustment Office	18	EA	7	10+ years	•
	Walls - Plaster/Drywall	2nd Floor - 209 Adjustment Office	1,497	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor - 312 Mother's Room	338	SF	7	10+ years	
	Doors - Transom Window	3rd Floor - 312 Mother's Room	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - 312 Mother's Room	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor - 312 Mother's Room	338	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor - 312 Mother's Room	6	EA	7	6-10 years	
	Power Distribution	3rd Floor - 312 Mother's Room	18	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - 312 Mother's Room	1,156	SF	7	10+ years	
	Work Sink	3rd Floor - 312 Mother's Room	1,100	EA	7	10+ years	
	TOTAL ON INC.	ord ricor or 2 modifier of Nooni		_/ \	,	ioi youis	



Catego	ry : Room		R	uilding	: Main	<u></u> :	25 W Fairfield AVENUE, Officago, IE 00047
Outego	y : Noom			ananig	. wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
C. Cup	AC Unit	Basement- Engineer's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement- Engineer's Office	207	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement- Engineer's Office	1	EA	7	10+ years	
	Floor - Concrete	Basement- Engineer's Office	207	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement- Engineer's Office	3	EA	7	6-10 years	
	Power Distribution	Basement- Engineer's Office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement- Engineer's Office	599	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Custodial break room 003	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Custodial break room 003	1	EA	7		
	Floor - Concrete Epoxy/ Painted			SF	7	10+ years	
		Custodial break room 003	300			10+ years	
	Lighting - Pendent/Surface	Custodial break room 003	6	EΑ	7	6-10 years	
	Power Distribution	Custodial break room 003	6	EA	7	10+ years	
	Walls - Masonry	Custodial break room 003	700	SF	7	10+ years	
	Work SInk	Custodial break room 003	1	EA	7	10+ years	
_Auditoriu	m & Theater						
	Balcony Seating	Basement	129	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	5,627	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Concrete	Basement	141	SF	7	10+ years	
	Floor - Wood	Basement	5,486	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	Basement	. 6	EA	7	6-10 years	
	Lighting - Chandelier, Incandescent	Basement	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement	7	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement	8	EΑ	7	6-10 years	
	Main Floor Seating	Basement	518	EA	7	10+ years	
	Sound System	Basement	1	EΑ	7	6-10 years	
	Stage	Basement	1,106	SF	7	10+ years	
	Stage Curtain	Basement	6	EA	7	10+ years	
	Stage Lighting System	Basement	1	EA	7	6-10 years	
	Stage-Stairs - Wood	Basement	16	LF	7	10+ years	
	Stairs - Asphalt	Basement	30	LF	7	10+ years	
	Storage/ Closet	Basement	8	SF	7	10+ years	
	Walls - Masonry		2,344	SF	7		
		Basement		SF SF		10+ years	
	Walls - Plaster/Drywall	Basement	4,688	SF	7	10+ years	
_Gymnasi							
	Ceiling - Plaster/Drywall	2nd Floor	4,371	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	7	10+ years	
	Floor - Wood	2nd Floor	4,371	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure	2nd Floor	18	ĒΑ	7	6-10 years	
	Sodium					,	
	Scoreboards	2nd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,686	SF	7	10+ years	
	,		1,230	=	-	- ,	



Catego	ory : Room		В	uilding	: Main		25 W Fairnerd AVENUE, Officago, IE 00047
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Walls - Plaster/Drywall	2nd Floor	1,330	SF	7	10+ years	
Locker/S	Shower Room						
	AC Unit	Next to 004 (now used as office)	1	EA	7	6-10 years	
	Accessories	Next to 004 (now used as office)	75	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Next to 004 (now used as office)	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Next to 004 (now used as office)	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	Next to 004 (now used as office)	150	SF	7	10+ years	
	Floor Drain	Next to 004 (now used as office)	1	EA	7	10+ years	
	Lavatory	Next to 004 (now used as office)	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Next to 004 (now used as office)	2	EA	7	10+ years	
	Partitions	Next to 004 (now used as office)	2	EA	7	10+ years	
	Showers	Next to 004 (now used as office)	1	EA	4	1-2 years	No fixtures present
	Walls - Plaster/Drywall	Next to 004 (now used as office)	500	SF	7	10+ years	·
	Water Closet	Next to 004 (now used as office)	1	EA	7	10+ years	
Lunch &	Multipurpose Room						
<u> Lanon a</u>	Ceiling - Splined	Basement	1,784	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Basement	1,704	EA	7	10+ years	
	Floor - Tile	Basement	1,774	SF	7	10+ years	
	Floor - Tile	Basement	1,774	SF	5	1-2 years	Broken and worn tiles
	Lighting - Pendent/Surface	Basement	25	EA	7	6-10 years	Broken and worn tiles
	Serving Line	Basement	25 25	LF	7	10+ years	
	Walls - Masonry	Basement	1,794	SF	7	10+ years	
	a.easey	2400	.,. •	О.	·	.e. yeare	
_MDF_ID							
	Doors - Transom Window	2nd floor - 212 MDF	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor - 212 MDF	1	EA	7	10+ years	
	Finishes	2nd floor - 212 MDF	1,196	SF	7	10+ years	
	Other Cooling Unit	2nd floor - 212 MDF	1	EA	7	6-10 years	
	Window AC Unit	2nd floor - 212 MDF	1	EA	7	6-10 years	
_Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	35	SF	7	10+ years	
	Storage Room	1st Floor	86	SF	7	10+ years	
	Janitor's Closet	2nd Floor	27	SF	7	10+ years	
	Janitor's Closet	2nd Floor	8	SF	7	10+ years	
	Storage Room	2nd Floor	86	SF	7	10+ years	
	Janitor's Closet	3rd Floor	35	SF	7	10+ years	
	Janitor's Closet	3rd Floor	35	SF	5	10+ years	
	Storage Room	3rd Floor	86	SF	7	10+ years	
	Air Tunnel	Basement	286	SF	7	10+ years	
	Boiler Room	Basement	1,668	SF	7	10+ years	
	- 2		.,550	٥.	•	121 / 500.0	

Campus Name: Brentano Page : 13 of 37 Assessment Date: 11/28/2023



Catego	Category : Room		В	uilding	: Main	21	723 N Faimeld AVENUE, Chicago, IL 60047
2 2 50			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coal Room	Basement	497	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	913	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	196	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,404	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	102	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	957	SF	7	10+ years	
	Storage Room	Basement	450	SF	7	10+ years	
	Storage Room	Basement	207	SF	7	10+ years	
	Storage Room	Basement	980	SF	7	10+ years	
	Storage Room	Basement	82	SF	7	10+ years	
	Storage Room	Basement	711	SF	7	10+ years	
	Storage Room	Basement	94	SF	7	10+ years	
	Storage Room	Basement	165	SF	5	1-2 years	Hole in ceiling next to pump room
	Clorage Room	Basement	100	O.	J	1 Z years	Tible in beining flext to pump foom
Prep Ro							
	Ceiling - Plaster/Drywall	Basement - Backstage	144	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Backstage	561	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Backstage	35	SF	4	0-1 year	Plaster missing and chipping
	Doors - Wood Doors inclu hw	Basement - Backstage	1	EA	7	10+ years	
	Floor - Concrete	Basement - Backstage	740	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - Backstage	3	EA	7	6-10 years	
	Walls - Masonry	Basement - Backstage	521	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement - Backstage	940	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Caring room (by door 1)	285	SF	7	10+ years	
	Floor - Tile	Basement - Caring room (by door 1)	285	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - Caring room (by door 1)	4	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	Basement - Caring room (by door 1)	25	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - Caring room (by door 1)	658	SF	7	10+ years	
Restroor	n						
	Accessories	017	54	SF	7	6-10 years	
	Ceiling - Lay-in	017	54	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	017	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	017	54	SF	7	10+ years	
	Floor Drain	017	1	EA	7	10+ years	
	Hand Dryer	017	1	EA	7	6-10 years	
	Lavatory	017	1	EA	7	10+ years	
	Lighting - Lay-in	017	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	017	60	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	017	240	SF	7	10+ years	
	Water Closet	017	1	EA	7	10+ years	
	Accessories	1st - Inside 117	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Inside 117	23	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st - Inside 117	20	SF	4	0-1 year	Cracking plaster, looks like it is about
	Coming - Flaster/Drywall	ist - moide i i <i>l</i>	20	OI.	7	0-i yeai	Ordening plaster, looks like it is about



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
					_		to fall
	Doors - Steel Doors incl hw	1st - Inside 117	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - Inside 117	43	SF	7	10+ years	
	Lavatory	1st - Inside 117	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st - Inside 117	1	EA	7	6-10 years	
	Partitions	1st - Inside 117	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st - Inside 117	210	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - Inside 117	50	SF	5	0-1 year	Large crack and cracking plaster
	Water Closet	1st - Inside 117	1	EA	7	10+ years	
	Accessories	1st - Main Office	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - Main Office	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - Main Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - Main Office	45	SF	7	10+ years	
	Lavatory	1st - Main Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st - Main Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st - Main Office	256	SF	7	10+ years	
	Water Closet	1st - Main Office	1	EA	7	10+ years	
	Accessories	1st Floor	527	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	527	SF	7	10+ years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	527	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,213	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	383	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	383	SF	7	10+ years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	383	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	7	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	194	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	594	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	348	SF	7	10+ years	
						•	



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor	7	EA	7	10+ years	
	Accessories	1st floor inside 108 teachers lounge	77	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside 108 teachers lounge	77	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside 108 teachers lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside 108 teachers lounge	77	SF	7	10+ years	
	Hand Dryer	1st floor inside 108 teachers lounge	1	EA	7	6-10 years	
	Lavatory	1st floor inside 108 teachers lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor inside 108 teachers lounge	1	EA	7	6-10 years	
	Partitions	1st floor inside 108 teachers lounge	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor inside 108 teachers lounge	5	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor inside 108 teachers lounge	345	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor inside 108 teachers lounge	121	SF	7	10+ years	
	Water Closet	1st floor inside 108 teachers lounge	2	EA	7	10+ years	
	Accessories	2nd Floor	383	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	383	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	383	SF	7	10+ years	
	Floor Drain	2nd Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	8	EΑ	7	10+ years	
	Walls - Concrete Block	2nd Floor	194	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	594	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	348	SF	7	10+ years	
	Water Closet	2nd Floor	8	EA	7	10+ years	
	Accessories	2nd Floor	527	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	527	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor	500	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	27	SF	5	1-2 years	Cracking
	Floor Drain	2nd Floor	1	EA	7	10+ years	Cracking
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	<u>•</u>	2nd Floor	3	EA	7	10+ years	
	Lavatory Lighting - Pendent/Surface		3 7	EA	7	-	
	•	2nd Floor		EA		6-10 years	
	Partitions	2nd Floor	2		7	10+ years	
	Urinals	2nd Floor	6	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,213	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd floor inside 208	77	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor inside 208	72	SF	7	10+ years	





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd floor inside 208	5	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor inside 208	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor inside 208	77	SF	7	10+ years	
	Lavatory	2nd floor inside 208	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor inside 208	1	EA	7	6-10 years	
	Partitions	2nd floor inside 208	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor inside 208	345	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd floor inside 208	6	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd floor inside 208	121	SF	7	10+ years	
	Water Closet	2nd floor inside 208	2	EA	7	10+ years	
	Accessories	3rd Floor	383	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	383	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	383	SF	7	10+ years	
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	5	EΑ	7	6-10 years	
	Partitions	3rd Floor	8	EΑ	7	10+ years	
	Walls - Concrete Block	3rd Floor	194	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	594	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	348	SF	7	10+ years	
	Water Closet	3rd Floor	8	EA	7	10+ years	
	Accessories	3rd Floor	527	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	527 527	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	13	EA	6	10+ years	
	Floor - Terrazzo	3rd Floor	482	SF	7	•	
	Floor - Terrazzo	3rd Floor	462 50	SF	5	10+ years	Cracking
	Floor Drain	3rd Floor	1	EA	7	1-2 years	Cracking
	Hand Dryer	3rd Floor	1	EA	7	10+ years 6-10 years	
		3rd Floor	3	EA	7	-	
	Lavatory			EA		10+ years	
	Lighting - Pendent/Surface	3rd Floor	7		7	6-10 years	
	Partitions	3rd Floor	2	EΑ	7	6-10 years	
	Urinals	3rd Floor	6	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,213	SF	7	10+ years	
	Water Closet	3rd Floor	2	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Boiler Room	62	SF	7	10+ years	D 1000
	Doors - Wood Doors inclu hw	Basement - Boiler Room	1	EA	4	1-2 years	Door is splitting
	Floor - Concrete	Basement - Boiler Room	62	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement - Boiler Room	1	EA	7	6-10 years	
	Walls - Masonry	Basement - Boiler Room	120	SF	6	6-10 years	



Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Walls - Plaster/Drywall Basement - Boiler Room 180 SF 10+ vears 7 EΑ 7 Water Closet Basement - Boiler Room 1 10+ years Ceiling - Plaster/Drywall Basement - Engineer's Office 92 SF 7 10+ years Doors - Wood Doors inclu hw Basement - Engineer's Office EΑ 1 6 6-10 years SF 7 Floor - Tile Ceramic/ Porcelain Basement - Engineer's Office 92 10+ years Basement - Engineer's Office EΑ 7 Lavatory 1 10+ years Lighting - Pendent/Surface Basement - Engineer's Office EΑ 7 6-10 years 1 Walls - Plaster/Drywall SF Basement - Engineer's Office 375 7 10+ years Water Closet Basement - Engineer's Office 1 EΑ 7 10+ years SF Accessories Basement - Men's - Auditorium 74 7 6-10 years SF Ceiling - Plaster/Drywall Basement - Men's - Auditorium 74 7 10+ vears Doors - Wood Doors inclu hw Basement - Men's - Auditorium 1 EΑ 7 10+ years Floor - Concrete 74 SF 7 Basement - Men's - Auditorium 10+ years 7 Lavatory Basement - Men's - Auditorium 1 EΑ 10+ years Lighting - Pendent/Surface 7 Basement - Men's - Auditorium 1 EΑ 6-10 years FΑ 7 Urinals Basement - Men's - Auditorium 1 10+ years 297 SF 7 Walls - Plaster/Drywall Basement - Men's - Auditorium 10+ years Water Closet Basement - Men's - Auditorium 1 EΑ 7 10+ years SF Basement - Women's - Auditorium 74 7 6-10 years Accessories SF Ceiling - Plaster/Drywall Basement - Women's - Auditorium 74 7 10+ years Doors - Wood Doors inclu hw Basement - Women's - Auditorium 1 EΑ 7 10+ years Basement - Women's - Auditorium SF 7 Floor - Concrete 74 10+ years EΑ 7 Lavatory Basement - Women's - Auditorium 1 10+ years 7 Lighting - Pendent/Surface Basement - Women's - Auditorium 1 FΑ 6-10 years EΑ 7 **Partitions** Basement - Women's - Auditorium 1 10+ years SF Walls - Plaster/Drywall Basement - Women's - Auditorium 297 7 10+ years Water Closet Basement - Women's - Auditorium EΑ 7 10+ years 1 180 SF 7 6-10 years Accessories Opposite lunchroom Ceiling - Plaster/Drywall SF Opposite lunchroom 180 7 10+ years Doors - Wood Doors inclu hw Opposite lunchroom 2 EΑ 6 10+ years SF Floor - Terrazzo Opposite lunchroom 180 7 10+ years Floor Drain Opposite lunchroom 1 EΑ 7 10+ years 7 Opposite lunchroom 1 FΑ Lavatory 10+ years Lighting - Pendent/Surface Opposite lunchroom 2 FΑ 6 6-10 years 7 **Partitions** Opposite lunchroom 4 EΑ 10+ years SF 7 Walls - Masonry Opposite lunchroom 500 10+ years SF Walls - Plaster/Drywall Opposite lunchroom 100 7 10+ years Water Closet EΑ Opposite lunchroom 7 10+ years Category: Classroom **Building: Main** Recommend Location Item - Type Quantity **UOM** Rank Replacement Comments Classroom #004 (Art Room) Ceiling - Lay-in Basement 892 SF 7 6-10 years

Campus Name: Brentano Page : 18 of 37 Assessment Date: 11/28/2023



Category : Classroom		В	uilding	: Main				
						Recommend		
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	Basement	8	SF	5	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years		
	Floor - Tile	Basement	900	SF	7	10+ years		
	Kiln	Basement	1	EA	7	10+ years		
	Lighting - Lay-in	Basement	13	EA	7	6-10 years		
	Storage/ Closet	Basement	50	SF	7	10+ years		
	Walls - Masonry	Basement	1,105	SF	7	10+ years		
	Walls - Masonry	Basement	25	SF	5	1-2 years	Deteriorating paint and masonry	
	Walls Wassiny	Basement	20	O.	J	1 Z years	Deteriorating paint and masonly	
lassroc	om #005 (Art Room)							
	Casework	Basement	23	LF	7	10+ years		
	Ceiling - Plaster/Drywall	Basement	831	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years		
	Floor - Tile	Basement	831	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	17	ĒΑ	7	6-10 years		
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	Re-lamp fixture	
	Marker Board	Basement	8	LF	7	•	re-iamp inture	
	Storage/ Closet			SF	7	6-10 years		
		Basement	150			10+ years		
	Walls - Plaster/Drywall	Basement	1,126	SF	7	10+ years		
	Work Sink	Basement	1	EA	7	10+ years		
lassroc	om #011 (Music Room)							
	AC Units	Basement	1	EA	7	6-10 years		
	Casework	Basement	20	LF	7	10+ years		
	Ceiling - Plaster/Drywall	Basement	867	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years		
	Floor - Tile	Basement	867	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	12	EA	7	6-10 years		
				LF		•		
	Marker Board	Basement	10		7	6-10 years		
	Storage/ Closet	Basement	100	SF	7	10+ years		
	Walls - Plaster/Drywall	Basement	1,150	SF	7	10+ years		
lassroc	om #013 (Regular Classroom)							
_	AC Units	Basement	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement	850	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	Basement	850	SF	7	10+ years		
	Lighting - Pendent/Surface			EA	7	6-10 years		
		Basement	4 000					
	Walls - Masonry	Basement	1,090	SF	7	10+ years		
lassroc	om #015 (Regular Classroom)							
	AC Units	Basement	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement	905	SF	7	10+ years		

Campus Name: Brentano Page : 19 of 37 Assessment Date: 11/28/2023



	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Wood	Basement	905	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	13	EA	7	6-10 years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Wall Mirrors	Basement	150	SF	7	10+ years	
	Walls - Masonry	Basement	1,199	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	m #017 (Pre School)						
Classico	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	945	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Wood Doors inclu riw	Basement	945	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	7	6-10 years	
	Marker Board	Basement	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,178	SF	7	10+ years	
	Work Sink	Basement	1,170	EA	7	10+ years	
Classroo	m #101 (Regular Classroom)						
Classico	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	881	SF	7	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Doors inclu riw	1st Floor	881	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
		1st Floor		SF	7	•	
	Walls - Plaster/Drywall	IST FIOOI	1,577	SF	,	10+ years	
Classroo	m #102 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	758	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	758	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,567	SF	7	10+ years	



Catego	Category : Classroom		В	2.	723 N Fairfield AVENUE, Chicago, IL 60047		
23.090	. ,			uilding		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #103 (Regular Classroom)		·			-	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	27	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	885	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Wood	1st Floor	885	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,576	SF	7	10+ years	
_Classroo	m #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	778	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	778	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	57	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,298	SF	7	10+ years	
_Classroo	m #105 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	17	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	885	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	885	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	2	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,583	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #106 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	867	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	867	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	121	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,090	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	296	SF	7	10+ years	
Classroo	m #107 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	31	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,175	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	1,175	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,547	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	275	SF	7	10+ years	
	walls - Flaster/Drywall	13(1100)	213	O.	,	10+ years	
Classroo	m #110 (Regular Classroom)						
	AC Units	1st Floor	2	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	903	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Wood	1st Floor	903	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	27	LF	7	6-10 years	
	Storage/ Closet	1st Floor	143	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,136	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	388	SF	7	10+ years	
Classroo	m #113 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	27	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	852	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	852	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,557	SF	7	10+ years	
	Work Sink	1st Floor	1,557	EA	7	10+ years	
	WOIR SHIR	13(1100)	1	LA	ı	10+ years	
Classroo	m #114 (Regular Classroom)						



Catego	Category : Classroom		R	uilding	· Main	21	23 N Fairneid AVENUE, Chicago, iL 60047
Catego	i y . Ciassi Colli			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. о а.р	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	766	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	766	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Marker Board	1st Floor	25	LF	7	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,181	SF	7	10+ years	
_Classroo	om #115 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	71	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	998	SF	7	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	998	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,650	SF	7	10+ years	
_Classroo	om #117 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,115	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,115	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,768	SF	7	10+ years	
Classroo	om #201 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	881	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	881	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	



Catego	ory : Classroom		В	uilding	: Main		•
- J				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,666	SF	7	10+ years	
Classro	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	770	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,303	SF	7	10+ years	
_Classro	om #203 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	875	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	875	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,659	SF	7	10+ years	
Classro	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	778	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	778	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	57	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,313	SF	7	10+ years	
Classro	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	31	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	883	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	883	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	118	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,697	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	876	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	876	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	32	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,195	SF	7	10+ years	
	vvalio i lactor/Drywan	2110 1 1001	1,100	O.	•	101 youro	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	31	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,175	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,175	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	['] 21	EΑ	7	6-10 years	
	Marker Board	2nd Floor	23	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	625	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	7	10+ years	
Classroo	om #210 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	955	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Bools ilicia IIW	2nd Floor	955	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	31	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	156	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	268	SF SF	7	10+ years 10+ years	
	Walls - Plaster/Drywall Walls - Plaster/Drywall		995	SF SF			
		2nd Floor			7	10+ years	
	vvireless System	ZNA FIOOF	1	ĽΑ	1	10+ years	
	Wireless System	2nd Floor 2nd Floor	1	EA	7	10+ years 10+ years	



Catego	ry : Classroom		В	uilding	: Main		25 W Taimed AVENUE, Officago, IE 00047
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	14	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	894	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	894	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	315	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,365	SF	7	10+ years	
Classroo	om #213 (Science)						
Oldssion	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	997	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	977	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,764	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
						•	
_Classroo	om #214 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	766	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	43	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,342	SF	7	10+ years	
Classroo	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	961	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	961	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,757	SF	7	10+ years	
Classroo	m #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	924	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	924	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,729	SF	7	10+ years	
	walls - Flastel/Drywall	ZIIU FIOOI	1,729	SF	,	10+ years	
Classroc	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	22	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	848	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	21	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	118	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,550	SF	7	10+ years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	770	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	770	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,303	SF	7	10+ years	
	rano i lactor, bi y wan	014 1 1001	1,303	J1	,	ioi youis	
Classroo	m #303 (Science Classroom)						

Campus Name: Brentano Page : 27 of 37 Assessment Date: 11/28/2023



Catego	ry : Classroom		В	uilding	: Main		23 N Faimeld AVENUE, Chicago, IL 60047
- Carogo	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	63	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	885	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	885	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	21	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,577	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	778	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	778	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	57	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,313	SF	7	10+ years	
Classroo	om #305 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	885	SF	7	10+ years	
	Chalk Board	3rd Floor	29	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	885	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	2	SF	7	6-10 years	Updated to reflect current observations
	Walls - Plaster/Drywall	3rd Floor	1,060	SF	7	10+ years	observations
	Walls - Plaster/Drywall	3rd Floor	530	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	883	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Transom Window	3ra Floor	9	SF	1	10+ years	



Category : Classroom		В	uilding	: Main			
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	883	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	67	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,398	SF	7	10+ years	
Classroc	om #307 (Library)						
	Casework	3rd Floor	75	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,934	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,940	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	33	EA	7	6-10 years	
		3rd Floor		SF	7		
	Walls - Plaster/Drywall	314 F1001	2,385	SF	,	10+ years	
lassroc	om #308/310 (Gymnasium)						
	AC Units	3rd Floor	2	EA	5	6-10 years	Reinstall or replace diffuser vanes
	Ceiling - Lay-in	3rd Floor	1,885	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,885	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	30	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	3,679	SF	7	10+ years	
Classroc	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	894	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	894	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	17	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	3	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,590	SF	7	10+ years	
lassroc	om #313 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	40	LF	7	10+ years	
			_	SF	7	•	
	Ceiling - Plaster/Drywall Doors - Transom Window	3rd Floor	977			10+ years	
		3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	



Catego	ry : Classroom		Bı	uilding	: Main		2011 Tallied 71 E110E, Officago, 12 000-7
2 3.10 30						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	977	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,670	SF	7	10+ years	
	Work Sink	3rd Floor	[′] 1	EA	7	10+ years	
Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	756	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	756	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,386	SF	7	10+ years	
Classroo	om #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	961	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	961	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,663	SF	7	10+ years	
Classroo	om #317 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	885	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	885	SF	7	10+ years	
	Floor - Wood	3rd Floor	10	SF	5	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	-
	Marker Board	3rd Floor	19	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,586	SF	7	10+ years	



atego	ry : Interior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	4,461	SF	7	10+ years	
	Doors - Transom Window	1st Floor	148	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	1st Floor	1,652	SF	7	10+ years	
	Floor - Terrazzo	1st Floor	701	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,083	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	50	SF	4	1-2 years	Broken and cracking tiles in the hallway of 101 to 106
	Lighting - Pendent/Surface	1st Floor	39	EA	7	6-10 years	•
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	Re-lamp fixture
	Walls - Plaster/Drywall	1st Floor	9,190	SF	7	10+ years	·
	Ceiling - Plaster/Drywall	2nd Floor	4,461	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	148	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	1,652	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	701	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	30	SF	5	1-2 years	Cracking
	Floor - Tile/Sheet	2nd Floor	2,188	SF	7	10+ years	o raisining
	Floor - Tile/Sheet	2nd Floor	20	SF	4	0-1 year	Cracking and chipping tile edges
	Lighting - Pendent/Surface	2nd Floor	40	ĒΑ	7	6-10 years	commission comprise the congre
	Walls - Plaster/Drywall	2nd Floor	9,190	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	4,457	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	4	SF	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	148	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EΑ	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	1,652	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor	701	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor	150	SF	5	1-2 years	Cracking
	Floor - Tile/Sheet	3rd Floor	2,113	SF	7	10+ years	Ordoning
	Lighting - Pendent/Surface	3rd Floor	40	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	125	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	9,190	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	5,365	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	3,303	EA	7	10+ years	
	Doors - Transom Window	Basement	140	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement	13	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Basement	2	EA	7	6-10 years	
	Floor - Asphalt Floor	Basement	5,155	SF	7	10+ years	
	Floor - Terrazzo	Basement	546	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	4	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	210	SF	7	10+ years	
	1 1001 - THE CETAITHO FUICEIAIH	Dascilletit	210	3F	′	TUT YEARS	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Basement	40	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement	3	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement	13	LF	7	10+ years	
	Walls - Masonry	Basement	4,890	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,999	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	3	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	744	SF	7	10+ years	
afetv							
,	Camera Viewing Station	Entire building	1	EA	7	6-10 years	
stairs							
	Ceiling - Plaster/Drywall	Basement entrance 1 vestibule to 1st floor	44	SF	7	10+ years	
	Floor - Asphalt	Basement entrance 1 vestibule to 1st floor	22	SF	7	10+ years	
	Handrails	Basement entrance 1 vestibule to 1st floor	40	LF	7	10+ years	
	Lighting - Pendent/Surface	Basement entrance 1 vestibule to 1st floor	1	EA	7	6-10 years	
	Stairs - Asphalt	Basement entrance 1 vestibule to 1st floor	18	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement entrance 1 vestibule to 1st floor	1,152	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North	386	SF	7	10+ years	
	Floor - Terrazzo	North	320	SF	7	10+ years	
	Handrails	North	112	LF	7	10+ years	
	Lighting - Pendent/Surface	North	6	EA	7	6-10 years	
	Stairs - Terrazzo	North	76	LF	7	10+ years	
	Walls - Plaster/Drywall	North	2,620	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North West	525	SF	7	10+ years	
	Floor - Terrazzo	North West	381	SF	7	10+ years	
	Handrails	North West	109	LF	7	10+ years	
	Handrails	North West	4	LF	7	10+ years	
	Lighting - Pendent/Surface	North West	6	EA	7	6-10 years	
	Stairs - Terrazzo	North West	82	LF	7	10+ years	
	Walls - Plaster/Drywall	North West	2,586	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	511	SF	7	10+ years	
	Floor - Asphalt	South	314	SF	7	10+ years	
	Handrails	South	107	LF	7	10+ years	
	Lighting - Pendent/Surface	South	6	EA	7	6-10 years	
	Stairs - Asphalt	South	72	LF	7	10+ years	
	Stairs - Asphalt	South	4	LF	4	0-1 year	Cracking near entrance
	Walls - Plaster/Drywall	South	3,054	SF	7	10+ years	Crashing from orthanoc



Catego	Category : Interior			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	South West	525	SF	7	10+ years	
	Floor - Asphalt	South West	381	SF	7	10+ years	
	Handrails	South West	113	LF	7	10+ years	
	Lighting - Pendent/Surface	South West	6	EA	7	6-10 years	
	Stairs - Asphalt	South West	82	LF	7	10+ years	
	Walls - Plaster/Drywall	South West	2,586	SF	7	10+ years	

Campus Name: Brentano Page : 33 of 37 Assessment Date: 11/28/2023



Category : Site **Building: Site**

Catego	ry : Site		Б	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	South	6,350	SF	6	6-10 years	
	Lighting	South	8	EA	6	10+ years	
	Surface - Synthetic including exc & retention	South	12,009	SF	6	6-10 years	
	Surface Symmotic including one a reterment	Coun	.2,000	O.	Ū	o to youro	
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EΑ	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	ΕA	5	2-5 years	
			·			,	
Fencing							
	Fencing - Chain Link	Entire Site	353	LF	6	2-5 years	
	Fencing - Iron and Concrete Post	Entire Site	322	LF	6	2-5 years	
	Fencing - New Standard Ornamental	Entire Site	628	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	30	LF	6	6-10 years	
_Landsca	pe						
	Benches	Entire Site	27	EA	7	10+ years	
	Irrigation	Entire Site	4,600	SF	6	6-10 years	
	Landscape - Grass	Entire Site	1,619	SF	7	6-10 years	
	Landscape - Grass	Entire Site	3,050	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	900	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	1,600	SF	5	2-5 years	
	Landscape - Hardscape- Pavers	Entire Site	240	SF	6	10+ years	
	Parkway trees	Entire Site	7	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	4,600	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	70	SF	7	10+ years	
	Trash Receptacles	Entire Site	70	EA	6	6-10 years	
	Trasif Neceptacies	Littile Site	,	LA	O	0-10 years	
Parking I							
	Concrete Curbs	Parking Lot - Southwest	280	LF	7	10+ years	
	Interior Plantings	Parking Lot - Southwest	90	LF	7	10+ years	
	Surface - Asphalt	Parking Lot - Southwest	6,324	SF	4	2-5 years	Cracks in surface
	Vehicular Screening	Parking Lot - Southwest	345	LF	7	10+ years	
	Concrete Curbs	Parking Lot- North	243	LF	6	10+ years	
	Interior Plantings	Parking Lot- North	30	LF	6	6-10 years	
	Lighting - Pole Mounted	Parking Lot- North	2	EA	6	10+ years	
	Surface - Asphalt	Parking Lot- North	1,997	SF	5	2-5 years	
				SF	4		Northeast edge of the building.
	Surface - Asphalt	Parking Lot- North	10,653	SF	4	1-2 years	Northeast edge of the building.

Campus Name: Brentano Page : 34 of 37 Assessment Date: 11/28/2023



Lorenz Brentano Math & Science Academy ES

2723 N Fairfield AVENUE, Chicago, IL 60647

Catego	Category : Site			uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Damaged asphalt/potholes
	Surface - Concrete	Parking Lot- North	258	SF	5	2-5 years	
	Trash Enclosure - Chain Links	Parking Lot- North	159	SF	5	6-10 years	
	Trash Enclosure - Masonry	Parking Lot- North	217	SF	6	10+ years	
	Vehicular Screening	Parking Lot- North	120	LF	6	6-10 years	
Playgrou	ind						
, 0	Equipment - Pre K 3-5	East	1	EA	6	10+ years	
	Equipment - School Age 5-12	East	1	EA	6	10+ years	
	Surface - Poured Surface	East	5,381	SF	6	10+ years	
_Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	517	LF	6	6-10 years	
	Sidewalks - Internal Walks	Entire Site	10	LF	5	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	12,535	SF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,380	SF	5	2-5 years	
Signage							
- 5- 5-	Flag Pole - Flag Pole	South	1	EA	6	10+ years	
	Marquee - Building Mounted Back Lighted w/ LED	South	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	South	6	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	mionaca ccago	1100111 200011011	Hambon	T Carrison	(0. /	700	71.00	Clop	
Art Room	Regular Classroom	Basement	004		900	30	0		
Art Room	Regular Classroom	Basement	005	005	831	36	15	N	N
Computer Lab	Regular Classroom	2nd Floor	210	210	955	205	103	N	N
Gymnasium	Special Program	3rd Floor	308/310	308	1,885	352	72	N	N
Kindergarten	Kindergarten	1st Floor	117	117	1,115	234	117	N	N
Kindergarten	Regular Classroom	1st Floor	106	106	867	200	100	Y	N
Kindergarten	Regular Classroom	1st Floor	107	107	1,175	184	92	N	Y
Library	Regular Classroom	3rd Floor	307	307	1,940	228	66	N	N
Music Room	Regular Classroom	Basement	011	011	867	48	20	Y	N
Office	Regular Classroom	2nd Floor	203	203	875	198	95	N	N
Office	Regular Classroom	2nd Floor	214	214	766	225	113	N	N
Other Instructional Use	Regular Classroom	2nd Floor	201	201	881	195	95	N	N
Other Instructional Use	Regular Classroom	3rd Floor	305	305	885	154	77	N	N
Pre School	Regular Classroom	1st Floor	105	105	885	154	77	Y	Y
Pre School	Regular Classroom	1st Floor	113	113	852	198	95	Y	N
Pre School	Regular Classroom	Basement	017	017	945	66	28	Y	N
Regular Classroom	Kindergarten	1st Floor	115	115	998	198	95	Y	N
Regular Classroom	Regular Classroom	1st Floor	101	101	881	198	95	Y	N
Regular Classroom	Regular Classroom	1st Floor	103	103	885	198	95	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	778	205	103	Y	N
Regular Classroom	Regular Classroom	1st Floor	110	110	903	205	103	Y	N
Regular Classroom	Regular Classroom	1st Floor	114	114	766	205	103	Y	N
Regular Classroom	Regular Classroom	2nd Floor	102	102	758	225	113	Y	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	770	195	98	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	778	190	95	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	883	154	77	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	876	386	193	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	1,175	184	92	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	894	156	78	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	961	198	95	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	217	924	198	95	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	848	195	98	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	770	195	98	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	778	190	95	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	883	192	96	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	894	156	78	N	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	756	220	110	N	N
Regular Classroom	Regular Classroom	3rd Floor	315	315	961	195	98	N	Υ



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	Basement	013		850	75	40		
Regular Classroom	Regular Classroom	Basement	015	015	905	110	55	Υ	N
Science	Regular Classroom	2nd Floor	213	213	977	195	98	N	N
Science Classroom	Regular Classroom	3rd Floor	303	303	885	189	95	N	N
Science Classroom	Regular Classroom	3rd Floor	313	313	977	195	39	N	N
Special Education	Regular Classroom	3rd Floor	317	317	885	195	95	N	Y

Page : 37 of 37 Campus Name: Brentano Assessment Date: 11/28/2023