

Category: Exterior

Exterior Stairs - Concrete

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1962	2	52,579
Campus Total			52,579

Building: Main

LF

5

6-10 years

Recommend Item - Type Location Quantity **UOM** Rank Replacement Comments Group Entrance Entrance Control - Audio and Video EΑ 6 6-10 years 1 1 Exterior Doors - Exterior AMP Door 1 4 EΑ 6 10+ years Exterior Doors - Transom Lite 2 FΑ 6 10+ years 1 LF Exterior Stairs - Concrete 24 Changed to match current 1 5 10+ years observations. Minor cracking Power Door Operator and Controls 1 2 EΑ 7 10+ years Ramp Handrail - Steel Ramp Handrail 55 LF 1 7 10+ years Quantity changed to match current observations. New LF Ramps - Concrete 1 35 10+ years New Stair Handrail - Steel Stair Handrail LF 6 10+ years Exterior Doors - Exterior Steel Door EΑ 10 - E CY - Elevator Machine Room 1 6 10+ years Exterior Doors - Store Front 11 - West Courtyard Door 1 FΑ 10+ years Changed to match current observations Exterior Doors - Transom Lite 11 - West Courtyard Door 1 1 EΑ 7 10+ years Exterior Stairs - Concrete 11 - West Courtyard Door 1 3 1 F 6 10+ years Quantity changed to match current observations Exterior Doors - Store Front 12 - West Court Yard Rm 109 Door 1 EΑ 7 10+ years 1 Exterior Stairs - Concrete 12 - West Court Yard Rm 109 Door LF 5 6-10 years Exterior Doors - Store Front 13 - West Court Yard Rm 109 Door FΑ 7 10+ years

13 - West Court Yard Rm 109 Door





gor	ry : Exterior		В	uilding	: Main		
						Recommend	
ıp	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Store Front	14 - West Court Yard Rm 111 Door	1	EA	7	10+ years	
	Exterior Stairs - Concrete	14 - West Court Yard Rm 111 Door	7	LF	5	6-10 years	
	Exterior Doors - Store Front	1 15 - West Court Yard Rm 111 Door	1	EA	7	10+ years	
	Exterior Stairs - Concrete	2 15 - West Court Yard Rm 111 Door	7	LF	6	10+ years	
	Fotorios Bassas Otara Francis	2	4	Ε.Δ	0	40	
	Exterior Doors - Store Front	16 - West Courtyard Door 2	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	16 - West Courtyard Door 2	1	EA	6	10+ years	
	Exterior Stairs - Concrete	16 - West Courtyard Door 2	8	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	2	2	EA	6	10+ years	
	Exterior Doors - Side lite	2	1	EA	6	10+ years	
	Exterior Stairs - Concrete	2	10	LF	5	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	2	60	LF	6	10+ years	
	Ramps - Concrete	2	60	LF	6	10+ years	
	Exterior Doors - Side lite	3	2	EA	5	6-10 years	
	Exterior Doors - Store Front	3	2	EA	6	10+ years	
	Exterior Stairs - Concrete	3	10	LF	6	10+ years	
	Power Door Operator and Controls	3	1	ĒΑ	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	3	80	LF	6	10+ years	
		3	80	LF	5	•	
	Ramps - Concrete				_	6-10 years	Dedicated Nathana was far year
	Entrance Control - Audio and Video	4	1	EA	4	0-1 year	Padlocked. Not been used for year Not functional per the POC
	Exterior Doors - Exterior AMP Door	4	2	EA	6	10+ years	
	Exterior Doors - Side lite	4	2	EA	6	10+ years	
	Exterior Stairs - Concrete	4	10	LF	5	1-2 years	Cracking/chipping
	Exterior Doors - Exterior Steel Door	5 - Yard Storage	2	EA	4	1-2 years	Rusted. Does not fully close
	Exterior Doors - Transom Lite	5 - Yard Storage	2	EA	6	1-2 years	Boarded up
	Exterior Stairs - Concrete	5 - Yard Storage	16	LF	5	2-5 years	•
	Exterior Doors - Exterior Steel Door	6 - Boiler Room	1	EA	7	10+ years	Newly replaced
	Exterior Doors - Side lite	6 - Boiler Room	1	EA	7	10+ years	. to, ropiacoa
	Exterior Doors - Transom Lite	6 - Boiler Room	1	EΑ	7	10+ years	Newly replaced
	Exterior Stairs - Concrete	6 - Boiler Room	9	LF	4	1-2 years	Deteriorating/cracking
	Exterior Doors - Exterior Steel Door	7 - Electrical	2	EA	5	2-5 years	Deteriorating/cracking
			6	LF			
	Exterior Stairs - Concrete	7 - Electrical			6	10+ years	The description and sendition but a
	Exterior Doors - Exterior Steel Door	8 - Gym	2	EA	5	1-2 years	The door is in good condition but the sill is rotted
	Exterior Stairs - Concrete	8 - Gym	12	LF	6	10+ years	
	Exterior Doors - Store Front	9 - East Courtyard	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	9 - East Courtyard	1	EA	6	10+ years	
	Exterior Stairs - Concrete	9 - East Courtyard	5	LF	7	10+ years	

_Foundation



Catego	ry : Exterior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Foundation - Concrete	Entire Building	1,048	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF	6	10+ years	
	Foundation - Concrete	Entire Building	3	LF	5	1-2 years	Exposed rebar near parking lot
	Foundation - Concrete	Entire Building	12	LF	4	1-2 years	Water leaking through the clerestory
		Ü				•	windows. Precast concrete panel has shifted and cracked
	Superstructure - Concrete	Entire Building	52,379	SF	7	10+ years	Simod and Sidokod
	Superstructure - Concrete	Entire Building	200	SF	7	10+ years	Repaired
	Caparatractars Controls	Entire Danding	200	O.	•	101 youro	Nopuliou
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	7	6-10 years	Replaced. Quantity changed to match current observations
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	12	EA	7	6-10 years	Newly replaced
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Coping - Metal	Roof 1	846	LF	7	10+ years	Newly replaced
	Downspouts - Interior Downspouts	Roof 1	168	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	20,813	SF	7	10+ years	Newly replaced
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years	
	Roof Structure - Concrete	Roof 1	20,813	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	
	Coping - Metal	Roof 2	103	LF	7	10+ years	Newly replaced
	Downspouts - Interior Downspouts	Roof 2	54	LF	6	10+ years	, ,
	Roof - Modified Bitumen	Roof 2	4,106	SF	7	10+ years	Newly replaced
	Roof Hatch - Metal	Roof 2	1	ĒΑ	7	10+ years	,,
	Roof Structure - Concrete	Roof 2	4,106	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	1	EΑ	7	10+ years	
	Coping - Metal	Roof 3	48	LF	7	10+ years	Newly replaced
	Downspouts - Exterior Downspouts	Roof 3	29	LF	6	10+ years	Nowly replaced
	Parapet - Parapet > 30"	Roof 3	48	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	144	SF	7	10+ years	Newly replaced
	Roof Structure - Concrete	Roof 3	144	SF	7	10+ years	Newly replaced
	Coping - Metal	Roof 4	46	LF	5	2-5 years	
		Roof 4	14	LF	6		
	Downspouts - Interior Downspouts Parapet - Parapet < 16" Height		46	LF	6	10+ years	
		Roof 4		SF		10+ years	Name
	Roof - Modified Bitumen	Roof 4	759 759	SF SF	7 7	10+ years	Newly replaced
	Roof Structure - Concrete	Roof 4				10+ years	
	Access Ladder - Metal	Roof 5	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof 5	20	LF	7	10+ years	Name
	Coping - Metal	Roof 5	99	LF	7	10+ years	Newly replaced
	Downspouts - Interior Downspouts	Roof 5	18	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 5	18	LF	6	10+ years	Newly replaced

Campus Name: Cather Page : 3 of 32 Assessment Date: 03/05/2024





ALL A						2908 W W	ashington BOULEVARD, Chicago, IL 60612
Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Roof 5	1,054	SF	7	10+ years	Newly replaced
	Roof Structure - Concrete	Roof 5	1,054	SF	7	10+ years	
	Access Ladder - Metal	Roof 6	1	EA	7	10+ years	
	Coping - Metal	Roof 6	282	LF	7	10+ years	Newly replaced
	Downspouts - Interior Downspouts	Roof 6	408	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 6	4,590	SF	7	10+ years	Newly replaced
	Roof Structure - Steel / Metal Deck/	Roof 6	4,590	SF	7	10+ years	
	Concrete Topping						
	Chimney - Metal Flue	Roof 7	60	LF	5	6-10 years	
	Coping - Metal	Roof 7	12	LF	7	10+ years	Newly replaced
	Downspouts - Exterior Downspouts	Roof 7	14	LF	7	10+ years	Newly replaced
	Roof - Modified Bitumen	Roof 7	156	SF	7	10+ years	Newly replaced
	Roof Structure - Concrete	Roof 7	156	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	200	SF	6	10+ years	
	Exterior Walls - Concrete Block	Entire Building	558	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	16,441	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	200	SF	3	1-2 years	Displaced/Cracking
	Exterior Walls - Prefabricated Metal Panel	Entire Building	8	SF	6	10+ years	
	Wall	3				,	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,096	SF	6	10+ years	
	vvaii						
Windows							
	Clerestory - Glass Double-Pane	Entire Building	260	SF	6	10+ years	
	Clerestory - Glass Single-Pane	Entire Building	1,056	SF	5	2-5 years	
	Curtain wall - Glazed Double Pane	Entire Building	1,026	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	4,968	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	150	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	6,974	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	774	SF	6	10+ years	
	Lintels - Steel	Entire Building	12	LF	6	10+ years	
	Storefront Windows	Entire Building	80	SF	6	10+ years	
	Storefront Windows	Entire Building	25	SF	6	10+ years	
	Windows - Louver	Entire Building	105	SF	6	10+ years	
0-1	Floatrical		_		- NA '		
Catego	ry : Electrical		В	uilding	: wain	Decemment	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System	Location	Quantity	CON	Naiik	Replacement	Comments
merger	Automatic Transfer Switch	Boiler Room	1	EA	6	6-10 years	
			•	SF	6		
	Emergency A/C Power - Corridors and	Entire Building	12,481	SF	O	6-10 years	





Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs		_				
	Emergency A/C Power - Gym	Entire Building	3,934	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	21	EA	7	6-10 years	
	Stairs	G				•	
	Emergency Battery Packs - Gym	Entire Building	4	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	20	EA	7	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	3	EA	7	6-10 years	
	Security System - CCTV	Entire Building	52,579	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	52,579	SF	6	6-10 years	
	Cooding Cyclonic Installation 2 closus.	g	02,0.0	•	· ·	0 .0 you.0	
//ain Se							
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	6-10 years	
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	7	6-10 years	
	PA System	Entire Building	52,579	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
	,		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	2nd Annunciator Panel located in Engineer's Office
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	-
	Fire Alarm Strobe Lights	Entire Building	52,579	SF	6	6-10 years	
		Entire Building	52,579	SF	6	6-10 years	
	Fire Alarm_System		0=,0.0				
Catego	•	g		uildina	: Main		
Catego	Fire Alarm_System ry: Mechanical	g		uilding	: Main	Recommend	
Froup	ry : Mechanical Item - Type	Location		uilding UOM	: Main Rank	Recommend Replacement	Comments
Group	ry : Mechanical Item - Type ling Systems	Location	В	UOM	Rank	Replacement	Comments
Group	ry : Mechanical Item - Type		В	_			Comments
Froup	ry : Mechanical Item - Type ling Systems Air Handling Unit-Package Single Zone-	Location	В	UOM	Rank	Replacement	Comments

Campus Name: Cather Page : 5 of 32 Assessment Date: 03/05/2024



	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Gas Heating and DX Cooling Coil - Less		•			•	
	than 5 tons						
	Roof Top Unit-Single Zone-Roof Mounted-	Main Roof	1	EA	6	6-10 years	Scheduled to be replaced, per
	Gas Heating and DX Cooling Coil - Less						engineer
	than 5 tons						
	Air Handling Unit-Package Single Zone-	Multipurpose Room	1	EA	6	6-10 years	
	Indoor- Hot Water Coils - 8001-12000 cfm						
	Air Intake	Multipurpose Room	1	EA	6	6-10 years	
Boiler S	ystems						
	Boiler Auxiliary- Electric- Hot Water Boiler -	Boiler Room	2	EA	7	10+ years	2023 install
	1001 - 2000 MBH						
	Chemical Pot Feeder	Boiler Room	1	EA	7	10+ years	
	Combustion Dampers	Boiler Room	2	EA	7	10+ years	
	Electric- Hot Water Boiler - 1001 - 2000	Boiler Room	2	EA	7	10+ years	2023 install
	MBH						
	Glycol Feed System	Boiler Room	1	EA	7	10+ years	
	Hot Water Pump	Boiler Room	2	EA	7	10+ years	Removed
	Piping - Dual Temperature Pipes- Steel	Boiler Room	52,579	LF	7	10+ years	Hot water only.
	Water Fill System	Boiler Room	1	EA	7	10+ years	Boilers, filled off hot water pumps, via
							pressure
Gas Boo	neter						pressure
Gas Boo	oster Gas Booster	Boiler Room	2	EA	6	6-10 years	pressure
	Gas Booster	Boiler Room	2	EA	6	6-10 years	pressure
Gas Boo	Gas Booster Devices					, 	pressure
	Gas Booster Devices Wall Heater - Electric	1st Floor	2	EA	6	6-10 years	
	Gas Booster Devices					, 	Could not locate. May have been
	Gas Booster Devices Wall Heater - Electric Unit Heater - Hot Water	1st Floor 1st Floor	2	EA EA	6 7	6-10 years 10+ years	
	Gas Booster Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil	1st Floor 1st Floor 1st Floor	2 1 3	EA EA	6 7 6	6-10 years 10+ years 6-10 years	Could not locate. May have been
	Gas Booster Devices Wall Heater - Electric Unit Heater - Hot Water	1st Floor 1st Floor	2	EA EA	6 7	6-10 years 10+ years	Could not locate. May have been
<u>Heating</u>	Gas Booster Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water	1st Floor 1st Floor 1st Floor Entire Building	2 1 3 325	EA EA LF	6 7 6 6	6-10 years 10+ years 6-10 years 6-10 years	Could not locate. May have been removed.
<u>Heating</u>	Gas Booster Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water	1st Floor 1st Floor 1st Floor	2 1 3	EA EA	6 7 6	6-10 years 10+ years 6-10 years	Could not locate. May have been removed. A lot of hydronic supply and return
<u>Heating</u>	Gas Booster Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water	1st Floor 1st Floor 1st Floor Entire Building	2 1 3 325	EA EA LF	6 7 6 6	6-10 years 10+ years 6-10 years 6-10 years	Could not locate. May have been removed. A lot of hydronic supply and return piping has been replaced with
<u>Heating</u>	Gas Booster Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water	1st Floor 1st Floor 1st Floor Entire Building	2 1 3 325	EA EA LF	6 7 6 6	6-10 years 10+ years 6-10 years 6-10 years	Could not locate. May have been removed. A lot of hydronic supply and return piping has been replaced with reconfiguration of boiler room and
<u>Heating</u>	Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water ical Plumbing Hydronic Supply and Return - Steel	1st Floor 1st Floor 1st Floor Entire Building Entire Building	2 1 3 325 400	EA EA LF	6 7 6 6	6-10 years 10+ years 6-10 years 6-10 years 10+ years	Could not locate. May have been removed. A lot of hydronic supply and return piping has been replaced with
<u>Heating</u>	Gas Booster Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water	1st Floor 1st Floor 1st Floor Entire Building	2 1 3 325	EA EA LF	6 7 6 6	6-10 years 10+ years 6-10 years 6-10 years	Could not locate. May have been removed. A lot of hydronic supply and return piping has been replaced with reconfiguration of boiler room and
Heating Mechan	Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water ical Plumbing Hydronic Supply and Return - Steel	1st Floor 1st Floor 1st Floor Entire Building Entire Building	2 1 3 325 400	EA EA LF	6 7 6 6	6-10 years 10+ years 6-10 years 6-10 years 10+ years	Could not locate. May have been removed. A lot of hydronic supply and return piping has been replaced with reconfiguration of boiler room and
Heating Mechan	Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water ical Plumbing Hydronic Supply and Return - Steel Hot Water Pump - Less than 10	1st Floor 1st Floor 1st Floor Entire Building Entire Building	2 1 3 325 400	EA EA LF	6 7 6 6	6-10 years 10+ years 6-10 years 6-10 years 10+ years	Could not locate. May have been removed. A lot of hydronic supply and return piping has been replaced with reconfiguration of boiler room and heating system What is located in elevator pump
Heating Mechan	Devices Wall Heater - Electric Unit Heater - Hot Water Cabinet Heaters - With Hot Water Coil Fin Tube - Hot Water ical Plumbing Hydronic Supply and Return - Steel Hot Water Pump - Less than 10	1st Floor 1st Floor 1st Floor Entire Building Entire Building Entire Building	2 1 3 325 400	EA EA LF LF	6 7 6 6	6-10 years 10+ years 6-10 years 6-10 years 10+ years	Could not locate. May have been removed. A lot of hydronic supply and return piping has been replaced with reconfiguration of boiler room and heating system

Campus Name: Cather Page : 6 of 32 Assessment Date: 03/05/2024



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Thermostats - DDC	Entire Building	1	EA	6	0-1 year	place not in use. Room 218, 217, 106, lunchroom, gym. Damaged
	Thermostats - Pneumatic	Entire Building	37	EA	4	0-1 year	Rat system is completely disconnected and discontinued
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	33	EA	4	0-1 year	Units do not work properly. Problems with dampers and actuators. Constantly worked on and fiddled with to make work properly. Plans in place for replacement of unit ventilators
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building Entire Building	5 3	EA EA	6 7	6-10 years 10+ years	Lunchroom
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	6	EA	7	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	· •	Location	quantity	COM	Raint	Коріцосіноні	
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	7	10+ years	Replace new in 2024
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	52,579	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	52,579	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	52,579	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	52,579	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	52,579	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	52,579	SF	6	6-10 years	



Catego	Category : Plumbing Building : Main						-
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Cioup	Sanitary Piping Storm Piping Vent Piping	Entire Building Entire Building Entire Building	52,579 52,579 52,579	SF SF SF	6 6 6	6-10 years 6-10 years 6-10 years	
Pumps	Pumps - Sump-Simplex	1st Floor	1	EA	6	6-10 years	Located under elevator pit.

Building: Main Category: Room

Catego	ry : Room		В	ullaing	: wain		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	103A - Counselor's Office/Waiting	1	EA	7	6-10 years	
	Ceiling - Splined	103A - Counselor's Office/Waiting	131	SF	7	10+ years	
	Doors - Side-lite	103A - Counselor's Office/Waiting	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103A - Counselor's Office/Waiting	1	EA	7	10+ years	
	Floor - Carpet	103A - Counselor's Office/Waiting	131	SF	7	6-10 years	
	Lighting - Pendent/Surface	103A - Counselor's Office/Waiting	1	EA	7	10+ years	
	Lighting - Pendent/Surface	103A - Counselor's Office/Waiting	1	EA	5	1-2 years	Missing cover
	Walls - Concrete Block	103A - Counselor's Office/Waiting	233	SF	7	10+ years	
	Ceiling - Lay-in	118A - Library Office	114	SF	7	10+ years	
	Ceiling - Lay-in	118A - Library Office	2	SF	5	1-2 years	Damaged tile and grid
	Doors - Side-lite	118A - Library Office	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	118A - Library Office	1	EA	7	10+ years	
	Floor - Tile	118A - Library Office	116	SF	7	10+ years	
	Lighting - Lay-in	118A - Library Office	2	EA	7	10+ years	
	Power Distribution	118A - Library Office	2	EA	7	10+ years	
	Walls - Concrete Block	118A - Library Office	172	SF	7	10+ years	
	Work SInk	118A - Library Office	1	EA	7	10+ years	
	AC Unit	126 Conference Room	1	EA	7	6-10 years	
	Ceiling - Exposed	126 Conference Room	494	SF	7	10+ years	
	Doors - Side-lite	126 Conference Room	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	126 Conference Room	1	EA	7	10+ years	
	Floor - Carpet	126 Conference Room	464	SF	7	6-10 years	
	Floor - Carpet	126 Conference Room	38	SF	4	0-1 year	Torn carpet
	Lighting - Pendent/Surface	126 Conference Room	6	EA	7	10+ years	
	Storage/ Closet	126 Conference Room	8	SF	7	10+ years	
	Walls - Concrete Block	126 Conference Room	646	SF	7	10+ years	
	Work SInk	126 Conference Room	1	EA	7	10+ years	
	Ceiling - Splined	135 - Health Services	202	SF	7	10+ years	
	Doors - Wood Doors inclu hw	135 - Health Services	2	EA	7	10+ years	
	Floor - Carpet	135 - Health Services	202	SF	7	6-10 years	
	Lighting - Pendent/Surface	135 - Health Services	1	EA	7	10+ years	
	Lighting - Pendent/Surface	135 - Health Services	2	EA	5	1-2 years	Missing cover
	Walls - Concrete Block	135 - Health Services	403	SF	7	10+ years	-

Campus Name: Cather Page: 8 of 32 Assessment Date: 03/05/2024





Category : Room			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	135 - Health Services	1	EA	7	10+ years	
	Ceiling - Lay-in	238 Assistant Principal/Counseling	404	SF	7	10+ years	
	Doors - Steel Doors incl hw	238 Assistant Principal/Counseling	1	EA	7	10+ years	
	Floor - Carpet	238 Assistant Principal/Counseling	399	SF	7	6-10 years	
	Floor - Carpet	238 Assistant Principal/Counseling	5	SF	5	1-2 years	Torn
	Lighting - Lay-in	238 Assistant Principal/Counseling	6	EA	7	6-10 years	
	Walls - Concrete Block	238 Assistant Principal/Counseling	622	SF	7	10+ years	
	Ceiling - Splined	All gender lounge	260	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	All gender lounge	1	EA	7	10+ years	
	Floor - Tile	All gender lounge	260	SF	6	6-10 years	
	Lighting - Pendent/Surface	All gender lounge	3	EA	7	6-10 years	Qty updated
	Walls - Concrete Block	All gender lounge	402	SF	7	10+ years	
	AC Unit	Engineer	1	EA	7	6-10 years	
	Ceiling - Exposed	Engineer	108	SF	7	10+ years	
	Doors - Steel Doors incl hw	Engineer	1	EA	7	10+ years	
	Floor - Tile	Engineer	108	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer	3	EA	5	1-2 years	Missing cover
	Power Distribution	Engineer	2	EA	7	10+ years	
	Walls - Concrete Block	Engineer	395	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym	39	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym	15	SF	4	0-1 year	Water damaged
	Doors - Wood Doors inclu hw	Gym	1	EA	7	10+ years	
	Floor - Tile	Gym	54	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym	2	EA	5	1-2 years	Missing covers
	Power Distribution	Gym	2	EA	7	10+ years	
	Walls - Concrete Block	Gym	176	SF	7	10+ years	
	Walls - Plaster/Drywall	Gym	40	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen	86	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen	1	EA	7	10+ years	
	Floor - Tile Quarry	Kitchen	86	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen	2	EA	5	1-2 years	Missing covers
	Power Distribution	Kitchen	2	EA	7	10+ years	
	Walls - Concrete Block	Kitchen	276	SF	7	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main Office	420	SF	7	10+ years	
	Doors - Transom Window	Main Office	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Carpet	Main Office	360	SF	7	6-10 years	
	Floor - Tile	Main Office	60	SF	7	10+ years	
	Lighting - Lay-in	Main Office	10	EA	7	10+ years	
	Storage/ Closet	Main Office	112	SF	7	10+ years	
	Walls - Concrete Block	Main Office	510	SF	7	10+ years	
	AC Unit	Principal	1	ĒΑ	7	6-10 years	
	Ceiling - Lay-in	Principal	165	SF	7	10+ years	





	ry : Room		D	uilding	· Main	2000 77 77	asilington BOOLE VARD, Chicago, IL 60612
Calego	iy . Kooiii		Б	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Doors - Wood Doors inclu hw	Principal	Qualitity 1	EA	7	10+ years	Comments
				SF	7		
	Floor - Carpet	Principal	165			6-10 years	
	Lighting - Lay-in	Principal	4	EA	7	10+ years	
	Storage/ Closet	Principal	7	SF	7	10+ years	
	Walls - Concrete Block	Principal	310	SF	7	10+ years	
Gymnas	ia						
_ Оупппас	Ceiling - Exposed	1st Floor	3,934	SF	7	10+ years	No occupancy signage
	Doors - Steel Doors incl hw	1st Floor	2,934	EA	7	10+ years	No occupancy signage
	Doors - Wood Doors inclu hw	1st Floor		EA	7		
			6	SF		10+ years	
	Floor - Tile	1st Floor	43		7	10+ years	
	Floor - Wood	1st Floor	3,891	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EΑ	7	10+ years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	500	SF	7	10+ years	
	Stage Curtain	1st Floor	6	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	2	EA	7	10+ years	
	Stage-Stairs - Terrazzo	1st Floor	25	LF	7	10+ years	
	Stage-Stairs - Tile	1st Floor	20	LF	7	10+ years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	6,236	SF	6	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor	696	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	696	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	10+ years	
	Serving Line	1st Floor	20	LF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	739	SF	7	10+ years	
	Walls - Structural Glazed Tile	13111001	739	Si	,	10+ years	
Library							
•	AC Unit	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,060	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,060	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	ĒΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	1,096	SF	7	10+ years	
Locker	Shower Room						
_Locker/S		Ond Class legitaria Lauter D	450	<u> </u>	7	40	
	Ceiling - Plaster/Drywall	2nd Floor Janitor's Locker Room	158	SF	7	10+ years	

Campus Name: Cather Page: 10 of 32 Assessment Date: 03/05/2024





Catego	ry : Room		В	uilding	: Main		•
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor Janitor's Locker Room	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Janitor's Locker Room	158	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Janitor's Locker Room	3	EΑ	7	6-10 years	
	Partitions	2nd Floor Janitor's Locker Room	1	ĒΑ	7	10+ years	
	Student Lockers - One Tier	2nd Floor Janitor's Locker Room	3	EA	7	10+ years	
	Student Lockers - Three Tiers	2nd Floor Janitor's Locker Room	10	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Janitor's Locker Room	381	SF	7	10+ years	
Lunch &	Multipurpose Room						
uncn &	AC Unit	117	2	ГΛ	7	6.10 years	
			2	EA	7	6-10 years	
	Ceiling - Exposed	117	1,380	SF	7	10+ years	
	Ceiling - Plaster/Drywall	117	160	SF	7	10+ years	
	Doors - Side-lite	117	50	SF	7	10+ years	No occupancy signage
	Doors - Steel Doors incl hw	117	2	EΑ	7	10+ years	
	Floor - Tile	117	1,540	SF	7	10+ years	
	Lighting - Pendent/Surface	117	40	EΑ	7	10+ years	
	Storage/ Closet	117	16	SF	7	10+ years	
	Walls - Concrete Block	117	1,108	SF	7	10+ years	
	Ceiling - Splined	Faculty Lounge	482	SF	7	10+ years	
	Ceiling - Splined	Faculty Lounge	20	SF	4	0-1 year	Water damage
	Doors - Transom Window	Faculty Lounge	188	SF	7	6-10 years	Water damage
				EA			No seement signers
	Doors - Wood Doors inclu hw	Faculty Lounge	2		7	10+ years	No occupancy signage
	Floor - Tile	Faculty Lounge	502	SF	7	10+ years	
	Lighting - Pendent/Surface	Faculty Lounge	10	EΑ	7	10+ years	
	Walls - Concrete Block	Faculty Lounge	661	SF	7	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	101	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Portable unit
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	Repaired
_Mechan	ical/ Service Rooms						
	Boiler Room	1st Floor	992	SF	7	10+ years	
	Janitor's Closet	1st Floor	26	SF	7	10+ years	
	Janitor's Closet	1st Floor	26	SF	7	10+ years	
	Loading Docks	1st Floor	116	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	150	SF	7		
				SF SF		10+ years	
	Mechanical/ Service Rooms	1st Floor	59		7	10+ years	
	Storage Room	1st Floor	231	SF	7	10+ years	
	Storage Room	1st Floor	40	SF	7	10+ years	
	Storage Room	1st Floor	311	SF	7	10+ years	
	Storage Room	1st Floor	40	SF	7	10+ years	

Campus Name: Cather Page : 11 of 32 Assessment Date: 03/05/2024





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage Room	1st Floor	25	SF	7	10+ years	
	Storage Room	1st Floor	377	SF	7	10+ years	
	Vaults	1st Floor	104	SF	7	10+ years	
	Janitor's Closet	2nd Floor	50	SF	7	10+ years	
	Janitor's Closet	2nd Floor	38	SF	7	10+ years	
				-		, , , , , , , , , , , , , , , , , , , ,	
Prep Roc	om.						
	Casework	201A	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	201A	307	SF	7	10+ years	
	Doors - Wood Doors inclu hw	201A 201A	1	EA	7	10+ years	
	Floor - Terrazzo	201A 201A	307	SF	7	10+ years	
	Lighting - Pendent/Surface	201A 201A	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	201A 201A	1	EA	6		
	Walls - Plaster/Drywall	201A 201A	620	SF	7	6-10 years	
	Work Sink	201A 201A	1	EA	7	10+ years	
	WORK SILIK	201A	ı	EA	1	10+ years	
_Restroom	^						
1762110011	Accessories	109A	34	SF	7	6-10 years	
	Ceiling - Lay-in	109A	24	SF	7	10+ years	
	Ceiling - Lay-in	109A	10	SF	5	1-2 years	Water damaged
	Doors - Wood Doors inclu hw	109A 109A	10	EA	7	10+ years	Water damaged
	Floor - Tile Ceramic/ Porcelain	109A 109A	34	SF	7	10+ years	
	Hand Dryer	109A 109A	1	EA	7	6-10 years	
	Lavatory	109A 109A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	109A 109A	1	EA	7	-	
	Walls - Tile Ceramic/ Porcelain	109A 109A	166	SF	7	10+ years	
	Water Closet	109A 109A	100	EA	7	10+ years	
			34	SF	7	10+ years	
	Accessories	111A		SF SF		6-10 years	
	Ceiling - Lay-in	111A	34		7	10+ years	
	Doors - Wood Doors inclu hw	111A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	111A	34	SF	7	10+ years	
	Hand Dryer	111A	1	EΑ	7	6-10 years	
	Lavatory	111A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	111A	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	111A	166	SF	7	10+ years	
	Water Closet	111A	1	EA	7	10+ years	
	Accessories	1st Floor - All Gender	39	SF	7	6-10 years	
	Ceiling - Splined	1st Floor - All Gender	39	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - All Gender	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - All Gender	39	SF	7	10+ years	
	Lavatory	1st Floor - All Gender	1	EA	7	10+ years	
	1:1: D 1 1/0 (1st Floor - All Gender	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface					,	
	Lighting - Pendent/Surrace Lighting - Wall Mounted Partitions	1st Floor - All Gender 1st Floor - All Gender 1st Floor - All Gender	1 1	EA EA	, 7 7	10+ years	

Campus Name: Cather Page : 12 of 32 Assessment Date: 03/05/2024





Category : Room			Building : Main					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Tile Ceramic/ Porcelain	1st Floor - All Gender	179	SF	7	10+ years		
	Water Closet	1st Floor - All Gender	1	EA	7	10+ years		
	Accessories	1st Floor - All Gender inside Lounge	48	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor - All Gender inside Lounge	48	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor - All Gender inside Lounge	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - All Gender inside Lounge	48	SF	7	10+ years		
	Floor Drain	1st Floor - All Gender inside Lounge	1	EA	7	6-10 years		
	Lavatory	1st Floor - All Gender inside Lounge	1	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor - All Gender inside Lounge	4	EA	7	10+ years		
	Lighting - Wall Mounted	1st Floor - All Gender inside Lounge	1	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor - All Gender inside Lounge	201	SF	7	10+ years		
	Water Closet	1st Floor - All Gender inside Lounge	1	EA	7	10+ years		
	Accessories	1st Floor - East	176	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor - East	176	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - East	1	EA	6	2-5 years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - East	166	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - East	10	SF	4	0-1 year	Missing tiles	
	Floor Drain	1st Floor - East	1	EA	7	10+ years		
	Lavatory	1st Floor - East	3	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor - East	2	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor - East	1	EA	5	1-2 years	Damaged cover	
	Partitions	1st Floor - East	3	EA	7	10+ years	•	
	Urinals	1st Floor - East	2	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor - East	404	SF	7	10+ years		
	Water Closet	1st Floor - East	3	EA	7	10+ years		
	Accessories	1st Floor - East	176	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor - East	176	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - East	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - East	175	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - East	1	SF	4	0-1 year	Missing or damaged tiles	
	Floor Drain	1st Floor - East	1	ĒΑ	7	10+ years	3	
	Lavatory	1st Floor - East	3	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor - East	3	EA	7	10+ years		
	Partitions	1st Floor - East	5	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor - East	404	SF	7	10+ years		
	Water Closet	1st Floor - East	5	EA	7	10+ years		
	Accessories	1st Floor - West	138	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor - West	138	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor - West	1	ĒΑ	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - West	128	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - West	10	SF	4	0-1 year	Missing tiles	
	Floor Drain	1st Floor - West	1	EΑ	7	10+ years	3 ·	
	Lavatory	1st Floor - West	2	EΑ	7	10+ years		
	Lighting - Pendent/Surface	1st Floor - West	2	EΑ	7	10+ years		

Campus Name: Cather Page : 13 of 32 Assessment Date: 03/05/2024





Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor - West	1	EA	5	1-2 years	Broken cover
	Partitions	1st Floor - West	2	EA	7	10+ years	
	Urinals	1st Floor - West	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - West	355	SF	7	10+ years	
	Water Closet	1st Floor - West	2	EA	7	10+ years	
	Accessories	1st Floor - West	138	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - West	138	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - West	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - West	128	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - West	10	SF	4	0-1 year	Missing tiles
	Floor Drain	1st Floor - West	1	EA	7	10+ years	ŭ
	Lavatory	1st Floor - West	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - West	3	EA	7	10+ years	
	Partitions	1st Floor - West	4	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - West	355	SF	7	10+ years	
	Water Closet	1st Floor - West	4	ĒΑ	7	10+ years	
	Accessories	2nd Floor Boys Restroom used as	120	SF	7	6-10 years	
		storage			-	- · · · · · · · · · · · · · · · · · · ·	
	Ceiling - Plaster/Drywall	2nd Floor Boys Restroom used as	120	SF	7	10+ years	
	Coming Thatien, 21, mail	storage	.20	O.	•	ioi youro	
	Doors - Wood Doors inclu hw	2nd Floor Boys Restroom used as	1	EA	7	10+ years	
	Boold Wood Boold Mold IIW	storage	•		•	101 youro	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys Restroom used as	120	SF	7	10+ years	
	ricor The Geranno, Forcelan	storage	120	Oi.	,	101 years	
	Floor Drain	2nd Floor Boys Restroom used as	1	EA	7	10+ years	
	1 loor Brain	storage		L/ \	,	101 years	
	Lighting - Pendent/Surface	2nd Floor Boys Restroom used as	1	EA	7	6-10 years	
	Lighting Tendent/Ounded	storage		L/ \	,	o to years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Boys Restroom used as	329	SF	7	10+ years	
	Walls - The Ceramic, Torcelain	storage	323	Oi	'	10+ years	
	Accessories	2nd Floor Boys South West	134	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boys South West	134	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Boys South West	104	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys South West	132	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys South West	2	SF	5	1-2 years	Missing or damaged tile
	Floor Drain	2nd Floor Boys South West	1	EA	7	10+ years	Missing of damaged the
	Lavatory	2nd Floor Boys South West	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Boys South West	3	EA	7	6-10 years	
	Partitions	2nd Floor Boys South West	2	EA	7	10+ years	
	Urinals	2nd Floor Boys South West	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Boys South West 2nd Floor Boys South West	349	SF	6	10+ years 10+ years	
		2nd Floor Boys South West 2nd Floor Boys South West		Sr EA	7		
	Water Closet Accessories	2nd Floor Boys South West 2nd Floor East Unisex	2 39	SF	7	10+ years 6-10 years	
		2nd Floor East Unisex 2nd Floor East Unisex	39	SF SF	7		
	Ceiling - Splined	ZIIU FIOOI East Offisex	39	ЗF	′	10+ years	

Campus Name: Cather Page : 14 of 32 Assessment Date: 03/05/2024





Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor East Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor East Unisex	39	SF	7	10+ years	
	Lavatory	2nd Floor East Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor East Unisex	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor East Unisex	173	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor East Unisex	5	SF	6	1-2 years	Cracks in mortar
	Water Closet	2nd Floor East Unisex	1	EA	7	10+ years	
	Accessories	2nd Floor Girls'	140	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls'	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girls'	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls'	140	SF	7	10+ years	
	Floor Drain	2nd Floor Girls'	1	EA	7	10+ years	
	Lavatory	2nd Floor Girls'	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls'	3	EA	7	6-10 years	
	Partitions	2nd Floor Girls'	4	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls'	387	SF	6	10+ years	
	Water Closet	2nd Floor Girls'	4	EA	7	10+ years	
	Accessories	2nd Floor Teacher Lounge	50	SF	7	6-10 years	The lounge and restroom have been reconfigured
	Ceiling - Splined	2nd Floor Teacher Lounge	50	SF	7	10+ years	C
	Doors - Wood Doors inclu hw	2nd Floor Teacher Lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Teacher Lounge	50	SF	7	10+ years	
	Floor Drain	2nd Floor Teacher Lounge	1	EA	7	10+ years	
	Lavatory	2nd Floor Teacher Lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Teacher Lounge	1	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor Teacher Lounge	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Teacher Lounge	240	SF	7	10+ years	Tile on all wall surfaces
	Water Closet	2nd Floor Teacher Lounge	1	EA	7	10+ years	
	Accessories	Engineer	94	SF	7	6-10 years	
	Ceiling - Splined	Engineer	89	SF	7	10+ years	
	Ceiling - Splined	Engineer	5	SF	4	1-2 years	Damaged tiles
	Doors - Steel Doors incl hw	Engineer	1	EA	7	10+ years	•
	Floor - Concrete	Engineer	47	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Engineer	47	SF	7	10+ years	
	Lavatory	Engineer	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Engineer	3	EA	7	10+ years	
	Lighting - Wall Mounted	Engineer	1	EA	7	10+ years	
	Partitions	Engineer	1	EA	7	10+ years	
	Showers	Engineer	1	ĒΑ	7	10+ years	
	Urinals	Engineer	1	EA	7	10+ years	
	Walls - Concrete Block	Engineer	145	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Engineer	145	SF	7	10+ years	
	Water Closet	Engineer	1	EA	7	10+ years	
	Accessories	Health Services'	25	SF	7	6-10 years	

Campus Name: Cather Page : 15 of 32 Assessment Date: 03/05/2024





Catego	ry : Room	Building : Main						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Splined	Health Services'	25	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Health Services'	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Health Services'	25	SF	7	10+ years		
	Lavatory	Health Services'	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Health Services'	1	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Health Services'	139	SF	7	10+ years		
	Water Closet	Health Services'	1	EA	7	10+ years		
	Accessories	Kitchen	48	SF	7	6-10 years		
	Ceiling - Lay-in	Kitchen	48	SF	7	10+ years		
	Doors - Steel Doors incl hw	Kitchen	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Kitchen	22	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Kitchen	26	SF	7	10+ years		
	Lavatory	Kitchen	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Kitchen	2	EA	7	10+ years		
	Student Lockers - One Tier	Kitchen	5	EA	7	10+ years		
	Walls - Concrete Block	Kitchen	142	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Kitchen	129	SF	7	10+ years		
	Water Closet	Kitchen	1	EA	7	10+ years		
	Accessories	Principal	23	SF	7	6-10 years		
	Ceiling - Lay-in	Principal	23	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Principal	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Principal	23	SF	7	10+ years		
	Lavatory	Principal	1	EA	7	10+ years		
	Lighting - Lay-in	Principal	1	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Principal	132	SF	7	10+ years		
	Water Closet	Principal	1	EA	7	10+ years		

Category: Classroom **Building: Main**

					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
m #101 (Regular Classroom)						
AC Units	1st Floor	2	EA	7	6-10 years	
Casework	1st Floor	18	LF	7	10+ years	
Ceiling - Exposed	1st Floor	692	SF	7	10+ years	
Ceiling - Plaster/Drywall	1st Floor	50	SF	7	10+ years	
Doors - Side-lite	1st Floor	32	SF	7	10+ years	
Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years	
Floor - Tile	1st Floor	720	SF	7	10+ years	
Floor - Tile	1st Floor	30	SF	5	0-1 year	Cracked tiles
Lighting - Pendent/Surface	1st Floor	20	EΑ	7	10+ years	
Marker Board	1st Floor	12	LF	7	6-10 years	
Storage/ Closet	1st Floor	8	SF	7	10+ years	
Walls - Concrete Block	1st Floor	944	SF	7	10+ years	
	m #101 (Regular Classroom) AC Units Casework Ceiling - Exposed Ceiling - Plaster/Drywall Doors - Side-lite Doors - Steel Doors incl hw Floor - Tile Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet	AC Units 1st Floor Casework 1st Floor Ceiling - Exposed 1st Floor Ceiling - Plaster/Drywall 1st Floor Doors - Side-lite 1st Floor Doors - Steel Doors incl hw 1st Floor Floor - Tile 1st Floor Floor - Tile 1st Floor Lighting - Pendent/Surface 1st Floor Marker Board 1st Floor Storage/ Closet 1st Floor	## #101 (Regular Classroom) AC Units	##101 (Regular Classroom) AC Units	##101 (Regular Classroom) AC Units	Item - Type Location Quantity UOM Rank Replacement Im #101 (Regular Classroom) 1st Floor 2 EA 7 6-10 years AC Units 1st Floor 18 LF 7 10+ years Casework 1st Floor 692 SF 7 10+ years Ceiling - Exposed 1st Floor 50 SF 7 10+ years Ceiling - Plaster/Drywall 1st Floor 32 SF 7 10+ years Doors - Side-lite 1st Floor 32 SF 7 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 30 SF 5 0-1 year Floor - Tile 1st Floor 30 SF 5 0-1 year Lighting - Pendent/Surface 1st Floor 20 EA 7 10+ years Marker Board 1st Floor 12 LF 7 6-10 years Storage/ Closet 1st Floor 8 SF 7 10+ years

Campus Name: Cather Page : 16 of 32 Assessment Date: 03/05/2024





Catego	ry : Classroom		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Classroc	m #102 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	18	LF	7	10+ years		
	Ceiling - Exposed	1st Floor	692	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	50	SF	7	10+ years		
	Doors - Side-lite	1st Floor	32	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	745	SF	7	10+ years		
	Floor - Tile	1st Floor	5	SF	5	1-2 years	Damaged tiles	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	8	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	944	SF	7	10+ years		
_Classroc	m #103 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	18	LF	7	10+ years		
	Ceiling - Exposed	1st Floor	692	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	50	SF	7	10+ years		
	Doors - Side-lite	1st Floor	32	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years		
	Floor - Tile	1st Floor	742	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	8	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	936	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	8	SF	6	6-10 years		
Classroo	m #104 (Regular Classroom)							
<u> </u>	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	21	LF	7	10+ years		
	Ceiling - Exposed	1st Floor	692	SF	7	10+ years		
	Ceiling - Splined	1st Floor	50	SF	7	10+ years		
	Doors - Side-lite	1st Floor	32	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	742	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	8	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	944	SF	7	10+ years		
01	#400 (D							
_Classroc	m #106 (Regular Classroom)	4 . 🖯	<u> </u>			0.40		
	AC Units	1st Floor	1	EA	7	6-10 years		





Catego	ry : Classroom		B	uilding	: Main		-
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	43	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	1,026	SF	7	10+ years	
	Ceiling - Splined	1st Floor	149	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,175	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,172	SF	7	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	692	SF	7	10+ years	
	Ceiling - Splined	1st Floor	50	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	737	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	944	SF	7	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	692	SF	7	10+ years	
	Ceiling - Splined	1st Floor	50	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	742	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	944	SF	7	10+ years	
Classroo	om #109 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	1,044	SF	7	10+ years	
	Ceiling - Splined	1st Floor	69	SF	7	10+ years	
		-				,	

Campus Name: Cather Page : 18 of 32 Assessment Date: 03/05/2024





Catego	ry : Classroom		В	uilding	: Main		asimigion boole vard, Chicago, il 60612
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Store Front	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,098	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	ĒΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	1,104	SF	7	10+ years	
	Work Sink	1st Floor	2	EΑ	7	10+ years	
Classroo	om #110 (Store Room)						
Oldooroc	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Casework Ceiling - Exposed	1st Floor	692	SF	7	•	
	Ceiling - Exposed Ceiling - Splined	1st Floor	50	SF	7	10+ years 10+ years	
	Doors - Side-lite	1st Floor	32	SF SF		•	
					7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	742	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	944	SF	7	10+ years	
Classroo	om #111 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	1,034	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	79	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Store Front	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,107	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	10+ years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,104	SF	7	10+ years	
	Work Sink	1st Floor	2	EΑ	7	10+ years	
Classroo	om #112 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	692	SF	7	10+ years	
	Ceiling - Exposed Ceiling - Plaster/Drywall	1st Floor	50	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	725	SF	7		
	FIOOI - THE	151 11001	725	SF	1	10+ years	

Campus Name: Cather Page: 19 of 32 Assessment Date: 03/05/2024





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	1st Floor	25	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	ŭ
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	944	SF	7	10+ years	
Classroo	om #113 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	692	SF	7	10+ years	
	Ceiling - Splined	1st Floor	50	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	742	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7		
						6-10 years	
	Storage/ Closet Walls - Concrete Block	1st Floor 1st Floor	8	SF SF	7	10+ years	
	vvalis - Concrete Block	TST FIOOT	944	SF	7	10+ years	
Classroo	om #114 (Other Instructional Use)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	692	SF	7	10+ years	
	Ceiling - Splined	1st Floor	50	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	742	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	944	SF	7	10+ years	
Classroo	om #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Exposed	1st Floor	742	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	742	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	944	SF	7	10+ years	
	Walls Colloide Block	13(1100)	344	Oi.	,	10+ years	

Campus Name: Cather Page : 20 of 32 Assessment Date: 03/05/2024





Category : Classroom			Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Classroo	m #201 (Art Room)								
	Casework	2nd Floor	67	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	1,356	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	20	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years			
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	Not observed		
	Floor - Terrazzo	2nd Floor	1,356	SF	7	10+ years			
	Gas Line	2nd Floor	7	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Science Lab Fume Hood	2nd Floor	1	EA	6	6-10 years			
	Science Lab Shower	2nd Floor	1	EA	7	10+ years			
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	Locked		
	Walls - Concrete Block	2nd Floor	590	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	590	SF	7	10+ years			
	Work Sink	2nd Floor	7	EA	7	10+ years			
						·			
Classroo	m #203 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	9	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	529	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	2nd Floor	529	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	Lock		
	Walls - Concrete Block	2nd Floor	802	SF	7	10+ years	2001		
	Walls Colloid Blook	2110 1 1001	002	O.	•	Tot youro			
Classroo	m #204 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	16	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	760	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	754	SF	7	10+ years			
	Floor - Tile	2nd Floor	6	SF	5	1-2 years	Chips		
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	Simpo		
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	Locked		
	Walls - Concrete Block	2nd Floor	928	SF	7	10+ years	Lookou		
	vvalio - Condicid Dioon	2110 1 1001	920	Ji	,	TOT years			

Campus Name: Cather Page : 21 of 32 Assessment Date: 03/05/2024





Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #205 (Regular Classroom)					_	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	21	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	7	10+ years	
	Floor - Tile	2nd Floor	5	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	Damagod
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor		SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	944	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
	Work on ik	2110 1 1001		L/\	•	101 years	
Classroo	om #206 (Other Instructional Use)						
Classiuc	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Hardware	2nd Floor	1	EA	6	1-2 years	Hardware missing - hole
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	Hardware missing - note
	Doors - Steel Doors incl hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor 2nd Floor	944	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor 2nd Floor	250	SF	7	10+ years	
	Walls - Wetal Fallel	2110 1-1001	230	SF	,	10+ years	
Classroo	om #207 (Regular Classroom)						
Classiuc	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	746	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	4	SF	5	1-2 years	Water damage
	Doors - Side-lite	2nd Floor 2nd Floor	10	SF	7	•	water damage
	Doors - Steel Doors incl hw	2nd Floor		EA	7	10+ years	
			1	SF		10+ years	
	Floor - Tile	2nd Floor 2nd Floor	750		7	10+ years	
	Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor	20 12	EA LF	7 7	6-10 years	
				SF		6-10 years	
	Storage/ Closet	2nd Floor	8	SF SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	940		7	10+ years	
	Walls - Concrete Block	2nd Floor	4	SF SF	6	6-10 years	
	Walls - Metal Panel	2nd Floor	250	21	7	10+ years	





Category : Classroom		В	uilding				
			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroor	n #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	Lock
	Walls - Concrete Block	2nd Floor	944	SF	7	10+ years	
Classroor	m #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	944	SF	7	10+ years	
01	!!O40 (Ot - - -						
Classroor	m #210 (Computer Lab)	0 15				0.10	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	685	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	685	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	210	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	867	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroor	m #211 (Faculty Lounge)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Hardware	2nd Floor	1	EA	6	6-10 years	Hardware in good condition
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	•
	Floor - Tile	2nd Floor	750	SF	7	10+ years	

Campus Name: Cather Page : 23 of 32 Assessment Date: 03/05/2024





Category : Classroom		В	uilding	: Main				
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	8	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	944	SF	7	10+ years		
lassroo	m #212 (Store Room)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	37	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	750	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	20	ĒΑ	7	6-10 years		
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	Locked	
	Walls - Concrete Block	2nd Floor	944	SF	6	10+ years	No wall damage observed	
			•	•		.o. yea.e	no nan damage essented	
lassroo	m #213 (Regular Classroom)	0.4 51	4			0.40		
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	18	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	742	SF	7	10+ years	_	
	Floor - Tile	2nd Floor	8	SF	5	1-2 years	Damaged	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	8	SF	7	6-10 years	Locked	
	Walls - Concrete Block	2nd Floor	944	SF	7	10+ years		
lassroo	m #214 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	17	LF	7	10+ years		
	Casework	2nd Floor	1	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	750	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	8	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor 2nd Floor	944	SF	7	10+ years		
	Trails Colloide Block	2110 1 1001	344	01	,	TOT years		
assroo	m #215 (Other Instructional Use)							

Campus Name: Cather Page : 24 of 32 Assessment Date: 03/05/2024





Catego	ry : Classroom		В	uilding	: Main		, , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	760	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	760	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	928	SF	7	10+ years	
_Classroo	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	Locked
	Walls - Concrete Block	2nd Floor	844	SF	7	10+ years	Looked
Classroo	om #217 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	38	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Hardware	2nd Floor	1	EA	7	6-10 years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Loose cover
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	Loose cover
	Walls - Concrete Block	2nd Floor	671	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	250	SF	7	10+ years	
		2nd Floor		EA	7	,	
	Work Sink	2110 F1001	3	EA	1	10+ years	
_Classroo	om #218 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	

Campus Name: Cather Page : 25 of 32 Assessment Date: 03/05/2024





Catego	ry : Classroom		B	uilding	: Main		
				_		Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	671	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	250	SF	7	10+ years	
Classroo	m #219 (Regular Classroom)						
21000100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework		16	LF	7	•	
		2nd Floor				10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	756	SF	7	10+ years	NA
	Ceiling - Plaster/Drywall	2nd Floor	4	SF	5	1-2 years	Water damage
	Doors - Hardware	2nd Floor	1	EA	7	6-10 years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	760	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	928	SF	7	10+ years	
:lassroo	m #220 (Regular Classroom)						
ZICICOT CC	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	760	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	756	SF	7	10+ years	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Chips
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	10+ years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	928	SF	7	10+ years	
atego	ry : Interior		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Splined	1st Floor East Corridor	2,440	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor East Corridor	2	ĒΑ	7	10+ years	
			_				
	Doors - Store Front	1st Floor East Corridor	8	EA	7	10+ years	

Campus Name: Cather Page : 26 of 32 Assessment Date: 03/05/2024





Category : Interior

Building : Main

Catego	ry : Interior		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile/Sheet	1st Floor East Corridor	2,440	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor East Corridor	19	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor East Corridor	3,275	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor East Corridor	140	SF	7	10+ years		
	Ceiling - Splined	1st Floor North	1,433	SF	7	10+ years		
	Ceiling - Splined	1st Floor North	5	SF	4	1-2 years	Damaged tiles	
	Doors - Steel Doors incl hw	1st Floor North	2	EA	7	10+ years	3	
	Doors - Store Front	1st Floor North	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor North	1,443	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor North	10	EA	7	6-10 years		
	Student Lockers - One Tier	1st Floor North	1	EΑ	7	10+ years		
	Student Lockers - Two Tiers	1st Floor North	9	EA	7	10+ years		
	Walls - Concrete Block	1st Floor North	2,089	SF	7	10+ years		
	Ceiling - Splined	1st Floor South	1,543	SF	7	10+ years		
	Ceiling - Splined	1st Floor South	10	SF	4	0-1 year	Damaged tiles	
	Doors - Steel Doors incl hw	1st Floor South	2	ĒΑ	7	10+ years	g	
	Floor - Tile/Sheet	1st Floor South	1,563	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor South	11	ĒΑ	7	6-10 years		
	Walls - Concrete Block	1st Floor South	2,089	SF	7	10+ years		
	Ceiling - Splined	1st Floor West Corridor	895	SF	7	10+ years		
	Drinking Fountains - Single Fountain	1st Floor West Corridor	1	ĒΑ	7	10+ years		
	Drinking Fountains - Single Fountain	1st Floor West Corridor	1	EA	5	1-2 years	Fountain not working	
	Floor - Tile/Sheet	1st Floor West Corridor	900	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor West Corridor	5	ĒΑ	7	6-10 years		
	Walls - Concrete Block	1st Floor West Corridor	1,140	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor West Corridor	140	SF	7	10+ years		
	Ceiling - Splined	2nd Floor East Corridor	1,350	SF	7	10+ years		
	Ceiling - Splined	2nd Floor East Corridor	5	SF	4	0-1 year	Damaged	
	Drinking Fountains - Single Fountain	2nd Floor East Corridor	1	ĒΑ	7	10+ years	3.0	
	Floor - Tile/Sheet	2nd Floor East Corridor	1,360	SF	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor East Corridor	11	ĒΑ	7	6-10 years		
	Student Lockers - One Tier	2nd Floor East Corridor	1	EA	7	10+ years		
	Student Lockers - Two Tiers	2nd Floor East Corridor	21	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor East Corridor	1,400	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor East Corridor	96	SF	7	10+ years		
	Ceiling - Splined	2nd Floor North Corridor	1,580	SF	7	10+ years		
	Ceiling - Splined	2nd Floor North Corridor	3	SF	5	1-2 years	Loose tiles	
	Floor - Tile/Sheet	2nd Floor North Corridor	1,583	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor North Corridor	11	ĒΑ	7	6-10 years		
	Student Lockers - Two Tiers	2nd Floor North Corridor	80	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor North Corridor	2,089	SF	7	10+ years		
	Ceiling - Splined	2nd Floor South Corridor	1,563	SF	7	10+ years		
	Floor - Tile/Sheet	2nd Floor South Corridor	1,563	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor South Corridor	11	EA	7	6-10 years		
			• •		•	3 .0 ,00.0		

Campus Name: Cather Page : 27 of 32 Assessment Date: 03/05/2024





Catego	Category : Interior		Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Student Lockers - Two Tiers	2nd Floor South Corridor	67	EΑ	7	10+ years				
	Walls - Concrete Block	2nd Floor South Corridor	2,089	SF	7	10+ years				
	Ceiling - Splined	2nd Floor West Corridor	870	SF	7	10+ years				
	Ceiling - Splined	2nd Floor West Corridor	7	SF	4	1-2 years	Damaged and loose tiles			
	Drinking Fountains - Single Fountain	2nd Floor West Corridor	2	EA	7	10+ years				
	Floor - Tile/Sheet	2nd Floor West Corridor	877	SF	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor West Corridor	5	EA	7	6-10 years				
	Student Lockers - One Tier	2nd Floor West Corridor	4	EΑ	7	10+ years				
	Student Lockers - Two Tiers	2nd Floor West Corridor	50	EA	7	10+ years				
	Walls - Concrete Block	2nd Floor West Corridor	1,280	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	2nd Floor West Corridor	140	SF	7	10+ years				
Safety										
,	Camera Viewing Station	1st Floor	2	EA	7	6-10 years				
	Metal Detector	1st Floor	3	EΑ	7	6-10 years				
	Security Cameras	1st Floor	18	EΑ	7	6-10 years				
	Security Cameras	1st Floor	1	EA	7	6-10 years				
Stairs										
	Ceiling - Splined	North East	160	SF	7	10+ years				
	Floor - Terrazzo	North East	55	SF	7	10+ years				
	Floor - Terrazzo	North East	5	SF	5	1-2 years	Cracks			
	Floor - Tile	North East	140	SF	7	10+ years				
	Handrails	North East	90	LF	7	10+ years				
	Lighting - Pendent/Surface	North East	2	EA	7	6-10 years				
	Stairs - Terrazzo	North East	90	LF	7	10+ years				
	Walls - Concrete Block	North East	626	SF	7	6-10 years				
	Ceiling - Splined	North West	160	SF	7	10+ years				
	Floor - Terrazzo	North West	37	SF	7	10+ years				
	Floor - Terrazzo	North West	3	SF	5	1-2 years	Cracked			
	Floor - Tile	North West	136	SF	7	10+ years				
	Handrails	North West	44	LF	7	10+ years				
	Lighting - Pendent/Surface	North West	2	EA	7	6-10 years				
	Stairs - Terrazzo	North West	90	LF	7	10+ years				
	Walls - Concrete Block	North West	706	SF	7	10+ years				
	Ceiling - Splined	South East	160	SF	7	10+ years				
	Floor - Terrazzo	South East	60	SF	7	10+ years				
	Floor - Tile	South East	140	SF	7	10+ years				
	Handrails	South East	44	LF	7	10+ years				
	Lighting - Pendent/Surface	South East	2	EA	7	6-10 years				
	Stairs - Terrazzo	South East	90	LF	7	10+ years				
	Walls - Concrete Block	South East	626	SF	7	10+ years				
	Ceiling - Splined	South West	160	SF	7	10+ years				
	Floor - Terrazzo	South West	40	SF	7	10+ years				

Campus Name: Cather Page : 28 of 32 Assessment Date: 03/05/2024



Catego	ry : Interior		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile	South West	136	SF	7	10+ years				
	Handrails	South West	44	LF	7	10+ years				
	Lighting - Pendent/Surface	South West	2	EA	7	6-10 years				
	Stairs - Terrazzo	South West	90	LF	7	10+ years				
	Walls - Concrete Block	South West	706	SF	7	10+ years				
<u>Vertical</u>	Conveyance									
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years				

Campus Name: Cather Page : 29 of 32 Assessment Date: 03/05/2024



Category : Site Building : Site

Category : Site			Building : Site							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Athletic										
	Surface - Asphalt	Athletic Track	4,005	SF	6	10+ years				
	Surface - Asphalt Surface - Synthetic	Athletic Turf Field - North	11,091	SF	7	6-10 years				
		Basketball - Northwest		EA	6	10+ years				
	Lighting		3		-		Dualian			
	Lighting	Basketball - Northwest	1	EA	4	0-1 year	Broken			
	Surface - Asphalt	Basketball - Northwest	6,120	SF	6	10+ years				
Civil/Dra	inage									
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	7	10+ years	Fixed			
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	10+ years				
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	6	10+ years				
	o Dramage one manner		·		· ·	. o v y cano				
Fencing										
	Fencing - Chain Link	Entire Site	235	LF	6	10+ years				
	Fencing - Chain Link	Entire Site	332	LF	4	0-1 year	Missing			
	Fencing - New Standard Ornamental	Entire Site	934	LF	6	10+ years				
	Fencing - New Standard Ornamental	Entire Site	20	LF	4	1-2 years	Bent			
1 1										
Landsca		F .: 0':				4.0				
	Benches	Entire Site	1	EA	6	10+ years				
	Landscape - Grass	Entire Site	17,489	SF	6	10+ years				
	Landscape - Hardscape- Concrete	Entire Site	1,942	SF	6	10+ years				
	Landscape - Hardscape- Concrete	Entire Site	200	SF	5	1-2 years	Spalling/cracking. Quantity changed to match current observations			
	Lighting - Pole Mounted	Entire Site	11	EA	6	6-10 years	to materi current observations			
	Parkway trees	Entire Site	14	EA	6	10+ years				
	Parkway trees	Entire Site	1	EA	4	1-2 years	Missing			
	Planting Beds/ Area	Entire Site	900	SF	6	10+ years	Missing			
		Entire Site	120	SF	6	10+ years				
	Retaining Wall - Masonry			Sr EA	6					
	Trash Receptacles	Entire Site	8	EA	6	10+ years				
Parking I	_ot									
	Concrete Curbs	North East	428	LF	6	10+ years				
	Concrete Curbs	North East	5	LF	6	1-2 years	Broken			
	Interior Plantings	North East	17	LF	6	10+ years				
	Lighting - Pole Mounted	North East	2	ĒΑ	6	10+ years				
	Surface - Asphalt	North East	8,402	SF	6	6-10 years				
	Surface - Asphalt	North East	2,200	SF	4	1-2 years	Cracking/potholes. Quantity changed			
	·		·			•	to match current observations			
	Surface - Concrete	North East	650	SF	6	10+ years				
	Surface - Concrete	North East	100	SF	5	1-2 years	Cracking			
	Trash Compactor	North East	1	EA	6	10+ years	•			
	·					-				

Campus Name: Cather Page : 30 of 32 Assessment Date: 03/05/2024



Willa Cather Elementary School

2908 W Washington BOULEVARD, Chicago, IL 60612

Catego	Category : Site			uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Trash Enclosure - Chain Links	North East	117	SF	6	10+ years	
_Playgrou	ınd						
	Equipment - Pre K 3-5	Central Courtyard	1	EA	6	10+ years	
	Surface - Poured Surface	Central Courtyard	2,400	SF	6	6-10 years	
	Equipment - School Age 5-12	North	1	EΑ	6	10+ years	
	Equipment - Swingset	North	1	EA	6	10+ years	
	Surface - Poured Surface	North	2,496	SF	6	2-5 years	
Sidewalk	KS.						
	Sidewalks - Perimeter Sidewalks	Entire Site	14,500	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	800	SF	4	0-1 year	Cracking/uneven
_Signage							
0 0	Flag Pole - Flag Pole	South	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	South	1	EA	6	10+ years	Changed to match current observations
	Monument - Building Mounted Cut Letter Sign	South	1	EA	4	0-1 year	Missing letter.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Cather Page : 31 of 32 Assessment Date: 03/05/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classicom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Science	2nd Floor	201	201	1,356	230	44	N	Υ
Computer Lab	Computer Lab	2nd Floor	210	210	685	138	22	N	N
Faculty Lounge	Regular Classroom	2nd Floor	211	210	750	88	11	N	N
Kindergarten	Kindergarten	1st Floor	109	109	1,113	115	35	Υ	Υ
Other Instructional Use	Regular Classroom	1st Floor	114	114	750	115	22	N	N
Other Instructional Use	Regular Classroom	2nd Floor	206	206	750	92	12	N	Υ
Other Instructional Use	Regular Classroom	2nd Floor	215	215	760	138	22	Υ	N
Other Instructional Use	Science	2nd Floor	217	216	750	115	22	N	N
Pre School	Pre School	1st Floor	111	111	1,113	115	35	N	Υ
Regular Classroom	Office	2nd Floor	213	212	750	115	22	N	Υ
Regular Classroom	Office	2nd Floor	214	213	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	112	112	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	113	113	750	115	22	N	Υ
Regular Classroom	Regular Classroom	1st Floor	115	115	750	115	22	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	529	80	12	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	760	138	22	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	750	92	12	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	750	92	12	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	750	92	13	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	750	92	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	216	215	750	115	22	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	218	217	750	115	22	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	219	219	760	138	22	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	220	220	760	138	22	N	Υ
Regular Classroom	Science	1st Floor	106	106	1,175	147	44	N	Υ
Store Room	Regular Classroom	1st Floor	110	110	750	115	22	N	N
Store Room	Regular Classroom	2nd Floor	212	211	750	115	22	N	N