



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main (Urban Prep)	1906	3	110,540
Annex (Chicago Academy Advanced Tech)	1959	2	48,600
Campus Total			159,140

Category : Exterior Building : Main (Urban Prep)

Category . Exterior			Building . Main (Orban Frep)						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance	<u>,</u>		Ī			_			
	Entrance Control - Audio and Video	#1 S	1	EA	6	6-10 years			
	Exterior Doors - Exterior FRP Door	#1 S	4	EA	6	10+ years			
	Exterior Doors - Transom Lite	#1 S	2	EA	6	10+ years			
	Exterior Stairs - Concrete	#1 S	30	LF	6	10+ years			
	Power Door Operator and Controls	#1 S	2	EA	7	6-10 years			
	Ramp Handrail - Steel_Ramp Handrail	#1 S	30	LF	6	10+ years			
	Ramps - Concrete	#1 S	15	LF	6	10+ years			
	Stair Handrail - Steel_Stair Handrail	#1 S	6	LF	6	6-10 years			
	Exterior Doors - Exterior FRP Door	#10 Exit E	2	EΑ	6	10+ years			
	Exterior Doors - Transom Lite	#10 Exit E	1	EΑ	6	10+ years			
	Exterior Doors - Exterior Steel Door	#11 Exit S	1	EA	6	10+ years			
	Exterior Doors - Transom Lite	#11 Exit S	1	EA	6	10+ years			
	Exterior Stairs - Concrete	#11 Exit S	3	LF	6	10+ years			
	Exterior Doors - Exterior FRP Door	#12 S	4	EA	6	10+ years			
	Exterior Doors - Transom Lite	#12 S	2	EA	6	10+ years			
	Exterior Doors - Exterior Wood Door	#13 Roof Door	1	EA	4	0-1 year	No hardware, misaligned		
	Exterior Doors - Exterior FRP Door	#2 Exit S	1	EA	6	10+ years			
	Exterior Doors - Transom Lite	#2 Exit S	1	EA	6	10+ years			
	Exterior Stairs - Concrete	#2 Exit S	3	LF	6	10+ years			
	Entrance Control - Audio and Video	#3 S	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	#3 S	5	EA	6	10+ years			
	Exterior Doors - Transom Lite	#3 S	2	EA	6	10+ years			
	Exterior Stairs - Concrete	#3 S	15	LF	7	10+ years			



: Exterior				•	Urban Prep)	
					Recommend	
	Location	Quantity	UOM	Rank	Replacement	Comments
Power Door Operator and Controls	#3 S	1	EΑ	7	6-10 years	
Ramp Handrail - Steel_Ramp Handrail	#3 S	24	LF	6	10+ years	
Ramps - Concrete	#3 S	12	LF	6	10+ years	
Exterior Doors - Exterior FRP Door	#4 Exit N	1	EΑ	6	10+ years	
Exterior Doors - Exterior Steel Door	#5 N	2	EA	6	10+ years	
Exterior Doors - Exterior Steel Door	#6 N	1	EA	6	10+ years	
Exterior Doors - Transom Lite	#6 N	1	EΑ	6	10+ years	
Exterior Doors - Exterior Steel Door	#6.5 N	2	EΑ	6	10+ years	
Exterior Doors - Exterior Steel Door	#7 N	1	EA	6	10+ years	
Exterior Doors - Exterior Steel Door	#8 N	1	EA	5		
Exterior Doors - Exterior FRP Door		2	EA	6	10+ years	
Exterior Doors - Transom Lite		1	EA	6	10+ years	
Exterior Doors - Exterior Steel Door	Fire Escape	5	EA	6	10+ years	
e						
	West and North Facades	3	EA	7	10+ vears	
	West and North Facades					
•			LF	4	•	Several anchors and supports
		–		•	· , , · · · ·	broken, heavily corroded
Paints	West and North Facades	224	LF	3	0-1 year	Chipping, corrosion throughout
1						
	Entire Building	1.050	LF	7	10+ vears	
	•					Settling, cracking
						Comming, or actually
						Erosion of walls, cracking
Superstructure - Heavy Timber	Entire Building	110,540	SF	7	10+ years	g
Exterior Lighting - Parapet or Roof Mounted	Entire Building	11	EA	6	6-10 years	
	Entire Building	13	EA	6	6-10 years	
Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	6-10 years	
em						
Coping - Clay Tile	East Low Roof	115	LF	6	10+ years	
	East Low Roof	65	LF	6	10+ years	
Parapet - Parapet < 16" Height	East Low Roof	115	LF	6	10+ years	
Roof - Asphalt Gravel Ballast	East Low Roof	2,205	SF	4	0-1 year	Poor drainage, plant growth
Roof - Modified Bitumen	East Low Roof	120	SF	6	10+ years	3 3
Roof Structure - Heavy Timber	East Low Roof	2,325	SF	7	10+ years	
Access Ladder - Metal	East Roof	1	ĒΑ	4	0-1 year	No handrail, dangerous access
Coping - Clay Tile	East Roof	316	LF	6	10+ years	.
EEEEEEE GEEFF OFFFS EEEE GOFFFS	Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Exterior FRP Door Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Doors - Exterior Steel Door Exterior Escape Foundation - Concrete Foundation - Masonry Foundation - Masonry Foundation - Heavy Timber Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Wall Mounted	Exterior Doors - Exterior Steel Door #6 N Exterior Doors - Exterior Steel Door #6.5 N Exterior Doors - Exterior Steel Door #6.5 N Exterior Doors - Exterior Steel Door #7 N Exterior Doors - Exterior Steel Door #8 N Exterior Doors - Exterior FRP Door #9 E Exterior Doors - Exterior Steel Door #9 E Exterior Doors - Exterior Steel Door #9 E Exterior Doors - Exterior Steel Door Fire Escape Exterior Doors - Exterior Steel Door West and North Facades Exterior Doors - Exterior Steel Door West and North Facades Exterior Doors - Exterior Steel Door West and North Facades Fire Escape West and North Facades Fire Escape West and North Facades Fire Escape West and North Facades Foundation - Concrete Entire Building Foundation - Concrete Entire Building Foundation - Masonry Entire Building Foundation - Masonry Entire Building Exterior Lighting - Parapet or Roof Mounted Entire Building Exterior Lighting - Wall Mounted Ent	Exterior Doors - Exterior Steel Door #6 N 1 Exterior Doors - Transom Lite #6 N 1 Exterior Doors - Exterior Steel Door #6.5 N 2 Exterior Doors - Exterior Steel Door #6.5 N 2 Exterior Doors - Exterior Steel Door #7 N 1 Exterior Doors - Exterior Steel Door #8 N 1 Exterior Doors - Exterior Steel Door #9 E 2 Exterior Doors - Exterior Steel Door #9 E 1 Exterior Doors - Exterior Steel Door #9 E 1 Exterior Doors - Exterior Steel Door #9 E 1 Exterior Doors - Exterior Steel Door #9 E 1 Exterior Doors - Exterior Steel Door #9 E 1 Exterior Doors - Exterior Steel Door West and North Facades 2 Exterior Doors - Exterior Steel Door West and North Facades 112 Exterior Doors - Exterior Steel Door West and North Facades 112 Exterior Doors - Exterior Steel Door West and North Facades 112 Exterior Doors - Exterior Steel Door West and North Facades 112 Exterior Doors - Exterior Steel Door West and North Facades 112 Exterior Doors - Exterior Steel Door West and North Facades 112 Exterior Doors - Exterior Steel Door West and North Facades 112 Exterior Lighting - Concrete Entire Building 1,050 Exterior Lighting - Wall Mounted Entire Building 40 Exterior Lighting - Parapet or Roof Mounted Entire Building 110,540 Exterior Lighting - Wall Mounted Entire Building 11 Exterior Lighting - Wall Mounted Entire Building 13 Exterior Lighting - Wall Mounted Entire Building 14 Exterior Lighting - Wall Mounted Entire Building 13 Exterior Lighting - Wall Mounted Entire Building 14 Exterior Lighting - Wall Mounted Entire Building 13 Exterior Lighting - Wall Mounted Entire Building 13 Exterior Lighting - Wall Mounted Entire Building 14 Exterior Lighting - Wall Mounted Entire Building 14 Exterior Lighting - Wall Mounted Entire Building 15 Exterior Lighting - Wall Mounted Entire Building 15 Ext	Exterior Doors - Exterior Steel Door	Exterior Doors - Exterior Steel Door	Exterior Doors - Exterior Steel Door

Campus Name: Medill Page : 2 of 57 Assessment Date: 08/14/2023



jor	y : Exterior		В	uliaing	. wain (Urban Prep)	
	Itam Tuna	Location	Overetie	LICA	Dank	Recommend	Comments
)	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	East Roof	210	LF	6	10+ years	
	Parapet - 16" - 30" Height	East Roof	158	LF	6	10+ years	
	Parapet - Parapet > 30"	East Roof	158	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	East Roof	5,765	SF	6	6-10 years	
	Roof Hatch - Metal	East Roof	1	EA	3	0-1 year	Not used
	Roof Structure - Heavy Timber	East Roof	5,765	SF	7	10+ years	
	Access Ladder - Wood	Main Roof	1	EA	4	0-1 year	Ladder uneven, broken
	Access Ladder - Wood	Main Roof	1	EΑ	4	1-2 years	Ladder unstable
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	8	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	50	LF	6	10+ years	
	Chimney - Metal Flue	Main Roof	6	LF	6	10+ years	
	Coping - Terra Cotta	Main Roof	360	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	220	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	267	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	3	LF	5	10+ years	
	Parapet - Parapet > 30"	Main Roof	90	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Main Roof	7,064	SF	6	6-10 years	
	Roof - Modified Bitumen	Main Roof	900	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	4	0-1 year	Hatch not aligned with ladder
		Main Roof		SF	7	•	riateri not aligned with ladder
	Roof Structure - Heavy Timber	West Low Roof	7,964	SF LF		10+ years	
	Coping - Stone		180 60	LF LF	6	10+ years	
	Coping - Terra Cotta	West Low Roof		LF LF	6	10+ years	
	Downspouts - Exterior Downspouts	West Low Roof	105		6	10+ years	
	Downspouts - Interior Downspouts	West Low Roof	16	LF	6	10+ years	
	Parapet - 16" - 30" Height	West Low Roof	240	LF	6	10+ years	Diameter and the second second
	Roof - Asphalt Gravel Ballast	West Low Roof	2,079	SF	4	1-2 years	Plant growth, cracking
	Roof - Modified Bitumen	West Low Roof	1,850	SF	5	2-5 years	
	Roof Structure - Heavy Timber	West Low Roof	3,929	SF	7	10+ years	
	Access Ladder - Wood	West Roof	1	EA	4	0-1 year	Loose
	Coping - Stone	West Roof	250	LF	7	10+ years	
	Coping - Terra Cotta	West Roof	125	LF	7	10+ years	
	Coping - Terra Cotta	West Roof	125	LF	7	10+ years	
	Downspouts - Exterior Downspouts	West Roof	220	LF	6	10+ years	
	Parapet - 16" - 30" Height	West Roof	500	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	West Roof	6,764	SF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	West Roof	4,357	SF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	West Roof	200	SF	4	1-2 years	Leaks
	Roof - Modified Bitumen	West Roof	1,500	SF	6	10+ years	-
	Roof Hatch - Wood	West Roof	1	EA	3	0-1 year	Not used
	Roof Structure - Heavy Timber	West Roof	12,821	SF	7	10+ years	
	I motor		12,021	<u> </u>	•	. o . youro	

Campus Name: Medill Page : 3 of 57 Assessment Date: 08/14/2023



Chicago Technology Academy High School

Catego	ry : Exterior	_	B	uildina	· Main (Urban Prep)	_
Outogo	Ty Laterior			ananig		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Cornice - Metal Projecting	Entire Building	1,720	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	40,000	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	4,000	SF	4	0-1 year	Severe efflorescence on interior
	Exterior Walls - Brick	Entire Building	350	SF	4	1-2 years	Wall is bowing
	Exterior Walls - Stone-Cast	Entire Building	8,278	SF	6	10+ years	3
	Exterior Walls - Terra Cotta	Entire Building	800	SF	6	10+ years	
Windows	S						
	Guard - Guards wire guard	Entire Building	3,580	SF	6	10+ years	
	Lintels - Brick	Entire Building	450	LF	6	10+ years	
	Lintels - Steel	Entire Building	565	LF	6	10+ years	
	Lintels - Stone	Entire Building	150	LF	6	10+ years	
	Windows - Louver	Entire Building	20	SF	5	2-5 years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,580	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,820	SF	5	2-5 years	
	Windows - Sash Lexan	Entire Building	280	SF	6	10+ years	
	Windows - Wood- Single-pane	Entire Building	104	SF	5	2-5 years	
Catego	ry : Electrical		В	uilding	: Main (Urban Prep)	
					•	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						

Category . Liectrical			Building . Main (Orban Frep)					
					Recommend			
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
cy System								
Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	ATS faults - breaker trips, loose connection, accumulation of dust		
Emergency A/C Power - Corridors and Stairs	Entire Building	18,620	SF	6	10+ years			
Emergency A/C Power - Gym	Entire Building	3,876	SF	6	10+ years			
Emergency A/C Power - Lunchrooms	Entire Building	3,142	SF	6	10+ years			
Emergency A/C Power - Multipurpose Room	Entire Building	3,661	SF	6	10+ years			
Emergency A/C Power - Students Toilets	Entire Building	1,919	SF	6	10+ years			
Emergency Battery Packs - Corridors and Stairs	Entire Building	72	EA	6	6-10 years			
Emergency Battery Packs - Gym	Entire Building	6	EA	6	6-10 years			
Emergency Battery Packs - Lunchrooms	Entire Building	13	EA	6	6-10 years			
Emergency Battery Packs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	Room 314: Ordered 60 battery back ups and waiting for delivery. It will be completed before school starts		
Emergency Battery Packs - Students Toilets	Entire Building	8	EA	6	6-10 years			
Security System - CCTV	Entire Building	110,540	SF	6	6-10 years			
Security System - Intrusion Detection	Entire Building	110,540	SF	6	6-10 years			
Exit Signs - Corridors and Stairs	Entire Building	33	EA	6	6-10 years			
Exit Signs - Gym	Entire Building	4	EA	6	6-10 years			
Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years			
	Item - Type cy System Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency A/C Power - Multipurpose Room Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency A/C Power - Hultipurpose Emergency A/C Power - Multipurpose Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Hunchrooms Emergency Battery Packs - Gym Emergency Battery Packs - Hunchrooms Emergency Battery Packs - Hunchrooms Emergency Battery Packs - Hunchrooms Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Entire Building Entire Building	Item - Type Cy System Automatic Transfer Switch Electrical Room 1 Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency A/C Power - Lunchrooms Emergency A/C Power - Multipurpose Entire Building 3,876 Emergency A/C Power - Multipurpose Entire Building 3,661 Room Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Entire Building Emergency Battery Packs - Gym Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Multipurpose Entire Building 6 Emergency Battery Packs - Multipurpose Entire Building 2 Emergency Battery Packs - Students Toilets Security System - CCTV Entire Building 8 Security System - Intrusion Detection Entire Building 110,540 Exit Signs - Corridors and Stairs Entire Building 3 Entire Building 4	Item - Type Location Quantity UOM cy System Automatic Transfer Switch Electrical Room 1 EA Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Entire Building 3,876 SF Emergency A/C Power - Lunchrooms Entire Building 3,142 SF Emergency A/C Power - Multipurpose Entire Building 3,661 SF Room Emergency A/C Power - Students Toilets Entire Building 1,919 SF Emergency Battery Packs - Corridors and Entire Building 72 EA Stairs Emergency Battery Packs - Gym Entire Building 72 EA Emergency Battery Packs - Lunchrooms Entire Building 13 EA Emergency Battery Packs - Multipurpose Entire Building 13 EA Emergency Battery Packs - Multipurpose Entire Building 13 EA Emergency Battery Packs - Students Toilets Entire Building 14 EA Security System - CCTV Entire Building 110,540 SF Exit Signs - Corridors and Stairs Entire Building 133 EA Exit Signs - Gym Entire Building 133 EA	Item - Type Location Quantity UOM Rank cy System Automatic Transfer Switch Electrical Room 1 EA 4 Emergency A/C Power - Corridors and Entire Building 18,620 SF 6 Stairs Emergency A/C Power - Gym Entire Building 3,876 SF 6 Emergency A/C Power - Lunchrooms Entire Building 3,142 SF 6 Emergency A/C Power - Multipurpose Entire Building 3,661 SF 6 Room Emergency A/C Power - Students Toilets Entire Building 1,919 SF 6 Emergency Battery Packs - Corridors and Entire Building 72 EA 6 Stairs Emergency Battery Packs - Gym Entire Building 72 EA 6 Emergency Battery Packs - Multipurpose Entire Building 13 EA 6 Emergency Battery Packs - Multipurpose Entire Building 13 EA 6 Emergency Battery Packs - Multipurpose Entire Building 10,540 SF 6 Security System - CCTV Entire Building 110,540 SF 6 Exercity System - Intrusion Detection Entire Building 110,540 SF 6 Exit Signs - Corridors and Stairs Entire Building 33 EA 6 Exit Signs - Gym Entire Building 33 EA 6	Item - Type		

Campus Name: Medill Page : 4 of 57 Assessment Date: 08/14/2023



Catego	ry : Electrical		В	uilding	: Main (Urban Prep)	
_				_	·	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 1600 A 277/480/3PH	Electrical Room	1	EA	7	10+ years	
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	110,540	SF	6	10+ years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building, Electrical Room, 2nd Floor, Basement	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building, Electrical Room, 2nd Floor, Basement	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building, Electrical Room, 2nd Floor, Basement	1	EA	4	1-2 years	Corrosion
	Lighting and Power Panels - Above 100 A	Entire Building, Electrical Room, 2nd Floor, Basement	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building, Electrical Room, 2nd Floor, Basement	10	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building, Electrical Room, 2nd Floor, Basement	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building, Electrical Room, 2nd Floor, Basement	18	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building, Electrical Room, 2nd Floor, Basement	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building, Electrical Room, 2nd Floor, Basement	2	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building, Electrical Room, 2nd Floor, Basement	2	EA	6	10+ years	

Category: Fire Protection

Building: Main (Urban Prep)

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarm						
Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
Fire Alarm Strobe Lights	Entire Building	110,540	SF	7	10+ years	
Fire Alarm_System	Entire Building	110,540	SF	7	10+ years	
Fire Pump Controller	Entire Building	1	EA	7	10+ years	



Category : Fire Protection			В	uilding	: Main (Urban Prep)	-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Pump Re	oom Assembly						
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	7	6-10 years	
	Jockey Pump	Mechanical Room	1	EΑ	5	2-5 years	Working better after packing
							replacement and valves
0 : 11	0.1						
Sprinkle	,						
	Combination Wet and Dry Sprinkler System	Entire Building	110,540	SF	4	2-5 years	Nothing has been done since last assessment
	Sprinkler Heads	Entire Building	110,540	SF	7	10+ years	
	Sprinkler Piping	Entire Building	110,540	SF	6	10+ years	
Catego	ry : Mechanical		В	uildina	· Main (Urban Prep)	
Guiogo	i y . iniconamical			unung	· Maiii (Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litionina						
	Heat Pump- Ceiling Mounted- Electric Heating & DX Cooling- Remote Mounted Compressor - Less than 3 tons	2nd Floor	1	EA	6	6-10 years	MDF room
	Condensing Unit- Roof Mounted - Less than 5 tons	Attic	1	EA	5	6-10 years	CU unit for MDF room (split system)
Air Hand	lling Systems						
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 45001 - 60000 cfm	Mechanical Room	1	EA	6	6-10 years	New belts had been replaced 06/2023
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 45001 - 60000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	50	LF	5	10+ years	
	Zone Dampers	Mechanical Room	42	EA	6	6-10 years	Steam traps are located in AHU 2 room
	Zone Dampers	Mechanical Room	42	EA	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	50	LF	5 5	6-10 years	
	and Ducts	Modifical Notifi	30	LI	3	J-10 years	
	Zone Dampers	Mechanical Room	16	EA	6	6-10 years	Steam traps are located in AHU 1 room
	Zone Dampers	Mechanical Room	16	EA	5	6-10 years	

Campus Name: Medill Page : 6 of 57 Assessment Date: 08/14/2023



Catego	ry : Mechanical		В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler S	ystems						
•	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	1	EA	5	6-10 years	
	Pressure Boiler - 101 - 150 HP						
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	1	EA	3	0-1 year	Boiler 1 needs parts for low water
	Pressure Boiler - 151 - 200 HP						cutoff. Not in proper working condition
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	7	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	Boiler 2 has three leaking tubes.
	Steam- Low Pressure Boiler - 101 - 150 HP						Requires repair and maintenance
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	
	Steam- Low Pressure Boiler - 151 - 200 HP					•	
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	5	6-10 years	
	Steam Traps	Boiler Room	60	EA	5	6-10 years	
	Vacuum Pump	Boiler Room	2	EA	6	6-10 years	
					•	5 10 , 5 5 11 5	
Heating	Devices						
	Cabinet Heaters - With Electric Coil	Basement	4	EA	5	6-10 years	
	Fin Tube - Steam	Basement	150	LF	5	2-5 years	
	Radiators - Steam	Basement	5	EA	5	6-10 years	
	Unit Heater - Electric	Basement, Boiler Room	1	EA	6	6-10 years	
	Unit Heater - Gas	Basement, Boiler Room	1	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	13	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	
-							
Tempera	ature Control DDC System	Entire Building	110 510	SF	7	10	Installed in 2022
			110,540	SF SF	7 6	10+ years	
	Electric Controls	Entire Building	3	SF	О	6-10 years	Controls had been observed in science labs 111, 211, 311 and gym
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	MDF room
	Thermostats - DDC	Entire Building	108	EA	6	6-10 years	WEI TOOM
	Thermostats DDO	Entire Building	100	L/\	O	o ro years	
Ventilation	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Basement, Roof, 3rd Floor	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Basement, Roof, 3rd Floor	5	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Basement, Roof, 3rd Floor	2	EA	5	0-1 year	Not in active use
	Exhaust Fans- Roof Mounted - 1501 - 8000	Basement, Roof, 3rd Floor	3	EA	6	6-10 years	
	CFM					•	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Basement, Roof, 3rd Floor	1	EA	6	6-10 years	
	CFM					•	
	Exhaust Fans- Roof Mounted - 500 - 1500	Basement, Roof, 3rd Floor	1	EA	7	6-10 years	

Campus Name: Medill Page : 7 of 57 Assessment Date: 08/14/2023



ALL I							1301 W 14th STREET, Chicago, IL 60608
Catego	ry : Mechanical		В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	CFM						
	Exhaust Fans- Roof Mounted - 500 - 1500	Basement, Roof, 3rd Floor	1	EA	7	6-10 years	
	CFM						
	Exhaust Fans- Roof Mounted - 500 - 1500	Basement, Roof, 3rd Floor	3	EA	6	6-10 years	
	CFM						
Catego	ry : Plumbing		В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate			•			•	
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	7	10+ years	
	Gas ricator 100000 500000 B10/rin	Wednamed Room	_	L/ \	,	101 years	
Dining							
<u>Piping</u>	Domostic Dining Hot Water Beturn Lines	Entire Building	110 510	OF.	e	2 5 1/22/2	
	Domestic Piping-Hot Water Return Lines	Entire Building	110,540	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	110,540	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	110,540	SF	6	2-5 years	
	Fixtures	Entire Building	110 510	C.E.	6	2 E vecro	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	110,540	SF	6	2-5 years	
	(Horizontal Lines)	Entire Duilding	440 540	C.E.	•	2.5.4.5.	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	110,540	SF	6	2-5 years	
	(Risers)	Entire Building	110 510	C.E.	6	2 E vecro	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	110,540	SF	6	2-5 years	
	(from Risers to Fixtures)	Entire Building	110 510	C.E.	6	6.10 , , , , , , , ,	
	Sanitary Piping	Entire Building	110,540	SF	6	6-10 years	
	Storm Piping	Entire Building	110,540	SF SF	6	6-10 years	
	Vent Piping	Entire Building	110,540	SF	6	6-10 years	
_							
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room, Basement	1	EA	6	6-10 years	
	Pumps - Sump-Duplex	Mechanical Room, Basement	1	EA	6	6-10 years	
_	_		_				
Catego	ry : Room		В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	003A- Kitchen Manager	65	SF	7	10+ years	
	Doors - Steel Doors incl hw	003A- Kitchen Manager	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	003A- Kitchen Manager	65	SF	7	6-10 years	
	Lighting - Pendent/Surface	003A- Kitchen Manager	1	EA	7	6-10 years	
	Power Distribution	003A- Kitchen Manager	6	EA	7	10+ years	
	Walls - Masonry	003A- Kitchen Manager	99	SF	7	10+ years	
	Walls - Plaster/Drywall	003A- Kitchen Manager	297	SF	6	10+ years	
	Ceiling - Plaster/Drywall	011A Gym office basement	104	SF	7	10+ years	
	•	•				·	
							A 1 D - 1 - 00/44/0000

Campus Name: Medill Page : 8 of 57 Assessment Date: 08/14/2023



Catego	ry : Room	-	В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	011A Gym office basement	1	EA	7	10+ years	
	Floor - Carpet	011A Gym office basement	104	SF	7	6-10 years	
	Lighting - Lay-in	011A Gym office basement	2	EA	7	6-10 years	
	Power Distribution	011A Gym office basement	4	EA	7	10+ years	
	Walls - Concrete Block	011A Gym office basement	104	SF	7	10+ years	
	Walls - Plaster/Drywall	011A Gym office basement	110	SF	7	10+ years	
	AC Unit	104A Conference/office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	104A Conference/office	195	SF	7	10+ years	
	Doors - Wood Doors inclu hw	104A Conference/office	1	EA	7	10+ years	
	Floor - Carpet	104A Conference/office	195	SF	7	6-10 years	
	Lighting - Pendent/Surface	104A Conference/office	4	EA	7	6-10 years	
	Power Distribution	104A Conference/office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	104A Conference/office	753	SF	7	10+ years	
	AC Unit	104b Workroom	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	104b Workroom	236	SF	7	10+ years	
	Doors - Wood Doors inclu hw	104b Workroom	1	EA	7	10+ years	
	Floor - Carpet	104b Workroom	236	SF	7	6-10 years	
	Lighting - Pendent/Surface	104b Workroom	4	EA	7	6-10 years	
	Power Distribution	104b Workroom	10	EA	7	10+ years	
	Walls - Plaster/Drywall	104b Workroom	890	SF	7	10+ years	
	Work SInk	104b Workroom	1	EA	7	6-10 years	
	AC Unit	1st Flr Main office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Flr Main office	630	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Flr Main office	2	EA	7	10+ years	
	Floor - Carpet	1st Flr Main office	630	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Flr Main office	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Flr Main office	1	EA	5	1-2 years	No fixture cover
	Power Distribution	1st Flr Main office	12	EA	7	10+ years	
	Storage/ Closet	1st Flr Main office	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Flr Main office	1,300	SF	7	10+ years	
	AC Unit	203	2	EA	7	6-10 years	
	Ceiling - Lay-in	203	370	SF	6	10+ years	
	Doors - Wood Doors inclu hw	203	2	EA	6	10+ years	
	Floor - Carpet	203	370	SF	6	6-10 years	
	Lighting - Lay-in	203	4	EA	6	6-10 years	
	Power Distribution	203	14	EA	7	10+ years	
	Walls - Plaster/Drywall	203	1,160	SF	6	10+ years	
	AC Unit	205		EA	7	6-10 years	
	Ceiling - Lay-in	205	370	SF	6	10+ years	
	Doors - Wood Doors inclu hw	205	2	ĒΑ	6	10+ years	
	Floor - Carpet	205	370	SF	6	6-10 years	
	Lighting - Lay-in	205	4	ĒΑ	6	6-10 years	
	Power Distribution	205	14	EA	7	10+ years	
	Walls - Plaster/Drywall	205	1,160	SF	6	10+ years	
			.,		-	, , , , , , , , , , , , , , , , , , , ,	



Category : Room			Building : Main (Urban Prep)					
_				_	·	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	AC Unit	207	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	207	280	SF	6	10+ years		
	Doors - Wood Doors inclu hw	207	1	EA	6	10+ years		
	Floor - Carpet	207	280	SF	6	6-10 years		
	Lighting - Pendent/Surface	207	5	EA	6	6-10 years		
	Power Distribution	207	3	EΑ	7	10+ years		
	Walls - Plaster/Drywall	207	837	SF	6	10+ years		
	Ceiling - Plaster/Drywall	216	465	SF	6	10+ years		
	Doors - Wood Doors inclu hw	216	1	EΑ	6	10+ years		
	Floor - Carpet	216	465	SF	6	6-10 years		
	Lighting - Pendent/Surface	216	5	EΑ	6	6-10 years		
	Power Distribution	216	12	EΑ	7	10+ years		
	Storage/ Closet	216	155	SF	7	6-10 years		
	Walls - Plaster/Drywall	216	1,242	SF	6	10+ years		
	Work SInk	216	1	EΑ	7	6-10 years		
	AC Unit	216A & 216B room	2	EΑ	7	6-10 years		
	Ceiling - Plaster/Drywall	216A & 216B room	280	SF	6	10+ years		
	Doors - Wood Doors inclu hw	216A & 216B room	2	EA	6	10+ years		
	Floor - Carpet	216A & 216B room	280	SF	6	6-10 years		
	Lighting - Pendent/Surface	216A & 216B room	8	EΑ	6	6-10 years		
	Power Distribution	216A & 216B room	20	EΑ	7	10+ years		
	Walls - Plaster/Drywall	216A & 216B room	1,176	SF	6	10+ years		
	AC Unit	218	4	EΑ	7	6-10 years		
	Ceiling - Plaster/Drywall	218	2,938	SF	6	10+ years		
	Doors - Wood Doors inclu hw	218	1	EΑ	6	10+ years		
	Floor - Carpet	218	2,938	SF	6	6-10 years		
	Lighting - Pendent/Surface	218	60	EΑ	6	6-10 years		
	Power Distribution	218	38	EΑ	7	10+ years		
	Storage/ Closet	218	51	SF	7	10+ years		
	Storage/ Closet	218	7	SF	7	10+ years		
	Walls - Plaster/Drywall	218	2,718	SF	6	10+ years		
	AC Unit	305	1	EA	7	2-5 years		
	Ceiling - Plaster/Drywall	305	280	SF	6	10+ years		
	Doors - Wood Doors inclu hw	305	1	EΑ	6	10+ years		
	Floor - Tile	305	280	SF	6	10+ years		
	Lighting - Pendent/Surface	305	5	EΑ	6	6-10 years		
	Power Distribution	305	4	EA	7	10+ years		
	Walls - Plaster/Drywall	305	925	SF	7	10+ years		
	AC Unit	307A Teacher's Lounge	1	EΑ	7	6-10 years		
	Ceiling - Plaster/Drywall	307A Teacher's Lounge	398	SF	6	10+ years		
	Doors - Wood Doors inclu hw	307A Teacher's Lounge	1	ĒΑ	6	10+ years		
	Floor - Tile	307A Teacher's Lounge	398	SF	6	10+ years		
	Lighting - Pendent/Surface	307A Teacher's Lounge	6	ĒΑ	6	6-10 years		
	Power Distribution	307A Teacher's Lounge	4	EA	7	10+ years		
						,		

Campus Name: Medill Page : 10 of 57 Assessment Date: 08/14/2023



Catego	ry : Room	-	В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	307A Teacher's Lounge	1,148	SF	6	10+ years	
	AC Unit	310A	1	EA	7	6-10 years	
	Ceiling - Exposed	310A	527	SF	7	10+ years	
	Doors - Wood Doors inclu hw	310A	1	EA	7	10+ years	
	Floor - Carpet	310A	527	SF	6	10+ years	
	Lighting - Pendent/Surface	310A	8	EA	7	6-10 years	
	Power Distribution	310A	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	310A	1,250	SF	7	10+ years	
	AC Unit	310B	1	EA	7	6-10 years	
	Ceiling - Exposed	310B	527	SF	7	10+ years	
	Doors - Wood Doors inclu hw	310B	1	EA	7	10+ years	
	Floor - Carpet	310B	527	SF	7	10+ years	
	Lighting - Pendent/Surface	310B	8	EA	7	6-10 years	
	Power Distribution	310B	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	310B	1,250	SF	7	10+ years	
	Ceiling - Plaster/Drywall	312 Counselor's Dept	315	SF	7	10+ years	
	Doors - Wood Doors inclu hw	312 Counselor's Dept	1	EA	7	10+ years	
	Floor - Tile	312 Counselor's Dept	315	SF	7	10+ years	
	Lighting - Pendent/Surface	312 Counselor's Dept	10	EA	6	6-10 years	
	Power Distribution	312 Counselor's Dept	20	EA	7	10+ years	
	Walls - Plaster/Drywall	312 Counselor's Dept	985	SF	7	10+ years	
	Ceiling - Plaster/Drywall	312A Office	198	SF	6	10+ years	
	Doors - Wood Doors inclu hw	312A Office	1	EA	6	10+ years	
	Floor - Carpet	312A Office	198	SF	6	6-10 years	
	Lighting - Pendent/Surface	312A Office	6	EA	6	6-10 years	
	Power Distribution	312A Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	312A Office	652	SF	6	10+ years	
	AC Unit	312B Office	1	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	312B Office	225	SF	7	10+ years	
	Doors - Wood Doors inclu hw	312B Office	1	EA	7	10+ years	
	Floor - Carpet	312B Office	225	SF	6	6-10 years	
	Lighting - Pendent/Surface	312B Office	8	EA	6	6-10 years	
	Power Distribution	312B Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	312B Office	882	SF	7	10+ years	
	Ceiling - Plaster/Drywall	312C & 312D workroom	244	SF	6	10+ years	
	Doors - Wood Doors inclu hw	312C & 312D workroom	2	EA	6	6-10 years	
	Floor - Tile	312C & 312D workroom	244	SF	7	10+ years	
	Lighting - Pendent/Surface	312C & 312D workroom	6	EA	6	6-10 years	
	Power Distribution	312C & 312D workroom	12	EA	7	10+ years	
	Walls - Plaster/Drywall	312C & 312D workroom	1,188	SF	7	10+ years	
	Work SInk	312C & 312D workroom	1	EΑ	7	10+ years	
	AC Unit	314	6	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	314	2,570	SF	6	10+ years	
	Doors - Wood Doors inclu hw	314	1	ĒΑ	7	10+ years	
		-	·	** *	-	- ,	

Campus Name: Medill Page : 11 of 57 Assessment Date: 08/14/2023



Catego	ry : Room		Building : Main (Urban Prep)						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	314	1	EA	7	10+ years			
	Floor - Carpet	314	2,570	SF	7	2-5 years			
	Lighting - Pendent/Surface	314	52	EA	7	6-10 years			
	Lighting - Pendent/Surface	314	42	EA	6	6-10 years			
	Market Board	314	16	LF	7	6-10 years			
	Power Distribution	314	32	EA	7	6-10 years			
	Walls - Plaster/Drywall	314	2,156	SF	7	10+ years			
	AC Unit	316 Office	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	316 Office	415	SF	6	10+ years			
	Doors - Wood Doors inclu hw	316 Office	1	EA	7	10+ years			
	Floor - Carpet	316 Office	415	SF	6	6-10 years			
	Lighting - Pendent/Surface	316 Office	6	EA	6	6-10 years			
	Power Distribution	316 Office	10	EΑ	7	10+ years			
	Walls - Plaster/Drywall	316 Office	1,142	SF	6	10+ years			
	AC Unit	Rm 005A- Security and Current Engineer Office	2	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Rm 005A- Security and Current Engineer Office	148	SF	7	10+ years			
	Doors - Steel Doors incl hw	Rm 005A- Security and Current Engineer Office	1	EA	7	10+ years			
	Floor - Carpet	Rm 005A- Security and Current Engineer Office	148	SF	7	6-10 years			
	Lighting - Pendent/Surface	Rm 005A- Security and Current Engineer Office	2	EA	7	6-10 years			
	Power Distribution	Rm 005A- Security and Current Engineer Office	4	EA	7	10+ years			
	Walls - Plaster/Drywall	Rm 005A- Security and Current Engineer Office	404	SF	7	10+ years			
_Gymnasi	ia								
•	Ceiling - Plaster/Drywall	011 Gymnasium Basement	2,956	SF	7	10+ years			
	Doors - Transom Window	011 Gymnasium Basement	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	011 Gymnasium Basement	2	EΑ	7	10+ years			
	Floor - Wood	011 Gymnasium Basement	2,956	SF	7	10+ years			
	Lighting - Pendent/Surface	011 Gymnasium Basement	19	EA	7	6-10 years			
	Sound System	011 Gymnasium Basement	1	EA	7	6-10 years			
	Walls - Concrete Block	011 Gymnasium Basement	1,256	SF	7	10+ years			
	Walls - Plaster/Drywall	011 Gymnasium Basement	9,440	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Basement weight room	920	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement weight room	2	EA	7	10+ years			
	Floor - Sport Flooring	Basement weight room	920	SF	7	6-10 years			
	Lighting - Pendent/Surface	Basement weight room	18	EA	7	6-10 years			
	Storage/ Closet	Basement weight room	30	SF	7	10+ years			
	Walls - Plaster/Drywall	Basement weight room	1,140	SF	7	10+ years			



atego	ry : Room		В	uilding	: Main (Urban Prep)	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Rm 001- Storage	1,081	SF	7	10+ years	
	Ceiling - Lay-in	Rm 001- Storage	10	SF	5	1-2 years	Water damaged ceiling tiles
	Doors - Wood Doors inclu hw	Rm 001- Storage	1	EΑ	7	10+ years	3
	Floor - Carpet	Rm 001- Storage	1,091	SF	4	0-1 year	Extensive damaged carpet
	ricor carpor	Tim oo i Otorago	1,001	O.	•	o i youi	throughout
	Lighting - Lay-in	Rm 001- Storage	21	EA	7	6-10 years	imoughout
	Lighting Lay-in	Rm 001- Storage	1	EA	5	1-2 years	Broken fixture cover
	Storage/ Closet	Rm 001- Storage	451	SF	7	10+ years	Biokeri lixture cover
	Walls - Plaster/Drywall	Rm 001- Storage	1,060	SF	6	10+ years	
	Walls - Plastel/Drywall	Kill 001- Storage	1,060	SF	O	10+ years	
itchen							
	Ceiling - Exposed	Rm 003	440	SF	7	10+ years	
	Doors - Steel Doors incl hw	Rm 003	2	ĒΑ	7	10+ years	
	Floor - Tile Quarry	Rm 003	440	SF	7	10+ years	
	Lighting - Pendent/Surface	Rm 003	5	EA	7	6-10 years	
	Storage/ Closet		73	SF	7		
		Rm 003				10+ years	
	Walls - Metal Panel	Rm 003	637	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 003	86	SF	7	10+ years	
cker/S	Shower Room						
	Accessories	Basement boys locker room	485	SF	7	6-10 years	
	7.0000001100	(Northeast end)	100	О.	•	o ro youro	
	Benches, ped mounted	Basement boys locker room	20	LF	7	10+ years	
	benches, ped modified	-	20	LI	,	TOT years	
	Calling Diagton/Drawall	(Northeast end)	405	C.E.	7	10	
	Ceiling - Plaster/Drywall	Basement boys locker room	485	SF	7	10+ years	
		(Northeast end)			_		
	Doors - Wood Doors inclu hw	Basement boys locker room	1	EA	7	10+ years	
		(Northeast end)					
	Floor - Concrete Epoxy/ Painted	Basement boys locker room	485	SF	7	10+ years	
		(Northeast end)					
	Lighting - Pendent/Surface	Basement boys locker room	8	EA	7	6-10 years	
		(Northeast end)				•	
	Storage/ Closet	Basement boys locker room	33	SF	7	10+ years	
	Clorage, Crossi	(Northeast end)		•	•	. o . y ca. c	
	Student Lockers - One Tier	Basement boys locker room	64	EA	7	10+ years	
	Olddelli Eddkers - Olie Fiel	(Northeast end)	0-1	L/\	,	101 years	
	Walls - Concrete Block	Basement boys locker room	625	SF	7	10 Lyoars	
	Walls - Collete block		023	SI	1	10+ years	
	Malla Diagram/Dominia	(Northeast end)	450	0.5	-	40	
	Walls - Plaster/Drywall	Basement boys locker room	459	SF	7	10+ years	
		(Northeast end)			_	0.40	
	Accessories	Basement boys locker room (south	723	SF	7	6-10 years	
		end)					
	Benches, ped mounted	Basement boys locker room (south	18	LF	7	10+ years	
	•	end)				•	

Campus Name: Medill Page : 13 of 57 Assessment Date: 08/14/2023



Catego	ry : Room		В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement boys locker room (south end)	723	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement boys locker room (south end)	1	EA	7	10+ years	
	Floor - Concrete	Basement boys locker room (south end)	411	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement boys locker room (south end)	312	SF	7	10+ years	
	Floor Drain	Basement boys locker room (south end)	5	EA	7	10+ years	
	Hand Dryer	Basement boys locker room (south end)	1	EA	7	6-10 years	
	Lavatory	Basement boys locker room (south end)	2	EA	7	10+ years	
	Lighting - Lay-in	Basement boys locker room (south end)	12	EA	7	6-10 years	
	Partitions	Basement boys locker room (south end)	2	EA	7	10+ years	
	Showers	Basement boys locker room (south end)	7	EA	7	10+ years	
	Storage/ Closet	Basement boys locker room (south end)	52	SF	7	10+ years	
	Student Lockers - One Tier	Basement boys locker room (south end)	69	EA	7	10+ years	
	Urinals	Basement boys locker room (south end)	2	EA	7	10+ years	
	Walls - Concrete Block	Basement boys locker room (south end)	930	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement boys locker room (south end)	357	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement boys locker room (south end)	352	SF	7	10+ years	
	Water Closet	Basement boys locker room (south end)	2	EA	7	10+ years	
	Accessories	Basement unisex locker room	162	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement unisex locker room	162	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement unisex locker room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement unisex locker room	162	SF	7	10+ years	
	Floor Drain	Basement unisex locker room	2	ĒΑ	7	10+ years	
	Hand Dryer	Basement unisex locker room	_ 1	EA	7	6-10 years	
	Lavatory	Basement unisex locker room	1	EΑ	7	10+ years	
	Lighting - Lay-in	Basement unisex locker room	3	EA	7	6-10 years	
	Showers	Basement unisex locker room	1	EA	7	10+ years	
	Student Lockers - One Tier	Basement unisex locker room	6	EA	7	10+ years	
	Claderic Lookers One field	Eddernent unidex looker rount	O	L/\	,	ioi youis	

Campus Name: Medill Page : 14 of 57 Assessment Date: 08/14/2023



atego	ry : Room		В	uilding	: Main (Urban Prep)	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Basement unisex locker room	309	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement unisex locker room	80	SF	7	10+ years	
	Water Closet	Basement unisex locker room	1	EA	7	10+ years	
ınch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Rm 004- Cafeteria	1,940	SF	7	10+ years	
	Doors - Steel Doors incl hw	Rm 004- Cafeteria	4	EA	7	10+ years	
	Floor - Tile	Rm 004- Cafeteria	1,940	SF	7	10+ years	
	Lighting - Pendent/Surface	Rm 004- Cafeteria	36	EA	7	6-10 years	
	Lighting - Pendent/Surface	Rm 004- Cafeteria	1	EA	6	6-10 years	
	Serving Line	Rm 004- Cafeteria	24	LF	7	10+ years	
	Walls - Metal Panel	Rm 004- Cafeteria	1,510	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 004- Cafeteria	1,050	SF	7	10+ years	
	AC Unit	Rm 004A- Overflow Dining	1,000	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Rm 004A- Overflow Dining	763	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 004A- Overflow Dining	703	EA	7	10+ years	
	Floor - Tile	Rm 004A- Overflow Dining	763	SF	7	10+ years	
	Lighting - Pendent/Surface	Rm 004A- Overflow Dining	11	EΑ	7	6-10 years	No first one and first one and
	Lighting - Pendent/Surface	Rm 004A- Overflow Dining	1	EA	5	1-2 years	No fixture cover and fixture not working
	Market Board	Rm 004A- Overflow Dining	30	LF	7	10+ years	
	Walls - Metal Panel	Rm 004A- Overflow Dining	651	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 004A- Overflow Dining	528	SF	7	10+ years	
	Ceiling - Exposed	Rm 004B- Overflow Dining	439	SF	7	10+ years	
	Doors - Steel Doors incl hw	Rm 004B- Overflow Dining	2	ĒΑ	7	10+ years	
	Floor - Tile	Rm 004B- Overflow Dining	439	SF	7	10+ years	
	Lighting - Pendent/Surface	Rm 004B- Overflow Dining	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	Rm 004B- Overflow Dining	1,500	SF	7	10+ years	Quantity changed to match curre
	walls - Flaster/Drywall	Kill 004b- Overnow Diffing	1,500	SI	,	10+ years	observation
F ID	F						
	Doors - Wood Doors inclu hw	213 MDF room	1	EA	6	10+ years	
	Finishes	213 MDF room	422	SF	7	10+ years	
	Other Cooling Unit	213 MDF room	1	EA	7	6-10 years	
chani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	48	SF	7	10+ years	
	Storage Room	1st Floor	55	SF	7	10+ years	Rank changed to match current observation
	Storage Room	1st Floor	192	SF	7	10+ years	Rank changed to match current observation
	Storage Room	1st Floor	33	SF	7	10+ years	Rank changed to match current observation

Campus Name: Medill Page : 15 of 57 Assessment Date: 08/14/2023



Category : Room			Building : Main (Urban Prep)					
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage Room	1st Floor	30	SF	7	10+ years	Rank changed to match current observation	
	Storage Room	1st Floor	88	SF	7	10+ years	Rank changed to match current	
	Storage Room	150 11001	00	SI	,	10+ years	observation	
	Janitor's Closet	2nd Floor	20	SF	7	10+ years	observation	
	Storage Room	2nd Floor	60	SF	7	10+ years		
	Storage Room	2nd Floor	33	SF	7	10+ years		
	Storage Room	2nd Floor	98	SF	7	10+ years		
	Storage Room	2nd Floor	192	SF	7	10+ years		
	Janitor's Closet	3rd Floor	46	SF	7	10+ years		
	Storage Room	3rd Floor	67	SF	7	10+ years		
	Storage Room	3rd Floor	63	SF	7	10+ years		
	Storage Room	3rd Floor	67	SF	7	10+ years		
	Storage Room	3rd Floor	30	SF	7	10+ years		
	Storage Room	3rd Floor	100	SF	7	10+ years		
	Storage Room	3rd Floor	43	SF	7	10+ years		
	Air Tunnel	Basement	1,310	SF	7	10+ years		
	Boiler Room	Basement	1,407	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	52	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	308	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	162	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	65	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	394	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	124	SF	7	10+ years		
	Storage Room	Basement	4,380	SF	7	10+ years		
	Vaults	Basement	200	SF	7	10+ years		
	vauits	basement	200	OI.	,	10+ years		
p Ro								
	Casework	107A Prep room	26	LF	7	10+ years		
	Ceiling - Lay-in	107A Prep room	287	SF	7	10+ years		
	Doors - Wood Doors inclu hw	107A Prep room	1	EA	7	10+ years		
	Floor - Tile	107A Prep room	287	SF	7	10+ years		
	Lighting - Lay-in	107A Prep room	4	EA	7	6-10 years		
	Walls - Plaster/Drywall	107A Prep room	813	SF	7	10+ years		
	Work Sink	107A Prep room	1	EA	7	10+ years		
	Casework	309A Prep room	25	LF	6	10+ years		
	Ceiling - Lay-in	309A Prep room	275	SF	7	10+ years		
	Doors - Wood Doors inclu hw	309A Prep room	1	EA	6	10+ years		
	Floor - Tile	309A Prep room	275	SF	6	10+ years		
	Lighting - Lay-in	309A Prep room	3	ĒΑ	6	6-10 years		
	Walls - Plaster/Drywall	309A Prep room	805	SF	7	10+ years		
	Work Sink	309A Prep room	1	ĒΑ	7	10+ years		

Campus Name: Medill Page : 16 of 57 Assessment Date: 08/14/2023



Catego	ry : Room		В	uilding	: Main (Urban Prep)	· • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st floor men's staff next to room 110	160	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor men's staff next to room 110	160	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor men's staff next to room 110	1	EA	7	10+ years	
	Floor - Tile	1st floor men's staff next to room 110	160	SF	7	10+ years	
	Lavatory	1st floor men's staff next to room 110	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor men's staff next to room 110	4	EA	7	6-10 years	
	Partitions	1st floor men's staff next to room 110	1	EA	7	10+ years	
	Urinals	1st floor men's staff next to room 110	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor men's staff next to room 110	818	SF	7	10+ years	
	Water Closet	1st floor men's staff next to room 110	1	EA	7	10+ years	
	Accessories	1st floor boys next to room 108	294	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor boys next to room 108	294	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor boys next to room 108	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor boys next to room 108	294	SF	7	10+ years	
	Floor Drain	1st floor boys next to room 108	1	ĒΑ	7	10+ years	
	Hand Dryer	1st floor boys next to room 108	1	EΑ	7	6-10 years	
	Lavatory	1st floor boys next to room 108	4	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st floor boys next to room 108	6	EA	7	6-10 years	
	Partitions	1st floor boys next to room 108	5	EA	7	10+ years	
	Urinals	1st floor boys next to room 108	4	EΑ	6	10+ years	
	Walls - Plaster/Drywall	1st floor boys next to room 108	849	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st floor boys next to room 108	60	SF	7	10+ years	
	Water Closet	1st floor boys next to room 108	5	EA	7	10+ years	
	Accessories	1st floor girls next to room 106	249	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor girls next to room 106	249	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor girls next to room 106	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor girls next to room 106	249	SF	7	10+ years	
	Floor Drain	1st floor girls next to room 106	1	EA	7	10+ years	
	Hand Dryer	1st floor girls next to room 106	1	EA	7	6-10 years	
	Lavatory	1st floor girls next to room 106	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor girls next to room 106	3	EA	7	6-10 years	
	Partitions	1st floor girls next to room 106	5	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor girls next to room 106	815	SF	7	10+ years	
	Water Closet	1st floor girls next to room 106	5	EA	7	10+ years	
	Water Ologet	13t floor girls flext to footh 100	3	LA	,	10+ years	



Catego	ry : Room		В	uilding	: Main (Urban Prep)	· • •
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st floor women's staff next to room 111	160	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor women's staff next to room	160	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor women's staff next to room	1	EA	7	10+ years	
	Floor - Tile	1st floor women's staff next to room	160	SF	7	10+ years	
	Lavatory	1st floor women's staff next to room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor women's staff next to room	4	EA	7	6-10 years	
	Partitions	1st floor women's staff next to room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor women's staff next to room	818	SF	7	10+ years	
	Water Closet	1st floor women's staff next to room	2	EA	7	10+ years	
	Accessories	2nd floor women's staff next to 217	160	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor women's staff next to 217	160	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor women's staff next to 217	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd floor women's staff next to 217	160	SF	6	10+ years	
	Lavatory	2nd floor women's staff next to 217	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd floor women's staff next to 217	4	ĒΑ	6	6-10 years	
	Partitions	2nd floor women's staff next to 217	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd floor women's staff next to 217	818	SF	6	10+ years	
	Water Closet	2nd floor women's staff next to 217	2	EA	6	10+ years	
	Accessories	2nd floor boys next to room 210	294	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys next to room 210	294	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor boys next to room 210	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys next to room 210	294	SF	6	6-10 years	
	Floor Drain	2nd floor boys next to room 210	1	EA	7	10+ years	
	Hand Dryer	2nd floor boys next to room 210	1	EA	7	6-10 years	
			-	EA	6	•	
	Lavatory	2nd floor boys next to room 210	4	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor boys next to room 210	6			6-10 years	
	Partitions	2nd floor boys next to room 210	5	EΑ	7	6-10 years	
	Urinals	2nd floor boys next to room 210	4	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd floor boys next to room 210	867	SF	6	10+ years	
	Water Closet	2nd floor boys next to room 210	5	EA	6	10+ years	
	Accessories	2nd floor girls next to room 208	198	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls next to room 208	198	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor girls next to room 208	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls next to room 208	198	SF	6	10+ years	
	Floor Drain	2nd floor girls next to room 208	1	EA	7	10+ years	

Campus Name: Medill Page : 18 of 57 Assessment Date: 08/14/2023



Catego	ry : Room		В	uilding	: Main (Urban Prep)	
				_	•	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	2nd floor girls next to room 208	1	EA	7	6-10 years	
	Lavatory	2nd floor girls next to room 208	4	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor girls next to room 208	3	EA	6	6-10 years	
	Partitions	2nd floor girls next to room 208	5	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd floor girls next to room 208	739	SF	6	10+ years	
	Water Closet	2nd floor girls next to room 208	5	EA	6	10+ years	
	Accessories	2nd floor men's staff next to room 216	160	SF	7	6-10 years	No key, last assessment data
	Ceiling - Plaster/Drywall	2nd floor men's staff next to room 216	160	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor men's staff next to room 216	1	EA	6	10+ years	
	Floor - Tile	2nd floor men's staff next to room 216	160	SF	6	10+ years	
	Lavatory	2nd floor men's staff next to room 216	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor men's staff next to room 216	4	EA	6	6-10 years	
	Partitions	2nd floor men's staff next to room 216	1	EA	7	6-10 years	
	Urinals	2nd floor men's staff next to room 216	1	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd floor men's staff next to room 216	818	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd floor men's staff next to room 216	10	SF	5	1-2 years	Damaged wall
	Water Closet	2nd floor men's staff next to room 216	1	EA	6	10+ years	
	Accessories	3rd floor boys next to room 310	294	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys next to room 310	294	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor boys next to room 310	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys next to room 310	294	SF	6	10+ years	
	Floor Drain	3rd floor boys next to room 310	1	EA	7	10+ years	
	Hand Dryer	3rd floor boys next to room 310	1	EA	7	6-10 years	
	Lavatory	3rd floor boys next to room 310	4	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor boys next to room 310	6	EA	6	6-10 years	
	Partitions	3rd floor boys next to room 310	5	EA	7	2-5 years	
	Urinals	3rd floor boys next to room 310	4	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd floor boys next to room 310	867	SF	6	10+ years	
	Water Closet	3rd floor boys next to room 310	5	EA	6	10+ years	
	Accessories	3rd floor girls across from 307A	198	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor girls across from 307A	198	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor girls across from 307A	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor girls across from 307A	198	SF	6	10+ years	

Campus Name: Medill Page : 19 of 57 Assessment Date: 08/14/2023



Catego	ry : Room		В	Building : Main (Urban Prep)							
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Floor Drain	3rd floor girls across from 307A	1	EA	7	10+ years					
	Hand Dryer	3rd floor girls across from 307A	1	EA	7	6-10 years					
	Lavatory	3rd floor girls across from 307A	4	EA	6	10+ years					
	Lighting - Pendent/Surface	3rd floor girls across from 307A	4	EA	6	6-10 years					
	Partitions	3rd floor girls across from 307A	5	EA	7	10+ years					
	Walls - Plaster/Drywall	3rd floor girls across from 307A	739	SF	6	10+ years					
	Water Closet	3rd floor girls across from 307A	5	EA	6	10+ years					
	Accessories	3rd floor unisex staff next to rm. 308	82	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	3rd floor unisex staff next to rm. 308	82	SF	6	10+ years					
	Doors - Wood Doors inclu hw	3rd floor unisex staff next to rm. 308	1	EA	6	10+ years					
	Floor - Tile Ceramic/ Porcelain	3rd floor unisex staff next to rm. 308	82	SF	6	10+ years					
	Floor Drain	3rd floor unisex staff next to rm. 308	1	EA	7	10+ years					
	Hand Dryer	3rd floor unisex staff next to rm. 308	1	EA	7	6-10 years					
	Lavatory	3rd floor unisex staff next to rm. 308	1	EA	6	10+ years					
	Lighting - Pendent/Surface	3rd floor unisex staff next to rm. 308	1	EA	6	6-10 years					
	Walls - Plaster/Drywall	3rd floor unisex staff next to rm. 308	390	SF	6	10+ years					
	Water Closet	3rd floor unisex staff next to rm. 308	1	EA	6	10+ years					
	Accessories	3rd floor unisex staff next to rm. 313	72	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	3rd floor unisex staff next to rm. 313	72	SF	6	10+ years					
	Doors - Wood Doors inclu hw	3rd floor unisex staff next to rm. 313	1	ĒΑ	7	10+ years					
	Floor - Tile	3rd floor unisex staff next to rm. 313	72	SF	6	10+ years					
	Floor Drain	3rd floor unisex staff next to rm. 313	1	EA	7	10+ years					
	Hand Dryer	3rd floor unisex staff next to rm. 313	1	EA	7	6-10 years					
	Lavatory	3rd floor unisex staff next to rm. 313	1	EΑ	6	10+ years					
	Lighting - Pendent/Surface	3rd floor unisex staff next to rm. 313	4	EA	6	6-10 years					
	Walls - Plaster/Drywall	3rd floor unisex staff next to rm. 313	479	SF	6	10+ years					
	Water Closet	3rd floor unisex staff next to rm. 313	1	EA	6	10+ years					
	Ceiling - Plaster/Drywall	Basement toilet in Mech. 006E	162	SF	6	10+ years					
	Doors - Wood Doors inclu hw	Basement toilet in Mech. 006E	1	EA	6	10+ years					
	Floor - Tile	Basement toilet in Mech. 006E	162	SF	4	0-1 years	Damaged and broken 9x9 floor tile				
	Floor Drain	Basement toilet in Mech. 006E	1	EA	7	10+ years	Damaged and broken 5x5 hoor the				
	Lighting - Wall Mounted	Basement toilet in Mech. 006E	2	EA	4	0-1 year	No light fixture				
	Partitions	Basement toilet in Mech. 006E	2	EA	7	10+ years	Rank changed to match current				
	i aititoris	basement tollet in Mech. Oool	2	LA	,	10+ years	observation				
	Showers	Basement toilet in Mech. 006E	1	EA	5	0-1 year	Shower not working				
	Walls - Concrete Block	Basement toilet in Mech. 006E	146	SF	6	6-10 years	g				
	Walls - Masonry	Basement toilet in Mech. 006E	269	SF	5	1-2 years	Damaged and cracking masonry				
	Walls - Plaster/Drywall	Basement toilet in Mech. 006E	224	SF	6	6-10 years	barriaged and cracking macerny				
	Accessories	Men's basement- Across from	196	SF	7	6-10 years					
	7.0000001100	Cafeteria 004	100	O.	•	o to youro					
	Ceiling - Plaster/Drywall	Men's basement- Across from	196	SF	7	10+ years					
	Coming Flactor/DryWall	Cafeteria 004	130	J1	,	101 yours					
	Doors - Wood Doors inclu hw	Men's basement- Across from	1	EA	7	10+ years					
	20010 11000 20013 111010 1110	Cafeteria 004	'	L/\	,	101 yours					
		Odiotolia oot									

Campus Name: Medill Page : 20 of 57 Assessment Date: 08/14/2023



Catego	ry : Room		Building : Main (Urban Prep)							
	_					Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile Ceramic/ Porcelain	Men's basement- Across from Cafeteria 004	196	SF	7	10+ years				
	Floor Drain	Men's basement- Across from Cafeteria 004	1	EA	7	10+ years				
	Lavatory	Men's basement- Across from Cafeteria 004	2	EA	7	10+ years				
	Lighting - Pendent/Surface	Men's basement- Across from Cafeteria 004	4	EA	7	6-10 years				
	Partitions	Men's basement- Across from Cafeteria 004	1	EA	7	10+ years				
	Urinals	Men's basement- Across from Cafeteria 004	2	EA	7	10+ years				
	Walls - Plaster/Drywall	Men's basement- Across from Cafeteria 004	808	SF	7	10+ years				
	Water Closet	Men's basement- Across from Cafeteria 004	1	EA	7	10+ years				
	Accessories	Unisex between 004 & 004A/B (Basement)	96	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Unisex between 004 & 004A/B (Basement)	96	SF	7	10+ years				
	Doors - Steel Doors incl hw	Unisex between 004 & 004A/B (Basement)	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Unisex between 004 & 004A/B (Basement)	96	SF	7	10+ years				
	Floor Drain	Unisex between 004 & 004A/B (Basement)	1	EA	7	10+ years				
	Hand Dryer	Unisex between 004 & 004A/B (Basement)	1	EA	7	6-10 years				
	Lavatory	Unisex between 004 & 004A/B (Basement)	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Unisex between 004 & 004A/B (Basement)	2	EA	6	6-10 years				
	Walls - Concrete Block	Unisex between 004 & 004A/B (Basement)	80	SF	7	10+ years				
	Walls - Plaster/Drywall	Unisex between 004 & 004A/B (Basement)	240	SF	7	10+ years				
	Water Closet	Unisex between 004 & 004A/B (Basement)	1	EA	7	10+ years				
	Accessories	Women's basement- Across from Cafeteria 004	196	SF	7	6-10 years				
	Ceiling - Exposed	Women's basement- Across from Cafeteria 004	196	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Women's basement- Across from Cafeteria 004	1	EA	7	10+ years				



Catego	ry : Room		D	uildina	· Main /	Urban Prep)	1301 W 14th STREET, Chicago, IL 6060
Catego	ry : Room		ь	ullaing	: wain (
O	Home Time	Laastian	Overtitue	LIOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Women's basement- Across from Cafeteria 004	196	SF	7	10+ years	
	Floor Drain	Women's basement- Across from Cafeteria 004	1	EA	7	10+ years	
	Lavatory	Women's basement- Across from Cafeteria 004	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's basement- Across from Cafeteria 004	4	EA	7	6-10 years	
	Partitions	Women's basement- Across from Cafeteria 004	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Women's basement- Across from Cafeteria 004	808	SF	6	10+ years	
	Water Closet	Women's basement- Across from Cafeteria 004	3	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main (Urban Prep)	
						Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #002 (Store Room)						
	AC Units	Basement	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	912	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	50	SF	5	0-1 year	Damaged plaster and peeling paint
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	962	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement	1	EA	5	1-2 years	Broken fixture cover
	Walls - Plaster/Drywall	Basement	1,250	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	25	SF	5	0-1 year	Holes in the walls
lassroc	m #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	816	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	812	SF	7	10+ years	
	Floor - Tile	1st Floor	4	SF	5	1-2 years	Cracked floor tiles
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,314	SF	7	10+ years	
Classroc	m #100C (Other Instructional Use)						
Classroc	Ceiling - Plaster/Drywall	1st Floor	154	SF	7	10+ years	
Classroc		1st Floor 1st Floor	154 1	SF EA SF	7 7	10+ years 10+ years	

Campus Name: Medill Page : 22 of 57 Assessment Date: 08/14/2023



Catego	Category : Classroom		В	uildina	: Main (Urban Prep)	1301 W 1411 31 REE1, Chicago, IL 60606
Jaiogo	. ,			9	(Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Pendent/Surface	1st Floor	4	EA	6	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	560	SF	7	10+ years	
_Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	956	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	956	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,473	SF	7	10+ years	
Classro	om #102 (Regular Classroom)						
Classion	AC Units	1st Floor	1	EA	7	6 10 voore	
		1st Floor	•	SF		6-10 years	
	Ceiling - Plaster/Drywall		816		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	816	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	151	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,314	SF	7	10+ years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	788	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	782	SF	7	10+ years	
	Floor - Tile	1st Floor	6	SF	5	1-2 years	Cracked floor tiles
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Cracked field theo
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	95	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,303	SF	6	10+ years	
Ola	44.05 (Damilar Classes)						
_Classroc	om #105 (Regular Classroom)	4 . 🗔				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	832	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	832	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,205	SF	7	10+ years	

Campus Name: Medill Page : 23 of 57 Assessment Date: 08/14/2023



Category : Classroom			В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Naceroo	m #106 (Regular Classroom)						
JIASSIUC	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	898	SF			
					7	10+ years	
	Doors - Side-lite	1st Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	898	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,407	SF	7	10+ years	
Classroc	m #107 (Science)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	90	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,124	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	, 2	ĒΑ	7	10+ years	
	Eye Wash Station	1st Floor	_ 1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,104	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Cracked floor tiles
	Gas Line	1st Floor	18	EA	7	10+ years	Ordokod noor theo
	Lighting - Lay-in	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Science Lab Elements	1st Floor	1,124	SF	7	10+ years	
	Science Lab Shower	1st Floor	1,124	EA	7	10+ years	
	Storage/ Closet	1st Floor	130	SF	, 5	10+ years	Dealing point falling to the floor
	Walls - Plaster/Drywall		1,128	SF		,	Peeling paint falling to the floor
		1st Floor			7 7	10+ years	
	Work Sink	1st Floor	7	EA	/	10+ years	
lassroc	m #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	992	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	992	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,428	SF	7	10+ years	
:lassroo	m #109 (Regular Classroom)						
iuooi UC	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,032	SF	7	10+ years	
	Doors - Wood Doors inclu hw					•	
	DOOLS - MOOD DOOLS IUCIA UM	1st Floor	2	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main (Urban Prep)	· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,032	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,474	SF	7	10+ years	
_Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	874	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	874	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,384	SF	7	10+ years	
	wans - Flaster/Drywan	13111001	1,304	OI.	,	10+ years	
_Classroo	om #111 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	802	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	802	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	110	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,413	SF	7	10+ years	
Classroo	om #113 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,032	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	1,032	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,532	SF	7	10+ years	
Classroo	om #200 (Store Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	816	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor 2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,298	SF	6	•	
	vvalis - Flastel/Drywall	ZIIU FIUUI	1,290	SF	O	10+ years	

Campus Name: Medill Page : 25 of 57 Assessment Date: 08/14/2023



Catego	ry : Classroom		В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #201 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	956	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	956	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	42	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,473	SF	6	10+ years	
Classroc	m #202 (Office)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	143	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,298	SF	6	10+ years	
Classroo	m #208 (Office)						
CIGOSTOC	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,028	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1,020	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,028	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,373	SF	6	10+ years	
Classroo	m #209 (Office)						
_ Oldssi UC	AC Units	2nd Floor	3	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	826	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	826	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,327	SF	6	10+ years	
Classroo	m #210 (Office)						
UassiUC	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	898	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	090	EA	6	10+ years	
	Floor - Tile	2nd Floor	898	SF	6	10+ years	
	1.007 1110	2110 1 1001	330	51	J	ioi youis	

Campus Name: Medill Page : 26 of 57 Assessment Date: 08/14/2023



Catego	Category : Classroom		В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,407	SF	6	10+ years	
Classroo	om #211 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	90	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,032	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	1,040	SF	6	6-10 years	
	Gas Line	2nd Floor	. 8	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,032	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,368	SF	6	10+ years	
	Work Sink	2nd Floor	4	ĒΑ	7	10+ years	
Classro	om #214 (Office)						
Olassio	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	992	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	992	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,428	SF	6	10+ years	
Classro	om #215 (Office)						
Classiu	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,032	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1,032	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,032	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,474	SF	6	10+ years	
	vvalis i laster/brywan	2110 1 1001	1,777	O.	O	101 years	
Classroo	om #217 (Office)	0 15				0.40	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	802	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	802	SF	6	10+ years	

Campus Name: Medill Page : 27 of 57 Assessment Date: 08/14/2023



Category : Classroom		В	uilding	: Main (Urban Prep)	•	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	21	EΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	100	SF	7	10+ years	
	Walls - Masonry	2nd Floor	10	SF	5	0-1 year	Damaged
	Walls - Plaster/Drywall	2nd Floor	1,371	SF	6	10+ years	-
Classroo	om #219 (Vacant)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,032	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1,002	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,024	SF	6	6-10 years	
	Floor - Tile	2nd Floor	8	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	Damageu
	Marker Board	2nd Floor 2nd Floor	16	LF	7		
		2nd Floor 2nd Floor	7	SF		6-10 years	
	Storage/ Closet				7	10+ years	
	Walls - Concrete Block	2nd Floor	560	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	430	SF	7	10+ years	
Classroo	om #300 (Store Room)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years	
	Floor - Tile	3rd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	152	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,314	SF	6	10+ years	
Classroo	om #301 (Store Room)						
	AC Units	3rd Floor	2	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	956	SF	6	10+ years	
	Floor - Tile	3rd Floor	956	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	46	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,473	SF	6	10+ years	
01	(1000 (Otara Baras)						
Classroc	om #302 (Store Room)						
	AC Units	3rd Floor	3	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years	
	Floor - Tile	3rd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	200	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,298	SF	6	10+ years	

Campus Name: Medill Page : 28 of 57 Assessment Date: 08/14/2023



Catego	ry : Classroom		В	uilding	: Main (Urban Prep)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #303 (Store Room)		•			•	
	AC Units	3rd Floor	2	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	788	SF	6	10+ years	
	Floor - Tile	3rd Floor	788	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,303	SF	6	10+ years	
Classroo	om #304 (Office)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,028	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	2-5 years	
	Floor - Tile	3rd Floor	1,028	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	109	SF	7	10+ years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,373	SF	6	10+ years	
	vvalis - i laster/brywali	314 1 1001	1,575	Oi	O	10+ years	
Classroo	om #307 (Office)						
	AC Units	3rd Floor	2	EΑ	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	826	SF	6	10+ years	
	Floor - Tile	3rd Floor	826	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,327	SF	6	10+ years	
Classroo	om #308 (Office)						
	AC Units	3rd Floor	2	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	898	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	898	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	24	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,407	SF	7	10+ years	
Classroo	om #309 (Lunch Room)						
	AC Units	3rd Floor	3	EA	7	2-5 years	
	Casework	3rd Floor	86	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	1,192	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1,192	EA	6	10+ years	
	Eye Wash Station	3rd Floor	4	EA	6	10+ years 10+ years	
	Floor - Tile	3rd Floor	1 102	SF	7	10+ years 10+ years	
	Gas Line	3rd Floor	1,192	SF EA	6		
		3rd Floor	15		6	10+ years	
	Lighting - Pendent/Surface	310 11001	24	EA	О	6-10 years	



Catego	Category : Classroom		В	uilding	: Main (Urban Prep)	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Science Lab Elements	3rd Floor	1,192	SF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,726	SF	6	10+ years	
	Work Sink	3rd Floor	8	EA	7	6-10 years	
Classroo	om #310 (Office)						
	AC Units	3rd Floor	2	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	966	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	992	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,428	SF	7	10+ years	
	walls - Plaster/Drywall	310 11001	1,420	SF	,	10+ years	
Classroo	om #311 (Office)						
	AC Units	3rd Floor	2	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,027	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,032	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,464	SF	6	10+ years	
Classroo	om #313 (Office)						
	AC Units	3rd Floor	2	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	802	SF	7	10+ years	
	Floor - Tile	3rd Floor	802	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,369	SF	7	10+ years	
Classroo	om #315 (Office)						
OldoolUt	AC Units	3rd Floor	2	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,032	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1,032	EA	7		
				SF		10+ years	
	Floor - Tile	3rd Floor	1,032		6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,544	SF	6	10+ years	

Campus Name: Medill Page : 30 of 57 Assessment Date: 08/14/2023



Catego	Category : Interior			uilding	: Main (Urban Prep)	
0	Name Time	Laadlan	0	LIOM	Danie	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	4,500	SF	7	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	4,450	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	50	SF	4	1-2 years	Cracked floor tiles
	Lighting - Pendent/Surface	1st Floor	54	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	245	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	9,260	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	4,489	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	11	SF EA	6 7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	4 200		7 7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,380	SF SF	=	6-10 years	Damarad
	Floor - Tile/Sheet Lighting - Pendent/Surface	2nd Floor 2nd Floor	120 51	SF EA	4 6	0-1 year 6-10 years	Damaged
	Student Lockers - One Tier	2nd Floor	219	EA	7	•	
	Walls - Plaster/Drywall	2nd Floor	9,260	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	4,500	SF SF	7	10+ years 10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	4,500	Sr EA	7	10+ years 10+ years	
	Floor - Tile/Sheet	3rd Floor	4,480	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	20	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	3rd Floor	53	EA	6	6-10 years	Damaged
	Student Lockers - One Tier	3rd Floor	183	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	9,260	SF	6	10+ years	
	Ceiling - Lay-in	Basement	317	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	3,795	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	6,733	EA	7	10+ years	
	Doors - Wood Doors include hw	Basement	4	EA	7	10+ years	
	Drinking Fountains - Double Water Cooler	Basement	1	EA	7	6-10 years	
	Floor - Asphalt Floor	Basement	89	SF	6	10+ years	
	Floor - Epoxy/ Painted	Basement	780	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	37	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	3,144	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	62	SF	4	0-1 year	Multiple locations of seriously damaged floor tiles
	Lighting - Lay-in	Basement	4	EA	7	6-10 years	- 3
	Lighting - Pendent/Surface	Basement	50	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement	2	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement	7	LF	7	10+ years	
	Walls - Concrete Block	Basement	1,579	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	3,846	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	12	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	4,443	SF	7	10+ years	

Campus Name: Medill Page : 31 of 57 Assessment Date: 08/14/2023



Group Safety	Item - Type	Location				Pecommend			
	Item - Type	Location		Recommend					
Safety			Quantity	UOM	Rank	Replacement	Comments		
	Camera Viewing Station	1st Floor	2	EA	7	6-10 years			
	Metal Detector	1st Floor	2	EA	7	6-10 years			
	Security Cameras	1st Floor	3	EA	7	6-10 years			
Ctains									
_Stairs	Osilias Disatan/Danasall	04-:- // 4 /0)	004	0.5		40			
	Ceiling - Plaster/Drywall	Stair # 1 (S)	364	SF SF	6	10+ years			
	Floor - Asphalt	Stair # 1 (S)	336	SF LF	6	10+ years			
	Handrails	Stair # 1 (S)	106		7	10+ years			
	Lighting - Wall Mounted	Stair # 1 (S)	8	EA LF	6 6	6-10 years			
	Stairs - Asphalt	Stair # 1 (S)	83	SF	-	10+ years			
	Walls - Plaster/Drywall	Stair # 1 (S)	1,560		6 7	10+ years			
	Ceiling - Plaster/Drywall	Stair # 4 (SE- basement to 1st only)	177	SF	/ 7	10+ years			
	Handrails	Stair # 4 (SE- basement to 1st only)	25	LF	•	10+ years			
	Lighting - Pendent/Surface	Stair # 4 (SE- basement to 1st only)	3	EA	7 7	6-10 years			
	Stairs - Asphalt	Stair # 4 (SE- basement to 1st only)	25	LF	•	10+ years			
	Walls - Plaster/Drywall	Stair # 4 (SE- basement to 1st only)	1,700	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Stair #2 (E)	364	SF	7	10+ years			
	Floor - Tile	Stair #2 (E)	336	SF	7	10+ years			
	Handrails	Stair #2 (E)	106	LF	7	10+ years			
	Lighting - Pendent/Surface	Stair #2 (E)	9	EA	7	6-10 years			
	Stairs - Asphalt	Stair #2 (E)	83	LF	6	10+ years			
	Walls - Plaster/Drywall	Stair #2 (E)	1,560	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Stairs #3 (SW)	364	SF	6	10+ years			
	Floor - Tile	Stairs #3 (SW)	336	SF	6	10+ years			
	Handrails	Stairs #3 (SW)	106	LF	7	10+ years			
	Lighting - Pendent/Surface	Stairs #3 (SW)	9	EA	6	6-10 years			
	Stairs - Asphalt	Stairs #3 (SW)	83	LF	6	10+ years			
	Walls - Plaster/Drywall	Stairs #3 (SW)	1,560	SF	6	10+ years			
Vertical C	Conveyance								
	Elevator - Hydraulic Elevator	Basement to 3rd floor	1	EA	7	10+ years			



Category : Exterior			В	Building: Annex (Chicago Academy Advanced Tech)					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance									
	Entrance Control - Audio and Video	#1 N	1	EA	6	6-10 years			
	Exterior Doors - Exterior Steel Door	#1 N	3	EΑ	6	10+ years			
	Exterior Doors - Transom Lite	#1 N	3	EA	6	10+ years			
	Power Door Operator and Controls	#1 N	2	EA	7	6-10 years			
	Exterior Doors - Exterior Steel Door	#2 Exit E	3	EA	6	10+ years			
	Exterior Doors - Transom Lite	#2 Exit E	3	EA	6	10+ years			
	Exterior Doors - Transom Lite Exterior Doors - Exterior Steel Door	#2 EXILE #3 S	1	EA	6	10+ years			
	Exterior Stairs - Concrete	#3 S	5	LF	6				
		#3 S #4 S			-	10+ years			
	Exterior Doors - Exterior Steel Door		1	EA	7	10+ years			
	Exterior Stairs - Concrete	#4 S	3	LF	7	10+ years			
	Exterior Doors - Exterior Steel Door	#5 Exit S	2	EΑ	6	6-10 years			
	Exterior Doors - Transom Lite	#5 Exit S	1	EA	6	6-10 years			
	Exterior Stairs - Concrete	#5 Exit S	6	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	#6 S	1	EA	6	10+ years			
	Exterior Stairs - Concrete	#6 S	3	LF	5	6-10 years			
	Exterior Doors - Exterior Steel Door	#6.5 S Vault	2	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	#7 S	2	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	#8 Exit W	1	EΑ	6	10+ years			
	Entrance Control - Audio and Video	#9 W	1	EΑ	6	6-10 years			
	Exterior Doors - Exterior Steel Door	#9 W	3	EΑ	6	10+ years			
	Exterior Doors - Transom Lite	#9 W	3	EA	6	10+ years			
Foundation	on								
	Foundation - Concrete	Entire Building	1,040	LF	7	10+ years			
	Superstructure - Concrete	Entire Building	48,600	SF	7	10+ years			
	•	Ŭ	,			,			
Lighting									
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	14	EA	7	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	4	0-1 year	Missing cover		
Roof Sys	tem								
•	Access Ladder - Metal	Main Roof	1	EA	7	10+ years			
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	30	LF	7	10+ years			
	Liner					,			
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	20	LF	7	10+ years			
	Liner			=-	-	- ,			
	Coping - Stone	Main Roof	915	LF	6	10+ years			
	Downspouts - Interior Downspouts	Main Roof	150	LF	6	10+ years			
	Parapet - Parapet < 16" Height	Main Roof	915	LF	6	10+ years			
	Roof - EPDM/ Synthetic Rubber	Main Roof	25,809	SF	4	0-1 year	Large area of bubbling, water under		
	TOOL EL DIVII OYTHITERO TRABBEI	IVIGITI INDUI	23,009	Oi.	7	0-1 year	Large area or bubbling, water under		

Page : 33 of 57 Campus Name: Medill Assessment Date: 08/14/2023



Security System - Intrusion Detection

Exit Signs - Corridors and Stairs

Exit Signs - Gym

Exit Signs - Lunchroom

Chicago Technology Academy High School 1301 W 14th STREET, Chicago, IL 60608

Category : Exterior			В	Building : Annex (Chicago Academy Advanced Tech)					
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
							membrane		
	Roof Hatch - Metal	Main Roof	1	EA	7	6-10 years			
	Roof Structure - Concrete	Main Roof	25,809	SF	7	10+ years			
	Coping - Stone	SE Low Roof	135	LF	6	10+ years			
	Downspouts - Interior Downspouts	SE Low Roof	45	LF	6	10+ years			
	Parapet - 16" - 30" Height	SE Low Roof	135	LF	6	10+ years			
	Roof - EPDM/ Synthetic Rubber	SE Low Roof	1,121	SF	7	2-5 years			
	Roof - EPDM/ Synthetic Rubber	SE Low Roof	95	SF	5	0-1 year	Leak		
	Roof Structure - Concrete	SE Low Roof	1,216	SF	7	10+ years			
Walls									
	Canopy - Concrete/ Stucco	Entire Building	434	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	16,200	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	500	SF	5	2-5 years	Stepped cracking		
		J .					3		
Window									
	Guard - Guards perforated	Entire Building	4,230	SF	6	10+ years			
	Lintels - Steel	Entire Building	922	LF	6	10+ years			
	Skylite - Lexan	Entire Building	50	SF	6	10+ years			
	Windows - Casement Aluminum Double- pane	Entire Building	7,540	SF	6	10+ years			
	Windows - Louver	Entire Building	32	SF	6	10+ years			
Category : Electrical			В	Building : Annex (Chicago Academy Advanced					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Emerge	ncy System								
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years			
	Emergency A/C Power - Corridors and	Entire Building	5,095	SF	6	6-10 years			
	Stairs	Ü	,			•			
	Emergency A/C Power - Gym	Entire Building	3,800	SF	6	6-10 years			
	Emergency A/C Power - Lunchrooms	Entire Building	1,685	SF	6	6-10 years			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	31	EA	6	6-10 years			
	Emergency Battery Packs - Gym	Entire Building	7	EA	6	6-10 years			
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EΑ	6	6-10 years			
	Emergency Battery Packs - Students Toilets	Entire Building	8	EΑ	6	6-10 years			
	Security System - CCTV	Entire Building	48,600	SF	6	6-10 years			
	Converte Cyptoms Interval on Detection	Entire Duilding	40,000	OI CE	-	o fo yours	4070 in stalled		

Campus Name: Medill Page : 34 of 57 Assessment Date: 08/14/2023

48,600

13

2

SF

EΑ

EΑ

EΑ

5

6

6

2-5 years

6-10 years

6-10 years

6-10 years

1978 installed

Entire Building

Entire Building

Entire Building

Entire Building



Category : Electrical			В	Building : Annex (Chicago Academy Advanced Tech)					
Craun	Itam Tuna	Location	Quantity	UOM	Donk	Recommend Replacement	Comments		
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments		
//ain Se									
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years			
	Main Electrical Service - 2000 A 277/480/3PH	Electrical Room	1	EA	4	2-5 years	Operational, no undue deterioration but 40+ years old		
	PA System	Entire Building	48,600	SF	6	6-10 years			
Power D	istribution								
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years			
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	7	10+ years			
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	7	10+ years			
	Lighting and Power Panels - 100 A	Entire Building	2	ΕA	7	6-10 years			
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years			
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	,			
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	4		6	10+ years 6-10 years			
			4	EΑ		•			
	Main Distribution Panels - 400 - 600 amp	Entire Building	•	EΑ	7	10+ years			
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years			
atego	ry : Fire Protection		В	uilding	: Annex	(Chicago Aca	demy Advanced Tech)		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar	m		-						
	Fire Alarm Panel	Mechanical Room	1	EA	7	6-10 years			
	Fire Alarm Strobe Lights	Mechanical Room	48,600	SF	6	6-10 years			
	Fire Alarm_System	Mechanical Room	48,600	SF	6	6-10 years			
	File Alaim_System	Mechanical Room	40,000	SI	O	0-10 years			
Category : Mechanical		Building : Annex (Chicago Academy Advanced Tech)							
Catego	ry : Mechanical		В	uilding	: Annex		demy Advanced Tech)		
		Location		_		Recommend			
Group	Item - Type	Location	B Quantity	uilding UOM	: Annex Rank				
Group	Item - Type ling Systems		Quantity	UOM	Rank	Recommend Replacement			
Group	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam	Gym	Quantity 1	UOM	Rank 5	Recommend Replacement 6-10 years			
Group	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam Fan Coil Unit- Celing Mounted - Steam	Gym Gym	Quantity 1	UOM EA EA	Rank 5 5	Recommend Replacement 6-10 years 6-10 years			
Group	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam Fan Coil Unit- Celing Mounted - Steam Roof Top Unit-Single Zone-Roof Mounted-	Gym	Quantity 1	UOM	Rank 5	Recommend Replacement 6-10 years			
Group	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam Fan Coil Unit- Celing Mounted - Steam	Gym Gym	Quantity 1	UOM EA EA	Rank 5 5	Recommend Replacement 6-10 years 6-10 years			
Group	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam Fan Coil Unit- Celing Mounted - Steam Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Gym Gym	Quantity 1	EA EA EA	Rank 5 5	Recommend Replacement 6-10 years 6-10 years 6-10 years			
Group	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam Fan Coil Unit- Celing Mounted - Steam Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted-	Gym Gym Roof	Quantity 1 1 1	UOM EA EA	5 5 6	Recommend Replacement 6-10 years 6-10 years			
Group	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam Fan Coil Unit- Celing Mounted - Steam Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Gym Gym Roof	Quantity 1 1 1	EA EA EA	5 5 6	Recommend Replacement 6-10 years 6-10 years 6-10 years			
Group	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam Fan Coil Unit- Celing Mounted - Steam Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Gym Gym Roof	Quantity 1 1 1	EA EA EA	5 5 6	Recommend Replacement 6-10 years 6-10 years 6-10 years			
Group Air Hand	Item - Type ling Systems Fan Coil Unit- Celing Mounted - Steam Fan Coil Unit- Celing Mounted - Steam Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Gym Gym Roof	Quantity 1 1 1	EA EA EA	5 5 6	Recommend Replacement 6-10 years 6-10 years 6-10 years			

Campus Name: Medill Page : 35 of 57 Assessment Date: 08/14/2023



Category : Mechanical			Building : Annex (Chicago Academy Advanced Tech)					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Chemical Feed System	Boiler Room	1	EA	7	10+ years		
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years		
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years		
	Feed Water Pumps and Tank	Boiler Room	1	EA	7	6-10 years		
	Non Condensing - Fire Tube - Scotch Marine- Steam - Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years		
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years		
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years		
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years		
	Steam Traps	Boiler Room	40	ĒA	5	6-10 years		
Heating	Devices							
· ·	Fin Tube - Steam	Entire Building	472	LF	6	10+ years		
	Cabinet Heaters - With Steam Coil	Entire Building	2	EA	5	6-10 years		
	Unit Heater - Electric	Entire Building, Boiler Room	2	EA	7	6-10 years		
	Unit Heater - Steam	Entire Building, Boiler Room	1	EA	5	2-5 years		
_Tempera	ature Control							
	Electric Controls	Entire Building	43,505	SF	6	6-10 years		
	Electric Thermostat	Entire Building	2	EA	6	2-5 years	Termostat for gym	
	Electric Thermostat	Entire Building	31	EA	5	2-5 years	0.	
	Pneumatic System	Entire Building	5,095	SF	4	1-2 years	Non Functional, manual control. Not connected to new DDC system in main building	
Unit Ven	itilation							
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	30	EA	6	6-10 years		
_Ventilation	on							
	Exhaust Fans- Indoor - Less than 500 CFM	Roof, 1st Floor (Kitchen), 2nd Floor	2	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof, 1st Floor (Kitchen), 2nd Floor	3	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof, 1st Floor (Kitchen), 2nd Floor	4	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof, 1st Floor (Kitchen), 2nd Floor	1	EA	7	6-10 years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof, 1st Floor (Kitchen), 2nd Floor	1	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof, 1st Floor (Kitchen), 2nd Floor	1	EA	6	6-10 years		
	CFM Exhaust Fans- Roof Mounted - 500 - 1500		-			•		

Campus Name: Medill Page : 36 of 57 Assessment Date: 08/14/2023



tom. Type						demy Advanced Tech)
tom Tune					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof, 1st Floor (Kitchen), 2nd Floor	2	EA	6	6-10 years	
Roof Mounted Duct Work	Roof, 1st Floor (Kitchen), 2nd Floor	150	LF	7	10+ years	
Type II Exhaust Hood- Warming Kitchen	Roof, 1st Floor (Kitchen), 2nd Floor	1	EA	6	6-10 years	
: Plumbing		В	uilding	: Annex		demy Advanced Tech)
_						
tem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	2-5 years	1979 installed
	•					
Fixtures	·				-	
Fixtures	-			4	2-5 years	Pipe clamps
Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	48,600	SF	6	6-10 years	
Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	48,600	SF	6	6-10 years	
Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	48,600	SF	6	6-10 years	
	Entire Building	48,600	SF	6	6-10 years	
Storm Piping	Entire Building	48,600	SF	6		
Vent Piping	Entire Building	48,600	SF	5	6-10 years	
Pumps - Ejector-Duplex	Boiler Room, 1st floor	1	EA	6	6-10 years	
Pumps - Sump-Duplex	Boiler Room, 1st floor	1	EA	6	6-10 years	
: Room		В	uilding	: Annex	(Chicago Aca	demy Advanced Tech)
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
tive Suites/Offices						
AC Unit	106 Offices	1	EA	7	6-10 years	
		780				
						Water damaged ceiling tiles
		1				
		780				
				=		Missing tiles
Lighting - Pendent/Surface	106 Offices	24	EA	7	6-10 years	wildowing tiled
FT / M _C _CCCFCFC(C(CCS) _FF / M dfCCCFF	Roof Mounted Duct Work Type II Exhaust Hood- Warming Kitchen : Plumbing tem - Type Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping Vent Piping Pumps - Ejector-Duplex Pumps - Sump-Duplex : Room tem - Type tive Suites/Offices AC Unit Ceiling - Splined Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	Roof, 1st Floor (Kitchen), 2nd Floor Roof, 1st Floor Roof Roof, 1st Floor Roof, 1st Floor Roof Roof Roof, 1st Floor Roof Roof Roof Roof Roof, 1st Floor Roof Roof Roof Roof Roof Roof Roof R	Roof Mounted Duct Work Type II Exhaust Hood- Warming Kitchen Plumbing tem - Type Location Quantity Boller Room 1 Comestic Piping-Hot Water Return Lines Comestic Piping-Hot Water Return Risers to Fixtures Comestic Piping-Hot/Cold Water Supply Horizontal Lines) Comestic Piping-Hot/Cold Water Supply Horizontal Lines) Comestic Piping-Hot/Cold Water Supply Fixiers Comestic Piping-Hot/Cold	Roof Mounted Duct Work Roof, 1st Floor (Kitchen), 2nd Floor 150 LF	Roof, 1st Floor (Kitchen), 2nd Floor 150	Roof, 1st Floor (Kitchen), 2nd Floor 150

Assessment Date: 08/14/2023 Campus Name: Medill Page : 37 of 57



Category : Room			Building : Annex (Chicago Academy Advanced Tech)					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Power Distribution	106 Offices	16	EA	7	10+ years		
	Walls - Concrete Block	106 Offices	600	SF	7	10+ years		
	Walls - Structural Glazed Tile	106 Offices	460	SF	7	10+ years		
	Ceiling - Splined	109 Main Office	790	SF	7	10+ years		
	Doors - Wood Doors inclu hw	109 Main Office	1	EA	7	10+ years		
	Floor - Carpet	109 Main Office	640	SF	7	6-10 years		
	Floor - Tile	109 Main Office	150	SF	7	10+ years		
	Lighting - Pendent/Surface	109 Main Office	24	ĒΑ	7	6-10 years		
	Power Distribution	109 Main Office	12	ĒΑ	7	10+ years		
	Walls - Concrete Block	109 Main Office	580	SF	7	10+ years		
	Walls - Structural Glazed Tile	109 Main Office	430	SF	7	10+ years		
	AC Unit	110D Conference room	1	EA	7	6-10 years		
	Ceiling - Splined	110D Conference room	153	SF	7	10+ years		
	Doors - Side-lite	110D Conference room	155	SF	7	10+ years		
	Doors - Wood Doors inclu hw	110D Conference room	13	EA	7	•		
	Floor - Tile			SF	7	10+ years		
		110D Conference room	153			10+ years		
	Lighting - Pendent/Surface	110D Conference room	2	EA	6	6-10 years		
	Power Distribution	110D Conference room	6	EA	7	10+ years		
	Walls - Concrete Block	110D Conference room	450	SF	7	10+ years		
	Ceiling - Splined	114 Teachers Lounge	272	SF	7	10+ years		
	Doors - Wood Doors inclu hw	114 Teachers Lounge	1	EA	7	10+ years		
	Floor - Tile	114 Teachers Lounge	272	SF	7	10+ years		
	Lighting - Pendent/Surface	114 Teachers Lounge	6	EA	7	6-10 years		
	Power Distribution	114 Teachers Lounge	8	EA	7	10+ years		
	Walls - Concrete Block	114 Teachers Lounge	550	SF	7	10+ years		
	Work SInk	114 Teachers Lounge	1	EA	7	10+ years		
	Ceiling - Plaster/Drywall	Engineer's Office	68	SF	7	10+ years		
	Doors - Side-lite	Engineer's Office	13	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Engineer's Office	1	EΑ	7	10+ years		
	Floor - Tile	Engineer's Office	58	SF	6	10+ years		
	Floor - Tile	Engineer's Office	10	SF	5	0-1 year	Missing floor tiles	
	Lighting - Pendent/Surface	Engineer's Office	2	EA	7	6-10 years	G	
	Power Distribution	Engineer's Office	4	EΑ	7	10+ years		
	Walls - Concrete Block	Engineer's Office	297	SF	6	10+ years		
	AC Unit	Rm 111- Administrative Office	1	ĒΑ	7	6-10 years		
	Ceiling - Splined	Rm 111- Administrative Office	665	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Rm 111- Administrative Office	1	EA	7	10+ years		
	Floor - Tile	Rm 111- Administrative Office	665	SF	7	10+ years		
	Lighting - Pendent/Surface	Rm 111- Administrative Office	21	EA	7	6-10 years		
	Power Distribution	Rm 111- Administrative Office	12	EA	7	10+ years		
	Storage/ Closet	Rm 111- Administrative Office	105	SF	7	10+ years		
	Walls - Concrete Block	Rm 111- Administrative Office	480	SF SF	7			
				SF SF		10+ years		
	Walls - Concrete Block	Rm 111- Administrative Office	9		7	10+ years		
	Walls - Masonry	Rm 111- Administrative Office	255	SF	7	10+ years		

Campus Name: Medill Page : 38 of 57 Assessment Date: 08/14/2023



itego	ry : Room		В	uilding	: Annex		demy Advanced Tech)
		L	0			Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Metal Panel	Rm 111- Administrative Office	106	SF	7	10+ years	
	AC Unit	Rm 112- Dean's office	1	EA	7	6-10 years	
	Ceiling - Splined	Rm 112- Dean's office	358	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 112- Dean's office	4	EA	7	10+ years	
	Floor - Tile	Rm 112- Dean's office	358	SF	7	10+ years	
	Lighting - Pendent/Surface	Rm 112- Dean's office	7	EA	7	6-10 years	
	Power Distribution	Rm 112- Dean's office	8	EA	7	10+ years	
	Walls - Concrete Block	Rm 112- Dean's office	1,290	SF	6	10+ years	
	Work SInk	Rm 112- Dean's office	1	EA	7	10+ years	
	Ceiling - Splined	Rm 118- Kitchen office	80	SF	6	10+ years	
	Doors - Side-lite	Rm 118- Kitchen office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 118- Kitchen office	1	EA	7	10+ years	
	Floor - Tile	Rm 118- Kitchen office	80	SF	6	10+ years	
	Lighting - Pendent/Surface	Rm 118- Kitchen office	2	EA	7	6-10 years	
	Power Distribution	Rm 118- Kitchen office	4	EA	7	10+ years	
	Storage/ Closet	Rm 118- Kitchen office	7	SF	7	10+ years	
	Storage/ Closet	Rm 118- Kitchen office	15	SF	7	10+ years	
	Walls - Concrete Block	Rm 118- Kitchen office	286	SF	7	10+ years	
mnasi		Ast Flace				40	
	Bleacher Seating	1st Floor	60	EA	7	10+ years	
	Ceiling - Splined	1st Floor	3,800	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile	1st Floor	3,800	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	56	EA	7	6-10 years	
	Storage/ Closet	1st Floor	136	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	3,724	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	48	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,638	SF	7	10+ years	
cker/S	hower Room						
	Accessories	Rm 120A- Storage Former 1st Floor	317	SF	4	1-2 years	Most accessories are not there
		Men's					
	Ceiling - Plaster/Drywall	Rm 120A- Storage Former 1st Floor Men's	317	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 120A- Storage Former 1st Floor	1	EA	6	10+ years	
		Men's				-	
	Floor - Tile Ceramic/ Porcelain	Rm 120A- Storage Former 1st Floor	317	SF	6	10+ years	
		Men's					
	Floor Drain	Rm 120A- Storage Former 1st Floor	2	EA	7	10+ years	
		Men's					
	Lighting - Pendent/Surface	Rm 120A- Storage Former 1st Floor	4	EA	6	6-10 years	
	- •	Men's				•	
	Showers	Rm 120A- Storage Former 1st Floor	1	EA	7	10+ years	

Campus Name: Medill Page : 39 of 57 Assessment Date: 08/14/2023



Name	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
Walls - Structural Glazed Tile Rm 120A- Storage Former 1st Floor Men's Water Closet Rm 120A- Storage Former 1st Floor Rm 120A- Storage Former 1st Floor Rm 120B- Former Unisex Shower Floor - Tile Ceramic/ Porcelain Floor Drain Rm 120B- Former Unisex Shower Rm 120B- Former	10+ years 10+ years 10+ years 10+ years 10+ years	
Walls - Structural Glazed Tile Rm 120A- Storage Former 1st Floor Men's Water Closet Rm 120A- Storage Former 1st Floor Men's Ceiling - Plaster/Drywall Rm 120B- Former Unisex Shower Plaster/Drywall Rm 120B- Former Unisex Shower Rm 122B- Storage - Former	10+ years 10+ years 10+ years 10+ years	
Ceiling - Plaster/Drywall Rm 120B- Former Unisex Shower 73 SF 6 Ceiling - Plaster/Drywall Rm 120B- Former Unisex Shower 73 SF 6 Floor - Tile Ceramic/ Porcelain Rm 120B- Former Unisex Shower 121 SF 6 Floor Drain Rm 120B- Former Unisex Shower 2 EA 7 Lighting - Pendent/Surface Rm 120B- Former Unisex Shower 1 EA 6 Lighting - Pendent/Surface Rm 120B- Former Unisex Shower 2 EA 6 Showers Rm 120B- Former Unisex Shower 6 EA 4 Walls - Structural Glazed Tile Rm 120B- Former Unisex Shower 485 SF 6 Benches, ped mounted Rm 122A- Storage - Former 10 LF 6 Women's Locker Ceiling - Plaster/Drywall Rm 122A- Storage - Former 194 SF 6 Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former 1 EA 6 Women's Locker	10+ years 10+ years 10+ years	
Ceiling - Plaster/Drywall Rm 120B- Former Unisex Shower Floor - Tile Ceramic/ Porcelain Rm 120B- Former Unisex Shower Floor Drain Rm 120B- Former Unisex Shower Rm 120B- Former Unisex Shower Elighting - Pendent/Surface Rm 120B- Former Unisex Shower Rm 120B- Former Unisex Showe	10+ years 10+ years	
Floor - Tile Ceramic/ Porcelain Floor Drain Rm 120B- Former Unisex Shower Rm 120B- Former Unisex Shower 2 EA 7 Lighting - Pendent/Surface Rm 120B- Former Unisex Shower Lighting - Pendent/Surface Rm 120B- Former Unisex Shower Rm 120B- Former U	10+ years	
Floor Drain Rm 120B- Former Unisex Shower 2 EA 7 Lighting - Pendent/Surface Rm 120B- Former Unisex Shower 1 EA 6 Lighting - Pendent/Surface Rm 120B- Former Unisex Shower 2 EA 6 Showers Rm 120B- Former Unisex Shower 6 EA 4 Walls - Structural Glazed Tile Rm 120B- Former Unisex Shower 485 SF 6 Benches, ped mounted Rm 122A- Storage - Former 10 LF 6 Women's Locker Ceiling - Plaster/Drywall Rm 122A- Storage - Former 194 SF 6 Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former 1 EA 6 Women's Locker		
Lighting - Pendent/Surface Rm 120B- Former Unisex Shower 1 EA 6 Lighting - Pendent/Surface Rm 120B- Former Unisex Shower 2 EA 6 Showers Rm 120B- Former Unisex Shower 6 EA 4 Walls - Structural Glazed Tile Rm 120B- Former Unisex Shower 485 SF 6 Benches, ped mounted Rm 122A- Storage - Former 10 LF 6 Women's Locker Ceiling - Plaster/Drywall Rm 122A- Storage - Former 194 SF 6 Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former 1 EA 6 Women's Locker	10+ years	
Lighting - Pendent/Surface Rm 120B- Former Unisex Shower 2 EA 6 Showers Rm 120B- Former Unisex Shower 6 EA 4 Walls - Structural Glazed Tile Rm 120B- Former Unisex Shower 485 SF 6 Benches, ped mounted Rm 122A- Storage - Former 10 LF 6 Women's Locker Ceiling - Plaster/Drywall Rm 122A- Storage - Former 194 SF 6 Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former 1 EA 6 Women's Locker	<i>y</i> =	Rank changed to match current observation
Showers Rm 120B- Former Unisex Shower 6 EA 4 Walls - Structural Glazed Tile Rm 120B- Former Unisex Shower 485 SF 6 Benches, ped mounted Rm 122A- Storage - Former 10 LF 6 Women's Locker Ceiling - Plaster/Drywall Rm 122A- Storage - Former 194 SF 6 Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former 1 EA 6 Women's Locker	6-10 years	
Walls - Structural Glazed Tile Rm 120B- Former Unisex Shower 485 SF 6 Benches, ped mounted Rm 122A- Storage - Former 10 LF 6 Women's Locker Ceiling - Plaster/Drywall Rm 122A- Storage - Former 194 SF 6 Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former 1 EA 6 Women's Locker	6-10 years	
Benches, ped mounted Rm 122A- Storage - Former Women's Locker Ceiling - Plaster/Drywall Rm 122A- Storage - Former Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former Rm 122A- Storage - Former The Author of the Auth	1-2 years	Shower is not being used
Women's Locker Ceiling - Plaster/Drywall Rm 122A- Storage - Former 194 SF 6 Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former 1 EA 6 Women's Locker	10+ years	
Women's Locker Doors - Wood Doors inclu hw Rm 122A- Storage - Former 1 EA 6 Women's Locker	6-10 years	
Women's Locker	10+ years	
Floor - Tile Ceramic/ Porcelain Rm 122A- Storage - Former 194 SF 6	10+ years	
Women's Locker	10+ years	
Lavatory Rm 122A- Storage - Former 1 EA 7 Women's Locker	10+ years	
	6-10 years	
Partitions Rm 122A- Storage - Former 2 EA 7 Women's Locker	10+ years	
Walls - Structural Glazed Tile Rm 122A- Storage - Former 509 SF 6 Women's Locker	10+ years	
Water Closet Rm 122A- Storage - Former 2 EA 4 Women's Locker	0-1 year	Water closets were removed
nch & Multipurpose Room		
	10+ years	
Doors - Wood Doors inclu hw 119 (includes kitchen) 2 EA 7	10+ years	
	10+ years	
	6-10 years	
	10+ years	
	10+ years	
	iut years	
DF_IDF	10+ years 10+ years 10+ years	

Campus Name: Medill Page : 40 of 57 Assessment Date: 08/14/2023



Catego	ry : Room		В	uilding	: Annex	(Chicago Aca	demy Advanced Tech)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	Room 206-A	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Room 206-A	1	EA	7	10+ years	
	Finishes	Room 206-A	263	SF	7	10+ years	
	Window AC Unit	Room 206-A	1	EA	7	6-10 years	
_Mechan	ical/ Service Rooms						
	Boiler Room	1st Floor	1,213	SF	7	10+ years	
	Janitor's Closet	1st Floor	39	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	395	SF	7	10+ years	
	Storage Room	1st Floor	1,394	SF	7	10+ years	
	Janitor's Closet	2nd Floor	48	SF	5	10+ years	
	Storage Room	2nd Floor	74	SF	5	10+ years	
Prep Ro	om						
	Casework	Rm 101A- Prep Room	20	LF	7	10+ years	
	Ceiling - Lay-in	Rm 101A- Prep Room	245	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 101A- Prep Room	2	EA	7	10+ years	
	Floor - Tile	Rm 101A- Prep Room	245	SF	7	10+ years	
	Lighting - Lay-in	Rm 101A- Prep Room	6	EA	7	6-10 years	
	Power Distribution	Rm 101A- Prep Room	12	EA	7	10+ years	
	Walls - Concrete Block	Rm 101A- Prep Room	90	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 101A- Prep Room	390	SF	7	10+ years	
	Walls - Traster/Drywaii Walls - Structural Glazed Tile	Rm 101A- Prep Room	20	SF	7	10+ years	
	Work Sink	Rm 101A- Prep Room	1	EA	7	10+ years	
Restroo	m						
Tresitoo	Accessories	1st Floor Girl's- Across from 107	400	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girl's- Across from 107	400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Girl's- Across from 107	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girl's- Across from 107	400	SF	7	10+ years	
	Floor Drain	1st Floor Girl's- Across from 107	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girl's- Across from 107	2	EA	7	6-10 years	
	Lavatory	1st Floor Girl's- Across from 107	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Girl's- Across from 107	4	EA	7	6-10 years	
	Partitions	1st Floor Girl's- Across from 107	7	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girl's- Across from 107	750	SF	7		
				Sr EA	-	10+ years	
	Water Closet	1st Floor Girl's- Across from 107	7 68	SF	7 7	10+ years	
	Accessories	1st Fir Women's- Across from 113		SF SF		6-10 years	
	Ceiling - Plaster/Drywall	1st Fir Women's- Across from 113	68		7	10+ years	
	Doors - Wood Doors inclu hw	1st Fir Women's- Across from 113	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr Women's- Across from 113	68	SF	7	10+ years	
	Lavatory	1st Flr Women's- Across from 113	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Flr Women's- Across from 113	1	EA	6	6-10 years	



Catego	ry : Room		Building : Annex (Chicago Academy Advanced Tech)				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Wall Mounted	1st Flr Women's- Across from 113	1	EA	6	6-10 years	
	Partitions	1st Flr Women's- Across from 113	1	EA	7	10+ years	
	Walls - Concrete Block	1st Flr Women's- Across from 113	148	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Flr Women's- Across from 113	188	SF	7	10+ years	
	Water Closet	1st Flr Women's- Across from 113	1	EA	7	10+ years	
	Accessories	1st floor Boys- Across from 111	205	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor Boys- Across from 111	205	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor Boys- Across from 111	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor Boys- Across from 111	205	SF	7	10+ years	
	Floor Drain	1st floor Boys- Across from 111	1	EA	7	10+ years	
	Hand Dryer	1st floor Boys- Across from 111	2	EA	7	6-10 years	
	Lavatory	1st floor Boys- Across from 111	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor Boys- Across from 111	4	EA	6	6-10 years	
	Partitions	1st floor Boys- Across from 111	3	EA	7	10+ years	
	Urinals	1st floor Boys- Across from 111	3	EA	7	10+ years	
	Walls - Concrete Block	1st floor Boys- Across from 111	55	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st floor Boys- Across from 111	450	SF	7	10+ years	
	Water Closet	1st floor Boys- Across from 111	3	EΑ	7	10+ years	
	Accessories	1st flr unisex- Across from 111	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr unisex- Across from 111	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr unisex- Across from 111	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr unisex- Across from 111	55	SF	7	10+ years	
	Floor Drain	1st flr unisex- Across from 111	1	EA	7	10+ years	
	Hand Dryer	1st flr unisex- Across from 111	1	EA	7	6-10 years	
	Lavatory	1st flr unisex- Across from 111	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr unisex- Across from 111	1	EΑ	7	6-10 years	
	Walls - Concrete Block	1st flr unisex- Across from 111	50	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st flr unisex- Across from 111	215	SF	7	10+ years	
	Water Closet	1st flr unisex- Across from 111	1	ĒΑ	7	10+ years	
	Accessories	2nd Floor Girl's- Across from 207	400	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girl's- Across from 207	400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girl's- Across from 207	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girl's- Across from 207	400	SF	7	10+ years	
	Floor Drain	2nd Floor Girl's- Across from 207	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Girl's- Across from 207	2	EΑ	7	6-10 years	
	Lavatory	2nd Floor Girl's- Across from 207	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girl's- Across from 207	6	EΑ	6	6-10 years	
	Partitions	2nd Floor Girl's- Across from 207	12	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girl's- Across from 207	750	SF	7	10+ years	
	Water Closet	2nd Floor Girl's- Across from 207	12	EA	7	10+ years	
	Accessories	2nd Floor Unisex inside MDF Room	40	SF	7	6-10 years	
	/1000301163	206A	40	Oi.	'	o- io years	
	Ceiling - Plaster/Drywall	2nd Floor Unisex inside MDF Room	40	SF	7	10+ years	
	Coming - Flaster/Drywan	206A	40	Oi	,	10+ years	



Catego	ry : Room		Building : Annex (Chicago Academy Advanced Tech)					
_				Recommend		Recommend	d	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	2nd Floor Unisex inside MDF Room 206A	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex inside MDF Room 206A	40	SF	7	10+ years		
	Lavatory	2nd Floor Unisex inside MDF Room 206A	1	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor Unisex inside MDF Room 206A	1	EA	7	6-10 years		
	Lighting - Wall Mounted	2nd Floor Unisex inside MDF Room 206A	1	EA	7	6-10 years		
	Partitions	2nd Floor Unisex inside MDF Room 206A	1	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor Unisex inside MDF Room 206A	95	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor Unisex inside MDF Room 206A	95	SF	7	10+ years		
	Water Closet	2nd Floor Unisex inside MDF Room 206A	1	EA	7	10+ years		
	Accessories	2nd floor Boys- Across from 211	205	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd floor Boys- Across from 211	205	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd floor Boys- Across from 211	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd floor Boys- Across from 211	205	SF	6	10+ years		
	Floor Drain	2nd floor Boys- Across from 211	1	ĒΑ	7	10+ years		
	Hand Dryer	2nd floor Boys- Across from 211	2	EΑ	7	6-10 years		
	Lavatory	2nd floor Boys- Across from 211	3	EA	6	10+ years		
	Lighting - Pendent/Surface	2nd floor Boys- Across from 211	5	EΑ	6	6-10 years		
	Partitions	2nd floor Boys- Across from 211	3	EA	7	10+ years		
	Urinals	2nd floor Boys- Across from 211	7	EA	6	10+ years		
	Walls - Concrete Block	2nd floor Boys- Across from 211	55	SF	6	10+ years		
	Walls - Structural Glazed Tile		450	SF				
		2nd floor Boys- Across from 211			6	10+ years		
	Water Closet	2nd floor Boys- Across from 211	3	EA	6	10+ years		
	Accessories	In Boiler Room 104	41	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	In Boiler Room 104	41	SF	7	10+ years		
	Doors - Wood Doors inclu hw	In Boiler Room 104	1	EA	7	10+ years		
	Floor - Tile	In Boiler Room 104	41	SF	6	10+ years		
	Floor Drain	In Boiler Room 104	1	EA	7	10+ years		
	Lavatory	In Boiler Room 104	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	In Boiler Room 104	1	EA	6	6-10 years		
	Showers	In Boiler Room 104	1	EA	7	10+ years	Rank changed to match current observation	
	Walls - Concrete Block	In Boiler Room 104	230	SF	7	10+ years		
	Water Closet	In Boiler Room 104	1	ĒΑ	7	10+ years		
	Accessories	In Rm 111- Administrative Office	20	SF	7	6-10 years		
		Suite	20	.	•	3 .0 ,00.0		



Catego	ry : Room	-	Building : Annex (Chicago Academy Advanced Tech)				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	In Rm 111- Administrative Office Suite	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Rm 111- Administrative Office Suite	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Rm 111- Administrative Office Suite	20	SF	7	10+ years	
	Lavatory	In Rm 111- Administrative Office Suite	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Rm 111- Administrative Office Suite	1	EA	7	6-10 years	
	Walls - Concrete Block	In Rm 111- Administrative Office Suite	72	SF	7	10+ years	
	Walls - Structural Glazed Tile	In Rm 111- Administrative Office Suite	72	SF	7	10+ years	
	Water Closet	In Rm 111- Administrative Office Suite	1	EA	7	10+ years	
	Accessories	In Room 112	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 112	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 112	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 112	20	SF	7	10+ years	
	Lavatory	In Room 112	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	In Room 112	1	EΑ	7	6-10 years	
	Walls - Concrete Block	In Room 112	72	SF	7	10+ years	
	Walls - Structural Glazed Tile	In Room 112	72	SF	7	10+ years	
	Water Closet	In Room 112	1	EA	7	10+ years	

Category : Classroom

Building: Annex (Chicago Academy Advanced Tech)

			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroc	om #101 (Science Lab Level 1)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	64	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,120	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Eye Wash Station	1st Floor	1	EΑ	7	6-10 years		
	Floor - Tile	1st Floor	1,120	SF	7	10+ years		
	Gas Line	1st Floor	8	EA	6	10+ years		
	Lighting - Lay-in	1st Floor	33	EΑ	7	6-10 years		
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Science Lab Elements	1st Floor	6	SF	7	10+ years		
	Science Lab Fume Hood	1st Floor	1	EA	7	10+ years		
	Science Lab Shower	1st Floor	1	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	345	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	390	SF	7	10+ years		



Catego	ry : Classroom		Building : Annex (Chicago Academy Advanced Tech)				
_	_					Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	1st Floor	90	SF	7	10+ years	
	Work Sink	1st Floor	8	EA	7	10+ years	
Classroo	om #102 (Science Lab Level 2)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	53	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	980	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	980	SF	7	10+ years	
	Gas Line	1st Floor	6	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	28	EΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Science Lab Elements	1st Floor	5	SF	7	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	280	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	711	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	135	SF	7	10+ years	
	Work Sink	1st Floor	6	EA	7	10+ years	
:lassroc	om #103 (Science Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	790	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	560	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	430	SF	7	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
lassro	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	790	SF	6	10+ years 10+ years	
	Doors - Wood Doors inclu hw	1st Floor	190	SF EA	7	10+ years 10+ years	
	Floor - Tile	1st Floor	790	SF	6	•	
	Lighting - Pendent/Surface	1st Floor	790 24	Sr EA	6	10+ years	
		1st Floor		LF	_	6-10 years	
	Marker Board		20	LF SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	560		7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	433	SF	7	10+ years	



ategory : Classroom		Building : Annex (Chicago Academy Advanced Tech)						
		0	11014	D	Recommend	0		
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
lassroom #107 (Regular Classroom)								
AC Units	1st Floor	1	EA	7	6-10 years			
Casework	1st Floor	8	LF	7	10+ years			
Ceiling - Splined	1st Floor	20	SF	6	1-2 years	Surface of the ceiling tiles is deteriorating		
Ceiling - Splined	1st Floor	770	SF	6	10+ years			
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
Floor - Tile	1st Floor	790	SF	7	10+ years			
Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years			
Marker Board	1st Floor	20	LF	7	6-10 years			
Walls - Concrete Block	1st Floor	560	SF	7	10+ years			
Walls - Structural Glazed Tile	1st Floor	430	SF	7	10+ years			
Work Sink	1st Floor	1	EA	7	10+ years			
lassroom #113 (Art Room)								
AC Units	1st Floor	1	EA	7	6-10 years			
Casework	1st Floor	12	LF	7	10+ years			
Casework	1st Floor	12	LF	7	10+ years	Rank changed to match current observation		
Ceiling - Splined	1st Floor	1,305	SF	7	10+ years			
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
Floor - Tile	1st Floor	1,305	SF	7	10+ years			
Lighting - Pendent/Surface	1st Floor	39	EA	7	6-10 years			
Marker Board	1st Floor	16	LF	7	6-10 years			
Walls - Concrete Block	1st Floor	550	SF	7	10+ years			
Walls - Plaster/Drywall	1st Floor	170	SF	7	10+ years			
Walls - Structural Glazed Tile	1st Floor	420	SF	7	10+ years			
Work Sink	1st Floor	4	EA	7	10+ years			
assroom #117 (Regular Classroom)								
AC Units	1st Floor	1	EA	7	6-10 years			
Casework	1st Floor	12	LF	7	10+ years			
Ceiling - Splined	1st Floor	770	SF	7	10+ years			
Ceiling - Splined	1st Floor	20	SF	6	1-2 years	Ceiling surface is deteriorating		
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	-		
Floor - Tile	1st Floor	780	SF	7	10+ years			
Floor - Tile	1st Floor	10	SF	5	0-1 year	Missing tiles		
Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	•		
Marker Board	1st Floor	20	LF	7	6-10 years			
Walls - Concrete Block	1st Floor	560	SF	7	10+ years			
Walls - Structural Glazed Tile	1st Floor	430	SF	7	10+ years			
lassroom #201 (Regular Classroom)								



Jaiego	ry : Classroom		В	Building : Annex (Chicago Academy Advanced Tech)					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	5	2-5 years			
	Ceiling - Splined	2nd Floor	830	SF	6	10+ years			
	Ceiling - Splined	2nd Floor	10	SF	4	0-1 year	Damaged		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	3		
	Floor - Tile	2nd Floor	840	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	24	ĒΑ	6	6-10 years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	615	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	335	SF	6	10+ years			
Classroo	om #202 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	6	10+ years			
	Ceiling - Splined	2nd Floor	790	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	790	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	790 24	EA	7	6-10 years			
	Marker Board	2nd Floor 2nd Floor		LF	7	6-10 years			
		2nd Floor	18	SF		•			
	Walls - Concrete Block		600	SF SF	7 7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	460	SF	,	10+ years			
Classroo	om #203 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	16	LF	5	10+ years			
	Ceiling - Splined	2nd Floor	785	SF	6	10+ years			
	Ceiling - Splined	2nd Floor	5	SF	5	1-2 years	Damaged		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	770	SF	6	10+ years			
	Floor - Tile	2nd Floor	20	SF	4	0-1 year	Damaged		
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	-		
	Marker Board	2nd Floor	18	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	560	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	430	SF	6	10+ years			
	Work Sink	2nd Floor	1	ĒΑ	5	1-2 years	Damaged		
lassroo	om #204 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	785	SF	6	10+ years			
	Ceiling - Splined	2nd Floor	5	SF	4	0-1 year	Damaged		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Damagod		
	Poors - MADOR POORS HIGH HM	2110 I 1001	790	SF	7	TOT years			



Catego	Category : Classroom			Building : Annex (Chicago Academy Advanced Tech)					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	6-10 years			
	Marker Board	2nd Floor	18	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	600	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	460	SF	7	10+ years			
Classroc	om #205 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	6	10+ years			
	Ceiling - Splined	2nd Floor	780	SF	6	6-10 years			
	Ceiling - Splined	2nd Floor	10	SF	4	0-1 year	Damaged		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	ŭ		
	Floor - Tile	2nd Floor	790	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	24	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	20	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	560	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	430	SF	7	10+ years			
Classroo	om #206 (Regular Classroom)								
31400100	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	5	10+ years			
	Ceiling - Splined	2nd Floor	790	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	787	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years			
	Marker Board	2nd Floor	18	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	600	SF	7	10+ years			
	Walls - Concrete Block Walls - Structural Glazed Tile	2nd Floor	460	SF	7	10+ years			
	Work Sink	2nd Floor	1	EA	7	6-10 years			
	WORK SILIK	2110 F1001	1	LA	,	6-10 years			
Classroc	om #207 (Regular Classroom)								
	AC Units	2nd Floor	1	EΑ	7	6-10 years			
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Splined	2nd Floor	770	SF	6	10+ years	_		
	Ceiling - Splined	2nd Floor	20	SF	4	0-1 year	Damaged		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	790	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years			
	Marker Board	2nd Floor	20	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	560	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	430	SF	7	10+ years			
	Work Sink	2nd Floor	1	EA	5	1-2 years	Damaged		
Classroo	om #209 (Store Room)								



Category : Classroom			В	Building : Annex (Chicago Academy Advanced Tech)					
_				_		Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	770	SF	6	10+ years			
	Ceiling - Splined	2nd Floor	20	SF	4	0-1 year	Damaged		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	•		
	Floor - Tile	2nd Floor	790	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	24	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	20	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	560	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	430	SF	7	10+ years			
	vvalis - diructural diazeu Tile	2110 1 1001	430	Oi.	,	10+ years			
lassroc	om #211 (Library)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	780	SF	6	10+ years			
	Ceiling - Splined	2nd Floor	10	SF	4	0-1 year	Damaged		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	_ aagoa		
	Floor - Tile	2nd Floor	790	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years			
	Marker Board	2nd Floor	18	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	560	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	430	SF	7	10+ years			
	Work Sink	2nd Floor	1	EA	7	6-10 years			
	Work Only	2114 1 1001	•		•	o ro youro			
lassroc	om #212 (Faculty Lounge)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Ceiling - Splined	2nd Floor	905	SF	6	10+ years			
	Ceiling - Splined	2nd Floor	25	SF	4	0-1 year	Damaged		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	3		
	Floor - Tile	2nd Floor	930	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	26	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	27	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	780	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	310	SF	7	10+ years			
	Valid Stradardi Glazda Tilo	2114 1 1001	010	O.	•	101 youro			
lassroc	nm #213 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	770	SF	7	10+ years			
	Ceiling - Splined	2nd Floor	20	SF	6	2-5 years			
				ĒΑ		•			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			



Category : Classroom			Building : Annex (Chicago Academy Advanced Tech					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years		
	Marker Board	2nd Floor	18	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	560	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	430	SF	7	10+ years		
Classroo	m #214 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	12	LF	7	10+ years		
	Ceiling - Splined	2nd Floor	820	SF	7	10+ years		
	Ceiling - Splined	2nd Floor	10	SF	6	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	820	SF	6	10+ years		
	Floor - Tile	2nd Floor 2nd Floor	10	SF	4	•	Damaged	
				SF EA	4 6	0-1 year	Damageu	
	Lighting - Pendent/Surface	2nd Floor	24		_	6-10 years		
	Marker Board	2nd Floor	18	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	600	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	385	SF	6	10+ years		
	Wireless System	2nd Floor	1	EA	7	6-10 years		
Classroo	m #215 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	40	SF	5	1-2 years	Damaged	
	Ceiling - Splined	2nd Floor	730	SF	7	10+ years	3	
	Ceiling - Splined	2nd Floor	20	SF	6	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years		
	Floor - Tile	2nd Floor	790	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years		
	Marker Board	2nd Floor	18	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	560	SF	6			
				SF SF	_	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	430		6	10+ years		
	Work Sink	2nd Floor	1	EA	7	6-10 years		
Classroo	m #217 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	12	LF	7	10+ years		
	Ceiling - Splined	2nd Floor	750	SF	6	10+ years		
	Ceiling - Splined	2nd Floor	40	SF	4	0-1 year	Damaged	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	770	SF	7	6-10 years		
	Floor - Tile	2nd Floor	20	SF	4	0-1 year	Damaged	
	Lighting - Pendent/Surface	2nd Floor	24	EΑ	6	6-10 years	- 9	
	Marker Board	2nd Floor	18	LF	7	6-10 years		

Campus Name: Medill Page : 50 of 57 Assessment Date: 08/14/2023



Catego	ry : Classroom	В	uilding	: Annex	(Chicago Aca	demy Advanced Tech)	
						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Walls - Concrete Block	2nd Floor	560	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	430	SF	6	10+ years	
Classroc	m #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	805	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	25	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	600	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	385	SF	7	10+ years	
Classroo	m #219 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	790	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	790	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	560	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	430	SF	7	10+ years	
Classroo	m #220 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	760	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	30	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	790	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	560	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	430	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Catego	ry : Interior		В	uilding	: Annex		demy Advanced Tech)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							



Catego	Category : Interior		В	demy Advanced Tech)					
Guiogo	.y . Illiconor					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	1st Floor	2,539	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	70	SF	7	10+ years			
	Doors - Wood Doors include hw	1st Floor	11	EA	7	10+ years			
	Drinking Fountains - Single Water Cooler	1st Floor	3	EΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	812	SF	7	10+ years			
	Floor - Tile/Sheet	1st Floor	1,797	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	25	ĒΑ	7	6-10 years			
	Student Lockers - One Tier	1st Floor	299	EΑ	7	10+ years			
	Walls - Concrete Block	1st Floor	2,878	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	5,120	SF	7	10+ years			
	Ceiling - Splined	2nd Floor	2,240	SF	6	6-10 years			
	Drinking Fountains - Single Fountain	2nd Floor	2,210	EA	7	10+ years			
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EΑ	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	2,240	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years			
	Student Lockers - Two Tiers	2nd Floor	449	EΑ	6	10+ years			
	Walls - Concrete Block	2nd Floor	2,124	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	3,492	SF	7	10+ years			
	vvalis Ciraciarai Giazca File	2110 1 1001	0,402	O.	,	101 years			
Safety									
Carety	Camera Viewing Station	1st Floor	1	EA	7	6-10 years			
	Security Cameras	1st Floor	10	EA	7	6-10 years			
	Security Cameras Security Cameras	1st Floor	2	EA	7	6-10 years			
	Security Cameras	13(1100)	2	LA	,	0-10 years			
Stairs									
	Ceiling - Plaster/Drywall	NE Stair- By Door #1	218	SF	7	10+ years			
	Ceiling - Splined	NE Stair- By Door #1	367	SF	7	10+ years			
	Floor - Concrete Epoxy/ Painted	NE Stair- By Door #1	99	SF	7	10+ years			
	Floor - Tile	NE Stair- By Door #1	50	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	NE Stair- By Door #1	218	SF	7	10+ years			
	Handrails	NE Stair- By Door #1	34	LF	7	10+ years			
	Lighting - Pendent/Surface	NE Stair- By Door #1	2	EΑ	7	6-10 years			
	Stairs - Rubber	NE Stair- By Door #1	17	LF	6	10+ years			
	Walls - Structural Glazed Tile	NE Stair- By Door #1	1,298	SF	7	10+ years			
	Ceiling - Plaster/Drywall	NW Stairs- By Door 9	100	SF	6	10+ years			
	Ceiling - Splined	NW Stairs- By Door 9	301	SF	6	1-2 years	Surface of ceiling tiles are		
		5 2, 255. 5		•	· ·	/ 000	deteriorating		
	Floor - Concrete	NW Stairs- By Door 9	75	SF	7	10+ years	•		
	Floor - Tile Ceramic/ Porcelain	NW Stairs- By Door 9	195	SF	7	10+ years			
	Handrails	NW Stairs- By Door 9	34	LF	7	10+ years			
	Lighting - Pendent/Surface	NW Stairs- By Door 9	3	EA	6	6-10 years			
	Stairs - Rubber	NW Stairs- By Door 9	17	LF	7	10+ years			
	Walls - Structural Glazed Tile	NW Stairs- By Door 9	1,406	SF	6	10+ years			
	Ceiling - Plaster/Drywall	SE Stair- By Door #2	218	SF	7	10+ years			
		•				•			

Campus Name: Medill Page : 52 of 57 Assessment Date: 08/14/2023



Catego	ry : Interior		Building : Annex (Chicago Academy Advanced Tech)					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Splined	SE Stair- By Door #2	334	SF	7	10+ years		
	Floor - Concrete	SE Stair- By Door #2	75	SF	7	10+ years		
	Floor - Tile	SE Stair- By Door #2	50	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	SE Stair- By Door #2	218	SF	7	10+ years		
	Handrails	SE Stair- By Door #2	34	LF	7	10+ years		
	Lighting - Pendent/Surface	SE Stair- By Door #2	2	EA	7	6-10 years		
	Stairs - Tile	SE Stair- By Door #2	17	LF	7	10+ years		
	Walls - Structural Glazed Tile	SE Stair- By Door #2	1,497	SF	7	10+ years		
Vertical	Conveyance							
	Elevator - Hydraulic Elevator	1st to 3rd floors	1	EA	6	10+ years		

Campus Name: Medill Page : 53 of 57 Assessment Date: 08/14/2023



Building · Site

Category : Site			Building : Site						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Civil/Dra									
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	10+ years			
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years			
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	14	EA	6	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	5	6-10 years			
Fencing									
· ·	Fencing - Chain Link	Entire Site	743	LF	5	6-10 years			
	Fencing - Iron and Concrete Post	Entire Site	435	LF	5	2-5 years			
	Fencing - New Standard Ornamental	Entire Site	743	LF	6	10+ years			
_Landsca	pe								
	Benches	Entire Site	1	EA	6	10+ years			
	Benches	Entire Site	1	EA	6	10+ years			
	Irrigation	Entire Site	360	SF	7	6-10 years			
	Landscape - Grass	Entire Site	5,850	SF	6	10+ years			
	Landscape - Hardscape- Asphalt	Entire Site	4,295	SF	6	10+ years			
	Landscape - Hardscape- Concrete	Entire Site	450	SF	6	10+ years			
	Landscape - Hardscape- Pavers	Entire Site	3,200	SF	7	10+ years			
	Landscape - Poured Rubber Surface	Entire Site	1,160	SF	6	6-10 years			
	Parkway trees	Entire Site	24	EA	6	10+ years			
	Trash Receptacles	Entire Site	3	EA	6	10+ years			
D- dia -	Lat								
Parking	Concrete Curbs	Entire Site	60	LF		10			
		Entire Site	60	LF LF	6	10+ years			
	Interior Plantings		30		6	10+ years			
	Surface - Asphalt	Entire Site	61,955	SF	6	10+ years			
	Trash Compactor	Entire Site	1	EA	6	10+ years			
	Trash Enclosure - Chain Links	Entire Site	415	SF	6	10+ years			
	Vehicular Screening	Entire Site	300	LF	6	10+ years			
Sidewall									
	Sidewalks - Perimeter Sidewalks	Entire Site	21,000	SF	6	10+ years			
Signage									
5 5	Flag Pole - Building Mounted Flag Pole	North	1	EA	7	10+ years			
	Flag Pole - Building Mounted Flag Pole	North	1	EA	7	10+ years			
	Marquee - Building Mounted Back Lighted	North	1	EA	7	10+ years			
	w/ LÉD	NI d		- ^	-	40			
	Monument - Building Mounted Cut Letter	North	1	EA	7	10+ years			



Chicago Technology Academy High School

1301 W 14th STREET, Chicago, IL 60608

Category : Site Building : Site

Recommend

Group Item - Type Location Quantity UOM Rank Replacement Comments

Sign

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Medill Page: 55 of 57 Assessment Date: 08/14/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main (Urban Prep)									
Lunch Room	Science	3rd Floor	309	309	1,192	140	25	N	N
Office	Regular Classroom	2nd Floor	202	202	816	84	39	N	N
Office	Regular Classroom	2nd Floor	208	208	1,028	140	52	N	N
Office	Regular Classroom	2nd Floor	209	209	826	100	20	N	N
Office	Regular Classroom	2nd Floor	210	210	898	84	26	N	N
Office	Regular Classroom	2nd Floor	214	214	992	84	39	N	N
Office	Regular Classroom	2nd Floor	215	215	1,032	84	39	N	N
Office	Regular Classroom	2nd Floor	217	217	802	40	10	N	N
Office	Regular Classroom	3rd Floor	304	304	1,028	140	52	N	N
Office	Regular Classroom	3rd Floor	307	307	826	100	20	N	N
Office	Regular Classroom	3rd Floor	308	308	898	84	26	N	N
Office	Regular Classroom	3rd Floor	310	310	992	84	39	N	N
Office	Regular Classroom	3rd Floor	311	311	1,032	84	39	N	N
Office	Regular Classroom	3rd Floor	313	313	802	40	10	N	N
Office	Regular Classroom	3rd Floor	315	315	1,032	64	12	N	N
Office	Science	2nd Floor	211	211	1,040	120	25	N	N
Other Instructional Use	Store Room	1st Floor	100C	100C	154	21	10		
Regular Classroom	Regular Classroom	1st Floor	100	100	816	84	39	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	956	104	39	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	816	84	39	N	Ν
Regular Classroom	Regular Classroom	1st Floor	103	103	788	84	26	N	Ν
Regular Classroom	Regular Classroom	1st Floor	105	105	832	100	20	N	Ν
Regular Classroom	Regular Classroom	1st Floor	106	106	898	84	26	N	Ν
Regular Classroom	Regular Classroom	1st Floor	108	108	992	84	39	N	Ν
Regular Classroom	Regular Classroom	1st Floor	109	109	1,032	84	39	N	Ν
Regular Classroom	Regular Classroom	1st Floor	110	110	874	84	39	N	Ν
Regular Classroom	Regular Classroom	1st Floor	111	111	802	83	39	N	Ν
Regular Classroom	Regular Classroom	1st Floor	113	113	1,032	74	12	N	Ν
Science	Science	1st Floor	107	107	1,124	100	20	N	Ν
Store Room	Regular Classroom	2nd Floor	200	200	816	84	39	N	N
Store Room	Regular Classroom	2nd Floor	201	201	956	104	39	N	N
Store Room	Regular Classroom	3rd Floor	300	300	816	84	39	N	N
Store Room	Regular Classroom	3rd Floor	301	301	956	104	39	N	N
Store Room	Regular Classroom	3rd Floor	302	302	816	84	39	N	N
Store Room	Regular Classroom	3rd Floor	303	303	788	84	26	N	N
Store Room	Special Program	Basement	002	002	962	90	45		
Vacant	Regular Classroom	2nd Floor	219	219	1,032	64	12	N	Ν





Classroom Summary

Classicolli Sullillary				EL DI			0		
			Doom	Floor Plan	A ====	Glazed Window	Operable Window	Window	Cmart
0	Internal ad Hanna	Been Leasting	Room	Room	Area			Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Annex (Chicago Aca						1		1	T
Art Room	Science Classroom	1st Floor	113	113/115	1,305	216	108	N	N
Computer Lab	Regular Classroom	2nd Floor	220	221	790	126	54	N	N
Faculty Lounge	Regular Classroom	2nd Floor	212	212	930	162	81	N	N
Library	Regular Classroom	2nd Floor	211	211	790	144	72	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	790	135	63	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	790	144	72	N	N
Regular Classroom	Regular Classroom	1st Floor	117	117	790	144	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	840	135	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	790	117	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	790	135	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	790	126	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	790	144	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	790	117	54	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	790	144	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	790	135	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	830	126	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	790	144	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	790	144	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	830	144	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	790	144	72	N	N
Science Classroom	Regular Classroom	1st Floor	103	103	790	135	63	N	N
Science Lab Level 1	Kindergarten	1st Floor	101	101	1,120	216	99	N	N
Science Lab Level 2	Kindergarten	1st Floor	102	102	980	162	72	Y	N
Store Room	Regular Classroom	2nd Floor	209	209	790	144	72	N	N

Campus Name: Medill Page : 57 of 57 Assessment Date: 08/14/2023