

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	2004	3	112,806
Campus Total			112,806

Category : Exterior Building : Main

				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio	1 - Main	1	EA	5	2-5 years	
	Exterior Doors - Side lite	1 - Main	2	EA	6	10+ years	
	Exterior Doors - Store Front	1 - Main	4	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	1 - Main	6	EΑ	6	10+ years	
	Power Door Operator and Controls	1 - Main	1	EA	7	6-10 years	
	Exterior Doors - Store Front	2	2	EA	5	0-1 year	Broken glass and covered with plywood
	Exterior Doors - Transom Lite	2	2	EA	7	10+ years	
	Exterior Doors - Store Front	3	1	EA	7	10+ years	
	Exterior Doors - Store Front	3	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	3	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	3	2	EA	7	10+ years	
	Entrance Control - Audio	4	1	EΑ	5	2-5 years	
	Exterior Doors - Side lite	4	2	EA	6	10+ years	
	Exterior Doors - Store Front	4	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	4	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	5	1	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	6	1	EA	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	6a - OVH	1	EA	6	10+ years	
	Door					•	
	Exterior Doors - Exterior Steel Door	7 - Penthouse	2	EA	6	10+ years	
	Exterior Stairs - Concrete	7 - Penthouse	5	LF	7	10+ years	
	Exterior Doors - Store Front	8 - Greenroof	1	EA	7	10+ years	No transom/side lite - included with windows.



Catego	ry : Exterior		В	uilding	: Main		
0	Mana Tama	Landin	0	HOM	D/	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Concrete	8 - Greenroof	5	LF	7	10+ years	
Foundati	on						
r oundui	Foundation - Concrete	Entire Building	1,132	LF	6	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	112,806	SF	7	10+ years	
	Topping	ŭ	,			,	
Lighting							
Ligiting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EA	7	6-10 years	Quantity changed to match current
		· ·				•	observations
	Exterior Lighting - Wall Mounted	Entire Building	21	EA	6	6-10 years	
Roof Svs	etem						
XOOI CYS	Access Ladder - Metal	A	1	EA	7	10+ years	
	Chimney - Metal Flue	Α	40	LF	6	10+ years	
	Coping - Metal	Α	786	LF	6	10+ years	
	Downspouts - Interior Downspouts	Α	552	LF	7	10+ years	
	Parapet - 16" - 30" Height	Α	686	LF	7	10+ years	
	Parapet - Parapet > 30"	A	100	LF	7	10+ years	
	Roof - Modified Bitumen	A	28,753	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	A	28,753	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	В	640	LF	7	6-10 years	
	Downspouts - Exterior Downspouts	В	30	LF	7	10+ years	
	Parapet - Parapet < 16" Height	В	340	LF	7	10+ years	
	Roof - Modified Bitumen	В	6,480	SF	6	6-10 years	Asphalt gravel not part of this roofin- photo showing exterior downspout
	Roof Structure - Steel / Metal Deck/	В	6,480	SF	7	10+ years	- prioto snowing exterior downspout
	Concrete Topping					-	
	Coping - Metal	С	108	LF	7	10+ years	Added to match current observation
	Roof - Modified Bitumen	С	1,036	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	С	1,036	SF	7	10+ years	
	Concrete Topping		,			, , , , ,	
	Coping - Stone	D	215	LF	7	6-10 years	
	Downspouts - Interior Downspouts	D	60	LF	7	10+ years	
	Parapet - Parapet > 30"	D	215	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	D	1.787	SF	6	6-10 years	
	Roof - Green Roof	D	3,000	SF	6	10+ years	
	Roof - Modified Bitumen	D	987	SF	7	10+ years	
				SF SF			
	Roof Structure - Steel / Metal Deck/ Concrete Topping	D	5,774	5F	7	10+ years	
	Coping - Metal	E	174	LF	6	10+ years	
	Downspouts - Interior Downspouts	Ē	60	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	E	174	LF	7	10+ years	
	Roof - Modified Bitumen	E	1,710	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	E	1,710	SF	7	10+ years	
	Concrete Topping	_	1,110		-	, , , , , , , , , , , , , , , , , , , ,	
	Coping - Metal	F	27	LF	6	10+ years	
	Downspouts - Interior Downspouts	F	15	LF	7	10+ years	
	Parapet - 16" - 30" Height	F	27	LF	7	10+ years	
		F	756	SF	6		
	Roof - Modified Bitumen					6-10 years	
	Roof Structure - Steel / Metal Deck/	F	756	SF	7	6-10 years	
	Concrete Topping						
Walls							
	Canopy - Concrete/ Stucco	Entire Building	1,460	SF	7	10+ years	Added to match current observations
	Exterior Walls - Brick	Entire Building	36,325	SF	7	10+ years	
	Exterior Walls - Concrete Block	Entire Building	4,788	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,402	SF	7	10+ years	
A.C. 1		·				•	
Vindows	Clerestory - Glass Double-Pane	Entire Building	1,804	SF	7	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	3,467	SF	6	10+ years	
	Curtain wall - Glazed Double Pane		,	SF	5		Chattarad
		Entire Building	100			0-1 year	Shattered
	Guard - Guards perforated	Entire Building	1,582	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,343	LF	7	10+ years	
	Storefront Windows	Entire Building	820	SF	6	10+ years	
	Windows - Casement Steel Double-pane	Entire Building	240	SF	6	10+ years	
	Windows - Louver	Entire Building	1,202	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,888	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
0	Itama Tuma	Laastian	O	HOM	Donk	Recommend	Commonto
Group	Item - Type ncy System	Location	Quantity	UOM	Rank	Replacement	Comments
merger	UPS - Greater than 60	1st Floor	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	24,855	SF	6	10+ years	
	Stairs	 	1,000			- ,	
	Emergency A/C Power - Gym	Entire Building	5,140	SF	6	10+ years	
	Emergency Battery Packs - Corridors and	Entire Building	8	EA	6	6-10 years	
	Stairs Emergency Battery Packs - Gym	Entire Building	10	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	37	EA	6	6-10 years	
	Exit Signs - Gorndors and Stairs Exit Signs - Gym	Entire Building	5	EA	6	6-10 years	
						•	
	Cyit Ciana Lunchroom	Entire Duilding					
	Exit Signs - Lunchroom Exit Signs - Multipurpose Room	Entire Building Entire Building	6 2	EA EA	6 6	6-10 years 6-10 years	



Category : Electrical

Claremont STEM Magnet Elementary School 2300 W 64th STREET, Chicago, IL 60636

Recommend

Building: Main

Group	Item - Type	Location	Quantity	UOM	Donk	Recommend Replacement	Comments
Group	Security System - CCTV	Entire Building	112,806	SF	Rank 7	6-10 years	Comments
	Security System - Corv Security System - Intrusion Detection	Entire Building	112,806	SF	7	6-10 years	
	Automatic Transfer Switch	Mechanical Room	112,000	EA	6	10+ years	Fire pump.
	Automatic Transfer Switch	Mechanical Room	1	EA	6	10+ years	i ile puilip.
	Automatic Transfer Switch	Wechanical Room	ı	LA	U	10+ years	
Main Se	rvice						
	PA System	Entire Building	112,806	SF	6	10+ years	
	Independent Electrical Service for	Entire Building	1	EA	6	10+ years	Fire pump.
	emergency power						
	Independent Electrical Service for	Entire Building	1	EΑ	6	10+ years	
	emergency power						
	Main Electrical Service - 2001 to 3000 A	Mechanical Room	1	EA	7	10+ years	
	277/480/3PH						
Power D	vistribution						
	Lighting and Power Panels - Above 100 A	Entire Building	21	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	ΕA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	_ 5	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EΑ	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	8	EΑ	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	4	EA	7	10+ years	
	amp	Little Ballaling	7	LA	,	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	4	EA	6	10+ years	
	Transionners - 2117-00 - 120/200	Entire ballaring	7	LA	U	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
	No	1	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Annunciator.
	Fire Alarm Strobe Lights	Entire Building	112,806	SF	7	10+ years	
	Fire Alarm_System	Entire Building	112,806	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
Pump Ro	oom Assembly						
	Fire Pump - 51-75hp	Mechanical Room	1	EA	6	10+ years	
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	
Sprinkle	r System						
оринке	•	Entire Building	110 000	er_	7	1011/22/2	
	Sprinkler Heads	Entire Building	112,806	SF	7	10+ years	
	Sprinkler Piping	Entire Building	112,806	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	112,806	SF	7	10+ years	
Campus I	Name: Claremont		Page: 4 of 39				Assessment Date: 11/01/202



Catego	ry : Fire Protection		В	uilding	: Main		2300 W 0411 011(EE1, Officago, 12 00030
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catago	ry : Mechanical		D	uilding	· Main		
Calego	ry . Mechanical		В	ullaing	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	· · · · · · · · · · · · · · · · · · ·		,				
	Chiller-Air Cooled-Screw Type-Roof	Lower Roof	1	EA	6	6-10 years	
	Mounted - 301 - 400 tons	20.00.1.000.	•		· ·	0 .0 ,00.0	
	Glycol Feed	Lower Roof	1	EA	6	6-10 years	
	Pressure Fill System	Lower Roof	1	EA	6	6-10 years	Previously not assesed
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	5	6-10 years	•
	than 5 tons					•	
_Air Hand	lling Systems						
	Air Handling Unit-Package Single Zone-	Boiler Room - less than 4000CFM	1	EA	6	10+ years	
	Indoor- Hot Water Coils - Less than 4000					·	
	cfm						
	Air Intake	Boiler Room - less than 4000CFM	1	EA	7	10+ years	
	Fan Power Box - Fan Power Box with	Entire Building	6	EA	6	10+ years	
	Electric Coil						
	Fan Power Box - Fan Power Box with Hot	Entire Building	55	EA	6	10+ years	Fan powers box are inside ceiling
	Water Coil						
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	7	10+ years	
	Indoor- Hot Water and Chilled Water Coils -						
	12001-20000 cfm						
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	7	10+ years	
	Indoor- Hot Water and Chilled Water Coils -						
	12001-20000 cfm				_		
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	7	10+ years	
	Indoor- Hot Water and Chilled Water Coils -						
	4000-8000 cfm	M 1 : 15	4	^	-	40	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	7	10+ years	
	Indoor- Hot Water and Chilled Water Coils -						
	8001-12000 cfm	Machanical Dage	4	Ε.	7	40	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils -	Mechanical Room	1	EA	7	10+ years	
	Greater than 30,000 cfm						
	Air Intake	Mechanical Room	2	EA	7	10+ years	
	Air Intake Air Intake	Mechanical Room	3	EA	7	10+ years	
	VAV Box	Mechanical Room	16	EA	7 7	10+ years 10+ years	
	Indoor Return Fans- Centrifugal Inline -	Mechanical Room	2	EA	, 6	10+ years 10+ years	
	10001 - 20000 CFM	MEGHANICAI NOON	2	ĽA	O	TOT years	
	Indoor Return Fans- Centrifugal Inline -	Mechanical Room	1	EA	6	10+ years	
	5000 - 10000 CFM						
	Indoor Return Fans- Centrifugal Inline -	Mechanical Room	1	EA	6	10+ years	

Campus Name: Claremont Page : 5 of 39 Assessment Date: 11/01/2023



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Greater than 20000 CFM						
	Indoor Return Fans- Centrifugal Inline - Less	Mechanical Room	1	EA	6	10+ years	
	than 5000 CFM						
D 11 O							
Boiler Sy							
	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	6	10+ years	
	- Greater than 4000 MBH	Deilar Deam	0	Ε.	0	40	
	Chemical Pot Feeder	Boiler Room Boiler Room	2	EA EA	6 6	10+ years	
	Combustion Dampers Glycol Feed System	Boiler Room	1	EA EA	6	10+ years 10+ years	
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	6		
	Tube- Force Draft- Hot Water Boiler -	Bollet Room	1	EA	O	10+ years	
	Greater than 4000 MBH						
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	6	10+ years	
	Tube- Force Draft- Hot Water Boiler -	Boller Room	'	LA	O	10+ years	
	Greater than 4000 MBH						
	Greater than 4000 MBH						
Gas Boo	ester						
	Gas Booster	Boiler Room	2	EA	6	10+ years	
Heating	Devices						
Licating	Cabinet Heaters - With Hot Water Coil	Entire Building	11	EA	7	10+ years	
	Fin Tube - Hot Water	Entire Building	64	LF	6	10+ years	
	Unit Heater - Electric	Entire Building	1	EA	7	10+ years	
	Unit Heater - Hot Water	Entire Building	5	EΑ	7	10+ years	
	Radiator Panels - Hot Water	Entire Building	8	EA	6	10+ years	
Mechani	cal Plumbing						
	Chilled Water Pump - 21 - 50 HP	Boiler Room	1	EA	6	10+ years	
	Chilled Water Pump - 21 - 50 HP	Boiler Room	1	EA	6	10+ years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	5	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	5	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	5	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EΑ	6	10+ years	
	Hot Water Pump - Less than 10	Boiler Room	1	EΑ	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	880	LF	6	10+ years	
<u> Fempera</u>	ature Control						
	DDC System	Entire Building	112,806	SF	6	10+ years	
	Thermostats - DDC	Entire Building	77	EA	6	10+ years	
(11" · ·							
/entilation	on						



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	12	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	7	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	10+ years	
Catego	y : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	112,806	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	112,806	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	112,806	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	112,806	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	112,806	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	112,806	SF	7	10+ years	
	Sanitary Piping	Entire Building	112,806	SF	7	10+ years	
	Storm Piping	Entire Building	112,806	SF	7	10+ years	
	Vent Piping	Entire Building	112,806	SF	7	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	6-10 years	Sump pump inside elevator pit
Catego	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices						
, willingt	Ceiling - Lay-in	108C Post Production	81	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108C Post Production	1	EA	7	10+ years	
Campus	lame: Claremont	ח	age : 7 of 39				Assessment Date: 11/01/2023
Campus I	iame. Giaremuni	F	aye . 1 UI Ja				Mosessilletti Date. 11/01/2023



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	108C Post Production	81	SF	7	6-10 years	
	Lighting - Lay-in	108C Post Production	1	EA	7	6-10 years	
	Walls - Concrete Block	108C Post Production	90	SF	7	10+ years	
	Walls - Plaster/Drywall	108C Post Production	50	SF	7	10+ years	
	Ceiling - Lay-in	112 - Main Office	871	SF	7	10+ years	
	Doors - Steel Doors incl hw	112 - Main Office	2	EA	7	10+ years	
	Doors - Store Front	112 - Main Office	1	EA	7	10+ years	
	Floor - Carpet	112 - Main Office	523	SF	6	6-10 years	
	Floor - Terrazzo	112 - Main Office	348	SF	7	10+ years	
	Lighting - Lay-in	112 - Main Office	17	EA	7	10+ years	
	Power Distribution	112 - Main Office	16	EA	7	10+ years	
	Storage/ Closet	112 - Main Office	20	SF	7	10+ years	
	Walls - Concrete Block	112 - Main Office	552	SF	7	10+ years	
	Walls - Plaster/Drywall	112 - Main Office	966	SF	7	10+ years	
	Ceiling - Lay-in	115 - Waiting Room	64	SF	7	10+ years	
	Doors - Side-lite	115 - Waiting Room	80	SF	7	10+ years	
	Doors - Steel Doors incl hw	115 - Waiting Room	1	EA	7	10+ years	
	Floor - Carpet	115 - Waiting Room	64	SF	7	6-10 years	
	Lighting - Lay-in	115 - Waiting Room	2	EA	7	10+ years	
	Power Distribution	115 - Waiting Room	4	EA	7	10+ years	
	Walls - Concrete Block	115 - Waiting Room	54	SF	7	10+ years	
	Walls - Plaster/Drywall	115 - Waiting Room	69	SF	7	10+ years	
	Ceiling - Lay-in	117 - Work Room	205	SF	7	10+ years	
	Doors - Steel Doors incl hw	117 - Work Room	1	EA	7	10+ years	
	Floor - Tile	117 - Work Room	205	SF	7	10+ years	
	Lighting - Lay-in	117 - Work Room	3	EA	7	10+ years	
	Power Distribution	117 - Work Room	14	EA	7	10+ years	
	Walls - Concrete Block	117 - Work Room	207	SF	7	10+ years	
	Walls - Plaster/Drywall	117 - Work Room	212	SF	7	10+ years	
	Ceiling - Lay-in	118 - Assistant Principal's Office	205	SF	7	10+ years	
	Doors - Side-lite	118 - Assistant Principal's Office	12	SF	7	10+ years	
	Doors - Steel Doors incl hw	118 - Assistant Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	118 - Assistant Principal's Office	205	SF	7	6-10 years	
	Lighting - Lay-in	118 - Assistant Principal's Office	2	EA	7	10+ years	
	Power Distribution	118 - Assistant Principal's Office	10	EA	7	10+ years	
	Walls - Concrete Block	118 - Assistant Principal's Office	213	SF	7	10+ years	
	Walls - Plaster/Drywall	118 - Assistant Principal's Office	240	SF	7	10+ years	
	Ceiling - Lay-in	119 - Conference Room	207	SF	7	10+ years	
	Doors - Side-lite	119 - Conference Room	10	SF	7	10+ years	
	Doors - Steel Doors incl hw	119 - Conference Room	1	ĒΑ	7	10+ years	
	Floor - Carpet	119 - Conference Room	207	SF	7	6-10 years	
	Lighting - Lay-in	119 - Conference Room	2	EA	7	10+ years	
	Power Distribution	119 - Conference Room	14	EΑ	7	10+ years	
	Walls - Concrete Block	119 - Conference Room	133	SF	7	10+ years	
	The second bloom		.50	٥.	•	,	



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Plaster/Drywall	119 - Conference Room	339	SF	7	10+ years				
	Ceiling - Lay-in	120 - Principal's Office	207	SF	7	10+ years				
	Doors - Side-lite	120 - Principal's Office	10	SF	7	10+ years				
	Doors - Steel Doors incl hw	120 - Principal's Office	1	EA	7	10+ years				
	Floor - Carpet	120 - Principal's Office	207	SF	7	6-10 years				
	Lighting - Lay-in	120 - Principal's Office	2	EA	7	6-10 years				
	Power Distribution	120 - Principal's Office	14	EA	7	10+ years				
	Walls - Concrete Block	120 - Principal's Office	133	SF	7	10+ years				
	Walls - Plaster/Drywall	120 - Principal's Office	339	SF	7	10+ years				
	Walls - Plaster/Drywall	120 - Principal's Office	3	SF	6	1-2 years				
	Ceiling - Lay-in	122 - Pantry	75	SF	7	10+ years				
	Floor - Tile	122 - Pantry	75	SF	7	6-10 years				
	Lighting - Lay-in	122 - Pantry	1	EA	7	6-10 years				
	Power Distribution	122 - Pantry	4	EA	7	10+ years				
	Walls - Concrete Block	122 - Pantry	144	SF	7	10+ years				
	Walls - Plaster/Drywall	122 - Pantry	80	SF	7	10+ years				
	Work SInk	122 - Pantry	1	EA	7	10+ years				
	Ceiling - Lay-in	126 - Mail Boxes	173	SF	7	10+ years				
	Ceiling - Lay-in	126 - Mail Boxes	2	SF	4	1-2 years	Water damage			
	Doors - Steel Doors incl hw	126 - Mail Boxes	2	EA	7	10+ years	ŭ			
	Floor - Carpet	126 - Mail Boxes	175	SF	7	6-10 years				
	Lighting - Lay-in	126 - Mail Boxes	3	EA	7	10+ years				
	Power Distribution	126 - Mail Boxes	4	EA	7	10+ years				
	Storage/ Closet	126 - Mail Boxes	64	SF	7	10+ years				
	Walls - Concrete Block	126 - Mail Boxes	203	SF	7	10+ years				
	Walls - Plaster/Drywall	126 - Mail Boxes	158	SF	7	10+ years				
	Ceiling - Lay-in	134 - Gym Office	115	SF	7	10+ years				
	Doors - Side-lite	134 - Gym Office	12	SF	7	10+ years				
	Doors - Steel Doors incl hw	134 - Gym Office	1	EA	7	10+ years				
	Floor - Tile	134 - Gym Office	115	SF	7	6-10 years				
	Lighting - Lay-in	134 - Gym Office	2	EA	7	6-10 years				
	Power Distribution	134 - Gym Office	10	EA	7	10+ years				
	Walls - Concrete Block	134 - Gym Office	284	SF	7	10+ years				
	Ceiling - Lay-in	141 - Engineer's Office	236	SF	7	10+ years				
	Doors - Steel Doors incl hw	141 - Engineer's Office	1	EA	7	10+ years				
	Floor - Tile	141 - Engineer's Office	236	SF	7	10+ years				
	Lighting - Lay-in	141 - Engineer's Office	4	ĒΑ	7	10+ years				
	Power Distribution	141 - Engineer's Office	18	EA	7	10+ years				
	Walls - Concrete Block	141 - Engineer's Office	525	SF	7	10+ years				
	Ceiling - Lay-in	144 - Lunchroom Manager Office (133)	74	SF	7	10+ years				
	Doors - Side-lite	144 - Lunchroom Manager Office (133)	25	SF	7	10+ years				
	Doors - Steel Doors incl hw	144 - Lunchroom Manager Office	1	EA	7	10+ years				



Catego	ry : Room		В	uilding	: Main		-
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Flace Tile/Object	(133)	7.4	0.5	7	0.40	
	Floor - Tile/Sheet	144 - Lunchroom Manager Office	74	SF	7	6-10 years	
	Lighting - Lay-in	(133) 144 - Lunchroom Manager Office	1	EA	7	6-10 years	
	Lighting - Lay-in	(133)	•	LA	,	0-10 years	
	Power Distribution	144 - Lunchroom Manager Office	12	EA	7	10+ years	
		(133)	· -		•	.o. you.o	
	Walls - Concrete Block	144 - Lunchroom Manager Office	181	SF	7	10+ years	
		(133)					
	Ceiling - Lay-in	174 - Cath/Cot Room in 176A	82	SF	7	10+ years	
	Doors - Steel Doors incl hw	174 - Cath/Cot Room in 176A	1	EA	6	0-1 year	Missing door handle and hardware
	Floor - Tile	174 - Cath/Cot Room in 176A	82	SF	7	10+ years	
	Lighting - Lay-in	174 - Cath/Cot Room in 176A	1	EA	6	10+ years	
	Power Distribution	174 - Cath/Cot Room in 176A	6	EA	7	10+ years	
	Walls - Concrete Block	174 - Cath/Cot Room in 176A	84	SF	7	10+ years	
	Walls - Plaster/Drywall	174 - Cath/Cot Room in 176A	66	SF	7	10+ years	
	Work SInk	174 - Cath/Cot Room in 176A	1	ĒΑ	7	10+ years	
	Ceiling - Lay-in	176A - Counselor Office	377	SF	7	10+ years	
	Doors - Side-lite	176A - Counselor Office	12	SF	7	10+ years	
	Doors - Steel Doors incl hw	176A - Counselor Office	1	EA	7	10+ years	
	Floor - Tile	176A - Counselor Office	377	SF	7	10+ years	
	Lighting - Lay-in	176A - Counselor Office	5	EA	7	10+ years	
	Lighting - Lay-in	176A - Counselor Office	1	EA	6	6-10 years	
	Power Distribution	176A - Counselor Office	14	EA	7	10+ years	
	Walls - Concrete Block	176A - Counselor Office	613	SF	7	-	
		176A - Counselor Office	274	SF		10+ years	
	Walls - Plaster/Drywall			SF EA	7	10+ years	
	Work SInk	176A - Counselor Office	1		7	10+ years	
	Ceiling - Lay-in	176C	126	SF	7	10+ years	
	Doors - Side-lite	176C	12	SF	7	10+ years	
	Doors - Steel Doors incl hw	176C	1	EA	7	10+ years	
	Floor - Carpet	176C	126	SF	7	6-10 years	
	Lighting - Lay-in	176C	2	EA	7	10+ years	
	Power Distribution	176C	14	EA	7	10+ years	
	Walls - Concrete Block	176C	78	SF	7	10+ years	
	Walls - Plaster/Drywall	176C	277	SF	7	10+ years	
	Ceiling - Lay-in	176D	148	SF	7	10+ years	
	Doors - Side-lite	176D	12	SF	7	10+ years	
	Doors - Steel Doors incl hw	176D	1	EA	7	10+ years	
	Floor - Carpet	176D	148	SF	7	6-10 years	
	Lighting - Lay-in	176D	2	EA	7	10+ years	
	Power Distribution	176D	14	EA	7	10+ years	
	Walls - Concrete Block	176D	196	SF	7	10+ years	
	Walls - Plaster/Drywall	176D	196	SF	7	10+ years	
	Ceiling - Lay-in	176E	150	SF	7	10+ years	
	20ga,		.00	٥.	•	10. 30010	



Catego	ry : Room		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	176E	12	SF	7	10+ years	
	Doors - Steel Doors incl hw	176E	1	EA	7	10+ years	
	Floor - Carpet	176E	150	SF	7	6-10 years	
	Lighting - Lay-in	176E	2	EA	7	10+ years	
	Power Distribution	176E	14	EA	7	10+ years	
	Walls - Concrete Block	176E	283	SF	7	10+ years	
	Walls - Plaster/Drywall	176E	59	SF	7	10+ years	
	Ceiling - Lay-in	217 - Library Work Room	300	SF	7	10+ years	
	Doors - Steel Doors incl hw	217 - Library Work Room	1	EA	7	10+ years	
	Floor - Carpet	217 - Library Work Room	300	SF	7	6-10 years	
	Lighting - Lay-in	217 - Library Work Room	4	EA	7	6-10 years	
	Power Distribution	217 - Library Work Room	14	EA	7	10+ years	
	Storage/ Closet	217 - Library Work Room	6	SF	7	10+ years	
	Walls - Concrete Block	217 - Library Work Room	108	SF	7	10+ years	
	Walls - Plaster/Drywall	217 - Library Work Room	435	SF	6	10+ years	Casework door falling off.
	Work SInk	217 - Library Work Room	1	EA	7	10+ years	G
	Ceiling - Exposed	320 - Faculty Lounge	175	SF	7	10+ years	
	Ceiling - Lay-in	320 - Faculty Lounge	490	SF	7	10+ years	
	Ceiling - Plaster/Drywall	320 - Faculty Lounge	70	SF	7	10+ years	
	Doors - Side-lite	320 - Faculty Lounge	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	320 - Faculty Lounge	1	EA	7	10+ years	
	Floor - Carpet	320 - Faculty Lounge	735	SF	6	6-10 years	
	Lighting - Lay-in	320 - Faculty Lounge	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	320 - Faculty Lounge	3	EA	7	10+ years	
	Power Distribution	320 - Faculty Lounge	20	EA	7	10+ years	
	Walls - Concrete Block	320 - Faculty Lounge	393	SF	7	10+ years	
	Walls - Plaster/Drywall	320 - Faculty Lounge	530	SF	7	10+ years	
	Work SInk	320 - Faculty Lounge	1	EA	7	10+ years	
		, ,				•	
_Gymnas							
	Bleacher Seating	133	57	EA	7	10+ years	
	Ceiling - Exposed	133	5,140	SF	7	10+ years	
	Doors - Steel Doors incl hw	133	7	EA	7	10+ years	
	Floor - Sport Flooring	133	5,040	SF	7	6-10 years	
	Floor - Terrazzo	133	100	SF	7	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	133	16	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	133	6	EA	7	6-10 years	
	Lighting - Wall Mounted	133	4	EΑ	7	6-10 years	
	Scoreboards	133	1	EA	7	10+ years	
	Sound System	133	1	EA	7	10+ years	
	Stage	133	700	SF	7	10+ years	
	Stage Curtain	133	3	EA	7	10+ years	
	Stage Lift	133	1	EA	7	10+ years	
	Stage Lighting System	133	1	EA	7	10+ years	
						-	



Catego	Category: Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage-Stairs - Terrazzo	133	53	LF	7	10+ years	
	Storage/ Closet	133	170	SF	7	10+ years	
	Walls - Concrete Block	133	5,900	SF	7	10+ years	
	Walls - Concrete Block	133	2,200	SF	7	10+ years	
	Walls - Masonry	133	1,000	SF	7	10+ years	
Kitchen					_		
	Ceiling - Lay-in	1st Floor	1,080	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,080	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Storage/ Closet	1st Floor	153	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,300	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	700	SF	7	10+ years	
Librani							
Library	Casework	2nd Floor	34	LF	7	10 L Voors	
	Casework Ceiling - Exposed	2nd Floor 2nd Floor	2,844	SF	7	10+ years	
						10+ years	
	Ceiling - Lay-in	2nd Floor	594	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	930	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	3	EA	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	4,348	SF	6	6-10 years	
	Floor - Carpet	2nd Floor	20	SF	4	0-1 year	Torn.
	Lighting - Lay-in	2nd Floor	11	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	29	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	180	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	2,844	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,748	SF	7	10+ years	
Lunch 8	Multipurpose Room						
<u> LUHCH (X</u>	Ceiling - Lay-in	151 - Dining Room	5,095	SF	7	10+ years	Max occupancy sign not posted
	Ceiling - Lay-in	151 - Dining Room	5,095	SF	4	1-2 years	Water damage
	Doors - Steel Doors incl hw	151 - Dining Room	11	EA	7	10+ years	vvator damage
	Floor - Terrazzo	151 - Dining Room	5,100	SF	7	6-10 years	
	Lighting - Lay-in	151 - Dining Room	5,100	EA	7	6-10 years	
			37			-	
	Lighting - Lay-in	151 - Dining Room		EA	7	6-10 years	
	Serving Line	151 - Dining Room	57	LF	7	10+ years	
	Storage/ Closet	151 - Dining Room	158	SF	7	10+ years	
	Walls - Concrete Block	151 - Dining Room	400	SF	7	10+ years	
	Walls - Concrete Block	151 - Dining Room	1,300	SF	7	10+ years	

Campus Name: Claremont Page: 12 of 39 Assessment Date: 11/01/2023



Catego	Category : Room			uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	151 - Dining Room	2,150	SF	7	10+ years	
	Walls - Structural Glazed Tile	151 - Dining Room	1,200	SF	7	10+ years	
	Ceiling - Lay-in	153 - Dishwash	190	SF	7	10+ years	Max occupancy sign not posted
	Doors - Steel Doors incl hw	153 - Dishwash	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	153 - Dishwash	190	SF	7	6-10 years	
	Lighting - Lay-in	153 - Dishwash	3	EA	7	6-10 years	
	Walls - Concrete Block	153 - Dishwash	477	SF	7	10+ years	
	Ceiling - Lay-in	300N	1,682	SF	7	10+ years	
	Doors - Steel Doors incl hw	300N	2	EA	7	10+ years	
	Floor - Tile	300N	1,682	SF	7	6-10 years	
	Lighting - Lay-in	300N	21	EΑ	7	6-10 years	
	Market Board	300N	15	LF	7	6-10 years	
	Storage/ Closet	300N	16	SF	5	10+ years	Ceiling tiles misplaced.
	Walls - Concrete Block	300N	902	SF	7	10+ years	
	Walls - Plaster/Drywall	300N	261	SF	7	10+ years	
_MDF_ID	E						
_	Doors - Steel Doors incl hw	227	1	EA	7	10+ years	
	Finishes	227	135	SF	7	10+ years	
	Other Cooling Unit	227	1	ĒΑ	5	6-10 years	CRAC unit.
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	44	SF	7	10+ years	
	Janitor's Closet	1st Floor	64	SF	7	10+ years	
	Janitor's Closet	1st Floor	50	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	20	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	288	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	107	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	80	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	320	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	150	SF	7	10+ years	
	Storage Room	1st Floor	262	SF	7	10+ years	
	Storage Room	1st Floor	400	SF	7	10+ years	
	Storage Room	1st Floor	406	SF	7	10+ years	
	Storage Room	1st Floor	30	SF	7	10+ years	
	Janitor's Closet	2nd Floor	40	SF	7	10+ years	
	Janitor's Closet	2nd Floor	35	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	48	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	4,060	SF	7	10+ years	
	Storage Room	2nd Floor	406	SF	7	10+ years	
	Janitor's Closet	3rd Floor	34	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	80	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	114	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	1,870	SF	7	10+ years	
	Modifically dervice Rooms	314 1 1001	1,070	O.	•	101 yours	

Campus Name: Claremont Page: 13 of 39 Assessment Date: 11/01/2023



Catego	ategory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Mechanical/ Service Rooms	3rd Floor	35	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	1,350	SF	7	10+ years	
	Storage Room	3rd Floor	312	SF	7	10+ years	
	Storage Room	3rd Floor	432	SF	7	10+ years	
	Storage Room	3rd Floor	294	SF	7	10+ years	
Prep Ro	om						
•	Casework	203A	14	LF	6	10+ years	Finish peeling
	Ceiling - Lay-in	203A	120	SF	7	10+ years	e p = 5g
	Doors - Steel Doors incl hw	203A	1	ĒΑ	7	10+ years	
	Floor - Tile	203A	120	SF	7	6-10 years	
	Lighting - Lay-in	203A	2	EA	7	6-10 years	
	Walls - Concrete Block	203A	293	SF	7	10+ years	
Restroor	m						
	Accessories	100B	67	SF	7	10+ years	
	Ceiling - Lay-in	100B	61	SF	7	10+ years	
	Ceiling - Lay-in	100B	6	SF	6	10+ years	
	Doors - Steel Doors incl hw	100B	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	100B	67	SF	7	10+ years	
	Floor Drain	100B	1	ĒΑ	7	10+ years	
	Lavatory	100B	1	EΑ	7	10+ years	
	Lighting - Lay-in	100B	1	EΑ	7	10+ years	
	Walls - Concrete Block	100B	137	SF	7	10+ years	
	Water Closet	100B	107	EA	7	10+ years	
	Accessories	102B	67	SF	7	10+ years	
	Ceiling - Lay-in	102B	67	SF	7	10+ years	
	Doors - Steel Doors incl hw	102B	1	EA	7	,	
		102B	67	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain					10+ years	
	Floor Drain	102B	1	EΑ	7	10+ years	
	Lavatory	102B	1	EΑ	7	10+ years	
	Lighting - Lay-in	102B	1	EA	7	10+ years	
	Walls - Concrete Block	102B	137	SF	7	10+ years	
	Water Closet	102B	1	EA	7	10+ years	
	Accessories	104B	67	SF	7	10+ years	
	Ceiling - Lay-in	104B	67	SF	7	10+ years	
	Doors - Steel Doors incl hw	104B	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	104B	67	SF	7	6-10 years	
	Floor Drain	104B	1	EA	7	10+ years	
	Lavatory	104B	1	EA	7	10+ years	
	Lighting - Lay-in	104B	1	EA	7	6-10 years	
	Walls - Concrete Block	104B	137	SF	6	10+ years	
	Water Closet	104B	1	EA	6	10+ years	
	Accessories	106B	67	SF	7	10+ years	

Campus Name: Claremont Page: 14 of 39 Assessment Date: 11/01/2023



Catego	Category : Room		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	106B	67	SF	7	10+ years	
	Doors - Steel Doors incl hw	106B	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	106B	67	SF	7	6-10 years	
	Floor Drain	106B	1	EA	7	10+ years	
	Lavatory	106B	1	EA	7	10+ years	
	Lighting - Lay-in	106B	1	EA	7	6-10 years	
	Walls - Concrete Block	106B	137	SF	6	10+ years	
	Water Closet	106B	1	EA	6	10+ years	
	Accessories	176A-1 Toilet	82	SF	7	10+ years	
	Ceiling - Lay-in	176A-1 Toilet	38	SF	7	10+ years	
	Ceiling - Plaster/Drywall	176A-1 Toilet	44	SF	7	10+ years	
	Doors - Steel Doors incl hw	176A-1 Toilet	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	176A-1 Toilet	82	SF	7	10+ years	
	Floor Drain	176A-1 Toilet	2	EA	7	10+ years	
	Lavatory	176A-1 Toilet	1	EA	7	10+ years	
	Lighting - Lay-in	176A-1 Toilet	1	EA	7	10+ years	
	Lighting - Lay-in	176A-1 Toilet	2	EA	7	10+ years	
	Showers	176A-1 Toilet	1	EA	7	10+ years	
	Walls - Concrete Block	176A-1 Toilet	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	176A-1 Toilet	75	SF	7	10+ years	
	Water Closet	176A-1 Toilet	1	EA	7	10+ years	
	Accessories	1st Floor - North Men	60	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - North Men	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - North Men	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - North Men	60	SF	7	6-10 years	
	Floor Drain	1st Floor - North Men	1	EA	7	10+ years	
	Lavatory	1st Floor - North Men	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - North Men	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor - North Men	125	SF	7	10+ years	
	Water Closet	1st Floor - North Men	1	ĒΑ	7	10+ years	
	Accessories	1st Floor - Principals	53	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Principals	53	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Principals	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Principals	53	SF	7	6-10 years	
	Floor Drain	1st Floor - Principals	1	ĒΑ	7	10+ years	
	Lavatory	1st Floor - Principals	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - Principals	1	ΕA	7	6-10 years	
	Walls - Concrete Block	1st Floor - Principals	200	SF	7	10+ years	
	Water Closet	1st Floor - Principals	1	EA	7	10+ years	
	Accessories	1st Floor - South	190	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - South	190	SF	6	6-10 years	
	Floor - Terrazzo	1st Floor - South	50	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - South	130	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - South	10	SF	4	0-1 year	Damaged.
	1 1001 The Octamic, 1 orderall	13t i 1001 - 00tti i	10	Oi.	7	o-i yeai	Damagea.

Campus Name: Claremont Page: 15 of 39 Assessment Date: 11/01/2023



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st Floor - South	1	EA	7	10+ years	
	Lavatory	1st Floor - South	3	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor - South	7	EA	7	10+ years	
	Partitions	1st Floor - South	2	EA	7	10+ years	
	Urinals	1st Floor - South	2	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor - South	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - South	270	SF	7	10+ years	
	Water Closet	1st Floor - South	1	EA	7	10+ years	
	Water Closet	1st Floor - South	1	EA	4	1-2 years	Toilet removed
	Accessories	1st Floor North	255	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor North	255	SF	7	10+ years	
	Floor - Terrazzo	1st Floor North	95	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor North	160	SF	7	6-10 years	
	Floor Drain	1st Floor North	1	EA	7	10+ years	
	Lavatory	1st Floor North	3	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor North	9	EA	7	6-10 years	
	Partitions	1st Floor North	4	EA	7	•	
	Walls - Concrete Block		· · · · · · · · · · · · · · · · · · ·	SF	7	10+ years	
		1st Floor North	278			10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor North	296	SF	7	10+ years	
	Water Closet	1st Floor North	4	EA	7	10+ years	
	Accessories	1st Floor North	255	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor North	255	SF	7	10+ years	
	Floor - Terrazzo	1st Floor North	95	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor North	150	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor North	10	SF	4	0-1 year	damaged
	Floor Drain	1st Floor North	1	EΑ	7	10+ years	
	Lavatory	1st Floor North	3	EΑ	6	10+ years	
	Lighting - Lay-in	1st Floor North	9	EΑ	7	6-10 years	
	Partitions	1st Floor North	2	EA	7	10+ years	
	Urinals	1st Floor North	2	EΑ	6	10+ years	
	Walls - Concrete Block	1st Floor North	278	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor North	296	SF	7	10+ years	
	Water Closet	1st Floor North	2	EΑ	6	10+ years	
	Accessories	1st Floor South	190	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor South	190	SF	6	6-10 years	
	Floor - Terrazzo	1st Floor South	50	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor South	140	SF	7	6-10 years	
	Floor Drain	1st Floor South	1	EA	7	10+ years	
	Lavatory	1st Floor South	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor South	7	EA	7	6-10 years	
	Partitions	1st Floor South	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor South	80	SF	7		
				SF SF		10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor South	270		7	10+ years	
	Water Closet	1st Floor South	3	EA	7	10+ years	

Campus Name: Claremont Page : 16 of 39 Assessment Date: 11/01/2023



Catego	ry : Room		В	uilding	: Main		
	B		0 "	11011	_ ·	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor South	1	EA	4	1-2 years	Out of order
	Accessories	2nd Floor - North	224	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - North	224	SF	6	6-10 years	
	Floor - Terrazzo	2nd Floor - North	64	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - North	150	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - North	10	SF	4	0-1 year	Damaged.
	Floor Drain	2nd Floor - North	1	EA	7	10+ years	
	Lavatory	2nd Floor - North	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor - North	7	EA	7	10+ years	
	Partitions	2nd Floor - North	2	EA	7	10+ years	
	Urinals	2nd Floor - North	2	EA	7	10+ years	Good condition
	Walls - Concrete Block	2nd Floor - North	128	SF	7	10+ years	
	Walls - Tile	2nd Floor - North	304	SF	7	10+ years	
	Water Closet	2nd Floor - North	2	EA	6	10+ years	
	Accessories	2nd Floor - North Unisex	40	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - North Unisex	38	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - North Unisex	2	SF	4	1-2 years	Water damage
	Doors - Steel Doors incl hw	2nd Floor - North Unisex	_ 1	EΑ	7	10+ years	Trate: damage
	Floor - Tile Ceramic/ Porcelain	2nd Floor - North Unisex	40	SF	7	10+ years	
	Floor Drain	2nd Floor - North Unisex	1	EA	7	10+ years	
	Lavatory	2nd Floor - North Unisex	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor - North Unisex	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor - North Unisex	87	SF	7	10+ years	
	Water Closet	2nd Floor - North Unisex	1	EA	7	10+ years	
	Accessories	2nd Floor - North Onisex 2nd Floor - South	242	SF	7	10+ years	
		2nd Floor - South	242	SF	6		
	Ceiling - Plaster/Drywall Floor - Terrazzo	2nd Floor - South	242 88	SF SF	-	10+ years	
				SF SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - South	154		7	10+ years	
	Floor Drain	2nd Floor - South	1	EΑ	7	10+ years	
	Lavatory	2nd Floor - South	3	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor - South	7	EΑ	7	10+ years	
	Partitions	2nd Floor - South	2	EA	7	10+ years	
	Urinals	2nd Floor - South	2	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor - South	128	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - South	304	SF	7	10+ years	
	Water Closet	2nd Floor - South	2	EA	6	10+ years	
	Accessories	2nd Floor - South Women	56	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor - South Women	56	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor - South Women	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - South Women	56	SF	7	6-10 years	
	Floor Drain	2nd Floor - South Women	1	EA	7	10+ years	
	Lavatory	2nd Floor - South Women	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor - South Women	1	ĒΑ	7	10+ years	
	Walls - Concrete Block	2nd Floor - South Women	119	SF	7	10+ years	
	Trails Control Diook	Zild i looi Goddi Wollion	113	5 1	,	ioi youis	

Campus Name: Claremont Page: 17 of 39 Assessment Date: 11/01/2023



Category : Room			Building : Main							
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Water Closet	2nd Floor - South Women	1	EA	7	10+ years				
	Accessories	2nd Floor North	224	SF	7	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor North	224	SF	6	6-10 years				
	Floor - Terrazzo	2nd Floor North	64	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor North	160	SF	7	10+ years				
	Floor Drain	2nd Floor North	1	EA	7	10+ years				
	Lavatory	2nd Floor North	3	EA	7	10+ years				
	Lighting - Lay-in	2nd Floor North	7	EA	7	6-10 years				
	Partitions	2nd Floor North	4	EA	7	10+ years				
	Walls - Concrete Block	2nd Floor North	128	SF	7	10+ years				
	Walls - Tile	2nd Floor North	304	SF	7	10+ years				
	Water Closet	2nd Floor North	4	EA	7	10+ years				
	Accessories	2nd Floor South	197	SF	7	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor South	197	SF	6	10+ years				
	Floor - Terrazzo	2nd Floor South	57	SF	7	6-10 years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor South	140	SF	6	6-10 years				
	Floor Drain	2nd Floor South	1	EA	7	10+ years				
	Lavatory	2nd Floor South	3	EA	6	10+ years				
	Lighting - Lay-in	2nd Floor South	7	EA	6	6-10 years				
	Partitions	2nd Floor South	4	EA	7	10+ years				
	Walls - Concrete Block	2nd Floor South	128	SF	7	10+ years				
	Walls - Tile	2nd Floor South	304	SF	7	10+ years				
	Water Closet	2nd Floor South	4	EA	6	10+ years				
	Accessories	3rd Floor - North Unisex	56	SF	7	10+ years				
	Ceiling - Lay-in	3rd Floor - North Unisex	54	SF	7	10+ years				
	Ceiling - Lay-in	3rd Floor - North Unisex	2	SF	4	1-2 years	Water damage			
	Doors - Steel Doors incl hw	3rd Floor - North Unisex	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd Floor - North Unisex	56	SF	7	10+ years				
	Floor Drain	3rd Floor - North Unisex	1	EA	7	10+ years				
	Lavatory	3rd Floor - North Unisex	1	EA	7	10+ years				
	Lighting - Lay-in	3rd Floor - North Unisex	1	EA	7	10+ years				
	Walls - Concrete Block	3rd Floor - North Unisex	149	SF	7	10+ years				
	Water Closet	3rd Floor - North Unisex	1	EA	7	10+ years				
	Accessories	3rd Floor - South Women	56	SF	7	10+ years				
	Ceiling - Lay-in	3rd Floor - South Women	56	SF	7	10+ years				
	Doors - Steel Doors incl hw	3rd Floor - South Women	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd Floor - South Women	56	SF	7	6-10 years				
	Floor Drain	3rd Floor - South Women	1	EA	7	10+ years				
	Lavatory	3rd Floor - South Women	1	EA	7	10+ years				
	Lighting - Lay-in	3rd Floor - South Women		EA	7	6-10 years				
	Walls - Concrete Block	3rd Floor - South Women	116	SF	7	10+ years				
	Walls - Concrete Block	3rd Floor - South Women	3	SF	5	1-2 years	Cracks			
	Water Closet	3rd Floor - South Women	1	EA	7	10+ years				
	Accessories	3rd Floor North	242	SF	7	10+ years				

Campus Name: Claremont Page: 18 of 39 Assessment Date: 11/01/2023



Catego	Category : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	3rd Floor North	242	SF	6	6-10 years			
	Floor - Terrazzo	3rd Floor North	88	SF	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor North	154	SF	7	6-10 years			
	Floor Drain	3rd Floor North	1	EA	7	10+ years			
	Lavatory	3rd Floor North	3	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor North	7	EA	7	6-10 years			
	Partitions	3rd Floor North	4	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor North	128	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor North	304	SF	7	10+ years			
	Water Closet	3rd Floor North	4	EA	7	10+ years			
	Accessories	3rd Floor North	197	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor North	190	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor North	7	SF	5	1-2 years	Water damage		
	Floor - Terrazzo	3rd Floor North	57	SF	7	6-10 years	3.		
	Floor - Tile	3rd Floor North	140	SF	7	6-10 years			
	Floor Drain	3rd Floor North	1	ĒΑ	7	10+ years			
	Lavatory	3rd Floor North	3	EΑ	7	10+ years			
	Lighting - Lay-in	3rd Floor North	7	EΑ	7	6-10 years			
	Partitions	3rd Floor North	2	EA	7	10+ years			
	Urinals	3rd Floor North	2	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor North	128	SF	7	10+ years			
	Walls - Tile	3rd Floor North	304	SF	7	10+ years			
	Water Closet	3rd Floor North	2	EA	7	10+ years			
	Accessories	3rd Floor South	224	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor South	224	SF	6	6-10 years			
	Floor - Terrazzo	3rd Floor South	57	SF	7	10+ years			
	Floor - Tile	3rd Floor South	167	SF	7	10+ years			
	Floor Drain	3rd Floor South	1	EA	7	10+ years			
	Lavatory	3rd Floor South	3	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor South	9	EA	7	6-10 years			
	Partitions	3rd Floor South	2	EA	7	10+ years			
	Urinals	3rd Floor South	2	EA	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor South	128	SF	7	10+ years			
	Walls - Tile	3rd Floor South	336	SF	7	10+ years			
	Water Closet	3rd Floor South	2	EA	7	10+ years			
	Accessories	3rd Floor South	224	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor South	220	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor South	4	SF	5	1-2 years	Water damage		
	Floor - Terrazzo	3rd Floor South	64	SF	7	6-10 years	vvater uarriage		
	Floor - Tile	3rd Floor South	160	SF	7	6-10 years			
	Floor Drain	3rd Floor South	1	EA	7	10+ years			
		3rd Floor South	3	EA	7	10+ years 10+ years			
	Lavatory Lighting - Lay-in	3rd Floor South	3 7	EA EA	7	•			
	Partitions	3rd Floor South	4	EA	7	6-10 years			
	r artitions	Sid Floor South	4	EA	,	10+ years			

Campus Name: Claremont Page: 19 of 39 Assessment Date: 11/01/2023



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Structural Glazed Tile	3rd Floor South	128	SF	7	10+ years				
	Walls - Tile	3rd Floor South	304	SF	7	10+ years				
	Water Closet	3rd Floor South	4	EA	7	10+ years				
	Accessories	Kitchen - Mens	56	SF	7	10+ years				
	Ceiling - Lay-in	Kitchen - Mens	56	SF	7	10+ years				
	Doors - Steel Doors incl hw	Kitchen - Mens	1	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Kitchen - Mens	56	SF	7	10+ years				
	Floor Drain	Kitchen - Mens	1	EA	7	10+ years				
	Lavatory	Kitchen - Mens	1	EA	7	10+ years				
	Lighting - Lay-in	Kitchen - Mens	1	EA	7	10+ years				
	Walls - Concrete Block	Kitchen - Mens	140	SF	7	10+ years				
	Water Closet	Kitchen - Mens	1	EA	7	10+ years				
	Accessories	Kitchen Womens	56	SF	7	10+ years				
	Ceiling - Lay-in	Kitchen Womens	48	SF	7	10+ years				
	Ceiling - Lay-in	Kitchen Womens	8	SF	4	1-2 years	Water damage			
	Doors - Steel Doors incl hw	Kitchen Womens	1	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Kitchen Womens	56	SF	7	6-10 years				
	Floor Drain	Kitchen Womens	1	EA	7	10+ years				
	Lavatory	Kitchen Womens	1	EA	7	10+ years				
	Lighting - Lay-in	Kitchen Womens	1	EA	7	6-10 years				
	Walls - Concrete Block	Kitchen Womens	146	SF	7	10+ years				
	Water Closet	Kitchen Womens	1	EA	7	10+ years				

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #100 (Kindergarten)						
	Casework	1st Floor	11	LF	7	10+ years	
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,156	SF	7	10+ years	
	Doors - Side-lite	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,156	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	968	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	230	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #101 (Special Education)						
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	520	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	

Campus Name: Claremont Page : 20 of 39 Assessment Date: 11/01/2023



Catego	ategory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	520	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	564	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #102 (Pre School)						
	Casework	1st Floor	21	LF	7	10+ years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,156	SF	7	10+ years	
	Doors - Side-lite	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,156	SF	7	•	
		1st Floor		EA		10+ years	
	Lighting - Lay-in	1st Floor	14 60	SF	7	10+ years	
	Storage/ Closet			SF SF	7	10+ years	
	Walls - Concrete Block	1st Floor	868		7	10+ years	
	Walls - Plaster/Drywall	1st Floor	330	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #103 (Office)						
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	520	SF	7	10+ years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	520	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	7	EΑ	7	10+ years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	564	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #104 (Kindergarten)						
	Casework	1st Floor	11	LF	7	10+ years	
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,156	SF	7	10+ years	
	Doors - Side-lite	1st Floor	24	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Steel Doors Incl hw Doors - Wood Doors inclu hw	1st Floor	2	EA	7		
				SF		10+ years	
	Floor - Tile Lighting - Lay-in	1st Floor 1st Floor	1,156 14	SF EA	7 7	10+ years 10+ years	
		TST FIGOR	1/1	- Δ	,	TH+ VASIS	



Catego	ategory : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	868	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	330	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #105 (Office)						
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	520	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	520	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	264	SF		-	
				SF SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550		7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #106 (Kindergarten)						
	Casework	1st Floor	29	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,156	SF	7	10+ years	
	Doors - Side-lite	1st Floor	24	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,156	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	868	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	330	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #107 (Regular Classroom)						
21000100	Casework	1st Floor	35	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	860	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
			12	Sr EA	7 7		
	Doors - Wood Doors inclu hw	1st Floor				10+ years	
	Floor - Tile	1st Floor	860	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	520	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	470	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2	SF	5	1-2 years	Missing cover plate
Classroo	om #108 (Computer Lab)						
	Casework	1st Floor	29	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,156	SF	7	10+ years	
	Doors - Side-lite	1st Floor	24	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,156	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	, 14	ĒΑ	7	6-10 years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,098	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	100	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
			·		•	.o. you.o	
Classroo	om #109 (Regular Classroom)	4 . 5					
	Casework	1st Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	860	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	860	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	756	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	236	SF	7	10+ years	
Classroo	om #200 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	843	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	3	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	Ŭ
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	846	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	9	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	Locked
	Walls - Concrete Block	2nd Floor	631	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	216	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		2300 W 0411 011(E11, Officago, 12 00030
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #202 (Regular Classroom)						
	Casework	2nd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	840	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	840	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	334	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	522	SF	7	10+ years	
Classroo	m #203 (Science)						
	Casework	2nd Floor	73	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,288	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,288	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	15	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,111	SF	7	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroo	m #204 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	846	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	846	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	334	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	522	SF	7	10+ years	
Classroo	m #205 (Special Education)						
	Casework	2nd Floor	34	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	560	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
			•	_, .	•	. o . youro	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	560	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EΑ	7	10+ years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	577	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	252	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	846	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
						-	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA SF	7	10+ years	
	Floor - Tile	2nd Floor	846		7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	334	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	522	SF	7	10+ years	
Classroo	om #207 (Special Education)						
	Casework	2nd Floor	52	LF	7	10+ years	
	Casework	2nd Floor	2	LF	6	0-1 year	Damage to door.
	Ceiling - Lay-in	2nd Floor	560	SF	7	10+ years	ŭ
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	560	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
				SF			
	Walls - Concrete Block	2nd Floor	267		7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	504	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	40	LF	4	0-1 year	Damage to doors.
	Ceiling - Lay-in	2nd Floor	846	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	846	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	334	SF	7	10+ years	
	vvalis - Cultulete Dluck	ZHU FIUUI	334	JГ	1	IUT YEAIS	

Campus Name: Claremont Page : 25 of 39 Assessment Date: 11/01/2023



Catego	ry : Classroom		В	uilding	: Main		
_			• 414			Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	518	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4	SF	6	10+ years	
lassroc	m #209 (Special Education)						
	Casework	2nd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	580	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	580	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	7	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	248	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	464	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
assroc	m #210 (Regular Classroom)						
	Casework	2nd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	843	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	3	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	20	LF	4	2-5 years	Trator damage
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	846	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	397	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	504	SF	7	10+ years	
assroo	m #211 (Regular Classroom)						
433100	Casework	2nd Floor	46	LF	4	0-1 year	Damage to doors.
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	840	SF	7	10+ years	Damage to doors.
	Chalk Board	2nd Floor 2nd Floor	14	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor 2nd Floor	14	SF	7	10+ years	
			14		7	-	
	Doors - Wood Doors inclu hw	2nd Floor		EA		10+ years	
	Floor - Tile	2nd Floor	840	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	383	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	504	SF	7	10+ years	
assroc	m #212 (Regular Classroom)						
	Casework	2nd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	846	SF	7	10+ years	



:ateno	ry : Classroom		R	uilding	· Main		2300 W 64th STREET, Chicago, IL 6063
Jaicgo	i y . Olassi oom			anamg	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Chalk Board	2nd Floor	14	LF	4	2-5 years	Commonto
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	846	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	6-10 years	Locked
	Walls - Concrete Block	2nd Floor	397	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	504	SF	7	10+ years	
laceroo	om #213 (Regular Classroom)						
iassiuu	Casework	2nd Floor	45	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	840	SF	7		
	Chalk Board	2nd Floor	12	LF		10+ years	
	Doors - Side-lite	2nd Floor	14	SF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	14	EA	7 7	10+ years	
		2nd Floor	840	SF	7	10+ years	
	Floor - Tile	2nd Floor 2nd Floor		SF EA		10+ years	
	Lighting - Lay-in	2nd Floor	12 16	LF	7 7	10+ years	
	Marker Board	2nd Floor	635	SF	7	6-10 years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor	252	SF	7	10+ years 10+ years	
	Walls - Flaster/Drywall	2110 1 1001	232	OI.	,	10+ years	
lassroc	om #214 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Casework	2nd Floor	4	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	844	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	16	LF	4	2-5 years	· ·
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	846	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	522	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	334	SF	7	10+ years	
lassroc	om #216 (Other Instructional Use)						
	Casework	2nd Floor	43	LF	7	10+ years	
	Casework	2nd Floor	2	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	846	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Orialit Board						

Campus Name: Claremont Page : 27 of 39 Assessment Date: 11/01/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	846	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	635	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	252	SF	7	10+ years	
Classroo	om #301 (Art Room)						
-	Casework	3rd Floor	31	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,400	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	4	1-2 years	Water damage
	Chalk Board	3rd Floor	28	LF	4	2-5 years	Trator damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,412	SF	7	6-10 years	
			•		7	•	
	Lighting - Lay-in	3rd Floor	15	EA		6-10 years	
	Storage/ Closet	3rd Floor	136	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,052	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
Classroo	om #302 (Regular Classroom)						
	Casework	3rd Floor	47	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	846	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroo	om #303 (Regular Classroom)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	841	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	Trator damage
	Doors - Wood Doors inclu hw	3rd Floor	14	EA	7	10+ years	
			846	SF			
	Floor - Tile	3rd Floor			7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	

Campus Name: Claremont Page : 28 of 39 Assessment Date: 11/01/2023



Outcgo	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroc	om #304 (Regular Classroom)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	846	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	5	6-10 years	
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroc	om #305 (Regular Classroom)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	846	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroc	om #306 (Regular Classroom)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	845	SF	7	6-10 years	
	Floor - Tile	3rd Floor	1	SF	4	1-2 years	Chipped tiles
	Lighting - Lay-in	3rd Floor	12	EΑ	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	Locked
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroc	om #307 (Regular Classroom)						
	Casework	3rd Floor	46	LF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	841	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	1-2 years	Cracked tile
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	846	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	13	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroo	om #308 (Regular Classroom)						
Cidooioc	Casework	3rd Floor	46	LF	7	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	-	
	Doors - Wood Doors inclu hw	3rd Floor	14	EA	7	10+ years	
				SF		10+ years	
	Floor - Tile	3rd Floor	846		7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroc	om #309 (Other Instructional Use)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	846	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	640	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	261	SF	7	10+ years	
Classroo	om #310 (Regular Classroom)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	14	EA	7	10+ years	
	Floor - Tile	3rd Floor		SF			
			841	SF SF	7	6-10 years	Chinned tiles
	Floor - Tile	3rd Floor	5		4	1-2 years	Chipped tiles
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	



	y : Classroom			uilding	. IVIAIII		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroor	m #312 (Regular Classroom)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	846	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroor	m #314 (Regular Classroom)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	846	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	352	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	522	SF	7	10+ years	
Classroor	m #324 (Other Instructional Use)						
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,519	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	, 10	SF	4	1-2 years	Water damage
	Chalk Board	3rd Floor	18	LF	4	2-5 years	3
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	1,529	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	13	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	315	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	1,453	SF	7	10+ years	
	Walls - Masonry	3rd Floor	324	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	476	SF	7	10+ years	



	y : Interior		В	uilding	: Main		
ou.ogo.	y :			ununig		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	,,,		•				
COITIGO	Ceiling - Lay-in	1st Floor	6,535	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	40	SF	7	10+ years	
	Doors - Side-lite	1st Floor	75	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	16	EA	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	7	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EΑ	7	10+ years	
	Floor - Terrazzo	1st Floor	6,575	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	97	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	4	EΑ	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	3	EA	7	6-10 years	
	Walls - Masonry	1st Floor	6,382	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	977	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - At Student Services	165	SF	7	10+ years	
	Doors - Side-lite	1st Floor - At Student Services	12	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor - At Student Services	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor - At Student Services	165	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor - At Student Services	3	EΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor - At Student Services	38	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - At Student Services	312	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - By Engineer's Office	305	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - By Engineer's Office	8	SF	4	0-1 year	Missing tile
	Doors - Steel Doors incl hw	1st Floor - By Engineer's Office	2	EΑ	7	10+ years	ge
	Floor - Tile/Sheet	1st Floor - By Engineer's Office	313	SF	7	10+ years	
	Lighting - Lay-in	1st Floor - By Engineer's Office	5	ĒΑ	7	10+ years	
	Walls - Concrete Block	1st Floor - By Engineer's Office	1,083	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	7,325	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	40	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	5	ĒΑ	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	7,365	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	7	6-10 years	
	Lighting - Lay-in	2nd Floor	100	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	4	EA	7	6-10 years	
	Walls - Masonry	2nd Floor	7,549	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	407	SF	7	10+ years	
	Ceiling - Exposed	3rd Floor	590	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	6,485	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	35	SF	4	1-2 years	Water damage
	Ceiling - Plaster/Drywall	3rd Floor	220	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	5	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EΑ	7	10+ years	
				— / \	•	10. ,00.0	



Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	95	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	10+ years	
	Lighting - Wall Mounted	3rd Floor	4	EA	7	10+ years	
	Student Lockers - One Tier	3rd Floor	160	EA	7	10+ years	
	Walls - Masonry	3rd Floor	7,558	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	250	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	407	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen - Between Staff Restrooms	38	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen - Between Staff Restrooms	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen - Between Staff Restrooms	38	SF	7	10+ years	
	Lighting - Lay-in	Kitchen - Between Staff Restrooms	1	EA	7	10+ years	
	Walls - Concrete Block	Kitchen - Between Staff Restrooms	130	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule 100 (on plan)	384	SF	7	10+ years	
	Doors - Side-lite	Vestibule 100 (on plan)	63	SF	7	10+ years	
	Doors - Store Front	Vestibule 100 (on plan)	4	EA	7	10+ years	
	Doors - Transom Window	Vestibule 100 (on plan)	16	SF	7	10+ years	
	Floor - Terrazzo	Vestibule 100 (on plan)	348	SF	7	6-10 years	
	Floor - Terrazzo	Vestibule 100 (on plan)	36	SF	7	6-10 years	
	Lighting - Lay-in	Vestibule 100 (on plan)	6	EA	7	6-10 years	
	Walls - Concrete Block	Vestibule 100 (on plan)	292	SF	7	10+ years	
	Walls - Masonry	Vestibule 100 (on plan)	292	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule 127 (on plan)	217	SF	7	10+ years	
	Doors - Side-lite	Vestibule 127 (on plan)	24	SF	7	10+ years	
	Doors - Steel Doors incl hw	Vestibule 127 (on plan)	4	EΑ	7	10+ years	
	Doors - Store Front	Vestibule 127 (on plan)	4	EA	7	10+ years	
	Doors - Transom Window	Vestibule 127 (on plan)	8	SF	7	10+ years	
	Floor - Terrazzo	Vestibule 127 (on plan)	217	SF	7	10+ years	
	Lighting - Lay-in	Vestibule 127 (on plan)	4	EA	7	10+ years	
	Walls - Concrete Block	Vestibule 127 (on plan)	435	SF	7	10+ years	
	Walls - Structural Glazed Tile	Vestibule 127 (on plan)	25	SF SF	7	10+ years	
	Ceiling - Plaster/Drywall Doors - Side-lite	Vestibule 151 (on plan)	364 18	SF SF	7 7	10+ years	
	Doors - Store Front	Vestibule 151 (on plan)		SF EA		10+ years	
		Vestibule 151 (on plan)	6 9	SF	7	10+ years	
	Doors - Transom Window Floor - Terrazzo	Vestibule 151 (on plan)	364	SF SF	7 7	10+ years	
	Lighting - Lay-in	Vestibule 151 (on plan) Vestibule 151 (on plan)	304 6	Sr EA	7	10+ years 10+ years	
	Walls - Concrete Block	Vestibule 151 (on plan) Vestibule 151 (on plan)	483	SF	7	10+ years 10+ years	
	Ceiling - Plaster/Drywall	Vestibule 151 (on plan) Vestibule 163 (on plan)	202	SF SF	7	10+ years 10+ years	
	Doors - Side-lite	Vestibule 163 (on plan)	18	SF SF	7	10+ years 10+ years	
	Doors - Steel Doors incl hw	Vestibule 163 (on plan)	2	EA	7	10+ years	
	Doors - Steel Doors Inc. Hw Doors - Store Front	Vestibule 163 (on plan)	4	EA	7	10+ years	
	Doors - Transom Window	Vestibule 163 (on plan)	8	SF	7	10+ years	
	Floor - Terrazzo	Vestibule 163 (on plan)	202	SF	7	10+ years	
	Lighting - Lay-in	Vestibule 163 (on plan)	4	EA	7	10+ years	
	Lighting - Lay-III	vestibule 100 (off plaif)	7	LA	,	10+ years	

Campus Name: Claremont Page : 33 of 39 Assessment Date: 11/01/2023



	ategory : Interior			uilding			
	Na Tama	Landin	0 "	11014	D	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Vestibule 163 (on plan)	278	SF	7	10+ years	
	Walls - Masonry	Vestibule 163 (on plan)	50	SF	7	10+ years	
ıfety							
,	Camera Viewing Station	Entire Building	4	EA	7	10+ years	
	Security Cameras	Entire Building	16	EA	7	6-10 years	
	Security Cameras	Entire Building	8	EA	7	6-10 years	
	Security Cameras	Entire Building	6	EA	7	6-10 years	
	Security Cameras	Entire Building	11	EA	7	6-10 years	
airs							
	Ceiling - Lay-in	Stair #1	890	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair #1	140	SF	7	10+ years	
	Floor - Terrazzo	Stair #1	988	SF	7	6-10 years	
	Handrails	Stair #1	260	LF	7	10+ years	
	Lighting - Lay-in	Stair #1	12	EA	7	6-10 years	
	Lighting - Wall Mounted	Stair #1	8	EA	7	6-10 years	
	Lighting - Wall Mounted	Stair #1	2	EA	5	1-2 years	Does not work.
	Stairs - Terrazzo	Stair #1	380	LF	7	10+ years	Dece not work.
	Walls - Concrete Block	Stair #1	2,078	SF	7	10+ years	
	Ceiling - Lay-in	Stair #2	600	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair #2	106	SF	7	10+ years	
	Floor - Terrazzo	Stair #2 Stair #2	676	SF	7	10+ years	
	Handrails			LF	7	•	
		Stair #2	254			10+ years	
	Lighting - Lay-in	Stair #2	8	EA	7	10+ years	
	Lighting - Pendent/Surface	Stair #2	2	EA	7	6-10 years	
	Lighting - Wall Mounted	Stair #2	7	EA	7	10+ years	
	Lighting - Wall Mounted	Stair #2	1	EA	5	1-2 years	Does not work.
	Stairs - Terrazzo	Stair #2	330	LF	7	10+ years	
	Walls - Concrete Block	Stair #2	1,205	SF	7	10+ years	
	Ceiling - Lay-in	Stair #3	470	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair #3	116	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair #3	12	SF	4	1-2 years	Water damage
	Floor - Terrazzo	Stair #3	598	SF	7	6-10 years	3
	Handrails	Stair #3	254	LF	7	10+ years	
	Lighting - Lay-in	Stair #3	8	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	Stair #3	2	EA	7	6-10 years	
	Lighting - Wall Mounted	Stair #3	7	EA	7	6-10 years	
	Lighting - Wall Mounted	Stair #3	1	EA	5	1-2 years	Does not work.
	Stairs - Terrazzo	Stair #3	330	LF			DOGS HOL WOLK.
	Walls - Concrete Block	Stair #3 Stair #3	818	SF	7 7	10+ years 10+ years	

Campus Name: Claremont Page : 34 of 39 Assessment Date: 11/01/2023



Building: Main Category: Interior

Recommend Item - Type Location UOM Group Quantity Rank Replacement Comments Elevator - Hydraulic Elevator 1st Floor EΑ 10+ years 7

Campus Name: Claremont Page: 35 of 39 Assessment Date: 11/01/2023



Category : Site Building : Site

Catego	ry : Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	- G						
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	10	EA	7	10+ years	
Fencing							
	Fencing - Chain Link	Entire Site	886	LF	6	10+ years	Quantity changed to match current observations
	Fencing - Guard Rail	Entire Site	20	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,546	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	8	LF	5	0-1 year	Broken gate
andsca	pe						
	Benches	Entire Site	6	EA	7	6-10 years	
	Irrigation	Entire Site	81,198	SF	6	6-10 years	
	Landscape - Grass	Entire Site	83,550	SF	7	6-10 years	Quantity changed to reflect the new landscaping area
	Landscape - Hardscape- Concrete	Entire Site	6,512	SF	6	10+ years	. •
	Landscape - Hardscape- Pavers	Entire Site	3,636	SF	7	10+ years	
	Lighting - Pole Mounted	Entire Site	26	EA	7	6-10 years	Added to match current observation
	Parkway trees	Entire Site	56	EA	7	6-10 years	
	Planting Beds/ Area	Entire Site	1,904	SF	7	6-10 years	
	Play Area - Grass	Entire Site	4,100	SF	7	10+ years	New 2023
	Play Area - Hardscape- Concrete	Entire Site	2,800	SF	7	10+ years	New 2023
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
arking	ot						
· ·	Concrete Curbs	Parking Lot- East	20	LF	6	10+ years	
	Interior Plantings	Parking Lot- East	25	LF	6	10+ years	
	Lighting - Pole Mounted	Parking Lot- East	4	EA	7	10+ years	
	Surface - Asphalt	Parking Lot- East	10,800	SF	6	6-10 years	
	Vehicular Screening	Parking Lot- East	218	LF	7	10+ years	
	Surface - Asphalt	Parking Lot- West	24,156	SF	6	6-10 years	
	Trash Compactor	Parking Lot- West	1	EΑ	6	6-10 years	Added to match current observation
	Trash Enclosure - Masonry	Parking Lot- West	830	SF	6	10+ years	
Playgrou	nd						
	Equipment - Pre K 3-5	South	2	EA	7	10+ years	
	Surface - Poured Surface	South	3,350	SF	7	10+ years	
Sidewalk	is .						
	Sidewalks - Internal Walks	Entire Site	465	LF	7	10+ years	
Sidewalk		Entire Site	465	LF	7	10+ years	



Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	20,463	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	4	1-2 years	Cracking/uneven sidewalk
_Signage							
	Flag Pole - Flag Pole	South East	2	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	South East	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	South East	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Claremont Page: 37 of 39 Assessment Date: 11/01/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Art Room	3rd Floor	301	301	1,412	144	44	N	Υ
Computer Lab	Computer Lab	2nd Floor	200	238	846	108	36		Υ
Computer Lab	Kindergarten	1st Floor	108	164	1,156	171	13	Y	Υ
Kindergarten	Kindergarten	1st Floor	100	180	1,156	171	13	Y	Υ
Kindergarten	Kindergarten	1st Floor	104	170	1,156	171	13	Y	Υ
Kindergarten	Kindergarten	1st Floor	106	167	1,156	171	13	Y	Υ
Office	Special Education	1st Floor	103	154	520	90	5	Y	Υ
Office	Special Education	1st Floor	105	155	520	90	5	Y	
Other Instructional Use	Music Room	3rd Floor	324	324	1,529	176	0	N	N
Other Instructional Use	Regular Classroom	2nd Floor	216	230	846	108	18		Υ
Other Instructional Use	Regular Classroom	3rd Floor	309	326	846	108	18		Υ
Pre School	Kindergarten	1st Floor	102	173	1,156	171	13	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	107	156	860	135	8	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	109	157	860	135	8	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	237	840	108	18		Υ
Regular Classroom	Regular Classroom	2nd Floor	204	236	846	108	18		Υ
Regular Classroom	Regular Classroom	2nd Floor	206	235	846	108	18		Υ
Regular Classroom	Regular Classroom	2nd Floor	208	234	846	108	18		Υ
Regular Classroom	Regular Classroom	2nd Floor	210	233	846	108	18		Υ
Regular Classroom	Regular Classroom	2nd Floor	211	223	840	108	18		Υ
Regular Classroom	Regular Classroom	2nd Floor	212	232	846	108	18		Υ
Regular Classroom	Regular Classroom	2nd Floor	213	224	840	108	18		Υ
Regular Classroom	Regular Classroom	2nd Floor	214	231	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	302	338	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	303	323	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	304	337	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	305	324	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	306	336	846	18	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	307	325	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	308	335	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	310	334	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	312	333	846	108	18		Υ
Regular Classroom	Regular Classroom	3rd Floor	314	332	846	108	18		Υ
Science	Science	2nd Floor	203	216	1,288	112	56	N	Υ
Special Education	Special Education	1st Floor	101	153	520	90	5	Υ	Υ
Special Education	Special Education	2nd Floor	205	220	560	72	12		Υ
Special Education	Special Education	2nd Floor	207	221	560	72	12		Υ
Special Education	Special Education	2nd Floor	209	222	580	72	24		Υ



Classroom Summary

-				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board

Campus Name: Claremont Page : 39 of 39 Assessment Date: 11/01/2023