

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1902	3	66,959
Addition	1957	1	5,345
Annex	2013	4	35,331
Campus Total			107,635

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 - East	1	EA	6	6-10 years	
	Exterior Doors - Side lite	1 - East	6	EA	6	6-10 years	
	Exterior Doors - Store Front	1 - East	3	EA	7	6-10 years	
	Exterior Stairs - Concrete	1 - East	18	LF	6	10+ years	
	Exterior Stairs - Stone	1 - East	10	LF	6	10+ years	
	Exterior Doors - Side lite	10 - North	6	EA	7	6-10 years	
	Exterior Doors - Store Front	10 - North	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	10 - North	2	EA	7	6-10 years	
	Exterior Stairs - Stone	10 - North	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	8 - West	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	8 - West	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	9 - Northwest	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	9 - Northwest	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Fire Escape 2 & 3	2	EA	4	0-1 year	Rusted
	Exterior Doors - Side lite	Fire Escape 2 & 3	1	EA	6	2-5 years	Added to match current observations
	Exterior Doors - Transom Lite	Fire Escape 2 & 3	1	EA	6	2-5 years	
	Exterior Stairs - Concrete	Fire Escape 2 & 3	6	LF	6	10+ years	
_Fire Esca	ape						
	Exterior Doors - Exterior Steel Door	2 and 3	2	EA	4	0-1 year	Rusted.
	Exterior Doors - Side lite	2 and 3	1	EA	6	2-5 years	
	Exterior Doors - Transom Lite	2 and 3	1	EA	6	2-5 years	



Catego	ry : Exterior		В	Building : Main					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Fire Escape	2 and 3	238	LF	5	1-2 years	Rusted throughout		
	Paints	2 and 3	238	LF	3	0-1 year	Rusted throughout.		
Foundati	on								
	Foundation - Masonry	Entire Building	680	LF	6	10+ years			
	Superstructure - Heavy Timber	Entire Building	63,332	SF	7	10+ years			
	Superstructure - Metal Deck/ Concrete	Entire Building	3,773	SF	7	10+ years			
	Topping								
Lighting									
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	12	EA	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	17	EA	6	6-10 years			
Roof Sys	stem								
•	Access Ladder - Metal	A - Main	1	EA	5	6-10 years	Fixed		
	Chimney - Brick Chimney- Concrete/ Mortar	A - Main	45	LF	6	10+ years			
	Liner					·			
	Chimney - Brick Chimney- Concrete/ Mortar	A - Main	20	LF	3	0-1 year	Extensive cracking/loose bricks		
	Liner								
	Coping - Stone	A - Main	863	LF	6	10+ years			
	Coping - Stone	A - Main	26	LF	4	0-1 year	Loose stone coping		
	Downspouts - Exterior Downspouts	A - Main	126	LF	6	6-10 years			
	Downspouts - Interior Downspouts	A - Main	120	LF	7	10+ years			
	Parapet - 16" - 30" Height	A - Main	608	LF	6	10+ years			
	Parapet - 16" - 30" Height	A - Main	6	LF	5	0-1 year	Spalled/cracked		
	Parapet - Parapet < 16" Height	A - Main	53	LF	6	10+ years			
	Parapet - Parapet > 30"	A - Main	192	LF	6	10+ years			
	Parapet - Parapet > 30"	A - Main	10	LF	5	1-2 years	Spalled/cracked		
	Parapet - Parapet > 30"	A - Main	20	LF	5	1-2 years	Spalled/cracked		
	Roof - EPDM/ Synthetic Rubber	A - Main	11,344	SF	6	2-5 years			
	Roof - EPDM/ Synthetic Rubber	A - Main	1,276	SF	4	0-1 year	The roofing material is detached from		
							the substrate along the entire parape		
							wall. Quantity changed to match		
	-				_		current observations		
	Roof Hatch - Metal	A - Main	1	EA	7	10+ years			
	Roof Structure - Heavy Timber	A - Main	12,620	SF	7	10+ years			
	Coping - Stone	B - Mid West Roofs	140	LF	6	10+ years			
	Downspouts - Exterior Downspouts	B - Mid West Roofs	60	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	B - Mid West Roofs	140	LF	6	6-10 years			
	Roof - EPDM/ Synthetic Rubber	B - Mid West Roofs	1,872	SF	6	2-5 years	Dode bloom the recent of the control		
	Roof - EPDM/ Synthetic Rubber	B - Mid West Roofs	480	SF	3	0-1 year	Bubbling throughout the parapet wall		
	Roof Hatch - Metal	B - Mid West Roofs	2	EA	3	1-2 years	Decommissioned		
	Roof Structure - Heavy Timber	B - Mid West Roofs	2,352	SF	6	10+ years			

Campus Name: Coonley Page : 2 of 42 Assessment Date: 11/06/2023



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Stone	C - Mid-Low West Roofs	34	LF	6	10+ years	
	Downspouts - Exterior Downspouts	C - Mid-Low West Roofs	42	LF	5	2-5 years	
	Parapet - Parapet < 16" Height	C - Mid-Low West Roofs	34	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	C - Mid-Low West Roofs	132	SF	5	2-5 years	
	Roof Structure - Heavy Timber	C - Mid-Low West Roofs	132	SF	7	10+ years	
	Coping - Clay Tile	D - boiler room	375	LF	6	10+ years	
	Downspouts - Exterior Downspouts	D - boiler room	22	LF	6	2-5 years	
	Parapet - Parapet < 16" Height	D - boiler room	375	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	D - boiler room	3,153	SF	5	2-5 years	
	Roof - EPDM/ Synthetic Rubber	D - boiler room	620	SF	3	0-1 year	Bubbling throughout the parapet wall.
	Roof Structure - Steel with Clay Tile Arch	D - boiler room	3,773	SF	6	10+ years	geageate parapeta
_Walls							
VVAIIO	Cornice - Cast Stone	Entire Building	532	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	532	LF	5	2-5 years	
	Exterior Walls - Brick	Entire Building	27,261	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	5	2-5 years	
	Exterior Walls - Brick	Entire Building Entire Building	120	SF	3	0-1 year	Open joints/shifting bricks
	Exterior Walls - Stone-Cut	Entire Building	6,012	SF	6	•	Open joints/smitting bricks
		Entire Building Entire Building	40	SF	4	10+ years	Challed/Creaking stone
	Exterior Walls - Stone-Cut	Entire Building	40	SF	4	1-2 years	Spalled/Cracking stone
_Windows							
	Guard - Guards perforated	Entire Building	962	SF	6	6-10 years	
	Lintels - Brick	Entire Building	50	LF	6	6-10 years	
	Lintels - Steel	Entire Building	204	LF	7	6-10 years	
	Lintels - Stone	Entire Building	390	LF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,330	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	5	6-10 years	
	Exit Signs - Lunchroom	Entire Building	1	EA	5	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	21	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Security System - CCTV	Entire Building	66,959	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	66,959	SF	5	6-10 years	
_Main Se	rvice						
_waii oe	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	10+ years	

Campus Name: Coonley Page : 3 of 42 Assessment Date: 11/06/2023



	Schools					•	4046 N Leavitt STREET, Chicago, IL 6061
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	120/208/3PH						
	PA System	Entire Building	66,959	SF	5	6-10 years	
	•	Ğ	•			•	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	17	EΑ	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	3	EΑ	7	10+ years	
	amp	3	_			, , , , , ,	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	10+ years	
	120/210 120/200	Zitaro Dananig	·	_, .	Ü	ioi youro	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EΑ	6	6-10 years	Annunciator.
	Fire Alarm Strobe Lights	Entire Building	66,959	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	66,959	SF	5	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	4	1-2 years	Over 35 years old not reliable
Dumn D	oom Assembly						
ump ix	Fire Pump - 25-50 hp	Sprinkler Room	1	EA	5	6-10 years	
	The Fullip - 25-50 lip	Spillikier Room	'	LA	3	0-10 years	
Sprinkle	r System						
•	Dry Sprinkler System	Entire Building	66,959	SF	6	10+ years	
	Sprinkler Heads	Entire Building	66,959	SF	7	10+ years	
	Sprinkler Piping	Entire Building	66,959	SF	6	10+ years	
	Opinikier i iping	Entire Building	00,333	Oi	O	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Conc	litioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	5	6-10 years	Serve evaporator fan coil units in offices.
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	5	6-10 years	Serve evaporator fan coil units in
	than 5 tons	11001	•	_, .	ŭ	o io youio	offices.
ir Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	6	6-10 years	Serves room 004.
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	6	6-10 years	Serves Engineer's Office.
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	5	6-10 years	Serves Main Building.
			·	 ·	ŭ	, Jul. J	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Double Delivery- Steam Coils - 45001 -						
	60000 cfm				_	0.40	
	Air Intake	Mechanical Room	1	ΕA	5	6-10 years	
	Auxiliaries - 45001 - 60000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	5	6-10 years	
	Missing or Existing Shaft						
	Zone Dampers	Mechanical Room	36	EA	5	6-10 years	
Boiler Sy	vstems						
701101 0)	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	6-10 years	
	Pressure Boiler - 76 - 100 HP	Bollof Room	-		Ū	o io youio	
	Chemical Feeder	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	1	EΑ	5	10+ years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EΑ	5	6-10 years	
	Steam- Low Pressure Boiler - 76 - 100 HP	Bollot Room	•		Ü	o ro youro	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	
	Steam- Low Pressure Boiler - 76 - 100 HP	Bolief Room		L/\	9	o to years	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	10+ years	
	Steam Traps	Boiler Room	25	EA	5	6-10 years	
	Vacuum Pump	Boiler Room	1	EA	5	6-10 years	GYM Vacuum pump is abandoned
	vacuum Fump	Boller Room	I	LA	5	0-10 years	now is served by RTU
							now to corved by rene
Gas Boo	ster						
	Gas Booster	Mechanical Room	2	EA	6	10+ years	
leat Exc	changers						
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	1	EA	7	10+ years	
	Туре					•	
- - - - -	Devices						
uniy	Unit Heater - Steam	Boiler Room	1	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	6	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	1	EΑ	5	6-10 years	Electrical wall heater functional
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	6-10 years	Electrical wall floater failetierial
	Odbinet ricators - With Flot Water Con	Entire Ballating	7		Ü	o to years	
empera	ture Control						
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	
	Pneumatic System	Entire Building	66,959	SF	5	6-10 years	
	Thermostats - Pneumatic	Entire Building	6	ĒΑ	5	6-10 years	Pneumatic thermostats are function
	Thermostats - Pneumatic	Entire Building	30	ΕA	5	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
entilatio							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	3	EA	5	6-10 years	
	CFM Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	6	10+ years	
	500 CFM	Entire building	'	LA	U	10+ years	
			_				
atego	ry : Plumbing		В	uilding	: Main	D	
roup	Itom Tuno	Location	Quantity	UOM	Rank	Recommend	Comments
roup	Item - Type	Location	Quantity	UCIVI	Kalik	Replacement	Comments
ot Wate		Doiler Doom	1	ΓΛ		6.10 voore	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
ping							
	Domestic Piping-Hot Water Return Lines	Entire Building	66,959	SF	4	2-5 years	Pipes are original and have clams
	Domestic Piping-Hot Water Return Risers	Entire Building	66,959	SF	4	2-5 years	Pipes are original and have clams
	Domestic Piping-Hot Water from Risers to	Entire Building	66,959	SF	4	2-5 years	Pipes are original and have clams
	Fixtures	Fatina Duildina	00.050	C.E.	4	0.5.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Dince are evisional and have alone
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	66,959	SF	4	2-5 years	Pipes are original and have clams
	Domestic Piping-Hot/Cold Water Supply	Entire Building	66,959	SF	4	2-5 years	Pipes are original and have clams
	(Risers)	Zitaro Dananig	00,000	O.	•	2 o youro	r ipos aro original and have slame
	Domestic Piping-Hot/Cold Water Supply	Entire Building	66,959	SF	4	2-5 years	Pipes are original and have clams
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	66,959	SF	5	6-10 years	
	Storm Piping	Entire Building	66,959	SF	5	6-10 years	
	Vent Piping	Entire Building	66,959	SF	5	6-10 years	
ımps							
шрѕ	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	10+ years	Under elevator.
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	10+ years	
	_		_			•	
atego	ry : Room		В	uilding	: Main	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	Ceiling - Exposed	002A Engineer's Office	214	SF	7	10+ years	
	Doors - Wood Doors inclu hw	002A Engineer's Office	2	EΑ	7	10+ years	
	Floor - Wood	002A Engineer's Office	214	SF	7	10+ years	
	Lighting - Pendent/Surface	002A Engineer's Office	4	EA	7	6-10 years	



Category : Room			Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Power Distribution	002A Engineer's Office	8	EA	7	10+ years				
	Walls - Masonry	002A Engineer's Office	288	SF	7	10+ years				
	Walls - Plaster/Drywall	002A Engineer's Office	288	SF	7	10+ years				
	AC Unit	100A	1	EA	7	6-10 years				
	Ceiling - Lay-in	100A	450	SF	6	10+ years				
	Doors - Wood Doors inclu hw	100A	2	EA	7	10+ years				
	Floor - Wood	100A	450	SF	7	10+ years				
	Lighting - Lay-in	100A	8	EA	7	6-10 years				
	Storage/ Closet	100A	6	SF	7	10+ years				
	Walls - Plaster/Drywall	100A	679	SF	6	10+ years				
	AC Unit	100B office	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	100B office	400	SF	6	10+ years				
	Doors - Side-lite	100B office	48	SF	6	10+ years				
	Doors - Transom Window	100B office	35	SF	6	10+ years				
	Doors - Wood Doors inclu hw	100B office	1	EA	6	10+ years				
	Floor - Wood	100B office	400	SF	7	10+ years				
	Lighting - Pendent/Surface	100B office	4	EA	7	6-10 years				
	Storage/ Closet	100B office	12	SF	7	10+ years				
	Walls - Plaster/Drywall	100B office	800	SF	6	10+ years				
	Work SInk	100B office	1	EA	7	6-10 years				
	AC Unit	300 F & G Office	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	300 F & G Office	416	SF	7	10+ years				
	Ceiling - Plaster/Drywall	300 F & G Office	4	SF	4	1-2 years	Water damage			
	Doors - Wood Doors inclu hw	300 F & G Office	2	EA	6	6-10 years				
	Floor - Tile	300 F & G Office	419	SF	6	6-10 years				
	Floor - Tile	300 F & G Office	1	SF	4	1-2 years	Missing tile on riser			
	Lighting - Pendent/Surface	300 F & G Office	4	EA	7	6-10 years	Good condition			
	Lighting - Pendent/Surface	300 F & G Office	1	EA	6	1-2 years	Relamp			
	Power Distribution	300 F & G Office	8	EA	6	10+ years				
	Walls - Plaster/Drywall	300 F & G Office	790	SF	6	6-10 years				
	Walls - Plaster/Drywall	300 F & G Office	10	SF	4	1-2 years	Large cracks			
	AC Unit	Basement Teachers Lounge	1	EA	7	6-10 years				
	Ceiling - Exposed	Basement Teachers Lounge	466	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Basement Teachers Lounge	2	EA	6	10+ years				
	Floor - Wood	Basement Teachers Lounge	466	SF	7	10+ years				
	Lighting - Pendent/Surface	Basement Teachers Lounge	4	EA	7	6-10 years				
	Power Distribution	Basement Teachers Lounge	8	EA	7	6-10 years				
	Walls - Metal Panel	Basement Teachers Lounge	693	SF	7	10+ years				
	Work SInk	Basement Teachers Lounge	1	EA	7	10+ years				
	Ceiling - Exposed	Basement- next to Engineer's Office	136	SF	7	10+ years				
	Floor - Wood	Basement- next to Engineer's Office	136	SF	7	10+ years				
	Lighting - Pendent/Surface	Basement- next to Engineer's Office	1	EA	7	10+ years				
	Walls - Masonry	Basement- next to Engineer's Office	153	SF	7	10+ years				
	Walls - Plaster/Drywall	Basement- next to Engineer's Office	72	SF	7	10+ years				



Catego	ry : Room		В	uilding	: Main		
				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	Main office first floor	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	Main office first floor	285	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main office first floor	1	EA	7	10+ years	
	Floor - Wood	Main office first floor	285	SF	7	10+ years	
	Lighting - Pendent/Surface	Main office first floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Main office first floor	692	SF	7	10+ years	
Library							
•	AC Unit	305 - Library	2	EA	7	6-10 years	
	Casework	305 - Library	12	LF	6	6-10 years	
	Ceiling - Lay-in	305 - Library	935	SF	7	10+ years	
	Doors - Transom Window	305 - Library	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	305 - Library	1	ĒΑ	7	10+ years	
	Floor - Wood	305 - Library	935	SF	7	10+ years	
	Lighting - Lay-in	305 - Library	12	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	305 - Library	1,411	SF	7	10+ years	
	Walls - Plaster/Drywall	305 - Library	10	SF	5	1-2 years	Large cracks
	wane racton by wan	coc Library		O.	Ü	. 2 yours	Large Gracile
MDF_ID	F						
	Doors - Wood Doors inclu hw	In Classroom 307	1	EA	7	10+ years	
	Finishes	In Classroom 307	80	SF	7	10+ years	
	Finishes	In Classroom 307	20	SF	5	2-5 years	
	Window AC Unit	In Classroom 307	1	EA	7	6-10 years	
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	7	SF	5	6-10 years	
	Janitor's Closet	2nd floor	7	SF	7	10+ years	
	Janitor's Closet	2nd floor	20	SF	7	10+ years	
	Air Intake Plenums	Support Spaces	566	SF	7	10+ years	
	Air Intake Plenums	Support Spaces	566	SF	7	10+ years	
	Boiler Room	Support Spaces	1,180	SF	7	10+ years	
	Coal Room	Support Spaces	494	SF	7	10+ years	
	Janitor's Closet	Support Spaces	22	SF	7	10+ years	
	Janitor's Closet	Support Spaces	22	SF	7	10+ years	
	Mechanical/ Service Rooms	Support Spaces	595	SF	7	10+ years	
	Mechanical/ Service Rooms	Support Spaces	408	SF	7	10+ years	
	Storage Room	Support Spaces Support Spaces	300	SF	7	10+ years	
	Storage Room	Support Spaces	500	SF	7	10+ years	
	Storage Room	Support Spaces	350	SF	7	10+ years	
	Storage Room Storage Room	Support Spaces	196	SF	5	2-5 years	
Destina	_						
Restroor		OOOD Francisco-de Office Tell (70		7	0.40	
	Accessories	002B Engineer's Office Toilet	72	SF	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	002B Engineer's Office Toilet	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	002B Engineer's Office Toilet	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	002B Engineer's Office Toilet	72	SF	7	10+ years	
	Lavatory	002B Engineer's Office Toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	002B Engineer's Office Toilet	1	EA	7	6-10 years	
	Showers	002B Engineer's Office Toilet	1	EA	7	6-10 years	
	Walls - Masonry	002B Engineer's Office Toilet	74	SF	7	10+ years	
	Walls - Plaster/Drywall	002B Engineer's Office Toilet	74	SF	7	10+ years	
	Water Closet	002B Engineer's Office Toilet	1	EA	7	10+ years	
	Accessories	004A boys	300	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	004A boys	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	004A boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	004A boys	300	SF	7	10+ years	
	Floor Drain	004A boys	1	EA	7	10+ years	
	Hand Dryer	004A boys	2	EA	7	6-10 years	
	Lavatory	004A boys	2	EA	7	10+ years	
	Lighting - Pendent/Surface	004A boys	4	EA	7	6-10 years	
	Partitions	004A boys	3	EA	7	10+ years	
	Urinals	004A boys	1	EA	7	6-10 years	
	Urinals	004A boys	2	EA	5	1-2 years	Not working
	Walls - Plaster/Drywall	004A boys	405	SF	7	10+ years	ŭ
	Walls - Tile Ceramic/ Porcelain	004A boys	221	SF	7	10+ years	
	Water Closet	004A boys	3	ĒA	7	10+ years	
	Accessories	004B girls	375	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	004B girls	375	SF	7	10+ years	
	Doors - Wood Doors inclu hw	004B girls	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	004B girls	375	SF	7	10+ years	
	Floor Drain	004B girls	1	ĒΑ	7	10+ years	
	Hand Dryer	004B girls	2	EA	7	6-10 years	
	Lavatory	004B girls	2	EA	7	10+ years	
	Lighting - Pendent/Surface	004B girls	4	ĒΑ	7	6-10 years	
	Partitions	004B girls	5	EA	7	10+ years	
	Walls - Plaster/Drywall	004B girls	500	SF	7	10+ years	
	Walls - Structural Glazed Tile	004B girls	253	SF	7	10+ years	
	Water Closet	004B girls	5	ĒΑ	7	10+ years	
	Accessories	006A women	300	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	006A women	3	SF	7	10+ years	
	Ceiling - Plaster/Drywall	006A women	297	SF	7	10+ years	
	Doors - Wood Doors inclu hw	006A women	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	006A women	300	SF	7	10+ years	
	Floor Drain	006A women	1	EA	7	10+ years	
	Hand Dryer	006A women	2	EA	7	6-10 years	
	Lavatory	006A women	2	EA	7	10+ years	
	Lighting - Pendent/Surface	006A women	2	EA	7	6-10 years	
	Lighting i chacht outlace	550/ (WOITIGH	2	L/\	,	o io years	



Category : Room		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	006A women	4	EA	7	10+ years	
	Walls - Plaster/Drywall	006A women	221	SF	7	10+ years	
	Walls - Plaster/Drywall	006A women	15	SF	6	6-10 years	
	Walls - Structural Glazed Tile	006A women	450	SF	7	10+ years	
	Water Closet	006A women	4	EA	7	10+ years	
	Accessories	006B men	300	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	006B men	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	006B men	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	006B men	300	SF	7	10+ years	
	Floor Drain	006B men	1	ĒΑ	7	10+ years	
	Hand Dryer	006B men	2	ΕA	7	6-10 years	
	Lavatory	006B men	2	ΕA	7	10+ years	
	Lighting - Pendent/Surface	006B men	3	ΕA	6	6-10 years	
	Partitions	006B men	1	ΕA	7	10+ years	
	Urinals	006B men	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	006B men	450	SF	7	10+ years	
	Walls - Structural Glazed Tile	006B men	222	SF	7	10+ years	
	Water Closet	006B men	1	EA	7	10+ years	
	Accessories	100C girls	86	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	100C girls	86	SF	7	10+ years	
	Doors - Wood Doors inclu hw	100C girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	100C girls	86	SF	7	10+ years	
	Floor Drain	100C girls	1	EA	7	10+ years	
	Hand Dryer	100C girls	1	EA	5	6-10 years	
	Lavatory	100C girls	1	EA	7	10+ years	
	Lighting - Pendent/Surface	100C girls	2	EA	7	6-10 years	
	Partitions	100C girls	1	EA	7	10+ years	
	Walls - Plaster/Drywall	100C girls	100	SF	7	10+ years	
	Walls - Flaster/Drywaii Walls - Structural Glazed Tile	100C girls	149	SF	7	10+ years	
	Water Closet	100C girls	149	EA	7	•	
	Accessories	100D boys	87	SF	7	10+ years 6-10 years	
	Ceiling - Plaster/Drywall		87 87	SF	7	-	
	Doors - Wood Doors inclu hw	100D boys 100D boys	1	EA	7	10+ years	
			87	SF		10+ years	
	Floor - Tile Ceramic/ Porcelain	100D boys 100D boys	1	SF EA	7 7	10+ years	
	Floor Drain		1	EA EA		10+ years	
	Hand Dryer	100D boys	1	EA EA	5	6-10 years	
	Lavatory	100D boys	1		7	10+ years	
	Lighting - Pendent/Surface	100D boys	2	EΑ	7	6-10 years	
	Partitions	100D boys	1	EA	7	10+ years	
	Walls - Plaster/Drywall	100D boys	110	SF	7	10+ years	
	Walls - Structural Glazed Tile	100D boys	100	SF	7	10+ years	
	Water Closet	100D boys	1	EA	7	10+ years	
	Accessories	101C - Classroom Toilet Room	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	101C - Classroom Toilet Room	43	SF	6	10+ years	



Category : Room			Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Wood Doors inclu hw	101C - Classroom Toilet Room	1	EA	6	10+ years				
	Floor - Terrazzo	101C - Classroom Toilet Room	43	SF	6	10+ years				
	Lavatory	101C - Classroom Toilet Room	1	EΑ	7	10+ years				
	Lighting - Pendent/Surface	101C - Classroom Toilet Room	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	101C - Classroom Toilet Room	92	SF	6	10+ years				
	Water Closet	101C - Classroom Toilet Room	1	EA	6	10+ years				
	Accessories	106A	78	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	106A	78	SF	7	10+ years				
	Doors - Wood Doors inclu hw	106A	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	106A	78	SF	7	10+ years				
	Lavatory	106A	1	EA	6	10+ years				
	Lighting - Pendent/Surface	106A	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	106A	151	SF	7	10+ years				
	Walls - Plaster/Drywall	106A	1	SF	5	1-2 years	Hole in wall			
	Water Closet	106A	1	EA	6	10+ years				
	Accessories	200A boys	245	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	200A boys	245	SF	7	10+ years				
	Doors - Wood Doors inclu hw	200A boys	1	EΑ	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	200A boys	245	SF	7	10+ years				
	Floor Drain	200A boys	1	EA	7	10+ years				
	Hand Dryer	200A boys	2	EA	7	10+ years				
	Lavatory	200A boys	2	EΑ	7	10+ years				
	Lighting - Lay-in	200A boys	3	EΑ	7	6-10 years				
	Partitions	200A boys	3	EA	7	10+ years				
	Urinals	200A boys	3	EA	7	10+ years				
	Walls - Plaster/Drywall	200A boys	400	SF	7	10+ years				
	Walls - Structural Glazed Tile	200A boys	163	SF	7	10+ years				
	Water Closet	200A boys	3	EA	7	10+ years				
	Accessories	200B girls	245	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	200B girls	245	SF	7	10+ years				
	Doors - Wood Doors inclu hw	200B girls	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	200B girls	245	SF	7	10+ years				
	Floor Drain	200B girls	1	EA	7	10+ years				
	Hand Dryer	200B girls	2	EΑ	7	10+ years				
	Lavatory	200B girls	2	EΑ	7	10+ years				
	Lighting - Lay-in	200B girls	3	EΑ	7	6-10 years				
	Partitions	200B girls	6	EΑ	7	10+ years				
	Walls - Plaster/Drywall	200B girls	400	SF	7	10+ years				
	Walls - Structural Glazed Tile	200B girls	205	SF	7	10+ years				
	Water Closet	200B girls	6	EA	7	10+ years				
	Accessories	200C mens	57	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	200C mens	57	SF	7	10+ years				
	Doors - Wood Doors inclu hw	200C mens	1	ĒΑ	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	200C mens	57	SF	7	10+ years				
			٠.		-	. ,				



Category : Room			В	uilding	Building : Main					
						Recommend				
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor Drain	200C mens	1	EA	7	10+ years				
	Lavatory	200C mens	1	EA	7	10+ years				
	Lighting - Pendent/Surface	200C mens	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	200C mens	57	SF	7	10+ years				
	Walls - Structural Glazed Tile	200C mens	64	SF	7	10+ years				
	Water Closet	200C mens	1	EA	7	10+ years				
	Accessories	200D womens	57	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	200D womens	57	SF	7	10+ years				
	Doors - Wood Doors inclu hw	200D womens	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	200D womens	57	SF	7	10+ years				
	Floor Drain	200D womens	1	EA	7	10+ years				
	Lavatory	200D womens	1	EA	7	10+ years				
	Lighting - Lay-in	200D womens	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	200D womens	57	SF	7	10+ years				
	Walls - Structural Glazed Tile	200D womens	64	SF	7	10+ years				
	Water Closet	200D womens	1	EA	7	10+ years				
	Accessories	300A boys	245	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	300A boys	245	SF	7	10+ years				
	Doors - Wood Doors inclu hw	300A boys	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	300A boys	245	SF	7	10+ years				
	Floor Drain	300A boys	1	EA	7	10+ years				
	Hand Dryer	300A boys	2	EA	7	10+ years				
	Lavatory	300A boys	2	EA	7	10+ years				
	Lighting - Lay-in	300A boys	3	EA	7	6-10 years				
	Partitions	300A boys	3	EA	7	10+ years				
	Urinals	300A boys	3	EA	7	10+ years				
	Walls - Plaster/Drywall	300A boys	400	SF	7	10+ years				
	Walls - Structural Glazed Tile	300A boys	205	SF	7	10+ years				
	Water Closet	300A boys	3	ĒA	7	10+ years				
	Accessories	300B girls	245	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	300B girls	243	SF	7	10+ years				
	Ceiling - Plaster/Drywall	300B girls	2	SF	5	1-2 years	Cracks			
	Doors - Wood Doors inclu hw	300B girls	1	EΑ	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	300B girls	245	SF	7	10+ years				
	Floor Drain	300B girls	1	EA	7	10+ years				
	Hand Dryer	300B girls	2	EΑ	7	10+ years				
	Lavatory	300B girls	2	EΑ	7	10+ years				
	Lighting - Lay-in	300B girls	3	EA	7	6-10 years				
	Partitions	300B girls	6	EA	7	10+ years				
	Walls - Plaster/Drywall	300B girls	400	SF	7	10+ years				
	Walls - Structural Glazed Tile	300B girls	205	SF	7	10+ years				
	Water Closet	300B girls	6	EA	7	10+ years				
	Accessories	300C mens	57	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	300C mens	57 57	SF SF	7	-				
	Ceiling - Flaster/Drywall	300C mens	57	SF	′	10+ years				

Campus Name: Coonley Page : 12 of 42 Assessment Date: 11/06/2023



Catego	ry : Room		В	uilding	: Main			
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	300C mens	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	300C mens	57	SF	7	10+ years		
	Floor Drain	300C mens	1	EΑ	7	10+ years		
	Lavatory	300C mens	1	EA	7	10+ years		
	Lighting - Lay-in	300C mens	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	300C mens	57	SF	7	10+ years		
	Walls - Structural Glazed Tile	300C mens	64	SF	7	10+ years		
	Water Closet	300C mens	1	EA	7	10+ years		
	Accessories	300D womens	57	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	300D womens	57	SF	7	10+ years		
	Doors - Wood Doors inclu hw	300D womens	1	EΑ	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	300D womens	57	SF	7	10+ years		
	Floor Drain	300D womens	1	EA	7	10+ years		
	Lavatory	300D womens	1	EΑ	7	10+ years		
	Lighting - Pendent/Surface	300D womens	1	EΑ	7	6-10 years		
	Walls - Plaster/Drywall	300D womens	57	SF	7	10+ years		
	Walls - Structural Glazed Tile	300D womens	64	SF	7	10+ years		
	Water Closet	300D womens	1	EΑ	7	10+ years		
	Accessories	Basement in Tank Room	36	SF	5	6-10 years		
	Ceiling - Exposed	Basement in Tank Room	36	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement in Tank Room	1	EA	6	10+ years		
	Floor - Epoxy/ Painted	Basement in Tank Room	36	SF	7	10+ years		
	Lighting - Wall Mounted	Basement in Tank Room	1	EA	7	10+ years		
	Walls - Masonry	Basement in Tank Room	76	SF	5	2-5 years		
	Water Closet	Basement in Tank Room	1	EA	7	10+ years		

Category : Classroom

Group Item - Type		Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #003 (Auditoriu	m)	2004	quantity	CC	rtanit	rtopiacomont	Commente
AC Units	,	Basement	1	EA	7	6-10 years	
Ceiling - Expose	ed	Basement	437	SF	7	10+ years	
Doors - Wood D	oors inclu hw	Basement	1	EA	7	10+ years	
Floor - Tile		Basement	437	SF	7	10+ years	
Lighting - Pend	ent/Surface	Basement	10	EA	7	10+ years	
Marker Board		Basement	26	LF	7	6-10 years	
Walls - Plaster/D	Drywall	Basement	756	SF	7	10+ years	
lassroom #004 (Other Ins	structional Use)						
AC Units	•	Basement	1	EA	7	6-10 years	Room size corrected
Ceiling - Lay-in		Basement	800	SF	7	10+ years	
Doors - Wood D		Basement	1	EA	7	10+ years	
Floor - Concrete	Epoxy/ Painted	Basement	800	SF	7	10+ years	
Lighting - Pende		Basement	8	EA	7	10+ years	

Building: Main

Campus Name: Coonley Page : 13 of 42 Assessment Date: 11/06/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	Basement	10	LF	7	6-10 years	
	Storage/ Closet	Basement	180	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,026	SF	7	10+ years	
Classroo	om #005 (Office)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Exposed	Basement	466	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	466	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	600	SF	7	10+ years	
Classroo	om #006 (Art Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Exposed	Basement	1,295	SF	7	10+ years	
	Floor - Tile	Basement	1,295	SF	6	10+ years	
	Kiln	Basement	1,233	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,340	SF	7	10+ years	
	Work Sink	Basement	2	EA	7	10+ years	
Classroo	om #007 (Store Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	960	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Wood	Basement	960	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	7	6-10 years	
	Marker Board	Basement	20	LF	7	6-10 years	
	Storage/ Closet	Basement	60	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	890	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	om #008 (Special Education)						
21.2001.00	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Exposed	Basement	440	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	440	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement	2	EA	6	6-10 years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Walls - Concrete Block	Basement	511	SF	7	10+ years	
			189	SF SF	7	-	
	Walls - Masonry	Basement	189	SF	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #101 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	38	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	825	SF	6	10+ years	
	Floor - Tile	1st Floor	5	SF	4	1-2 years	Tiles Cracking
	Lighting - Pendent/Surface	1st Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,316	SF	6	10+ years	
	·					-	
Classroo	m #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	860	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,420	SF	6	10+ years	
01	"400 (D						
Classroo	m #103 (Regular Classroom)	4 . 5				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Storage/ Closet	1st Floor	155	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,421	SF	6	10+ years	
Classroo	m #104 (Regular Classroom)						
CIGGSIOU	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	860	SF	6	10+ years	
		1001	000	٥.	•	,	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Storage/ Closet	1st Floor	78	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,421	SF	6	10+ years	
Classroc	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood Bools inclu hw	1st Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
				LF		•	
	Marker Board	1st Floor	28 155	SF	7 7	6-10 years	
	Storage/ Closet	1st Floor		SF SF		10+ years	
	Walls - Plaster/Drywall	1st Floor	1,424	SF	6	10+ years	
Classroc	om #106 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,007	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,007	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,489	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #107 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	860	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	860	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	155	SF	7	10+ years	
	SICIACE/ CIOSEI	ISLEIOOF	155	٦r	1	ru+ vears	



Catego	ory : Classroom		В	uilding	: Main		TOTO IN ECONIC OTTLEET, Officago, IE 00010
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,421	SF	6	10+ years	
Classroo	om #108 (Kindergarten)						
<u> </u>	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Bools Ilicia IIW	1st Floor	840	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7		
		1st Floor	192	SF		6-10 years	
	Storage/ Closet				7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,420	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	5	2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor	860	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	860	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	155	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,416	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	872	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Cracks
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Clacks
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu Tw	2nd Floor 2nd Floor	877	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor		EA	7	,	
	Marker Board	2nd Floor 2nd Floor	12 18	LF	7	6-10 years 6-10 years	
	Storage/ Closet	2nd Floor 2nd Floor	120	SF	, 5		
				SF SF	5 7	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	1,420	35	1	10+ years	
_Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	852	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	852	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	155	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,421	SF	6	6-10 years	
Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	859	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	859	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	78	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,421	SF	6	6-10 years	
Classroc	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	852	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Wood	2nd Floor	852	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	155	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,416	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	4	1-2 years	Large crack
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	930	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	6	SF	5	1-2 years	Cracks
	Chalk Board	2nd Floor	8	LF	4	2-5 years	0.0000
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	936	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	78	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,421	SF	6	6-10 years	
	vvalis - i lastei/DiyWall	Z110 1 1001	1,421	3F	O	0-10 years	



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #207 (Regular Classroom)	. —					
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	860	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	860	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	155	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,401	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Large cracks
`laceroo	om #208 (Regular Classroom)						
μασσιυί	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	7	•	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Doors inclu riw	2nd Floor 2nd Floor	840	SF	6	10+ years 6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7		
	Marker Board	2nd Floor 2nd Floor	24			6-10 years	
				LF	7	6-10 years	
	Storage/ Closet	2nd Floor	192	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,421	SF	6	6-10 years	
lassroc	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	860	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	860	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	155	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,419	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	1-2 years	Cracked paint
	·					•	•
Classroc	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	854	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	858	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	96	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,421	SF	6	6-10 years	
Classroo	om #303 (Science Lab Level 3)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	50	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	852	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Eve Wash Station	3rd Floor	1	EA	7	6-10 years	
	,		852	SF		•	
	Floor - Tile Gas Line	3rd Floor		Sr EA	7	10+ years	
		3rd Floor	2		6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	155	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	21	SF	4	0-1 year	Large crack
	Work Sink	3rd Floor	3	EA	7	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	859	SF	7	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	859	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	78	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,421	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	854	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	vvater damage
		3rd Floor		SF	7	•	
	Floor - Wood		859			10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	155	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,416	SF	7	10+ years	



XIII S	Schools					<u> </u>	4046 N Leavitt STREET, Chicago, IL 6061
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	5	SF	4	1-2 years	Water damage
lassroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	860	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	860	SF	6	6-10 years	
	Lighting - Chandelier, Incandescent	3rd Floor	3	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	ΕA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	155	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,421	SF	7	10+ years	
	Walle Flasion Bry Wall	010 1 1001	1,121	O.	•	101 youro	
lassroc	om #308 (Regular Classroom)	3rd Floor			7	C 10	
	AC Units		1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	840	SF EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1		7	10+ years	
	Floor - Wood	3rd Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	192	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,421	SF	7	10+ years	
atego	ry : Interior		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor	• •	Location	Quantity	OOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor Corridor	2,574	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor Corridor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor Corridor	2,574	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Corridor	24	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor Corridor	2,187	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor Corridor	2,574	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor Corridor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor Corridor	2,574	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor Corridor	24	EA	7	6-10 years	Good condition
	Walls - Plaster/Drywall	2nd Floor Corridor	2,187	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor Corridor	2,274	SF	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor Corridor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor Corridor	524	SF	7	10+ years	
	Floor - Wood	3rd Floor Corridor	1,750	SF	7	10+ years	
			•			•	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor Corridor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor Corridor	2,187	SF	7	10+ years	
Safety							
,	Camera Viewing Station	Main building	1	EA	7	10+ years	
	Security Cameras	Main building	12	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North Stair	300	SF	6	10+ years	
	Floor - Tile	North Stair	360	SF	7	10+ years	
	Handrails	North Stair	200	LF	7	10+ years	
	Lighting - Pendent/Surface	North Stair	7	EA	6	6-10 years	
	Stairs - Rubber	North Stair	96	LF	6	10+ years	
	Walls - Plaster/Drywall	North Stair	674	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South Stairs	300	SF	6	10+ years	
	Floor - Tile	South Stairs	360	SF	6	10+ years	
	Handrails	South Stairs	200	LF	7	10+ years	
	Lighting - Pendent/Surface	South Stairs	7	EA	6	6-10 years	
	Stairs - Rubber	South Stairs	96	LF	6	10+ years	
	Walls - Plaster/Drywall	South Stairs	674	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West Stairs	300	SF	6	10+ years	
	Floor - Tile	West Stairs	300	SF	6	10+ years	
	Handrails	West Stairs	30	LF	7	10+ years	
	Lighting - Pendent/Surface	West Stairs	4	EA	6	6-10 years	
	Stairs - Rubber	West Stairs	15	LF	6	10+ years	
	Walls - Plaster/Drywall	West Stairs	546	SF	6	10+ years	
	Walls - Structural Glazed Tile	West Stairs	546	SF	6	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	



Category : Exterior Building : Addition

	ry : Exterior	Building : Addition							
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ntrance									
	Entrance Control - Audio and Video	2 - East	1	EA	7	6-10 years			
	Exterior Doors - Store Front	2 - East	4	EA	6	6-10 years			
	Exterior Doors - Transom Lite	2 - East	4	EA	6	6-10 years			
	Ramp Handrail - Steel_Ramp Handrail	2 - East	32	LF	7	10+ years			
	Ramps - Concrete	2 - East	16	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	3	1	EA	6	6-10 years			
	Exterior Stairs - Concrete	3	9	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	3A - Southwest	2	EA	6	6-10 years			
oundati	on								
	Foundation - Concrete	Entire Building	245	LF	7	10+ years			
	Superstructure - Steel	Entire Building	5,136	SF	7	10+ years			
ighting									
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	6-10 years			
oof Sys	stem								
	Access Ladder - Metal	E - Main	1	EΑ	7	6-10 years			
	Coping - Stone	E - Main	244	LF	7	10+ years			
	Downspouts - Interior Downspouts	E - Main	188	LF	7	6-10 years			
	Parapet - Parapet < 16" Height	E - Main	244	LF	7	10+ years			
	Roof - EPDM/ Synthetic Rubber	E - Main	3,360	SF	4	1-2 years	Soft spots throughout the roof		
	Roof Structure - Steel / Metal Deck/	E - Main	3,360	SF	6	10+ years			
	Concrete Topping					•			
	Coping - Stone	F - Lower Roofs	138	LF	7	10+ years			
	Downspouts - Interior Downspouts	F - Lower Roofs	24	LF	6	6-10 years	Quantity changed to match curren observations		
	Parapet - Parapet < 16" Height	F - Lower Roofs	138	LF	7	10+ years	obcorvations		
	Roof - EPDM/ Synthetic Rubber	F - Lower Roofs	1,676	SF	5	2-5 years			
	Roof - EPDM/ Synthetic Rubber	F - Lower Roofs	100	SF	4	1-2 years	Bubbling		
	Roof Structure - Steel / Metal Deck/	F - Lower Roofs	1,776	SF	7	10+ years	Bubbinig		
	Concrete Topping	1 Lower Roote	1,7.7.0	O.	·	101 youro			
/alls									
	Exterior Walls - Brick	Entire Building	5,078	SF	7	10+ years			
	Exterior Walls - Brick	Entire Building	320	SF	4	0-1 year	Open joints		
/indows	3								
	Guard - Guards perforated	Entire Building	116	SF	6	6-10 years			
	Lintels - Steel	Entire Building	26	LF	6	6-10 years			

Campus Name: Coonley Page : 23 of 42 Assessment Date: 11/06/2023



Catego	ry : Exterior		В	uildina	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Windows - Sash Aluminum Double-pane	Entire Building	148	SF	6	6-10 years	
Catego	ry : Electrical		В	uildina	: Additio	on	
Calcgo	ry . Electrical			unung	. Additiv	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ncy System		,				
Linorgo	Security System - Intrusion Detection	Electrical Room	5,345	SF	5	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	2,543	EA	7	6-10 years	
	Stairs	Entire building	2	LA	,	0-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	6	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	5,345	SF	6	6-10 years	
	Emergency A/C Fower - Gym	Entire Building	5,545	SF	O	6-10 years	
Main Se	rvice						
	PA System	Entire Building	5,345	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding			
				<u> </u>		Recommend	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	-	Location	Quantity	UOM	Rank		Comments
•	m					Replacement	Comments
•	-	Location Entire Building Entire Building	Quantity 5,345 5,345	SF SF	Rank 6 5		Comments
Fire Alar	m Fire Alarm Strobe Lights Fire Alarm_System	Entire Building	5,345 5,345	SF SF	6 5	10+ years 6-10 years	Comments
Fire Alar	m Fire Alarm Strobe Lights	Entire Building	5,345 5,345	SF SF	6	10+ years 6-10 years	Comments
Fire Alar	mFire Alarm Strobe Lights Fire Alarm_System ry: Mechanical	Entire Building Entire Building	5,345 5,345 B	SF SF uilding	6 5 : Additi o	10+ years 6-10 years On Recommend	
Fire Alar Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type	Entire Building	5,345 5,345	SF SF	6 5	10+ years 6-10 years	
Fire Alar Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type lling Systems	Entire Building Entire Building Location	5,345 5,345 B Quantity	SF SF uilding UOM	6 5 : Addition	10+ years 6-10 years on Recommend Replacement	Comments
Fire Alar Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type lling Systems Air Handling Unit- Package Single Zone-	Entire Building Entire Building	5,345 5,345 B	SF SF uilding	6 5 : Additi o	10+ years 6-10 years On Recommend	Comments
Fire Alar Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type Iling Systems Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 8001-12000 cfm	Entire Building Entire Building Location Mechanical Room	5,345 5,345 B Quantity	SF SF uilding UOM	6 5 : Additional Rank	10+ years 6-10 years on Recommend Replacement	Comments
Fire Alar Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type lling Systems Air Handling Unit- Package Single Zone-	Entire Building Entire Building Location	5,345 5,345 B Quantity	SF SF uilding UOM	6 5 : Addition	10+ years 6-10 years on Recommend Replacement	Comments
Fire Alar Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type lling Systems Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 8001-12000 cfm Roof Top Unit-Single Zone-Roof Mounted-	Entire Building Entire Building Location Mechanical Room	5,345 5,345 B Quantity	SF SF uilding UOM	6 5 : Additional Rank	10+ years 6-10 years on Recommend Replacement	
Fire Alar Catego Group Air Hanc	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type Iling Systems Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 8001-12000 cfm Roof Top Unit-Single Zone-Roof Mounted-Gas Heating and DX Cooling Coil - 11 - 20 tons	Entire Building Entire Building Location Mechanical Room	5,345 5,345 B Quantity	SF SF uilding UOM	6 5 : Additional Rank	10+ years 6-10 years on Recommend Replacement	Comments
Fire Alar Catego Group	Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type Iling Systems Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 8001-12000 cfm Roof Top Unit-Single Zone-Roof Mounted-Gas Heating and DX Cooling Coil - 11 - 20 tons	Entire Building Entire Building Location Mechanical Room	5,345 5,345 B Quantity	SF SF uilding UOM	6 5 : Additional Rank	10+ years 6-10 years on Recommend Replacement	Comments

Campus Name: Coonley Page : 24 of 42 Assessment Date: 11/06/2023



Catego	Category : Mechanical			Building : Addition					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
•	ature Control	Location	Quantity	OO!!!	Runn	Ropidoomont			
•	Electric Controls	1st Floor	2,406	SF	6	10+ years			
	Electric Thermostat	1st Floor	1	EA	6	10+ years			
_Ventilati	on								
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	5	6-10 years			

Category: Plumbing Building: Addition

Group Piping	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storm Piping	Entire Building	5,345	SF	6	10+ years	

Building: Addition Category: Room

Craun	Hom Type	Lagation	Quantity	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	Gym Office - Inside of Storage Room	50	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Office - Inside of Storage Room	1	EA	7	10+ years	
	Floor - Tile	Gym Office - Inside of Storage Room	50	SF	7	10+ years	
	Lighting - Pendent/Surface	Gym Office - Inside of Storage Room	1	EA	7	6-10 years	
	Walls - Concrete Block	Gym Office - Inside of Storage Room	103	SF	7	10+ years	
_Gymnas	iia						
	Ceiling - Splined	Ground	2,336	SF	6	6-10 years	Max occupancy sign not posted
	Ceiling - Splined	Ground	50	SF	4	1-2 years	Broken and missing tiles throughout
	Ceiling - Splined	Ground	20	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	Ground	4	EA	7	10+ years	
	Floor - Wood	Ground	2,406	SF	7	10+ years	
	Lighting - Lay-in	Ground	7	EA	6	6-10 years	
	Scoreboards	Ground	1	EA	7	10+ years	
	Sound System	Ground	1	EA	7	10+ years	
	Stage	Ground	449	SF	6	6-10 years	
	Stage Curtain	Ground	6	EA	7	10+ years	
	Stage Lift	Ground	1	EA	7	10+ years	
	Stage Lighting System	Ground	1	EA	7	10+ years	



Building: Addition Category: Room

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	Ground	125	SF	7	10+ years	
	Walls - Concrete Block	Ground	3,552	SF	7	10+ years	

Category: Interior Building: Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	,		<u>-</u>			•	
	Ceiling - Plaster/Drywall	Gymnasium Lobby	408	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gymnasium Lobby	8	EA	6	10+ years	
	Drinking Fountains - Single Fountain	Gymnasium Lobby	3	EA	7	10+ years	
	Floor - Terrazzo	Gymnasium Lobby	408	SF	7	10+ years	
	Lighting - Lay-in	Gymnasium Lobby	4	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Gymnasium Lobby	750	SF	7	10+ years	

Campus Name: Coonley Page : 26 of 42 Assessment Date: 11/06/2023



Category : Exterior Building : Annex

Jatego	ry : Exterior		В	ullaing	: Annex		
`	Hom Type	Location	Ouantitu	LIOM	Donk	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
intrance							
	Entrance Control - Audio and Video	4 - South	1	EA	7	6-10 years	
	Exterior Doors - Side lite	4 - South	1	EΑ	7	10+ years	
	Exterior Doors - Store Front	4 - South	2	EA	7	10+ years	
	Power Door Operator and Controls	4 - South	1	EA	7	6-10 years	
	Exterior Doors - Side lite	5 - West	1	EA	7	10+ years	
	Exterior Doors - Store Front	5 - West	2	EA	6	10+ years	
	Entrance Control - Audio and Video	6 - North	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	6 - North	1	EA	7	10+ years	
	Entrance Control - Audio and Video	7 - West	1	EA	7	6-10 years	
	Exterior Doors - Store Front	7 - West	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Chiller	2	EA	7	10+ years	Added to match current observation
oundati	on						
	Foundation - Concrete	Entire Building	349	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	10,299	SF	7	10+ years	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	10+ years	
Roof Sys	etem						
	Access Ladder - Metal	H - Main	1	EA	7	10+ years	
	Coping - Metal	H - Main	302	LF	7	10+ years	
	Coping - Stone	H - Main	133	LF	7	10+ years	
	Downspouts - Exterior Downspouts	H - Main	24	LF	7	10+ years	
	Downspouts - Interior Downspouts	H - Main	340	LF	7	10+ years	Quantity changed to match current observations
	Parapet - 16" - 30" Height	H - Main	435	LF	7	10+ years	
	Roof - Metal	H - Main	401	SF	7	10+ years	
	Roof - Modified Bitumen	H - Main	9,941	SF	6	10+ years	
	Roof Hatch - Metal	H - Main	1	EΑ	7	10+ years	
	Roof Structure - Steel / Metal Deck/	H - Main	10,342	SF	7	10+ years	
	Concrete Topping		.0,012	•	·	.o. you.o	
Walls							
	Exterior Walls - Brick	Entire Building	8,943	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	13,011	SF	7	10+ years	
Vindows							



	ry : Exterior		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Curtain wall - Glazed Double Pane	Entire Building	2,513	SF	7	10+ years	
	Lintels - Steel	Entire Building	26	LF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	1,488	SF	7	10+ years	
	pane	9	,,,,,			, , , , , , , , , , , , , , , , , , , ,	
	Windows - Louver	Entire Building	210	SF	7	10+ years	Added to match current observatio
		3				, , , , , ,	
Categor	ry : Electrical		В	uilding	: Annex		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>mergen</u>	cy System						
	Security System - CCTV	Entire Building	35,331	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	35,331	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	8	EA	6	6-10 years	
	Stairs	Zimio Bananig	· ·		Ŭ	o ro youro	
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Facks - Students Tollets	Entire Building	0	LA	O	0-10 years	
Main Ser	vice						
	Main Electrical Service - 800 A and	Electrical Room	1	EA	6	10+ years	
	277/480/3PH					, , , , ,	
	PA System	Entire Building	35,331	SF	6	6-10 years	
	-,	3	,	_	-	,	
Power Di	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/240	Entire Building	2	EA	6	10+ years	
	Transformers - 277/400 - 120/240	Little Building	2	LA	O	10+ years	
Catego	ry : Fire Protection		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarr	m						
	Fire Alarm Panel	Electrical Room	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Electrical Room	35,331	SF	7	10+ years	
	Fire Alarm_System	Electrical Room	35,331	SF	6	10+ years	
	Fire Pump Controller	Electrical Room	1	EA	6	10+ years	
	The Full poolitioner	Licotrical Room	•		U	101 years	
_	oom Assembly						
-ump Rc							

Campus Name: Coonley Page : 28 of 42 Assessment Date: 11/06/2023



Catego	ry : Fire Protection	В	Building : Annex				
2 30	. ,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Jockey Pump	025 Water Room	1	EΑ	6	10+ years	
	,					•	
Sprinkler	System						
·	Sprinkler Heads	Entire Building	35,331	SF	7	10+ years	
	Sprinkler Piping	Entire Building	35,331	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	35,331	SF	7	10+ years	
Catago	w. Maahaniaal		ь	ر دادادان در	. Annov		
Catego	ry : Mechanical		В	ullaing	: Annex	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Item - Type	Location	Quantity	UOIVI	Naiik	Replacement	Comments
Air Cond	•	D 4		ΕΛ		40	
	Chemical Pot Feeder	Roof	1	EΑ	6	10+ years	
	Chiller-Air Cooled-Screw Type-Roof Mounted - 101 - 200 tons	Roof	1	EA	6	10+ years	
	Glycol Feed	Roof	1	EA	6	10+ years	
	Pressure Fill System	Roof	1	EA	6	10+ years	
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	Serves MDF room.
	than 5 tons	11001	'	L/\	Ū	o to years	COIVES WEIT TOOM.
Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	2	EA	7	10+ years	RF 1, RF 2, Serves AHU1, AHU2
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 15001- 20000 cfm	Mechanical Room - AHU-2	1	EA	6	10+ years	AHU-2, serves classrooms and hallways, annex, second floor.
	Air Intake	Mechanical Room - AHU-2	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-2	14	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 15001- 20000 cfm	Mechanical Room - AHU1	1	EA	6	10+ years	AHU-1, Serves kitchen and cafeteria first floor, annex.
	Air Intake	Mechanical Room - AHU1	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU1	4	EA	6	6-10 years	
Heating I	Devices						
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	6	EA	6	10+ years	
	Unit Heater - Electric	Mechanical Room	3	EA	6	10+ years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	400	LF	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	150	LF	7	10+ years	
	Dual Temperature Pump - 10 - 20 HP	Mechanical Room	2	EΑ	7	10+ years	
	Dual Temperature Pump - Less than 10	Mechanical Room	2	EA	6	10+ years	
	·					•	

Campus Name: Coonley Page : 29 of 42 Assessment Date: 11/06/2023



Catego	ry : Mechanical		В	uilding	: Annex		TO TO TV ESAVIR OTTIEL I, Officago, IE 000 To
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
Топроге	DDC System	Entire Building	35,331	SF	6	10+ years	
	Electric Thermostat	Entire Building	3	EA	6	10+ years	
	Thermostats - DDC	Entire Building	16	EA	6	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Annex		
_						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - Less than 150000 BTU/HR	112A Water Heater Room	2	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	35,331	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	35,331	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	35,331	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	35,331	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	35,331	SF	7	10+ years	Pipes inside the wall
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	35,331	SF	7	10+ years	
	Sanitary Piping	Entire Building	35,331	SF	7	10+ years	Sanitary pipe inside the wall
	Storm Piping	Entire Building	35,331	SF	7	10+ years	711-
	Vent Piping	Entire Building	35,331	SF	7	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	112A Water Heater Room	1	EA	6	10+ years	



Catego	ry : Room		В	uilding	: Annex	(-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Lay-in	Ground Floor Kitchen Manager's Office	90	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Ground Floor Kitchen Manager's Office	1	EA	7	10+ years	
	Floor - Tile	Ground Floor Kitchen Manager's Office	90	SF	7	10+ years	
	Lighting - Lay-in	Ground Floor Kitchen Manager's Office	1	EA	7	6-10 years	
	Power Distribution	Ground Floor Kitchen Manager's Office	2	EA	7	10+ years	
	Walls - Concrete Block	Ground Floor Kitchen Manager's Office	146	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	Ground Floor	1,400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Ground Floor	9	EA	7	10+ years	
	Floor - Tile Quarry	Ground Floor	1,400	SF	7	10+ years	
	Lighting - Lay-in	Ground Floor	18	EA	7	6-10 years	
	Serving Line	Ground Floor	20	LF	7	10+ years	
	Storage/ Closet	Ground Floor	120	SF	7	10+ years	
	Walls - Concrete Block	Ground Floor	3,497	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	Ground Floor	3,938	SF	7	10+ years	Max occupancy sign not posted
	Ceiling - Lay-in	Ground Floor	30	SF	4	1-2 years	Missing or loose tiles
	Doors - Wood Doors inclu hw	Ground Floor	4	EA	7	10+ years	Wildeling of 10000 tilled
	Floor - Tile	Ground Floor	3,968	SF	7	10+ years	
	Lighting - Lay-in	Ground Floor	18	EA	7	6-10 years	
	Walls - Concrete Block	Ground Floor	6,600	SF	7	10+ years	
_MDF_ID	F						
<u> </u>	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	360	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	Ductless split system.
	-					-	
_Mechan	ical/ Service Rooms						
	Boiler Room	1st Floor	108	SF	7	10+ years	
	Janitor's Closet	1st Floor	30	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	2,500	SF	7	10+ years	
	Storage Room	1st Floor	32	SF	7	10+ years	
	Vaults	1st Floor	160	SF	7	10+ years	
	Janitor's Closet	2nd Floor	30	SF	7	10+ years	

Campus Name: Coonley Page : 31 of 42 Assessment Date: 11/06/2023



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	3rd Floor	45	SF	7	10+ years	
	_						
estroor		04 []	00	05		0.40	
	Accessories	2nd Floor	60	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	60	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	95	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	298	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	298	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	3	EA	7	6-10 years	
	Lavatory	2nd Floor	4	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Partitions	2nd Floor	5	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	666	SF	7	10+ years	
	Water Closet	2nd Floor	5	ĒΑ	7	10+ years	
	Accessories	2nd Floor	270	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	270	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	270	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	3	EA	7	6-10 years	
	Lavatory	2nd Floor	4	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7		
			3		7	10+ years	
	Urinals	2nd Floor		EA		10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	400	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	3rd Floor	60	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	60	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	60	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	190	SF	7	10+ years	
	Water Closet	3rd Floor	1	EA	7	10+ years	
	Accessories	3rd Floor	270	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	270	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	270	SF	7	10+ years	



atego	ry : Room		Building : Annex					
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor Drain	3rd Floor	1	EΑ	7	10+ years		
	Hand Dryer	3rd Floor	3	EΑ	7	6-10 years		
	Lavatory	3rd Floor	4	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years		
	Partitions	3rd Floor	2	EA	7	10+ years		
	Urinals	3rd Floor	3	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd Floor	400	SF	7	10+ years		
	Water Closet	3rd Floor	2	ĒΑ	7	10+ years		
	Accessories	3rd Floor	298	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	290	SF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	8	SF	4	1-2 years	Water damage	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	298	SF	7	10+ years	Water damage	
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Hand Dryer	3rd Floor	3	EA	7	6-10 years		
			_	EA				
	Lavatory	3rd Floor	4		7	10+ years		
	Lighting - Lay-in	3rd Floor	6	EΑ	7	6-10 years		
	Partitions	3rd Floor	5	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd Floor	666	SF	7	10+ years		
	Water Closet	3rd Floor	5	EA	7	10+ years		
	Accessories	Ground Floor Corridor next to Storage	91	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Ground Floor Corridor next to Storage	91	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Ground Floor Corridor next to Storage	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Ground Floor Corridor next to Storage	91	SF	7	10+ years		
	Floor Drain	Ground Floor Corridor next to Storage	1	EA	7	10+ years		
	Hand Dryer	Ground Floor Corridor next to Storage	1	EA	7	6-10 years		
	Lavatory	Ground Floor Corridor next to Storage	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Ground Floor Corridor next to Storage	2	EA	7	10+ years		
	Walls - Concrete Block	Ground Floor Corridor next to Storage	220	SF	7	10+ years		
	Water Closet	Ground Floor Corridor next to Storage	1	EA	7	10+ years		
	Accessories	Ground Floor in Dining Room-West	56	SF	7	6-10 years		
	Ceiling - Lay-in	Ground Floor in Dining Room-West	56	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Ground Floor in Dining Room-West	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Ground Floor in Dining Room-West	56	SF	7	10+ years		
	Floor Drain	Ground Floor in Dining Room-West	1	ĒΑ	7	10+ years		



Category : Room Building : Annex							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Ground Floor in Dining Room-West	1	EΑ	7	10+ years	
	Lighting - Lay-in	Ground Floor in Dining Room-West	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Ground Floor in Dining Room-West	140	SF	7	10+ years	
	Water Closet	Ground Floor in Dining Room-West	1	EA	7	10+ years	
	Accessories	Ground Floor in Dining-East	56	SF	7	6-10 years	
	Ceiling - Lay-in	Ground Floor in Dining-East	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Ground Floor in Dining-East	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Ground Floor in Dining-East	56	SF	7	10+ years	
	Floor Drain	Ground Floor in Dining-East	1	EA	7	10+ years	
	Lavatory	Ground Floor in Dining-East	1	EA	7	10+ years	
	Lighting - Lay-in	Ground Floor in Dining-East	1	EA	7	10+ years	
	Walls - Concrete Block	Ground Floor in Dining-East	140	SF	7	10+ years	
	Water Closet	Ground Floor in Dining-East	1	EA	7	10+ years	
Catego	ry : Classroom		В	uildina	: Annex		
2 3 0	,		_	9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #211 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	820	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	820	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	450	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	450	SF	7	10+ years	
Classroo	om #212 (Regular Classroom)						
Oldooroc	Ceiling - Lay-in	2nd Floor	820	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	820	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	900	SF	7	10+ years	
Classraa	om #213 (Regular Classroom)						
Ciassiuc		2nd Floor	820	SF	7	101 2000	
	Ceiling - Lay-in Doors - Side-lite	2nd Floor 2nd Floor		SF SF	7	10+ years	
	Doors - Side-lite Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	16 1	SF EA	7 7	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	820	SF	7 7	10+ years	
		2nd Floor 2nd Floor		SF EA		10+ years	
	Lighting - Lay-in Marker Board		13 25	LF	7 7	6-10 years	
	IVIAINEI DUATU	2nd Floor	25	LF	,	6-10 years	

Page : 34 of 42 Campus Name: Coonley Assessment Date: 11/06/2023



Catego	ry : Classroom		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	900	SF	7	10+ years	
Classroo	om #214 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	864	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	864	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	920	SF	7	10+ years	
Classroo	nm #216 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	864	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	864	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	11	EΑ	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	890	SF	7	10+ years	
Classroo	nm #217 (Science Classroom)						
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	820	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	820	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	900	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #311 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	820	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	820	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	3rd Floor	2	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	2	EA	5	1-2 years	Does not work.
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	450	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	450	SF	7	10+ years	

Campus Name: Coonley Page : 35 of 42 Assessment Date: 11/06/2023





Catego	ry : Classroom	Building : Annex								
~	Ham. Turns	Lasatian	O	ПОМ	Donk	Recommend	Comments			
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
`laceroo	m #312 (Regular Classroom)									
Classico	Ceiling - Lay-in	3rd Floor	820	SF	7	10+ years				
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years				
	Floor - Tile	3rd Floor	820	SF	7	10+ years				
		3rd Floor	4	EA	7	10+ years				
	Lighting - Chandelier, Incandescent	3rd Floor	9	EA	7	,				
	Lighting - Lay-in					6-10 years				
	Marker Board	3rd Floor	25	LF SF	7 7	6-10 years				
	Walls - Plaster/Drywall	3rd Floor	900	5F	7	10+ years				
Classroo	m #313 (Regular Classroom)									
	Ceiling - Lay-in	3rd Floor	820	SF	7	10+ years				
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years				
	Floor - Tile	3rd Floor	820	SF	7	10+ years				
	Lighting - Chandelier, Incandescent	3rd Floor	4	EΑ	7	10+ years				
	Lighting - Lay-in	3rd Floor	9	EΑ	7	6-10 years				
	Marker Board	3rd Floor	25	LF	7	6-10 years				
	Walls - Plaster/Drywall	3rd Floor	900	SF	7	10+ years				
01	·					·				
Classroo	m #314 (Regular Classroom)									
	Ceiling - Lay-in	3rd Floor	864	SF	7	10+ years				
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years				
	Floor - Tile	3rd Floor	864	SF	7	10+ years				
	Lighting - Chandelier, Incandescent	3rd Floor	4	EA	7	10+ years				
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years				
	Marker Board	3rd Floor	25	LF	7	6-10 years				
	Walls - Plaster/Drywall	3rd Floor	920	SF	7	10+ years				
Classroo	m #316 (Regular Classroom)									
	Ceiling - Lay-in	3rd Floor	864	SF	7	10+ years				
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years				
	Floor - Tile	3rd Floor	864	SF	7	10+ years				
	Lighting - Chandelier, Incandescent	3rd Floor	2	ĒΑ	7	10+ years				
	Lighting - Lay-in	3rd Floor	9	ĒΑ	7	6-10 years				
	Marker Board	3rd Floor	25	LF	7	6-10 years				
	Walls - Concrete Block	3rd Floor	890	SF	7	10+ years				
		J. J	300	SF	7	10+ years				

Campus Name: Coonley Page : 36 of 42 Assessment Date: 11/06/2023



Category : Classroom

John C Coonley Elementary School 4046 N Leavitt STREET, Chicago, IL 60618

	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	820	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	3rd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	900	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uildina	: Annex		
ou.ogo.	, <u>, , , , , , , , , , , , , , , , , , </u>		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	1,400	2004	quantity	00	rtann	rtopiacomont	
Corridor	Online Lawin	On d Elece	4.005	05		40	
	Ceiling - Lay-in	2nd Floor	1,225	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	1,225	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	3	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	710	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,420	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,225	SF	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,225	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Lighting - Wall Mounted	3rd Floor	3	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	200	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	710	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	710	SF	7	10+ years	
	Ceiling - Lay-in	Ground Floor	850	SF	7	10+ years	
	Drinking Fountains - Single Fountain	Ground Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	Ground Floor	850	SF	7	10+ years	
	Lighting - Lay-in	Ground Floor	7	EA	7	6-10 years	
	Student Lockers - One Tier	Ground Floor	7	EA	7	10+ years	
	Walls - Concrete Block	Ground Floor	904	SF	7	10+ years	
Stairs							
	Ceiling - Lay-in	Stair A	810	SF	7	10+ years	
	Floor - Tile	Stair A	819	SF	7	10+ years	
	Handrails	Stair A	282	LF	7	10+ years	
	Lighting - Lay-in	Stair A	5	ĒΑ	7	6-10 years	
Campus N	Jame: Coonley		Page : 37 of 42				Assessment Date: 11/06/202

Building: Annex

Recommend



Catego	Category : Interior			uilding	: Annex			
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	Stair A	1	EA	6	1-2 years	Relamp	
	Lighting - Wall Mounted	Stair A	6	EA	7	6-10 years		
	Stairs - Rubber	Stair A	518	LF	7	10+ years		
	Walls - Plaster/Drywall	Stair A	1,139	SF	7	10+ years		
	Ceiling - Lay-in	Stair B	810	SF	7	10+ years		
	Floor - Tile	Stair B	810	SF	7	10+ years		
	Handrails	Stair B	282	LF	7	10+ years		
	Lighting - Lay-in	Stair B	5	EA	7	6-10 years		
	Lighting - Lay-in	Stair B	1	EΑ	5	1-2 years	Does not work.	
	Lighting - Wall Mounted	Stair B	6	EΑ	7	6-10 years		
	Stairs - Rubber	Stair B	518	LF	7	10+ years		
	Walls - Plaster/Drywall	Stair B	1,139	SF	7	10+ years		

Campus Name: Coonley Page : 38 of 42 Assessment Date: 11/06/2023



Category : Site Building : Site

Jaicgo	y . Site			unung	. Oile	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic	nem Type	Location	Quantity	00111	Italik	Replacement	Comments
шепс	Surface - Synthetic	Southwest	26,194	SF	6	6-10 years	
	Carrage Cyrianous	Couli Wool	20,101	O.	Ü	o io youio	
ivil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	7	10+ years	Quantity changed to match current observations
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	7	10+ years	
encing							
choing	Fencing - Chain Link	Entire Site	365	LF	6	6-10 years	
	Fencing - Iron and Concrete Post	Entire Site	224	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	528	LF	7	10+ years	
l							
andsca	Benches	Entire Site	3	EA	6	10+ years	
	Landscape - Grass	Entire Site	1,300	SF	6	10+ years	
	Landscape - Grass	Entire Site	14,300	SF	5	1-2 years	Bare soil
	Landscape - Hardscape- Concrete	Entire Site	5,800	SF	7	10+ years	Daic 3011
	Landscape - Mulch	Entire Site	200	SF	6	6-10 years	
	Lighting - Pole Mounted	Entire Site	5	EA	7	6-10 years	Added to match current observation
	Parkway trees	Entire Site	26	EA	7	10+ years	Added to match current observation
		Entire Site	5,520	SF	7		
	Planting Beds/ Area			SF SF	-	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	2,750		5	2-5 years	
	Trash Receptacles	Entire Site	4	EA	6	6-10 years	
	Walking Path - Crushed Stone	Entire Site	520	SF	6	6-10 years	
Parking I	ot						
	Concrete Curbs	Entire Site	141	LF	7	10+ years	
	Interior Plantings	Entire Site	90	LF	7	10+ years	
	Lighting - Pole Mounted	Entire Site	2	EA	7	10+ years	
	Pavers	Entire Site	14,535	SF	6	10+ years	
	Trash Compactor	Entire Site	1	EA	7	10+ years	
	Trash Enclosure - Masonry	Entire Site	420	SF	7	10+ years	
	Vehicular Screening	Entire Site	68	LF	7	10+ years	
laygrou	nd						
iayyi uu	Equipment - Pre K 3-5	South	1	EA	6	6-10 years	
	Equipment - School Age 5-12	South	1	EA	6	6-10 years	
	Surface - Poured Surface	South	3,900	SF	4	0-1 year	Cracking old and worn.
						•	-
idewalk	S						



Catego	ry : Site	В	uilding	: Site			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	738	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	8,890	SF	7	10+ years	
Signage							
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	
	Monument - Sign	Entire Site	1	EA	7	10+ years	Quantity changed to match current observations

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Coonley Page: 40 of 42 Assessment Date: 11/06/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	intended Osage	Noon Location	Nullibei	Number	(31)	Alea	Alea	Зюр	Board
Art Room	Play Room	Basement	006	Girl's Play	1,295	0	0	N	Υ
Alt Room	Tidy Room	Basement	000	Rm	1,200			11	'
Auditorium	Music Room	Basement	003	Theater	437	62	24		Y
radionam	Widolo Room	Basement	000	room 00	107	02			
Kindergarten	Pre School	1st Floor	101	101	830	120	60	N	Υ
Kindergarten	Regular Classroom	1st Floor	102	102	860	77	38	N	Υ
Kindergarten	Regular Classroom	1st Floor	107	107	860	230	115	N	Υ
Kindergarten	Regular Classroom	1st Floor	108	108	840	77	38	N	Υ
Office	Office	Basement	005	n/a	466	43	21	N	N
Other Instructional Use	Band Room	Basement	004	Band Room	800	62	24		Υ
Pre School	Regular Classroom	1st Floor	106	106	1,007	152	76	N	Υ
Regular Classroom	Kindergarten	1st Floor	103	103	850	218	109	N	Υ
Regular Classroom	Library	2nd Floor	204	204	859	172	86	N	Υ
Regular Classroom	Music Room	3rd Floor	308	308	840	243	122	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	860	152	76	N	Υ
Regular Classroom	Regular Classroom	1st Floor	105	105	850	218	109	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	860	184	92	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	877	77	38	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	852	184	92	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	852	218	109	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	936	172	86	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	860	256	122	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	840	77	38	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	860	156	78	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	302	858	77	38	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	859	172	86	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	306	859	218	109	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	860	138	69	N	Υ
Science Lab Level 3	Auditorium	3rd Floor	303	n/a	852	184	92	N	Υ
Special Education	Play Room	Basement	800	Girl's Play Rm	440	66	33	N	Υ
Store Room	Other Instructional Use	Basement	007	n/a	960	180	90	N	N
Building : Annex									
Regular Classroom	Regular Classroom	2nd Floor	211	211	820	120	28	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	820	120	28	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	820	120	28	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	214	864	120	28	N	Υ





Classroom Summary

-				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	216	216	864	120	28	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	311	311	820	120	28	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	312	820	120	28	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	313	313	820	120	196	N	Y
Regular Classroom	Regular Classroom	3rd Floor	314	314	864	120	28	N	Y
Regular Classroom	Regular Classroom	3rd Floor	316	316	864	120	28	N	Y
Science Classroom	Regular Classroom	2nd Floor	217	217	820	120	28	N	Υ
Science Classroom	Science Classroom	3rd Floor	317	317	820	120	28	N	Υ