

# **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1924	4	125,776
Addition 2	1956	4	31,184
Campus Total			156,960

Category : Exterior Building : Main

	Ty : Exterior	_	aa9				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	e						
	Exterior Doors - Exterior Steel Door	10-Main roof access	1	EA	6	6-10 years	Changed to match current observations
	Exterior Stairs - Concrete	10-Main roof access	3	LF	5	2-5 years	
	Exterior Stairs - Steel or Aluminum	10-Main roof access	3	LF	5	2-5 years	
	Stair Handrail - Steel_Stair Handrail	10-Main roof access	6	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	2	1	EA	5	6-10 years	
	Exterior Doors - Transom Lite	2	1	EA	7	10+ years	
	Exterior Stairs - Concrete	2	50	LF	6	10+ years	
	Exterior Stairs - Concrete	2	10	LF	5	1-2 years	Cracking
	Stair Handrail - Steel_Stair Handrail	2	3	LF	6	10+ years	· ·
	Exterior Doors - Exterior Steel Door	3	3	EA	6	10+ years	
	Exterior Doors - Store Front	3A	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	3A	9	EA	6	10+ years	Quantity changed to match current observations
	Exterior Stairs - Concrete	3A	60	LF	7	10+ years	Newly replaced
	Ramp Handrail - Steel_Ramp Handrail	3A	72	LF	7	10+ years	Newly replaced
	Ramps - Concrete	3A	36	LF	7	10+ years	Newly replaced
	Stair Handrail - Steel_Stair Handrail	3A	10	LF	7	10+ years	New
	Exterior Doors - Exterior Stainless Steel	4	2	EA	6	6-10 years	
	Door						
	Exterior Stairs - Concrete	4	7	LF	5	10+ years	
	Exterior Doors - Exterior FRP Door	5	2	EA	6	10+ years	Changed to match current observations



Catego	ry : Exterior		R	uilding	: Main	390	to in Lawridate Avenue, Criicago, il 60616
Catego	TY . Exterior			ananig	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	6	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	6	2	EA	6	10+ years	
	Entrance Control - Audio and Video	7	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	7	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	7	2	EA	7	10+ years	
	Exterior Stairs - Concrete	7	24	LF	6	10+ years	
	Power Door Operator and Controls	7	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	7	25	LF	6	10+ years	
	Ramps - Concrete	7	25	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	7	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	8A	1	EA	4	0-1 year	Corroded
	Exterior Doors - Exterior Steel Door	8B	1	EΑ	6	10+ years	Concaca
	Exterior Doors - Overhead Rolling/ Garage	8OHD	1	EΑ	5	6-10 years	
	Door	00110		L/ \	0	o to years	
	Exterior Doors - Exterior Steel Door	Fire Escape 2nd Floor	1	EA	4	0-1 year	Corroded
	Exterior Doors - Transom Lite	Fire Escape 2nd Floor	1	EA	4	0-1 year	Corroded
	Exterior Doors - Fransom Elle  Exterior Doors - Exterior Steel Door	Fire Escape 3rd Floor	1	EA	5	2-5 years	Conoded
	Exterior Doors - Transom Lite	Fire Escape 3rd Floor	1	EA	5	2-5 years 2-5 years	
		Fire Escape 4th Floor	1		5 5	2-5 years 2-5 years	
	Exterior Doors - Exterior Steel Door	Fire Escape 4th Floor	1	EA EA	5 5	2-5 years 2-5 years	
	Exterior Doors - Transom Lite	Fire Escape 4th Floor	ı	EA	5	2-5 years	
Fire Esc	ape						
	Exterior Doors - Exterior Steel Door	North Courtyard	2	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	North Courtyard	1	EA	4	0-1 year	Corroded
	Exterior Doors - Transom Lite	North Courtyard	3	EA	6	6-10 years	
	Fire Escape	North Courtyard	77	LF	6	6-10 years	Changed to match current
	•	,				,	observations
	Paints	North Courtyard	77	LF	5	6-10 years	
Foundati	ion						
_roundat	Foundation - Concrete	Entire Building	841	LF	7	10+ years	
	Foundation - Concrete	Entire Building	32	LF	6	1-2 years	Seeping water/cracking
	Superstructure - Concrete	Entire Building	60	SF	7	10+ years	Cooping mater, eraerang
	Superstructure - Concrete	Entire Building	125,716	SF	7	10+ years	
	Cuporoli dotale Control	Litting Building	123,7 13	O.	•	.o. youro	
_Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	10+ years	
Roof Sys	stem						
,	Roof - Asphalt Shingle	A	7,937	SF	5	2-5 years	
	Roof Structure - Concrete	A	7,937	SF	7	10+ years	
	Coping - Stone	В	311	LF	6	10+ years	
	. 5				-	- ,	



3900 N Lawndale AVENUE, Chicago, IL 60618

Catego	ry : Exterior		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Interior Downspouts	В	296	LF	6	10+ years	Quantity changed to match current observations
	Parapet - 16" - 30" Height	В	301	LF	6	10+ years	
	Parapet - Parapet > 30"	В	10	LF	6	10+ years	
	Roof - Modified Bitumen	В	2,992	SF	6	6-10 years	
	Roof Structure - Concrete	В	2,992	SF	7	10+ years	
	Access Ladder - Metal	С	1	EA	7	10+ years	
	Coping - Stone	С	54	LF	6	10+ years	
	Downspouts - Interior Downspouts	С	71	LF	6	10+ years	Standing water
	Parapet - Parapet < 16" Height	С	54	LF	5	6-10 years	
	Roof - Modified Bitumen	С	180	SF	6	6-10 years	
	Roof Structure - Concrete	С	180	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	D	4	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	D	4	LF	6	10+ years	
	Coping - Stone	D	35	LF	6	10+ years	
	Downspouts - Exterior Downspouts	D	104	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	D	264	LF	5	6-10 years	Quantity changed to match current observations
	Parapet - 16" - 30" Height	D	35	LF	6	10+ years	oboot valions
	Roof - Modified Bitumen	D	8,064	SF	5	2-5 years	
	Roof - Modified Bitumen	D	500	SF	4	1-2 years	Cracking
	Roof Structure - Concrete	D	8,564	SF	7	10+ years	• · a a · · · · · · · · · · · · · · · ·
	Coping - Metal	E	60	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Ē	5	LF	6	10+ years	Quantity changed to match current observations
	Parapet - Parapet > 30"	E	60	LF	6	10+ years	
	Roof - Modified Bitumen	E	225	SF	6	6-10 years	
	Roof Structure - Concrete	Ē	225	SF	7	10+ years	
	Access Ladder - Metal	F	1	ĒΑ	4	0-1 year	Missing the top screws/not secured
	Coping - Stone	F	40	LF	5	10+ years	3
	Downspouts - Interior Downspouts	F	60	LF	6	10+ years	
	Parapet - 16" - 30" Height	F	40	LF	6	10+ years	
	Roof - Modified Bitumen	F	361	SF	6	6-10 years	
	Roof Structure - Concrete	F	361	SF	7	10+ years	
	Roof - Asphalt Shingle	G	8,296	SF	6	6-10 years	
	Roof Structure - Concrete	G	8,296	SF	7	10+ years	
	Coping - Stone	Н	45	LF	6	10+ years	Quantity changed to match current observations
	Downspouts - Interior Downspouts	Н	145	LF	6	10+ years	
	Parapet - Parapet < 16" Height	H	16	LF	5	10+ years	Changed to match current observations
	Parapet - Parapet > 30"	Н	29	LF	6	10+ years	Changed to match current



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations
	Roof - Modified Bitumen	Н	1,353	SF	6	6-10 years	
	Roof Structure - Concrete	Н	1,323	SF	7	6-10 years	
	Access Ladder - Metal	I	1	EA	5	10+ years	Changed to match current
							observations
	Coping - Stone	I	82	LF	6	10+ years	
	Downspouts - Interior Downspouts	I	79	LF	6	10+ years	
	Parapet - Parapet < 16" Height	I	82	LF	6	10+ years	
	Roof - Modified Bitumen	1	390	SF	6	6-10 years	
	Roof Structure - Concrete	1	390	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	J	60	LF	6	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	J	95	LF	5	1-2 years	Cracking/open joints
	Liner					·	
	Coping - Stone	J	116	LF	6	10+ years	
	Downspouts - Interior Downspouts	J	14	LF	6	10+ years	
	Parapet - 16" - 30" Height	J	116	LF	7	10+ years	
	Roof - Modified Bitumen	J	2,337	SF	5	2-5 years	
	Roof Structure - Concrete	J	2,337	SF	7	10+ years	
	Access Ladder - Metal	K	1	ĒΑ	7	10+ years	
	Coping - Stone	K	34	LF	5	6-10 years	
	Downspouts - Interior Downspouts	K	54	LF	6	10+ years	
	Parapet - 16" - 30" Height	K	34	LF	6	10+ years	Changed to match current
	raidpot 10 00 Hoight		01		Ü	101 youro	observations
	Roof - Modified Bitumen	K	228	SF	6	6-10 years	
	Roof Structure - Concrete	K	228	SF	7	10+ years	
	Coping - Stone	N	323	LF	6	10+ years	
	Downspouts - Interior Downspouts	N	150	LF	6	10+ years	
	Parapet - 16" - 30" Height	N	238	LF	7	10+ years	
	Parapet - Parapet > 30"	N	85	LF	7	10+ years	
	Roof - Modified Bitumen	N	3,253	SF	6	6-10 years	
	Roof Structure - Concrete	N	3,253	SF	7	10+ years	
	Coping - Stone	0	119	LF	6	10+ years	Quantity changed to match current
	Coping - Storie	0	119	LIT	O	10+ years	observations
	Downspouts - Interior Downspouts	0	145	LF	6	10+ years	UD3GI VALIUII3
	Parapet - Parapet < 16" Height	0	94	LF	7		Changed to match current
	rarapet - Parapet < 10 Height	O	94	LF	1	10+ years	
	Derenet Derenet 20"	0	0.5		7	10	observations
	Parapet - Parapet > 30"	0	25	LF SF	7	10+ years	
	Roof - Modified Bitumen	0	2,058		6	6-10 years	
	Roof Structure - Concrete	0	2,058	SF	7	10+ years	
<u>Walls</u>							
	Exterior Walls - Brick	Entire Building	24,006	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	700	SF	5	6-10 years	





Category : Exterior Building : Main							
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	1,000	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	120	SF	4	0-1 year	Cracking
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,220	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	4,678	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	2,000	SF	4	1-2 years	Cracking/chipping
ndows	3						
	Clerestory - Glass Double-Pane	Entire Building	80	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	2,665	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	4	SF	6	10+ years	
	Lintels - Brick	Entire Building	3	LF	6	10+ years	
	Lintels - Steel	Entire Building	3	LF	6	10+ years	
	Lintels - Steel	Entire Building	519	LF	6	10+ years	
	Lintels - Stone	Entire Building	792	LF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	474	SF	6	10+ years	
	pane						
	Windows - Casement Steel	Entire Building	10	SF	5	6-10 years	
	Windows - Decorative	Entire Building	40	SF	6	10+ years	
	Windows - Insulated Panel	Entire Building	587	SF	6	10+ years	
	Windows - Louver	Entire Building	161	SF	5	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	10,290	SF	6	10+ years	
	Windows - Wood- Single-pane	Entire Building	85	SF	5	6-10 years	
	Windows - Wood- Single-pane	Entire Building	9	SF	3	0-1 year	Broken glass

**Category : Electrical Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
ŭ	Automatic Transfer Switch	Electrical Room	1	EA	6	2-5 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	6,360	SF	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	22,634	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	7,924	SF	6	10+ years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	8	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	1	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	1	EA	2	0-1 year	Exit sign has been repaired
	Exit Signs - Corridors and Stairs	Entire Building	24	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	4	EA	6	6-10 years	

Campus Name: Disney II HS Page : 5 of 53 Assessment Date: 06/24/2024





Catego	ry : Electrical		В	uilding	: Main		•
<b>0</b>	Mana Tana	Laadlan	Overstites	11014	D I-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - CCTV	Entire Building	125,776	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	125,776	SF	5	6-10 years	
lain Sei	rvice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	4	2-5 years	Main electrical service is over 50 years
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	125,776	SF	6	6-10 years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	8	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open slot exposed conductor with a live front condition
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	6-10 years	Panel cover was put it back
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	4	0-1 year	Panel Door is missing
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Tallet Door is missing
atego	ry : Fire Protection		В	uilding	: Main		
`*a	Hom Type	Location	Quantitu	UOM	Donk	Recommend Replacement	Comments
<b>Fire Alar</b>	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
ile Alai	Fire Alarm Strobe Lights	Entire Building	125,776	SF	6	10+ years	
			125,776	SF	6		
	Fire Alarm_System	Entire Building	125,776	SF.	6	6-10 years	
prinklei	System						
	Sprinkler Heads	Entire Building	200	SF	7	10+ years	
	Sprinkler Piping	Entire Building	1,000	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	1,000	SF	6	10+ years	No fire pump works on city pressure
atego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ir Cond		200311	- Guaritity		. wiin		
00110	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years	Rm 402
:- 11							
AIT Hand	ling Systems  Air Handling Unit- Package Single Zone-	Entire Building	1	EA	7	10+ years	AHU-3
	AIT HODGING LIDIT- POCKAGE SIDGIE (ODE-	Entire Building	1	<b>⊢</b> /\	,	THE VACE	Δ H I I = 3



Catego	Category : Mechanical		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Air Intake	Entire Building	1	EA	7	10+ years			
	Air Handling Unit- Package Single Zone-	Entire Building	1	EA	5	6-10 years	AHU-2		
	Indoor- Steam Coils - Greater than 30,000								
	cfm								
	Air Intake	Entire Building	1	EA	6	10+ years			
	Air Handling Unit- Package Single Zone-	Entire Building	1	EA	5	6-10 years	AHU-1		
	Indoor- Steam Coils - 12001-20000 cfm								
	Air Intake	Entire Building	1	EA	6	10+ years			
	Indoor Return Fans- Centrifugal Inline -	Mechanical Room	1	EA	7	10+ years	Per engineer return fan was replaced		
	5000 - 10000 CFM					•	2024		
Boiler Sy	estems								
_,	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP	Entire Building	2	EA	6	10+ years			
		Fasting Building	,	_^	•	40			
	Chemical Feed System	Entire Building	1	EA	6	10+ years			
	Combustion Dampers	Entire Building	1	EA	6	10+ years			
	Condensate Pump	Entire Building	1	EA	6	10+ years			
	Condensate Pump	Entire Building	1	EA	6	10+ years			
	Feed Water Pumps and Tank	Entire Building	1	EA	5	6-10 years			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Entire Building	1	EA	5	10+ years			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Entire Building	1	EA	5	10+ years			
	Piping - Condensate Pipe- Steel	Entire Building	100	LF	6	6-10 years	Pipes are insulated and looks in good condition		
	Piping - Condensate Pipe- Steel	Entire Building	900	LF	5	10+ years	Condition		
	Piping - Steam Pipe- Steel	Entire Building	1,000	LF	5	10+ years			
	Steam Traps	Entire Building	179	EA	5	6-10 years			
	·	, , , , , , , , , , , , , , , , , , ,			-	,			
<u>Heating</u>		4 ( 5)		Ε.Δ.		0.40			
	Wall Heater - Electric	1st Floor	1	EΑ	6	6-10 years			
	Unit Heater - Steam	Basement	1	EA	5	6-10 years			
	Unit Heater - Steam	Basement	1	EA	5	6-10 years			
	Radiators - Steam	Entire Building	122	EA	5	10+ years			
	Fin Tube - Steam	Entire Building	80	LF	6	10+ years			
_Tempera	ture Control								
	Electric Thermostat	Entire Building	2	EA	5	6-10 years			
	Pneumatic System	Entire Building	125,776	SF	4	0-1 year	That temperature control system not functional temperature control manually by the engineer		
	Thermostats - Pneumatic	Entire Building	18	EA	4	0-1 year	Pneumatic temperature control system nonfunctional		





Group

Category : Mechanical

Item - Type

Thermostats - Pneumatic

Pneumatic temperature control

system nonfunctional

Comments

Unit Ven	ilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	1	EA	6	6-10 years	Ceilings mounted units vent serves room 218A
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	20	EA	6	6-10 years	
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	10	EA	6	6-10 years	
Ventilatio	n						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	4	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
Catego	y : Plumbing		В	Building	: Main		
_	<u> </u>			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Less than 150000 BTU/HR	Basement Basement	2 2	EA EA	6 6	6-10 years 6-10 years	
_Piping							
1 0	Domestic Piping-Hot Water Return Lines	Entire Building	125,776	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	125,776	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	125,776	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	125,776	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	125,776	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	125,776	SF	6	6-10 years	
	Sanitary Piping	Entire Building	125,776	SF	6	6-10 years	
	Storm Piping	Entire Building	125,776	SF	6	6-10 years	
	Vent Piping	Entire Building	125,776	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	10+ years	
Campus N	lame: Disnev II HS		Page : 8 of 53				Assessment Date: 06/24/202

**Building: Main** 

Rank

4

UOM

EΑ

Quantity

35

Location

**Entire Building** 

Recommend

Replacement

0-1 year







**Building: Main Category: Plumbing** 

Recommend Group Location Quantity UOM Item - Type Rank Replacement Comments Pumps - Sump-Simplex **Entire Building** 10+ years Sump pump located inside the EΑ 6 elevator pit

Category: Room Building: Main

alego	ry : Room		D	ullaing	. IVIAIII		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	trative Suites/Offices	Location	Quantity	COM	Italik	Replacement	Comments
ımınıs		400		ГΛ	7	0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	AC Unit	106	1	EA SF	7	6-10 years	
	Ceiling - Plaster/Drywall	106	384		6	10+ years	
	Doors - Transom Window	106	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	106	1	EA SF	6	10+ years	Tawa aawaat
	Floor - Carpet	106	384		4	0-1 year	Torn carpet
	Lighting - Pendent/Surface	106	5	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	106	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	106	812	SF SF	6	10+ years	
	Ceiling - Splined	107A	76		6	10+ years	
	Doors - Side-lite	107A	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	107A	2	EA	6	10+ years	
	Floor - Wood	107A	56	SF	6	10+ years	Daniel and Handing
	Floor - Wood	107A	20	SF	5	1-2 years	Damaged flooring
	Lighting - Lay-in	107A	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	107A	205	SF	6	10+ years	
	AC Unit	213A - Lamination / supply room	1	EA	7	6-10 years	
	Ceiling - Lay-in	213A - Lamination / supply room	306	SF	6	10+ years	
	Ceiling - Plaster/Drywall	213A - Lamination / supply room	27	SF	6	10+ years	
	Doors - Wood Doors inclu hw	213A - Lamination / supply room	3	EA	6	10+ years	
	Floor - Tile	213A - Lamination / supply room	333	SF	6	10+ years	
	Lighting - Lay-in	213A - Lamination / supply room	1	EΑ	7	6-10 years	
	Lighting - Lay-in	213A - Lamination / supply room	1	EA	5	1-2 years	Missing cover
	Power Distribution	213A - Lamination / supply room	10	EA	7	10+ years	
	Storage/ Closet	213A - Lamination / supply room	28	SF	7	10+ years	
	Walls - Plaster/Drywall	213A - Lamination / supply room	522	SF	6	10+ years	
	Ceiling - Lay-in	213D - Office Copy Room	192	SF	7	10+ years	<b></b>
	Ceiling - Lay-in	213D - Office Copy Room	20	SF	5	1-2 years	Damaged ceiling tiles
	Doors - Wood Doors inclu hw	213D - Office Copy Room	2	EA	7	10+ years	
	Floor - Tile	213D - Office Copy Room	207	SF	6	10+ years	5
	Floor - Tile	213D - Office Copy Room	5	SF	5	1-2 years	Damaged tiles
	Lighting - Lay-in	213D - Office Copy Room	2	EΑ	7	6-10 years	
	Power Distribution	213D - Office Copy Room	10	EA	6	10+ years	
	Walls - Plaster/Drywall	213D - Office Copy Room	425	SF	6	10+ years	
	Walls - Plaster/Drywall	213D - Office Copy Room	5	SF	4	1-2 years	Hole in wall
	AC Unit	213E - Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	213E - Office	230	SF	6	10+ years	
	Doors - Wood Doors inclu hw	213E - Office	1	EA	7	10+ years	



Category : Room			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	213E - Office	230	SF	6	10+ years	
	Lighting - Lay-in	213E - Office	2	EA	7	6-10 years	
	Power Distribution	213E - Office	18	EA	6	10+ years	
	Storage/ Closet	213E - Office	18	SF	5	10+ years	
	Walls - Plaster/Drywall	213E - Office	495	SF	6	10+ years	
	AC Unit	311A	1	EA	7	10+ years	
	Ceiling - Lay-in	311A	580	SF	6	10+ years	
	Doors - Wood Doors inclu hw	311A	3	EA	6	10+ years	
	Floor - Terrazzo	311A	100	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	311A	480	SF	6	10+ years	
	Lighting - Lay-in	311A	6	EA	5	1-2 years	Missing covers
	Power Distribution	311A	2	EA	7	10+ years	•
	Storage/ Closet	311A	12	SF	7	10+ years	
	Walls - Plaster/Drywall	311A	120	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	311A	700	SF	7	10+ years	
	Ceiling - Lay-in	311B - gym office	190	SF	6	10+ years	
	Doors - Wood Doors inclu hw	311B - gym office	1	ĒΑ	6	10+ years	
	Floor - Terrazzo	311B - gym office	190	SF	6	10+ years	
	Lighting - Lay-in	311B - gym office	2	EA	7	6-10 years	
	Power Distribution	311B - gym office	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	311B - gym office	368	SF	6	10+ years	Wood paneling
	Ceiling - Plaster/Drywall	313	670	SF	6	10+ years	Troca parioling
	Doors - Wood Doors inclu hw	313	1	EA	6	10+ years	
	Floor - Wood	313	670	SF	6	10+ years	
	Lighting - Pendent/Surface	313	6	EA	7	6-10 years	
	Power Distribution	313	6	EA	6	10+ years	
	Walls - Plaster/Drywall	313	1,650	SF	6	10+ years	
	AC Unit	411 Office	1,050	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	411 Office	505	SF	6	10+ years	
	Doors - Wood Doors inclu hw	411 Office	1	EA	7	10+ years	
	Floor - Tile	411 Office	505	SF	6	6-10 years	
	Lighting - Pendent/Surface	411 Office	7	EA	7	6-10 years	
	Lighting - Pendent/Surface	411 Office	1	EA	6	6-10 years	
	•	411 Office		EA	7		
	Power Distribution		6 666	SF	6	10+ years	
	Walls - Plaster/Drywall	411 Office	530	SF SF	6	10+ years	
	Ceiling - Plaster/Drywall	413				10+ years	
	Doors - Wood Doors inclu hw	413	1	EA	7	10+ years	
	Floor - Wood	413	530	SF	6	10+ years	
	Lighting - Pendent/Surface	413	5	EA	7	6-10 years	
	Walls - Plaster/Drywall	413	660	SF	6	10+ years	
	Ceiling - Plaster/Drywall	433 Office	353	SF	6	10+ years	
	Doors - Wood Doors inclu hw	433 Office	3	EA	6	10+ years	
	Floor - Tile	433 Office	353	SF	6	10+ years	
	Lighting - Pendent/Surface	433 Office	1	EA	6	6-10 years	



Catego	Category : Room		В	uilding	: Main	330			
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Power Distribution	433 Office	4	EΑ	6	10+ years			
	Storage/ Closet	433 Office	377	SF	7	10+ years			
	Walls - Plaster/Drywall	433 Office	547	SF	6	10+ years			
	Ceiling - Plaster/Drywall	SE Office above Stair 5	165	SF	6	10+ years			
	Doors - Wood Doors inclu hw	SE Office above Stair 5	1	EA	6	10+ years			
	Floor - Wood	SE Office above Stair 5	165	SF	6	10+ years			
	Lighting - Pendent/Surface	SE Office above Stair 5	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	SE Office above Stair 5	487	SF	6	10+ years			
	Ceiling - Plaster/Drywall	SW Office above Stair 4	150	SF	6	10+ years			
	Ceiling - Plaster/Drywall	SW Office above Stair 4	15	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	SW Office above Stair 4	1	ĒΑ	6	10+ years			
	Floor - Wood	SW Office above Stair 4	165	SF	6	10+ years			
	Lighting - Pendent/Surface	SW Office above Stair 4	1	ĒΑ	6	6-10 years			
	Walls - Plaster/Drywall	SW Office above Stair 4	487	SF	6	10+ years			
	Traile Tractor, 21, Trail	on omes above clair i	101	O.	Ü	.o. youro			
_Auditoriu	ım & Theater								
	Balcony Seating	1st Floor	300	EA	7	10+ years			
	Balcony Seating	1st Floor	4	EA	4	1-2 years	Damaged or missing seats		
	Ceiling - Plaster/Drywall	1st Floor	6,567	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Concrete	1st Floor	4,200	SF	7	10+ years			
	Floor - Tile	1st Floor	2,317	SF	6	6-10 years			
	Floor - Tile	1st Floor	50	SF	4	0-1 year	Damaged tiles		
	Lighting - Pendent/Surface	1st Floor	15	EΑ	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	136	EΑ	6	6-10 years			
	Main Floor Seating	1st Floor	820	EA	7	10+ years			
	Sound System	1st Floor	1	EA	7	6-10 years			
	Stage	1st Floor	1,766	SF	6	10+ years			
	Stage Curtain	1st Floor	9	EA	7	6-10 years			
	Stage Lift	1st Floor	1	EA	7	10+ years			
	Stage Lighting System	1st Floor	1	EΑ	7	6-10 years			
	Stage-Stairs - Wood	1st Floor	15	LF	6	10+ years			
	Stairs - Terrazzo	1st Floor	5	LF	6	10+ years			
	Storage/ Closet	1st Floor	207	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	8,408	SF	6	10+ years			
Gvmnas	ia								
	Bleacher Seating	3rd Floor	160	EA	6	10+ years	Qty updated		
	Bleacher Seating	3rd Floor	17	EΑ	5	1-2 years	Damaged or missing seats		
	Ceiling - Plaster/Drywall	3rd Floor	7,924	SF	6	10+ years	- <del>-</del>		
	Doors - Wood Doors inclu hw	3rd Floor	6	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	3rd Floor	1,400	SF	7	10+ years			
	Floor - Wood	3rd Floor	6,344	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	29	ĒΑ	7	6-10 years	Qty updated		
	5 5				-	J			



Category : Room			Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	3rd Floor	1	EΑ	6	6-10 years		
	Scoreboards	3rd Floor	1	EA	7	10+ years		
	Storage/ Closet	3rd Floor	68	SF	7	10+ years	Locked	
	Walls - Masonry	3rd Floor	5,660	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	500	SF	6	10+ years		
	·							
Library								
•	Casework	430 Currently Gym	227	LF	6	10+ years		
	Ceiling - Plaster/Drywall	430 Currently Gym	3,684	SF	6	10+ years		
	Doors - Transom Window	430 Currently Gym	12	SF	6	10+ years		
	Doors - Wood Doors inclu hw	430 Currently Gym	4	EA	6	10+ years		
	Floor - Carpet	430 Currently Gym	3,684	SF	6	6-10 years		
	Lighting - Pendent/Surface	430 Currently Gym	14	EA	7	6-10 years		
	Storage/ Closet	430 Currently Gym	100	SF	7	10+ years	Locked	
	Walls - Plaster/Drywall	430 Currently Gym	2,273	SF	6	10+ years	Locked	
	Walls - Flastel/Drywall	450 Currently Gym	2,213	OI.	U	10+ years		
_Locker/S	hower Room							
	Accessories	3rd Floor	728	SF	7	6-10 years		
	Benches, ped mounted	3rd Floor	32	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	728	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	3	ĒΑ	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	721	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	7	SF	4	1-2 years	Cracking near drain	
	Floor Drain	3rd Floor	1	EΑ	7	10+ years	oraciming recar aram.	
	Lavatory	3rd Floor	4	EΑ	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	11	EA	7	6-10 years		
	Partitions	3rd Floor	3	EA	7	10+ years		
	Showers	3rd Floor	4	EA	7	10+ years		
	Student Lockers - Two Tier	3rd Floor	30	EA	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	730	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd Floor	730 790	SF	6	•		
	Water Closet	3rd Floor	790	EA	7	10+ years		
			_			10+ years		
	Accessories	3rd Floor	728	SF	7	6-10 years		
	Benches, ped mounted	3rd Floor	32	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	728	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	728	SF	6	10+ years		
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Lavatory	3rd Floor	4	EA	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	11	EA	7	6-10 years		
	Partitions	3rd Floor	1	EA	7	10+ years		
	Showers	3rd Floor	3	EΑ	7	10+ years		
	Showers	3rd Floor	1	EA	5	1-2 years	Out of service	
	Student Lockers - Two Tier	3rd Floor	30	EA	6	10+ years		



Catego	ry : Room		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Urinals	3rd Floor	2	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	730	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd Floor	790	SF	6	10+ years		
	Water Closet	3rd Floor	1	EA	7	10+ years		
	Accessories	3rd Floor Unisex Accessible	124	SF	7	6-10 years		
	Benches, ped mounted	3rd Floor Unisex Accessible	4	LF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor Unisex Accessible	124	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor Unisex Accessible	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor Unisex Accessible	124	SF	6	10+ years		
	Floor Drain	3rd Floor Unisex Accessible	1	EA	7	10+ years		
	Hand Dryer	3rd Floor Unisex Accessible	1	EA	7	6-10 years		
	Lavatory	3rd Floor Unisex Accessible	1	EA	5	1-2 years	Out of order	
	Lighting - Pendent/Surface	3rd Floor Unisex Accessible	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor Unisex Accessible	1	EA	5	1-2 years	Loose cover	
	Showers	3rd Floor Unisex Accessible	1	EA	7	10+ years		
	Student Lockers - One Tier	3rd Floor Unisex Accessible	4	EΑ	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor Unisex Accessible	120	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	3rd Floor Unisex Accessible	196	SF	6	10+ years		
	Water Closet	3rd Floor Unisex Accessible	1	EA	7	10+ years		
_MDF_ID								
	Doors - Steel Doors incl hw	in Office 313	1	EA	7	10		
	Finishes	in Office 313	1 98	SF	7 7	10+ years		
		in Office 313	90	EA	7	10+ years		
	Window AC Unit	In Office 313	ı	EA	,	6-10 years		
_Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	35	SF	7	10+ years		
	Storage Room	1st Floor	100	SF	7	10+ years		
	Janitor's Closet	3rd Floor	25	SF	7	10+ years		
	Storage Room	4th FIr - Storage at Library (430A on plans)	369	SF	7	10+ years	Locked no access	
	Air Tunnel	Basement	1,425	SF	5	10+ years		
	Boiler Room	Basement	2,140	SF	5	10+ years		
	Mechanical/ Service Rooms	Basement	1,900	SF	5	10+ years		
	Storage Room	Basement	4,200	SF	5	10+ years		
	Janitor's Closet	Janitor's Closets	40	SF	7	10+ years		
Prep Ro	om							
TIED KO	Ceiling - Plaster/Drywall	109 Kiln Room	380	SF	6	10+ years		
	Doors - Transom Window	109 Kiln Room	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	109 Kiln Room	3	EA	6	10+ years		
	Floor - Tile	109 Kiln Room	380	SF	4	1-2 years	Damaged tiles throughout	
	Lighting - Pendent/Surface	109 Kiln Room	3	EA	7	6-10 years	Damaged med injugitori	
	Lighting 1 chachirounace	100 Kiili ROOM	3	LA	,	o io yeais		



**Disney II Magnet School** 3900 N Lawndale AVENUE, Chicago, IL 60618 **Building: Main** Category : Room Recommend

_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	109 Kiln Room	39	SF	7	10+ years	
	Walls - Plaster/Drywall	109 Kiln Room	700	SF	6	10+ years	
Restroor	n						
	Ceiling - Exposed	104A	81	SF	7	10+ years	
	Doors - Wood Doors inclu hw	104A	1	ĒΑ	6	10+ years	
	Floor - Tile	104A	81	SF	4	0-1 year	Damage throughout
	Lavatory	104A	1	ĒΑ	6	10+ years	_ aa.g. a aga
	Lighting - Pendent/Surface	104A	1	EA	6	6-10 years	
	Partitions	104A	2	ĒΑ	5	0-1 year	Doors missing
	Walls - Plaster/Drywall	104A	282	SF	6	10+ years	
	Walls - Plaster/Drywall	104A	5	SF	4	0-1 year	Hole in wall
	Accessories	105	45	SF	7	6-10 years	. Total III III III
	Ceiling - Plaster/Drywall	105	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105	1	ĒΑ	6	10+ years	
	Floor - Terrazzo	105	45	SF	6	10+ years	
	Floor Drain	105	1	EA	7	10+ years	
	Lavatory	105	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	105	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	105	250	SF	6	10+ years	
	Water Closet	105	1	EA	6	10+ years	
	Accessories	1st Floor West	249	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor West	249	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor West	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor West	249	SF	6	10+ years	
	Floor Drain	1st Floor West	1	EA	7	10+ years	
	Hand Dryer	1st Floor West	1	EA	7	6-10 years	
	Lavatory	1st Floor West	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor West	5	EA	7	6-10 years	
	Partitions	1st Floor West	5	EA	7	10+ years	
	Urinals	1st Floor West	3	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor West	426	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor West	301	SF	6	10+ years	
	Water Closet	1st Floor West	5	EA	7	10+ years	
	Accessories	1st Floor West	61	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor West	61	SF	7	10+ years	
	Doors - Transom Window	1st Floor West	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw		1	EA	6	•	
		1st Floor West	·=	SF		10+ years	
	Floor - Terrazzo	1st Floor West	61		7	10+ years	
	Hand Dryer	1st Floor West	1	EΑ	7	10+ years	
	Lavatory	1st Floor West	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor West	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor West	276	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor West	70	SF	7	10+ years	



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor West	1	EA	7	10+ years	
	Accessories	1st Floor West	370	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor West	370	SF	6	10+ years	
	Doors - Transom Window	1st Floor West	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor West	1	EA	6	10+ years	
	Floor - Terrazzo	1st Floor West	370	SF	6	10+ years	
	Floor Drain	1st Floor West	1	EA	7	10+ years	
	Hand Dryer	1st Floor West	1	EA	7	6-10 years	
	Lavatory	1st Floor West	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor West	7	EA	7	6-10 years	
	Partitions	1st Floor West	7	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor West	360	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor West	343	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor West	5	SF	5	1-2 years	Damaged wall tiles
	Water Closet	1st Floor West	7	EA	7	10+ years	-
	Accessories	1st FIr - Unisex Adj. to large auditorium	154	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FIr - Unisex Adj. to large auditorium	154	SF	6	10+ years	
	Doors - Transom Window	1st Flr - Unisex Adj. to large auditorium	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Flr - Unisex Adj. to large auditorium	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr - Unisex Adj. to large auditorium	154	SF	6	6-10 years	
	Floor Drain	1st Flr - Unisex Adj. to large auditorium	1	EA	7	10+ years	
	Hand Dryer	1st Flr - Unisex Adj. to large auditorium	1	EA	7	10+ years	
	Lavatory	1st Flr - Unisex Adj. to large auditorium	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Flr - Unisex Adj. to large auditorium	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st FIr - Unisex Adj. to large auditorium	300	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Flr - Unisex Adj. to large auditorium	174	SF	6	10+ years	
	Water Closet	1st Flr - Unisex Adj. to large auditorium	1	EA	7	10+ years	
	Accessories	213C	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	213C	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	213C	1	EΑ	7	10+ years	
	Floor - Terrazzo	213C	35	SF	6	10+ years	
	Lavatory	213C	1	EA	6	10+ years	
	,		·	** *	-	· ,	




Category : Room		B	uilding	: Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Wall Mounted	213C	1	EA	7	6-10 years	
	Showers	213C	1	EA	4	0-1 year	Corroded
	Walls - Plaster/Drywall	213C	134	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	213C	114	SF	6	10+ years	
	Water Closet	213C	1	EA	7	10+ years	
	Accessories	2nd Floor West	372	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor West	372	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor West	1	ĒΑ	7	10+ years	
	Floor - Terrazzo	2nd Floor West	372	SF	6	10+ years	
	Floor Drain	2nd Floor West	1	EA	7	10+ years	
	Hand Dryer	2nd Floor West	1	EΑ	7	6-10 years	
	Lavatory	2nd Floor West	4	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor West	7	EA	7	6-10 years	
	Partitions	2nd Floor West	7	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor West	393	SF	6	10+ years	
	Walls - Flaster/Drywall Walls - Tile Ceramic/ Porcelain	2nd Floor West 2nd Floor West	300	SF	6	10+ years	
	Water Closet	2nd Floor West	7	EA	7	-	
				SF		10+ years	
	Accessories	2nd Floor West	190	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor West	190		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor West	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor West	190	SF	6	10+ years	
	Floor Drain	2nd Floor West	1	EA	7	10+ years	
	Hand Dryer	2nd Floor West	1	EA	7	6-10 years	
	Lavatory	2nd Floor West	4	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor West	5	EA	7	6-10 years	
	Partitions	2nd Floor West	5	EA	7	10+ years	
	Urinals	2nd Floor West	3	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor West	319	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor West	300	SF	7	10+ years	
	Water Closet	2nd Floor West	2	EA	7	10+ years	
	Accessories	2nd Floor West	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor West	32	SF	6	10+ years	
	Doors - Transom Window	2nd Floor West	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor West	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor West	32	SF	7	10+ years	
	Hand Dryer	2nd Floor West	1	EA	7	10+ years	
	Lavatory	2nd Floor West	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor West	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor West	171	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor West	70	SF	7	10+ years	
	Water Closet	2nd Floor West	1	ĒΑ	7	10+ years	
	Accessories	3rd Floor West	190	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor West	190	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor West	1	EA	7	10+ years	
	200.0 11000 20010 11010 1111	3.4 1.55. 1100.		_, .	•	io. youro	



Category : Room Building : Main

Catego	ry : Room		Building : Main								
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Floor - Terrazzo	3rd Floor West	190	SF	6	10+ years					
	Floor Drain	3rd Floor West	1	EA	7	10+ years					
	Hand Dryer	3rd Floor West	1	EA	7	6-10 years					
	Lavatory	3rd Floor West	4	EA	6	10+ years					
	Lighting - Pendent/Surface	3rd Floor West	4	EΑ	7	6-10 years					
	Lighting - Pendent/Surface	3rd Floor West	1	EA	6	6-10 years					
	Partitions	3rd Floor West	5	EΑ	7	10+ years					
	Urinals	3rd Floor West	3	EA	7	10+ years					
	Walls - Plaster/Drywall	3rd Floor West	313	SF	6	10+ years					
	Walls - Tile Ceramic/ Porcelain	3rd Floor West	300	SF	6	10+ years					
	Water Closet	3rd Floor West	2	EA	7	10+ years					
	Accessories	3rd Floor West	372	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	3rd Floor West	372	SF	6	10+ years					
	Doors - Wood Doors inclu hw	3rd Floor West	1	EA	7	10+ years					
	Floor - Terrazzo	3rd Floor West	372	SF	6	10+ years					
	Floor Drain	3rd Floor West	1	EA	7	10+ years					
	Hand Dryer	3rd Floor West	1	EA	7	6-10 years					
	Lavatory	3rd Floor West	4	EA	7	10+ years					
	Lighting - Pendent/Surface	3rd Floor West	6	EA	7	6-10 years					
	Partitions	3rd Floor West	7	EA	7	10+ years					
	Walls - Plaster/Drywall	3rd Floor West	393	SF	6	10+ years					
	Walls - Tile Ceramic/ Porcelain	3rd Floor West	300	SF	6	10+ years					
	Water Closet	3rd Floor West	7	EA	7	10+ years					
	Accessories	4th Floor Boys SE	150	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	4th Floor Boys SE	150	SF	6	10+ years					
	Doors - Wood Doors inclu hw	4th Floor Boys SE	1	EA	6	10+ years					
	Floor - Terrazzo	4th Floor Boys SE	150	SF	6	10+ years					
	Lavatory	4th Floor Boys SE	1	EA	7	10+ years					
	Lighting - Pendent/Surface	4th Floor Boys SE	3	EA	7	6-10 years					
	Partitions	4th Floor Boys SE	3	EA	7	10+ years					
	Walls - Structural Glazed Tile	4th Floor Boys SE	469	SF	6	10+ years					
	Water Closet	4th Floor Boys SE	2	EA	7	10+ years					
	Water Closet	4th Floor Boys SE	1	EA	4	0-1 year	Out of order				
	Accessories	4th Floor West	318	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	4th Floor West	318	SF	6	10+ years					
	Doors - Wood Doors inclu hw	4th Floor West	1	EA	7	10+ years					
	Floor - Terrazzo	4th Floor West	318	SF	6	10+ years					
	Floor Drain	4th Floor West	1	EA	7	10+ years					
	Hand Dryer	4th Floor West	1	EA	7	6-10 years					
	Lavatory	4th Floor West	4	EA	7	10+ years					
	Lighting - Pendent/Surface	4th Floor West	5	EA	7	6-10 years					
	Partitions	4th Floor West	5	EA	7	10+ years					
	Walls - Plaster/Drywall	4th Floor West	450	SF	6	10+ years					
			321	SF	6	10+ years					







Catego	ry : Room	В	uilding				
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	4th Floor West	5	EA	7	10+ years	
	Accessories	4th Floor West	190	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor West	190	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor West	1	EA	7	10+ years	
	Floor - Terrazzo	4th Floor West	190	SF	6	10+ years	
	Floor Drain	4th Floor West	1	EA	7	10+ years	
	Hand Dryer	4th Floor West	1	EA	7	6-10 years	
	Lavatory	4th Floor West	4	EA	7	10+ years	
	Lighting - Pendent/Surface	4th Floor West	5	EA	7	6-10 years	
	Partitions	4th Floor West	5	EA	7	10+ years	
	Urinals	4th Floor West	3	EA	7	10+ years	
	Walls - Plaster/Drywall	4th Floor West	333	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	4th Floor West	275	SF	6	10+ years	
	Water Closet	4th Floor West	2	EA	7	10+ years	
	Accessories	Across From 307	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Across From 307	65	SF	6	10+ years	
	Doors - Transom Window	Across From 307	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Across From 307	1	EA	6	10+ years	
	Floor - Terrazzo	Across From 307	65	SF	6	10+ years	
	Hand Dryer	Across From 307	1	EA	7	10+ years	
	Lavatory	Across From 307	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Across From 307	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Across From 307	250	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Across From 307	80	SF	6	10+ years	
	Water Closet	Across From 307	1	EA	7	10+ years	
						•	

Category: Classroom **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #101 (Exclusively Used by Outside O	rganization)					
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,169	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	4	0-1 year	Makeshift door installed
	Floor - Tile	1st Floor	1,149	SF	6	6-10 years	
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Damaged tile throughout
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	-
	Storage/ Closet	1st Floor	238	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,247	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classro	om #102 (Exclusively Used by Outside O	rganization)					
	AC Units	1st Floor	1	EA	7	6-10 years	

Campus Name: Disney II HS Page : 18 of 53 Assessment Date: 06/24/2024



**Building: Main** Category: Classroom Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments LF Casework 1st Floor 25 6 10+ years 1st Floor 794 SF 7 Ceiling - Plaster/Drywall 10+ years Doors - Transom Window 1st Floor 6 SF 7 10+ years Doors - Wood Doors inclu hw EΑ 7 1st Floor 1 10+ years SF Floor - Tile 1st Floor 789 6 6-10 years Floor - Tile SF 5 1st Floor 5 1-2 years Damaged tiles Lighting - Pendent/Surface 1st Floor 14 EΑ 7 6-10 years SF Storage/ Closet 1st Floor 54 7 10+ years SF Walls - Plaster/Drywall 1st Floor 1.116 7 10+ years Work Sink 1st Floor FΑ 7 10+ years Classroom #103/105/107 (Exclusively Used by Outside Organization) 2 AC Units 1st Floor EΑ 7 6-10 years LF Casework 1st Floor 47 6 10+ years 1st Floor 1.572 SF 6 Ceiling - Splined 10+ years Doors - Transom Window 1st Floor 24 SF 6 10+ years 2 FΑ Doors - Wood Doors inclu hw 1st Floor 6 10+ years Floor - Wood 1st Floor 1,572 SF 6 10+ years 7 Lighting - Lay-in 1st Floor 30 EΑ 6-10 years Walls - Plaster/Drywall SF 1st Floor 1,080 6 10+ years Work Sink 1st Floor 3 EΑ 10+ years Classroom #104 (Exclusively Used by Outside Organization) AC Units 1st Floor EΑ 7 6-10 years 1 Casework 1st Floor 38 LF 6 10+ years SF Ceiling - Plaster/Drywall 1st Floor 978 6 10+ years Doors - Transom Window 1st Floor SF 6 10+ years 1 Doors - Wood Doors inclu hw EΑ 6 1st Floor 1 10+ years Floor - Tile 1st Floor 963 SF 6 6-10 years SF Floor - Tile 1st Floor 15 5 1-2 years Damaged tiles Lighting - Pendent/Surface 7 6-10 years 1st Floor 24 EΑ Lighting - Pendent/Surface 6-10 years 1st Floor 1 EΑ 6 Storage/ Closet 97 SF 7 10+ years 1st Floor Walls - Plaster/Drywall 1st Floor 1,252 SF 6 10+ years Walls - Plaster/Drywall 1st Floor SF 4 0-1 vear Hole in wall Work Sink 1st Floor FΑ 7 1 10+ years Classroom #108 (Exclusively Used by Outside Organization) AC Units 1st Floor 1 EΑ 7 6-10 years Casework 10 LF 6 10+ years 1st Floor 724 SF 6 Ceiling - Plaster/Drywall 1st Floor 10+ years Doors - Transom Window 1st Floor 6 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 FΑ 6 10+ years



# **Building: Main** Category: Classroom Recommend Location Group Item - Type Quantity **UOM** Rank Replacement Comments Floor - Terrazzo 1st Floor 66 SF 10+ years 7 Floor - Wood 1st Floor 653 SF 6 10+ years Floor - Wood 1st Floor 5 SF 5 1-2 years Warped wood flooring near heating Lighting - Pendent/Surface 1st Floor EΑ 7 6-10 years Storage/ Closet 29 SF 7 1st Floor 10+ years Walls - Plaster/Drywall 1st Floor SF 10+ years 684 6 Work Sink 1st Floor 1 EΑ 10+ years Classroom #110 (Exclusively Used by Outside Organization) AC Units 1st Floor EΑ 7 6-10 years 1 Casework 1st Floor 15 LF 6 10+ years Ceiling - Plaster/Drywall 1st Floor SF 6 10+ years 586 LF Chalk Board 1st Floor 15 4 2-5 years Doors - Wood Doors inclu hw EΑ 6 1st Floor 1 10+ years Floor - Terrazzo 1st Floor 66 SF 10+ years SF Floor - Wood 1st Floor 520 6 10+ years Lighting - Pendent/Surface 7 1st Floor 5 EΑ 6-10 years Walls - Plaster/Drywall SF 1st Floor 639 6 10+ years Work Sink EΑ 7 1st Floor 1 10+ years Classroom #201 (Regular Classroom) AC Units 2nd Floor 1 EΑ 7 6-10 years 2nd Floor 10 LF 5 Casework 10+ years Ceiling - Plaster/Drywall 2nd Floor 790 SF 6 10+ years Doors - Transom Window 2nd Floor 6 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years Floor - Tile 2nd Floor 790 SF 6 6-10 years Floor - Tile 2nd Floor 10 SF 5 1-2 years Warped flooring 7 Lighting - Pendent/Surface 2nd Floor 20 FΑ 6-10 years Lighting - Pendent/Surface 5 2nd Floor 1 EΑ 1-2 years Lightning enclosure damaged LF 7 Marker Board 2nd Floor 20 6-10 years Storage/ Closet 2nd Floor SF 7 10+ years 10 Student Lockers - One Tier 2nd Floor 22 EΑ 6 10+ years Walls - Plaster/Drywall 2nd Floor 1.110 SF 6 10+ years Classroom #202 (Regular Classroom) AC Units 2nd Floor 1 EΑ 7 6-10 years Casework 2nd Floor LF 5 14 10+ years Ceiling - Plaster/Drywall 2nd Floor 814 SF 6 10+ years Doors - Transom Window 2nd Floor SF 6 6 10+ years Doors - Wood Doors inclu hw 2nd Floor EΑ 6 10+ years SF Floor - Tile 2nd Floor 804 6-10 years



	ry . Classroom		D	uildise	. Main	390	10 N Lawndale AVENUE, Chicago, IL 60618
Catego	ry : Classroom		Б	uilding	: wain	Decemberd	
Craun	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Floor - Tile	2nd Floor	quantity 10	SF	5	1-2 years	Comments Damaged tiles
			20	Sr EA	5 7	•	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor				6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	794	SF	6	10+ years	
	Floor - Tile	2nd Floor	6	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	34	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	22	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
Classroo	om #204 + 206 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,390	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,370	SF	6	6-10 years	
	Floor - Tile	2nd Floor	20	SF	5	1-2 years	Warped tile flooring
	Lighting - Pendent/Surface	2nd Floor	38	EA	7	6-10 years	warped tile hoofing
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
		2nd Floor	20	SF	7		
	Storage/ Closet			SF		10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,800	SF	6	10+ years	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	790	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	6	10+ years	
						•	





Category : Classroom		В	Building : Main					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Damaged or missing tiles	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years		
	Marker Board	2nd Floor	22	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	21	ĒΑ	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	5	SF	4	0-1 year	Cracked wall	
Classro	om #207 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	10	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	10+ years		
				SF				
	Doors - Transom Window	2nd Floor	6		6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood	2nd Floor	800	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years		
	Marker Board	2nd Floor	22	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	22	EΑ	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years		
Classroo	om #208 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	10+ years		
	Chalk Board	2nd Floor	22	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood Boors meid riw	2nd Floor	750	SF	6	10+ years		
	Floor - Wood	2nd Floor	50	SF	5		Warned and damaged wood floor	
					-	1-2 years	Warped and damaged wood floor	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years		
	Marker Board	2nd Floor	22	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	21	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,040	SF	6	10+ years		
Classroo	om #209 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	10	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	790	SF	6	10+ years		
	Chalk Board	2nd Floor	22	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	20070 TTOOG 20010 HIOIG HW	2110 1 1001	ı	_/ \	J	ioi youis		



Catego	ry : Classroom		В	uilding	· Main		O N Lawridale AVENOE, Chicago, IL 60616
Juliogo	.,		_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	750	SF	7	10+ years	
	Floor - Wood	2nd Floor	50	SF	5	1-2 years	Warped damaged wood floor
	Lighting - Pendent/Surface	2nd Floor	21	ĒA	7	6-10 years	. p
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	21	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood Doors med nw	2nd Floor	800	SF	6	10+ years	
						•	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7 7	6-10 years	
	Marker Board	2nd Floor	28	LF CF		6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,140	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	790	SF	6	10+ years	
	Floor - Wood	3rd Floor	10	SF	5	1-2 years	Unleveled floor area
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	6	10+ years	
Classroo	om #302 (Computer Lab)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	21	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	804	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	Ŭ
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	6	6-10 years	
	Floor - Tile	3rd Floor	4	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years	
	gg	0.0	21	_, .	•	o .o youro	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	10	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	790	SF	6	6-10 years	
	Floor - Tile	3rd Floor	10	SF	5	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	10	SF	5	1-2 years	Doors damaged
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	6	10+ years	Dooro damagod
	·		.,			, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	500	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	30	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Floor - Tile	3rd Floor	530	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	528	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	780	SF	6	6-10 years	
	Floor - Tile	3rd Floor	20	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	21	ĒΑ	7	6-10 years	3
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	880	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	5	SF	5	1-2 years	Missing/loose tiles
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	885	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	24	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	
	Walls - Metal Panel	3rd Floor	226	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	668	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
Classro	om #307 (Regular Classroom)						
_Ua55100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
				SF		•	
	Ceiling - Plaster/Drywall Doors - Transom Window	3rd Floor 3rd Floor	800 6	SF SF	6 6	10+ years	
			0			10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	800	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	6	10+ years	
_Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	790	SF	6	6-10 years	
	Floor - Tile	3rd Floor	10	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years	ŭ
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years	
Classro	om #309 (Regular Classroom)						
	` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `	3rd Floor	4	ГΛ	7	6.10 40055	
	AC Units		1	EA LF	7	6-10 years	
	Casework	3rd Floor	16		6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	



**Building: Main** Category: Classroom Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Doors - Wood Doors inclu hw 3rd Floor EΑ 10+ years 6 3rd Floor 800 SF 7 6-10 years Floor - Wood New flooring Lighting - Pendent/Surface 3rd Floor 20 FΑ 7 6-10 years Lighting - Pendent/Surface 3rd Floor 1 EΑ 6 6-10 years 8 1 F Marker Board 3rd Floor 6 6-10 years SF Storage/ Closet 3rd Floor 10 7 10+ years Walls - Plaster/Drywall SF 3rd Floor 1,110 6 10+ years Classroom #310 (Regular Classroom) **AC Units** 3rd Floor 1 EΑ 7 6-10 years Casework 3rd Floor 11 LF 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 800 SF 6 10+ years Doors - Transom Window 3rd Floor SF 6 1 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EΑ 6 10+ years 800 SF 6 Floor - Tile 3rd Floor 6-10 years Lighting - Pendent/Surface 3rd Floor 21 FΑ 7 6-10 years LF Marker Board 3rd Floor 38 6 6-10 years SF Storage/ Closet 3rd Floor 10 7 10+ years Locked SF Walls - Plaster/Drywall 1,140 3rd Floor 10+ years Classroom #402 (Computer Lab) **AC Units** 4th Floor 2 EΑ 7 6-10 years Ceiling - Plaster/Drywall SF 4th Floor 594 6 10+ years Doors - Wood Doors inclu hw 4th Floor 7 EΑ 10+ years Floor - Tile 4th Floor 594 SF 6 6-10 years Lighting - Pendent/Surface 4th Floor 6 EΑ 7 6-10 years LF Marker Board 4th Floor 8 7 6-10 years 4th Floor 842 SF Walls - Plaster/Drywall 6 10+ years Wireless System 4th Floor FΑ 7 6-10 years 1 Classroom #404 (Vacant) AC Units 4th Floor 7 1 EΑ 6-10 years Casework 4th Floor 16 LF 6 10+ years SF Ceiling - Lay-in 4th Floor 637 6 10+ years SF Doors - Transom Window 4th Floor 6 10+ years 1 SF Floor - Tile 4th Floor 637 6 6-10 years Lighting - Lay-in 4th Floor 12 EΑ 7 6-10 years Marker Board 4th Floor 16 LF 7 6-10 years SF Walls - Plaster/Drywall 4th Floor 941 6 10+ years Classroom #406 (Vacant) AC Units 4th Floor 1 EΑ 7 6-10 years 4th Floor LF Casework 15 6 10+ years



Walls - Plaster/Drywall

**Building: Main** Category: Classroom Recommend Quantity Group Item - Type Location UOM Rank Replacement Comments 4th Floor SF Ceiling - Lay-in 626 6 10+ years Doors - Wood Doors inclu hw 4th Floor EΑ 7 10+ years 1 Floor - Tile 4th Floor 626 SF 6 6-10 years Lighting - Lay-in 4th Floor 8 EΑ 7 6-10 years 20 LF Marker Board 4th Floor 6 6-10 years SF Walls - Plaster/Drywall 4th Floor 848 10+ years Classroom #408 (Regular Classroom) **AC Units** 4th Floor 1 EΑ 7 6-10 years LF Casework 4th Floor 18 7 10+ years Ceiling - Plaster/Drywall 4th Floor 769 SF 10+ years 6 Doors - Wood Doors inclu hw 4th Floor 1 EΑ 7 10+ years Floor - Tile 4th Floor 769 SF 6-10 years 6 Lighting - Pendent/Surface 4th Floor 8 EΑ 7 6-10 years Walls - Plaster/Drywall 4th Floor 627 SF 10+ years Classroom #410 (Vacant) AC Units 4th Floor EΑ 7 1 6-10 years 4th Floor 28 LF 7 Casework 10+ years Ceiling - Plaster/Drywall 4th Floor 750 SF 6 10+ years Doors - Wood Doors inclu hw 4th Floor 1 EΑ 7 10+ years SF Floor - Tile 4th Floor 750 6 6-10 years Lighting - Pendent/Surface 4th Floor 8 EΑ 7 6-10 years Marker Board 4th Floor 18 LF 7 6-10 years

Category : Interior Building : Main

4th Floor

Guicgo	iy i mitorioi			ananig	· Wall		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Splined	1st Floor	3,561	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EΑ	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	6	EΑ	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EΑ	7	10+ years	
	Floor - Terrazzo	1st Floor	3,561	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	32	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	133	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,695	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	40	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st flr - Auditorium Vestibule	607	SF	6	10+ years	
	Doors - Wood Doors include hw	1st flr - Auditorium Vestibule	8	EA	6	10+ years	
	Floor - Terrazzo	1st flr - Auditorium Vestibule	580	SF	6	10+ years	
	Floor - Terrazzo	1st flr - Auditorium Vestibule	27	SF	4	1-2 years	Large crack

701

SF

6

10+ years



ategory : Interior

Ruilding : Main

Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st flr - Auditorium Vestibule	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st flr - Auditorium Vestibule	770	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	3,601	SF	6	10+ years	_
	Ceiling - Splined	2nd Floor	20	SF	4	1-2 years	Damaged tiles
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	2	EA	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	3	EA	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	3,621	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	75	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6,082	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	4	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	3,611	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	10	SF	4	0-1 year	Damaged
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	2	EA	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	3	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	3,621	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	24	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	46	EA	6	10+ years	
	Student Lockers - Two Tiers	3rd Floor	55	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5,978	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	40	SF	7	10+ years	
	Ceiling - Splined	4th Floor	2,364	SF	6	10+ years	
	Doors - Wood Doors include hw	4th Floor	6	EA	6	10+ years	
	Drinking Fountains - Single Fountain	4th Floor	3	EA	7	10+ years	
	Floor - Terrazzo	4th Floor	2,364	SF	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	18	EA	7	6-10 years	
	Student Lockers - One Tier	4th Floor	75	EA	7	10+ years	
	Student Lockers - Two Tiers	4th Floor	12	EΑ	6	10+ years	
	Walls - Plaster/Drywall	4th Floor	2,281	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	4th Floor	40	SF	7	10+ years	
	Ceiling - Exposed	Basement (Unfinished Mechanical Access)	3,240	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement (Unfinished Mechanical Access)	1	EA	7	10+ years	
	Doors - Wood Doors include hw	Basement (Unfinished Mechanical Access)	1	EA	6	10+ years	
	Floor - Concrete	Basement (Unfinished Mechanical Access)	3,240	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement (Unfinished Mechanical Access)	14	EA	6	6-10 years	



Catego	Category : Interior		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Concrete Block	Basement (Unfinished Mechanical Access)	6,200	SF	6	10+ years			
	Walls - Plaster/Drywall	Basement (Unfinished Mechanical Access)	1,330	SF	6	10+ years			
	Ceiling - Exposed	Basement (corridor to Elevator)	148	SF	6	10+ years			
	Ceiling - Lay-in	Basement (corridor to Elevator)	74	SF	6	10+ years			
	Doors - Steel Doors incl hw	Basement (corridor to Elevator)	2	ĒΑ	7	10+ years			
	Floor - Tile/Sheet	Basement (corridor to Elevator)	260	SF	7	10+ years			
	Lighting - Lay-in	Basement (corridor to Elevator)	1	ĒΑ	7	6-10 years			
	Stairs - Concrete Stairs	Basement (corridor to Elevator)	20	LF	7	10+ years			
	Walls - Concrete Block	Basement (corridor to Elevator)	174	SF	6	10+ years			
	Walls - Plaster/Drywall	Basement (corridor to Elevator)	580	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Basement Area @ Stair 5	400	SF	6	10+ years			
	Doors - Wood Doors include hw	Basement Area @ Stair 5	1	EA	7	10+ years			
	Drinking Fountains - Single Fountain	Basement Area @ Stair 5	3	EA	7	10+ years			
	Floor - Terrazzo	Basement Area @ Stair 5	426	SF	6	10+ years			
	Lighting - Pendent/Surface	Basement Area @ Stair 5	2	EA	6	6-10 years			
	Walls - Concrete Block	Basement Area @ Stair 5	44	SF	6	10+ years			
	Walls - Plaster/Drywall	Basement Area @ Stair 5	290	SF	6	10+ years			
	vvalio i lactor/Brywali	Baddinon 7 noa @ Clair C	200	O.	J	101 youro			
Safety									
	Camera Viewing Station	1st Floor	2	EA	7	6-10 years			
	Metal Detector	1st Floor	1	EA	7	10+ years			
	Security Cameras	1st Floor	3	EA	7	6-10 years			
	Security Cameras	1st Floor	3	EA	7	6-10 years			
Stairs									
	Ceiling - Splined	1st/2nd from Large auditorium balcony to foyer	300	SF	6	10+ years			
	Floor - Terrazzo	1st/2nd from Large auditorium balcony to foyer	300	SF	6	10+ years			
	Handrails	1st/2nd from Large auditorium balcony to foyer	27	LF	7	10+ years			
	Lighting - Pendent/Surface	1st/2nd from Large auditorium balcony to foyer	1	EA	6	10+ years	Qty updated		
	Stairs - Terrazzo	1st/2nd from Large auditorium balcony to foyer	110	LF	6	10+ years	Qty updated		
	Walls - Plaster/Drywall	1st/2nd from Large auditorium balcony to foyer	1,652	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Gym stair to Balcony	50	SF	6	10+ years			
	Floor - Terrazzo	Gym stair to Balcony	50	SF	6	10+ years			
	Handrails	Gym stair to Balcony	36	LF	7	10+ years			
	Stairs - Terrazzo	Gym stair to Balcony	112	LF	6	10+ years			
	Walls - Masonry	Gym stair to Balcony	236	SF	6	10+ years			
	,	-,	_00		-	,			



3900 N Lawndale AVENUE, Chicago, IL 60618

Catego	ry : Interior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Gym stair to Balcony	112	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Metal stair next to 411	60	SF	7	10+ years	
	Handrails	Metal stair next to 411	15	LF	7	10+ years	
	Stairs - Concrete	Metal stair next to 411	48	LF	7	10+ years	Metal stair
	Walls - Plaster/Drywall	Metal stair next to 411	80	SF	7	10+ years	
	Ceiling - Splined	Metal stair next to 413	48	SF	7	10+ years	
	Handrails	Metal stair next to 413	15	LF	7	10+ years	
	Stairs - Concrete	Metal stair next to 413	48	LF	7	10+ years	These are metal stairs
	Walls - Plaster/Drywall	Metal stair next to 413	80	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair from 213D to exterior (SE corner)	124	SF	6	10+ years	
	Floor - Terrazzo	Stair from 213D to exterior (SE corner)	48	SF	6	10+ years	
	Handrails	Stair from 213D to exterior (SE corner)	22	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair from 213D to exterior (SE corner)	2	EA	6	6-10 years	
	Stairs - Terrazzo	Stair from 213D to exterior (SE corner)	88	LF	6	10+ years	
	Walls - Plaster/Drywall	Stair from 213D to exterior (SE corner)	680	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairway 1	1,071	SF	6	10+ years	
	Floor - Terrazzo	Stairway 1	1,055	SF	6	10+ years	
	Handrails	Stairway 1	199	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairway 1	4	EA	7	6-10 years	Qty updated
	Lighting - Pendent/Surface	Stairway 1	2	EA	6	6-10 years	ary apasion
	Stairs - Terrazzo	Stairway 1	446	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairway 1	2,885	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairway 2	1,216	SF	7	10+ years	
	Floor - Terrazzo	Stairway 2	983	SF	6	10+ years	
	Handrails	Stairway 2	232	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairway 2	3	ĒΑ	7	6-10 years	Qty updated
	Lighting - Pendent/Surface	Stairway 2	3	EA	6	6-10 years	
	Stairs - Concrete	Stairway 2	67	LF	7	10+ years	
	Stairs - Terrazzo	Stairway 2	387	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairway 2	4,047	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Stairway 2	67	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairway 4	1,201	SF	6	10+ years	
	Floor - Terrazzo	Stairway 4	1,058	SF	6	10+ years	
	Handrails	Stairway 4	396	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairway 4	1	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	Stairway 4	1	EA	6	6-10 years	
	Stairs - Terrazzo	Stairway 4	594	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairway 4	2,361	SF	6	10+ years	







Catego	ry : Interior		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	Stairway 5	1,523	SF	6	10+ years			
	Floor - Terrazzo	Stairway 5	1,370	SF	6	10+ years			
	Handrails	Stairway 5	368	LF	7	10+ years			
	Lighting - Pendent/Surface	Stairway 5	4	EΑ	7	6-10 years			
	Stairs - Terrazzo	Stairway 5	720	LF	6	10+ years			
	Walls - Plaster/Drywall	Stairway 5	3,091	SF	6	10+ years			
Vertical 0	Conveyance								
	Elevator - Hydraulic Elevator	2nd Floor	1	EA	7	10+ years			

Campus Name: Disney II HS Page : 31 of 53 Assessment Date: 06/24/2024



Category : Exterior Building : Addition 2

ategory . Exterior			unung		Recommend	
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance	Location	quantity	00111	Marin	Replacement	Comments
Entrance Control - Audio and Video	1- Main	1	EA	7	6-10 years	
Exterior Doors - Exterior FRP Door	1- Main	4	EA			
				6	10+ years	
Exterior Stairs - Stone	1- Main	180	LF	6	10+ years	
Power Door Operator and Controls	1- Main	1	EA	7	6-10 years	
Ramp Handrail - Steel_Ramp Handrai		130	LF	6	10+ years	
Ramps - Concrete	1- Main	65	LF	7	10+ years	
Stair Handrail - Steel_Stair Handrail	1- Main	48	LF	6	10+ years	
Exterior Doors - Exterior FRP Door	9	2	EA	6	10+ years	
Exterior Stairs - Concrete	9	12	LF	6	10+ years	
oundation						
Foundation - Concrete	Entire Building	286	LF	7	10+ years	
Superstructure - Concrete	Entire Building	31,184	SF	7	10+ years	
ighting						
ighting Exterior Lighting - Parapet or Roof Mo	unted Entire Building	6	EA	6	6-10 years	
Roof System						
Coping - Stone	N.4	275	LF		40	
	M	275		6	10+ years	
Downspouts - Interior Downspouts	M	240	LF	6	10+ years	01 11 11
Parapet - 16" - 30" Height	M	275	LF	6	10+ years	Changed to match current observations
Roof - Modified Bitumen	M	5,796	SF	5	2-5 years	
Roof - Modified Bitumen	M	2,000	SF	4	1-2 years	Cracking/bubbling
Roof Structure - Concrete	M	7,796	SF	7	10+ years	g a sau a g
1-II-						
/alls Exterior Walls - Brick	Entire Building	15,033	SF	6	10+ years	
Exterior Walls - Stone-Cut	Entire Building	2,012	SF	6	10+ years	
Exterior Walls - Stone-Cut  Exterior Walls - Stone-Cut	Entire Building Entire Building	2,012	SF	4	1-2 years	Cracking
Extensi Wans Stone Gat	Entire Building	00	O.	-	1 Z years	Ordoking
/indows						
Guard - Guards perforated	Entire Building	2,338	SF	7	10+ years	
Lintels - Brick	Entire Building	32	LF	6	10+ years	
Lintels - Steel	Entire Building	1,665	LF	6	10+ years	
Skylite - Lexan	Entire Building	95	SF	6	10+ years	
Windows - Decorative	Entire Building	544	SF	6	10+ years	
Windows - Insulated Panel	Entire Building	246	SF	6	10+ years	
Mindows Lawren	Entire Building	76	SF	6	10+ years	
Windows - Louver						

Campus Name: Disney II HS Page : 32 of 53 Assessment Date: 06/24/2024





Catego	ry : Exterior		В	uilding	: Addition	on 2	
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Electrical	В	uilding	: Additio	on 2		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
J	Emergency A/C Power - Corridors and Stairs	Entire Building	5,450	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	4,062	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	519	SF	6	10+ years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	2	EA	7	10+ years	Per engineer, Auditorium emergene battery packs were replaced 2023
	Emergency Battery Packs - Corridors and Stairs	Entire Building	8	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	1	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	1	EA	2	0-1 year	Stained exit sign glass
	Security System - CCTV	Entire Building	31,184	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	31,184	SF	6	6-10 years	
Main Sei	vice						
	PA System	Entire Building	31,184	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additio	on 2	
_	<del></del>	1	0		<b>D</b>	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	Fire alarm annunciator is located in
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	the main building
	Fire Alarm Strobe Lights	Entire Building	31,184	SF	7	10+ years	
	Fire Alarm_System	Entire Building	31,184	SF	6	10+ years	
	ry : Mechanical		В	uilding	: Addition	on 2	
Catego						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Commonto





Catego	ry : Mechanical		В	uilding	: Addition		o in Lawridale Avende, Chicago, il 606 i
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years	
Air Hand	lling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm	4th Floor	1	EA	6	10+ years	Ceiling mounted in 4th floor mechanical space
	Air Intake	4th Floor	1	EA	6	10+ years	
Boiler Sy	vstems						
,	Piping - Condensate Pipe- Steel	Entire Building	1	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Entire Building	1	LF	6	10+ years	
	Steam Traps	Entire Building	24	EA	5	6-10 years	
Heating	Devices						
0	Cabinet Heaters - With Steam Coil	1st Floor	4	EA	6	10+ years	
	Radiators - Steam	Entire Building	15	EA	5	10+ years	
	Fin Tube - Steam	Entire Building	506	LF	6	10+ years	
Tempera	ature Control						
·	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Per the engineer it's no electrical thermostat for the fourth floor AHU
	Pneumatic System	Entire Building	31,184	SF	4	0-1 year	Pneumatic temperature control nonfunctional
	Thermostats - Pneumatic	Entire Building	6	EA	4	0-1 year	Pneumatic system is abandoned nonfunctional, building engineer control temperature manually
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	20	EA	6	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	5	EA	6	6-10 years	





**Building: Addition 2** Category : Mechanical

Recommend Item - Type Location Quantity **UOM** Rank Replacement Comments Group

CFM

**Category: Plumbing Building: Addition 2** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Piping_							
	Domestic Piping-Hot Water Return Lines	Entire Building	31,184	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	31,184	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	31,184	SF	6	10+ years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	31,184	SF	6	10+ years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	31,184	SF	6	10+ years	
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	31,184	SF	6	10+ years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	31,184	SF	6	10+ years	
	Storm Piping	Entire Building	31,184	SF	6	10+ years	
	Vent Piping	Entire Building	31,184	SF	6	10+ years	

Category: Room **Building: Addition 2** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	001 Care Room	616	SF	6	10+ years	
	Doors - Wood Doors inclu hw	001 Care Room	1	EA	6	10+ years	
	Floor - Tile	001 Care Room	616	SF	6	10+ years	
	Lighting - Lay-in	001 Care Room	4	EA	7	6-10 years	
	Power Distribution	001 Care Room	2	EA	6	10+ years	
	Storage/ Closet	001 Care Room	320	SF	5	10+ years	
	Walls - Plaster/Drywall	001 Care Room	730	SF	6	10+ years	
	Walls - Plaster/Drywall	001 Care Room	130	SF	6	6-10 years	Repainted
	Work SInk	001 Care Room	1	EA	7	10+ years	
	Ceiling - Lay-in	004 Basement Kitchen Office	192	SF	6	10+ years	
	Doors - Steel Doors incl hw	004 Basement Kitchen Office	1	EA	6	10+ years	
	Floor - Tile	004 Basement Kitchen Office	192	SF	6	10+ years	
	Lighting - Lay-in	004 Basement Kitchen Office	3	EA	7	6-10 years	
	Power Distribution	004 Basement Kitchen Office	4	EA	7	10+ years	
	Walls - Concrete Block	004 Basement Kitchen Office	110	SF	6	10+ years	
	Walls - Plaster/Drywall	004 Basement Kitchen Office	340	SF	6	10+ years	
	AC Unit	123 Security Office	1	EA	5	6-10 years	
	Ceiling - Lay-in	123 Security Office	165	SF	7	10+ years	
	Doors - Wood Doors inclu hw	123 Security Office	1	EA	7	10+ years	

Campus Name: Disney II HS Page : 35 of 53 Assessment Date: 06/24/2024





**Building: Addition 2** Category : Room

_			anamg				
Croun	Itama Tuma	Logotion	Ougatitus	LIOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	123 Security Office	165	SF	6	10+ years	
	Lighting - Lay-in	123 Security Office	2	EA	7	6-10 years	
	Walls - Metal Panel	123 Security Office	210	SF	6	10+ years	
	Walls - Plaster/Drywall	123 Security Office	225	SF	6	10+ years	
	AC Unit	124 Engineer	1	EA	7	6-10 years	
	Ceiling - Lay-in	124 Engineer	172	SF	6	10+ years	
	Doors - Wood Doors inclu hw	124 Engineer	1	EA	7	10+ years	
	Floor - Terrazzo	124 Engineer	172	SF	6	10+ years	
	Lighting - Lay-in	124 Engineer	2	EA	7	6-10 years	
	Walls - Metal Panel	124 Engineer	60	SF	6	10+ years	
	Walls - Plaster/Drywall	124 Engineer	150	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	124 Engineer	150	SF	6	10+ years	
	AC Unit	128 Conference Room	1	EA	7	6-10 years	
	Ceiling - Lay-in	128 Conference Room	225	SF	7	10+ years	
	Doors - Wood Doors inclu hw	128 Conference Room	1	EA	7	10+ years	
	Floor - Tile	128 Conference Room	225	SF	6	10+ years	
	Lighting - Lay-in	128 Conference Room	5	ĒΑ	7	6-10 years	
	Power Distribution	128 Conference Room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	128 Conference Room	549	SF	7	10+ years	
	Ceiling - Plaster/Drywall	129 Admin Vault	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	129 Admin Vault	1	EA	7	10+ years	
	Floor - Tile	129 Admin Vault	32	SF	7	10+ years	
	Lighting - Pendent/Surface	129 Admin Vault	1	EA	7	6-10 years	
		129 Admin Vault	181	SF	7	,	
	Walls - Plaster/Drywall AC Unit			EA	7	10+ years	
		132 Admin Lunch Room	1			6-10 years	
	Ceiling - Lay-in	132 Admin Lunch Room	433	SF	6	10+ years	
	Doors - Wood Doors inclu hw	132 Admin Lunch Room	1	EA	7	10+ years	
	Floor - Tile	132 Admin Lunch Room	433	SF	7	10+ years	
	Lighting - Lay-in	132 Admin Lunch Room	9	EA	7	6-10 years	
	Walls - Plaster/Drywall	132 Admin Lunch Room	595	SF	7	10+ years	
	Work Slnk	132 Admin Lunch Room	1	EA	7	10+ years	
	AC Unit	133 Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	133 Office	271	SF	6	10+ years	
	Doors - Wood Doors inclu hw	133 Office	1	EA	7	10+ years	
	Floor - Tile	133 Office	271	SF	6	10+ years	
	Lighting - Lay-in	133 Office	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	133 Office	516	SF	7	10+ years	
	AC Unit	134 Office	1	EΑ	7	6-10 years	
	Ceiling - Lay-in	134 Office	265	SF	6	10+ years	
	Doors - Wood Doors inclu hw	134 Office	1	EA	7	10+ years	
	Floor - Tile	134 Office	265	SF	6	10+ years	
	Lighting - Lay-in	134 Office	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	134 Office	509	SF	6	10+ years	
		1st Flr - Main Office Foyer	144	SF	6	10+ years	






Catego	ry : Room		Building : Addition 2						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	1st Flr - Main Office Foyer	8	SF	5	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	1st Flr - Main Office Foyer	1	EA	7	10+ years			
	Floor - Terrazzo	1st Flr - Main Office Foyer	57	SF	6	10+ years			
	Floor - Tile	1st Flr - Main Office Foyer	95	SF	6	10+ years			
	Lighting - Lay-in	1st Flr - Main Office Foyer	6	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Flr - Main Office Foyer	324	SF	6	10+ years			
	AC Unit	1st Flr - Main Office Open Office	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st Flr - Main Office Open Office	383	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Flr - Main Office Open Office	1	EA	7	10+ years			
	Floor - Tile	1st Flr - Main Office Open Office	383	SF	6	10+ years			
	Lighting - Lay-in	1st Flr - Main Office Open Office	7	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Flr - Main Office Open Office	355	SF	6	10+ years			
	Ceiling - Lay-in	1st FIr Main Office Hallway	457	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Flr Main Office Hallway	1	EA	7	10+ years			
	Doors - Wood Doors inclu hw	1st Flr Main Office Hallway	1	EA	7	10+ years			
	Floor - Tile	1st Flr Main Office Hallway	457	SF	7	10+ years			
	Lighting - Lay-in	1st Flr Main Office Hallway	8	ĒΑ	7	6-10 years			
	Power Distribution	1st Flr Main Office Hallway	2	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Flr Main Office Hallway	316	SF	6	10+ years			
	Ceiling - Lay-in	417 Office	121	SF	6	10+ years			
	Doors - Side-lite	417 Office	32	SF	6	10+ years			
	Doors - Wood Doors inclu hw	417 Office	1	ĒΑ	6	10+ years			
	Floor - Tile	417 Office	121	SF	6	10+ years			
	Lighting - Lay-in	417 Office	2	ĒΑ	7	6-10 years			
	Power Distribution	417 Office	4	EΑ	6	10+ years			
	Walls - Plaster/Drywall	417 Office	256	SF	6	10+ years			
	Ceiling - Lay-in	419 Office	121	SF	6	10+ years			
	Doors - Side-lite	419 Office	32	SF	6	10+ years			
	Doors - Wood Doors inclu hw	419 Office	1	EA	6	10+ years			
	Floor - Tile	419 Office	121	SF	6	10+ years			
	Lighting - Lay-in	419 Office	2	EA	7	6-10 years			
	Power Distribution	419 Office	4	EA	6	10+ years			
	Walls - Plaster/Drywall	419 Office	256	SF	6	10+ years			
	Ceiling - Lay-in	421 Office	121	SF	6	10+ years			
	Doors - Side-lite	421 Office	32	SF	6	10+ years			
	Doors - Wood Doors inclu hw	421 Office	1	EA	6	10+ years			
	Floor - Tile	421 Office	121	SF	6	10+ years			
		421 Office	2	EA	7	6-10 years			
	Lighting - Lay-in Power Distribution	421 Office	4	EA	6	10+ years			
	Walls - Plaster/Drywall	421 Office	256	SF	6				
	Ceiling - Lay-in	421 Office 423 office	121	SF SF	6	10+ years 10+ years			
	Doors - Side-lite	423 office	32	SF SF	6				
	Doors - Side-lite Doors - Wood Doors inclu hw	423 office	32 1	SF EA	6	10+ years			
			121	SF	6	10+ years			
	Floor - Tile	423 office	121	ЭГ	Ö	10+ years			





Catego	Category : Room		В	uilding	: Additi	on 2	· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	423 office	2	EA	7	6-10 years	
	Power Distribution	423 office	4	EA	6	10+ years	
	Walls - Plaster/Drywall	423 office	256	SF	6	10+ years	
	Ceiling - Lay-in	425 Office	121	SF	6	10+ years	
	Doors - Wood Doors inclu hw	425 Office	1	EA	6	10+ years	
	Floor - Tile	425 Office	121	SF	6	10+ years	
	Lighting - Lay-in	425 Office	2	EA	7	6-10 years	
	Power Distribution	425 Office	4	EA	6	10+ years	
	Walls - Plaster/Drywall	425 Office	256	SF	6	10+ years	
	AC Unit	427	1	EA	7	10+ years	
	Ceiling - Lay-in	427	121	SF	6	10+ years	
	Doors - Side-lite	427	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	427	1	ĒΑ	6	10+ years	
	Floor - Tile	427	121	SF	6	10+ years	
	Lighting - Lay-in	427	2	EA	6	6-10 years	Missing covers
	Power Distribution	427	4	EΑ	6	10+ years	Triboning develo
	Walls - Plaster/Drywall	427	256	SF	6	10+ years	
	Ceiling - Lay-in	429 - Supply Room	121	SF	6	10+ years	
	Doors - Side-lite	429 - Supply Room	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	429 - Supply Room	1	EA	6	10+ years	
	Floor - Tile	429 - Supply Room	121	SF	6	10+ years	
	Lighting - Lay-in	429 - Supply Room	2	EA	5	1-2 years	Missing covers
	Power Distribution	429 - Supply Room	4	EA	6	10+ years	wildsing covers
	Walls - Plaster/Drywall	429 - Supply Room	256	SF	6	10+ years	
	Ceiling - Lay-in	431 - Supply Room	111	SF	6	10+ years	
	Ceiling - Lay-in	431 - Supply Room	10	SF	4	1-2 years	Water damage
	Doors - Side-lite	431 - Supply Room	32	SF	7	10+ years	Water damage
	Doors - Wood Doors inclu hw	431 - Supply Room	1	EA	6	10+ years	
	Floor - Tile	431 - Supply Room	121	SF	6	-	
	Lighting - Lay-in	431 - Supply Room 431 - Supply Room	121	EA	7	10+ years 6-10 years	
	Lighting - Lay-in	431 - Supply Room 431 - Supply Room	1	EA	6	6-10 years	Missing cover
							wissing cover
	Power Distribution	431 - Supply Room	4	EA SF	6	10+ years	
	Walls - Plaster/Drywall	431 - Supply Room	256	SF	6	10+ years	
_Auditoriu	ım & Theater						
	Ceiling - Lay-in	1st Floor	2,449	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	622	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	6	EΑ	6	10+ years	
	Floor - Tile	1st Floor	3,071	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	52	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Main Floor Seating	1st Floor	341	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Sound System	1001	Į.	_, 、	•	5 To yours	








Catego	ry : Room		В	uildina	: Additi		O N Lawridate AVENOE, Chicago, IL 60616
52.090	· <b>y</b> · · · · · · · · · · · · · · · · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Stage	1st Floor	230	SF	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Tile	1st Floor	30	LF	6	10+ years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,902	SF	6	10+ years	
Kitchen							
	Ceiling - Lay-in	Basement	1,220	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	, 4	EA	6	10+ years	
	Floor - Tile	Basement	1,210	SF	6	10+ years	
	Floor - Tile	Basement	10	SF	5	1-2 years	Damaged tiles
	Lighting - Lay-in	Basement	21	EA	7	6-10 years	Damaged mee
	Serving Line	Basement	16	LF	7	10+ years	
	Walls - Concrete Block	Basement	900	SF	6	10+ years	
	Walls - Metal Panel	Basement	1,050	SF	6	10+ years	
			,,,,,			, , , , , , , , , , , , , , , , , , , ,	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	Basement	3,282	SF	6	10+ years	
	Ceiling - Splined	Basement	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	4	EA	6	10+ years	
	Floor - Tile	Basement	4,062	SF	6	10+ years	
	Lighting - Lay-in	Basement	5	EA	7	6-10 years	
	Walls - Concrete Block	Basement	1,400	SF	6	10+ years	
	Walls - Metal Panel	Basement	1,200	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	315	SF	6	10+ years	
_Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	30	SF	7	10+ years	
	Janitor's Closet	4th Floor	72	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	175	SF	7	10+ years	
	Storage Room	Basement	540	SF	5	10+ years	
_Prep Ro	om						
	Casework	218A	25	LF	6	10+ years	
	Ceiling - Lay-in	218A	118	SF	6	10+ years	
	Doors - Wood Doors inclu hw	218A	2	EA	7	10+ years	
	Floor - Tile	218A	118	SF	6	6-10 years	
	Lighting - Lay-in	218A	3	EA	7	•	
	Walls - Plaster/Drywall	218A 218A	460	SF	6	6-10 years	
					_	10+ years	
	Work Sink	218A	1	EA	7	10+ years	
	Casework	316A	26	LF CF	6	10+ years	
	Ceiling - Lay-in	316A	136	SF	6	10+ years	







**Building: Addition 2** Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Lav-in 316A SF 4 0-1 vear Water damage Doors - Wood Doors inclu hw EΑ 6 316A 1 10+ years Floor - Tile 316A 144 SF 6 10+ years 2 EΑ 6 Lighting - Lay-in 316A 6-10 years SF Walls - Plaster/Drywall 316A 380 6 10+ years 7 Work Sink EΑ 10+ years 316A 1 316B - Currently Storage LF Casework 80 6 10+ years Ceiling - Plaster/Drywall SF 316B - Currently Storage 110 6 10+ years Doors - Wood Doors inclu hw 316B - Currently Storage 1 EΑ 6 10+ years SF Floor - Tile 316B - Currently Storage 110 6 10+ years Lighting - Pendent/Surface 316B - Currently Storage 3 EΑ 7 6-10 years Walls - Plaster/Drywall 316B - Currently Storage 426 SF 6 10+ years 25 LF 6 Casework 318A 10+ years SF 6 Ceiling - Plaster/Drywall 318A 118 10+ years Doors - Wood Doors inclu hw 318A EΑ 6 10+ years 1 118 SF 6 Floor - Tile 318A 10+ years Lighting - Pendent/Surface EΑ 7 318A 3 6-10 years Walls - Plaster/Drywall 318A 460 SF 6 10+ years Restroom SF 7 Accessories 1st Flr - Main Office South 22 6-10 years Ceiling - Plaster/Drywall 1st Flr - Main Office South 22 SF 7 10+ years Doors - Wood Doors inclu hw 1st Flr - Main Office South 1 FΑ 7 10+ years Floor - Tile 1st Flr - Main Office South 22 SF 7 10+ years Lavatory 1st Flr - Main Office South 1 EΑ 7 10+ years 1 EΑ 7 6-10 years Lighting - Pendent/Surface 1st Flr - Main Office South SF Walls - Tile Ceramic/ Porcelain 1st Flr - Main Office South 150 6 10+ years EΑ 7 Water Closet 1st Flr - Main Office South 10+ years 1 32 SF Accessories 1st Flr Main Office North 7 6-10 years SF Ceiling - Plaster/Drywall 1st Flr Main Office North 32 7 10+ years Doors - Wood Doors inclu hw 1st Flr Main Office North 1 EΑ 7 10+ years SF Floor - Tile 1st Flr Main Office North 32 7 10+ years Lavatory 1st Flr Main Office North 1 EΑ 7 10+ years Lighting - Pendent/Surface 1st Flr Main Office North 1 EΑ 7 6-10 years Walls - Tile Ceramic/ Porcelain 1st Flr Main Office North SF 7 10+ years 160 Water Closet 1st Flr Main Office North EΑ 7 10+ years SF Accessories 214 - Restroom/Storage 174 5 6-10 years Missing Used as storage-abandoned (Abandoned) Ceiling - Plaster/Drywall 214 - Restroom/Storage 174 SF 6 10+ years Used as storage-abandoned (Abandoned) Doors - Wood Doors inclu hw 214 - Restroom/Storage 1 EΑ 6 10+ years Used as storage-abandoned (Abandoned) Floor - Terrazzo 214 - Restroom/Storage 174 SF 6 10+ years Used as storage-abandoned (Abandoned)







Accessories

**Building: Addition 2** Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments 214 - Restroom/Storage Lavatory 2 FΑ 4 0-1 vear Removed Used as storage-(Abandoned) abandoned Lighting - Pendent/Surface 214 - Restroom/Storage 2 FΑ 6 Used as storage-abandoned 6-10 years (Abandoned) **Partitions** 214 - Restroom/Storage EΑ 5 1-2 years Damaged Used as storage-(Abandoned) abandoned Walls - Structural Glazed Tile 214 - Restroom/Storage SF Used as storage-abandoned 594 6 10+ years (Abandoned) Water Closet 214 - Restroom/Storage 4 EΑ 4 0-1 year Out of order Used as storage-(Abandoned) abandoned Accessories 3rd Floor Unisex East 190 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Floor Unisex East 190 SF 6 10+ years Doors - Wood Doors inclu hw EΑ 6 10+ years 3rd Floor Unisex East 1 SF 6 Floor - Terrazzo 3rd Floor Unisex East 190 10+ years Floor Drain EΑ 7 3rd Floor Unisex East 1 10+ years 7 Hand Dryer 3rd Floor Unisex East 1 FΑ 6-10 years Lavatory 3rd Floor Unisex East 1 EΑ 6 10+ years Lighting - Pendent/Surface 3rd Floor Unisex East 3 EΑ 7 6-10 years Urinals 3rd Floor Unisex East 1 EΑ 7 10+ vears Walls - Plaster/Drywall 3rd Floor Unisex East 200 SF 6 10+ years Walls - Structural Glazed Tile 3rd Floor Unisex East 370 SF 6 10+ years 7 Water Closet 3rd Floor Unisex East 1 EΑ 10+ years SF 7 Accessories 4th Floor Unisex 65 6-10 years SF Ceiling - Plaster/Drywall 4th Floor Unisex 65 6 10+ years Doors - Wood Doors inclu hw EΑ 6 4th Floor Unisex 1 10+ years Floor - Tile SF 4th Floor Unisex 65 6 10+ years 5 EΑ 1-2 years Perpetual drip Lavatory 4th Floor Unisex 1 Lighting - Pendent/Surface EΑ 7 6-10 years 4th Floor Unisex 1 **Partitions** 4th Floor Unisex 1 EΑ 7 10+ years Walls - Plaster/Drywall 4th Floor Unisex 100 SF 6 10+ years 4th Floor Unisex SF Walls - Tile Ceramic/ Porcelain 428 6 10+ years Water Closet 4th Floor Unisex EΑ 7 10+ years 1 SF 226 5 6-10 years Accessories Basement Ceiling - Plaster/Drywall 226 SF 6 6-10 years Basement Doors - Wood Doors inclu hw 7 Basement 1 EΑ 10+ years SF Floor - Terrazzo Basement 226 6 10+ years Hand Dryer **Basement** 1 EΑ 7 6-10 years Basement 1 EΑ 6 10+ years Lavatory Lighting - Pendent/Surface Basement 4 EΑ 5 6-10 years Missing diffuser **Partitions** Basement 1 EΑ 5 10+ vears Urinals **Basement** 1 EΑ 6 10+ years 465 SF 6 Walls - Structural Glazed Tile Basement 10+ years Water Closet Basement EΑ 6 10+ years SF 5 6-10 years

119

Basement





Catego	ry : Room		В	uilding	: Addition	on 2	
						Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement	119	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Terrazzo	Basement	119	SF	6	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	1	EA	7	6-10 years	
	Lavatory	Basement	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	2	EA	7	6-10 years	
	Partitions	Basement	1	EA	5	10+ years	
	Walls - Structural Glazed Tile	Basement	338	SF	6	10+ years	
	Water Closet	Basement	1	EA	6	10+ years	
atego	ry : Classroom		В	uilding	: Additio	on 2	
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	660	SF	6	10+ years	No damage observed
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	660	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	
lassroc	om #216 (Science Lab Level 3)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,180	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Damaged tile
	Ceiling - Lay-in	2nd Floor	12	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	ŭ
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,130	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	70	SF	6	10+ years	
	Gas Line	2nd Floor	1	ĒΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	70	SF	6	10+ years	
		2nd Floor	10	EA	7	10+ years	







Catego	ry : Classroom		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	686	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	686	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	830	SF	6	10+ years	2001.00
Classroo	nm #218 (Science Lab Level 1)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	68	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,255	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Water damage
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,195	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	70	SF	6	6-10 years	
	Gas Line	2nd Floor		EA		•	Otympdatad
		2nd Floor	4 17	EA	6 7	10+ years	Qty updated
	Lighting - Lay-in					6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Science Lab Fume Hood	2nd Floor	1	EA	7	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	70	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	7	10+ years	
Classroc	nm #219 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	19	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	686	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	686	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	Locked
	Marker Board	2nd Floor	28	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	830	SF	6	10+ years	
Classroc	nm #221 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	19	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	686	SF	6	10+ years	
			300	٥.	•	,	







Catego	ry : Classroom		В	uilding	: Additi	on 2	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	686	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	830	SF	6	10+ years	
Classroo	om #223 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	683	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	686	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	830	SF	6	10+ years	
Classroo	om #315 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	655	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	Trator damage
	Floor - Tile	3rd Floor	660	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	3rd Floor	800	SF	6	10+ years	Looked
Classro	om #316 Art (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	47	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	510	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	3	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	886	SF	6	10+ years	
	Work Sink	3rd Floor	2	EA	7	-	
	VVOIR SIIIR	Siu Fioui	2	EA	,	10+ years	







Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #317 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	678	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	-
	Floor - Tile	3rd Floor	686	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	830	SF	6	10+ years	
Classroc	om #318 (Science Lab Level 3)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	77	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	360	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Eye Wash Station	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,080	SF	6	6-10 years	
	Gas Line	3rd Floor	1	EΑ	7	10+ years	
	Lighting - Lay-in	3rd Floor	24	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Science Lab Shower	3rd Floor	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,050	SF	6	10+ years	
	Work Sink	3rd Floor	4	EA	7	10+ years	
Classroc	om #319 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	666	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	20	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	-
	Floor - Tile	3rd Floor	686	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	2	EA	6	6-10 years	Loose covers
	Marker Board	3rd Floor	28	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	3rd Floor	830	SF	6	10+ years	
Classroc	om #321 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	







Catego	ry : Classroom		В	uilding	: Addition	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	686	SF	6	10+ years	
	Chalk Board	3rd Floor	32	LF	4	2-5 years	Covered
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	686	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	3rd Floor	830	SF	6	10+ years	LOCKGO
Classroo	om #323 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	660	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	26	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw		1	EA		•	water damage
		3rd Floor			6	10+ years	
	Floor - Tile	3rd Floor	680	SF SF	6	10+ years	Dama and Class
	Floor - Tile	3rd Floor	6		5	1-2 years	Damaged tiles
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	830	SF	6	10+ years	
Classroo	om #414 (North) (Regular Classroom)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	75	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	912	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	10+ years	
	Floor - Tile	4th Floor	912	SF	6	6-10 years	
	Lighting - Lay-in	4th Floor	18	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	966	SF	6	10+ years	
	Work Sink	4th Floor	1	EA	7	10+ years	
Classroo	om #414 (South) (Science Lab Level 3)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	960	SF	6	10+ years	
	Ceiling - Lay-in	4th Floor	10	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	10+ years	
	Eye Wash Station	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	970	SF	6	6-10 years	
	Gas Line	4th Floor	2	EA	7	-	
	Lighting - Pendent/Surface					10+ years	
	Lianiina - Penaeni/Sunace	4th Floor	19	EΑ	7	6-10 years	







Catego	ry : Classroom	Building : Addition 2					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Science Lab Shower	4th Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	983	SF	6	10+ years	
	Work Sink	4th Floor	4	EA	7	10+ years	
_Classroo	om #415 (Office)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	594	SF	6	10+ years	
	Chalk Board	4th Floor	3	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	4th Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	4th Floor	594	SF	6	6-10 years	
	Lighting - Lay-in	4th Floor	6	ĒΑ	7	6-10 years	
	Lighting - Lay-in	4th Floor	3	EA	6	6-10 years	
	Marker Board	4th Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	675	SF	6	10+ years	
Classro	nm #418 (Music Room)						
Classion		4th Floor	4			0.40	
	AC Units		1	EA LF	7	6-10 years	
	Casework	4th Floor	38	SF	6	10+ years	
	Ceiling - Lay-in	4th Floor	700		6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	267	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	967	SF	6	6-10 years	
	Lighting - Lay-in	4th Floor	18	EA	7	6-10 years	
	Marker Board	4th Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,083	SF	6	10+ years	
_Classroo	om #420 (Art Room)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	1,053	SF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	674	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	4th Floor	1,727	SF	6	6-10 years	
	Lighting - Lay-in	4th Floor	<sup>′</sup> 19	ĒΑ	7	6-10 years	
	Marker Board	4th Floor	15	LF	7	6-10 years	
	Storage/ Closet	4th Floor	378	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,075	SF	6	10+ years	
	Work Sink	4th Floor	2	EA	7	10+ years	





Catego	ry : Interior	В	Building : Addition 2					
Calogo	.y i miene.		Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor						•		
COITIGO	Ceiling - Lay-in	1st Floor	638	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	576	SF	6	10+ years		
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	6-10 years		
	Floor - Terrazzo	1st Floor	982	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years		
	Stairs - Terrazzo	1st Floor	142	LF	7	10+ years		
	Walls - Metal Panel	1st Floor	460	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	390	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	1,290	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Water da	
	Drinking Fountains - Single Fountain	2nd Floor	0	EA	5 7	•		
	Floor - Terrazzo	2nd Floor		SF	6	10+ years	Qty updated	
		2nd Floor	1,290		_	10+ years		
	Lighting - Lay-in		12	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	1	EΑ	7	6-10 years		
	Student Lockers - One Tier	2nd Floor	138	EA	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	792	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	699	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	1,170	SF	6	10+ years	No missing or damaged tiles	
	Ceiling - Plaster/Drywall	3rd Floor	96	SF	6	10+ years		
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years		
	Floor - Terrazzo	3rd Floor	1,266	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	1	EA	7	6-10 years		
	Student Lockers - One Tier	3rd Floor	160	EA	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	541	SF	6	10+ years		
	Walls - Structural Glazed Tile	3rd Floor	573	SF	6	10+ years		
	Ceiling - Lay-in	4th Floor	876	SF	6	10+ years		
	Ceiling - Lay-in	4th Floor	10	SF	4	1-2 years	Water damage	
	Doors - Wood Doors include hw	4th Floor	5	EA	6	10+ years	-	
	Floor - Tile/Sheet	4th Floor	886	SF	7	6-10 years		
	Lighting - Lay-in	4th Floor	15	EA	6	6-10 years		
	Walls - Plaster/Drywall	4th Floor	678	SF	6	10+ years		
	Walls - Structural Glazed Tile	4th Floor	1,362	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Basement	194	SF	6	10+ years		
	Doors - Wood Doors include hw	Basement	1	ĒΑ	6	10+ years		
	Drinking Fountains - Triple Fountain	Basement	3	ĒΑ	7	10+ years		
	Floor - Terrazzo	Basement	194	SF	6	10+ years		
	Lighting - Pendent/Surface	Basement	2	EA	7	6-10 years		
	Walls - Concrete Block	Basement	350	SF	6	10+ years		
	Tame Control Disolit	Daoomont	330	٥.	J	. o . youro		
Safetv								
Salety	Camera Viewing Station	1st Floor	2	EA	7	6-10 years		
	Metal Detector	1st Floor	2	EA EA	7	6-10 years		
	IVICIAI DELECIOI	121 11001	1	EA	,	o- to years		



## **Disney II Magnet School** 3900 N Lawndale AVENUE, Chicago, IL 60618

Catego	ry : Interior		Building : Addition 2					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Security Cameras	1st Floor	5	EA	7	6-10 years	45 total cameras, entire building, main and addition(8 outside)	
Stairs								
	Ceiling - Lay-in	Stairway 6	128	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Stairway 6	721	SF	6	10+ years		
	Floor - Terrazzo	Stairway 6	832	SF	6	10+ years		
	Handrails	Stairway 6	272	LF	7	10+ years		
	Lighting - Lay-in	Stairway 6	3	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	Stairway 6	5	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	Stairway 6	1	EΑ	6	6-10 years		
	Stairs - Terrazzo	Stairway 6	432	LF	6	10+ years		
	Walls - Concrete Block	Stairway 6	239	SF	6	10+ years		
	Walls - Structural Glazed Tile	Stairway 6	2,292	SF	6	10+ years		
√ertical (	Conveyance							
	Wheelchair Lift - Platform Lift	1st Floor	1	EA	7	10+ years		



Category : Site Building : Site

	y . Site			unung	· Oite	D	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	1-2 years	Sinking
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	3
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	4	ΕA	7	10+ years	
	Civil Diamage Cite mainten		·	_, .	-	.o. you.o	
encing							
	Fencing - Chain Link	Entire Site	74	LF	6	6-10 years	
	Fencing - Iron and Concrete Post	Entire Site	318	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	82	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	5	LF	5	2-5 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	60	LF	6	10+ years	
andscar	De Benches	Entire Site	2	EA	7	10+ years	
	Benches	Entire Site	5	EΑ	5	6-10 years	
	Landscape - Grass	Entire Site	9,735	SF	6	10+ years	
	Landscape - Grass Landscape - Hardscape- Concrete	Entire Site	1,200	SF	7	10+ years	Replaced
	Landscape - Hardscape- Concrete	Entire Site	2,484	SF	6	10+ years	Replaced
	Parkway trees	Entire Site	29	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,550	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	660	SF	5	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	48	SF	6	6-10 years	
arking L	ot						
Ū	Surface - Asphalt	Entire Site	2,000	SF	7	10+ years	
	Surface - Asphalt	Entire Site	4,669	SF	4	0-1 year	Cracking/potholes
	Surface - Asphalt	Entire Site	3,550	SF	4	0-1 year	Cracking/potholes
	Canado /topinak	Zinaro Ono	0,000	O.	•	o i youi	Cracking/politicist
laygrou							
	Surface - Square Rubber Mats	Northeast	1,700	SF	4	0-1 year	Vegetation growth/separating
ervice C	Sarage						
	Service Garage - Free-Standing	North	400	SF	6	10+ years	
- المستملة	_						
idewalk	Sidewalks - Perimeter Sidewalks	Entire Site	115	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	9,326	SF	6	10+ years	
	Sidewaiks - Fellilletel Sidewaiks	Entire Site	9,320		O		
	Sidewalks - Perimeter Sidewalks	Entire Site	170	SF	4	0-1 year	Cracking

Campus Name: Disney II HS Page: 50 of 53 Assessment Date: 06/24/2024



3900 N Lawndale AVENUE, Chicago, IL 60618

Category : Site		В	uilding	: Site			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Signage							
5 5	Flag Pole - Flag Pole	Southeast Corner	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted	Southeast Corner	1	EA	7	10+ years	Quantity changed to match current
	Monument - Sign	Southeast Corner	1	EA	7	6-10 years	observations

## **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Disney II HS Page: 51 of 53 Assessment Date: 06/24/2024

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	•	•							•
Computer Lab	Computer Lab	3rd Floor	306	306	885	224	50	N	N
Computer Lab	Computer Lab	4th Floor	402	408	594	14	7	Y	N
Computer Lab	Regular Classroom	3rd Floor	302	302	814	192	50	N	N
Exclusively Used by Outside	Pre School	1st Floor	101	101	1,169	210	105	Y	N
Organization					,				
Exclusively Used by Outside	Pre School	1st Floor	102	102	794	186	93	Y	N
Organization									
Exclusively Used by Outside	Pre School	1st Floor	103/105/10	105	1,572	393	196	Y	N
Organization			7		,				
Exclusively Used by Outside	Pre School	1st Floor	104	104	978	192	96	Y	N
Organization									
Exclusively Used by Outside	Regular Classroom	1st Floor	108	108	724	106	53	Y	N
Organization									
Exclusively Used by Outside	Regular Classroom	1st Floor	110	110	586	108	54	Y	N
Organization									
Regular Classroom	Computer Lab	3rd Floor	304	304	530	128	30	N	N
Regular Classroom	Counseling Room	2nd Floor	202	202	814	192	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	800	212	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	800	212	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	204 + 206	204 + 206	1,390	352	90	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	800	212	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	800	212	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	800	200	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	800	212	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	800	200	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	800	212	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	800	212	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	800	212	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	800	212	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	800	200	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	800	212	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	800	200	60	N	N
Regular Classroom	Regular Classroom	4th Floor	408	400/402	769	278	139	Υ	N
Vacant	Regular Classroom	4th Floor	404	426	637	48	24	Υ	N
Vacant	Regular Classroom	4th Floor	406	426	626	64	32	Υ	N
Vacant	Regular Classroom	4th Floor	410	408/410/412	750	171	86	Υ	N
			-						-
Building : Addition 2									
Art Room	Art Room	4th Floor	420	420	1,727	0	0	N	N

Campus Name: Disney II HS Page : 52 of 53 Assessment Date: 06/24/2024







**Classroom Summary** 

,			D	Floor Plan	<b>A</b>	Glazed	Operable	Maries el econ	0
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Music Room	Music Room	4th Floor	418	418	967	0	0	N	N
Office	Regular Classroom	4th Floor	415	415	594	116	58	Y	N
Regular Classroom	Art Room	4th Floor	414 (North)	414	912	240	120	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	660	190	63	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	217	217	686	190	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	686	190	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	221	221	686	190	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	223	686	190	63	N	N
Regular Classroom	Regular Classroom	3rd Floor	319	319	686	190	63	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	323	323	686	190	63	N	Ν
Regular Classroom	Science Classroom	3rd Floor	316 Art	316	850	216	140	N	N
Science Lab Level 1	Science Lab Level 1	2nd Floor	218	218	1,265	285	100	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	216	216	1,200	310	100	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	318	318	1,080	264	90	N	N
Science Lab Level 3	Science Lab Level 3	4th Floor	414 (South)	414	970	214	210	Υ	N
Vacant	Regular Classroom	3rd Floor	315	315	660	190	63	N	N
Vacant	Regular Classroom	3rd Floor	317	317	686	190	63	N	N
Vacant	Regular Classroom	3rd Floor	321	321	686	190	63	N	N

Campus Name: Disney II HS Page : 53 of 53 Assessment Date: 06/24/2024