



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1995	2	71,980
Campus Total			71,980

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	· ·		•			•	
	Entrance Control - Audio and Video	#1 E Main Entrance	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#1 E Main Entrance	2	EA	6	10+ years	
	Exterior Doors - Side lite	#1 E Main Entrance	2	EA	6	10+ years	
	Exterior Doors - Store Front	#1 E Main Entrance	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 E Main Entrance	2	EA	6	10+ years	
	Power Door Operator and Controls	#1 E Main Entrance	1	EA	7	6-10 years	
	Exterior Doors - Store Front	#10 W	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#10 W	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#10 W	6	LF	6	6-10 years	
	Exterior Doors - Side lite	#11 S	4	EA	6	10+ years	
	Exterior Doors - Store Front	#11 S	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#11 S	1	EA	6	10+ years	
	Exterior Doors - Side lite	#12 S	4	EA	6	6-10 years	
	Exterior Doors - Store Front	#12 S	1	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#12 S	1	EA	6	10+ years	
	Exterior Doors - Side lite	#13 S	4	EA	6	10+ years	
	Exterior Doors - Store Front	#13 S	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#13 S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#13 S	3	LF	7	10+ years	
	Exterior Doors - Store Front	#2 S	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2 S	3	EA	6	6-10 years	
	Exterior Doors - Store Front	#3 S	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3 S	3	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#3.1 S	2	EA	6	6-10 years	
						-	



Catego	ry : Exterior		В	uilding	: Main		-
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Overhead Rolling/ Garage	#3.2 W OVH	1	EA	6	6-10 years	
	Door						
	Exterior Doors - Exterior Steel Door	#3.3 N	2	EA	6	6-10 years	
	Exterior Doors - Store Front	#4 N	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#4 N	3	EA	6	10+ years	
	Exterior Doors - Store Front	#5 N	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5 N	3	EA	6	10+ years	
	Exterior Doors - Store Front	#6 E	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 E	1	EA	6	10+ years	
	Exterior Doors - Side lite	#7 N	4	EA	6	10+ years	
	Exterior Doors - Store Front	#7 N	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 N	3	LF	6	6-10 years	
	Exterior Doors - Side lite	#8 N	4	EA	6	10+ years	
	Exterior Doors - Store Front	#8 N	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 N	3	LF	6	10+ years	
	Exterior Doors - Side lite	#9 N	4	EA	6	10+ years	
	Exterior Doors - Store Front	#9 N	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#9 N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 N	3	LF	6	10+ years	
_Foundati	on						
Odridati	Foundation - Concrete	Entire Building	880	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	71,780	SF	7	10+ years	
	Topping	Little Ballanig	71,700	Oi	'	101 years	
	Superstructure - Metal Deck/ Concrete	Entire Building	200	SF	5	1-2 years	Cracked slab in cafeteria
	Topping	Little Ballanig	200	O1	0	1 Z yours	Gracica siab in careteria
	. oppg						
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	10+ years	
_Roof Sys							
	Access Ladder - Metal	Entire Building	1	EA	7	10+ years	
	Chimney - Metal Flue	Entire Building	5	LF . –	6	6-10 years	
	Coping - Stone	Entire Building	1,280	LF	7	10+ years	
	Downspouts - Interior Downspouts	Entire Building	576	LF . –	4	0-1 year	Leaks at roof drains throughout
	Parapet - 16" - 30" Height	Entire Building	200	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Entire Building	1,080	LF	6	6-10 years	
	Roof - Modified Bitumen	Entire Building	38,800	SF	3	0-1 year	Holes, leaks, alligatoring. Seam cracks throughout
	Roof Hatch - Metal	Entire Building	1	EA	7	10+ years	- · · · · 3 · · · ·
	Roof Structure - Steel / Metal Deck/	Entire Building	38,800	SF	7	10+ years	
		S	,			,	

Campus Name: Finkl Page : 2 of 31 Assessment Date: 04/09/2024



Category : Exterior

William F Finkl Elementary School 2332 S Western AVENUE, Chicago, IL 60608

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
O. Gup	Concrete Topping	2 000	quantity	CO	rtaint	rtopiacomon.	
\\/alla							
_Walls	Canopy - Metal	Entire Building	520	SF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	31,853	SF	7	10+ years	
_Windows		F (400			10	
	Curtain wall - Louver Lintels - Stone	Entire Building Entire Building	432 1,060	SF LF	6 7	10+ years 10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,089	SF	6	10+ years	
	·					, , , , , , , , , , , , , , , , , , , ,	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	cy System	Location	Quantity	COM	Rank	Replacement	Comments
go	Emergency A/C Power - Corridors and	1st floor, Entire Building	14,216	SF	6	6-10 years	_
	Stairs					•	
	Emergency A/C Power - Gym	1st floor, Entire Building	3,471	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	1st floor, Entire Building	1,818	SF	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	74.000	EA SF	6	10+ years	
	Security System - CCTV	Entire Building	71,980	SF SF	6	6-10 years	
	Security System - Intrusion Detection Exit Signs - Corridors and Stairs	Entire Building	71,980	SF EA	6 2	6-10 years	Ciana haya na haakun hattariaa and
	Exit Signs - Corridors and Stairs	Entire Building	23	EA	2	0-1 year	Signs have no backup batteries and the school has no emergency
							generator.
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	Signs have no backup batteries and
	,	9				•	the school has no emergency
							generator.
	Exit Signs - Lunchroom	Entire Building	3	EA	2	0-1 year	Quantity changed to match current
							observations. Signs have no backup batteries and the school has no
							emergency generator.
	Emergency Battery Packs - Corridors and	Entire Building	19	EA	6	6-10 years	emergency generator.
	Stairs	9			· ·	o .o you.o	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	6-10 years	
_Main Sei	avice.						
_walli sel	Main Electrical Service - 1600 A	Electrical Room	1	EA	6	10+ years	
	277/480/3PH		•		-	-	
	PA System	Entire Building	71,980	SF	6	6-10 years	Control console located in MDF
							Room. User interface located in Main
							Office.

Building: Main

Campus Name: Finkl Page : 3 of 31 Assessment Date: 04/09/2024



Catego	ry : Electrical		B	Building	: Main		oz o westem were, emeage, iz eeee
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Independent Electrical Service for	Entire Building	1	EA	6	10+ years	
	emergency power						
	Independent Electrical Service for	Entire Building	1	EA	6	10+ years	
	emergency power						
Power D	istribution						
_ T OWEL D	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	4	0-1 year	Rank, Reason and Priority Rep
	ing and remain and reserve	g	•		•	o . you.	changed as open fuse receptacles
							expose live conductors presenting a
							live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	8	EA	7	10+ years	Quantity changed to match current
	11.14. IB B I 400.4	F # B ##				0.4	observations.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live
							conductors presenting a live front condition. Located in NE electrical
							closet.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live
	Lighting and Fower Fallets 7,5000 1007	Entire Building	·	L/\	7	o i youi	conductors presenting a live front
							condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live
							conductors presenting a live front
							condition. Located in SE electrical
							closet.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live
							conductors presenting a live front
							condition. Located in SW electrical closet.
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	Quantity changed to match current
	amp	Littile Building	ı	LA	,	10+ years	observations.
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	obool valiono.
	Transformers - 277/480 - 120/208	Entire Building	5	EΑ	6	10+ years	Quantity changed as total has been
		3				, , , , , ,	divided/aggregated. Location
							changed for clarification.
0-1	m Fine Buetestien		-	! I . ! !	- NA -:		
Catego	ry : Fire Protection		<u></u>	Building	: wain	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sioup	Rolli 13po	Location	Qualitity		Ruin	Ropidocinent	Commonto

			_		Recommend	
p Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Alarm						
Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present.
Fire Alarm Panel	Entire Building	1	EΑ	6	6-10 years	
Fire Alarm Strobe Lights	Entire Building	71,980	SF	6	10+ years	
Fire Alarm_System	Entire Building	71,980	SF	6	10+ years	

Campus Name: Finkl Page : 4 of 31 Assessment Date: 04/09/2024



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	Location changed for clarification.
Pump R	oom Assembly						
	Fire Pump - 25-50 hp	Fire Pump Room	1	EA	6	6-10 years	Location changed for clarification.
	Jockey Pump	Fire Pump Room	1	EA	6	10+ years	Location changed for clarification. No CPS Asset Tag present.
Sprinkle	r System						
	Sprinkler Heads	Entire Building	71,980	SF	7	10+ years	
	Sprinkler Piping	Entire Building	71,980	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	71,980	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Conc	• • • • • • • • • • • • • • • • • • •	Location	Quantity	CON	IVALIK	Replacement	Comments
	Condensing Unit- Roof Mounted - 11-20 tons Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	4	2-5 years 2-5 years	ACCU-3, serves kitchen and lunchroom spaces. 25-plus-year-old vintage unit that is operational and has been well maintained but has become deteriorated with signs of coil damage. Rank, Reason and Priority Rep adjusted to document that the equipment has exceeded its anticipated service life. ACCU-4, serves gym and associated spaces. 25-plus-year-old vintage unit that is operational and has been well maintained but has become deteriorated with signs of coil damage. Rank, Reason and Priority Rep adjusted to document that the
	Condensing Unit- Roof Mounted - Greater than 50 tons	Roof	1	EA	4	2-5 years	equipment has exceeded its anticipated service life. ACCU-1, serves south side of the building. 25-plus-year-old vintage unit that is operational and has been well maintained but has become deteriorated with signs of coil damage. Rank, Reason and Priority Rep adjusted to document that the equipment has exceeded its anticipated service life.

Campus Name: Finkl Page : 5 of 31 Assessment Date: 04/09/2024



Catego	ry : Mechanical		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Condensing Unit- Roof Mounted - Greater than 50 tons	Roof	1	EA	4	2-5 years	ACCU-2, serves north side of the building. 25-plus-year-old vintage unit that is operational and has been well maintained but has become deteriorated with signs of coil damage. Rank, Reason and Priority Rep adjusted to document that the equipment has exceeded its anticipated service life.	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	Component of a ductless split system serving the MDF Room.	
Air Hand	lling Systems							
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	62	EA	5	6-10 years	Quantity changed as total has been divided/aggregated.	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 20001-30000 cfm	Mech. Room - AHU-1	1	EA	5	6-10 years	AHU-1, serves south side of the building. Location changed for clarification.	
	Air Intake	Mech. Room - AHU-1	1	EΑ	5	6-10 years	Location changed for clarification.	
	Induction Fan	Mech. Room - AHU-1	1	EΑ	5	6-10 years	Location changed for clarification.	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 20001-30000 cfm	Mech. Room - AHU-2	1	EA	5	6-10 years	AHU-2, serves north side of building. Location changed for clarification.	
	Air Intake	Mech. Room - AHU-2	1	EA	5	6-10 years	Location changed for clarification.	
	Induction Fan	Mech. Room - AHU-2	1	EΑ	5	6-10 years	Location changed for clarification.	
	VAV Box	Mech. Room - AHU-2	6	EΑ	5	6-10 years	•	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 4000-8000 cfm	Mech. Room - AHU-3	1	EA	5	6-10 years	AHU-3, serves kitchen and lunchroom spaces. Location changed for clarification.	
	Air Intake	Mech. Room - AHU-3	1	EA	6	6-10 years	Location changed for clarification.	
	Induction Fan	Mech. Room - AHU-3	1	EA	5	6-10 years	Location changed for clarification.	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - Less than 4000 cfm	Mech. Room - AHU-4	1	EA	5	6-10 years	AHU-4, serves gym spaces. Location changed for clarification.	
	Air Intake	Mech. Room - AHU-4	1	EA	5	6-10 years	Location changed for clarification.	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	5	6-10 years	RF-1. Location changed for clarification.	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	5	6-10 years	RF-2. Location changed for clarification.	
	Indoor Return Fans- Centrifugal Inline - Less than 5000 CFM	Mechanical Room	1	EA	5	6-10 years	RF-3. Location changed for clarification.	
	Make Up Air Unit- Roof Mounted- Electric Coils - 6000 - 10,000 cfm	Roof	1	EA	5	6-10 years	Original to the building. Serves kitchen.	

Campus Name: Finkl Page : 6 of 31 Assessment Date: 04/09/2024



Catego	ry : Mechanical		В	uilding	Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy							
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	3	EA	5	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	3	EA	5	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	5	10+ years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	6	10+ years	B-3
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	6	10+ years	B-2
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	6	10+ years	B-1
	Water Fill System	Boiler Room	1	EA	6	10+ years	
Heating	Devices						
_	Radiator Panels - Hot Water	1st Floor	10	EA	6	10+ years	Located throughout the Main Office suite.
	Cabinet Heaters - With Hot Water Coil	Entire Building	8	EA	6	10+ years	Misdocumented in previous assessment. Located in lunchroom.
	Cabinet Heaters - With Hot Water Coil	Entire Building	10	EA	6	10+ years	Quantity changed to match current observations. Located in egress vestibules and associated stairwells.
	Unit Heater - Electric	Entire Building	1	EA	5	6-10 years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	10+ years	Located in kitchen delivery/loading vestibule.
	Unit Heater - Hot Water	Entire Building	1	EA	5	6-10 years	
	Unit Heater - Hot Water	Entire Building	1	EA	5	6-10 years	Location changed for clarification.
	Unit Heater - Hot Water	Entire Building	2	EA	5	6-10 years	One each located in the north and south mechanical rooms.
	Fin Tube - Hot Water	Entire Building	170	LF	6	10+ years	
Mechani	ical Plumbing						
	Hot Water Pump - 10 - 20 HP	Entire Building	1	EA	5	6-10 years	
	Hot Water Pump - 10 - 20 HP	Entire Building	1	ΕA	5	6-10 years	
	Hot Water Pump - Less than 10	Entire Building	1	EA	5	6-10 years	Associated with AHU-1. Location changed for clarification. No CPS Asset Tag present.
	Hot Water Pump - Less than 10	Entire Building	1	EA	5	6-10 years	Associated with AHU-3. Location changed for clarification. No CPS Asset Tag present.

Campus Name: Finkl Page : 7 of 31 Assessment Date: 04/09/2024



Catego	ry : Mechanical		R	uilding	· Main	20	32 S Western AVENUE, Chicago, IL 60608
Calcgo	y : McChamca			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
o.oup	Hot Water Pump - Less than 10	Entire Building	1	EA	5	6-10 years	Associated with AHU-2. Location changed for clarification. No CPS Asset Tag present.
	Hot Water Pump - Less than 10	Entire Building	1	EA	5	6-10 years	Associated with AHU-4. Location changed for clarification. No CPS Asset Tag present.
	Hydronic Supply and Return - Copper Hydronic Supply and Return - Steel	Entire Building Entire Building	700 100	LF LF	6 6	10+ years 10+ years	
empera	ture Control						
·	DDC System	Entire Building	71,980	SF	4	2-5 years	System has not had software upgrades and is operational strictly in default mode with other adjustments performed manually. System is 25-plus years old and has exceeded its anticipated service life.
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	
	Electric Thermostat	Entire Building	6	EΑ	6	6-10 years	
	Thermostats - DDC	Entire Building	46	EA	6	6-10 years	
√entilatio	nn						
ZOTTIIOTIC	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years	Quantity changed to match current observations.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	5	EA	6	6-10 years	Quantity changed to match current observations.
	Roof Mounted Duct Work	Entire Building	8	LF	5	6-10 years	Attached to the adjacent make-up ai unit. Quantity changed to match physical measurement obtained at the time of assessment.
	Type I Exhaust Hood- Kitchen	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations.
Catego	ry : Plumbing		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room Boiler Room	1	EA EA	5 6	6-10 years 6-10 years	
Piping							
- 							



Catego	ry : Plumbing		В	uilding	: Main		
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Lines	Entire Building	71,980	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	71,980	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	71,980	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	71,980	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	71,980	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	71,980	SF	6	10+ years	
	Sanitary Piping	Entire Building	71,980	SF	6	10+ years	
	Storm Piping	Entire Building	71,980	SF	6	10+ years	
	Vent Piping	Entire Building	71,980	SF	6	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	5	6-10 years	Location changed for clarification.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	10+ years	Elevator pit sump pump. Not accessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer.

Category: Room **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	100 Staff room	739	SF	7	10+ years	
	Doors - Wood Doors inclu hw	100 Staff room	1	EA	7	10+ years	
	Floor - Carpet	100 Staff room	614	SF	7	6-10 years	
	Floor - Tile	100 Staff room	125	SF	7	10+ years	
	Lighting - Lay-in	100 Staff room	12	EA	7	6-10 years	
	Lighting - Lay-in	100 Staff room	1	EA	5	1-2 years	Not working
	Power Distribution	100 Staff room	9	EA	7	10+ years	
	Walls - Concrete Block	100 Staff room	700	SF	7	10+ years	
	Work SInk	100 Staff room	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor assistant principals office	154	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor assistant principals office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor assistant principals office	154	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor assistant principals office	2	EA	7	6-10 years	
	Power Distribution	1st Floor assistant principals office	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor assistant principals office	181	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor assistant principals office	247	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor counselor north	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor counselor north	1	EA	7	10+ years	

Campus Name: Finkl Page : 9 of 31 Assessment Date: 04/09/2024



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	1st Floor counselor north	150	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor counselor north	2	EA	7	6-10 years	
	Power Distribution	1st Floor counselor north	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor counselor north	497	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor counselor office 118	139	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor counselor office 118	1	EA	7	10+ years	
	Floor - Carpet	1st Floor counselor office 118	139	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor counselor office 118	2	EA	7	6-10 years	
	Power Distribution	1st Floor counselor office 118	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor counselor office 118	474	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor custodian break area	482	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor custodian break area	2	EA	7	10+ years	
	Floor - Tile	1st Floor custodian break area	482	SF	7	10+ years	
	Lighting - Lay-in	1st Floor custodian break area	6	EA	7	6-10 years	
	Power Distribution	1st Floor custodian break area	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor custodian break area	1,105	SF	7	10+ years	
	AC Unit	1st Floor principals office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor principals office	267	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor principals office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor principals office	267	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor principals office	3	EA	7	6-10 years	
	Power Distribution	1st Floor principals office	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor principals office	263	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor principals office	329	SF	7	10+ years	
	Ceiling - Lay-in	1st floor main office/Business Office	796	SF	7	10+ years	
	Doors - Side-lite	1st floor main office/Business Office	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor main office/Business Office	1	EA	7	10+ years	
	Floor - Carpet	1st floor main office/Business Office	659	SF	7	6-10 years	
	Floor - Tile Quarry	1st floor main office/Business Office	137	SF	7	10+ years	
	Lighting - Lay-in	1st floor main office/Business Office	12	EA	7	6-10 years	
	Power Distribution	1st floor main office/Business Office	14	EA	7	10+ years	
	Storage/ Closet	1st floor main office/Business Office	220	SF	7	10+ years	
	Walls - Concrete Block	1st floor main office/Business Office	1,094	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor main office/Business Office	578	SF	7	10+ years	
	Work Sink	1st floor main office/Business Office	1	EA	7	10+ years	
	Ceiling - Lay-in	Case manager 1st floor 119	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Case manager 1st floor 119	1	EA	7	10+ years	
	Floor - Tile	Case manager 1st floor 119	150	SF	7	10+ years	
	Lighting - Lay-in	Case manager 1st floor 119	2	EA	7	6-10 years	
	Power Distribution	Case manager 1st floor 119	6	EA	7	10+ years	
	Walls - Concrete Block	Case manager 1st floor 119	180	SF	7	10+ years	
	Walls - Plaster/Drywall	Case manager 1st floor 119	180	SF	7	10+ years	
	Work SInk	Case manager 1st floor 119	1	ĒΑ	7	10+ years	
	Ceiling - Lay-in	Engineer's office	145	SF	7	10+ years	
	5	5				,	

Campus Name: Finkl Page : 10 of 31 Assessment Date: 04/09/2024



Category : Room			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	Engineer's office	1	EA	7	10+ years	
	Floor - Tile	Engineer's office	145	SF	7	10+ years	
	Lighting - Lay-in	Engineer's office	2	EA	7	6-10 years	
	Power Distribution	Engineer's office	8	EA	7	10+ years	
	Walls - Concrete Block	Engineer's office	467	SF	7	10+ years	
	Ceiling - Lay-in	Gym office	115	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gym office	1	EA	7	10+ years	
	Floor - Tile	Gym office	115	SF	7	10+ years	
	Lighting - Lay-in	Gym office	2	EA	7	6-10 years	
	Power Distribution	Gym office	8	EA	7	10+ years	
	Walls - Concrete Block	Gym office	420	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen office	67	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen office	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen office	67	SF	7	10+ years	
	Lighting - Lay-in	Kitchen office	1	EA	7	10+ years	
	Power Distribution	Kitchen office	4	EA	7	10+ years	
	Walls - Concrete Block	Kitchen office	123	SF	7	10+ years	
	Ceiling - Lay-in	Office in main office suite next to	146	SF	7	10+ years	
		Ass't principal					
	Ceiling - Lay-in	Office in main office suite next to	4	SF	5	1-2 years	Stained tile
		Ass't principal					
	Doors - Wood Doors inclu hw	Office in main office suite next to	1	EA	7	10+ years	
		Ass't principal					
	Floor - Carpet	Office in main office suite next to	150	SF	7	6-10 years	
		Ass't principal					
	Lighting - Lay-in	Office in main office suite next to	2	EA	7	6-10 years	
		Ass't principal					
	Power Distribution	Office in main office suite next to	6	EA	7	10+ years	
		Ass't principal					
	Walls - Concrete Block	Office in main office suite next to	180	SF	7	10+ years	
		Ass't principal					
	Walls - Plaster/Drywall	Office in main office suite next to	245	SF	7	10+ years	
		Ass't principal					
_Gymnas							
	Bleacher Seating	1st Floor	100	EA	7	10+ years	
	Ceiling - Exposed	1st Floor	3,471	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Sport Flooring	1st Floor	3,471	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	264	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	7,059	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	20	SF	5	1-2 years	Cracked block
						÷	

Campus Name: Finkl Page : 11 of 31 Assessment Date: 04/09/2024



Group				Building : Main				
Group						Recommend		
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
1.6%								
Kitchen	Cailing Lavin	4 at Elean com (am)	075		7	10		
	Ceiling - Lay-in	1st Floor servery	975	SF		10+ years		
	Doors - Steel Doors incl hw	1st Floor servery	2	EA	7	10+ years		
	Floor - Tile	1st Floor servery	975	SF	7	10+ years		
	Lighting - Lay-in	1st Floor servery	15	EA	7	6-10 years		
	Serving Line	1st Floor servery	24	LF	7	10+ years		
	Storage/ Closet	1st Floor servery	20	SF	7	10+ years		
	Walls - Concrete Block	1st Floor servery	1,151	SF	7	10+ years		
	Ceiling - Lay-in	Dishwashing room	145	SF	7	10+ years		
	Doors - Steel Doors incl hw	Dishwashing room	1	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	Dishwashing room	145	SF	7	10+ years		
	Lighting - Lay-in	Dishwashing room	2	EA	7	10+ years		
	Walls - Concrete Block	Dishwashing room	500	SF	7	10+ years		
	Ceiling - Lay-in	Room 1-10	963	SF	7	10+ years		
	Ceiling - Lay-in	Room 1-10	8	SF	4	1-2 years	Sagging tile	
	Doors - Steel Doors incl hw	Room 1-10	1	EA	7	10+ years	33 3	
	Floor - Concrete Epoxy/ Painted	Room 1-10	971	SF	7	10+ years		
	Lighting - Lay-in	Room 1-10	12	ĒΑ	7	6-10 years		
	Storage/ Closet	Room 1-10	220	SF	7	10+ years		
	Walls - Concrete Block	Room 1-10	1,248	SF	7	10+ years		
			,			,		
Library	0 1	0 15	100					
	Casework	2nd Floor	160	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	3,075	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years		
	Floor - Tile	2nd Floor	3,075	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor	28	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	1,245	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,245	SF	7	10+ years		
Locker/Sł	nower Room							
	Accessories	Women's staff locker room at kitchen	132	SF	7	6-10 years		
	Ceiling - Lay-in	Women's staff locker room at	96	SF	7	10+ years		
	Ceiling - Plaster/Drywall	kitchen Women's staff locker room at	36	SF	7	10+ years		
	Doors - Steel Doors incl hw	kitchen Women's staff locker room at kitchen	1	EA	7	10+ years		
	Doors - Steel Doors incl hw	Women's staff locker room at kitchen	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Women's staff locker room at	132	SF	7	10+ years		

Campus Name: Finkl Page : 12 of 31 Assessment Date: 04/09/2024



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		kitchen					
	Floor Drain	Women's staff locker room at	1	EA	7	10+ years	
		kitchen					
	Lavatory	Women's staff locker room at	1	EA	7	10+ years	
		kitchen			_	0.40	
	Lighting - Lay-in	Women's staff locker room at	4	EA	7	6-10 years	
	Partitions	kitchen Women's staff locker room at	1	EA	7	10	
	Partitions	kitchen	I	EA	7	10+ years	
	Showers	Women's staff locker room at	1	EA	7	10+ years	
	Silowers	kitchen	'	LA	,	10+ years	
	Student Lockers - Two Tier	Women's staff locker room at	8	EA	7	10+ years	
	Cladelik Edekere Two Tier	kitchen	· ·	_, ,	•	101 youro	
	Walls - Concrete Block	Women's staff locker room at	296	SF	7	10+ years	
		kitchen		_		,	
	Water Closet	Women's staff locker room at	1	EA	7	10+ years	
		kitchen					
Lunch &	Multipurpose Room						
	Ceiling - Exposed	Room 1-15	2,160	SF	7	10+ years	
	Doors - Steel Doors incl hw	Room 1-15	4	EA	7	10+ years	
	Floor - Tile	Room 1-15	2,130	SF	7	10+ years	
	Floor - Tile	Room 1-15	30	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	Room 1-15	4	EA	7	6-10 years	
	Walls - Concrete Block	Room 1-15	4,110	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 1-15	917	SF	7	10+ years	
	Ceiling - Lay-in	Room 1-52	1,845	SF	7	10+ years	
	Doors - Side-lite	Room 1-52	8	SF	7	10+ years	
	Doors - Steel Doors incl hw	Room 1-52	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Room 1-52	2	EA	7	10+ years	
	Floor - Tile	Room 1-52	1,825	SF	7	10+ years	One also diffe
	Floor - Tile	Room 1-52	20	SF	4	1-2 years	Cracked tile
	Lighting - Lay-in	Room 1-52	25	EΑ	7	6-10 years	Not woulding
	Lighting - Lay-in	Room 1-52	1	EA SF	5 7	1-2 years	Not working
	Storage/ Closet Walls - Concrete Block	Room 1-52 Room 1-52	220 697	SF SF	7	10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	Room 1-52 Room 1-52	312	SF SF	7	10+ years 10+ years	
	vvalis - r iasici/Drywall	1100111 1-02	312	J-	,	TOT YEARS	
_MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	125	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1 1	EA	7	6-10 years	Ductless split system.
	- · · · · · · · · · · · · · · · · · · ·		·		-	3 . ,	

Campus Name: Finkl Page: 13 of 31 Assessment Date: 04/09/2024



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	65	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	145	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	40	SF	7	10+ years	
	Vaults	1st Floor	230	SF	7	10+ years	
	Janitor's Closet	2nd Floor	50	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	2,525	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	38	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	38	SF	7	10+ years	
	Storage Room	2nd Floor	90	SF	7	10+ years	
	Storage Room	2nd Floor	55	SF	7	10+ years	
	Storage Room	2nd Floor	55	SF	7	10+ years	
	Storage Room	2nd Floor	95	SF	7	10+ years	
						·	
Prep Ro	om						
•	Ceiling - Lay-in	2nd Floor-215 Prep Room	180	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-215 Prep Room	1	EA	7	10+ years	
	Floor - Tile	2nd Floor-215 Prep Room	180	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor-215 Prep Room	4	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor-215 Prep Room	90	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor-215 Prep Room	502	SF	7	10+ years	
_Restroor							
	Accessories	1st Floor Northeast staff unisex	42	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor Northeast staff unisex	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Northeast staff unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Northeast staff unisex	42	SF	7	10+ years	
	Floor Drain	1st Floor Northeast staff unisex	1	EA	7	10+ years	
	Lavatory	1st Floor Northeast staff unisex	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Northeast staff unisex	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Northeast staff unisex	84	SF	7	10+ years	
	Water Closet	1st Floor Northeast staff unisex	1	EA	7	10+ years	
	Accessories	1st Floor boys' northeast	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor boys' northeast	180	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor boys' northeast	180	SF	7	10+ years	
	Hand Dryer	1st Floor boys' northeast	1	EA	7	6-10 years	
	Lavatory	1st Floor boys' northeast	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor boys' northeast	5	EA	7	6-10 years	
	Partitions	1st Floor boys' northeast	2	EA	7	10+ years	
	Urinals	1st Floor boys' northeast	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor boys' northeast	555	SF	7	10+ years	
	Water Closet	1st Floor boys' northeast	2	EA	7	10+ years	
	Accessories	1st Floor boys' southeast	180	SF	7	6-10 years	

Campus Name: Finkl Page : 14 of 31 Assessment Date: 04/09/2024



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Plaster/Drywall	1st Floor boys' southeast	180	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor boys' southeast	180	SF	7	10+ years				
	Hand Dryer	1st Floor boys' southeast	1	EA	7	6-10 years				
	Lavatory	1st Floor boys' southeast	3	EA	7	10+ years				
	Lighting - Lay-in	1st Floor boys' southeast	5	EA	7	6-10 years				
	Partitions	1st Floor boys' southeast	2	EA	7	10+ years				
	Urinals	1st Floor boys' southeast	2	EA	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	1st Floor boys' southeast	555	SF	7	10+ years				
	Water Closet	1st Floor boys' southeast	2	EA	7	10+ years				
	Accessories	1st Floor girls' northeast	180	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor girls' northeast	180	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor girls' northeast	180	SF	7	10+ years				
	Hand Dryer	1st Floor girls' northeast	1	ĒΑ	7	6-10 years				
	Lavatory	1st Floor girls' northeast	3	EΑ	7	10+ years				
	Lighting - Lay-in	1st Floor girls' northeast	5	EA	7	6-10 years				
	Partitions	1st Floor girls' northeast	4	EA	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	1st Floor girls' northeast	555	SF	7	10+ years				
	Water Closet	1st Floor girls' northeast	4	ĒΑ	7	10+ years				
	Accessories	1st Floor girls' southeast	180	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor girls' southeast	180	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor girls' southeast	180	SF	7	10+ years				
	Hand Dryer	1st Floor girls' southeast	1	ĒΑ	7	6-10 years				
	Lavatory	1st Floor girls' southeast	3	EA	7	10+ years				
	Lighting - Lay-in	1st Floor girls' southeast	5	ĒΑ	7	6-10 years				
	Partitions	1st Floor girls' southeast	4	EA	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	1st Floor girls' southeast	555	SF	7	10+ years				
	Water Closet	1st Floor girls' southeast	4	ĒΑ	7	10+ years				
	Accessories	1st Floor kindergarten	38	SF	7	6-10 years				
	Ceiling - Lay-in	1st Floor kindergarten	38	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor kindergarten	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor kindergarten	38	SF	7	10+ years				
	Floor Drain	1st Floor kindergarten	1	EA	7	10+ years				
	Lavatory	1st Floor kindergarten	1	EΑ	7	10+ years				
	Lighting - Lay-in	1st Floor kindergarten	1	EA	7	6-10 years				
	Walls - Tile Ceramic/ Porcelain	1st Floor kindergarten	75	SF	7	10+ years				
	Water Closet	1st Floor kindergarten	1	EA	7	10+ years				
	Accessories	1st Floor southeast staff unisex	42	SF	7	6-10 years				
	Ceiling - Lay-in	1st Floor southeast staff unisex	42	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor southeast staff unisex	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor southeast staff unisex	42	SF	7	10+ years				
	Floor Drain	1st Floor southeast staff unisex	1	EA	7	10+ years				
	Lavatory	1st Floor southeast staff unisex	1	EA	7	10+ years				
	Lighting - Lay-in	1st Floor southeast staff unisex	1	EA	7	6-10 years				
	Walls - Tile Ceramic/ Porcelain	1st Floor southeast staff unisex	94	SF	7	10+ years				
	vvalis - The Octainlo/ Policelalii	13t i 1001 30utilicast stall utilisex	34	JI	,	TOT years				

Campus Name: Finkl Page : 15 of 31 Assessment Date: 04/09/2024



Category : Room			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor southeast staff unisex	1	EA	7	10+ years	
	Accessories	1st Floor staff in main office	39	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor staff in main office	35	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor staff in main office	4	SF	4	1-2 years	Stained tile
	Doors - Wood Doors inclu hw	1st Floor staff in main office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor staff in main office	39	SF	7	10+ years	
	Floor Drain	1st Floor staff in main office	1	EA	4	1-2 years	Covered drain
	Lavatory	1st Floor staff in main office	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor staff in main office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor staff in main office	82	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor staff in main office	70	SF	7	10+ years	
	Water Closet	1st Floor staff in main office	1	EA	7	10+ years	
	Accessories	2nd Floor-NE Boy's Restroom	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-NE Boy's Restroom	180	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-NE Boy's Restroom	180	SF	7	6-10 years	
	Floor Drain	2nd Floor-NE Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	2nd Floor-NE Boy's Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-NE Boy's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor-NE Boy's Restroom	5	EA	7	6-10 years	
	Partitions	2nd Floor-NE Boy's Restroom	2	EA	7	10+ years	
	Urinals	2nd Floor-NE Boy's Restroom	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-NE Boy's Restroom	578	SF	7	10+ years	
	Water Closet	2nd Floor-NE Boy's Restroom	2	EA	7	10+ years	
	Accessories	2nd Floor-NE Girl's Restroom	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-NE Girl's Restroom	180	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-NE Girl's Restroom	180	SF	7	6-10 years	
	Floor Drain	2nd Floor-NE Girl's Restroom	1	ĒΑ	7	10+ years	
	Hand Dryer	2nd Floor-NE Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-NE Girl's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor-NE Girl's Restroom	5	EA	7	6-10 years	
	Partitions	2nd Floor-NE Girl's Restroom	4	ĒΑ	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-NE Girl's Restroom	578	SF	7	10+ years	
	Water Closet	2nd Floor-NE Girl's Restroom	4	ĒΑ	7	10+ years	
	Accessories	2nd Floor-NE Unisex Staff Restroom	42	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor-NE Unisex Staff Restroom	30	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-NE Unisex Staff Restroom	12	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor-NE Unisex Staff Restroom	1	EA	6	10+ years	Traite: damage
	Floor - Tile Ceramic/ Porcelain	2nd Floor-NE Unisex Staff Restroom	42	SF	7	6-10 years	
	Floor Drain	2nd Floor-NE Unisex Staff Restroom	1	EA	7	10+ years	
	Lavatory	2nd Floor-NE Unisex Staff Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor-NE Unisex Staff Restroom	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-NE Unisex Staff Restroom	80	SF	7	10+ years	
	Water Closet	2nd Floor-NE Unisex Staff Restroom	1	EA	7	10+ years	
	Accessories	2nd Floor-SE Boy's Restroom	180	SF	7	6-10 years	
	7.0000001100	Zha i loor o'L boy a realioon	100	Oi.	,	o io youis	

Campus Name: Finkl Page : 16 of 31 Assessment Date: 04/09/2024



Category : Room		В	uilding	: Main		-	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor-SE Boy's Restroom	180	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-SE Boy's Restroom	180	SF	7	6-10 years	
	Floor Drain	2nd Floor-SE Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	2nd Floor-SE Boy's Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-SE Boy's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor-SE Boy's Restroom	5	EA	7	6-10 years	
	Partitions	2nd Floor-SE Boy's Restroom	2	EA	7	10+ years	
	Urinals	2nd Floor-SE Boy's Restroom	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-SE Boy's Restroom	578	SF	7	10+ years	
	Water Closet	2nd Floor-SE Boy's Restroom	2	EA	7	10+ years	
	Accessories	2nd Floor-SE Girl's Restroom	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-SE Girl's Restroom	180	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-SE Girl's Restroom	180	SF	7	6-10 years	
	Floor Drain	2nd Floor-SE Girl's Restroom	1	ĒΑ	7	10+ years	
	Hand Dryer	2nd Floor-SE Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-SE Girl's Restroom	3	ΕA	7	10+ years	
	Lighting - Lay-in	2nd Floor-SE Girl's Restroom	5	EA	7	6-10 years	
	Partitions	2nd Floor-SE Girl's Restroom	4	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-SE Girl's Restroom	578	SF	7	10+ years	
	Water Closet	2nd Floor-SE Girl's Restroom	4	EA	7	10+ years	
	Accessories	2nd Floor-SE Unisex Staff Restroom	42	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor-SE Unisex Staff Restroom	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-SE Unisex Staff Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-SE Unisex Staff Restroom	42	SF	7	6-10 years	
	Floor Drain	2nd Floor-SE Unisex Staff Restroom	1	EA	7	10+ years	
	Lavatory	2nd Floor-SE Unisex Staff Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor-SE Unisex Staff Restroom	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-SE Unisex Staff Restroom	80	SF	7	10+ years	
	Water Closet	2nd Floor-SE Unisex Staff Restroom	1	EA	7	10+ years	
	Accessories	Custodial staff toilet	97	SF	7	6-10 years	
	Ceiling - Lay-in	Custodial staff toilet	95	SF	6	10+ years	
	Ceiling - Lay in	Custodial staff toilet	2	SF	4	1-2 years	Stained tile
	Doors - Wood Doors inclu hw	Custodial staff toilet	1	EA	6	10+ years	Stanled the
	Floor - Tile Ceramic/ Porcelain	Custodial staff toilet	97	SF	7	10+ years	
	Floor Drain	Custodial staff toilet	1	EA	7	10+ years	
	Lavatory	Custodial staff toilet	1	EA	7	10+ years	
	Lighting - Lay-in	Custodial staff toilet	1	EA	7	6-10 years	
	Partitions	Custodial staff toilet	1	EA	7		
	Student Lockers - Two Tiers	Custodial staff toilet	8	EA	7	10+ years 10+ years	
	Walls - Concrete Block	Custodial staff toilet	201	SF	7	10+ years	
	Water Closet	Custodial staff toilet	1	Sr EA	7	,	
	Accessories		38	SF	7	10+ years	
	Ceiling - Lay-in	In room 103 In room 103	36	SF SF	7 7	6-10 years	
	Ceiling - Lay-in	In room 103	2	SF	4	10+ years 1-2 years	Stained tile
	Gening - Lay-III	111100111 103	2	SI-	4	1-2 years	Stairled tile



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	In room 103	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In room 103	38	SF	7	10+ years	
	Floor Drain	In room 103	1	EA	7	10+ years	
	Lavatory	In room 103	1	EA	7	10+ years	
	Lighting - Lay-in	In room 103	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 103	75	SF	7	10+ years	
	Water Closet	In room 103	1	EA	7	10+ years	
	Accessories	In room 105	38	SF	7	6-10 years	
	Ceiling - Lay-in	In room 105	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In room 105	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In room 105	38	SF	7	10+ years	
	Floor Drain	In room 105	1	EA	7	10+ years	
	Lavatory	In room 105	1	EA	7	10+ years	
	Lighting - Lay-in	In room 105	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 105	85	SF	7	10+ years	
	Water Closet	In room 105	1	EA	7	10+ years	
	Accessories	In room 107	38	SF	7	6-10 years	
	Ceiling - Lay-in	In room 107	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In room 107	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In room 107	38	SF	7	10+ years	
	Floor Drain	In room 107	1	EA	7	10+ years	
	Lavatory	In room 107	1	EA	7	10+ years	
	Lighting - Lay-in	In room 107	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	In room 107	75	SF	7	10+ years	
	Water Closet	In room 107	1	EA	7	10+ years	

Catego	ry : Classroom	В	Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Classroo	m #101 (Regular Classroom)							
	Casework	1st Floor	50	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	840	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	840	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	30	SF	7	2-5 years	Door removed	
	Walls - Concrete Block	1st Floor	1,298	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	m #102 (Kindergarten)							
	Casework	1st Floor	36	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	852	SF	7	10+ years		
	Doors - Side-lite	1st Floor	4	SF	7	10+ years		

Campus Name: Finkl Page : 18 of 31 Assessment Date: 04/09/2024



Catego	ry : Classroom		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	852	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,018	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	236	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroo	om #103 (Kindergarten)						
	Casework	1st Floor	14	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,076	SF	7	10+ years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,076	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	1,076	EA	7	6-10 years	
	Marker Board	1st Floor		LF			
			12		7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,054	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	309	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #104 (Regular Classroom)						_
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	852	SF	7	10+ years	
	Doors - Transom Window	1st Floor	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	852	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	782	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	472	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #105 (Kindergarten)						
	Casework	1st Floor	14	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	1,076	SF	7	10+ years	
	Doors - Side-lite	1st Floor		SF SF	7		
			4			10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,076	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA LF	7	6-10 years	
	Marker Board	1st Floor	12	1 -	7	6-10 years	

Campus Name: Finkl Page : 19 of 31 Assessment Date: 04/09/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	824	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	539	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #106 (Regular Classroom)						
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	852	SF	7	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	852	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	782	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	472	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	Covered with belongings
Classroo	om #107 (Kindergarten)						
	Casework	1st Floor	14	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,076	SF	7	10+ years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,076	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,054	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	309	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
lassroo	om #108 (Regular Classroom)						
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	852	SF	7	10+ years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	852	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,018	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	236	SF	7	10+ years	
	Work Sink	1st Floor	230	EA	7	10+ years	
	WORK OHIK	13111001	'	LA	,	TOT years	

Campus Name: Finkl Page : 20 of 31 Assessment Date: 04/09/2024



Categor	y : Classroom		В	uilding	: Main		
	No. 11		0			Recommend	•
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroor	m #110 (Faculty Lounge)						
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	852	SF	7	10+ years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	852	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	N
	Lighting - Lay-in	1st Floor	1	EA	5	1-2 years	Not working
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,018	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	236	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroor	m #111 (Regular Classroom)						
	Casework	1st Floor	14	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,076	SF	7	10+ years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,076	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	[′] 15	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,054	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	324	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroor	m #112 (Art Room)						
CIGOGIOOI	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	852	SF	7	10+ years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	852	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	782	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	472	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #114 (Store Room)						
<u> </u>	Casework	1st Floor	30	LF	7	101.110070	
		1st Floor 1st Floor	36 852	LF SF	7 7	10+ years	
	Ceiling - Lay-in Doors - Side-lite	1st Floor 1st Floor	852 4	SF SF	7	10+ years	
	DOOLS - SIGE-IIIE	ISL FIOOI	4	ЭF	1	10+ years	



Catego	ry : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	852	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	5	1-2 years	Not working
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	782	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	472	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #116 (Regular Classroom)						
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	852	SF	7	10+ years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	828	SF	7	10+ years	
	Floor - Tile	1st Floor	24	SF	4	1-2 years	Damaged tile
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	Damaged tile
	Lighting - Lay-in	1st Floor	1	EA	5	1-2 years	Not working
	Marker Board	1st Floor	24	LF	7	6-10 years	Not working
	Walls - Concrete Block	1st Floor	1,018	SF	7	•	
				SF SF		10+ years	
	Walls - Plaster/Drywall	1st Floor	236		7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #201 (Store Room)						
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	800	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	868	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	288	SF	7	10+ years	
Classroc	om #202 (Other Instructional Use)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	vvalis - i-lastei/Diywali	ZIIU FIUUI	313	SI-	,	10+ years	

Campus Name: Finkl Page : 22 of 31 Assessment Date: 04/09/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
lassroo	m #203 (Store Room)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	906	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	1-2 years	Missing and water damage
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	,					,	
assroo	m #204 (Regular Classroom)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
	Trank Chink	2110 1 1001	·	_, ,	•	o royouro	
assroo	m #205 (Play Room)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	910	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	<u>-</u>
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	rano i laoton biy wan	2110 1 1001	313	01	•	ioi youis	
assroo	m #206 (Regular Classroom)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
		2nd Floor	918	SF	7	6-10 years	

Campus Name: Finkl Page : 23 of 31 Assessment Date: 04/09/2024



Catego	ry : Classroom		R	uilding	· Main	20	332 3 Western Avenue, Chicago, it 60606
Outogo	ry : Glacoroom			anamg	· Wani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classra	om #207 (Regular Classroom)						
Classio	` •	0.151	50			40	
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #209 (Other Instructional Use)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
OI-	#040 (Damilar Cl						
Classroo	om #210 (Regular Classroom)	0.15					
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	

Campus Name: Finkl Page : 24 of 31 Assessment Date: 04/09/2024



Catego	ry : Classroom		В	uilding	: Main		32 0 Western AVENOE, Onleage, in 00000
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #211 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,060	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,060	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	['] 12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,018	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	305	SF	7	10+ years	
_Classroo	om #212 (Store Room)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years	
_Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
	TOTAL CHINA	2110 1 1001	'	_/ \	,	o io youis	



Catego	ry : Classroom		Building : Main				
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #215 (Science Classroom)						
	Casework	2nd Floor	85	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,146	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,146	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	795	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	560	SF	7	10+ years	
	Work Sink	2nd Floor	3	EA	7	6-10 years	
Classroc	om #216 (Regular Classroom)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	918	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	315	SF	7	10+ years	
Classroo	om #217 (Computer Lab)						
	Casework	2nd Floor	96	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,075	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,075	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	990	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	305	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor		4-4-51	0.550	0.5	7	40	
	Ceiling - Lay-in	1st Floor	6,556	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	8	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	3	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	536	SF	7	10+ years	




Catego	ry : Interior		В	uilding	: Main		32 6 Western Avender, Onleage, in 60000
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	1st Floor	6,020	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	102	EA	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	56	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	15,255	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	5,920	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	100	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor	8	EA	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	6,020	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	86	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	120	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	14,720	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	20	SF	5	1-2 years	Cracked
Safety							
	Camera Viewing Station	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	17	EA	7	6-10 years	
	Security Cameras	1st Floor	48	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	Stair 1, NW	350	SF	7	10+ years	
	Floor - Tile	Stair 1, NW	410	SF	7	6-10 years	
	Handrails	Stair 1, NW	66	ĹF	7	10+ years	
	Lighting - Lay-in	Stair 1, NW	8	EA	7	6-10 years	
	Rescue Panel	Stair 1, NW	1	EA	7	10+ years	
	Stairs - Rubber	Stair 1, NW	130	LF	7	10+ years	
	Walls - Concrete Block	Stair 1, NW	840	SF	7	10+ years	
	Walls - Concrete Block	Stair 1, NW	10	SF	5	0-1 year	Cracked.
	Ceiling - Lay-in	Stair 2, NE	350	SF	7	10+ years	
	Floor - Tile	Stair 2, NE	410	SF	7	6-10 years	
	Handrails	Stair 2, NE	66	LF	7	10+ years	
	Lighting - Lay-in	Stair 2, NE	8	EA	7	6-10 years	
	Rescue Panel	Stair 2, NE	1	EA	7	10+ years	
	Stairs - Rubber	Stair 2, NE	130	LF	7	10+ years	
	Walls - Concrete Block	Stair 2, NE	850	SF	7	10+ years	
	Ceiling - Lay-in	Stair 3, SE	350	SF	7	10+ years	
	Floor - Tile	Stair 3, SE	410	SF	7	6-10 years	
	Handrails	Stair 3, SE	66	LF	7	10+ years	
	Lighting - Lay-in	Stair 3, SE	8	ĒΑ	7	6-10 years	
	Rescue Panel	Stair 3, SE	1	EA	7	10+ years	
	Stairs - Rubber	Stair 3, SE	130	LF	7	10+ years	
	Walls - Concrete Block	Stair 3, SE	850	SF	7	10+ years	
	Ceiling - Lay-in	Stair 4 SW	350	SF	7	10+ years	
	Floor - Tile	Stair 4 SW	410	SF	7	6-10 years	
						•	



Catego	ry : Interior		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Handrails	Stair 4 SW	66	LF	7	10+ years		
	Lighting - Lay-in	Stair 4 SW	8	EA	7	6-10 years		
	Rescue Panel	Stair 4 SW	1	EA	7	10+ years		
	Stairs - Rubber	Stair 4 SW	130	LF	7	10+ years		
	Walls - Concrete Block	Stair 4 SW	850	SF	7	10+ years		
Vertical	Conveyance							
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years		

Campus Name: Finkl Page : 28 of 31 Assessment Date: 04/09/2024





Category : Site **Building: Site**

atego	ry : Site	Building : Site							
	_					Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
hletic									
	Lighting	East	4	EA	6	10+ years			
	Surface - Asphalt	East	409	SF	6	6-10 years			
	,					,			
ivil/Dra	inage								
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	7	10+ years			
	Civil/ Drainage - Site Drain	Entire Site	8	EA	7	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	13	EΑ	7	10+ years			
	ŭ					,			
encing									
	Fencing - Chain Link	Entire Site	124	LF	4	1-2 years	Leaning, corroded		
	Fencing - Guard Rail	Entire Site	40	LF	5	2-5 years			
	Fencing - New Standard Ornamental	Entire Site	1,182	LF	7	10+ years			
andsca	Benches	Entire Site	28	EA	7	10+ years			
	Irrigation	Entire Site	25,991	SF	4	0-1 year	Irrigation not working per enginee		
	Landscape - Grass	Entire Site	59,927	SF	6	6-10 years	inigation not working per enginee		
	Landscape - Grass Landscape - Hardscape- Concrete	Entire Site	600	SF	5	2-5 years			
	Landscape - Hardscape- Concrete Landscape - Hardscape- Pavers	Entire Site	8,000	SF	6	6-10 years			
	Lighting - Pole Mounted	Entire Site	4	EA	7	10+ years			
	Parkway trees	Entire Site	9	EA	6	6-10 years			
	Planting Beds/ Area	Entire Site	942	SF	7	10+ years			
	Trash Receptacles	Entire Site	5	EA	6	6-10 years			
	Trasif Neceptacies	Littile Site	5	LA	O	0-10 years			
arking l									
	Concrete Curbs	Parking Lot- South	513	LF	6	10+ years			
	Interior Plantings	Parking Lot- South	408	LF	6	6-10 years			
	Lighting - Lighting	Parking Lot- South	4	EA	7	10+ years			
	Lighting - Lighting	Parking Lot- South	9	EA	6	6-10 years			
	Lighting - Pole Mounted	Parking Lot- South	9	EA	6	10+ years			
	Lighting - Pole Mounted	Parking Lot- South	20	EA	6	10+ years			
	Surface - Asphalt	Parking Lot- South	13,300	SF	6	6-10 years			
	Surface - Asphalt	Parking Lot- South	23,078	SF	4	1-2 years	Cracked, holes, uneven		
	Trash Enclosure - Chain Links	Parking Lot- South	726	SF	6	6-10 years			
	Vehicular Screening	Parking Lot- South	305	LF	6	6-10 years			
laygrou	nd								
uygiou	Equipment - Combo 3-12	East	1	EA	7	10+ years			
	Equipment - Pre K 3-5	East	1	EA	7	10+ years			
	Surface - Poured Surface	East	5,100	SF	7	10+ years			
			3,100	٥.	•	, care			

Campus Name: Finkl Page : 29 of 31 Assessment Date: 04/09/2024



Catego	ry : Site		В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	300	LF	6	6-10 years	
	Sidewalks - Internal Walks	Entire Site	1,604	LF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	950	SF	6	6-10 years	
_Signage							
0 0	Flag Pole - Flag Pole	East	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	East	1	EA	5	6-10 years	
	Monument - Building Mounted Cut Letter Sign	East	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Finkl Page: 30 of 31 Assessment Date: 04/09/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Olassi Com Cammary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	1st Floor	112	NA	852	90	9	N	Y
Computer Lab	Computer Lab	2nd Floor	217	2-25	1,075	105	12	N	Υ
Faculty Lounge	Regular Classroom	1st Floor	110	NA	852	90	9	N	N
Kindergarten	Kindergarten	1st Floor	103	NA	1,076	122	10	N	Y
Kindergarten	Kindergarten	1st Floor	105	NA	1,076	122	10	N	Υ
Kindergarten	Pre School	1st Floor	107	NA	1,076	122	10	N	Υ
Kindergarten	Regular Classroom	1st Floor	102	NA	852	90	9	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	202	2-11	918	90	9	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	209	2-14	918	90	9	N	N
Play Room	Regular Classroom	2nd Floor	205	2-18	918	90	9	N	N
Regular Classroom	Kindergarten	1st Floor	111	N/A	1,076	122	10	N	N
Regular Classroom	Regular Classroom	1st Floor	101	N/A	840	90	9	N	N
Regular Classroom	Regular Classroom	1st Floor	104	NA	852	90	9	N	Y
Regular Classroom	Regular Classroom	1st Floor	106	NA	852	90	9	N	Y
Regular Classroom	Regular Classroom	1st Floor	108	NA	852	90	9	N	Y
Regular Classroom	Regular Classroom	1st Floor	116	NA	852	90	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	2-09	918	90	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	2-07	918	90	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	2-16	918	90	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	2-05	918	90	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	2-27	918	90	9	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	2-21	1,060	90	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	2-31	918	90	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	2-33	918	90	9	N	Υ
Science Classroom	Science	2nd Floor	215	2-24	1,146	120	12	N	Υ
Store Room	Music Room	2nd Floor	201	2-42	800	135	45	N	N
Store Room	Regular Classroom	1st Floor	114	NA	852	90	9	N	N
Store Room	Regular Classroom	2nd Floor	203	2-20	918	90	9	N	Υ
Store Room	Regular Classroom	2nd Floor	212	2-29	918	90	9	N	Υ