



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1966	3	72,000
Campus Total			72,000

Category : Exterior Building : Main

				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1 - main entrance -N	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#1 - main entrance -N	3	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#1 - main entrance -N	24	LF	5	6-10 years	
	Power Door Operator and Controls	#1 - main entrance -N	2	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#1 - main entrance -N	30	LF	6	6-10 years	
	Ramps - Concrete	#1 - main entrance -N	25	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 - main entrance -N	12	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#10 - SW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 - NE	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2 - NE	10	LF	5	10+ years	
	Exterior Stairs - Stone	#2 - NE	10	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2 - NE	6	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - NW	3	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#3 - NW	30	LF	6	10+ years	
	Exterior Stairs - Stone	#3 - NW	10	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 - NW	5	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3.5 - NW	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#3.5 - NW	3	LF	6	10+ years	
	Entrance Control - Audio and Video	#4 - SW	1	EA	5	2-5 years	
	Entrance Control - Audio and Video	#4 - SW	1	EA	4	1-2 years	Cracked camera
	Exterior Doors - Exterior Steel Door	#4 - SW	2	EA	6	10+ years	
	Ramps - Concrete	#4 - SW	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 - SE	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6 - NW	1	EA	5	2-5 years	Bullet hole in door



Catego	ry : Exterior		В	uilding	: Main		W Grenshaw GTNEET, Officago, 12 00024
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Concrete	#6 - NW	15	LF	6	10+ years	
	Exterior Stairs - Stone	#6 - NW	3	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#6 - NW	12	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 - SW	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#7 - SW	8	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#7 - SW	160	LF	7	10+ years	
	Ramps - Concrete	#7 - SW	80	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#7 - SW	8	LF	7	10+ years	Repaired.
	Exterior Doors - Exterior Steel Door	#8 - SE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#8 - SE	8	LF	6	10+ years	
	Exterior Stairs - Stone	#8 - SE	4	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#8 - SE	5	LF	3	0-1 year	Missing
	Exterior Doors - Exterior Steel Door	#9 - NE	1	EA	6	6-10 years	ŭ
	Exterior Stairs - Concrete	#9 - NE	8	LF	6	10+ years	
	Exterior Stairs - Stone	#9 - NE	4	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	#9 - NE	5	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9.5 - SW	1	EA	6	6-10 years	
	Ramps - Concrete	#9.5 - SW	8	LF	6	10+ years	
	•					,	
_Foundat	ion						
	Foundation - Concrete	Entire Building	1,127	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	74,228	SF	7	10+ years	
Lighting							
igi.iii.ig	Exterior Lighting - Parapet or Roof Mounted	Entire Building	26	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	20	EA	7	10+ years	Repaired.
	5 5	J				,	•
_Roof Sys							
	Access Ladder - Metal	1 - Main Roof	3	EA	7	10+ years	
	Chimney - Brick Chimney- Stainless Steel	1 - Main Roof	44	LF	6	10+ years	
	Liner				_		
	Coping - Metal	1 - Main Roof	720	LF	7	10+ years	
	Downspouts - Interior Downspouts	1 - Main Roof	102	LF	6	6-10 years	
	Roof - Modified Bitumen	1 - Main Roof	19,271	SF	7	10+ years	New 2023.
	Roof Hatch - Metal	1 - Main Roof	3	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	1 - Main Roof	19,271	SF	7	10+ years	
	Concrete Topping	0 Low W == -f	-	Г^	7	40	
	Access Ladder - Metal	2 - Low W roof	7	EA	7	10+ years	
	Chimney - Metal Flue	2 - Low W roof	17	LF	6	6-10 years	
	Coping - Metal	2 - Low W roof	304	LF	6	6-10 years	
	Downspouts - Interior Downspouts	2 - Low W roof	26	LF	6	6-10 years	
	Roof - Modified Bitumen	2 - Low W roof	5,076	SF	7	2-5 years	
	Roof Structure - Steel / Metal Deck/	2 - Low W roof	5,076	SF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		W Grenshaw Office 1, Officago, 12 00024
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Concrete Topping		_			·	
	Access Ladder - Metal	3 - Mid W roof	1	EA	7	10+ years	
	Coping - Metal	3 - Mid W roof	135	LF	6	2-5 years	
	Downspouts - Interior Downspouts	3 - Mid W roof	23	LF	6	6-10 years	
	Roof - Modified Bitumen	3 - Mid W roof	2,133	SF	7	10+ years	New 2023.
	Roof Structure - Steel / Metal Deck/	3 - Mid W roof	2,133	SF	7	10+ years	
	Concrete Topping					•	
	Coping - Metal	4 - Elevator roof	32	LF	7	10+ years	
	Downspouts - Exterior Downspouts	4 - Elevator roof	8	LF	6	6-10 years	
	Parapet - 16" - 30" Height	4 - Elevator roof	32	LF	6	10+ years	
	Roof - Modified Bitumen	4 - Elevator roof	61	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	4 - Elevator roof	61	SF	7	10+ years	
	Concrete Topping					•	
	Access Ladder - Metal	5 - Low E roof	1	EA	7	10+ years	
	Coping - Metal	5 - Low E roof	271	LF	6	6-10 years	
	Downspouts - Interior Downspouts	5 - Low E roof	46	LF	6	6-10 years	
	Roof - Modified Bitumen	5 - Low E roof	5,791	SF	7	10+ years	New 2023.
	Roof Structure - Steel / Metal Deck/	5 - Low E roof	5,791	SF	7	10+ years	
	Concrete Topping					•	
<u>Walls</u>							
	Canopy - Metal	Entire Building	150	SF	7	10+ years	Replaced
	Canopy - Metal	Entire Building	115	SF	7	10+ years	
	Canopy - Metal	Entire Building	115	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,010	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	15,238	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	50	SF	6	10+ years	Repairs
	Exterior Walls - Concrete Block	Entire Building	150	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	504	SF	6	6-10 years	
	Wall				_		
	Exterior Walls - Stone-Cast	Entire Building	1,102	SF	5	10+ years	
Windows	3						
	Curtain wall - Louver	Entire Building	234	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	2,772	SF	6	6-10 years	
	Lintels - Steel	Entire Building	732	LF	6	10+ years	
	Lintels - Stone	Entire Building	14	LF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	8,338	SF	6	6-10 years	
	pane	- · · · · · · · · · · · · · · · · · · ·	2,230		-	,	
	Windows - Decorative	Entire Building	238	SF	6	6-10 years	
		Č				•	



Catego	ry : Electrical		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Automatic Transfer Switch	Boiler Room	2	EA	6	6-10 years	Associated with the emergency generator system.
	Automatic Transfer Switch	Boiler Room	2	EA	2	0-1 year	Quantity changed as total has been divided/aggregated. Associated with the abandoned UPS system. Rank adjusted to reflect that the units have been disconnected and removed from service; they have been deemed obsolete and have been abandoned in place.
	UPS - Greater than 60	Boiler Room	1	EA	2	0-1 year	Obsolete system with batteries removed; abandoned in place.
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	10+ years	Location changed for clarification. Emergency battery packs are located only in the 1st floor student restrooms.
	Security System - CCTV	Entire Building	72,000	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	72,000	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,547	SF	6	10+ years	Location changed for clarification.
	Emergency A/C Power - Gym	Entire Building	5,149	SF	6	10+ years	Location changed for clarification.
	Emergency A/C Power - Lunchrooms	Entire Building	3,035	SF	6	10+ years	Location changed for clarification.
	Emergency A/C Power - Students Toilets	Entire Building	1,740	SF	6	10+ years	Location changed for clarification.
	Exit Signs - Corridors and Stairs	Entire Building	¹ 15	ĒA	6	6-10 years	Location changed for clarification. Rank, Reason and Priority Rep changed as exit signs throughout the building have been upgraded since previous assessment and are intact with full legibility as intended in service.
	Exit Signs - Gym	Entire Building	5	EA	6	6-10 years	Location changed for clarification. Rank, Reason and Priority Rep changed as exit signs throughout the building have been upgraded since previous assessment and are intact with full legibility as intended in service.
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	Location changed for clarification. Rank, Reason and Priority Rep changed as exit signs throughout the building have been upgraded since previous assessment and are intact with full legibility as intended in



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Generator- Outdoor- Natural Gas - 60 - 100 KW	Site West	1	EA	6	6-10 years	service. No CPS Asset Tag present on exterior of unit. No keys to open the side panels were available at the time of assessment. Condition verified by Building Engineer. Priority Rep adjusted based on current observations and on the age of the equipment.
Main Se	rvice						
	PA System Main Electrical Service - 2000 A 120/208/3PH	Entire Building Switchgear Room	72,000 1	SF EA	6 6	6-10 years 6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	6	EA	7	10+ years	Quantity changed as total has been divided/aggregated. Location changed for clarification.
	Lighting and Power Panels - Above 100 A	Entire Building	17	EA	7	10+ years	Quantity established as total has been divided/aggregated. Many panels are screwed closed for safety purposes.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Location changed for clarification. Quantity changed as total has been divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Located in MDF Room.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep established as the panel is missing interior cover plates exposing live conductors and presenting a live front condition.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years	Location changed for clarification.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	Quantity changed to match current observations. One each located in the gym basement mechanical room and in the boiler room. Rank, Reason and Priority Rep adjusted based on current observations. Panel is intact and fully operational as intended despite signs of surface oxidation.
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	Location changed for clarification.



Category : Electrical				uilding			
						Recommend	
Group 1	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Dataplate was not directly accessible in a safe manner at the time of assessment due to the lack of appropriate and necessary climbing means.

Category: Fire Protection Building: Main

Group Fire Alar	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Tile Alai	Fire ALarm Anunciator Fire Alarm Panel	Entire Building Entire Building	1	EA EA	6 6	6-10 years 6-10 years	No CPS Asset Tag present.
	Fire Alarm Strobe Lights	Entire Building	72,000	SF	4	2-5 years	Rank, Reason and Priority Rep changed as the system is functional and passes inspection, however it is 25-plus years old and has exceeded its anticipated service life.
	Fire Alarm_System	Entire Building	72,000	SF	4	2-5 years	Rank, Reason and Priority Rep changed as the system is functional and passes inspection, however it is 25-plus years old and has exceeded its anticipated service life.

Category : Mechanical **Building: Main**

0	Mann Trima	Lagation	Oa	HOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	Iling Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	Basement	1	EA	5	6-10 years	Located in the gym basement mechanical room. Serves gym.
	Air Intake	Basement	1	EA	5	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	100	LF	6	10+ years	
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Basement	1	EA	5	6-10 years	Located in the gym basement mechanical room.
Boiler Sy	ystems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	1	EA	5	6-10 years	Actuators and dampers not directly accessible in a safe manner at the time of assessment due to a lack of



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							reliable climbing means. Located in a crawl space inside the Boiler Room. Condition verified by Building Engineer.
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Located in the gym basement mechanical room.
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	6	6-10 years	B-1
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	6	6-10 years	B-2
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Steam Traps	Boiler Room	65	EA	6	6-10 years	
Heating							
	PTAC - Electric Heating and Self Contained Cooling	1st Floor	1	EA	6	6-10 years	Located in the counseling office.
	Wall Heater - Electric	1st Floor	2	EA	6	6-10 years	Located in the main office restroom and in the kitchen manager office.
	Radiators - Steam	Basement	3	EA	6	6-10 years	Quantity changed to match current observations.
	Radiators - Steam	Basement	1	EA	6	6-10 years	
	Fin Tube - Steam	Entire Building	24	LF	5	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	21	EA	5	6-10 years	Quantity changed as total has been divided/aggregated. Since previous assessment, all units in the school are fully operational; many have exterior front covers with scratched/peeling paint.
Tempera	ture Control						
•	DDC System	Entire Building	72,000	SF	2	0-1 year	Rank, Reason and Priority Rep changed based on current observations and per detailed review with Building Engineer that the system is 25-plus years old and nonfunctional; all spaces in the building are subject to manual temperature control of the equipment.
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations and per review with Building Engineer.



Catego	ry : Mechanical		В	uilding	: Main		
C	Have Time	Lagation	O	шом	Donk	Recommend	Community
Group	Item - Type Thermostats - DDC	Location Entire Building	Quantity 57	EA	Rank 4	0-1 year	Rank, Reason and Priority Rep changed based on current observations and per detailed review with Building Engineer that the system is 25-plus years old and nonfunctional; there is no communication between the thermostats and the equipment such that all spaces in the building are subject to manually-adjusted temperature control.
Unit Ven							
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	55	EA	5	6-10 years	Well-maintained vintage units subject to frequent repairs.
Ventilation							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EΑ	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	5	EA	7	10+ years	Quantity, Rank and Priority Rep changed as units have been replaced since previous assessment. Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	6	EA	7	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	Rank, Reason and Priority Rep established as the unit is not equipped with a fire suppression system.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	dyddoni.
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat							
	Gas Heater - 150000 - 300000 BTU/HR	Entire Building	2	EA	7	10+ years	Item Type, Rank, Reason and Priority Rep changed as the water heaters have been replaced since previous assessment.



Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	72,000	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	72,000	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	72,000	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	72,000	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	72,000	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	72,000	SF	6	6-10 years	
	Sanitary Piping	Entire Building	72,000	SF	6	6-10 years	
	Storm Piping	Entire Building	72,000	SF	6	6-10 years	
	Vent Piping	Entire Building	72,000	SF	6	6-10 years	
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present.
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Elevator pit sump pump. Not directly accessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer.
	Pumps - Sump-Simplex	Entire Building	1	EA	5	6-10 years	Located in the gym basement mechanical room.

Building: Main Category: Room

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	1st- Counselor office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st- Counselor office	148	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Counselor office	1	EA	7	10+ years	
	Floor - Tile	1st- Counselor office	148	SF	7	10+ years	
	Lighting - Lay-in	1st- Counselor office	3	EA	7	10+ years	
	Power Distribution	1st- Counselor office	4	EA	7	10+ years	
	Walls - Concrete Block	1st- Counselor office	216	SF	7	10+ years	
	Walls - Plaster/Drywall	1st- Counselor office	217	SF	7	10+ years	
	Ceiling - Lay-in	1st- Library Reference Office	91	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Library Reference Office	1	EA	7	10+ years	
	Floor - Tile	1st- Library Reference Office	91	SF	7	10+ years	
	Lighting - Lay-in	1st- Library Reference Office	2	EA	6	6-10 years	
	Power Distribution	1st- Library Reference Office	6	EA	7	10+ years	







Building: Main Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments 1st- Library Reference Office Walls - Concrete Block 96 SF 10+ vears 7 Walls - Plaster/Drvwall 1st-Library Reference Office 96 SF 7 10+ years Work SInk 1st-Library Reference Office 1 FΑ 7 10+ years 1st- Main Office 7 AC Unit EΑ 6-10 years SF Ceiling - Lay-in 1st- Main Office 350 7 10+ years Doors - Wood Doors inclu hw 7 1st- Main Office EΑ 10+ years 1 Floor - Tile 1st- Main Office 350 SF 7 10+ years Lighting - Lay-in 1st- Main Office 8 EΑ 7 10+ years Power Distribution 1st- Main Office 4 EΑ 7 10+ years SF Storage/ Closet 1st- Main Office 106 7 10+ years SF Storage/ Closet 1st- Main Office 59 7 10+ years Walls - Concrete Block 1st- Main Office 339 SF 7 10+ years Walls - Plaster/Drywall 332 SF 7 1st- Main Office 10+ years SF 7 Ceiling - Lay-in 3rd-Teacher's Lounge 278 10+ years Doors - Wood Doors inclu hw EΑ 3rd- Teacher's Lounge 1 6 10+ years Floor - Tile 278 SF 7 3rd- Teacher's Lounge 10+ years EΑ 7 Lighting - Lay-in 3rd- Teacher's Lounge 5 6-10 years Power Distribution 3rd-Teacher's Lounge 6 EΑ 7 10+ years SF Walls - Concrete Block 3rd- Teacher's Lounge 506 7 10+ vears SF Walls - Plaster/Drywall 3rd- Teacher's Lounge 90 7 10+ years AC Unit Assistant Principal's Office 1 EΑ 7 6-10 years Assistant Principal's Office SF 7 Ceiling - Lay-in 222 10+ years Doors - Wood Doors inclu hw 7 Assistant Principal's Office 1 EΑ 10+ years 222 SF Floor - Tile Assistant Principal's Office 7 10+ years Lighting - Lay-in EΑ 7 Assistant Principal's Office 2 6-10 years Power Distribution Assistant Principal's Office 10 EΑ 7 10+ years SF Walls - Concrete Block Assistant Principal's Office 526 7 10+ years Conference room in principal office SF 7 Ceiling - Lay-in 136 10+ years Doors - Wood Doors inclu hw EΑ Conference room in principal office 1 7 10+ years Floor - Tile Conference room in principal office 136 SF 7 10+ years Lighting - Lay-in Conference room in principal office 2 EΑ 7 6-10 years Power Distribution Conference room in principal office 2 EΑ 7 10+ vears 20 SF 7 10+ years Storage/ Closet Conference room in principal office Walls - Concrete Block Conference room in principal office 300 SF 7 10+ vears 7 AC Unit Engineer's Office 1 EΑ 6-10 years SF 7 Ceiling - Lay-in Engineer's Office 86 10+ years Doors - Wood Doors inclu hw Engineer's Office 1 EΑ 7 10+ years Floor - Tile SF Engineer's Office 86 7 10+ years Lighting - Lay-in Engineer's Office 1 EΑ 7 6-10 years Power Distribution Engineer's Office 4 EΑ 7 10+ vears Storage/ Closet SF Engineer's Office 14 7 10+ years Engineer's Office SF 7 Walls - Concrete Block 208 10+ years Ceiling - Lay-in Gym office 160 SF 7 10+ years Doors - Wood Doors inclu hw Gym office 2 EΑ 7 10+ years



Category : Room			В	uilding	: Main		W Grenshaw GTREET, Officago, in 00024
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Gym office	160	SF	7	10+ years	
	Lighting - Lay-in	Gym office	2	EA	7	6-10 years	
	Power Distribution	Gym office	2	EA	7	10+ years	
	Walls - Concrete Block	Gym office	240	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen office	54	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen office	20	SF	4	1-2 years	Minor damage
	Doors - Wood Doors inclu hw	Kitchen office	1	EΑ	7	10+ years	
	Floor - Tile Quarry	Kitchen office	74	SF	7	10+ years	
	Lighting - Lay-in	Kitchen office	1	EΑ	6	6-10 years	
	Power Distribution	Kitchen office	4	EA	7	10+ years	
	Walls - Concrete Block	Kitchen office	202	SF	7	10+ years	
	AC Unit	Office - New Principal	1	EA	7	6-10 years	
	Ceiling - Lay-in	Office - New Principal	177	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office - New Principal	1	EA	7	10+ years	
	Floor - Tile	Office - New Principal	177	SF	7	10+ years	
	Lighting - Lay-in	Office - New Principal	4	EA	7	6-10 years	
	Power Distribution	Office - New Principal	4	EA	7	10+ years	
	Walls - Concrete Block	Office - New Principal	280	SF	7	10+ years	
	Walls - Concrete Block	Office - New Principal	2	SF	7	10+ years	
	AC Unit	Old main office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Old main office	410	SF	7	10+ years	
	Doors - Steel Doors incl hw	Old main office	1	EA	7	10+ years	
	Doors - Transom Window	Old main office	15	SF	7	10+ years	
	Floor - Tile	Old main office	410	SF	7	10+ years	
	Lighting - Lay-in	Old main office	9	EA	7	6-10 years	
	Power Distribution	Old main office	10	EA	7	10+ years	
	Walls - Concrete Block	Old main office	730	SF	7	10+ years	
	AC Unit	Teachers lounge 106	1	EA	7	6-10 years	
	Ceiling - Lay-in	Teachers lounge 106	366	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Teachers lounge 106	1	EA	7	10+ years	
	Floor - Tile	Teachers lounge 106	366	SF	7	10+ years	
	Lighting - Lay-in	Teachers lounge 106	8	EΑ	7	6-10 years	
	Power Distribution	Teachers lounge 106	8	EΑ	6	10+ years	
	Walls - Concrete Block	Teachers lounge 106	520	SF	7	10+ years	
Clinic							
	AC Unit	2nd- 203 Nurse	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd- 203 Nurse	272	SF	7	10+ years	
	Ceiling - Lay-in	2nd- 203 Nurse	6	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd- 203 Nurse	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd- 203 Nurse	278	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	2nd- 203 Nurse	5	EA	7	6-10 years	
	Walls - Concrete Block	2nd- 203 Nurse	506	SF	7	10+ years	





Catego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd- 203 Nurse	90	SF	7	10+ years	
ymnas							
	Ceiling - Plaster/Drywall	1st Floor	5,149	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	5,149	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Not working
	Stage	1st Floor	849	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	16	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	4,366	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,972	SF	7	10+ years	
itchen							
	Ceiling - Plaster/Drywall	1st Floor	820	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	820	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Serving Line	1st Floor	16	LF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,597	SF	7	10+ years	
ibrary							
	AC Unit	1st Floor	2	EΑ	7	6-10 years	
	Casework	1st Floor	98	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,397	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Carpet	1st Floor	1,397	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	34	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,320	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	254	SF	7	10+ years	
0 0 (0 m/C	Shower Room						
ocker/S	Accessories	Kitchen	49	SF	7	6-10 years	
	Ceiling - Lay-in	Kitchen	33	SF SF	7	10+ years	
	Ceiling - Lay-in Ceiling - Lay-in	Kitchen	16	SF SF		1-2 years	Minor danago
	Doors - Wood Doors inclu hw		16		4		Minor danage
		Kitchen		EA	7	10+ years	
	Floor - Tile/Sheet	Kitchen	49	SF	7	10+ years	
	Lighting - Lay-in	Kitchen	1	EA	7	6-10 years	





Catego	ory : Room		В	uilding	· Main		W Grenshaw STREET, Chicago, IL 60624
Outogo	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	Kitchen	7	EA	7	10+ years	
	Walls - Concrete Block	Kitchen	148	SF	7	10+ years	
					-	, , , , , , , , , , , , , , , , , , , ,	
Lunch &	Multipurpose Room						
	AC Unit	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	3,035	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	3,025	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Cracked tile
	Lighting - Lay-in	1st Floor	56	EA	7	6-10 years	
	Storage/ Closet	1st Floor	300	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	950	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	324	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,274	SF	7	10+ years	
						Ţ	
_MDF_ID							
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	234	SF	5	10+ years	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	
Mechan	ical/ Service Rooms						
IVIOOHUH	Janitor's Closet	1st Floor	29	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	91	SF	7	10+ years	
	Storage Room	1st Floor	86	SF	7	10+ years	
	Storage Room	1st Floor	596	SF	7	10+ years	
	Vaults	1st Floor	62	SF	7	10+ years	
	Janitor's Closet	2nd Floor	29	SF	5	10+ years	
	Janitor's Closet	3rd Floor	29	SF	5	10+ years	
	Vaults	3rd Floor	234	SF	7	10+ years	
	Boiler Room	Basement	1,446	SF	5	10+ years	
	Crawl Space - Unfinished	Basement	20,650	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	820	SF	5	10+ years	
	Storage Room	Basement	250	SF	7	10+ years	
	Vaults	Basement	202	SF	7	10+ years	
_						Ť	
_Restroo		407	0.4		7	0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Accessories	107	24	SF SF	7	6-10 years	
	Ceiling - Lay-in	107	24		7	10+ years	
	Doors - Wood Doors inclu hw	107	1	EA	7	10+ years	
	Floor - Tile	107	24	SF	7	10+ years	
	Lavatory	107	1	EΑ	7	10+ years	
	Lighting - Lay-in	107	1	EA	7	6-10 years	
	Walls - Concrete Block	107	67	SF	7	10+ years	







Building: Main Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Water Closet 107 EΑ 10+ vears 7 109 24 SF 7 6-10 years Accessories Ceiling - Plaster/Drywall 109 24 SF 7 10+ years Doors - Wood Doors inclu hw EΑ 7 109 1 10+ years 6 SF 7 Floor - Tile 109 6-10 years SF Floor - Tile 7 109 18 10+ years 109 EΑ 7 Lavatory 1 10+ years Lighting - Pendent/Surface 109 1 EΑ 7 10+ years Walls - Concrete Block 109 67 SF 7 10+ years Water Closet 109 1 EΑ 7 10+ years Accessories 111 23 SF 7 6-10 years Ceiling - Plaster/Drywall 111 23 SF 7 10+ years Doors - Wood Doors inclu hw 1 EΑ 7 111 10+ years SF 7 Floor - Tile 111 23 10+ years EΑ 7 Lavatory 111 1 10+ years Lighting - Pendent/Surface 7 111 1 FΑ 6-10 years Walls - Vinyl Coated Gypsum Panel SF 111 67 7 10+ years Water Closet 111 1 EΑ 7 10+ years SF Accessories 1st Floor 280 7 6-10 years Ceiling - Plaster/Drywall SF 1st Floor 280 7 10+ years Doors - Side-lite 1st Floor 14 SF 7 10+ years Doors - Wood Doors inclu hw 7 10+ years 1st Floor 1 EΑ SF 7 Floor - Tile Ceramic/ Porcelain 1st Floor 280 10+ years 7 Floor Drain 1st Floor FΑ 10+ years 1 Hand Dryer EΑ 5 1-2 years 1st Floor 1 Not working Lavatory 1st Floor 3 FΑ 7 10+ vears Lighting - Lay-in 1st Floor 1 EΑ 7 6-10 years Lighting - Pendent/Surface 3 EΑ 7 6-10 years 1st Floor 1 Lighting - Wall Mounted 1st Floor EΑ 7 6-10 years **Partitions** 1st Floor 2 EΑ 7 10+ years Urinals 1st Floor 5 EΑ 7 10+ years Walls - Plaster/Drywall 1st Floor 50 SF 7 10+ years Walls - Structural Glazed Tile SF 7 1st Floor 496 10+ years Walls - Tile Ceramic/ Porcelain 150 SF 7 10+ years 1st Floor Water Closet 2 7 1st Floor EΑ 10+ years SF 7 Accessories 1st Floor 300 6-10 years SF Ceiling - Plaster/Drywall 1st Floor 300 7 10+ years Doors - Side-lite SF 7 1st Floor 14 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 7 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor 300 7 10+ years Floor Drain 1st Floor EΑ 7 10+ years 1 Hand Drver FΑ 1st Floor 1 4 1-2 years Not working Lavatory 1st Floor 3 EΑ 7 10+ years Lighting - Lay-in 1st Floor 1 EΑ 7 6-10 years





Catego	Category : Room		В	uilding	: Main		. 5 :
_				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	3	EΑ	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	1	EA	7	6-10 years	
	Partitions	1st Floor	5	EA	7	10+ years	
	Partitions	1st Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	696	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	150	SF	7	10+ years	
	Water Closet	1st Floor	6	ĒΑ	7	10+ years	
	Accessories	2nd Floor	280	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	280	SF	5	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	Trator damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	280	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	-	
			· · · · · · · · · · · · · · · · · · ·	EA		6-10 years	
	Lighting - Pendent/Surface	2nd Floor	3		7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	-	EΑ	7	6-10 years	
	Partitions	2nd Floor	2	EΑ	7	10+ years	
	Urinals	2nd Floor	4	EΑ	7	10+ years	0.4.6.1
	Urinals	2nd Floor	1	EA	6	1-2 years	Out of order
	Walls - Structural Glazed Tile	2nd Floor	696	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	43	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	43	SF	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	87	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	5	SF	6	6-10 years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	300	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	300	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	300	SF	7	10+ years	
	Floor Drain	2nd Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	6	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EΑ	7	10+ years	
	Lighting - Wall Mounted	2nd Floor	1	EΑ	7	10+ years	
		2.10 1 1001	•		•	10. 300.0	





Catego	Category : Room		В	uilding	: Main			
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Partitions	2nd Floor	5	EA	7	10+ years		
	Partitions	2nd Floor	1	EA	5	0-1 year	Does not lock.	
	Walls - Structural Glazed Tile	2nd Floor	692	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	4	SF	5	0-1 year	Missing	
	Water Closet	2nd Floor	6	EA	6	6-10 years	-	
	Accessories	3rd Floor	280	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	280	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	280	SF	7	10+ years		
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Hand Dryer	3rd Floor	1	EΑ	7	6-10 years		
	Lavatory	3rd Floor	3	EA	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years		
	Lighting - Wall Mounted	3rd Floor	1	EA	7	6-10 years		
	Partitions	3rd Floor	2	EΑ	7	10+ years		
	Urinals	3rd Floor	5	EΑ	7	10+ years		
	Walls - Structural Glazed Tile	3rd Floor	696	SF	7	10+ years		
	Water Closet	3rd Floor	2	EA	7	10+ years		
	Accessories	3rd Floor	43	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	43	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	43	SF	7	10+ years		
	Lavatory	3rd Floor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	1	EA	7	6-10 years		
	Walls - Concrete Block	3rd Floor	82	SF	7	10+ years		
	Water Closet	3rd Floor	1	EA	7	10+ years		
	Accessories	3rd Floor	300	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	300	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	14	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	300	SF	7	10+ years		
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Hand Dryer	3rd Floor	1	EA	7			
		3rd Floor		EA		6-10 years		
	Lavatory		3		7	10+ years		
	Lighting - Lay-in	3rd Floor	1	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	3	EΑ	7	6-10 years		
	Lighting - Wall Mounted	3rd Floor	1	EΑ	7	6-10 years		
	Partitions	3rd Floor	6	EA	7	10+ years		
	Walls - Structural Glazed Tile	3rd Floor	693	SF	7	10+ years	0 1 1	
	Walls - Structural Glazed Tile	3rd Floor	3	SF	5	0-1 year	Cracked	
	Water Closet	3rd Floor	6	EA	7	10+ years		
	Accessories	Boiler Room	131	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Boiler Room	131	SF	7	10+ years		





Catego	ategory : Room		В	uilding	: Main				
3						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	Boiler Room	2	EA	7	10+ years			
	Floor - Tile	Boiler Room	116	SF	6	10+ years			
	Floor - Tile	Boiler Room	15	SF	4	1-2 years	Broken missing tile		
	Lavatory	Boiler Room	1	EA	4	1-2 years	No lavatory		
	Lighting - Pendent/Surface	Boiler Room	2	EA	7	10+ years	·		
	Partitions	Boiler Room	1	EA	7	10+ years			
	Student Lockers - One Tier	Boiler Room	1	EA	7	10+ years			
	Walls - Concrete Block	Boiler Room	260	SF	7	10+ years			
	Water Closet	Boiler Room	1	EA	3	1-2 years	Not in service		
	Accessories	Conference room in principal office	45	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Conference room in principal office	45	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Conference room in principal office	1	ĒΑ	7	10+ years			
	Floor - Tile/Sheet	Conference room in principal office	45	SF	7	10+ years			
	Lavatory	Conference room in principal office	1	EA	7	10+ years			
	Lighting - Lay-in	Conference room in principal office	1	EΑ	7	6-10 years			
	Walls - Concrete Block	Conference room in principal office	93	SF	7	10+ years			
	Water Closet	Conference room in principal office	1	EA	7	10+ years			
	Accessories	Engineer's office	25	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Engineer's office	25	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Engineer's office	1	EA	7	10+ years			
	Floor - Tile	Engineer's office	25	SF	7	10+ years			
	Lavatory	Engineer's office	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Engineer's office	1	EA	7	6-10 years			
	Walls - Concrete Block	Engineer's office	70	SF	7	10+ years			
	Water Closet	Engineer's office	1	EA	7	10+ years			
	Accessories	In old main office	43	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	In old main office	43	SF	7	10+ years			
	Doors - Wood Doors inclu hw	In old main office	1	EA	7	10+ years			
	Floor - Tile	In old main office	43	SF	7	10+ years			
	Hand Dryer	In old main office	43	EA	7	10+ years			
	Lavatory	In old main office	1	EA	7	10+ years			
	Lighting - Pendent/Surface	In old main office	1	EA	7	6-10 years			
	Walls - Concrete Block	In old main office	92	SF	7	10+ years			
	Water Closet	In old main office	1	EA	7	10+ years			
	Accessories	Kitchen	30	SF	7	6-10 years			
			30	SF		•			
	Ceiling - Plaster/Drywall	Kitchen	30 1	SF SF	7	10+ years			
	Doors - Transom Window	Kitchen	30	SF	7 7	10+ years			
	Floor - Tile	Kitchen	30 1	SF EA	7 7	10+ years			
	Lavatory	Kitchen	•			10+ years	Not working		
	Lighting - Lay-in	Kitchen	1	EΑ	5	1-2 years	Not working		
	Partitions	Kitchen	1	EA	7	10+ years			
	Walls - Concrete Block	Kitchen	96	SF	7	10+ years			
	Water Closet	Kitchen	1	EA	7	10+ years			
	Accessories	Men's restroom 1st floor	83	SF	7	6-10 years			





Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	Men's restroom 1st floor	83	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Men's restroom 1st floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Men's restroom 1st floor	83	SF	7	10+ years			
	Lavatory	Men's restroom 1st floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Men's restroom 1st floor	1	EA	7	6-10 years			
	Partitions	Men's restroom 1st floor	1	EA	7	10+ years			
	Urinals	Men's restroom 1st floor	2	EA	7	10+ years			
	Walls - Concrete Block	Men's restroom 1st floor	224	SF	7	10+ years			
	Water Closet	Men's restroom 1st floor	1	EA	7	10+ years			
	Accessories	Opposite main office	40	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Opposite main office	40	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Opposite main office	1	EA	7	10+ years			
	Floor - Tile	Opposite main office	40	SF	7	10+ years			
	Lavatory	Opposite main office	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Opposite main office	1	EA	7	6-10 years			
	Walls - Concrete Block	Opposite main office	80	SF	7	10+ years			
	Water Closet	Opposite main office	1	EA	7	10+ years			
	Accessories	Women's restroom 1st floor	82	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Women's restroom 1st floor	82	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Women's restroom 1st floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Women's restroom 1st floor	82	SF	7	10+ years			
	Lavatory	Women's restroom 1st floor	2	EA	7	10+ years			
	Lighting - Pendent/Surface	Women's restroom 1st floor	1	EA	7	6-10 years			
	Partitions	Women's restroom 1st floor	2	EA	7	10+ years			
	Walls - Concrete Block	Women's restroom 1st floor	224	SF	7	10+ years			
	Water Closet	Women's restroom 1st floor	2	EΑ	7	10+ years			

Building: Main Category: Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #102 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	732	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	727	SF	6	10+ years	
	Floor - Tile	1st Floor	5	SF	4	1-2 years	Dented tile
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	958	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
	Work Sink	1st Floor	1	EA	7	10+ years	





Catego	ry : Classroom		В	uilding	: Main		W Grensnaw STREET, Chicago, iL 60024
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	716	SF	7	10+ years	
	Floor - Tile	1st Floor	4	SF	6	2-5 years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	948	SF	7	10+ years	
Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	720	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	5	1-2 years	Missing doors
	Student Lockers - One Tier	1st Floor	2	EA	6	10+ years	•
	Walls - Concrete Block	1st Floor	958	SF	7	10+ years	
Classroo	om #107 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,017	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	. 8	SF	4	1-2 years	Damaged tile
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	3
	Floor - Tile	1st Floor	1,025	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	22	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	72	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,019	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroc	m #108 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	750	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	5	10+ years	
	-					-	





Catego	Category : Classroom		В	uilding	: Main		VV Ciciisiaw CTREET, Chicago, ie 00024
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Walls - Concrete Block	1st Floor	909	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	54	SF	7	10+ years	
Classro	om #109 (Office)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,025	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	865	SF	7	10+ years	
	Floor - Tile	1st Floor	160	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	22	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	72	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,018	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #110 (Office)						
Classion	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	740	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	740	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	24	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	952	SF	7	•	
	Walls - Concrete Block Walls - Plaster/Drywall	1st Floor	112	SF SF	7	10+ years	
	Walls - Plaster/Drywall Work Sink		112		4	10+ years	No found
	WORK SILIK	1st Floor	ı	EA	4	1-2 years	No faucet
_Classroo	om #111 (Fitness Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	38	LF	7	2-5 years	
	Ceiling - Lay-in	1st Floor	1,025	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,025	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	72	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,018	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classro	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
						-	





Catego	ry : Classroom		В	uilding	: Main		
_	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	948	SF	7	10+ years	
Classro	om #201 (Regular Classroom)						
Ciassio	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	661	SF	7	10+ years	
	Doors - Wood Doors inclu hw		1		7	•	
		2nd Floor		EA SF		10+ years	
	Floor - Tile	2nd Floor	661		7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	901	SF	7	10+ years	
Classro	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	948	SF	7	10+ years	
Classro	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	948	SF	7	10+ years	
Classro	om #205 (Science Lab Level 1)						
<u> </u>	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Centry - Lay-III	2110 1 1001	720	SI	,	10+ years	





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	948	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroc	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	7	10+ years	
				SF	7	,	
	Walls - Concrete Block	2nd Floor	948	SF	/	10+ years	
Classroc	m #207 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	728	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	948	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroc	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	746	SF	7	10+ years	
	Floor - Tile	2nd Floor	4	SF	4	0-1 year	Chipped
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Спірроц
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	5		
	Walls - Concrete Block			SF SF		10+ years	
		2nd Floor	733	SF SF	7 7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	74	5F	,	10+ years	
Classroo	om #209 (Regular Classroom)						





Catego	ry : Classroom		R	uilding	: Main	4021	W Grenshaw STREET, Chicago, IL 60624
Catego	y . Olassi oom			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. о а.р	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	733	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	74	SF	7	10+ years	
Classroo	m #210 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	747	SF	7	10+ years	
	Floor - Tile	2nd Floor	3	SF	4	0-1 year	Cracked
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	0.00.00
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	733	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	74	SF	7	10+ years	
Classroo	m #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	747	SF	7	10+ years	
	Floor - Tile	2nd Floor	3	SF	4	0-1 year	Cracked
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Ordoned
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	733	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	74	SF	7	10+ years	
Classroo	m #212 (Music Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor 2nd Floor	733	SF	5 7	10+ years	
	Walls - Colloiete Diock	2110 1 1001	733	Oi.	,	10+ years	





Assessment Date: 03/07/2024

Catago	Classes and		В	: a :	. Main		
Catego	ry : Classroom		В	uilding	: wain		
C=====	Itama Tura	Lagation	O antitu	LIOM	Donle	Recommend	Comments
Group	Item - Type Walls - Plaster/Drywall	Location 2nd Floor	Quantity 74	UOM SF	Rank	Replacement 10+ years	Comments
	walls - Plaster/Drywall	2110 F1001	74	SF	7	10+ years	
01	(1040 (O) D						
Classroo	m #213 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	733	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	74	SF	7	10+ years	
Classroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	728	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EΑ	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	725	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	74	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
						, , , , ,	
Classroo	m #215 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	554	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	554	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	637	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	74	SF	7	10+ years	
Classroo	m #216 (Other Instructional Use)						
<i>J</i> 1833100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor 2nd Floor	554	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA	7	•	
	Floor - Tile	2nd Floor 2nd Floor	546	SF	7	10+ years 10+ years	
				SF SF			
	Floor - Tile	2nd Floor	8	C.L	4	0-1 year	Chipped





Catego	ry : Classroom		В	uilding	: Main	-	W Grensnaw STREET, Chicago, IL 60024
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	637	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	74	SF	7	10+ years	
Classroo	om #217 (Science)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	890	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	45	SF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	776	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	306	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
						, , , , , , , , , , , , , , , , , , , ,	
_Classroo	om #218 (Art Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	890	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EΑ	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	776	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	306	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
_Classroo	om #300 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Carpet	3rd Floor	720	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	948	SF	7	10+ years	
	Traile Solidiolo Blook	014 1 1001	040	0.	•	101 yours	





Catego	ry : Classroom		В	uilding	: Main	-	W Olchshaw Office 1, Officago, ie 00024
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	660	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	658	SF	7	10+ years	
	Floor - Tile	3rd Floor	2	SF	4	0-1 year	Chipped
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	901	SF	7	10+ years	
_Classroo	om #302 (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	945	SF	7	10+ years	
Classroo	om #304 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	. 4	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Floor - Tile	3rd Floor	718	SF	7	10+ years	
	Floor - Tile	3rd Floor	2	SF	4	0-1 year	Damaged.
	Lighting - Lay-in	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	945	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
_Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	728	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	35	SF	7	10+ years	
	· ·					,	





Catego	ry : Classroom		В	uilding	: Main	-	VV Stellshaw OTNEET, Officago, ie 00024
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor	958	SF	7	10+ years	
Classia	and #200 (Demiller Classes and						
Classroo	om #306 (Regular Classroom)	_ .					
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	715	SF	7	10+ years	
	Floor - Tile	3rd Floor	5	SF	4	0-1 year	Chipped
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	945	SF	7	10+ years	
Classro	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	720	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	945	SF	7	10+ years	
	Walls Controle Block	3/4 / 100/	040	O.	•	101 years	
Classroo	om #308 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	750	SF	6	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	730	SF	7	10+ years	
	Floor - Tile	3rd Floor	20	SF	4	0-1 year	Chipped
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	634	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	3	SF	5	0-1 year	Cracked
	Walls - Plaster/Drywall	3rd Floor	74	SF	7	10+ years	
_Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	6	6-10 years	
	Casework Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	20010 WOOD DOOR HOLD TW	014 1 1001	·	L/ \	,	ioi youis	





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	3rd Floor	748	SF	7	10+ years	
	Floor - Tile	3rd Floor	2	SF	4	0-1 year	Chipped
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	673	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	74	SF	7	10+ years	
	Wallo T lastel/BTyWall	01011001	, ,	0.	•	To Fyddio	
Classroc	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	742	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	12	LF	4	2-5 years	Trator damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	749	SF	7	10+ years	
	Floor - Tile	3rd Floor	1	SF	4	0-1 year	Chipped
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	Опіррец
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	673	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	74	SF	7	10+ years	
	Walls Tlastel/DryWall	314 1 1001	7-4	O.	,	TOT years	
Classroc	om #311 (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	673	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	74	SF	7	•	
	Walls - Flastel/Drywall	314 F1001	74	SF	,	10+ years	
Classroc	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	_ <u></u> 1	EA	7	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	10+ years	





Catogo	ry : Classroom		P	uilding	· Main	.02.	W Grenshaw STREET, Chicago, IL 606
Calego	Ty . Classicolli		В	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Walls - Concrete Block	3rd Floor	725	SF	7	10+ years	Comments
	Walls - Plaster/Drywall	3rd Floor	74	SF	7	10+ years	
	vvalis - i lastei/Drywali	314 1 1001	74	01	,	10+ years	
Classroc	om #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	715	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	10	SF	5	0-1 year	Glue on wall
	Walls - Plaster/Drywall	3rd Floor	74	SF	7	10+ years	
laceror	om #314 (Music Room)						
iassiuc	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	120	EA	6	10+ years	
	Floor - Tile		· · · · · · · · · · · · · · · · · · ·	SF	7	•	
		3rd Floor 3rd Floor	728 12	SF EA	7	10+ years 6-10 years	
	Lighting - Lay-in Marker Board			LF	7		
		3rd Floor	16	SF		6-10 years	
	Storage/ Closet	3rd Floor	20		5	10+ years	
	Walls - Concrete Block	3rd Floor	726	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	74	SF	7	10+ years	
lassroc	om #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	554	SF	7	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	554	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	725	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	74	SF	7	10+ years	
lassroo	om #316 (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	554	SF	7	10+ years	
	coming Lay in	014 1 1001	554	٥.	,	101 yours	





Category: Classroom

Graun	Itom Type	Location	Ougastite		OM I	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity		-	Rank	Replacement	Comments
	Chalk Board	3rd Floor			LF -^	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor			EA	6	10+ years	
	Floor - Tile	3rd Floor	55		SF	7	10+ years	
	Lighting - Lay-in	3rd Floor			EA	7	6-10 years	
	Storage/ Closet	3rd Floor	2		SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	63		SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	7	4 5	SF	7	10+ years	
Catego	ry : Interior			Build	ding : N	Main		
							Recommend	
Group	Item - Type	Location	Quantity	, U	OM I	Rank	Replacement	Comments
Corridor								
	Ceiling - Lay-in	1st Floor	3,76	7 5	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	0 E	EΑ	7	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor			EΑ	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor			EΑ	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor			SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	33		SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,42		SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor		4 5	SF	4	1-2 years	Damaged tile
	Lighting - Lay-in	1st Floor	11		EA	7	6-10 years	Damaged the
	Walls - Concrete Block	1st Floor	1,00		SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	4,46		SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	3,28		SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor			EA	7	6-10 years	
		2nd Floor		-	SF			
	Floor - Tile/Sheet		3,26			7	10+ years	One also d
	Floor - Tile/Sheet	2nd Floor			SF	4	0-1 year	Cracked
	Lighting - Lay-in	2nd Floor			EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,00		SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	3,12		SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	3,28		SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor			EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	3,24		SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor			SF	4	0-1 year	Cracked
	Lighting - Lay-in	3rd Floor		-	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	-		EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,00		SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	3,13	9 5	SF	7	10+ years	
Safety								
Calcly	Camera Viewing Station	Entire building		1 E	EA	7	6-10 years	
	Metal Detector	Entire building			EA	7	6-10 years	
	Security Cameras	Entire building			EA	7	6-10 years	
	Security Cameras Security Cameras	Entire building			EA	7	6-10 years	
	Cooking Camerao		'			•	o io youio	
Campue	Name: Frazier Prospective		Page : 30 of 35					Assessment Date: 03/07/2024
Campus	valilo. I razioi i 103peolive		1 age . 30 01 33					A336331116111 Date: 03/01/2024

Building: Main

Recommend





Catego	ry : Interior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security Cameras	Entire building	1	EΑ	7	6-10 years	
	Security Cameras	Entire building	6	EA	7	6-10 years	
	•	3				,	
stairs							
	Ceiling - Plaster/Drywall	Basement	1,904	SF	7	10+ years	
	Floor - Concrete	Basement	418	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	50	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	50	SF	4	1-2 years	Damaged
	Handrails	Basement	64	ĹF	7	10+ years	
	Lighting - Pendent/Surface	Basement	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	2	EA	5	1-2 years	Not working
	Stairs - Concrete	Basement	112	LF	7	10+ years	3
	Walls - Concrete Block	Basement	2,740	SF	7	10+ years	
	Ceiling - Lay-in	Central	314	SF	7	10+ years	
	Floor - Terrazzo	Central	266	SF	7	10+ years	
	Handrails	Central	130	LF	7	10+ years	
	Lighting - Pendent/Surface	Central	3	EA	7	6-10 years	
	Lighting - Wall Mounted	Central	3	ĒΑ	7	6-10 years	
	Stairs - Terrazzo	Central	48	LF	7	10+ years	
	Walls - Concrete Block	Central	392	SF	7	10+ years	
	Walls - Structural Glazed Tile	Central	390	SF	7	10+ years	
	Ceiling - Plaster/Drywall	East	314	SF	7	10+ years	
	Floor - Terrazzo	East	266	SF	7	10+ years	
	Handrails	East	130	LF	7	10+ years	
	Lighting - Pendent/Surface	East	6	EA	7	6-10 years	
	Lighting - Wall Mounted	East	3	EA	7	6-10 years	
	Stairs - Terrazzo	East	48	LF	7	10+ years	
	Walls - Concrete Block	East	690	SF	7	10+ years	
	Walls - Structural Glazed Tile	East	692	SF	7	10+ years	
	Ceiling - Lay-in	West	314	SF	7	10+ years	
	Floor - Terrazzo	West	266	SF	7	10+ years	
	Handrails	West	130	LF	7	10+ years	
	Lighting - Pendent/Surface	West	6	EA	7	6-10 years	
	Lighting - Wall Mounted	West	3	EA	7	6-10 years	
	Stairs - Terrazzo	West	48	LF	7	10+ years	
	Walls - Concrete Block	West	392	SF	7	10+ years	
	Walls - Plaster/Drywall	West	390	SF	7	10+ years	
/ortical (Conveyance						
enical (Elevator - Hydraulic Elevator	1st to 3rd floor	1	EA	7	10 L VOORO	
	Elevator - Hydraulic Elevator	151 10 310 11001	1	EA	1	10+ years	



Catego	Category : Site		В	uilding	: Site		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	10+ years	
_Fencina							
	Fencing - Chain Link	Entire Site	71	LF	4	0-1 year	Leaning.
	Fencing - New Standard Ornamental	Entire Site	300	LF	7	10+ years	Chain link fence replacement
	Fencing - New Standard Ornamental	Entire Site	1,116	LF	6	6-10 years	·
	Fencing - New Standard Ornamental	Entire Site	106	LF	4	1-2 years	Corroded
_Landsca	pe						
	Landscape - Grass	Entire Site	12,678	SF	6	6-10 years	
	Parkway trees	Entire Site	4	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	2,047	SF	6	10+ years	
	Planting Beds/ Area	Entire Site	450	SF	4	0-1 year	Planters falling apartment
	Play Area - Hardscape- Asphalt	Entire Site	10,829	SF	5	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	1,500	SF	4	0-1 year	Cracking, uneven areas
	Trash Receptacles	Entire Site	6	EA	6	10+ years	-
Parking	Lot						
Ū	Concrete Curbs	Parking Lot- South	30	LF	6	10+ years	
	Surface - Asphalt	Parking Lot- South	5,159	SF	6	6-10 years	
	Surface - Asphalt	Parking Lot- South	6,000	SF	4	0-1 year	Damaged from construction, potholes
	Trash Enclosure - Chain Links	Parking Lot- South	1,861	SF	7	10+ years	Being replaced, under construction
Playgrou	und						
	Equipment - Combo 3-12	NW site	1	EA	5	2-5 years	
	Surface - Poured Surface	NW site	2,311	SF	4	0-1 year	Damaged.
Sidewall	KS						
	Sidewalks - Internal Walks	Entire Site	153	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	10	LF	5	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	7,927	SF	6	10+ years	
Signage							
-5-5-	Flag Pole - Flag Pole	Entire Site	7	EA	6	10+ years	
	Flag Pole - Flag Pole	Entire Site	1	EA	5	2-5 years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back lighted w/	Entire Site	1	EA	7	10+ years	
	LED Monument - Building Mounted Cut Letter	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter	Entire Site	1	ΕA	7	10+ years	

Page : 32 of 35



Frazier Prospective IB Magnet ES

4027 W Grenshaw STREET, Chicago, IL 60624

Category : Site Building : Site

Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments

Sign

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Frazier Prospective Page: 33 of 35 Assessment Date: 03/07/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			1 1111111111111111111111111111111111111		(0-)	1	1		
Art Room	Art Room	2nd Floor	218	217	890	178	34	N	N
Computer Lab	Regular Classroom	1st Floor	102	105	732	89	36	N	Υ
Fitness Room	Regular Classroom	1st Floor	111	112	1,025	222	43	N	N
Kindergarten	Kindergarten	1st Floor	107	108	1,025	222	43	N	Υ
Music Room	Regular Classroom	2nd Floor	212	213	750	148	29	N	N
Music Room	Regular Classroom	2nd Floor	215	212	554	111	22	N	N
Music Room	Regular Classroom	3rd Floor	314	315	728	87	35	N	Υ
Office	Regular Classroom	1st Floor	109	110	1,025	222	43	N	Υ
Office	Regular Classroom	1st Floor	110	115	740	148	29	N	Υ
Office	Regular Classroom	3rd Floor	300	301	720	94	40	N	Υ
Other Instructional Use	Regular Classroom	2nd Floor	207	204	728	92	38	N	N
Other Instructional Use	Regular Classroom	2nd Floor	216	214	554	111	22	N	N
Regular Classroom	Regular Classroom	1st Floor	103	102	720	94	34	N	Υ
Regular Classroom	Regular Classroom	1st Floor	105	104	720	94	34	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	200	201	720	89	35	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	200	661	80	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	203	720	89	35	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	205	720	88	35	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	207	720	92	38	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	209	750	148	29	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	206	750	148	29	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	208	750	148	29	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	215	728	148	29	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	300	660	80	33	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	302	728	92	38	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	307	720	92	38	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	304	720	92	38	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	306	750	148	29	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	311	750	148	29	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	313	750	148	29	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	310	750	148	29	N	N
Regular Classroom	Regular Classroom	3rd Floor	315	312	554	111	22	N	Υ
Science	Science	2nd Floor	217	216	890	178	34	N	Υ
Science Lab Level 1	Regular Classroom	2nd Floor	205	202	720	88	35	N	N
Store Room	Regular Classroom	1st Floor	108	113	750	148	29	N	N
Store Room	Regular Classroom	2nd Floor	210	211	750	148	29	N	N
Store Room	Regular Classroom	2nd Floor	213	210	750	148	29	N	N
Store Room	Regular Classroom	3rd Floor	302	303	720	92	38	N	N



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Store Room	Regular Classroom	3rd Floor	311	308	750	148	29	N	N
Store Room	Regular Classroom	3rd Floor	316	314	554	111	22	N	N
Vacant	Regular Classroom	3rd Floor	304	305	720	92	38	N	N
Vacant	Regular Classroom	3rd Floor	308	309	750	148	29	N	N