

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 2008 | 3 | 208,200 |
| Campus Total | | | 208,200 |

Category : Exterior Building : Main

| | | | | | | Recommend | |
|----------|---------------------------------------|---|----------|-----|------|-------------|------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | | | • | | | • | |
| | Exterior Doors - Store Front | Access door to roof 4 | 1 | EA | 4 | 0-1 year | Door leaks |
| | Exterior Stairs - Concrete | Access door to roof 4 | 3 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Access door to roof 5 | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Entrance 2-West | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Entrance 3-West | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Side lite | Entrance 4-South / Library | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | Entrance 4-South / Library | 3 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 4-South / Library | 3 | EA | 6 | 10+ years | |
| | Entrance Control - Audio and Video | Entrance 5-South | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Side lite | Entrance 5-South | 6 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | Entrance 5-South | 5 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 5-South | 5 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | Entrance 5-South | 240 | LF | 7 | 10+ years | |
| | Power Door Operator and Controls | Entrance 5-South | 1 | EA | 7 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | Entrance 5-South | 240 | LF | 7 | 10+ years | |
| | Ramps - Concrete | Entrance 5-South | 120 | LF | 7 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | Entrance 5-South | 80 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Entrance 5A-East / Outside Yard Storage | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 5A-East / Outside Yard Storage | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | Entrance 6-East | 3 | EA | 7 | 10+ years | |
| | Entrance Control - Audio and Video | Entrance 6A-East / Loading Dock pedestrian door | 1 | EA | 6 | 10+ years | |





| Catego | ry : Exterior | | В | uilding | : Main | · | 7001 0 Hollian Avenoe, Ollicago, le 00002 | | |
|-----------|---|---------------------------------|----------|---------|--------|-------------|---|--|--|
| | | | | _ | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Exterior Doors - Exterior Steel Door | Entrance 6A-East / Loading Dock | 1 | EA | 6 | 10+ years | | | |
| | | pedestrian door | | | | | | | |
| | Exterior Doors - Transom Lite | Entrance 6A-East / Loading Dock | 1 | EA | 6 | 10+ years | | | |
| | Francisco Deservo Occardo e de Dellino de Occardo | pedestrian door | 4 | _^ | 0 | 0.40 | | | |
| | Exterior Doors - Overhead Rolling/ Garage | Entrance 6B-East / Loading Dock | 1 | EA | 6 | 6-10 years | | | |
| | Door Entrance Control - Audio and Video | Entrance 7-North / Gym | 1 | EA | 6 | 6-10 years | | | |
| | Exterior Doors - Side lite | Entrance 7-North / Gym | 2 | EA | 6 | 10+ years | | | |
| | Exterior Doors - Store Front | Entrance 7-North / Gym | 4 | EA | 6 | 10+ years | | | |
| | Exterior Doors - Store Front Exterior Doors - Transom Lite | Entrance 7-North / Gym | 4 | EA | 6 | 10+ years | | | |
| | Entrance Control - Audio and Video | Entrance 8-North / Basement | 1 | EA | 7 | 10+ years | | | |
| | Exterior Doors - Store Front | Entrance 8-North / Basement | 4 | EA | 7 | 10+ years | | | |
| | Exterior Doors - Store Front Exterior Doors - Transom Lite | Entrance 8-North / Basement | 3 | EA | 6 | 10+ years | | | |
| | Exterior Stairs - Concrete | Entrance 8-North / Basement | 330 | LF | 7 | 10+ years | | | |
| | Power Door Operator and Controls | Entrance 8-North / Basement | 1 | EA | 7 | 10+ years | | | |
| | Stair Handrail - Steel_Stair Handrail | Entrance 8-North / Basement | 90 | LF | 7 | 10+ years | | | |
| | Exterior Doors - Exterior Steel Door | Entrance 9-NW | 2 | EA | 6 | 10+ years | | | |
| | Entrance Control - Audio and Video | Main Entrance 1-West | 1 | EA | 6 | 10+ years | | | |
| | Exterior Doors - Side lite | Main Entrance 1-West | 6 | EA | 6 | 10+ years | | | |
| | Exterior Doors - Store Front | Main Entrance 1-West | 6 | EA | 6 | 10+ years | | | |
| | Exterior Doors - Store Front Exterior Doors - Transom Lite | Main Entrance 1-West | 6 | EA | 6 | 10+ years | | | |
| | Exterior Stairs - Concrete | Main Entrance 1-West | 736 | LF | 6 | 10+ years | | | |
| | Exterior Stairs - Concrete | Main Entrance 1-West | 4 | LF | 4 | 0-1 year | Cracked, spalled steps | | |
| | Power Door Operator and Controls | Main Entrance 1-West | 1 | EA | 7 | 10+ years | Cracked, spalled steps | | |
| | Ramp Handrail - Steel_Ramp Handrail | Main Entrance 1-West | 330 | LF | 7 | 10+ years | | | |
| | Ramps - Concrete | Main Entrance 1-West | 150 | LF | 7 | 10+ years | | | |
| | Stair Handrail - Steel_Stair Handrail | Main Entrance 1-West | 375 | LF | 7 | 10+ years | | | |
| | Stall Harlarali Steel_Stall Harlarali | Main Entrance 1 West | 0/0 | | , | 101 years | | | |
| _Foundat | ion | | | | | | | | |
| | Foundation - Concrete | Entire Building | 1,800 | LF | 7 | 10+ years | | | |
| | Superstructure - Concrete | Entire Building | 208,200 | SF | 7 | 10+ years | | | |
| | | | | | | | | | |
| _Lighting | | | | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 25 | EA | 6 | 6-10 years | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 38 | EA | 6 | 6-10 years | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 76 | EA | 6 | 6-10 years | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 51 | EA | 6 | 6-10 years | | | |
| _Roof Sv | stem | | | | | | | | |
| | Access Ladder - Metal | Roof 1 - Main | 1 | EA | 7 | 10+ years | | | |
| | Coping - Metal | Roof 1 - Main | 1,155 | LF | 7 | 10+ years | | | |
| | Downspouts - Interior Downspouts | Roof 1 - Main | 2,480 | LF | 7 | 10+ years | | | |
| | Parapet - 16" - 30" Height | Roof 1 - Main | 1,155 | LF | 7 | 10+ years | | | |
| | . a.apot 10 00 Holgit | 1.001 1 Main | 1,100 | | , | ioi youis | | | |





| Comments |
|----------|
| Comments |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| Repaired |
| Topanoa |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| _ |



Category : Exterior

Sarah E. Goode STEM Academy 7651 S Homan AVENUE, Chicago, IL 60652

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------|---|------------------------------------|----------------|----------|---------|--------------------------|--|
| | Lintels - Steel Windows - Casement Aluminum Double- | Entire Building Entire Building | 1,390 2,834 | LF SF | 7 7 | 10+ years 10+ years | |
| | pane Windows - Louver | Entire Building | 90 | SF | 7 | 10+ years | |
| ateno | ry : Electrical | - | R | uilding | · Main | • | |
| alego | y . Liectricai | | | unung | . Walli | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| merger | ncy System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 4 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 208,200 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 208,200 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 49,539 | SF | 7 | 10+ years | |
| | Emergency A/C Power - Gym | Entire Building | 12,000 | SF | 7 | 10+ years | Location changed for clarification as the gym occupies space on multiple floors. |
| | Emergency A/C Power - Lunchrooms | Entire Building | 6,656 | SF | 7 | 10+ years | |
| | Emergency A/C Power - Pool | Entire Building | 7,047 | SF | 7 | 10+ years | Location changed for clarification as the pool occupies space on multiple floors. |
| | Emergency A/C Power - Students Toilets | Entire Building | 5,856 | SF | 7 | 10+ years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 32 | ĒΑ | 6 | 6-10 years | |
| | Exit Signs - Gym | Entire Building | 14 | ĒĀ | 6 | 6-10 years | Location changed for clarification as the gym occupies space on multiple floors. Quantity changed as total habeen divided/aggregated. |
| | Exit Signs - Lunchroom | Entire Building | 4 | EA | 7 | 6-10 years | Quantity changed to match current observations. |
| | Exit Signs - Pool | Entire Building | 7 | EA | 7 | 6-10 years | Location changed for clarification as the pool occupies space on multiple floors. Quantity changed as total habeen divided/aggregated. |
| | Emergency Generator- Indoor- Natural Gas - Above 250 KW | Generator Room | 1 | EA | 6 | 10+ years | soon amada aggi eganda. |
| //ain Sei | vice | | | | | | |
| | Main Electrical Service - 2001 to 3000 A 120/208/3PH | Electrical Room | 1 | EA | 7 | 10+ years | |
| | Main Electrical Service - 2001 to 3000 A 277/480/3PH | Electrical Room | 1 | EA | 7 | 10+ years | |
| | PA System | Entire Building | 208,200 | SF | 6 | 6-10 years | |

Building: Main



| Catego | ry : Electrical | | В | uilding | : Main | | |
|------------|--|-----------------|----------|---------|--------|---------------------------------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | istribution | Location | Quantity | CON | Italik | Replacement | Comments |
| -owel Di | Lighting and Power Panels - Above 100 A | Entire Building | 59 | EA | 7 | 10+ years | Quantity changed as total has beer |
| | Lighting and Fower Fallets - Above 100 A | Entire Building | 39 | LA | , | 10+ years | divided/aggregated. Location changed for clarification. |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 10 | EA | 7 | 10+ years | Quantity changed as total has beer divided/aggregated. Location changed for clarification. |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 4 | EA | 7 | 10+ years | Quantity changed as total has beer divided/aggregated. Location changed for clarification. |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 5 | EA | 7 | 10+ years | changed for damication. |
| | Transformers - 277/480 - 120/208 | Entire Building | 6 | EA | 7 | 10+ years | Quantity changed as total has been divided/aggregated. |
| Categoi | ry : Fire Protection | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Aları | m | | | | | | |
| | Fire ALarm Anunciator | Entire Building | 1 | EA | 6 | 6-10 years | No CPS Asset Tag present. |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Fire Alarm Strobe Lights | Entire Building | 208,200 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 208,200 | SF | 6 | 6-10 years | |
| | Fire Pump Controller | Entire Building | 1 | EA | 6 | 10+ years | |
| Pump Ro | oom Assembly | | | | | | |
| | Fire Pump - Greater than 75hp | Mechanical Room | 1 | EA | 6 | 10+ years | |
| | Jockey Pump | Mechanical Room | 1 | EA | 6 | 10+ years | |
| | | | | | | , , , , , , , , , , , , , , , , , , , | |
| Sprinkler | System | | | | | | |
| | Dry Sprinkler System | Entire Building | 550 | SF | 7 | 10+ years | |
| | Sprinkler Heads | Entire Building | 208,200 | SF | 7 | 6-10 years | |
| | Sprinkler Piping | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Wet Sprinkler System | Entire Building | 207,650 | SF | 7 | 10+ years | |
| Categoi | ry : Mechanical | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Air Cond | | Location | Quantity | CON | Naiik | Replacement | Comments |
| AII COHO | Heat Pump- Ceiling Mounted- Hot Water | Entire Building | | Ε^ | 6 | 6 10 2000 | Quantity shanged as total has been |
| | Heat Pump- Ceiling Mounted- Hot Water Heating & DX Cooling- Self Contained Condessor Water Cooled Compressor - 4 - | Entire Building | 62 | EA | ъ | 6-10 years | Quantity changed as total has been divided/aggregated. Ceiling mounted, or mounted to a ceiling- |



| Catego | ry : Mechanical | | В | uilding | : Main | | <u> </u> |
|-----------|---|--------------------|----------|---------|--------|-------------|---|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | 5 tons Heat Pump- Ceiling Mounted- Hot Water Heating & DX Cooling- Self Contained Condessor Water Cooled Compressor - | Entire Building | 48 | EA | 6 | 6-10 years | mounted shelf assembly. Quantity changed as total has been divided/aggregated. Ceiling mounted, or mounted to a ceiling- |
| | Less than 3 tons Heat Pump- Floor Mounted- Hot Water Heating & DX Cooling- Self Contained Condessor Water Cooled Compressor - Greater than 5 tons | Mechanical Room | 1 | EA | 7 | 6-10 years | mounted shelf assembly. Serves radiant floor heating in lunchroom and music suite. Priority Rep adjusted based on current observations and on the age of the equipment. |
| | Heat Pump- Floor Mounted- Hot Water Heating & DX Cooling- Self Contained Condessor Water Cooled Compressor - Greater than 5 tons | Mechanical Room | 1 | EA | 7 | 6-10 years | Serves the Dectron pool area air dehumidification unit (AHU-B1). Priority Rep adjusted based on current observations and on the age of the equipment. |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | 6-10 years | Location changed for clarification. |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | 6-10 years | Component of a ductless split system serving MDF Room. |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | 6-10 years | Location changed for clarification. |
| _Air Hand | lling Systems | | | | | | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 12001-20000 cfm | East Gym Mezzanine | 1 | EA | 6 | 10+ years | AHU-1-2. No CPS Asset Tag present. |
| | Air Intake | East Gym Mezzanine | 1 | EA | 7 | 10+ years | |
| | Dehumidification Unit- Indoor- Hot Water Heating- DX Cooling with Self Contained Compressor - Greater than 8000 cfm | Mechanical Room | 1 | EA | 6 | 10+ years | AHU-B-1 |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - Greater than 30,000 cfm | Mechanical Room | 1 | EA | 6 | 10+ years | DOAU B-1. |
| | Air Intake | Mechanical Room | 1 | EA | 7 | 10+ years | |
| | Energy Recovery Unit | Mechanical Room | 1 | EA | 7 | 10+ years | Integral with, and internal to, the air handling unit itself. Rank changed based on review with Building Engineer that adjustments have been completed since previous assessment. No CPS Asset Tag present. |
| | Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM | Mechanical Room | 1 | EA | 7 | 10+ years | BF-1. A bypass fan which circulates outside air to specific mechanical spaces; operates when the primary |



| Catego | ry : Mechanical | | В | uilding | : Main | | | |
|-----------|---|--------------------|----------|---------|--------|-------------|--|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 12001-20000 cfm | West Gym Mezzanine | 1 | EA | 6 | 10+ years | air handler (DOAU B-1) is not running. AHU-1-1. No CPS Asset Tag present. | |
| | Air Intake | West Gym Mezzanine | 1 | EA | 7 | 10+ years | | |
| Boiler Sy | estems | | | | | | | |
| , | Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP | Mechanical Room | 2 | EA | 6 | 10+ years | | |
| | Chemical Pot Feeder | Mechanical Room | 1 | EA | 6 | 10+ years | | |
| | Chemical Pot Feeder | Mechanical Room | 1 | EA | 6 | 10+ years | | |
| | Chemical Pot Feeder | Mechanical Room | 1 | EA | 6 | 10+ years | | |
| | Condensing- Hot Water Boiler - 1001 - 2000 | Mechanical Room | 2 | EΑ | 6 | 10+ years | B-1 and B-2 | |
| | MBH | Woorlamour Room | _ | | Ū | 101 youro | B Tana B Z | |
| | Glycol Feed System | Mechanical Room | 1 | EA | 6 | 10+ years | | |
| | Water Fill System | Mechanical Room | 1 | EA | 6 | 10+ years | | |
| | Water Fill System | Mechanical Room | ' | LA | O | 10+ years | | |
| Heat Exc | changers | | | | | | | |
| | Heat Exchanger - Water to Water Plate Type | Mechanical Room | 1 | EA | 6 | 10+ years | Domestic HX, serves the domestic water heating system. No CPS Ass Tag present. | |
| | Heat Exchanger - Water to Water Plate Type | Mechanical Room | 1 | EA | 6 | 10+ years | Pool HX, serves the pool water heating system. No CPS Asset Tag present. | |
| | Heat Exchanger - Water to Water Shell Type | Roof | 1 | EA | 7 | 10+ years | Solar panels for the heating of pool water and domestic hot water. No CPS Asset Tag present. | |
| | Heat Exchanger - Water to Water Shell Type | Roof | 1 | EA | 7 | 10+ years | Solar panels for the heating of pool water and domestic hot water. No CPS Asset Tag present. | |
| | Heat Exchanger - Water to Water Shell Type | Roof | 1 | EA | 7 | 10+ years | Solar panels for the heating of pool water and domestic hot water. No CPS Asset Tag present. | |
| | Heat Exchanger - Water to Water Shell Type | Roof | 1 | EA | 7 | 10+ years | Solar panels for the heating of pool water and domestic hot water. No CPS Asset Tag present. | |
| | Heat Exchanger - Water to Water Shell Type | Roof | 1 | EA | 7 | 10+ years | Solar panels for the heating of pool water and domestic hot water. No CPS Asset Tag present. | |
| | Heat Exchanger - Water to Water Shell Type | Roof | 1 | EA | 7 | 10+ years | Solar panels for the heating of pool water and domestic hot water. No | |
| | Heat Exchanger - Water to Water Shell | Roof | 1 | EA | 7 | 10+ years | CPS Asset Tag present. Solar panels for the heating of pool | |



| Catego | ry : Mechanical | | В | uilding | : Main | | |
|-------------|---|-----------------|----------|---------|--------|-------------|--|
| | | | . | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Туре | | | | | | water and domestic hot water. No CPS Asset Tag present. |
| Heating | Devices | | | | | | |
| | Unit Heater - Electric | Entire Building | 16 | EA | 6 | 6-10 years | |
| | Fin Tube - Electric | Entire Building | 30 | LF | 6 | 10+ years | Located above the vestibule doors in the main entrance lobby. Two 15-foot sections. |
| | Cabinet Heaters - With Electric Coil | Entire Building | 16 | EA | 6 | 10+ years | |
| | Under Floor Heating- Hot Water | Entire Building | 800 | SF | 6 | 10+ years | Serves the south cantilevered area of the music suites. |
| | Under Floor Heating- Hot Water | Entire Building | 1,000 | SF | 6 | 10+ years | Serves the north cantilevered area of the lunchroom. |
| | Radiator Panels - Electric | Entire Building | 16 | EA | 7 | 10+ years | Ceiling mounted in east and west stairways on 2nd and 3rd floors. |
| _Mechani | cal Plumbing | | | | | | |
| | Hydronic Supply and Return - Copper | Entire Building | 1,250 | LF | 7 | 10+ years | |
| | Hydronic Supply and Return - Steel | Entire Building | 300 | LF | 7 | 10+ years | |
| | Hot Water Pump - Less than 10 | Mechanical Room | 1 | EA | 6 | 10+ years | No CPS Asset Tag present. |
| | Hot Water Pump - Less than 10 | Mechanical Room | 1 | EA | 6 | 10+ years | No CPS Asset Tag present. |
| | Condenser Pump - Greater than 50 HP | Mechanical Room | 2 | EA | 6 | 10+ years | Ground loop pumps serving the 110 ceiling-mounted heat pumps throughout the building. |
| _Tempera | ature Control | | | | | | |
| | DDC System | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Electric Thermostat | Entire Building | 8 | EA | 7 | 6-10 years | Quantity changed based on current observations. |
| | Electric Thermostat | Entire Building | 7 | EA | 7 | 6-10 years | |
| | Thermostats - DDC | Entire Building | 114 | EA | 7 | 6-10 years | |
| _Ventilatio | | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 6 | EA | 6 | 10+ years | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 1 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 5 | EA | 6 | 10+ years | Quantity changed to match current observations and as total has been divided/aggregated. |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 7 | EA | 6 | 10+ years | Quantity changed to match current observations and as total has been divided/aggregated. |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 3 | EA | 6 | 10+ years | Quantity changed to match current observations and as total has been |



| Catego | ry : Mechanical | | В | uilding | · Main | • | 651 S Homan Avenue, Chicago, IL 60652 |
|-----------|---|-----------------|----------|---------|--------|-------------|--|
| Outogo | i y . inconamoui | | | ananig | · Wani | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 1 | EA | 6 | 10+ years | divided/aggregated. EF-9 (230 cfm), EF-15 (160 cfm) and EF-17 (340 cfm). Item Type (EF-6, 225 cfm) changed to match current observations. Location changed for clarification. |
| | Type I Exhaust Hood- Kitchen | Entire Building | 2 | EA | 6 | 10+ years | Location changed for clarification. |
| Catego | ry : Plumbing | | В | uilding | : Main | | |
| Group | Itom Type | Logotion | Quantity | UOM | Donk | Recommend | Comments |
| Group | Item - Type | Location | Quantity | UOW | Rank | Replacement | Comments |
| _Hot Wate | Electric Heater - 20 - 50 KW | Kitchen | 1 | EA | 6 | 6-10 years | Originally served the dishwasher system; fully operational but not in service since 2013 when the room was converted to a storage room. |
| | Gas Heater - Greater than 600000 BTU/HR | Mechanical Room | 2 | EA | 6 | 6-10 years | |
| | Hot Water Storage Tank_Gas - 201 - 500 Gallons | Mechanical Room | 1 | EA | 7 | 10+ years | |
| Piping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Sanitary Piping | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Storm Piping | Entire Building | 208,200 | SF | 7 | 10+ years | |
| | Vent Piping | Entire Building | 208,200 | SF | 7 | 10+ years | |
| Pool Sys | etems | | | | | | |
| | Pool Drain Piping | Basement | 140 | LF | 7 | 10+ years | Location changed for clarification. |
| | Pool Filtration System including Pump | Basement | 1 | EA | 6 | 10+ years | Location changed for clarification. |
| | Pool Hot Water Heater - Gas Fired | Basement | 1 | EA | 7 | 10+ years | Location changed for clarification. Rank, Reason and Priority Rep changed as the heater has been replaced since previous assessment. |
| | Pool Supply and Return Piping | Basement | 300 | LF | 7 | 10+ years | Location changed for clarification. |

Campus Name: Goode HS Page : 9 of 60 Assessment Date: 04/16/2024





| Catego | ry : Plumbing | | В | uilding | : Main | | |
|---------|--------------------------------------|-----------------|----------|---------|--------|-------------|--|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | |
| _Pumps_ | | | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Pumps - Sump-Duplex | Entire Building | 1 | EA | 6 | 6-10 years | Location changed for clarification. No |
| | | | | | | | CPS Asset Tag present. |
| | Pumps - Sump-Duplex | Entire Building | 1 | EA | 6 | 6-10 years | No CPS Asset Tag present. |
| | Pumps - Sump-Duplex | Entire Building | 1 | EA | 6 | 6-10 years | No CPS Asset Tag present. |
| | Pumps - Sump-Duplex | Entire Building | 1 | EA | 6 | 6-10 years | Item Type changed to match current |
| | | | | | | | observations. |
| | Pumps - Sump-Duplex | Entire Building | 1 | EA | 6 | 6-10 years | Item Type changed to match current |
| | | | | | | | observations. |
| | Pumps - Sump-Simplex | Entire Building | 1 | EA | 6 | 6-10 years | No CPS Asset Tag present. |
| | Pumps - Sump-Simplex | Entire Building | 1 | EA | 6 | 6-10 years | Elevator pit sump pump. Not directly |
| | | | | | | | accessible at the time of assessment. |
| | | | | | | | Condition verified by Building |
| | | | | | | | Engineer. No CPS Asset Tag |
| | | | | | | | available. |
| | Pumps - Sump-Simplex | Entire Building | 1 | EA | 6 | 6-10 years | Elevator pit sump pump. Not directly |
| | | | | | | | accessible at the time of assessment. |
| | | | | | | | Condition verified by Building |
| | | | | | | | Engineer. No CPS Asset Tag |
| | | | | | | | available. |
| | | | | | | | |

Category : Room **Building: Main**

| | | | | | Recommend | |
|-------------------------------|------------------------|----------|-----|------|-------------|----------|
| Group Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Administrative Suites/Offices | | | | | | |
| Ceiling - Exposed | 000 A Sound Equipment | 124 | SF | 7 | 10+ years | |
| Doors - Steel Doors incl hw | 000 A Sound Equipment | 1 | EA | 7 | 10+ years | |
| Floor - Concrete | 000 A Sound Equipment | 124 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | 000 A Sound Equipment | 1 | EA | 7 | 6-10 years | |
| Power Distribution | 000 A Sound Equipment | 6 | EA | 7 | 10+ years | |
| Walls - Concrete Block | 000 A Sound Equipment | 235 | SF | 7 | 10+ years | |
| Ceiling - Exposed | 000 Scene Shop | 1,114 | SF | 7 | 10+ years | |
| Doors - Steel Doors incl hw | 000 Scene Shop | 2 | EA | 7 | 10+ years | |
| Floor - Concrete | 000 Scene Shop | 1,114 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | 000 Scene Shop | 14 | EA | 7 | 6-10 years | |
| Power Distribution | 000 Scene Shop | 6 | EA | 7 | 10+ years | |
| Walls - Concrete Block | 000 Scene Shop | 2,116 | SF | 7 | 10+ years | |
| Ceiling - Lay-in | 003 A Concession Stand | 135 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | 003 A Concession Stand | 1 | EA | 7 | 10+ years | |
| Floor - Tile | 003 A Concession Stand | 135 | SF | 7 | 10+ years | |
| Lighting - Lay-in | 003 A Concession Stand | 4 | EA | 7 | 6-10 years | |
| Power Distribution | 003 A Concession Stand | 4 | EA | 7 | 10+ years | |

Campus Name: Goode HS Page : 10 of 60 Assessment Date: 04/16/2024







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Walls - Plaster/Drywall 003 A Concession Stand 480 SF 10+ vears 7 SF 7 Ceiling - Lav-in 004 Green Room 381 10+ years Doors - Steel Doors incl hw 004 Green Room FΑ 7 10+ years 1 Floor - Tile SF 7 004 Green Room 381 10+ years Lighting - Lay-in 004 Green Room 6 EΑ 7 6-10 years 7 Power Distribution 004 Green Room 50 EΑ 10+ years Walls - Concrete Block 004 Green Room SF 7 711 10+ years Work SInk 004 Green Room 1 EΑ 7 10+ years Ceiling - Lay-in 005 A Park District Ticket Office 108 SF 7 10+ years Doors - Wood Doors inclu hw 005 A Park District Ticket Office FΑ 7 10+ years 1 Floor - Tile 005 A Park District Ticket Office 108 SF 7 10+ years Lighting - Lay-in 005 A Park District Ticket Office EΑ 7 6-10 years 1 Power Distribution 6 EΑ 7 005 A Park District Ticket Office 10+ years SF 7 Walls - Concrete Block 005 A Park District Ticket Office 340 10+ years Ceiling - Plaster/Drywall SF 7 005 C Athletic director 155 10+ years Doors - Wood Doors inclu hw FΑ 7 005 C Athletic director 1 10+ years Floor - Tile SF 005 C Athletic director 155 7 10+ years Lighting - Lay-in 005 C Athletic director 3 EΑ 7 6-10 years 6 Power Distribution EΑ 7 10+ vears 005 C Athletic director Walls - Concrete Block 005 C Athletic director 420 SF 7 10+ years Ceiling - Lay-in 100 SF 7 10+ years 006 A Athletic Director SF 7 Doors - Side-lite 006 A Athletic Director 9 10+ years Doors - Wood Doors inclu hw 7 006 A Athletic Director 1 EΑ 10+ years SF Floor - Terrazzo 100 7 10+ years 006 A Athletic Director EΑ 7 Lighting - Lay-in 006 A Athletic Director 2 6-10 years Power Distribution 006 A Athletic Director 6 EΑ 7 10+ years SF Walls - Structural Glazed Tile 006 A Athletic Director 360 7 10+ years Ceiling - Lay-in SF 7 006 A Coach Office 112 10+ years Doors - Side-lite SF 006 A Coach Office 40 7 10+ years Doors - Wood Doors inclu hw 006 A Coach Office 1 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 112 SF 7 10+ years 006 A Coach Office Lighting - Lav-in 006 A Coach Office 2 EΑ 7 6-10 years 7 Power Distribution 6 FΑ 006 A Coach Office 10+ years Walls - Concrete Block 212 SF 7 10+ years 006 A Coach Office SF 7 Ceiling - Plaster/Drywall 007A Mens Pool Coach 140 10+ years 7 Doors - Steel Doors incl hw 007A Mens Pool Coach EΑ 10+ years 1 SF Floor - Concrete Epoxy/ Painted 007A Mens Pool Coach 140 7 10+ years Lighting - Lay-in 6-10 years 007A Mens Pool Coach 4 EΑ 7 Power Distribution 007A Mens Pool Coach 6 EΑ 7 10+ years SF Walls - Concrete Block 007A Mens Pool Coach 480 7 10+ years SF Ceiling - Plaster/Drywall 007B Womens Pool Coach 140 7 10+ years Doors - Steel Doors incl hw FΑ 7 007B Womens Pool Coach 10+ years 1 Floor - Concrete Epoxy/ Painted 007B Womens Pool Coach 140 SF 7 10+ years Lighting - Lay-in 007B Womens Pool Coach EΑ 7 6-10 years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Power Distribution 007B Womens Pool Coach 6 EΑ 10+ vears 7 480 SF 7 Walls - Concrete Block 007B Womens Pool Coach 10+ years Ceiling - Lav-in 008 F Womens Coach 140 SF 7 10+ years Doors - Wood Doors inclu hw EΑ 7 008 F Womens Coach 10+ years SF Floor - Tile Ceramic/ Porcelain 008 F Womens Coach 140 7 10+ years EΑ 7 Lighting - Lay-in 008 F Womens Coach 6-10 years 4 Power Distribution 6 EΑ 7 008 F Womens Coach 10+ years 008 F Womens Coach SF 10+ years Walls - Concrete Block 480 7 SF Ceiling - Lav-in 008 G Training 95 7 10+ years SF Doors - Side-lite 008 G Training 8 7 10+ years Doors - Wood Doors inclu hw 008 G Training 1 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 008 G Training 95 SF 7 10+ years Lighting - Lay-in 2 EΑ 7 6-10 years 008 G Training 6 EΑ 7 Power Distribution 008 G Training 10+ years Walls - Concrete Block SF 7 008 G Training 180 10+ years Ceiling - Lay-in SF 7 100 A Workroom 419 10+ years SF 7 Doors - Side-lite 100 A Workroom 110 10+ years Doors - Store Front 100 A Workroom 2 EΑ 7 10+ years SF Doors - Transom Window 100 A Workroom 16 7 10+ vears SF Floor - Terrazzo 100 A Workroom 419 7 10+ years Lighting - Lay-in 100 A Workroom 8 EΑ 7 6-10 years Power Distribution 6 7 100 A Workroom EΑ 10+ years SF 7 Storage/ Closet 100 A Workroom 80 10+ years SF Walls - Plaster/Drywall 100 A Workroom 796 6 10+ years Work SInk FΑ 7 100 A Workroom 1 10+ years SF Ceiling - Lav-in 100 E Library Office 168 7 10+ years Doors - Side-lite 100 E Library Office SF 70 7 10+ years Doors - Store Front 100 E Library Office EΑ 7 1 10+ years 100 E Library Office SF Doors - Transom Window 8 7 10+ years Floor - Carpet 100 E Library Office 168 SF 6 6-10 years Lighting - Lay-in 100 E Library Office FΑ 7 6-10 years 4 Power Distribution 100 E Library Office 6 EΑ 7 10+ vears 100 E Library Office SF Walls - Plaster/Drywall 319 6 10+ years Ceiling - Lay-in 100 F Professional Library 353 SF 7 10+ years Doors - Side-lite SF 7 100 F Professional Library 70 10+ years EΑ 7 Doors - Store Front 100 F Professional Library 10+ years 1 SF Doors - Transom Window 100 F Professional Library 8 7 10+ years SF 6-10 years Floor - Carpet 100 F Professional Library 353 6 Lighting - Lay-in 100 F Professional Library 8 EΑ 7 6-10 years Power Distribution 100 F Professional Library 6 EΑ 7 10+ vears SF Walls - Plaster/Drywall 100 F Professional Library 670 6 10+ years SF 7 Ceiling - Lav-in 105A Auditorium Lighting Control 174 10+ years Doors - Steel Doors incl hw 105A Auditorium Lighting Control EΑ 7 10+ years Doors - Wood Doors inclu hw 105A Auditorium Lighting Control 7 EΑ 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Floor - Carpet 105A Auditorium Lighting Control 174 SF 6-10 years 7 105A Auditorium Lighting Control EΑ 7 6-10 years Lighting - Lay-in 1 Power Distribution 105A Auditorium Lighting Control 6 FΑ 7 10+ years Walls - Concrete Block 105A Auditorium Lighting Control 96 SF 7 10+ years SF Walls - Plaster/Drywall 105A Auditorium Lighting Control 328 7 10+ years SF 7 Ceiling - Lay-in 105B sound Control 121 10+ years Doors - Steel Doors incl hw 105B sound Control EΑ 7 10+ years 2 SF Floor - Carpet 105B sound Control 121 7 6-10 years Lighting - Lay-in 105B sound Control 2 EΑ 7 6-10 years Power Distribution 105B sound Control 6 FΑ 7 10+ vears Walls - Concrete Block 105B sound Control 88 SF 7 10+ years Walls - Plaster/Drywall 105B sound Control 265 SF 7 10+ years Ceiling - Lay-in 105C Follow Spot SF 7 10+ years 84 Doors - Steel Doors incl hw 7 105C Follow Spot 1 EΑ 10+ years Floor - Carpet 105C Follow Spot SF 84 6 6-10 years FΑ 7 Lighting - Lay-in 105C Follow Spot 1 6-10 years 7 Power Distribution 105C Follow Spot 4 EΑ 10+ vears SF Walls - Concrete Block 105C Follow Spot 48 7 10+ years SF Walls - Plaster/Drywall 105C Follow Spot 336 7 10+ years SF Ceiling - Lay-in 107 Fitness Room 2,040 7 10+ years Doors - Side-lite 107 Fitness Room 120 SF 7 10+ years SF 7 10+ years Doors - Transom Window 107 Fitness Room 60 7 Doors - Wood Doors inclu hw 107 Fitness Room EΑ 10+ years 107 Fitness Room SF Floor - Wood 2.040 7 10+ years Lighting - Lay-in EΑ 7 6-10 years 107 Fitness Room 22 Power Distribution 107 Fitness Room 6 EΑ 7 10+ years 30 SF Storage/ Closet 107 Fitness Room 7 10+ years Walls - Plaster/Drywall 107 Fitness Room 3,876 SF 7 10+ years Ceiling - Lay-in 113 Police SF 212 7 10+ years Doors - Side-lite 113 Police 8 SF 7 10+ years Doors - Wood Doors inclu hw 113 Police 1 FΑ 7 10+ years Floor - Tile 113 Police 212 SF 7 10+ years Lighting - Lay-in 7 113 Police FΑ 6-10 years 4 Power Distribution 113 Police 6 FΑ 7 10+ years Walls - Concrete Block SF 7 113 Police 725 10+ years SF 7 Ceiling - Lay-in 114 Attendance Office 140 10+ years SF Doors - Side-lite 114 Attendance Office 8 7 10+ years Doors - Wood Doors inclu hw 114 Attendance Office 1 EΑ 7 10+ years SF Floor - Tile 114 Attendance Office 140 7 10+ years Lighting - Lay-in 114 Attendance Office 1 EΑ 7 6-10 years Lighting - Lay-in 114 Attendance Office 1 EΑ 5 1-2 years Not working Power Distribution FΑ 7 114 Attendance Office 30 10+ years Walls - Concrete Block 114 Attendance Office 200 SF 7 10+ years SF Walls - Plaster/Drywall 114 Attendance Office 280 7 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Ceiling - Lav-in 115 Security 140 SF 10+ vears 7 Doors - Side-lite 8 SF 7 115 Security 10+ years Doors - Wood Doors inclu hw 115 Security 1 FΑ 7 10+ years Floor - Tile 115 Security SF 7 140 10+ years Lighting - Lay-in 115 Security 2 EΑ 7 6-10 years Power Distribution 6 7 115 Security EΑ 10+ years Walls - Structural Glazed Tile 115 Security 480 SF 7 10+ years SF 10+ years Ceiling - Lay-in 120 A Office 140 7 SF Doors - Side-lite 120 A Office 8 7 10+ years Doors - Wood Doors inclu hw 120 A Office EΑ 7 10+ years 1 Floor - Carpet 120 A Office 140 SF 6 6-10 years Lighting - Lay-in 120 A Office 2 EΑ 7 6-10 years Power Distribution 120 A Office 6 EΑ 7 10+ years SF Walls - Plaster/Drywall 120 A Office 480 6 10+ years SF 7 Ceiling - Lay-in 120 Attendance Office 140 10+ years Doors - Wood Doors inclu hw FΑ 7 120 Attendance Office 1 10+ years SF Floor - Carpet 120 Attendance Office 140 6 6-10 years Lighting - Lay-in 120 Attendance Office 4 EΑ 7 6-10 years Power Distribution 8 120 Attendance Office EΑ 7 10+ vears Walls - Concrete Block 120 Attendance Office 200 SF 6 10+ years Walls - Plaster/Drywall 120 Attendance Office 280 SF 6 10+ years SF 7 10+ years Ceiling - Lay-in 121 A Faculty Cafeteria 307 Doors - Store Front 2 7 121 A Faculty Cafeteria EΑ 10+ years SF 7 Floor - Terrazzo 121 A Faculty Cafeteria 307 10+ years 121 A Faculty Cafeteria 6 EΑ 7 Lighting - Lay-in 6-10 years Power Distribution 121 A Faculty Cafeteria 8 EΑ 7 10+ years SF Walls - Concrete Block 121 A Faculty Cafeteria 246 7 10+ years Walls - Masonry 121 A Faculty Cafeteria SF 7 122 10+ years Work SInk 121 A Faculty Cafeteria 1 EΑ 7 10+ years Ceiling - Lay-in 121 B Dishwashing Room 288 SF 7 10+ years Doors - Steel Doors incl hw 121 B Dishwashing Room FΑ 7 10+ years 1 Floor - Concrete Epoxy/ Painted 121 B Dishwashing Room 288 SF 7 10+ years FΑ 7 Lighting - Lay-in 121 B Dishwashing Room 6 6-10 years Power Distribution 121 B Dishwashing Room 8 FΑ 7 10+ years SF 7 Walls - Structural Glazed Tile 121 B Dishwashing Room 560 10+ years 121 B Dishwashing Room EΑ 7 Work SInk 2 10+ years SF Ceiling - Lay-in 121 C Tray Drop-Off 160 7 10+ years Floor - Terrazzo 121 C Tray Drop-Off SF 160 7 10+ years Lighting - Lay-in 121 C Tray Drop-Off 2 EΑ 7 6-10 years 121 C Tray Drop-Off Power Distribution 2 EΑ 7 10+ vears SF Walls - Concrete Block 121 C Tray Drop-Off 260 7 10+ years Work SInk 121 C Tray Drop-Off 2 FΑ 7 10+ years Ceiling - Lay-in 122 West Workroom / Mailboxes 424 SF 7 10+ years Doors - Wood Doors inclu hw 122 West Workroom / Mailboxes 2 EΑ 7 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile 122 West Workroom / Mailboxes 424 SF 10+ vears 6 6 EΑ 7 6-10 years Lighting - Lav-in 122 West Workroom / Mailboxes Power Distribution 122 West Workroom / Mailboxes 6 FΑ 7 10+ years Walls - Plaster/Drywall 678 SF 122 West Workroom / Mailboxes 6 10+ years 7 Work SInk 122 West Workroom / Mailboxes 1 EΑ 10+ years SF 220 7 Ceiling - Lay-in 124 A Conference Room 10+ years Doors - Wood Doors inclu hw 124 A Conference Room EΑ 7 10+ years 1 SF Floor - Carpet 124 A Conference Room 220 6 6-10 years Lighting - Lay-in 124 A Conference Room 4 EΑ 7 6-10 years Power Distribution 124 A Conference Room 8 EΑ 7 10+ vears Walls - Plaster/Drywall 124 A Conference Room 600 SF 6 10+ years Ceiling - Lay-in 124 B Office 140 SF 7 10+ years Doors - Wood Doors inclu hw 124 B Office EΑ 7 10+ years SF Floor - Carpet 124 B Office 140 6 6-10 years Lighting - Lay-in EΑ 7 124 B Office 4 6-10 years Power Distribution 6 FΑ 7 124 B Office 10+ years SF 7 Walls - Plaster/Drywall 124 B Office 480 10+ years Ceiling - Lay-in SF 124 C Assistant Principals 140 7 10+ years Doors - Wood Doors inclu hw EΑ 124 C Assistant Principals 7 10+ vears 1 Floor - Carpet 124 C Assistant Principals 140 SF 6 6-10 years Lighting - Lay-in 124 C Assistant Principals 4 EΑ 7 6-10 years 6 7 10+ years Power Distribution 124 C Assistant Principals EΑ SF Walls - Plaster/Drywall 124 C Assistant Principals 480 6 10+ years SF 7 Ceiling - Lay-in 124 D Assistant Principal 140 10+ years Doors - Wood Doors inclu hw EΑ 7 124 D Assistant Principal 1 10+ years Floor - Carpet 124 D Assistant Principal 140 SF 6 6-10 years 7 Lighting - Lay-in 124 D Assistant Principal EΑ 6-10 years 4 Power Distribution 124 D Assistant Principal 6 EΑ 7 10+ years SF Walls - Plaster/Drywall 124 D Assistant Principal 480 6 10+ years Ceiling - Lay-in 124 E Principals Office 237 SF 7 10+ years Doors - Wood Doors inclu hw 124 E Principals Office FΑ 7 10+ years 1 Floor - Carpet 124 E Principals Office 237 SF 6 6-10 years FΑ 7 Lighting - Lay-in 124 E Principals Office 6-10 years 4 Power Distribution 124 E Principals Office 6 FΑ 7 10+ years SF Walls - Plaster/Drywall 124 E Principals Office 640 6 10+ years SF 7 Ceiling - Lay-in 124 G Vault 130 10+ years Doors - Wood Doors inclu hw 124 G Vault 1 EΑ 7 10+ years Floor - Tile SF 124 G Vault 130 7 10+ years Lighting - Lay-in 124 G Vault 2 EΑ 7 6-10 years Power Distribution 124 G Vault 6 EΑ 7 10+ vears SF Walls - Concrete Block 124 G Vault 80 7 10+ years 400 SF 7 Walls - Plaster/Drywall 124 G Vault 10+ years Ceiling - Lay-in 124 Main Office 810 SF 7 10+ years SF Doors - Side-lite 124 Main Office 7 8 10+ years







Category: Room **Building: Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Doors - Wood Doors inclu hw 124 Main Office EΑ 10+ vears 7 630 SF 6-10 years Floor - Carpet 124 Main Office 6 Floor - Terrazzo 124 Main Office 180 SF 7 10+ years EΑ 7 Lighting - Chandelier, Incandescent 124 Main Office 15 6-10 years 7 Lighting - Lay-in 124 Main Office 6 EΑ 6-10 years Power Distribution 7 124 Main Office 40 EΑ 10+ years Walls - Plaster/Drywall SF 124 Main Office 1,010 6 10+ years SF Walls - Structural Glazed Tile 124 Main Office 130 7 10+ years Ceiling - Lav-in 125 A Kitchen Office 130 SF 7 10+ years Doors - Steel Doors incl hw EΑ 7 10+ years 125 A Kitchen Office 1 Floor - Tile 125 A Kitchen Office 130 SF 6 10+ years Lighting - Lay-in 125 A Kitchen Office 2 EΑ 7 6-10 years Power Distribution EΑ 7 125 A Kitchen Office 4 10+ years SF 7 Walls - Concrete Block 125 A Kitchen Office 460 10+ years SF 7 Ceiling - Lay-in 125 D Engineer's Office 165 10+ years Doors - Steel Doors incl hw FΑ 7 125 D Engineer's Office 1 10+ years SF 7 Floor - Concrete Epoxy/ Painted 125 D Engineer's Office 165 10+ years Lighting - Lay-in 125 D Engineer's Office 2 EΑ 7 6-10 years Power Distribution 125 D Engineer's Office 6 EΑ 7 10+ vears Walls - Concrete Block 125 D Engineer's Office 520 SF 7 10+ years Ceiling - Lay-in 126 A Vault is Office 130 SF 7 10+ years Doors - Wood Doors inclu hw 7 10+ years 126 A Vault is Office 1 EΑ Floor - Tile SF 126 A Vault is Office 130 6 10+ years 7 Lighting - Lay-in 126 A Vault is Office FΑ 6-10 years 4 Power Distribution 6 EΑ 7 126 A Vault is Office 10+ years SF Walls - Concrete Block 126 A Vault is Office 50 7 10+ years SF Walls - Plaster/Drywall 126 A Vault is Office 480 6 10+ years Ceiling - Lay-in 220 SF 7 126 C Conference Room 10+ years Doors - Wood Doors inclu hw 126 C Conference Room 1 EΑ 7 10+ years Floor - Carpet 126 C Conference Room 220 SF 6 6-10 years Lighting - Lay-in 126 C Conference Room FΑ 7 6-10 years 6 Power Distribution 126 C Conference Room 6 EΑ 7 10+ vears SF 7 Walls - Plaster/Drywall 126 C Conference Room 600 10+ years Ceiling - Lav-in 126 D SF 7 10+ years 140 Doors - Wood Doors inclu hw 7 126 D 1 EΑ 10+ years SF Floor - Carpet 126 D 140 6 6-10 years Lighting - Lay-in 126 D 4 EΑ 7 6-10 years Power Distribution 6 126 D EΑ 7 10+ years Walls - Plaster/Drywall 126 D 480 SF 7 10+ years SF Ceiling - Lav-in 126 E Office 140 7 10+ years Doors - Wood Doors inclu hw 126 E Office EΑ 7 10+ years 1 126 E Office SF Floor - Carpet 140 6 6-10 years Lighting - Lay-in 126 E Office EΑ 7 6-10 years Power Distribution 6 7 126 E Office EΑ 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Walls - Plaster/Drywall 126 E Office 480 SF 10+ vears 6 126 F Office SF 7 Ceiling - Lav-in 140 10+ years Doors - Wood Doors inclu hw 126 F Office FΑ 7 10+ years 1 Floor - Carpet SF 126 F Office 140 6 6-10 years 7 Lighting - Lay-in 126 F Office 3 EΑ 6-10 years 5 Lighting - Lay-in 126 F Office 1 EΑ 1-2 years Not working Power Distribution 126 F Office 6 EΑ 7 10+ years Walls - Plaster/Drywall SF 126 F Office 480 6 10+ years SF Ceiling - Lay-in 126 G Office Room 220 7 10+ years Doors - Wood Doors inclu hw 126 G Office Room EΑ 7 10+ years 1 Floor - Carpet 126 G Office Room 220 SF 6 6-10 years Lighting - Lay-in 126 G Office Room 8 EΑ 7 6-10 years Power Distribution 6 EΑ 7 126 G Office Room 10+ years SF Walls - Plaster/Drywall 126 G Office Room 600 6 10+ years Ceiling - Lay-in SF 7 126 Main East Office 810 10+ years Doors - Wood Doors inclu hw FΑ 7 126 Main East Office 1 10+ years 630 SF Floor - Carpet 126 Main East Office 6 6-10 years SF Floor - Terrazzo 126 Main East Office 180 7 10+ years Lighting - Chandelier, Incandescent 126 Main East Office 8 EΑ 7 6-10 years Lighting - Lay-in 126 Main East Office 6 EΑ 7 6-10 years Power Distribution 126 Main East Office 40 EΑ 7 10+ years 126 Main East Office SF Walls - Plaster/Drywall 1,010 6 10+ years Walls - Structural Glazed Tile SF 7 126 Main East Office 130 10+ years SF 7 Ceiling - Exposed 127B Recycling 265 10+ years Doors - Steel Doors incl hw 127B Recycling EΑ 7 1 10+ years SF Floor - Concrete 127B Recycling 265 7 10+ years Lighting - Pendent/Surface 127B Recycling 3 EΑ 7 6-10 years Walls - Concrete Block 127B Recycling 990 SF 7 10+ years Ceiling - Lay-in 128 East Workroom / Mailboxes SF 424 7 10+ years Doors - Wood Doors inclu hw 128 East Workroom / Mailboxes 4 EΑ 7 10+ years SF Floor - Tile 128 East Workroom / Mailboxes 424 7 10+ vears Lighting - Lav-in 128 East Workroom / Mailboxes 6 EΑ 7 6-10 years 6 7 10+ years Power Distribution 128 East Workroom / Mailboxes FΑ Storage/ Closet 128 East Workroom / Mailboxes 40 SF 7 10+ years Walls - Plaster/Drywall SF 7 128 East Workroom / Mailboxes 678 10+ years Work SInk EΑ 7 128 East Workroom / Mailboxes 10+ years 1 SF Ceiling - Lay-in 130 A Storage 446 7 10+ years Doors - Steel Doors incl hw 130 A Storage EΑ 7 10+ years SF Floor - Concrete Epoxy/ Painted 130 A Storage 446 7 10+ years EΑ Lighting - Lav-in 130 A Storage 6 7 6-10 years Power Distribution 130 A Storage 8 EΑ 7 10+ years SF 7 Walls - Concrete Block 130 A Storage 211 10+ years Walls - Plaster/Drywall 130 A Storage 635 SF 7 10+ years SF Ceiling - Lay-in 130 Bookstore 242 7 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Wood Doors inclu hw 130 Bookstore EΑ 10+ vears 7 242 SF Floor - Tile 130 Bookstore 6 10+ years Lighting - Lay-in 130 Bookstore 4 FΑ 7 6-10 years Power Distribution 6 EΑ 7 130 Bookstore 10+ years SF Walls - Concrete Block 130 Bookstore 114 7 10+ years SF Walls - Plaster/Drywall 130 Bookstore 344 6 10+ years Ceiling - Lay-in SF 7 132 B Workroom/Lab 75 10+ years Doors - Wood Doors inclu hw 132 B Workroom/Lab 1 EΑ 7 10+ years Floor - Terrazzo 132 B Workroom/Lab 75 SF 7 10+ years Lighting - Lav-in FΑ 7 6-10 years 132 B Workroom/Lab 1 Power Distribution 132 B Workroom/Lab 6 EΑ 7 10+ years Walls - Plaster/Drywall 132 B Workroom/Lab 120 SF 7 10+ years Work SInk EΑ 7 132 B Workroom/Lab 1 10+ years SF 7 Ceiling - Lay-in 132 D Exam Room 3 190 10+ years Doors - Wood Doors inclu hw EΑ 7 132 D Exam Room 3 10+ years 1 Floor - Tile 190 SF 7 132 D Exam Room 3 10+ years EΑ 7 Lighting - Lav-in 132 D Exam Room 3 3 6-10 years Power Distribution 132 D Exam Room 3 6 EΑ 7 10+ years Walls - Plaster/Drvwall SF 132 D Exam Room 3 560 7 10+ years Work SInk 132 D Exam Room 3 1 EΑ 7 10+ years Ceiling - Lay-in 132 E Exam Room 2 110 SF 7 10+ years Doors - Wood Doors inclu hw 132 E Exam Room 2 7 10+ years 1 EΑ Floor - Tile SF 7 132 E Exam Room 2 110 10+ years 7 Lighting - Lay-in 132 E Exam Room 2 2 FΑ 6-10 years 6 EΑ 7 Power Distribution 132 E Exam Room 2 10+ years SF Walls - Plaster/Drywall 132 E Exam Room 2 420 7 10+ years Work SInk 132 E Exam Room 2 EΑ 7 10+ years 1 110 SF 7 Ceiling - Lay-in 132 F Exam Room 1 10+ years Doors - Wood Doors inclu hw 132 F Exam Room 1 1 EΑ 7 10+ years Floor - Tile 132 F Exam Room 1 110 SF 7 10+ years Lighting - Lay-in 132 F Exam Room 1 2 FΑ 7 6-10 years Power Distribution 132 F Exam Room 1 6 EΑ 7 10+ years SF Walls - Plaster/Drywall 132 F Exam Room 1 420 7 10+ years Work SInk 132 F Exam Room 1 FΑ 7 10+ years 1 SF 7 Ceiling - Lay-in 132 G Counselor 140 10+ years Doors - Wood Doors inclu hw EΑ 7 132 G Counselor 10+ years 1 SF Floor - Carpet 132 G Counselor 140 6 6-10 years Lighting - Lay-in EΑ 7 132 G Counselor 2 6-10 years Power Distribution 132 G Counselor 6 EΑ 7 10+ years SF Walls - Plaster/Drywall 132 G Counselor 480 7 10+ years Ceiling - Lay-in SF 132 H Counselor 140 7 10+ years Doors - Wood Doors inclu hw FΑ 7 132 H Counselor 10+ years 1 Floor - Carpet 132 H Counselor 140 SF 6 6-10 years EΑ Lighting - Lay-in 132 H Counselor 2 7 6-10 years







Building: Main Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Power Distribution 132 H Counselor 6 EΑ 10+ vears 7 480 SF 7 Walls - Plaster/Drywall 132 H Counselor 10+ years Ceiling - Lav-in 132 I Counselor 140 SF 7 10+ years Doors - Wood Doors inclu hw EΑ 7 132 I Counselor 10+ years SF Floor - Carpet 132 I Counselor 140 6 6-10 years 7 Lighting - Lay-in 132 I Counselor 2 EΑ 6-10 years Power Distribution 132 I Counselor 6 EΑ 7 10+ years SF Walls - Plaster/Drywall 132 I Counselor 480 7 10+ years SF Ceiling - Lay-in 132 Nurses Office (Suite) 1,065 7 10+ years SF Doors - Side-lite 132 Nurses Office (Suite) 32 7 10+ years Doors - Wood Doors inclu hw 132 Nurses Office (Suite) 2 EΑ 7 10+ years Floor - Terrazzo 132 Nurses Office (Suite) 1.065 SF 7 10+ years 132 Nurses Office (Suite) 7 6-10 years Lighting - Lay-in 10 EΑ 7 Lighting - Lay-in 132 Nurses Office (Suite) 9 EΑ 6-10 years Power Distribution 132 Nurses Office (Suite) 10 7 EΑ 10+ years SF 7 Storage/ Closet 132 Nurses Office (Suite) 85 10+ years SF 7 Walls - Concrete Block 132 Nurses Office (Suite) 520 10+ years SF Walls - Plaster/Drywall 132 Nurses Office (Suite) 3.010 7 10+ years SF Ceiling - Lay-in 200A Attendance/Enrollment office 400 7 10+ years Doors - Wood Doors inclu hw 200A Attendance/Enrollment office 1 EΑ 7 10+ years Floor - Tile 200A Attendance/Enrollment office 400 SF 7 10+ years 7 Lighting - Lay-in 200A Attendance/Enrollment office 6 EΑ 6-10 years 7 Power Distribution 200A Attendance/Enrollment office 34 EΑ 10+ years SF 7 Storage/ Closet 200A Attendance/Enrollment office 105 10+ years Walls - Concrete Block SF 7 200A Attendance/Enrollment office 171 10+ years SF Walls - Plaster/Drywall 200A Attendance/Enrollment office 691 7 10+ years Ceiling - Plaster/Drywall SF 200B-2 Kiln room 87 7 10+ years Doors - Steel Doors incl hw EΑ 7 200B-2 Kiln room 1 10+ years SF Floor - Concrete Epoxy/ Painted 200B-2 Kiln room 87 7 10+ years Lighting - Lay-in 200B-2 Kiln room 2 EΑ 7 6-10 years Power Distribution 200B-2 Kiln room 3 FΑ 7 10+ vears Walls - Concrete Block 200B-2 Kiln room 178 SF 7 10+ years SF 7 Walls - Plaster/Drywall 142 200B-2 Kiln room 10+ years Ceiling - Plaster/Drywall 200C Area of Rescue assistance 28 SF 7 10+ years Doors - Steel Doors incl hw 7 200C Area of Rescue assistance 1 EΑ 10+ years SF 7 Floor - Tile 200C Area of Rescue assistance 28 10+ years Lighting - Pendent/Surface 200C Area of Rescue assistance 1 EΑ 7 6-10 years Walls - Concrete Block 225 SF 200C Area of Rescue assistance 7 10+ years SF Ceiling - Plaster/Drywall 200G area of rescue assistance 28 7 10+ years Doors - Steel Doors incl hw 200G area of rescue assistance 1 EΑ 7 10+ years Floor - Tile 200G area of rescue assistance 28 SF 7 10+ years FΑ 7 Lighting - Lay-in 200G area of rescue assistance 6-10 years 1 Power Distribution 200G area of rescue assistance 2 EΑ 7 10+ years Walls - Concrete Block SF 200G area of rescue assistance 125 7 10+ years

Campus Name: Goode HS Page : 19 of 60 Assessment Date: 04/16/2024







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Walls - Plaster/Drywall 200G area of rescue assistance 100 SF 10+ vears 7 200G-2 office in room 200G SF 7 Ceiling - Lav-in 89 10+ years Doors - Side-lite 200G-2 office in room 200G 10 SF 7 10+ years Doors - Wood Doors inclu hw EΑ 7 200G-2 office in room 200G 1 10+ years SF Floor - Carpet 200G-2 office in room 200G 89 7 6-10 years 2 EΑ 7 Lighting - Lay-in 200G-2 office in room 200G 6-10 years Power Distribution 200G-2 office in room 200G EΑ 7 4 10+ years SF Walls - Plaster/Drywall 200G-2 office in room 200G 305 7 10+ years Ceiling - Lay-in 200H-2 Practice room 101 SF 7 10+ years SF Doors - Side-lite 7 10+ years 200H-2 Practice room 10 Doors - Wood Doors inclu hw 200H-2 Practice room EΑ 7 10+ years 1 Floor - Carpet 200H-2 Practice room 101 SF 7 6-10 years 2 EΑ 7 6-10 years Lighting - Lay-in 200H-2 Practice room 7 Power Distribution 200H-2 Practice room 6 EΑ 10+ years 54 SF 7 Walls - Concrete Block 200H-2 Practice room 10+ years 324 SF Walls - Plaster/Drywall 200H-2 Practice room 7 10+ years SF Ceiling - Lay-in 200H-3 Practice room 97 7 10+ years SF Doors - Side-lite 200H-3 Practice room 10 7 10+ years Doors - Wood Doors inclu hw EΑ 7 10+ years 200H-3 Practice room 1 Floor - Carpet 200H-3 Practice room 97 SF 7 6-10 years Lighting - Lay-in 2 EΑ 7 6-10 years 200H-3 Practice room 7 Power Distribution 200H-3 Practice room 6 EΑ 10+ years SF 7 Walls - Concrete Block 200H-3 Practice room 60 10+ years SF Walls - Plaster/Drywall 200H-3 Practice room 320 7 10+ years Ceiling - Lay-in SF 7 200H-4 Practice room 138 10+ years SF Doors - Side-lite 200H-4 Practice room 10 7 10+ years Doors - Wood Doors inclu hw 200H-4 Practice room EΑ 7 10+ years 1 Floor - Carpet 138 SF 7 6-10 years 200H-4 Practice room 200H-4 Practice room Lighting - Lay-in 2 EΑ 7 6-10 years Power Distribution 200H-4 Practice room 6 EΑ 7 10+ years Walls - Concrete Block 200H-4 Practice room 87 SF 7 10+ years SF Walls - Plaster/Drywall 200H-4 Practice room 347 7 10+ years SF 7 Ceiling - Lay-in 90 200H-6 Office in 200H 10+ years Doors - Transom Window 10 SF 7 10+ years 200H-6 Office in 200H 7 Doors - Wood Doors inclu hw 200H-6 Office in 200H 1 EΑ 10+ years SF 7 Floor - Carpet 200H-6 Office in 200H 90 6-10 years Lighting - Lay-in 200H-6 Office in 200H 2 EΑ 7 6-10 years Power Distribution 200H-6 Office in 200H 6 EΑ 7 10+ years Walls - Plaster/Drywall 200H-6 Office in 200H 280 SF 7 10+ years SF Ceiling - Plaster/Drywall 215 area of rescue assistance 51 7 10+ years Doors - Wood Doors inclu hw 215 area of rescue assistance 2 FΑ 7 10+ years SF 7 Floor - Tile 215 area of rescue assistance 51 10+ years Lighting - Pendent/Surface 215 area of rescue assistance 1 EΑ 7 10+ years Power Distribution 215 area of rescue assistance EΑ 7 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Walls - Concrete Block 215 area of rescue assistance 390 SF 10+ years 7 SF 7 Ceiling - Exposed 315 area of rescue assistance 51 10+ years Doors - Wood Doors inclu hw 315 area of rescue assistance FΑ 7 10+ years Floor - Tile SF 7 315 area of rescue assistance 51 10+ years Lighting - Pendent/Surface 315 area of rescue assistance EΑ 7 6-10 years 1 Power Distribution 2 7 315 area of rescue assistance EΑ 10+ years Walls - Concrete Block 390 SF 7 315 area of rescue assistance 10+ years SF Ceiling - Lay-in Rm 217 Attendance Office 295 7 10+ years Doors - Side-lite Rm 217 Attendance Office 12 SF 7 10+ years SF Doors - Transom Window 28 7 10+ years Rm 217 Attendance Office Doors - Wood Doors inclu hw Rm 217 Attendance Office 1 EΑ 7 10+ years Floor - Tile Rm 217 Attendance Office 295 SF 7 10+ years EΑ 7 6-10 years Lighting - Lay-in Rm 217 Attendance Office 4 Rm 217 Attendance Office 7 Power Distribution 16 EΑ 10+ years 5 SF 7 Storage/ Closet Rm 217 Attendance Office 10+ years 710 SF Walls - Plaster/Drywall Rm 217 Attendance Office 7 10+ years SF Walls - Structural Glazed Tile Rm 217 Attendance Office 44 7 10+ years Ceiling - Lay-in SF Rm 229 Prep Room 385 7 10+ years Doors - Side-lite SF Rm 229 Prep Room 12 7 10+ years Rm 229 Prep Room SF Doors - Transom Window 7 7 10+ years Doors - Wood Doors inclu hw Rm 229 Prep Room 1 EΑ 7 10+ years SF 7 Floor - Tile/Sheet Rm 229 Prep Room 385 10+ years 7 Lighting - Pendent/Surface Rm 229 Prep Room 5 EΑ 6-10 years 7 Power Distribution Rm 229 Prep Room 18 FΑ 10+ years Storage/ Closet Rm 229 Prep Room 30 SF 7 10+ years SF Walls - Concrete Block Rm 229 Prep Room 60 7 10+ years SF Walls - Plaster/Drywall Rm 229 Prep Room 660 7 10+ years Walls - Structural Glazed Tile Rm 229 Prep Room 38 SF 7 10+ years Work SInk Rm 229 Prep Room 1 EΑ 7 10+ years Ceiling - Lay-in Rm 233 Prep Room 385 SF 7 10+ years Doors - Side-lite SF Rm 233 Prep Room 12 7 10+ years Doors - Transom Window SF Rm 233 Prep Room 7 7 10+ years 7 Doors - Wood Doors inclu hw Rm 233 Prep Room 1 FΑ 10+ years Floor - Tile Rm 233 Prep Room 385 SF 7 10+ vears 7 Lighting - Pendent/Surface Rm 233 Prep Room 5 EΑ 6-10 years EΑ 7 Power Distribution Rm 233 Prep Room 18 10+ years SF Storage/ Closet Rm 233 Prep Room 30 7 10+ years Rm 233 Prep Room SF Walls - Concrete Block 60 7 10+ years SF Walls - Plaster/Drywall Rm 233 Prep Room 660 7 10+ years Work SInk Rm 233 Prep Room 1 EΑ 7 10+ years Ceiling - Lay-in Rm 317 Attendance Office 295 SF 7 10+ years Doors - Wood Doors inclu hw FΑ 7 Rm 317 Attendance Office 10+ years 1 Floor - Tile Rm 317 Attendance Office 295 SF 6 10+ years EΑ Lighting - Lay-in Rm 317 Attendance Office 4 7 6-10 years





| Catego | ry : Room | | Ві | uilding | : Main | | · • • • • • • • • • • • • • • • • • • • |
|--------|---|--------------------------------------|------------|----------|--------|------------------------|---|
| Carego | ., | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Power Distribution | Rm 317 Attendance Office | 14 | EΑ | 7 | 10+ years | |
| | Storage/ Closet | Rm 317 Attendance Office | 5 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Rm 317 Attendance Office | 710 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | Rm 317 Attendance Office | 30 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Rm 329 Prep Room | 385 | SF | 6 | 10+ years | |
| | Doors - Side-lite | Rm 329 Prep Room | 12 | SF | 6 | 10+ years | |
| | Doors - Transom Window | Rm 329 Prep Room | 7 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Rm 329 Prep Room | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Rm 329 Prep Room | 385 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Rm 329 Prep Room | 5 | EA | 7 | 6-10 years | |
| | Power Distribution | Rm 329 Prep Room | 16 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Rm 329 Prep Room | 60 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Rm 329 Prep Room | 660 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | Rm 329 Prep Room | 30 | SF | 7 | 10+ years | |
| | Work SInk | Rm 329 Prep Room | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | Rm 333 Prep Room | 385 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Rm 333 Prep Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Rm 333 Prep Room | 385 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Rm 333 Prep Room | 5 | EA | 7 | 6-10 years | |
| | Power Distribution | Rm 333 Prep Room | 16 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Rm 333 Prep Room | 110 660 | SF SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall Walls - Structural Glazed Tile | Rm 333 Prep Room Rm 333 Prep Room | | SF SF | 6 | 10+ years | |
| | Work Sink | Rm 333 Prep Room | 30 2 | EA | 6 7 | 10+ years 10+ years | |
| | WORK SILIK | KIII 333 FIEP KOOIII | 2 | EA | , | 10+ years | |
| Gymnas | ia | | | | | | |
| , | Bleacher Seating | 001 Gymnasia | 717 | EA | 7 | 10+ years | |
| | Ceiling - Exposed | 001 Gymnasia | 12,000 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 001 Gymnasia | 10 | EA | 7 | 10+ years | |
| | Floor - Tile | 001 Gymnasia | 3,620 | SF | 7 | 10+ years | |
| | Floor - Wood | 001 Gymnasia | 8,380 | SF | 7 | 10+ years | |
| | Lighting - Metal Halide/ High Pressure Sodium | 001 Gymnasia | 64 | EA | 7 | 6-10 years | |
| | Scoreboards | 001 Gymnasia | 2 | EA | 7 | 6-10 years | |
| | Sound System | 001 Gymnasia | 1 | EA | 7 | 6-10 years | |
| | Stage | 001 Gymnasia | 3,228 | SF | 6 | 10+ years | |
| | Stage Curtain | 001 Gymnasia | 5 | EA | 7 | 6-10 years | |
| | Stage Lift | 001 Gymnasia | 1 | EA | 7 | 10+ years | |
| | Stage Lighting System | 001 Gymnasia | 1 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 001 Gymnasia | 40 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 001 Gymnasia | 5,440 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 001 Gymnasia | 5,900 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 001 Gymnasia | 1,530 | SF | 7 | 10+ years | |





| Group Item - Type Location Quantity UOM Rank Replacement Comments Kitchen Ceiling - Lay-in 125 Kitchen 2,225 SF 7 10+ years Doors - Steel Doors incl hw 125 Kitchen 2 EA 7 10+ years Floor - Concrete Epoxy/ Painted 125 Kitchen 2,225 SF 7 10+ years Lighting - Lay-in 125 Kitchen 15 EA 7 6-10 years Serving Line 125 Kitchen 40 LF 7 10+ years Storage/ Closet 125 Kitchen 160 SF 7 10+ years Walls - Concrete Block 125 Kitchen 3,560 SF 7 10+ years | Catego | Category : Room | | | Building : Main | | | <u> </u> | | |
|--|----------|-------------------------------------|----------------------------------|----------|-----------------|------|-------------|--------------|--|--|
| Caling - Lay-in 125 Kitchen 2 | | | | | J | | Recommend | | | |
| Ceiling - Lay-in 125 Kitchen 2.25 SF 7 10 + years Floor - Steel Doors - Steel Doors incl hw 125 Kitchen 2.25 SF 7 10 + years Floor - Concrete Epoxyl Painted 125 Kitchen 2.25 SF 7 10 + years Floor - Concrete Epoxyl Painted 125 Kitchen 15 E 7 10 + years Serving Line 125 Kitchen 40 LF 7 10 + years Storage/ Closel 125 Kitchen 3.560 SF 7 10 + years Storage/ Closel 125 Kitchen 3.560 SF 7 10 + years Storage/ Closel 125 Kitchen 3.560 SF 7 10 + years Storage/ Closel 125 Kitchen 3.560 SF 7 10 + years Storage/ Closel 100 Library 365 SF 7 10 + years Storage/ Ceiling - Lay-in 100 Library 365 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 365 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 365 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 360 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 360 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 360 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 360 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 360 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 360 SF 7 10 + years Storage/ Ceiling - Splined 100 Library 360 SF 7 360 Years Storage/ Ceiling - Splined 360 SF 7 360 Years SF | Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Doors - Steel Doors incl hw | Kitchen | | | | | | | | | |
| Doors - Steel Doors incl hw | | Ceiling - Lav-in | 125 Kitchen | 2,225 | SF | 7 | 10+ vears | | | |
| Floor - Concrete Epoxy/ Painted 125 Kitchen 2,225 SF 7 10+ years Lighting - Lay-in 125 Kitchen 15 EA 7 6-10 years Serving Line 125 Kitchen 40 LF 7 10+ years 125 Kitchen 40 LF 7 40+ years | | | | | | | | | | |
| Lighting - Lay-in 125 Kitchen 15 | | | | | | | | | | |
| Serving Line | | | 125 Kitchen | | ĒA | 7 | | | | |
| Storage Closet 125 Kitchen 160 SF 7 10+ years 10+ years 125 Kitchen 3,560 SF 7 10+ years | | | 125 Kitchen | | LF | 7 | | | | |
| Library | | | 125 Kitchen | 160 | SF | 7 | • | | | |
| Library | | | 125 Kitchen | | | | | | | |
| Casework | | | | • | | | , | | | |
| Ceiling - Lay-in | Library | | | | | | | | | |
| Ceiling - Splined 100 Library 5,190 SF 7 10+ years 1 | | | | | | | | | | |
| Doors - Store Front 100 Library 2 EA 7 10+ years | | Ceiling - Lay-in | | | | | 10+ years | | | |
| Doors - Store Front 100 Library 2 EA 7 10+ years | | Ceiling - Splined | 100 Library | 5,190 | | | 10+ years | | | |
| Doors - Transom Window | | | 100 Library | | | | | | | |
| Floor - Carpet | | Doors - Store Front | | 2 | EA | 7 | 10+ years | | | |
| Floor - Terrazzo | | Doors - Transom Window | 100 Library | 40 | | 7 | 10+ years | | | |
| Lighting - Chandelier, Incandescent 100 Library 120 EA 7 6-10 years Lighting - Pendent/Surface 100 Library 1,790 SF 7 10+ years Walls - Masonry 100 Library 1,790 SF 7 10+ years Walls - Plaster/Drywall 100 Library 1,790 SF 7 10+ years Walls - Plaster/Drywall 100 Library 1,790 SF 7 10+ years Walls - Plaster/Drywall 100 Library 1,790 SF 7 10+ years Walls - Plaster/Drywall 100 EA Mens Locker Room 2,310 SF 7 10+ years Walls - Plaster/Drywall 006 C Mens Locker Room 2,310 SF 7 10+ years Walls - Plaster/Drywall 006 C Mens Locker Room 2,310 SF 7 10+ years Walls - Plaster/Drywall 006 C Mens Locker Room 2,130 SF 7 10+ years Walls - Plaster/Drywall Walls - Walls - Plaster/Drywall Walls - W | | Floor - Carpet | 100 Library | 3,255 | | 6 | 6-10 years | | | |
| Lighting - Pendent/Surface 100 Library 1,790 SF 7 10+ years 1,790 SF 7 1,990 SF 7 1,9 | | | | 2,300 | SF | 7 | 10+ years | | | |
| Walls - Masonry 100 Library 1,790 SF 7 10+ years Locker/Shower Room 2,310 SF 7 10+ years Accessories 006 C Mens Locker Room 2,310 SF 7 6-10 years Benches, ped mounted 006 C Mens Locker Room 160 LF 7 10+ years Ceiling - Plaster/Drywall 006 C Mens Locker Room 2,310 SF 7 10+ years Doors - Steel Doors incl hw 006 C Mens Locker Room 2 EA 7 10+ years Floor - Concrete Epoxy/ Painted 006 C Mens Locker Room 2,130 SF 7 10+ years Floor - Tille Ceramic/ Porcelain 006 C Mens Locker Room 180 SF 7 10+ years Floor Drain 006 C Mens Locker Room 180 SF 7 10+ years Hand Dryer 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room< | | Lighting - Chandelier, Incandescent | 100 Library | 3 | EA | 7 | | | | |
| Nalls - Plaster/Drywall 100 Library 1,790 SF 7 10+ years | | Lighting - Pendent/Surface | 100 Library | 120 | | 7 | 6-10 years | | | |
| Accessories | | | | 1,790 | | 7 | 10+ years | | | |
| Accessories 006 C Mens Locker Room 2,310 SF 7 6-10 years Benches, ped mounted 006 C Mens Locker Room 160 LF 7 10+ years Ceiling - Plaster/Drywall 006 C Mens Locker Room 2,310 SF 7 10+ years Doors - Steel Doors incl hw 006 C Mens Locker Room 2 EA 7 10+ years Floor - Concrete Epoxy/ Painted 006 C Mens Locker Room 2 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 006 C Mens Locker Room 180 SF 7 10+ years Floor Drain 006 C Mens Locker Room 6 EA 7 10+ years Floor Drain 006 C Mens Locker Room 2 EA 7 10+ years Hand Dryer 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 2 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 2 EA 7 10+ years Showers | | Walls - Plaster/Drywall | 100 Library | 1,790 | SF | 7 | 10+ years | | | |
| Accessories 006 C Mens Locker Room 2,310 SF 7 6-10 years Benches, ped mounted 006 C Mens Locker Room 160 LF 7 10+ years Ceiling - Plaster/Drywall 006 C Mens Locker Room 2,310 SF 7 10+ years Doors - Steel Doors incl hw 006 C Mens Locker Room 2 EA 7 10+ years Floor - Concrete Epoxy/ Painted 006 C Mens Locker Room 2 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 006 C Mens Locker Room 180 SF 7 10+ years Floor Drain 006 C Mens Locker Room 6 EA 7 10+ years Floor Drain 006 C Mens Locker Room 2 EA 7 10+ years Hand Dryer 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 2 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 2 EA 7 10+ years Showers | Lookor/C | hower Doom | | | | | | | | |
| Benches, ped mounted 006 C Mens Locker Room 160 LF 7 10+ years Ceiling - Plaster/Drywall 006 C Mens Locker Room 2,310 SF 7 10+ years Doors - Steel Doors incl hw 006 C Mens Locker Room 2,310 SF 7 10+ years Floor - Concrete Epoxy/ Painted 006 C Mens Locker Room 2,130 SF 7 10+ years Floor - Tile Ceramic/ Porcelain 006 C Mens Locker Room 180 SF 7 10+ years Floor Drain 006 C Mens Locker Room 180 SF 7 10+ years Floor Drain 006 C Mens Locker Room 6 EA 7 10+ years Hand Dryer 006 C Mens Locker Room 2 EA 7 6-10 years Layatory 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 2 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 2 EA 7 10+ years Water Closet 006 C Mens Locker Room 310 SF 7 10+ years | LUCKEI/S | | 006 C Mons Locker Poem | 2 210 | QE. | 7 | 6 10 years | | | |
| Ceiling - Plaster/Drywall 006 C Mens Locker Room 2,310 SF 7 10+ years Doors - Steel Doors incl hw 006 C Mens Locker Room 2 EA 7 10+ years Floor - Concrete Epoxy/ Painted 006 C Mens Locker Room 2,130 SF 7 10+ years Floor - Tile Ceramic/ Porcelain 006 C Mens Locker Room 180 SF 7 10+ years Floor Drain 006 C Mens Locker Room 6 EA 7 10+ years Hand Dryer 006 C Mens Locker Room 2 EA 7 10+ years Lavatory 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 4 EA 6 2-5 years Not well lit Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 332 EA 7 10+ years Uri | | | | | | | • | | | |
| Doors - Steel Doors incl hw 006 C Mens Locker Room 2 EA 7 10+ years Floor - Concrete Epoxy/ Painted 006 C Mens Locker Room 2,130 SF 7 10+ years Floor - Tile Ceramic/ Porcelain 006 C Mens Locker Room 180 SF 7 10+ years Floor Drain 006 C Mens Locker Room 6 EA 7 10+ years Floor Drain 006 C Mens Locker Room 6 EA 7 10+ years Lavatory 006 C Mens Locker Room 2 EA 7 6-10 years Lavatory 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 4 EA 6 2-5 years Not well lit Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 2 EA 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 2 EA 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years 1 | | | | | | | , | | | |
| Floor - Concrete Epoxy/ Painted 006 C Mens Locker Room 2,130 SF 7 10+ years | | | | , | | | • | | | |
| Floor - Tile Ceramic/ Porcelain 006 C Mens Locker Room 180 SF 7 10+ years Floor Drain 006 C Mens Locker Room 6 EA 7 10+ years Hand Dryer 006 C Mens Locker Room 2 EA 7 6-10 years Lavatory 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 4 EA 6 2-5 years Not well lit Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 2 EA 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | | | | | | | |
| Floor Drain 006 C Mens Locker Room 6 EA 7 10+ years Hand Dryer 006 C Mens Locker Room 2 EA 7 6-10 years Lavatory 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 4 EA 6 2-5 years Not well lit Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 2 EA 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | , | | - | | | | |
| Hand Dryer Lavatory 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 4 EA 6 2-5 years Not well lit Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | | | - | | | | |
| Lavatory 006 C Mens Locker Room 2 EA 7 10+ years Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 4 EA 6 2-5 years Not well lit Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | | | | • | | | |
| Lighting - Lay-in 006 C Mens Locker Room 21 EA 7 6-10 years Lighting - Lay-in 006 C Mens Locker Room 4 EA 6 2-5 years Not well lit Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | | | | | | | |
| Lighting - Lay-in 006 C Mens Locker Room 4 EA 6 2-5 years Not well lit Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | | | | • | | | |
| Partitions 006 C Mens Locker Room 2 EA 7 10+ years Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | | | | | Not wall lit | | |
| Showers 006 C Mens Locker Room 6 EA 7 10+ years Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | - | | - | | Not well lit | | |
| Student Lockers - Two Tier 006 C Mens Locker Room 332 EA 7 10+ years Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | | | - | | | | |
| Urinals 006 C Mens Locker Room 1 EA 7 10+ years Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | - | | - | | | | |
| Walls - Concrete Block 006 C Mens Locker Room 5,480 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | | | | • | | | |
| Walls - Tile Ceramic/ Porcelain 006 C Mens Locker Room 310 SF 7 10+ years Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | = | | | | | | |
| Water Closet 006 C Mens Locker Room 2 EA 7 10+ years | | | | , | | | | | | |
| , | | | | | | | | | | |
| Accessories Out - I Coacii Lockei & Ollowei 100 OF 1 0-10 years | | | | | | | | | | |
| | | A0063301163 | Joon - I Coacii Lockei & Silowei | 130 | OI. | , | 0-10 years | | | |





| Catego | Category : Room | | В | Building : Main | | | | | |
|--------|-------------------------------------|-------------------------------|----------|-----------------|------|---|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Benches, ped mounted | 006F- 1 Coach Locker & Shower | 8 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 006F- 1 Coach Locker & Shower | 150 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 006F- 1 Coach Locker & Shower | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 006F- 1 Coach Locker & Shower | 150 | SF | 7 | 10+ years | | | |
| | Floor Drain | 006F- 1 Coach Locker & Shower | 2 | EA | 7 | 10+ years | | | |
| | Lavatory | 006F- 1 Coach Locker & Shower | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Chandelier, Incandescent | 006F- 1 Coach Locker & Shower | 1 | EΑ | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 006F- 1 Coach Locker & Shower | 2 | EA | 7 | 6-10 years | | | |
| | Showers | 006F- 1 Coach Locker & Shower | 1 | EΑ | 7 | 10+ years | | | |
| | Student Lockers - One Tier | 006F- 1 Coach Locker & Shower | 8 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | 006F- 1 Coach Locker & Shower | 119 | SF | 7 | 10+ years | | | |
| | Walls - Tile Ceramic/ Porcelain | 006F- 1 Coach Locker & Shower | 163 | SF | 7 | 10+ years | | | |
| | Water Closet | 006F- 1 Coach Locker & Shower | 1 | EA | 7 | 10+ years | | | |
| | Accessories | 008 A Womens Locker/Shower | 167 | SF | 7 | 6-10 years | | | |
| | | Room | | | | , | | | |
| | Ceiling - Plaster/Drywall | 008 A Womens Locker/Shower | 167 | SF | 7 | 10+ years | | | |
| | , i | Room | | | | , , , , , | | | |
| | Doors - Wood Doors inclu hw | 008 A Womens Locker/Shower | 1 | EA | 7 | 10+ years | | | |
| | | Room | • | | | , | | | |
| | Floor - Terrazzo | 008 A Womens Locker/Shower | 167 | SF | 7 | 10+ years | | | |
| | | Room | | - | | , | | | |
| | Floor Drain | 008 A Womens Locker/Shower | 1 | EA | 7 | 10+ years | | | |
| | | Room | | | | , , , , , | | | |
| | Hand Dryer | 008 A Womens Locker/Shower | 2 | EA | 7 | 6-10 years | | | |
| | , | Room | | | | , | | | |
| | Lavatory | 008 A Womens Locker/Shower | 2 | EA | 7 | 10+ years | | | |
| | , | Room | | | | , | | | |
| | Lighting - Lay-in | 008 A Womens Locker/Shower | 4 | EA | 7 | 6-10 years | | | |
| | 3 3 , | Room | | | | , | | | |
| | Partitions | 008 A Womens Locker/Shower | 3 | EA | 7 | 10+ years | | | |
| | | Room | | | | , , , , , , | | | |
| | Walls - Structural Glazed Tile | 008 A Womens Locker/Shower | 490 | SF | 7 | 10+ years | | | |
| | | Room | | | | , | | | |
| | Water Closet | 008 A Womens Locker/Shower | 3 | EA | 7 | 10+ years | | | |
| | | Room | | | | , , , , , , | | | |
| | Accessories | 008 C Womens Locker Room | 2,310 | SF | 7 | 6-10 years | | | |
| | Benches, ped mounted | 008 C Womens Locker Room | 160 | LF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 008 C Womens Locker Room | 2,310 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 008 C Womens Locker Room | 4 | EA | 7 | 10+ years | | | |
| | Floor - Concrete Epoxy/ Painted | 008 C Womens Locker Room | 2,130 | SF | 7 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 008 C Womens Locker Room | 180 | SF | 7 | 10+ years | | | |
| | Floor Drain | 008 C Womens Locker Room | 7 | EA | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 008 C Womens Locker Room | 20 | ΕA | 7 | 6-10 years | | | |
| | Showers | 008 C Womens Locker Room | 6 | ΕA | 7 | 10+ years | | | |
| | | | · · | | - | - , | | | |





| Category : Room | | | Building : Main | | | | | | |
|-----------------|---------------------------------|------------------------------|-----------------|-----|------|-------------|-------------|--|--|
| _ | | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Student Lockers - Two Tier | 008 C Womens Locker Room | 335 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | 008 C Womens Locker Room | 5,480 | SF | 7 | 10+ years | | | |
| | Walls - Tile Ceramic/ Porcelain | 008 C Womens Locker Room | 310 | SF | 7 | 10+ years | | | |
| | Accessories | 008 F-1 Women Coach Locker & | 167 | SF | 7 | 6-10 years | | | |
| | | Shower | | | | | | | |
| | Benches, ped mounted | 008 F-1 Women Coach Locker & | 8 | LF | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Ceiling - Lay-in | 008 F-1 Women Coach Locker & | 167 | SF | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Doors - Steel Doors incl hw | 008 F-1 Women Coach Locker & | 1 | EA | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Floor - Tile Ceramic/ Porcelain | 008 F-1 Women Coach Locker & | 167 | SF | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Floor Drain | 008 F-1 Women Coach Locker & | 2 | EA | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Lavatory | 008 F-1 Women Coach Locker & | 1 | EA | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Lighting - Lay-in | 008 F-1 Women Coach Locker & | 2 | EA | 7 | 6-10 years | | | |
| | | Shower | | | | | | | |
| | Showers | 008 F-1 Women Coach Locker & | 1 | EA | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Student Lockers - One Tier | 008 F-1 Women Coach Locker & | 8 | EA | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Walls - Concrete Block | 008 F-1 Women Coach Locker & | 119 | SF | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Walls - Tile Ceramic/ Porcelain | 008 F-1 Women Coach Locker & | 163 | SF | 7 | 10+ years | | | |
| | | Shower | | | | | | | |
| | Water Closet | 008 F-1 Women Coach Locker & | 1 | EA | 7 | 10+ years | | | |
| | | Shower | | _ | | | | | |
| | Accessories | 009 Girls Locker Room | 920 | SF | 7 | 6-10 years | | | |
| | Benches, ped mounted | 009 Girls Locker Room | 80 | LF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 009 Girls Locker Room | 920 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 009 Girls Locker Room | 2 | EA | 7 | 10+ years | | | |
| | Floor - Concrete Epoxy/ Painted | 009 Girls Locker Room | 920 | SF | 7 | 10+ years | | | |
| | Floor Drain | 009 Girls Locker Room | 6 | EA | 7 | 10+ years | | | |
| | Hand Dryer | 009 Girls Locker Room | 3 | EA | 7 | 6-10 years | | | |
| | Lavatory | 009 Girls Locker Room | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 009 Girls Locker Room | 13 | EA | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 009 Girls Locker Room | 1 | EA | 5 | 1-2 years | Not working | | |
| | Partitions | 009 Girls Locker Room | 3 | EA | 7 | 10+ years | | | |
| | Showers | 009 Girls Locker Room | 5 | EA | 7 | 10+ years | | | |
| | Student Lockers - One Tier | 009 Girls Locker Room | 30 | EA | 7 | 10+ years | | | |
| | Student Lockers - Two Tier | 009 Girls Locker Room | 78 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | 009 Girls Locker Room | 2,280 | SF | 7 | 10+ years | | | |
| | | | | | | | | | |





| Catego | Category : Room | | В | uilding | : Main | • | 001 0 Homan Avenue, Onicago, le 00032 |
|---------|---------------------------------|------------------------------|----------|---------|--------|-------------|---------------------------------------|
| | , | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Tile Ceramic/ Porcelain | 009 Girls Locker Room | 360 | SF | 7 | 10+ years | |
| | Water Closet | 009 Girls Locker Room | 3 | EA | 7 | 10+ years | |
| | Accessories | 015 Boys Locker Room | 920 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | 015 Boys Locker Room | 80 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 015 Boys Locker Room | 920 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 015 Boys Locker Room | 2 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 015 Boys Locker Room | 920 | SF | 7 | 10+ years | |
| | Floor Drain | 015 Boys Locker Room | 6 | EA | 7 | 10+ years | |
| | Hand Dryer | 015 Boys Locker Room | 3 | EA | 7 | 6-10 years | |
| | Lavatory | 015 Boys Locker Room | 3 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 015 Boys Locker Room | 15 | EA | 7 | 6-10 years | |
| | Partitions | 015 Boys Locker Room | 2 | EA | 7 | 10+ years | |
| | Showers | 015 Boys Locker Room | 6 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | 015 Boys Locker Room | 30 | EA | 7 | 10+ years | |
| | Student Lockers - Two Tier | 015 Boys Locker Room | 88 | EA | 7 | 10+ years | |
| | Urinals | 015 Boys Locker Room | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 015 Boys Locker Room | 2,280 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 015 Boys Locker Room | 360 | SF | 7 | 10+ years | |
| | Water Closet | 015 Boys Locker Room | 2 | EA | 7 | 10+ years | |
| | Accessories | 132 C Unisex Restroom/Shower | 117 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | 132 C Unisex Restroom/Shower | 1 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 132 C Unisex Restroom/Shower | 117 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 132 C Unisex Restroom/Shower | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 132 C Unisex Restroom/Shower | 117 | SF | 7 | 10+ years | |
| | Floor Drain | 132 C Unisex Restroom/Shower | 2 | EA | 7 | 10+ years | |
| | Lavatory | 132 C Unisex Restroom/Shower | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 132 C Unisex Restroom/Shower | 1 | EA | 7 | 10+ years | |
| | Showers | 132 C Unisex Restroom/Shower | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 132 C Unisex Restroom/Shower | 250 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 132 C Unisex Restroom/Shower | 170 | SF | 7 | 10+ years | |
| | Water Closet | 132 C Unisex Restroom/Shower | 1 | EA | 7 | 10+ years | |
| Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | 121 Cafeteria | 5,586 | SF | 7 | 10+ years | |
| | Ceiling - Lay in | 121 Cafeteria | 24 | SF | 4 | 1-2 years | Stained tile |
| | Doors - Wood Doors inclu hw | 121 Cafeteria | 4 | EA | 7 | 10+ years | Starriod tile |
| | Floor - Terrazzo | 121 Cafeteria | 5,610 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 121 Cafeteria | 116 | EA | 7 | 6-10 years | |
| | Walls - Metal Panel | 121 Cafeteria | 8,091 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 121 Cafeteria | 435 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 121 Cafeteria | 450 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 123 Servery Line | 1,046 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 123 Servery Line | 1,040 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 123 Servery Line | 1,046 | SF | 7 | 10+ years | |
| | . i.o Controlo Epoxy/ i aintou | 120 Colvery Line | 1,0-70 | 01 | , | ioi youis | |





| Category : Room | | | В | uilding | : Main | | |
|-----------------|----------------------------------|------------------|----------|----------|--------|-------------|--------------------------------------|
| _ | | | <u> </u> | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 123 Servery Line | 36 | EΑ | 7 | 6-10 years | |
| | Serving Line | 123 Servery Line | 50 | LF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 123 Servery Line | 1,673 | SF | 7 | 10+ years | |
| MDF ID | F | | | | | | |
| | Doors - Wood Doors inclu hw | 116 MDF_IDF | 1 | EA | 7 | 10+ years | |
| | Finishes | 116 MDF_IDF | 406 | SF | 7 | 10+ years | |
| | Other Cooling Unit | 116 MDF_IDF | 1 | EA | 4 | 1-2 years | Not in service, power needs updating |
| Machani | cal/ Service Rooms | | | | | | |
| леспаш | Janitor's Closet | 1st Floor | 350 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 45 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 45 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 80 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 80 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 54 | SF | 7 | 10+ years | |
| | | 1st Floor | 88 | SF | 7 | , | |
| | Storage Room | 1st Floor | 435 | SF | , 5 | 10+ years | |
| | Storage Room | 1st Floor | 350 | SF | 5 5 | 10+ years | |
| | Storage Room Janitor's Closet | 2nd Floor | 40 | SF | 5 7 | 10+ years | |
| | | | 13 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | | SF SF | | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 75 65 | SF SF | 7 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 36 | SF SF | | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | | | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 33 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 127 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 284 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 75 70 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 76 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 164 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 105 | SF | 7 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 39 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |





| Category : Room | | | В | | | | |
|-----------------|--|--|------------------------------|----------|--------|------------------------|----------------------|
| | | | Building : Main Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 45 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 45 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 68 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Janitor's Closet | Basement | 1,062 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 8,687 | SF | 7 | 10+ years | |
| | Storage Room | Basement | 85 | SF | 7 | 10+ years | |
| | Storage Room | Basement | 155 | SF | 7 | 10+ years | |
| | Storage Room | Basement | 3,478 | SF | 7 | 10+ years | |
| | Storage Room | Dasement | 3,470 | Oi | , | 10+ years | |
| Pool & N | atatorium | | | | | | |
| | Accessories | 007 Pool & Natatorium | 7,047 | SF | 7 | 6-10 years | |
| | Bleachers Seating/Plank Seating | 007 Pool & Natatorium | 14 | EΑ | 7 | 10+ years | |
| | Ceiling - Exposed | 007 Pool & Natatorium | 7,047 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 007 Pool & Natatorium | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 007 Pool & Natatorium | 7,047 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 007 Pool & Natatorium | 36 | EA | 7 | 6-10 years | |
| | Pool Basin | 007 Pool & Natatorium | 3,574 | SF | 7 | 10+ years | |
| | Pool Deck | 007 Pool & Natatorium | 1,313 | SF | 7 | 10+ years | |
| | Walls - Masonry | 007 Pool & Natatorium | 3,347 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 007 Pool & Natatorium | 10,042 | SF | 7 | 10+ years | |
| D . | | | | | | | |
| Restroon | n Accessories | 006 F Mens Restroom | 167 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 006 F Mens Restroom | 167 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 006 F Mens Restroom | 107 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 006 F Mens Restroom | 167 | SF | 7 | 10+ years | |
| | Floor Drain | 006 F Mens Restroom | 107 | EA | 7 | 10+ years | |
| | Hand Dryer | 006 F Mens Restroom | 2 | EA | 7 | 10+ years | |
| | Lavatory | 006 F Mens Restroom | 2 | EA | 7 | 10+ years | |
| | Lavatory Lighting - Lay-in | 006 F Mens Restroom | 4 | EA | 7 | , | |
| | Partitions | 006 F Mens Restroom | 2 | EA | 7 | 6-10 years | |
| | | | ∠ 1 | | 7 | 10+ years | |
| | Urinals | 006 F Mens Restroom | • | EΑ | | 10+ years | Looked when fluck ad |
| | Urinals Walls - Structural Glazed Tile | 006 F Mens Restroom 006 F Mens Restroom | 1 490 | EA SF | 6 7 | 1-2 years 10+ years | Leaked when flushed |
| | | | | | | | |







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Water Closet 006 F Mens Restroom 2 EΑ 10+ vears 7 200 SF 7 6-10 years Accessories 006 G Mens Restroom Ceiling - Plaster/Drywall 006 G Mens Restroom 200 SF 7 10+ years Floor - Concrete Epoxy/ Painted 200 SF 7 006 G Mens Restroom 10+ years Floor Drain 006 G Mens Restroom 1 FΑ 7 10+ years Hand Dryer 3 7 006 G Mens Restroom EΑ 6-10 years 3 EΑ 7 10+ years Lavatory 006 G Mens Restroom Lighting - Lay-in 006 G Mens Restroom 4 EΑ 7 6-10 years 2 **Partitions** 006 G Mens Restroom EΑ 7 10+ years Urinals 006 G Mens Restroom 1 FΑ 7 10+ years Walls - Concrete Block 006 G Mens Restroom 490 SF 7 10+ years Water Closet 006 G Mens Restroom 2 EΑ 7 10+ years Accessories 007A-1 Mens Coach Shower / Toilet 95 SF 7 6-10 years LF 7 **Benches** 007A-1 Mens Coach Shower / Toilet 4 10+ years Ceiling - Plaster/Drywall 007A-1 Mens Coach Shower / Toilet 95 SF 7 10+ years Doors - Steel Doors incl hw FΑ 7 007A-1 Mens Coach Shower / Toilet 1 10+ years 95 SF 7 Floor - Tile Ceramic/ Porcelain 007A-1 Mens Coach Shower / Toilet 10+ years Floor Drain 007A-1 Mens Coach Shower / Toilet 2 FΑ 7 10+ years 007A-1 Mens Coach Shower / Toilet 1 EΑ 7 10+ years Lavatory Lighting - Lay-in 007A-1 Mens Coach Shower / Toilet 1 EΑ 7 6-10 years Lighting - Lay-in 007A-1 Mens Coach Shower / Toilet 2 EΑ 7 6-10 years 007A-1 Mens Coach Shower / Toilet Lighting - Lay-in 1 EΑ 6 2-5 years 1 EΑ 7 Showers 007A-1 Mens Coach Shower / Toilet 10+ years 3 7 Student Lockers - One Tier 007A-1 Mens Coach Shower / Toilet FΑ 10+ years Walls - Concrete Block 007A-1 Mens Coach Shower / Toilet 360 SF 7 10+ years SF Walls - Tile Ceramic/ Porcelain 007A-1 Mens Coach Shower / Toilet 120 7 10+ years Water Closet 007A-1 Mens Coach Shower / Toilet EΑ 7 10+ years 1 007B-1 Womens Coach SF 7 6-10 years Accessories Shower/Toilet **Benches** 007B-1 Womens Coach 4 LF 7 10+ years Shower/Toilet Ceiling - Plaster/Drywall 007B-1 Womens Coach 95 SF 7 10+ vears Shower/Toilet Doors - Steel Doors incl hw 007B-1 Womens Coach FΑ 7 1 10+ years Shower/Toilet SF Floor - Tile Ceramic/ Porcelain 007B-1 Womens Coach 95 7 10+ years Shower/Toilet 007B-1 Womens Coach Floor Drain 2 EΑ 7 10+ years Shower/Toilet 007B-1 Womens Coach 1 EΑ 7 Lavatory 10+ years Shower/Toilet FΑ 007B-1 Womens Coach 2 7 Lighting - Chandelier, Incandescent 6-10 years Shower/Toilet Lighting - Lay-in 007B-1 Womens Coach EΑ 6 2-5 years







Building: Main Category: Room Recommend Replacement Comments Group Item - Type Location Quantity UOM Rank Shower/Toilet Lighting - Pendent/Surface 007B-1 Womens Coach 2 EΑ 7 6-10 years Shower/Toilet 007B-1 Womens Coach Showers 1 EΑ 7 10+ years Shower/Toilet Student Lockers - One Tier 007B-1 Womens Coach 4 EΑ 7 10+ years Shower/Toilet Walls - Concrete Block 007B-1 Womens Coach 360 SF 7 10+ years Shower/Toilet SF Walls - Tile Ceramic/ Porcelain 007B-1 Womens Coach 120 7 10+ years Shower/Toilet Water Closet 007B-1 Womens Coach 1 EΑ 7 10+ years Shower/Toilet Accessories 007C-Unisex 147 SF 7 6-10 years Ceiling - Plaster/Drywall SF 7 007C-Unisex 147 10+ years Doors - Wood Doors inclu hw FΑ 7 007C-Unisex 1 10+ years 147 SF Floor - Tile Ceramic/ Porcelain 007C-Unisex 7 10+ years Floor Drain 007C-Unisex 2 EΑ 7 10+ years 007C-Unisex 1 EΑ 7 10+ years Lavatory Lighting - Lay-in 007C-Unisex 2 EΑ 7 6-10 years Lighting - Lay-in 007C-Unisex 1 EΑ 5 1-2 years Not working **Partitions** 7 007C-Unisex 1 EΑ 10+ years EΑ 7 Showers 007C-Unisex 1 10+ years 3 7 Student Lockers - One Tier 007C-Unisex FΑ 10+ years Walls - Concrete Block 370 SF 7 007C-Unisex 10+ years SF Walls - Tile Ceramic/ Porcelain 007C-Unisex 175 7 10+ years Water Closet 007C-Unisex EΑ 7 10+ years 1 008 B Womens Restroom 198 SF 7 6-10 years Accessories Ceiling - Plaster/Drywall SF 008 B Womens Restroom 198 7 10+ years Floor - Concrete Epoxy/ Painted 008 B Womens Restroom 198 SF 7 10+ years Floor Drain 008 B Womens Restroom FΑ 7 10+ years 1 Hand Drver 008 B Womens Restroom 3 FΑ 7 6-10 years 3 7 008 B Womens Restroom FΑ 10+ vears Lavatory Lighting - Chandelier, Incandescent 008 B Womens Restroom 3 FΑ 7 6-10 years 7 Lighting - Lay-in 008 B Womens Restroom 1 EΑ 6-10 years 3 EΑ 7 Partitions 008 B Womens Restroom 10+ years SF Walls - Concrete Block 008 B Womens Restroom 317 7 10+ years Water Closet 008 B Womens Restroom 3 EΑ 7 10+ years SF Accessories 008F-1 A Womens Coach Office 175 7 6-10 years LF **Benches** 008F-1 A Womens Coach Office 8 7 10+ years SF Ceiling - Plaster/Drywall 008F-1 A Womens Coach Office 160 7 10+ years SF Ceiling - Plaster/Drywall 008F-1 A Womens Coach Office 15 4 1-2 years Missing part of ceiling Doors - Steel Doors incl hw 008F-1 A Womens Coach Office EΑ 7 10+ years 1 Floor - Tile Ceramic/ Porcelain SF 7 008F-1 A Womens Coach Office 175 10+ years







Building: Main Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Floor Drain 008F-1 A Womens Coach Office FΑ 10+ vears 7 EΑ 7 Lavatory 008F-1 A Womens Coach Office 1 10+ years Lighting - Lay-in 008F-1 A Womens Coach Office 3 FΑ 7 10+ years Showers 1 EΑ 7 008F-1 A Womens Coach Office 10+ years Student Lockers - One Tier 008F-1 A Womens Coach Office 4 EΑ 7 10+ years SF 595 7 Walls - Concrete Block 008F-1 A Womens Coach Office 10+ years Walls - Tile Ceramic/ Porcelain 008F-1 A Womens Coach Office 225 SF 7 10+ years 10+ years Water Closet 008F-1 A Womens Coach Office 1 EΑ 7 Accessories 011 Womens Restroom 225 SF 7 6-10 years SF Ceiling - Plaster/Drywall 011 Womens Restroom 225 7 10+ years Doors - Wood Doors inclu hw 011 Womens Restroom 1 EΑ 7 10+ years Floor - Terrazzo 011 Womens Restroom 225 SF 7 10+ years Floor Drain EΑ 7 011 Womens Restroom 1 10+ years 7 Hand Dryer 011 Womens Restroom 2 EΑ 6-10 years 3 EΑ 7 Lavatory 011 Womens Restroom 10+ years Lighting - Pendent/Surface 6 FΑ 7 011 Womens Restroom 6-10 years **Partitions** 011 Womens Restroom 4 EΑ 7 10+ years SF Walls - Structural Glazed Tile 011 Womens Restroom 685 7 10+ years EΑ Water Closet 011 Womens Restroom 4 7 10+ years 225 Accessories 013 Mens Restroom SF 7 6-10 years Ceiling - Plaster/Drywall 013 Mens Restroom 225 SF 7 10+ years Doors - Wood Doors inclu hw EΑ 7 013 Mens Restroom 1 10+ years SF Floor - Terrazzo 225 7 013 Mens Restroom 10+ years Floor Drain 013 Mens Restroom 1 FΑ 7 10+ years Hand Dryer 2 FΑ 7 6-10 years 013 Mens Restroom Lavatory 013 Mens Restroom 3 FΑ 7 10+ years Lighting - Pendent/Surface 6 013 Mens Restroom EΑ 7 6-10 years **Partitions** 2 EΑ 7 013 Mens Restroom 10+ years 2 Urinals 013 Mens Restroom EΑ 7 10+ years Walls - Structural Glazed Tile 013 Mens Restroom 685 SF 7 10+ years Water Closet 013 Mens Restroom 2 FΑ 7 10+ years Accessories 100 B Women 109 SF 7 6-10 years SF 7 10+ years Ceiling - Plaster/Drywall 100 B Women 109 Doors - Wood Doors inclu hw FΑ 7 10+ years 100 B Women 1 SF 7 Floor - Tile Ceramic/ Porcelain 100 B Women 109 10+ years EΑ 7 Floor Drain 100 B Women 10+ years 1 Hand Dryer 100 B Women 1 EΑ 7 6-10 years Lavatory 100 B Women 1 EΑ 7 10+ years Lighting - Lay-in 100 B Women 1 EΑ 7 6-10 years Walls - Concrete Block SF 100 B Women 350 7 10+ vears SF Walls - Tile Ceramic/ Porcelain 100 B Women 80 7 10+ years 100 B Women FΑ 7 Water Closet 1 10+ years Accessories 100 C Men 109 SF 7 6-10 years SF Ceiling - Plaster/Drywall 100 C Men 109 7 10+ years







Building: Main Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Doors - Wood Doors inclu hw 100 C Men EΑ 10+ vears 7 Floor - Tile Ceramic/ Porcelain 100 C Men 109 SF 7 10+ years Floor Drain 100 C Men FΑ 7 10+ years 1 Hand Dryer EΑ 7 100 C Men 6-10 years Lavatory 100 C Men 1 EΑ 7 10+ years 7 Lighting - Lay-in 100 C Men 1 EΑ 10+ years Walls - Concrete Block 100 C Men 350 SF 7 10+ years SF Walls - Tile Ceramic/ Porcelain 100 C Men 80 7 10+ years Water Closet 100 C Men 1 EΑ 7 10+ years SF Accessories 117 A Womens Restroom 903 7 6-10 years SF Ceiling - Plaster/Drywall 117 A Womens Restroom 903 7 10+ vears Floor - Terrazzo 117 A Womens Restroom 903 SF 7 10+ years Floor Drain 2 EΑ 7 117 A Womens Restroom 10+ years EΑ 7 Hand Dryer 117 A Womens Restroom 4 6-10 years 9 EΑ 7 Lavatory 117 A Womens Restroom 10+ years 4 FΑ 7 Lighting - Lay-in 117 A Womens Restroom 6-10 years Lighting - Lay-in 117 A Womens Restroom 11 EΑ 7 6-10 years Lighting - Lay-in 117 A Womens Restroom 2 EΑ 6 2-5 years Bulb out **Partitions** 117 A Womens Restroom 17 EΑ 7 10+ years Walls - Structural Glazed Tile 117 A Womens Restroom 2,050 SF 7 10+ years Water Closet 117 A Womens Restroom 17 EΑ 7 10+ years SF 7 Accessories 118 A Mens Restroom 830 6-10 years SF 7 Ceiling - Plaster/Drywall 118 A Mens Restroom 810 10+ years SF Ceiling - Plaster/Drywall 118 A Mens Restroom 20 5 1-2 years Stained ceiling Floor - Terrazzo 830 SF 7 118 A Mens Restroom 10+ years Floor Drain 118 A Mens Restroom 2 FΑ 7 10+ years 5 Hand Dryer 118 A Mens Restroom EΑ 7 6-10 years 9 EΑ 7 Lavatory 118 A Mens Restroom 10+ years Lighting - Chandelier, Incandescent 118 A Mens Restroom 13 EΑ 7 6-10 years Lighting - Lay-in 118 A Mens Restroom 4 EΑ 7 6-10 years **Partitions** 10 FΑ 7 10+ vears 118 A Mens Restroom Urinals 118 A Mens Restroom 6 EΑ 7 10+ years SF 7 Walls - Structural Glazed Tile 2.050 118 A Mens Restroom 10+ years Water Closet FΑ 7 10+ years 118 A Mens Restroom 10 SF 7 Accessories 118 B Unisex Toilet 50 6-10 years Ceiling - Plaster/Drywall 50 SF 7 118 B Unisex Toilet 10+ years 118 B Unisex Toilet Doors - Wood Doors inclu hw 1 EΑ 7 10+ years 50 SF Floor - Tile Ceramic/ Porcelain 118 B Unisex Toilet 7 10+ years Floor Drain 118 B Unisex Toilet 1 EΑ 7 10+ years 118 B Unisex Toilet 1 EΑ 7 10+ years Lavatory Lighting - Lay-in 118 B Unisex Toilet 1 FΑ 7 6-10 years Walls - Concrete Block 170 SF 7 118 B Unisex Toilet 10+ vears Walls - Tile Ceramic/ Porcelain 118 B Unisex Toilet 63 SF 7 10+ years EΑ Water Closet 118 B Unisex Toilet 7 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Accessories 124 F Staff Restroom (Main Office) 50 SF 6-10 years 7 124 F Staff Restroom (Main Office) SF 7 Ceiling - Plaster/Drywall 50 10+ years Doors - Wood Doors inclu hw 124 F Staff Restroom (Main Office) 1 EΑ 7 10+ years 124 F Staff Restroom (Main Office) SF 7 Floor - Tile Ceramic/ Porcelain 50 10+ years Floor Drain 124 F Staff Restroom (Main Office) 1 EΑ 7 10+ years 124 F Staff Restroom (Main Office) Lavatory 1 EΑ 6 10+ years Lighting - Lay-in 124 F Staff Restroom (Main Office) EΑ 7 6-10 years 1 Walls - Concrete Block 124 F Staff Restroom (Main Office) SF 170 7 10+ years Walls - Tile Ceramic/ Porcelain 124 F Staff Restroom (Main Office) 63 SF 7 10+ years Water Closet 124 F Staff Restroom (Main Office) 1 EΑ 7 10+ years Accessories 125 B Staff Restroom Mens 50 SF 7 6-10 years (Kitchen) 125 B Staff Restroom Mens SF Ceiling - Plaster/Drywall 50 7 10+ years (Kitchen) 125 B Staff Restroom Mens Doors - Steel Doors incl hw 1 EΑ 7 10+ years (Kitchen) 125 B Staff Restroom Mens SF Floor - Tile Ceramic/ Porcelain 50 7 10+ years (Kitchen) 125 B Staff Restroom Mens Floor Drain EΑ 7 1 10+ years (Kitchen) 125 B Staff Restroom Mens EΑ 7 Lavatory 1 10+ years (Kitchen) 125 B Staff Restroom Mens Lighting - Lay-in 1 EΑ 7 6-10 years (Kitchen) Student Lockers - One Tier 125 B Staff Restroom Mens EΑ 7 10+ years (Kitchen) 125 B Staff Restroom Mens Walls - Concrete Block SF 7 170 10+ years (Kitchen) Walls - Tile Ceramic/ Porcelain 125 B Staff Restroom Mens 63 SF 7 10+ years (Kitchen) Water Closet 125 B Staff Restroom Mens FΑ 7 1 10+ years (Kitchen) 125 C Staff Restroom Womens SF 7 Accessories 50 6-10 years (Kitchen) Ceiling - Plaster/Drywall 125 C Staff Restroom Womens 50 SF 7 10+ years (Kitchen) Doors - Steel Doors incl hw 125 C Staff Restroom Womens 1 EΑ 7 10+ years (Kitchen) Floor - Tile Ceramic/ Porcelain 125 C Staff Restroom Womens 50 SF 7 10+ years (Kitchen) Floor Drain 125 C Staff Restroom Womens FΑ 7 1 10+ years (Kitchen) Lavatory 125 C Staff Restroom Womens EΑ 7 10+ years 1 (Kitchen)







Building: Main Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Lighting - Lay-in 125 C Staff Restroom Womens FΑ 6-10 years 7 (Kitchen) Student Lockers - One Tier 125 C Staff Restroom Womens 4 FΑ 7 10+ years (Kitchen) Walls - Concrete Block 125 C Staff Restroom Womens 170 SF 7 10+ years (Kitchen) Walls - Tile Ceramic/ Porcelain 125 C Staff Restroom Womens 63 SF 7 10+ years (Kitchen) Water Closet 125 C Staff Restroom Womens 1 EΑ 7 10+ years (Kitchen) Accessories 126 B Staff Restroom (Main Office) 50 SF 7 6-10 years Ceiling - Plaster/Drywall 126 B Staff Restroom (Main Office) 50 SF 7 10+ years Doors - Wood Doors inclu hw 126 B Staff Restroom (Main Office) 1 EΑ 7 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 126 B Staff Restroom (Main Office) 50 10+ years Floor Drain 126 B Staff Restroom (Main Office) EΑ 7 1 10+ years 126 B Staff Restroom (Main Office) FΑ 7 Lavatory 1 10+ years 7 Lighting - Lay-in 126 B Staff Restroom (Main Office) 1 EΑ 6-10 years Walls - Plaster/Drywall 126 B Staff Restroom (Main Office) 178 SF 7 10+ years Walls - Tile Ceramic/ Porcelain SF 126 B Staff Restroom (Main Office) 63 7 10+ vears Water Closet 126 B Staff Restroom (Main Office) 1 EΑ 7 10+ years Accessories 218A men's restroom 306 SF 7 6-10 years Ceiling - Plaster/Drywall SF 7 218A men's restroom 306 10+ years Floor - Terrazzo SF 7 218A men's restroom 306 10+ years Floor Drain 218A men's restroom FΑ 7 10+ years 1 Hand Dryer 3 FΑ 7 6-10 years 218A men's restroom Lavatory 218A men's restroom 3 FΑ 7 10+ years Lighting - Lay-in 17 EΑ 7 6-10 years 218A men's restroom **Partitions** 3 EΑ 7 218A men's restroom 10+ years 2 Urinals 218A men's restroom EΑ 7 10+ years Walls - Structural Glazed Tile 218A men's restroom 811 SF 7 10+ years Water Closet 2 FΑ 7 10+ years 218A men's restroom Water Closet 1 EΑ 4 1-2 years Out of service 218A men's restroom SF 7 Accessories 50 6-10 years 218B Staff restroom Ceiling - Plaster/Drywall 50 SF 7 10+ years 218B Staff restroom Doors - Wood Doors inclu hw 7 218B Staff restroom 1 EΑ 10+ years Floor - Tile Ceramic/ Porcelain 50 SF 7 218B Staff restroom 10+ years Floor Drain 218B Staff restroom 1 EΑ 7 10+ years 218B Staff restroom 1 EΑ 7 10+ years Lavatory Lighting - Lay-in 218B Staff restroom 1 EΑ 7 6-10 years Walls - Concrete Block SF 218B Staff restroom 170 7 10+ vears Walls - Tile Ceramic/ Porcelain SF 218B Staff restroom 63 7 10+ years FΑ 7 Water Closet 218B Staff restroom 1 10+ years Accessories 218D women's restroom 306 SF 7 6-10 years SF Ceiling - Plaster/Drywall 218D women's restroom 306 7 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Floor - Terrazzo 218D women's restroom 306 SF 10+ years 7 Floor Drain EΑ 7 1 10+ years 218D women's restroom Hand Drver 3 FΑ 7 6-10 years 218D women's restroom 3 EΑ 7 Lavatory 218D women's restroom 10+ years Lighting - Lay-in 218D women's restroom 17 EΑ 7 6-10 years 7 **Partitions** 6 EΑ 10+ years 218D women's restroom Walls - Structural Glazed Tile SF 7 218D women's restroom 811 10+ years Water Closet 218D women's restroom 6 EΑ 7 10+ years Accessories 237A women's restroom 325 SF 7 6-10 years SF Ceiling - Plaster/Drywall 325 7 10+ years 237A women's restroom SF Floor - Terrazzo 325 7 10+ years 237A women's restroom Floor Drain 237A women's restroom 1 EΑ 7 10+ years Hand Dryer 3 EΑ 7 6-10 years 237A women's restroom 3 7 Lavatory 237A women's restroom EΑ 10+ years 17 7 Lighting - Lay-in 237A women's restroom EΑ 6-10 years FΑ Partitions 237A women's restroom 6 7 10+ years SF Walls - Structural Glazed Tile 237A women's restroom 814 7 10+ years Water Closet 237A women's restroom 6 EΑ 7 10+ years SF Accessories 237C staff restroom 48 7 6-10 years SF Ceiling - Plaster/Drywall 237C staff restroom 48 7 10+ years Doors - Wood Doors inclu hw 237C staff restroom 1 EΑ 7 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 237C staff restroom 48 10+ years 7 Floor Drain 237C staff restroom 1 EΑ 10+ years Lavatory 237C staff restroom 1 FΑ 7 10+ years Lighting - Lay-in FΑ 7 237C staff restroom 1 6-10 years SF Walls - Concrete Block 237C staff restroom 178 7 10+ years SF Walls - Tile Ceramic/ Porcelain 237C staff restroom 63 7 10+ years Water Closet EΑ 7 237C staff restroom 1 10+ years SF Accessories 237D boys restroom 326 7 6-10 years Ceiling - Plaster/Drywall 237D boys restroom 326 SF 7 10+ years Floor - Terrazzo SF 237D boys restroom 326 7 10+ vears Floor Drain 237D boys restroom EΑ 7 10+ years 1 7 Hand Dryer 237D boys restroom 3 FΑ 6-10 years 237D boys restroom 3 FΑ 7 Lavatory 10+ years 7 Lighting - Lay-in 237D boys restroom 17 EΑ 6-10 years EΑ 7 **Partitions** 237D boys restroom 3 10+ years Urinals 237D boys restroom 3 EΑ 7 10+ years Walls - Structural Glazed Tile SF 237D boys restroom 1,048 7 10+ years Water Closet 237D boys restroom 3 EΑ 7 10+ years SF Accessories 306 7 6-10 years 318A men's restroom SF Ceiling - Plaster/Drywall 306 7 10+ years 318A men's restroom Floor - Terrazzo 306 SF 7 10+ years 318A men's restroom Floor Drain EΑ 7 10+ years 318A men's restroom 1 7 Hand Dryer 318A men's restroom 3 EΑ 6-10 years







Building: Main Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Lavatory 318A men's restroom 3 EΑ 10+ vears 6 EΑ 7 6-10 years Lighting - Lav-in 10 318A men's restroom Lighting - Lay-in 7 FΑ 7 6-10 years 318A men's restroom Partitions 3 EΑ 7 318A men's restroom 10+ years 2 Urinals 318A men's restroom EΑ 6 10+ years SF 7 Walls - Structural Glazed Tile 811 10+ years 318A men's restroom Water Closet EΑ 318A men's restroom 3 6 10+ years SF Accessories 318B staff restroom 50 7 6-10 years Ceiling - Plaster/Drywall 318B staff restroom 50 SF 6 10+ years Doors - Wood Doors inclu hw 1 FΑ 7 10+ years 318B staff restroom Floor - Tile Ceramic/ Porcelain 318B staff restroom 50 SF 7 10+ years Floor Drain 318B staff restroom 1 EΑ 7 10+ years EΑ 6 Lavatory 318B staff restroom 1 10+ years 7 Lighting - Lay-in 318B staff restroom 1 EΑ 6-10 years Walls - Concrete Block SF 7 318B staff restroom 170 10+ years Walls - Tile Ceramic/ Porcelain SF 318B staff restroom 63 7 10+ years EΑ Water Closet 318B staff restroom 1 6 10+ years Accessories 318D women's restroom 306 SF 7 6-10 years SF Ceiling - Plaster/Drywall 306 6 10+ years 318D women's restroom Floor - Terrazzo SF 318D women's restroom 306 7 10+ years Floor Drain EΑ 7 10+ years 318D women's restroom 1 318D women's restroom 7 Hand Dryer 3 EΑ 10+ years 3 EΑ Lavatory 318D women's restroom 6 10+ years 7 Lighting - Lay-in 318D women's restroom FΑ 7 6-10 years Lighting - Lay-in 10 FΑ 7 318D women's restroom 6-10 years **Partitions** 318D women's restroom 6 EΑ 7 10+ years SF Walls - Structural Glazed Tile 811 7 10+ years 318D women's restroom Water Closet EΑ 6 318D women's restroom 6 10+ years SF 7 Accessories 337A women's restroom 325 6-10 years Ceiling - Plaster/Drywall 337A women's restroom 325 SF 6 10+ years Floor - Terrazzo SF 325 7 10+ years 337A women's restroom Floor Drain EΑ 7 10+ years 337A women's restroom 1 7 Hand Dryer 3 FΑ 6-10 years 337A women's restroom 3 FΑ 6 Lavatory 337A women's restroom 10+ years 7 Lighting - Lay-in 337A women's restroom 17 EΑ 6-10 years EΑ 7 Partitions 337A women's restroom 6 10+ years SF Walls - Structural Glazed Tile 337A women's restroom 814 7 10+ years Water Closet EΑ 337A women's restroom 6 6 10+ years SF Accessories 337C staff restroom 48 7 6-10 years SF Ceiling - Plaster/Drywall 337C staff restroom 48 6 10+ years Doors - Wood Doors inclu hw 337C staff restroom 1 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 48 SF 7 337C staff restroom 10+ years Floor Drain 337C staff restroom 1 EΑ 7 10+ years Lavatory 337C staff restroom EΑ 10+ years





| | De les | | | | | · · · · · · · · · · · · · · · · · · · | 651 5 Homan Avenue, Chicago, IL 60652 |
|----------|--|---------------------|----------|----------|--------|---------------------------------------|---------------------------------------|
| Catego | ry : Room | | В | uilding | : Main | _ | |
| | _ | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 337C staff restroom | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 337C staff restroom | 178 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 337C staff restroom | 63 | SF | 7 | 10+ years | |
| | Water Closet | 337C staff restroom | 1 | EA | 6 | 10+ years | |
| | Accessories | 337D boys restroom | 326 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 337D boys restroom | 326 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | 337D boys restroom | 326 | SF | 7 | 10+ years | |
| | Floor Drain | 337D boys restroom | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 337D boys restroom | 3 | EA | 7 | 6-10 years | |
| | Lavatory | 337D boys restroom | 3 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 337D boys restroom | 17 | EA | 7 | 6-10 years | |
| | Partitions | 337D boys restroom | 3 | EA | 7 | 10+ years | |
| | Urinals | 337D boys restroom | 3 | EA | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 337D boys restroom | 1,048 | SF | 7 | 10+ years | |
| | Water Closet | 337D boys restroom | 3 | EA | 6 | 10+ years | |
| | vvalor closet | dor B boye room dom | · · | | Ü | 101 youro | |
| Catego | ry : Classroom | | В | uilding | : Main | | |
| Calogo | . , | | _ | uug | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | om #010 (Regular Classroom) | | | | | | |
| Cidooroc | Ceiling - Lay-in | Basement | 1,302 | SF | 7 | 10+ years | |
| | Doors - Side-lite | Basement | 16 | SF | 7 | 10+ years | |
| | Doors - Transom Window | Basement | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 20 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Basement | 1,302 | SF | 7 | • | |
| | Lighting - Lay-in | Basement | | EA | 7 | 10+ years 6-10 years | |
| | | | 16 20 | SF | | | |
| | Storage/ Closet Wall Mirrors | Basement | 20 | SF SF | 7 | 10+ years | |
| | | Basement | - | SF SF | 7 | 10+ years | |
| | Walls - Concrete Block | Basement | 2,473 | SF. | 7 | 10+ years | |
| 01 | #040 (M : L) | | | | | | |
| Classroc | om #012 (Weight) | December | 0.50 | 05 | | 40 | |
| | Ceiling - Exposed | Basement | 950 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Basement | 2 | EA | 7 | 10+ years | |
| | Floor - Weight/ Fitness Room Floor Matting | Basement | 950 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 8 | EA | 7 | 6-10 years | |
| | Walls - Structural Glazed Tile | Basement | 1,725 | SF | 7 | 10+ years | |
| Classroo | om #100 D (Office) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,046 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 300 | SF | 7 | 10+ years | |
| | Doors - Store Front | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | 1st Floor | 1,046 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 24 | EA | 7 | 6-10 years | |
| | Lighting Lay III | 10111001 | 24 | _, 、 | • | J 10 yours | |
| | | | | | | | |





| Catego | ategory : Classroom | | В | uilding | : Main | <u>-</u> | 7001 O Homan Avenoe, Onleago, ie 00002 | | |
|----------|---|-----------|----------|---------|--------|-------------|--|--|--|
| | , | | _ | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| • | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 30 | SF | 7 | 10+ years | | | |
| | Walls - Masonry | 1st Floor | 993 | SF | 7 | 10+ years | | | |
| | Walls - Metal Panel | 1st Floor | 496 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor | 496 | SF | 7 | 10+ years | | | |
| 01 | #440 (Q | | | | | | | | |
| Classroo | om #119 (Special Education) | | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 774 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Carpet | 1st Floor | 774 | SF | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 1st Floor | 17 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EΑ | 5 | 1-2 years | Not working | | |
| | Marker Board | 1st Floor | 40 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 30 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor | 929 | SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 1st Floor | 309 | SF | 7 | 10+ years | | | |
| Classroo | om #200B (Art Room) | | | | | | | | |
| | Casework | 2nd Floor | 25 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,220 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | | | |
| | Doors - Side-life Doors - Wood Doors inclu hw | 2nd Floor | 20 | EA | 7 | • | | | |
| | Floor - Terrazzo | 2nd Floor | 1,220 | SF | 7 | 10+ years | | | |
| | | | , | | | 10+ years | | | |
| | Kiln | 2nd Floor | 1 | EΑ | 7 | 10+ years | | | |
| | Lighting - Chandelier, Incandescent | 2nd Floor | 12 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 23 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | | | |
| | Walls - Concrete Block | 2nd Floor | 248 | SF | 7 | 10+ years | | | |
| | Walls - Masonry | 2nd Floor | 66 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 915 | SF | 7 | 10+ years | | | |
| | Work Sink | 2nd Floor | 2 | EA | 7 | 10+ years | | | |
| Classroo | om #200D (Art Room) | | | | | | | | |
| | Casework | 2nd Floor | 25 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,220 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | 2nd Floor | 1,220 | SF | 7 | 10+ years | | | |
| | Lighting - Chandelier, Incandescent | 2nd Floor | 12 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 23 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 2nd Floor | 115 | SF | 7 | 10+ years | | | |
| | Storage/ Closet Storage/ Closet | 2nd Floor | 115 | SF | 7 | , | | | |
| | Storage/ Closet | ZHU FIUUI | 110 | SF | , | 10+ years | | | |
| | | | | | | | | | |





| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|------------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Concrete Block | 2nd Floor | 248 | SF | 7 | 10+ years | |
| | Walls - Masonry | 2nd Floor | 66 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 915 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 2 | EA | 7 | 10+ years | |
| Classroc | om #200G (Choral Room) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,250 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,250 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 3 | ĒΑ | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 25 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Sound Panels | 2nd Floor | 20 | EA | 7 | 10+ years | |
| | Sound System | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 7 | 10+ years | |
| | · | | .,==5 | σ. | • | , | |
| lassroc | m #200H (Band Room) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,570 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 3 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 1,570 | SF | 7 | 6-10 years | |
| | Instrument Storage Casework | 2nd Floor | 112 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 7 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 31 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Risers | 2nd Floor | 18 | LF | 7 | 10+ years | |
| | Sound Panels | 2nd Floor | 29 | EA | 7 | 10+ years | |
| | Sound System | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 284 | SF | 7 | 10+ years | |
| | Walls - Masonry | 2nd Floor | 66 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,145 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | ĒΑ | 7 | 10+ years | |
| `laceroo | om #216 (Regular Classroom) | | | | | | |
| //a33100 | Casework | 2nd Floor | 14 | LF | 7 | 101 2000 | |
| | | 2nd Floor 2nd Floor | | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | | 695 | | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 35 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 695 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 16 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |





| Catego | ory : Classroom | | В | uilding | : Main | | 651 S HOMAN AVENUE, Chicago, IL 60652 |
|----------|--------------------------------|-----------|----------|---------|--------|-------------|---------------------------------------|
| | • | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Student Lockers - One Tier | 2nd Floor | 28 | EΑ | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 31 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 784 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classroo | om #219 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | ĒΑ | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 70 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classroo | om #220 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | ĒΑ | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 290 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classroo | om #221 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | | | | | | - | |





| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|--|------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 70 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classroo | om #222 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 3 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classra | am #222 (Bogular Classroom) | | | | | | |
| Classio | om #223 (Regular Classroom) | 0 151 | 4.5 | | | 40 | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 3 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 70 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classroo | om #224 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in Lighting - Pendent/Surface | 2nd Floor | 22 | EA | 7 | • | |
| | Lighting - Felluelly Surface | ZIIU FIOOI | 22 | EA | , | 6-10 years | |
| | | | | | | | |





| Category : Classroom | | | В | uilding | : Main | Building : Main | | | | |
|----------------------|--------------------------------|-----------|----------|---------|--------|-----------------|----------|--|--|--|
| <u> </u> | | | | | | Recommend | | | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| • | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | | | | |
| | Walls - Concrete Block | 2nd Floor | 370 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 590 | SF | 7 | 10+ years | | | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | | | | |
| lassroo | om #225 (Computer Lab) | | | | | | | | | |
| | Casework | 2nd Floor | 8 | LF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,175 | SF | 7 | 10+ years | | | | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | 10+ years | | | | |
| | Doors - Transom Window | 2nd Floor | 49 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 1,175 | SF | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | , 2 | ĒΑ | 7 | 6-10 years | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 32 | EA | 7 | 6-10 years | | | | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | | | | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 2nd Floor | 234 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,160 | SF | 7 | 10+ years | | | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 66 | SF | 7 | 10+ years | | | | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 6-10 years | | | | |
| lassroo | om #226 (Regular Classroom) | | | | | | | | | |
| | Casework | 2nd Floor | 8 | LF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,175 | SF | 7 | 10+ years | | | | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | 10+ years | | | | |
| | Doors - Transom Window | 2nd Floor | 49 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | ĒΑ | 7 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 1,175 | SF | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | 2 | ĒΑ | 7 | 6-10 years | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 32 | EA | 7 | 6-10 years | | | | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | | | | |
| | Walls - Concrete Block | 2nd Floor | 234 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 960 | SF | 7 | 10+ years | | | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 66 | SF | 7 | 10+ years | | | | |
| lassroc | om #227 (Science Lab Level 2) | | | | | | | | | |
| | Casework | 2nd Floor | 92 | LF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,290 | SF | 7 | 10+ years | | | | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | 10+ years | | | | |
| | Doors - Transom Window | 2nd Floor | 49 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | | | | |
| | Eye Wash Station | 2nd Floor | 1 | EΑ | 7 | 10+ years | | | | |
| | _, = 114011 - 1411011 | | 1,290 | SF | 7 | . o . youro | | | | |





| Catego | ry : Classroom | | В | uilding | : Main | | 001 0 Homan Avenoe, Officago, le 00032 |
|-----------|--------------------------------|-----------|----------|---------|--------|-------------|--|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Gas Line | 2nd Floor | 5 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 28 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 2nd Floor | 1,290 | SF | 7 | 10+ years | |
| | Science Lab Shower | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 200 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 176 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 6 | EA | 7 | 10+ years | |
| Classroo | om #228 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 70 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| | | | | | | , , , , , , | |
| _Classroo | om #230 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 70 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classroo | om #231 (Science Lab Level 2) | | | | | | |
| | Casework | 2nd Floor | 92 | LF | 7 | 10+ years | |
| | | | | | | | |





| Catego | ry : Classroom | | В | Building : Main | | | | | |
|---------------------|--|-------------|----------|-----------------|------|-------------|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| - | Ceiling - Lay-in | 2nd Floor | 1,290 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 2nd Floor | 49 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | | | |
| | Eye Wash Station | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 1,290 | SF | 7 | 10+ years | | | |
| | Gas Line | 2nd Floor | 8 | ĒA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 28 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | | | |
| | Science Lab Elements | 2nd Floor | 1,290 | SF | 7 | 10+ years | | | |
| | Science Lab Shower | 2nd Floor | 1,233 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | 2nd Floor | 200 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 176 | SF | 7 | 10+ years | | | |
| | Work Sink | 2nd Floor | 8 | EA | 7 | 10+ years | | | |
| | WOIR SIIIR | 2110 1 1001 | O | LA | , | 10+ years | | | |
| Classroo | om #232 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 4 | ĒΑ | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 2nd Floor | 70 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 6 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 6 | 10+ years | | | |
| Classro | om #234 (Regular Classroom) | | | | | | | | |
| <u> Viassi () (</u> | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | | | |
| | Lighting - Lay-in Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | | | |
| | Walls - Concrete Block | 2nd Floor | 70 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | | | |
| | vvalis - i lastoi/Diywali | 2110 1 1001 | 890 | Ji | , | 10+ years | | | |
| | | | | | | | | | |





| Catego | Category : Classroom | | В | uilding | : Main | | |
|-----------|--------------------------------|-----------|-----------------|---------|--------|-------------|----------|
| | | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| _Classroo | om #235 (Science Lab Level 1) | | | | | | |
| | Casework | 2nd Floor | 92 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,290 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 49 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Eye Wash Station | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,290 | SF | 7 | 10+ years | |
| | Gas Line | 2nd Floor | 8 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 28 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 2nd Floor | 1,290 | SF | 7 | 10+ years | |
| | Science Lab Fume Hood | 2nd Floor | · 1 | EA | 7 | 10+ years | |
| | Science Lab Shower | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 200 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 176 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 8 | EA | 7 | 10+ years | |
| Classro | om #236 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | . <u>-</u> 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 70 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 890 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classro | om #238 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 14 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 7 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | | | | | | • | |





| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|--------------------------------|------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 3 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 420 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 590 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classroo | om #239 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 7 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 420 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 590 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 44 | SF | 7 | 10+ years | |
| Classroo | om #316 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 14 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 732 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 35 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 732 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 10 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 9 | EΑ | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | 6-10 years | |
| | Student Lockers - One Tier | 3rd Floor | 28 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 119 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 788 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Classroo | om #319 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | 20010 Hanson Window | 014 1 1001 | 72 | 0. | , | 101 yours | |





| Catego | ry : Classroom | В | uilding | : Main | | | |
|----------|--------------------------------|-----------|----------|--------|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 155 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 838 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Classroc | om #320 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 193 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 825 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Classroc | om #321 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 127 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 838 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Classroc | om #322 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 14 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | 10+ years | |





| Catego | ry : Classroom | | В | uilding | | | |
|---------|--|------------------------|------------|----------|--------|-------------|----------|
| | • | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _ | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 3 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 181 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 799 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| lassroo | om #323 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 3 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | | | |
| | Walls - Concrete Block | 3rd Floor | | SF | 6 7 | 6-10 years | |
| | | 3rd Floor | 151 817 | SF SF | | 10+ years | |
| | Walls - Plaster/Drywall Walls - Structural Glazed Tile | 3rd Floor 3rd Floor | 50 | SF SF | 7 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 31d F1001 | 50 | SI | , | 10+ years | |
| lassroc | om #324 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 4 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 792 | SF | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 3 | SF | 4 | 1-2 years | Damaged |
| | Lighting - Pendent/Surface | 3rd Floor | 22 | EA | 7 | 6-10 years | 9 |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 443 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 544 | SF | 6 | 10+ years | |
| lassroo | om #325 (Computer Lab) | | | | | | |
| _ | Casework | 3rd Floor | 4 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,382 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 24 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 49 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,382 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 1,362 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 310 1 1001 | 2 | LA | , | 0-10 years | |





| Catego | Category : Classroom | | R | uilding | · Main | | 651 S HOMAN AVENUE, Chicago, ic 60652 |
|----------|--------------------------------|-----------|----------|--------------|--------|--------------------------|---------------------------------------|
| Outego | 1 9 1 010331 00111 | | | _ | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Oroup | Lighting - Pendent/Surface | 3rd Floor | 30 | EA | 7 | 6-10 years | Comments |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 290 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,110 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 140 | SF | 7 | 10+ years | |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| Classros | om #326 (Computer Lab) | | | | | | |
| Classion | | 3rd Floor | 4 | 1.5 | | 10 | |
| | Casework | | 4 475 | LF SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,175 | | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,175 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 30 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 20 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 570 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 659 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 100 | SF | 7 | 10+ years | |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | om #327 (Science Lab Level 2) | | | | | | |
| | Casework | 3rd Floor | 85 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 24 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 49 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Gas Line | 3rd Floor | 5 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 25 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Science Lab Shower | 3rd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 293 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 850 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 176 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 4 | ĒΑ | 7 | 10+ years | |
| Classroo | om #328 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |





| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|---|-----------|----------|----------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 144 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 933 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Classroo | om #330 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 3 | EA | 7 | 6-10 years | |
| | Lighting - Lay-iii Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | | |
| | Walls - Concrete Block | | | SF | 7 | 6-10 years | |
| | | 3rd Floor | 144 | SF SF | | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 933 | | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Classroo | m #331 (Science Lab Level 2) | | | | | | |
| | Casework | 3rd Floor | 88 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Gas Line | 3rd Floor | 8 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 2 | EΑ | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 28 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Science Lab Shower | 3rd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 293 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 850 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 176 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 8 | EA | 7 | 10+ years | |
| | | 5.455 | O | _, 、 | • | .o. youro | |





| Catego | ry : Classroom | | В | Building : Main | | | 631 3 HOIHAH AVENUE, CHICAGO, IL 60652 |
|----------|--------------------------------|-----------|----------|-----------------|------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | |
| Classroo | om #332 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EΑ | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 164 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 933 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Classro | om #334 (Regular Classroom) | | | | | | |
| Classiuc | Casework | 3rd Floor | 16 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EΑ | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 119 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 933 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| | | | | | | , | |
| Classroo | om #335 (Science Lab Level 1) | 0.15 | | | | 40 | |
| | Casework | 3rd Floor | 85 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 24 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 49 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Gas Line | 3rd Floor | 8 | EΑ | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 2 | EΑ | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 28 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 3rd Floor | 1,290 | SF | 7 | 10+ years | |
| | Science Lab Fume Hood | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | | | | | | | |





| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|--------------------------------|-----------|----------|----------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 293 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 850 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 176 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 8 | EA | 7 | 10+ years | |
| Classroc | om #336 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | • | |
| | | | | | | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 3 | EΑ | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 119 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 933 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Classroc | om #338 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 12 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 7 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 3 | ĒΑ | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 443 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 533 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 55 | SF | 7 | 10+ years | |
| Classroo | om #339 (Regular Classroom) | | | | | | |
| CIGSSIUL | | Ord Floor | 45 | 1.5 | | 10 | |
| | Casework | 3rd Floor | 15 | LF CF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 7 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 3 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | 6-10 years | |





Category : Classroom

| ego | ry : Classroom | | Ь | ullaing | . Walli | Decemberd | |
|----------|--|------------------------|------------|----------|---------|-------------|----------|
| | Ham. Turns | Location | Overetites | HOM | Dank | Recommend | Comments |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 446 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 519 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 82 | SF | 7 | 10+ years | |
| `ateno | ry : Interior | | R | uilding | · Main | | |
| alego | y . Interior | | | unung | . Walli | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | • | |
| | Ceiling - Lay-in | 1st Floor | 11,674 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 3,330 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EΑ | 7 | 10+ years | |
| | Doors - Store Front | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Drinking Fountains - Double Water Cooler | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 15,004 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 42 | ĒΑ | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 156 | EA | 7 | 6-10 years | |
| | Walls - Masonry | 1st Floor | 5,208 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 5,526 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 9,588 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 11,355 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,225 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 208 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 28 | SF | 7 | 10+ years | |
| | Doors - Wood Doors include hw | 2nd Floor | 8 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | 2nd Floor | 6 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 108 | SF | 7 | 6-10 years | |
| | Floor - Terrazzo | 2nd Floor | 12,472 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 173 | EA | 7 | 6-10 years | |
| | Lighting - Lay-III Lighting - Wall Mounted | 2nd Floor | 164 | EA | 7 | 6-10 years | |
| | Stairs - Concrete Stairs | 2nd Floor | 2 | LF | 7 | | |
| | Student Lockers - One Tier | 2nd Floor 2nd Floor | 610 | EA | 7 6 | 10+ years | |
| | | 2nd Floor 2nd Floor | | SF | 7 | 10+ years | |
| | Walls - Masonry | | 1,450 | SF SF | | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 230 | | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 4,173 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 6,448 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor | 1,925 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 9,210 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 805 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 188 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 28 | SF | 7 | 10+ years | |
| | Doors - Wood Doors include hw | 3rd Floor | 4 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | 3rd Floor | 4 | EA | 7 | 10+ years | |

Building: Main





| Catego | ry : Interior | | В | Building : Main | | | 001 O Homan Avenoe, Omcago, ie 00002 |
|---------|--------------------------------------|---------------|----------|-----------------|--------|-------------|--------------------------------------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Terrazzo | 3rd Floor | 10,015 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 47 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 115 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 3rd Floor | 580 | EΑ | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 980 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 3,700 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 3,672 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd Floor | 650 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Basement | 4,725 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Basement | 8 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | Basement | 2 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | Basement | 4,725 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Basement | 36 | EA | 7 | 6-10 years | |
| | Walls - Masonry | Basement | 2,700 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Basement | 8,100 | SF | 7 | 10+ years | |
| | | | | | | | |
| _Safety | | | | | | | |
| | Camera Viewing Station | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Metal Detector | 1st Floor | 4 | EΑ | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 38 | EA | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 30 | EA | 7 | 6-10 years | |
| | | | | | | | |
| _Stairs | Calling Diagram/Downstall | Ot-: | F00 | 0.5 | 7 | 40 | |
| | Ceiling - Plaster/Drywall | Stairwell # A | 520 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | Stairwell # A | 1,362 | SF LF | 7 | 10+ years | |
| | Handrails | Stairwell # A | 246 | | 7 | 10+ years | |
| | Lighting - Lay-in | Stairwell # A | 16 | EΑ | 7 | 6-10 years | |
| | Lighting - Wall Mounted | Stairwell # A | 6 | EΑ | 7 7 | 6-10 years | |
| | Rescue Panel | Stairwell # A | 2 | EA | | 10+ years | |
| | Stairs - Terrazzo | Stairwell # A | 82 | LF SF | 7 7 | 10+ years | |
| | Walls - Masonry | Stairwell # A | 984 | | 7 7 | 10+ years | |
| | Walls - Metal Panel | Stairwell # A | 196 | SF | | 10+ years | |
| | Walls - Structural Glazed Tile | Stairwell # A | 816 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Stairwell # B | 280 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | Stairwell # B | 1,134 | SF | 7 | 10+ years | |
| | Handrails | Stairwell # B | 112 | LF. | 7 | 10+ years | |
| | Lighting - Lay-in | Stairwell # B | 6 | EΑ | 7 | 6-10 years | |
| | Rescue Panel | Stairwell # B | 1 | EA | 7 | 10+ years | |
| | Stairs - Terrazzo | Stairwell # B | 56 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | Stairwell # B | 2,088 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Stairwell # C | 380 | SF | 7 | 10+ years | One short |
| | Ceiling - Plaster/Drywall | Stairwell # C | 4 | SF | 5 | 1-2 years | Cracked |
| | Floor - Terrazzo | Stairwell # C | 1,134 | SF | 7 | 10+ years | |
| | Handrails | Stairwell # C | 160 | LF | 7 | 10+ years | |







Category : Interior **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Lay-in Stairwell # C 6 EΑ 6-10 years 7 Rescue Panel Stairwell # C EΑ 7 1 10+ years Stairs - Terrazzo Stairwell # C 68 LF 7 10+ years Stairwell # C SF 7 Walls - Concrete Block 2,088 10+ years SF Ceiling - Lay-in Stairwell # D 320 6 10+ years SF Floor - Concrete 7 Stairwell # D 436 10+ years Floor - Terrazzo Stairwell # D SF 7 10+ years 436 LF Handrails Stairwell # D 112 7 10+ years Lighting - Pendent/Surface Stairwell # D 6 EΑ 6 6-10 years Lighting - Wall Mounted Stairwell # D 4 EΑ 6 6-10 years Stairs - Concrete Stairwell # D 28 LF 6 10+ vears LF Stairs - Terrazzo Stairwell # D 38 7 10+ years Walls - Concrete Block Stairwell # D 600 SF 6 10+ years SF 6 Walls - Masonry Stairwell # D 120 10+ years Walls - Structural Glazed Tile Stairwell # D SF 6 480 10+ years Ceiling - Lay-in SF 7 Stairwell # F 280 10+ years Floor - Concrete SF 7 Stairwell # E 436 10+ years SF Floor - Terrazzo Stairwell # E 436 7 10+ years LF Handrails Stairwell # E 112 7 10+ years Lighting - Pendent/Surface Stairwell # E 6 EΑ 7 6-10 years Lighting - Wall Mounted Stairwell # E 4 EΑ 7 6-10 years Stairs - Concrete LF 7 Stairwell # E 28 10+ years LF Stairs - Terrazzo 7 Stairwell # E 28 10+ years Walls - Concrete Block SF 7 Stairwell # E 600 10+ years Stairwell # F 120 SF 7 Walls - Masonry 10+ years SF Walls - Structural Glazed Tile Stairwell # E 480 7 10+ years Ceiling - Plaster/Drywall SF Stairwell # F 60 7 10+ years Floor - Concrete Epoxy/ Painted Stairwell # F 414 SF 7 10+ years LF Handrails Stairwell # F 58 7 10+ years Lighting - Pendent/Surface Stairwell # F 4 EΑ 7 6-10 years Stairs - Concrete LF Stairwell # F 29 6 10+ vears SF Walls - Concrete Block Stairwell # F 1.200 7 10+ years SF 7 Ceiling - Plaster/Drywall Stairwell # G 380 10+ years Floor - Concrete Epoxy/ Painted Stairwell # G 280 SF 7 10+ years LF 7 Handrails Stairwell # G 38 10+ years Lighting - Pendent/Surface EΑ 7 Stairwell # G 4 6-10 years Stairs - Concrete LF Stairwell # G 29 7 10+ years Walls - Concrete Block SF Stairwell # G 960 7 10+ years SF Ceiling - Lay-in Stairwell # K 90 7 10+ years SF Floor - Concrete Epoxy/ Painted Stairwell # K 90 5 10+ years LF Handrails Stairwell # K 22 7 10+ years FΑ 7 Lighting - Lay-in Stairwell # K 4 6-10 years Rescue Panel Stairwell # K 1 EΑ 7 10+ years Stairs - Concrete LF 7 Stairwell # K 11 10+ years



Sarah E. Goode STEM Academy 7651 S Homan AVENUE, Chicago, IL 60652

| Catego | ry : Interior | | В | uilding | Building : Main | | | | | | |
|------------|---------------------------------|---------------|----------|---------|-----------------|-------------|----------|--|--|--|--|
| | | | | | | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | | |
| | Walls - Concrete Block | Stairwell # K | 528 | SF | 7 | 10+ years | | | | | |
| | Ceiling - Lay-in | Stairwell # L | 150 | SF | 7 | 10+ years | | | | | |
| | Floor - Concrete Epoxy/ Painted | Stairwell # L | 240 | SF | 5 | 10+ years | | | | | |
| | Handrails | Stairwell # L | 38 | LF | 7 | 10+ years | | | | | |
| | Lighting - Pendent/Surface | Stairwell # L | 2 | EΑ | 7 | 6-10 years | | | | | |
| | Stairs - Concrete | Stairwell # L | 19 | LF | 7 | 10+ years | | | | | |
| | Walls - Concrete Block | Stairwell # L | 480 | SF | 7 | 10+ years | | | | | |
| Vertical (| Conveyance | | | | | | | | | | |
| | Elevator - Hydraulic Elevator | 1st Floor | 1 | EA | 6 | 10+ years | | | | | |
| | Elevator - Lula | 1st Floor | 1 | EΑ | 6 | 10+ years | | | | | |



Category : Site Building : Site

| outogo. | y . Oite | | | unung | . 0 | Recommend | |
|---------|---|--------------------|-----------|-------|--------|-------------|----------|
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | item - Type | Location | Quantity | COM | Italik | Replacement | Comments |
| etic | Dug out | East | 2 | EA | | 10 | |
| | Dug out Metal Bleachers | East | 2 470 | LF | 6 7 | 10+ years | |
| | | | | SF | | 10+ years | |
| | Surface - Natural | East | 172,615 | | 6 | 10+ years | |
| | Metal Bleachers | NE | 315 | LF | 7 | 10+ years | |
| | Surface - Asphalt | NE Nua | 30,000 | SF | 6 | 6-10 years | |
| | Lighting | NW | 11 | EΑ | 7 | 10+ years | |
| | Metal Bleachers | NW | 1,885 | LF | 7 | 10+ years | |
| | Surface - Synthetic including exc & retention | NW | 93,190 | SF | 7 | 10+ years | |
| | Surface - Synthetic | NW | 41,225 | SF | 7 | 10+ years | |
| | Surface - Synthetic | NW | 7,020 | SF | 7 | 10+ years | |
| I/Drai | nage | | | | | | |
| | Civil/ Drainage - Bioswale | Entire Site | 38,165 | SF | 6 | 10+ years | |
| | Civil/ Drainage - Catch Basin | Entire Site | 11 | EΑ | 6 | 10+ years | |
| | Civil/ Drainage - Site Drain | Entire Site | 15 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 14 | EΑ | 6 | 10+ years | |
| | ON Dramage One Mariner | | | _, 、 | Ü | io. youro | |
| cing | | | | | | | |
| | Fencing - Chain Link | Entire Site | 2,225 | LF | 7 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 2,530 | LF | 7 | 10+ years | |
| | | | | | | | |
| dscar | | | | | | | |
| | Benches | Entire Site | 19 | EA | 7 | 10+ years | |
| | Landscape - Grass | Entire Site | 99,580 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Concrete | Entire Site | 11,580 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Pavers | Entire Site | 150 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Pavers | Entire Site | 13,755 | SF | 6 | 10+ years | |
| | Lighting - Pole Mounted | Entire Site | 39 | EA | 6 | 10+ years | |
| | Lighting - Pole Mounted | Entire Site | 9 | EA | 6 | 10+ years | |
| | Parkway trees | Entire Site | 125 | EA | 6 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 28,680 | SF | 6 | 10+ years | |
| | Retaining Wall - Concrete | Entire Site | 4,275 | SF | 7 | 10+ years | |
| | Retaining Wall - Concrete | Entire Site | 2,740 | SF | 7 | 10+ years | |
| | Retaining Wall - Masonry | Entire Site | 250 | SF | 7 | 10+ years | |
| | Trash Receptacles | Entire Site | 14 | EA | 6 | 10+ years | |
| | Walking Path - Crushed Stone | Entire Site | 2,700 | SF | 6 | 10+ years | |
| | Walking Path - Crushed Stone | Entire Site | 2,005 | SF | 6 | 10+ years | |
| , | - | | , , , , , | | | , | |
| king L | | D. I I N. d. | | | | | |
| | Concrete Curbs | Parking Lot- North | 1,120 | LF | 6 | 10+ years | |
| | Interior Plantings | Parking Lot- North | 215 | LF | 6 | 10+ years | |
| | | | | | | | |



| Catego | ry : Site | | В | uilding | _ | | |
|-----------|--|--------------------|----------|---------|------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pole Mounted | Parking Lot- North | 10 | EA | 6 | 10+ years | |
| | Pavers | Parking Lot- North | 38,865 | SF | 6 | 10+ years | |
| | Trash Compactor | Parking Lot- North | 1 | EA | 6 | 10+ years | |
| | Vehicular Screening | Parking Lot- North | 740 | LF | 6 | 10+ years | |
| _Sidewall | KS. | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 100 | LF | 7 | 10+ years | |
| | Sidewalks - Internal Walks | Entire Site | 5,210 | LF | 7 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 29,465 | SF | 7 | 10+ years | |
| _Signage | | | | | | | |
| | Flag Pole - Flag Pole | South | 1 | EA | 7 | 6-10 years | |
| | Marquee - Building Mounted Back Lighted w/ LED | South | 1 | EA | 6 | 6-10 years | |
| | Monument - Building Mounted Cut Letter Sign | South | 1 | EA | 6 | 6-10 years | |

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Goode HS Page: 58 of 60 Assessment Date: 04/16/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

| Classroom Summary | | | | Floor Plan | | Glazed | Operable | | |
|-------------------|-------------------|---------------|--------|------------|-------|--------|----------|--------|--------|
| | | | Room | Room | Area | Window | Window | Window | Smart- |
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | | | | | | | | | |
| Art Room | Art Room | 2nd Floor | 200B | 200B | 1,220 | 350 | 0 | N | N |
| Art Room | Art Room | 2nd Floor | 200D | 200d | 1,220 | 350 | 0 | N | N |
| Band Room | Band Room | 2nd Floor | 200H | 200H | 1,570 | 375 | 0 | N | N |
| Choral Room | Choral Room | 2nd Floor | 200G | 200G | 1,250 | 300 | 0 | N | N |
| Computer Lab | Computer Lab | 2nd Floor | 225 | 225 | 1,175 | 197 | 10 | Υ | Υ |
| Computer Lab | Computer Lab | 3rd Floor | 325 | 325 | 1,382 | 197 | 10 | Y | Υ |
| Computer Lab | Computer Lab | 3rd Floor | 326 | 326 | 1,175 | 173 | 7 | Υ | N |
| Computer Lab | Regular Classroom | 3rd Floor | 328 | 328 | 795 | 179 | 10 | Υ | N |
| Office | Computer Lab | 1st Floor | 100 D | 100 D | 1,046 | 175 | 45 | N | N |
| Regular Classroom | Computer Lab | 2nd Floor | 226 | 226 | 1,175 | 173 | 7 | Υ | N |
| Regular Classroom | Fitness Room | Basement | 010 | 010 | 1,302 | 0 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 695 | 36 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | 219 | 795 | 151 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 220 | 220 | 795 | 23 | 2 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 221 | 221 | 795 | 195 | 10 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 222 | 222 | 795 | 123 | 5 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 223 | 223 | 795 | 153 | 5 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 224 | 224 | 795 | 163 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 228 | 228 | 795 | 179 | 10 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 230 | 230 | 795 | 179 | 10 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 232 | 232 | 795 | 149 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 234 | 234 | 795 | 149 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 236 | 236 | 795 | 195 | 10 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 238 | 238 | 795 | 153 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 239 | 239 | 795 | 153 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 316 | 316 | 732 | 135 | 8 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 319 | 319 | 795 | 151 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 320 | 320 | 795 | 128 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 321 | 321 | 795 | 195 | 10 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 322 | 322 | 795 | 123 | 5 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 323 | 323 | 795 | 153 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 324 | 324 | 795 | 163 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 330 | 330 | 795 | 179 | 10 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 332 | 332 | 795 | 149 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 334 | 334 | 795 | 149 | 7 | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 336 | 336 | 795 | 195 | 10 | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 338 | 338 | 795 | 153 | 7 | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 339 | 339 | 795 | 153 | 7 | Y | N |

Campus Name: Goode HS Page : 59 of 60 Assessment Date: 04/16/2024





Classroom Summary

| | | | | Floor Plan | | Glazed | Operable | | |
|---------------------|---------------------|---------------|--------|------------|-------|--------|----------|--------|--------|
| | | | Room | Room | Area | Window | Window | Window | Smart- |
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Science Lab Level 1 | Science Lab Level 1 | 2nd Floor | 235 | 235 | 1,290 | 182 | 4 | Υ | Z |
| Science Lab Level 1 | Science Lab Level 1 | 3rd Floor | 335 | 335 | 1,290 | 182 | 4 | Υ | N |
| Science Lab Level 2 | Science Lab Level 2 | 2nd Floor | 227 | 227 | 1,290 | 182 | 6 | Υ | N |
| Science Lab Level 2 | Science Lab Level 2 | 2nd Floor | 231 | 231 | 1,290 | 202 | 6 | Υ | N |
| Science Lab Level 2 | Science Lab Level 2 | 3rd Floor | 327 | 327 | 1,290 | 182 | 6 | Υ | N |
| Science Lab Level 2 | Science Lab Level 2 | 3rd Floor | 331 | 331 | 1,290 | 202 | 6 | Υ | N |
| Special Education | Computer Lab | 1st Floor | 119 | 119 | 774 | 0 | 0 | N | N |
| Weight | Weight | Basement | 012 | 012 | 950 | 0 | 0 | | |