

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1953	3	63,323
Addition	2013	3	35,910
Campus Total			99,233

Catego	ry : Exterior	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1	1	EA	6	10+ years	
	Exterior Doors - Store Front	1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	1	1	EA	6	10+ years	
	Exterior Stairs - Concrete	1	48	LF	6	10+ years	
	Exterior Stairs - Concrete	1	48	LF	5	1-2 years	Cracked, corroding reinforcement
	Stair Handrail - Steel_Stair Handrail	1	30	LF	6	10+ years	•
	Exterior Doors - Exterior Steel Door	10	1	EA	6	10+ years	
	Exterior Stairs - Concrete	10	42	LF	6	10+ years	
	Exterior Stairs - Concrete	10	3	LF	5	1-2 years	Missing top of retaining wall. No support for post
	Stair Handrail - Steel_Stair Handrail	10	20	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	11	1	EA	6	10+ years	
	Exterior Stairs - Concrete	11	15	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	11	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	12	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	12	20	LF	5	0-1 year	Corroding
	Exterior Stairs - Stone	12	3	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	12	10	LF	5	0-1 year	Corroding
	Exterior Doors - Exterior Steel Door	13	1	EA	6	10+ years	-
	Exterior Stairs - Steel or Aluminum	13	20	LF	6	10+ years	
	Exterior Stairs - Stone	13	3	LF	5	1-2 years	Broken stone, piece missing
	Stair Handrail - Steel_Stair Handrail	13	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	14	1	EA	6	10+ years	



Building : Main Category : Exterior Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Exterior Stairs - Concrete 14 25 LF 6 10+ vears Exterior Stairs - Concrete LF 0-1 vear 14 10 4 Shattered concrete Stair Handrail - Steel_Stair Handrail 14 20 LF 6 10+ years Entrance Control - Audio and Video 15 ΕA 6 1 10+ years 2 Exterior Doors - Exterior Steel Door 15 EΑ 6 10+ years Exterior Doors - Transom Lite 15 1 EΑ 6 10+ years **Exterior Stairs - Concrete** 15 72 LF 6 10+ years Power Door Operator and Controls 15 1 EΑ 7 10+ years Ramp Handrail - Steel Ramp Handrail 15 42 LF 6 10+ years Ramps - Concrete LF 15 30 6 6-10 years LF Ramps - Concrete 15 36 5 1-2 vears Broken, spalled, exposed reinforcements Stair Handrail - Steel Stair Handrail 15 30 LF 6 10+ years ΕA Exterior Doors - Exterior AMP Door 16 4 6 10+ years 2 Exterior Doors - Transom Lite ΕA 16 6 10+ years 16 LF 6 Exterior Stairs - Concrete 120 10+ years LF 5 Exterior Stairs - Concrete 16 60 1-2 years Large cracks throughout stairs Exterior Doors - Exterior Steel Door 2 1 EΑ 6 10+ years 2 Exterior Doors - Transom Lite 1 ΕA 6 10+ vears 2 **Exterior Stairs - Stone** 21 LF 6 10+ years Exterior Stairs - Stone 2 2 LF 4 1-2 years Broken stone 2 LF 6 Stair Handrail - Steel Stair Handrail 10 10+ years Exterior Doors - Exterior Steel Door 2.5 6 1 EA 10+ years LF Exterior Stairs - Concrete 2.5 83 6 10+ years Stair Handrail - Steel Stair Handrail 2.5 21 LF 6 10+ years I F Stair Handrail - Steel Stair Handrail 2.5 3 3 0-1 year Not attached to wall, missing attachment **Exterior Doors - Store Front** 3 ΕA 6 10+ years 2 Exterior Doors - Transom Lite 3 1 ΕA 6 10+ years **Exterior Stairs - Concrete** 3 30 LF 6 10+ years LF Exterior Stairs - Concrete 3 35 5 1-2 years Cracked steps with corroding reinforcement 3 LF 6 12 Stair Handrail - Steel_Stair Handrail 10+ years Stair Handrail - Steel Stair Handrail 3 12 LF 3 0-1 vear Missing railing Exterior Doors - Exterior Steel Door 2 9 ΕA 6 10+ years Exterior Doors - Transom Lite 9 6 1 EΑ 10+ years LF **Exterior Stairs - Concrete** 9 45 6 6-10 years Exterior Stairs - Concrete 9 20 LF 5 1-2 years Large cracks on landing ,risers and treads LF 6 Exterior Stairs - Stone 9 6 10+ vears LF Stair Handrail - Steel_Stair Handrail 9 24 6 10+ years Foundation Foundation - Concrete 7 Entire Building 1,038 LF 10+ years



Catego	ry : Exterior		В		-		
				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Foundation - Concrete	Entire Building	20	LF	6	1-2 years	Foundation cracks are seeping water into the basement. Areas around the engineer's office. Also cracked and broken/spalled concrete at air and light wells to basement
	Superstructure - Steel with Clay Tile Arch	Entire Building	63,323	SF	7	10+ years	5
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	16	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years	
_Roof Sys	stem						
-	Access Ladder - Metal	A	3	EA	7	10+ years	
	Chimney - Brick Chimney- Stainless Steel Liner	A	34	LF	6	10+ years	
	Chimney - Brick Chimney- Stainless Steel Liner	A	6	LF	4	1-2 years	Open joints and large cracks
	Coping - Clay Tile	А	60	LF	6	10+ years	
	Coping - Stone	A	998	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A	12	LF	6	6-10 years	
	Downspouts - Interior Downspouts	A	320	LF	6	10+ years	
	Parapet - 16" - 30" Height	A	673	LF	6	10+ years	
	Parapet - 16" - 30" Height	A	15	LF	5	1-2 years	Open joints, no cracked to brick
	Parapet - Parapet > 30"	А	331	LF	6	10+ years	
	Parapet - Parapet > 30"	А	40	LF	4	1-2 years	Cracked brick, open joints
	Roof - Modified Bitumen	А	24,041	SF	4	0-1 year	Blistering throughout, soft spots
	Roof Hatch - Metal	A	3	ĒA	5	0-1 year	Old, flimsy latch, with repairs. Please do not close properly.
	Roof Structure - Steel with Clay Tile Arch	А	24,041	SF	7	10+ years	
	Coping - Stone	В	64	LF	6	10+ years	
	Downspouts - Interior Downspouts	В	32	LF	6	10+ years	
	Parapet - 16" - 30" Height	В	64	LF	6	10+ years	
	Roof - Modified Bitumen	В	440	SF	4	0-1 year	Blistering throughout
	Roof Structure - Steel with Clay Tile Arch	В	440	SF	7	10+ years	3 3
	Access Ladder - Metal	С	1	ĒA	7	10+ years	
	Coping - Stone	С	180	LF	6	10+ years	
	Downspouts - Interior Downspouts	C	100	LF	6	10+ years	
	Parapet - 16" - 30" Height	C	130	LF	6	10+ years	
	Parapet - Parapet > 30"	Ċ	50	LF	5	1-2 years	Open joints
	Roof - Modified Bitumen	C	3,850	SF	5	0-1 year	Blistering throughout
	Roof Structure - Steel with Clay Tile Arch	C	3,850	SF	7	10+ years	5 5

Walls



6140 S Melvina AVENUE, Chicago, IL 60638 **Category : Exterior Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Cheek-Wall - Stone Entire Building 376 SF 6 2-5 years Exterior Walls - Brick 16.562 SF 6 10+ years Entire Building Exterior Walls - Brick Entire Building 2.013 SF 4 1-2 years Open joints, cracked spalled, broke brick, bowing walls, walls pulling away from plumb. how much is this? Much damage has been caused by caulking that has been placed underneath the windows throughout the building. Apparently, water is getting trapped in the wall with no place to drain. Exterior Walls - Prefabricated Metal Panel Entire Building 285 SF 6 10+ years Wall Exterior Walls - Stone-Cast Entire Building 700 SF 6 10+ years Entire Building SF 5 10+ years Exterior Walls - Stone-Cast 100 Exterior Walls - Stone-Cast SF 4 Entire Building 12 1-2 years Spalled, broken, missing stone Windows Guard - Guards perforated Entire Building 174 SF 6 10+ years Lintels - Steel Entire Building 939 LF 6 10+ years LF Lintels - Steel Entire Building 30 4 1-2 years Corroding, deflecting and goals are causing damage to a wall above SF Skylite - Glass Double-Pane 6 Entire Building 96 10+ years Windows - Casement Aluminum Double-SF 5 Entire Building 6.195 0-1 vear Much damage has been caused by caulking that has been placed pane underneath the windows throughout the building. Apparently, water is getting trapped in the wall with no place to drain. This is causing buckling walls, spalling and breaking brick. Some covers between windows are also missing or falling off. Windows - Decorative Entire Building 204 SF 6 10+ years Windows - Louver Entire Building 115 SF 6 10+ years **Category : Electrical Building : Main** Recommend Item - Type Location Quantity UOM Rank Replacement Comments Group Emergency System UPS - 30 - 60 KW Boiler Room ΕA 3 0-1 year Abandoned/disconnected 1 Emergency A/C Power - Auditoium and SF Entire Building 3.959 6 6-10 years Aisle Liahtina Emergency A/C Power - Corridors and Entire Building 8.742 SF 6 6-10 years

Stairs



						6	140 S Melvina AVENUE, Chicago, IL 60638
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Students Toilets	Entire Building	1,497	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and	Entire Building	4	EA	6	6-10 years	
	Aisle Lighting						
	Emergency Battery Packs - Corridors and	Entire Building	20	EA	6	6-10 years	
	Stairs						
	Emergency Battery Packs - Gym	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose	Entire Building	2	EA	6	6-10 years	
	Room						
	Emergency Battery Packs - Students Toilets	Entire Building	1	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	63,323	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	63,323	SF	6	6-10 years	
		C C				2	
Main Se							
	Main Electrical Service - 1200 A	Boiler Room	1	EA	7	10+ years	
	277/480/3PH					-	
	PA System	Entire Building	63,323	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp	Entire Duliding	1		'	Tor years	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	10+ years	
	Transformers - 277/+00 - 120/200	Entire Duliding	Z	LA	0	TO+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Annunciator.
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building	63,323	SF	6	10+ years	
	Fire Alarm_System	Entire Building	63,323	SF	6	10+ years	
0-1	me - Maakaniaal		_				
Catego	ry : Mechanical		В	uilding	: Main	Decommond	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
			Quantity		Nalik	Replacement	Comments
Air Cond	5			F •		4.0	
	Chemical Pot Feeder	Mechanical Room	1	EA	4	1-2 years	Heavily corroded from leaks. Chiller



Catego	ry : Mechanical		B	uilding	: Main		
-			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Glycol Feed	Mechanical Room	1	EA	6	6 10 vooro	in Addition. Chiller located in addition.
	Condensing Unit- Roof Mounted - 31-50	Roof	1	EA	6	6-10 years 6-10 years	Chiller located in addition.
	tons	RUUI	I	EA	0	0-10 years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	5	2-5 years	Serves MDF room.
Air Hand	lling Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils and Chilled Water Coils - 8001 - 15000 cfm	2nd Floor	1	EA	5	6-10 years	Serves auditorium.
	Air Intake	2nd Floor	1	EA	5	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	2nd Floor	1	EA	5	2-5 years	
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	2nd Floor	100	LF	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils and Chilled Water Coils - 8001 - 15000 cfm	Basement - North	1	EA	4	2-5 years	Chilled water coil corroding heaving fan and motor dated
	Air Intake	Basement - North	1	EA	5	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Basement - North	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement - North	6	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement - North	50	LF	5	6-10 years	
	Zone Dampers	Basement - North	22	EA	5	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils and Chilled Water Coils - 25001 - 35000 cfm	Basement - South	1	EA	5	2-5 years	
	Air Intake	Basement - South	1	EA	5	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Basement - South	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement - South	6	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement - South	50	LF	5	6-10 years	
	Zone Dampers	Basement - South	12	EA	5	6-10 years	
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Entire Building	2	EA	5	2-5 years	
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Entire Building	1	EA	5	2-5 years	
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons	Roof	1	EA	6	6-10 years	

Boiler Systems



						6	140 S Melvina AVENUE, Chicago, IL 60638
Catego	ry : Mechanical		В	uilding	: Main	_	
•			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Auxiliary- Scotch Marine- Steam Low	Entire Building	2	EA	6	6-10 years	
	Pressure Boiler - 151 - 200 HP		-		-	0.40	
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	
	Chemical Feeder	Entire Building	2	EA	5	1-2 years	For hot water, deteriorated
	Combustion Dampers	Entire Building	4	EA	6	6-10 years	
	Condensate Pump	Entire Building	1	EA	5	2-5 years	
	Condensate Pump	Entire Building	1	EA	5	2-5 years	
	Feed Water Pumps and Tank	Entire Building	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	6-10 years	
	Steam- Low Pressure Boiler - 151 - 200 HP						
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	6-10 years	
	Steam- Low Pressure Boiler - 151 - 200 HP			. –	-		
	Piping - Condensate Pipe- Steel	Entire Building	400	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	400	LF	6	6-10 years	
	Steam Traps	Entire Building	30	EA	5	2-5 years	
	Vacuum Pump	Entire Building	2	EA	4	1-2 years	One pump leaking
Heat Exc	shanders						
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	1	EA	6	10+ years	
	Type		I	ĽA	0	IUT years	
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	1	EA	6	10+ years	
	Type		I	LA	0	ior years	
Heating							
	Radiators - Steam	Entire Building	27	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	4	EA	6	6-10 years	
	Unit Heater - Steam	Gym	2	EA	5	2-5 years	
Mechani	cal Plumbing						
	Chilled Water Pump - Less than 10	Basement	1	EA	5	2-5 years	
	Chilled Water Pump - Less than 10	Basement	1	EA	5	2-5 years	
	Chilled Water Pump - Less than 10	Basement	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	4	0-1 year	Leaking
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	10+ years	Hot and chilled water
-							
<u> l empera</u>	ture Control		-	F •		0.5	
	Electric Thermostat	Entire Building	3	EA	5	2-5 years	Gym unit heaters, computer room, MDF
	Hybrid Pneumatic/DDC System	Entire Building	63,323	SF	4	0-1 year	Engineer not able to adjust any
							temperatures, only monitor setpoints
							and current temperatures
	Thermostats - Pneumatic	Entire Building	40	EA	5	2-5 years	



6140 S Melvina AVENUE, Chicago, IL 60638 **Building : Main** Category : Mechanical Recommend **Replacement** Comments Item - Type Location Quantity UOM Rank Group Unit Ventilation Unit Ventilators- Floor Mounted- Hot Water Entire Building 31 ΕA 5 6-10 years & Chilled Water Coils Ventilation Exhaust Fans- Indoor - 1501 - 8000 CFM Entire Building 1 FΑ 5 Engineer keeps off due to age and 1-2 years corrosion, noisy Heavy vibrations Exhaust Fans- Indoor - 1501 - 8000 CFM Entire Building EA 1 4 1-2 years Exhaust Fans- Roof Mounted - 500 - 1500 ΕA 3 Not operational, corroded Entire Building 1 0-1 year CFM Roof Mounted Duct Work Entire Building 50 LF 5 2-5 years **Category : Plumbing Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement **Comments** Hot Water Gas Heater - 300001 - 600000 BTU/HR Mechanical Room 1 ΕA 6 6-10 years ΕA 6 Hot Water Storage Tank_Gas - 201 - 500 Mechanical Room 1 10+ years Gallons Piping SF Domestic Piping-Hot Water Return Lines Entire Building 63.323 6 6-10 years Domestic Piping-Hot Water Return Risers Entire Building SF 6 63.323 6-10 years Domestic Piping-Hot Water from Risers to SF Entire Building 63,323 6 6-10 years Fixtures Domestic Piping-Hot/Cold Water Supply Entire Building 63,323 SF 6 6-10 years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply 63.323 SF Entire Building 6 6-10 years (Risers) Domestic Piping-Hot/Cold Water Supply Entire Building 63,323 SF 6 6-10 years (from Risers to Fixtures) Sanitary Piping SF Entire Building 63,323 6 6-10 years Storm Piping SF 5 Entire Building 63,323 6-10 years Vent Piping 63,323 SF Entire Building 6 6-10 years Pumps Pumps - Ejector-Duplex Entire Building 1 ΕA 6 10+ years Pumps - Ejector-Duplex Entire Building 5 1 EΑ 2-5 years Pumps - Sump-Simplex Entire Building 1 ΕA 5 2-5 years In crawlspace.



Building : Main Category : Room Recommend **Replacement** Comments Group Item - Type Location Quantity UOM Rank Administrative Suites/Offices Ceiling - Plaster/Drywall 116 West- Office SF 6 104 10+ years Ceiling - Plaster/Drywall 116 West- Office 5 SF 5 0-1 year Water damage Doors - Wood Doors inclu hw 116 West- Office 1 6 EΑ 10+ years Floor - Tile/Sheet 116 West- Office SF 5 10+ years 109 Lighting - Pendent/Surface FΑ 116 West- Office 2 6 6-10 years Power Distribution 116 West- Office 4 FΑ 6 6-10 years SF Walls - Plaster/Drvwall 116 West- Office 224 6 10+ years SF Ceiling - Exposed Engineer's Office 220 6 10+ vears Doors - Wood Doors inclu hw **Engineer's Office** 1 EΑ 6 10+ years Floor - Tile/Sheet Engineer's Office 220 SF 0-1 year 4 Chipped tiles Lighting - Pendent/Surface Engineer's Office 2 EΑ 6 6-10 years Lighting - Pendent/Surface Engineer's Office 2 ΕA 5 0-1 vear Does not work. Power Distribution Engineer's Office 4 ΕA 6 6-10 years SF 5 Walls - Concrete Block Engineer's Office 568 1-2 vears Chipping paint Ceiling - Exposed Gymnasium Office 109 SF 6 10+ years Doors - Wood Doors inclu hw FΑ Gymnasium Office 1 6 10+ vears Gymnasium Office 5 Floor - Concrete 109 SF 10+ years Lighting - Pendent/Surface **Gymnasium Office** 1 EΑ 6 6-10 years **Power Distribution Gymnasium Office** 2 ΕA 6 6-10 years SF Walls - Concrete Block Gymnasium Office 201 6 10+ years Ceiling - Plaster/Drvwall Main Office 490 SF 6 10+ vears Doors - Wood Doors inclu hw Main Office 2 EΑ 6 10+ vears Floor - Tile Main Office SF 6 490 10+ vears Lighting - Pendent/Surface Main Office 8 EΑ 6 6-10 years **Power Distribution** Main Office ΕA 6 6-10 years 14 SF 5 Storage/ Closet Main Office 56 10+ years Walls - Plaster/Drywall SF Main Office 816 6 10+ years Ceiling - Plaster/Drywall Principal's Office SF 6 160 10+ years Doors - Wood Doors inclu hw ΕA Principal's Office 1 6 10+ years Floor - Tile Principal's Office 160 SF 6 10+ years Principal's Office Lighting - Pendent/Surface 4 ΕA 6 10+ vears Power Distribution Principal's Office 6 EΑ 6 6-10 years Walls - Plaster/Drywall Principal's Office 335 SF 6 10+ years Auditorium & Theater Ceiling - Plaster/Drywall 1st Floor SF 6 4.154 10+ vears Doors - Steel Doors incl hw 1st Floor 4 FΑ 6 10+ years Doors - Wood Doors inclu hw 8 ΕA 6 1st Floor 10+ years SF 5 Floor - Concrete 1st Floor 1,980 10+ years SF 6 Floor - Tile Ceramic/ Porcelain 1st Floor 194 10+ years Floor - Tile/Sheet 1st Floor 1,980 SF 5 10+ years Lighting - Pendent/Surface 1st Floor 63 ΕA 6 6-10 years Lighting - Pendent/Surface 1st Floor 21 EΑ 5 0-1 year Does not work.



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Main Floor Seating 1st Floor 419 ΕA 5 10+ vears 1st Floor 467 SF 6 Stage 10+ years Stage Curtain 1st Floor 5 FΑ 7 10+ years Stage Lighting System ΕA 5 1st Floor 1 6-10 years Stage-Stairs - Wood 25 1 F 1st Floor 6 10+ years SF Walls - Plaster/Drywall 1st Floor 2,465 6 10+ years Walls - Structural Glazed Tile SF 6 1st Floor 2,465 10+ years Gvmnasia Ceiling - Exposed Gymnasium 3,505 SF 6 10+ years Doors - Steel Doors incl hw Gymnasium 2 EΑ 6 10+ years Doors - Wood Doors inclu hw Gymnasium 2 EΑ 6 10+ years Floor - Wood Gymnasium SF 6 10+ years 3.505 Lighting - Pendent/Surface Gymnasium 10 ΕA 6 6-10 years Lighting - Pendent/Surface ΕA 5 Gymnasium 8 0-1 vear Does not work. Scoreboards Gymnasium 1 FΑ 5 6-10 years SF 5 Storage/ Closet Gymnasium 139 10+ years Walls - Concrete Block SF Gymnasium 2,416 6 10+ years SF Walls - Structural Glazed Tile Gymnasium 1,894 6 10+ years Librarv LF Casework Library used as Classroom 200B 75 6 6-10 years Ceiling - Plaster/Drywall Library used as Classroom 200B SF 1,387 7 10+ years Doors - Wood Doors inclu hw Library used as Classroom 200B 10+ years 3 EΑ 6 Floor - Tile Library used as Classroom 200B 1,387 SF 6 10+ years Library used as Classroom 200B Lighting - Pendent/Surface 33 ΕA 6 10+ vears Storage/ Closet Library used as Classroom 200B 66 SF 7 6-10 years Walls - Plaster/Drywall Library used as Classroom 200B SF 7 2.150 10+ years Lunch & Multipurpose Room Ceiling - Lay-in 016 Basement SF 6 1.807 6-10 years SF Ceiling - Lay-in 016 Basement 120 4 0-1 year Water damage throughout, broken and missing tiles throughout Doors - Steel Doors incl hw 016 Basement 1 EΑ 6 10+ years Doors - Wood Doors inclu hw 016 Basement 3 EΑ 6 10+ years Floor - Tile/Sheet 016 Basement 1.927 SF 5 10+ vears 6-10 years Lighting - Lay-in 016 Basement 20 ΕA 6 Lighting - Lay-in 016 Basement 9 ΕA 5 0-1 year Damaged enclosures and re-lamp fixtures Walls - Concrete Block SF 016 Basement 1,138 6 10+ years MDF IDF Doors - Steel Doors incl hw 2nd Floor 1 ΕA 6 10+ years



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Finishes 2nd Floor 143 SF 6-10 vears 7 2nd Floor ΕA 7 6-10 years Other Cooling Unit 1 Ductless split system. Mechanical/ Service Rooms Janitor's Closet 1st Floor 28 SF 5 10+ years 1st Floor 66 SF 5 Mechanical/ Service Rooms 10+ years Air Tunnel **Basement** 1.643 SF 5 10+ years SF 5 Air Tunnel Basement 1,643 10+ years SF 5 Boiler Room Basement 2.043 10+ years SF 5 Mechanical/ Service Rooms Basement 761 10+ years 1.858 SF 5 Storage Room Basement 10+ years Storage Room Basement 133 SF 5 10+ years SF 5 Storage Room Basement 133 10+ years SF Storage Room Basement 156 5 10+ years Storage Room SF 5 Basement 340 10+ years Storage Room Basement 203 SF 5 10+ years Restroom 014 Basement South Unisex SF 5 Accessories 33 6-10 years Ceiling - Plaster/Drywall 014 Basement South Unisex 33 SF 6 10+ years Doors - Wood Doors inclu hw 014 Basement South Unisex 1 EΑ 6 10+ years SF 5 Floor - Tile Ceramic/ Porcelain 014 Basement South Unisex 33 10+ years Lavatory 014 Basement South Unisex 1 EA 6 6-10 years Lighting - Pendent/Surface 6 014 Basement South Unisex 1 EA 6-10 years Partitions 014 Basement South Unisex 1 EA 4 0-1 year Door missing. 014 Basement South Unisex 2 ΕA 6 Urinals 10+ years 014 Basement South Unisex SF Walls - Concrete Block 64 6 10+ years Water Closet ΕA 6 014 Basement South Unisex 1 6-10 years Accessories 107A 20 SF 5 6-10 years SF Ceiling - Plaster/Drywall 107A 20 6 10+ years Doors - Wood Doors inclu hw ΕA 6 107A 1 10+ years SF Floor - Tile Ceramic/ Porcelain 107A 20 6 10+ years Lighting - Pendent/Surface 107A ΕA 6 6-10 years 1 Walls - Plaster/Drywall 107A 39 SF 6 10+ years Water Closet 107A 1 EΑ 6 6-10 years SF Accessories 20 7 6-10 years 109A Ceiling - Plaster/Drywall 109A 20 SF 6 10+ vears Doors - Wood Doors inclu hw 109A 1 FΑ 6 10+ years Floor - Tile Ceramic/ Porcelain 20 SF 6 109A 10+ years 7 Lavatory 109A 1 EΑ 10+ years Lighting - Pendent/Surface 109A 1 EΑ 6 10+ years Walls - Plaster/Drywall 109A SF 6 10+ years 14 SF Walls - Tile Ceramic/ Porcelain 109A 25 6 10+ years Water Closet 109A 1 EΑ 6 6-10 years



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Accessories 111A 47 SF 6-10 years 7 Ceiling - Plaster/Drywall 47 SF 111A 6 10+ vears Doors - Wood Doors inclu hw 111A 1 EΑ 6 10+ years Floor - Tile Ceramic/ Porcelain SF 6 111A 47 10+ years Lavatory 111A 1 EΑ 6 6-10 years Lighting - Pendent/Surface 1 EΑ 6 10+ years 111A Lighting - Wall Mounted 111A ΕA 6 10+ years 1 Partitions 111A 1 ΕA 7 6-10 years Walls - Plaster/Drywall 111A 91 SF 6 10+ years Water Closet EΑ 6 6-10 years 111A 1 Accessories 1st Floor 290 SF 5 6-10 vears Ceiling - Plaster/Drywall 1st Floor 275 SF 6 10+ years Ceiling - Plaster/Drywall SF 5 1-2 years 1st Floor 15 Bubbling ceiling ΕA 6 Doors - Wood Doors inclu hw 1st Floor 3 10+ years SF 6 Floor - Tile Ceramic/ Porcelain 1st Floor 290 10+ years Floor Drain FΑ 7 1st Floor 1 10+ years 2 Lavatorv 1st Floor EΑ 6 6-10 years Lighting - Lay-in 1st Floor 1 ΕA 6 6-10 years Lighting - Pendent/Surface 2 1st Floor ΕA 6 6-10 years Partitions 1st Floor 9 EΑ 5 6-10 years Walls - Plaster/Drywall 1st Floor 319 SF 6 10+ years Walls - Structural Glazed Tile SF 6 1st Floor 319 10+ years 9 6 Water Closet 1st Floor EA 6-10 years SF Accessories 1st Floor 282 5 6-10 years Ceiling - Plaster/Drywall 282 SF 6 1st Floor 10+ years Doors - Wood Doors inclu hw 1st Floor 2 ΕA 6 10+ vears SF Floor - Tile Ceramic/ Porcelain 1st Floor 282 6 10+ years Floor Drain ΕA 7 6-10 years 1st Floor 1 Lavatory 1st Floor 2 EΑ 6 6-10 years Lighting - Pendent/Surface 1st Floor 3 ΕA 6 6-10 years Lighting - Pendent/Surface 1st Floor 1 ΕA 5 0-1 year Does not work. Partitions 1st Floor 2 ΕA 5 6-10 vears 3 Urinals 1st Floor FΑ 6 6-10 years Urinals 1 FΑ 6 0-1 year Not working 1st Floor 325 SF Walls - Plaster/Drywall 1st Floor 6 10+ years Walls - Structural Glazed Tile 325 SF 6 1st Floor 10+ years ΕA Water Closet 1st Floor 2 6 6-10 years 307 SF 7 6-10 years Accessories 2nd Floor SF Ceiling - Plaster/Drywall 2nd Floor 307 7 10+ years Doors - Wood Doors inclu hw ΕA 2nd Floor 4 6 10+ vears SF Floor - Tile Ceramic/ Porcelain 2nd Floor 307 7 10+ years 2nd Floor FΑ 7 6-10 vears Floor Drain 1 Lavatory 2nd Floor 2 EΑ 7 6-10 years Lighting - Lay-in 2nd Floor 1 EΑ 7 10+ years



Building : Main Category : Room Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface 2nd Floor 3 ΕA 10+ vears 6 2nd Floor 9 ΕA 7 6-10 vears Partitions Walls - Plaster/Drywall 2nd Floor 353 SF 7 10+ years Walls - Structural Glazed Tile 353 SF 7 2nd Floor 10+ years 7 Water Closet 2nd Floor 9 EΑ 6-10 years SF 7 Accessories 2nd Floor 283 6-10 years Ceiling - Plaster/Drywall 2nd Floor 283 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EΑ 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor 283 SF 7 10+ years Floor Drain 2nd Floor FΑ 4 1-2 vears Not draining properly 1 2nd Floor 2 ΕA 7 6-10 vears Lavatorv Lighting - Pendent/Surface 2nd Floor 4 EΑ 6 10+ years 2nd Floor 2 ΕA 7 6-10 years Partitions ΕA 7 Urinals 2nd Floor 4 6-10 years Walls - Plaster/Drywall 332 SF 7 2nd Floor 10+ years Walls - Structural Glazed Tile 332 SF 7 2nd Floor 10+ years ΕA 7 Water Closet 2nd Floor 2 6-10 years Accessories 2nd Floor 59 SF 7 6-10 years Ceiling - Plaster/Drvwall SF 2nd Floor 59 7 10+ vears Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years Floor - Tile 2nd Floor 59 SF 6 10+ years Lavatory 2nd Floor 1 EΑ 6 6-10 years Lighting - Pendent/Surface 6 2nd Floor 1 EA 10+ years 7 Partitions 2nd Floor 1 FΑ 6-10 years Walls - Plaster/Drywall 135 SF 7 10+ years 2nd Floor SF Walls - Plaster/Drvwall 2nd Floor 5 5 1-2 vears Water damage around base of toilet Water Closet 2nd Floor 1 EA 6 6-10 years Accessories Engineer's Toilet 33 SF 5 6-10 years SF Ceiling - Exposed **Engineer's Toilet** 33 6 10+ years Doors - Wood Doors inclu hw **Engineer's Toilet** 1 ΕA 6 10+ years SF Floor - Concrete Epoxy/ Painted Engineer's Toilet 33 4 0-1 vear Damaged. Lavatorv Engineer's Toilet 1 EΑ 6 6-10 vears Lighting - Pendent/Surface **Engineer's Toilet** 1 FΑ 6 6-10 years Walls - Concrete Block Engineer's Toilet 61 SF 6 10+ years Water Closet 6 **Engineer's Toilet** 1 EA 6-10 years SF 5 Accessories Main Office Toilet 36 6-10 years SF Ceiling - Plaster/Drywall Main Office Toilet 36 6 10+ years Doors - Wood Doors inclu hw Main Office Toilet 6 1 EA 10+ years SF Floor - Tile Ceramic/ Porcelain Main Office Toilet 36 6 10+ years ΕA Main Office Toilet 1 6 6-10 years Lavatorv Lighting - Pendent/Surface Main Office Toilet 1 ΕA 6 6-10 years Walls - Plaster/Drvwall SF 6 Main Office Toilet 83 10+ vears Water Closet Main Office Toilet EA 6 6-10 years 1 SF 5 Accessories Mens at Gymnasium 117 6-10 years



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drywall Mens at Gymnasium 97 SF 6 10+ vears Ceiling - Plaster/Drywall Mens at Gymnasium 20 SF 5 0-1 year Bubbling and peeling paint Doors - Wood Doors inclu hw Mens at Gymnasium 1 EΑ 6 10+ years Floor - Tile Ceramic/ Porcelain Mens at Gymnasium SF 6 116 10+ years SF 5 Floor - Tile Ceramic/ Porcelain Mens at Gymnasium 1 0-1 year Chipped by door Mens at Gymnasium ΕA 6 Lavatory 1 6-10 years Lighting - Pendent/Surface Mens at Gymnasium ΕA 6 6-10 years 1 Partitions Mens at Gymnasium 1 ΕA 5 6-10 years Urinals Mens at Gymnasium 2 ΕA 6 6-10 years SF Walls - Plaster/Drywall Mens at Gymnasium 138 6 10+ years Mens at Gymnasium SF Walls - Structural Glazed Tile 138 6 10+ vears Mens at Gymnasium Water Closet 1 ΕA 6 6-10 years Accessories Womens at Gymnasium SF 5 6-10 years 131 5 Womens at Gymnasium SF Ceiling - Plaster/Drywall 50 0-1 year Water damage Ceiling - Plaster/Drywall Womens at Gymnasium SF 5 81 10+ years Doors - Wood Doors inclu hw Womens at Gymnasium EΑ 6 1 10+ years SF Floor - Tile Ceramic/ Porcelain Womens at Gymnasium 131 6 10+ years Lavatorv Womens at Gymnasium 2 ΕA 6 6-10 years Lighting - Pendent/Surface Womens at Gymnasium 1 ΕA 6 6-10 vears Womens at Gymnasium Partitions 2 EΑ 5 6-10 years Walls - Plaster/Drywall Womens at Gymnasium 137 SF 6 0-1 year Paint peeling and bubbling Walls - Structural Glazed Tile Womens at Gymnasium SF 6 137 10+ years Water Closet Womens at Gymnasium ΕA 6 2 6-10 years

Category : Classroom

Building : Main

	· j · · · · · · · · · · · · · · · · · · ·						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	om #019 (Office)					•	
	Ceiling - Exposed	Basement	1,405	SF	6	10+ years	
	Chalk Board	Basement	42	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	3	EA	6	10+ years	
	Floor - Tile	Basement	1,405	SF	6	10+ years	
	Lighting - Lay-in	Basement	18	EA	6	6-10 years	
	Marker Board	Basement	12	LF	6	6-10 years	
	Storage/ Closet	Basement	179	SF	5	10+ years	
	Walls - Concrete Block	Basement	995	SF	6	10+ years	
Classroo	om #100 (Health)						
	Ceiling - Plaster/Drywall	1st Floor	408	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	408	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	10+ years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	820	SF	7	10+ years	



6140 S Melvina AVENUE, Chicago, IL 60638 **Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Work Sink FΑ 1st Floor 7 10+ vears 1 Classroom #102 (Regular Classroom) 1st Floor 9 LF Casework 6 6-10 years Ceiling - Plaster/Drywall 1st Floor SF 6 10+ years 701 LF Chalk Board 1st Floor 21 4 2-5 years Doors - Wood Doors inclu hw 1st Floor FΑ 6 10+ years 1 SF Floor - Tile 1st Floor 701 6 10+ years Lighting - Pendent/Surface 1st Floor 20 EΑ 6 6-10 years Marker Board LF 1st Floor 21 6 6-10 years Walls - Plaster/Drywall 1,012 SF 1st Floor 6 10+ years Classroom #103 (Regular Classroom) LF Casework 1st Floor 9 6 6-10 vears Ceiling - Plaster/Drywall SF 1st Floor 701 6 10+ years Chalk Board 1st Floor 15 LF 4 2-5 years Doors - Wood Doors inclu hw ΕA 6 1st Floor 1 10+ years Floor - Tile SF 6 10+ years 1st Floor 701 Lighting - Pendent/Surface FΑ 1st Floor 20 6 6-10 years Marker Board 1st Floor 10 LF 6 6-10 years SF Walls - Plaster/Drywall 1st Floor 1.010 6 10+ years Classroom #104 (Regular Classroom) LF Casework 1st Floor 27 6 6-10 years Ceiling - Plaster/Drywall 1st Floor 702 SF 6 10+ vears Ceiling - Plaster/Drywall SF 1st Floor 8 5 0-1 year Damaged. Doors - Wood Doors inclu hw ΕA 1st Floor 1 6 10+ vears Floor - Tile 1st Floor 710 SF 6 10+ vears Lighting - Pendent/Surface 1st Floor 20 ΕA 6 6-10 years Marker Board LF 6 6-10 years 1st Floor 21 SF 6 Walls - Plaster/Drywall 1.020 10+ years 1st Floor Classroom #105 (Kindergarten) Casework 1st Floor 9 LF 6 6-10 years Ceiling - Plaster/Drywall SF 1st Floor 793 6 10+ years Doors - Wood Doors inclu hw 1st Floor ΕA 6 10+ years 1 SF Floor - Tile 1st Floor 793 6 10+ years Lighting - Pendent/Surface 1st Floor 20 ΕA 6 6-10 years LF Marker Board 1st Floor 32 6 6-10 years SF Storage/ Closet 1st Floor 82 5 10+ years Walls - Plaster/Drywall 1st Floor 1.021 SF 6 10+ years Classroom #106 (Regular Classroom)



Catego	ory : Classroom		B	uilding	: Main		
	, · · · · · · · · · · · · · · · · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	708	SF	6	10+ years	
	Chalk Board	1st Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	708	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	7	EA	5	0-1 year	Does not work.
	Marker Board	1st Floor	21	LF	6	6-10 years	2000.000
	Walls - Plaster/Drywall	1st Floor	1,018	SF	6	10+ years	
Classroo	om #107 (Kindergarten)						
	Casework	1st Floor	23	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	950	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	3	ĒA	6	10+ years	
	Floor - Tile	1st Floor	950	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	4	1-2 years	Lights do not turn on without holding
						-	switch up
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	64	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,053	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	Casework	1st Floor	22	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	711	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	711	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	10+ years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,021	SF	6	10+ years	
Classroo	om #109 (Kindergarten)						
	Casework	1st Floor	33	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,049	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,049	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	26	EA	7	10+ years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Storage/ Closet	1st Floor	41	SF	7	10+ years	
	Storage/ Closet	1st Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,421	SF	6	10+ years	Quantity updated to match current
		13(1100)	1,421	5	0	io+ years	observations



atego	ry : Classroom		B	uilding	: Main		
, and get			_			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Bubbling paint under window
	Work Sink	1st Floor	1	EA	7	6-10 years	
assroo	m #110 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	701	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	701	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	ĒA	6	10+ years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	990	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	12	SF	5	1-2 years	Paint cracking and chipping
lassroo	m #111 (Regular Classroom)						
1033100	Ceiling - Plaster/Drywall	1st Floor	292	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	292	EA	6	10+ years	
	Floor - Tile	1st Floor	292	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	292	EA	6	10+ years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	673	SF	6	10+ years	
		13(1100)	010	01	0	Tor years	
lassroo	m #112 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	732	SF	6	10+ years	
	Chalk Board	1st Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	5	0-1 year	Does not work.
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,039	SF	6	10+ years	
lassroo	m #113 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	751	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	751	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	6	10+ years	
		1st Floor	5	EA	5	0-1 year	Does not work.
	Lighting - Pengent/Surface						
	Lighting - Pendent/Surface Marker Board	1st Floor	21	LF	6	6-10 years	Dood Hot Work.



Catego	ry : Classroom		В	uilding	: Main		
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #200 (Computer Lab)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	761	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	761	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	ĒA	7	10+ years	
	Marker Board	2nd Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,109	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
						, ,	
Classroo	m #201 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	752	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2	SF	6	6-10 years	
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	754	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,058	SF	7	10+ years	
Classroo	m #202 (Faculty Lounge)						
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	486	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	-00	EA	6	10+ years	
	Floor - Tile	2nd Floor	486	SF	4	0-1 year	Damaged, old, worn.
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	10+ years	Damaged, old, worn.
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	51	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	800	SF	7	10+ years	
	Walle Platen, Drywall		000	01	,	ior youro	
Classroo	m #203 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	702	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	702	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,009	SF	7	10+ years	
0							
Classroo	m #204 (Regular Classroom)	a 151					
	Casework	2nd Floor	27	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	565	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	565	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	Updated quantity
	Marker Board	2nd Floor	10	LF	6	6-10 years	,
	Walls - Plaster/Drywall	2nd Floor	980	SF	7	10+ years	
Classroo	om #205 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	704	SF	7	10+ years	
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	704	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,004	SF	7	10+ years	
lassroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	710	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	710	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,010	SF	7	10+ years	
Classroo	m #207 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	699	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	699	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	703	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	703	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	31	LF	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		THE CHICKING AVENUE, CHICago, IE 00000
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #209 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	704	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	704	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	962	SF	7	10+ years	
	Walle Place Drywall		002	01	,	ior youro	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	706	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	706	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	ĒA	6	10+ years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,006	SF	7	10+ years	
			.,	•		let jeale	
Classroo	om #211 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	701	SF	7	10+ years	
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	701	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	959	SF	7	10+ years	
Classics							
Classion	om #212 (Regular Classroom)		0	LF		0.40	
	Casework	2nd Floor	9		6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	42	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	973	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Cracking
Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	5 754	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	734	EA	6	10+ years	
	Floor - Tile	2nd Floor	754	SF	7	10+ years	
		21011001	734	0	'	ior years	



NUR S					- NA 1	0	140 S Melvina AVENUE, Chicago, IL 60638
atego	ry : Classroom		В	uilding	: Main		
	Home Trues	Lesstian	Overstitue		Denk	Recommend	Commonto
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,047	SF	7	10+ years	
atego	ry : Interior		В	uilding	: Main		
	Hom Turo	Location	Quantity	UOM	Rank	Recommend	Comments
roup orridor	Item - Type	Location	Quantity		Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	4,103	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4,105	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	6	10+ years	
		1st Floor	o 4	EA	6 5		
	Drinking Fountains - Double Fountain		4		-	10+ years	
	Drinking Fountains - Single Fountain	1st Floor		EA SF	5	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	71		6	10+ years	
	Floor - Tile/Sheet	1st Floor	4,103	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years	
	Student Lockers - One Tier	1st Floor	186	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,870	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,870	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,141	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,141	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	202	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	2,335	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,335	SF	7	10+ years	
afety							
,	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
airs							
	Ceiling - Plaster/Drywall	North	693	SF	6	10+ years	
	Floor - Terrazzo	North	426	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North	72	SF	6	10+ years	
	Floor - Tile/Sheet	North	105	SF	7	10+ years	Updated to match current observations
	Handrails	North	54	LF	7	10+ years	Updated to match current observations
	Lighting - Pendent/Surface	North	4	EA	6	6-10 years	
	Lighting - Wall Mounted	North	1	EA	6	6-10 years	
	Stairs - Terrazzo	North	127	LF	6	10+ years	
	Walls - Plaster/Drywall		966	SF	6	•	
	wans - Flastel/Diywall	North	900	ЗГ	Ö	10+ years	



Category : Interior Building : Main Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Structural Glazed Tile SF North 966 6 10+ years Ceiling - Plaster/Drywall South 692 SF 6 10+ years Floor - Terrazzo South 426 SF 6 10+ years Floor - Tile Ceramic/ Porcelain South 71 SF 6 10+ years Floor - Tile/Sheet SF 7 South 105 10+ years LF Handrails 7 South 54 10+ years Updated to match current observations Lighting - Pendent/Surface 4 ΕA South 6 6-10 years 2 Lighting - Wall Mounted South ΕA 6 6-10 years Stairs - Terrazzo LF South 127 6 10+ years Walls - Plaster/Drvwall SF South 943 6 10+ years Walls - Structural Glazed Tile South 943 SF 6 10+ years Ceiling - Plaster/Drywall 305 SF 6 10+ years West SF Floor - Terrazzo 6 West 134 10+ years Floor - Tile/Sheet 88 SF 7 West 10+ years Updated to match current observations 54 LF Handrails West 7 10+ years Updated to match current observations Lighting - Pendent/Surface ΕA West 4 6 6-10 years Lighting - Wall Mounted 2 6-10 years West ΕA 6 Stairs - Terrazzo West 104 LF 6 10+ years Walls - Plaster/Drywall 522 SF 6 10+ years West Walls - Structural Glazed Tile SF 522 6 West 10+ years



Category : Exterior Building : Addition Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Entrance Exterior Doors - Store Front 2 FΑ 7 4 10+ years 4 2 ΕA 7 Exterior Doors - Transom Lite 10+ years Entrance Control - Audio and Video 5 1 ΕA 7 10+ years **Exterior Doors - Store Front** 5 1 ΕA 7 10+ years 5 Exterior Doors - Transom Lite 1 EΑ 7 10+ years Power Door Operator and Controls 5 1 ΕA 7 10+ years Exterior Doors - Exterior Steel Door 6 1 ΕA 7 10+ years Exterior Doors - Store Front 7 2 ΕA 7 10+ vears Exterior Doors - Transom Lite 7 1 ΕA 7 10+ years Exterior Doors - Store Front 8 2 FΑ 7 10+ years 8 Exterior Doors - Transom Lite 1 ΕA 7 10+ years Foundation LF 7 Foundation - Concrete Entire Building 427 10+ years SF 7 Superstructure - Metal Deck/ Concrete Entire Building 35.910 10+ years Topping Lighting Exterior Lighting - Wall Mounted Entire Building 8 FΑ 6 10+ years Roof System Access Ladder - Metal D 7 1 EΑ 10+ years Coping - Metal D 500 LF 7 10+ years D LF Coping - Stone 25 7 10+ years **Downspouts - Interior Downspouts** D 144 LF 6 10+ vears Parapet - 16" - 30" Height D LF 30 7 10+ years Parapet - Parapet > 30" D 460 LF 7 6-10 vears Roof - Modified Bitumen D SF 10+ years 11,970 6 Roof Hatch - Metal D 7 10+ years EA 1 Roof Structure - Steel / Metal Deck/ D 11,970 SF 7 10+ years Concrete Topping Walls Exterior Walls - Brick Entire Building 15,717 SF 7 10+ years SF Exterior Walls - Brick Entire Building 3 4 1-2 years Open joints Exterior Walls - Prefabricated Metal Panel 2.256 SF 7 Entire Building 10+ years Wall Windows Curtain wall - Glazed Double Pane SF 7 Entire Building 246 10+ years



Catego	ory : Exterior		Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lintels - Steel	Entire Building	524	LF	7	10+ years		
	Storefront Windows	Entire Building	4,912	SF	7	10+ years		
	Storefront Windows	Entire Building	48	SF	7	10+ years		
	Windows - Decorative	Entire Building	68	SF	7	10+ years		
	Windows - Louver	Entire Building	160	SF	7	10+ years		
Catego	Category : Electrical Building : Addition							
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
						-		

	Ecoulion	Caantrity	•••••		Replacement	Common to
Emergency System						
Exit Signs - Corridors and Stairs	Entire Building	11	EA	7	6-10 years	
Exit Signs - Lunchroom	Entire Building	2	EA	7	6-10 years	
Emergency Battery Packs - Corridors and	Entire Building	14	EA	6	6-10 years	
Stairs						
Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
Emergency A/C Power - Corridors and	Entire Building	7,845	SF	6	10+ years	
Stairs						
Emergency A/C Power - Lunchrooms	Entire Building	5,067	SF	6	10+ years	
Emergency A/C Power - Students Toilets	Entire Building	1,068	SF	6	10+ years	
Security System - CCTV	Entire Building	35,910	SF	6	6-10 years	
Security System - Intrusion Detection	Entire Building	35,910	SF	6	6-10 years	
Main Ormaine						
Main Service						
Independent Electrical Service for	1st Floor	1	EA	6	6-10 years	For fire
emergency power				•	4.0	
Main Electrical Service - 1600 A	Electrical Room	1	EA	6	10+ years	
120/208/3PH			~-			
PA System	Entire Building	35,910	SF	6	10+ years	
Power Distribution						
Lighting and Power Panels - Above 100 A	Entire Building	12	EA	7	10+ years	
Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
Main Distribution Panels - 400 - 000 amp Main Distribution Panels - Greater than 600	Entire Building	2	EA	7	10+ years	
		Z	LA	'	IUT years	
amp						

Category : Fire Protection	Bu					
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	35,910	SF	6	10+ years	
Fire Alarm_System	Entire Building	35,910	SF	6	10+ years	
Fire Pump Controller	Entire Building	1	EA	6	10+ years	



Catego	ory : Fire Protection		Building : Addition					
	,					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Pump R	oom Assembly							
	Fire Pump - Less than 25hp	Pump Room G06	1	EA	6	10+ years		
	Jockey Pump	Pump Room G06	1	EA	6	10+ years		
						,		
Sprinkle	r System							
	Sprinkler Heads	Entire Building	35,910	SF	7	10+ years		
	Sprinkler Piping	Entire Building	35,910	SF	7	10+ years		
	Wet Sprinkler System	Entire Building	35,910	SF	6	10+ years		
0-1	mer Masheniaal	-						
Catego	ory : Mechanical		В	uliding	: Additi			
Crown	Hom Tuno	Leastion	Quantity	UOM	Donk	Recommend	Commente	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Air Cond					-			
	Chemical Pot Feeder	Entire Building	1	EA	6	6-10 years	- · · ·	
	Chemical Pot Feeder	Entire Building	1	EA	4	0-1 year	Corroded	
	Chiller-Air Cooled-Scroll Type-Roof Mounted	Entire Building	1	EA	5	6-10 years	Currently down, repairs to be done	
	- Greater than 200 tons				-		per engineer	
	Glycol Feed	Entire Building	1	EA	6	10+ years		
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	Serves elevator room and MDF room	
	than 5 tons	Deef	1	Γ.	~	0.40		
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	I	EA	6	6-10 years	Serves elevator room and MDF room	
Air Hand	dling Systems							
	Air Handling Unit-Package Single Zone-	AHU1	1	EA	6	10+ years	AHU1	
	Indoor- Hot Water and Chilled Water Coils -							
	8001-12000 cfm							
	Air Intake	AHU1	1	EA	6	10+ years		
	VAV Box	AHU1	8	EA	6	6-10 years		
	Air Handling Unit-Package Single Zone-	AHU2	1	EA	6	10+ years	AHU2	
	Indoor- Hot Water and Chilled Water Coils -							
	20001-30000 cfm							
	Air Intake	AHU2	1	EA	6	10+ years		
	VAV Box	AHU2	21	EA	6	6-10 years		
	Fan Coil Unit- Celing Mounted - Electric	Elevator Machine Room	1	EA	6	10+ years	One in elevator mechanical room (other in MDF room included in room tab).	
Heating	Devices							
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years		
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years		
	Unit Heater - Hot Water	Entire Building	6	EA	6	6-10 years		
	Radiator Panels - Electric	Student Toilets	4	EA	6	6-10 years		
			-	-//	U	o io youio		



6140 S Melvina AVENUE, Chicago, IL 60638 **Building : Addition** Category : Mechanical Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Mechanical Plumbing Hydronic Supply and Return - Steel Entire Building 700 LF 6 10+ years Hot Water Pump - Less than 10 ΕA 6 6-10 years Mechanical Room 1 Hot Water Pump - Less than 10 Mechanical Room ΕA 6 10+ years 1 Hot Water Pump - Less than 10 FΑ Mechanical Room 6 10+ years 1 Hot Water Pump - Less than 10 Mechanical Room FΑ 6 6-10 years 1 Chilled Water Pump - Less than 10 Mechanical Room 1 FΑ 6 10+ years Chilled Water Pump - Less than 10 Mechanical Room 1 ΕA 6 10+ years Chilled Water Pump - Less than 10 Mechanical Room 1 ΕA 6 10+ years Chilled Water Pump - Less than 10 Mechanical Room 1 EΑ 6 10+ years Temperature Control **DDC System** Entire Building 35.910 SF 5 2-5 vears Electric Thermostat Entire Building 8 ΕA 6 6-10 years For unit heaters, split systems, kiln hood Thermostats - DDC Entire Building 30 EΑ 6 6-10 years Ventilation Exhaust Fans- Roof Mounted - 500 - 1500 5 FΑ 6 Entire Building 6-10 years CFM Exhaust Fans- Roof Mounted - Less than Entire Building 2 EΑ 6 6-10 years 500 CFM Type I Exhaust Hood- Kitchen Entire Building 1 EA 6 10+ years Type II Exhaust Hood- Warming Kitchen Entire Building 1 ΕA 6 6-10 years For art room kiln Type II Exhaust Hood- Warming Kitchen Entire Building ΕA 6 1 10+ years **Category : Plumbing Building : Addition** Recommend Location UOM Replacement Comments Group Item - Type Quantity Rank Hot Water Electric Heater - 20 - 50 KW ΕA 6 Kitchen 1 6-10 years Gas Heater - 150000 - 300000 BTU/HR Mechanical Room 2 ΕA 6 10+ years Piping SF Domestic Piping-Hot Water Return Lines Entire Building 35,910 6 10+ years Domestic Piping-Hot Water Return Risers SF Entire Building 35.910 6 10+ years SF Domestic Piping-Hot Water from Risers to Entire Building 35.910 6 10+ years Fixtures Domestic Piping-Hot/Cold Water Supply Entire Building 35,970 SF 6 10+ years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply SF Entire Building 35,910 6 10+ years (Risers)



Building : Addition Category : Plumbing Recommend UOM Location Group Item - Type Quantity Rank **Replacement** Comments Domestic Piping-Hot/Cold Water Supply Entire Building 10+ years 35,910 SF 6 (from Risers to Fixtures) Sanitary Piping Entire Building 35,910 SF 6 10+ years Storm Piping Entire Building 35,910 SF 6 10+ years Vent Piping SF 6 Entire Building 35,910 10+ years Pumps Pumps - Domestic Booster Pump-Duplex 6-10 years Mechanical Room ΕA 5 1 Pumps - Sump-Simplex ΕA 6 6-10 years Under elevator. Mechanical Room 1

Building : Addition

Category : Room

Catego	ry : Room	Building : Addition								
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Administ	rative Suites/Offices									
	Ceiling - Lay-in	214 Office	328	SF	7	10+ years				
	Doors - Side-lite	214 Office	45	SF	7	10+ years				
	Doors - Steel Doors incl hw	214 Office	1	ĒA	7	10+ years				
	Doors - Transom Window	214 Office	9	SF	7	10+ years				
	Floor - Tile	214 Office	328	SF	7	10+ years				
	Lighting - Pendent/Surface	214 Office	4	EA	7	10+ years				
	Power Distribution	214 Office	20	EA	6	6-10 years				
	Walls - Plaster/Drywall	214 Office	631	SF	7	10+ years				
	Ceiling - Lay-in	314 Office	328	SF	7	6-10 years				
	Doors - Side-lite	314 Office	45	SF	7	10+ years				
	Doors - Steel Doors incl hw	314 Office	1	EA	7	10+ years				
	Doors - Transom Window	314 Office	9	SF	7	10+ years				
	Floor - Tile	314 Office	328	SF	7	10+ years				
	Lighting - Pendent/Surface	314 Office	4	EA	7	6-10 years				
	Power Distribution	314 Office	20	EA	6	6-10 years				
	Walls - Plaster/Drywall	314 Office	631	SF	7	10+ years				
	Ceiling - Lay-in	Kitchen Office G15	161	SF	6	6-10 years				
	Doors - Side-lite	Kitchen Office G15	42	SF	6	10+ years				
	Doors - Steel Doors incl hw	Kitchen Office G15	1	EA	6	10+ years				
	Floor - Tile Quarry	Kitchen Office G15	161	SF	6	10+ years				
	Lighting - Pendent/Surface	Kitchen Office G15	3	EA	6	6-10 years				
	Power Distribution	Kitchen Office G15	8	EA	6	6-10 years				
	Walls - Concrete Block	Kitchen Office G15	163	SF	6	10+ years				
	Walls - Plaster/Drywall	Kitchen Office G15	121	SF	6	10+ years				
	Ceiling - Lay-in	Office 336 New Asset	204	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Office 336 New Asset	1	EA	7	10+ years				
	Floor - Tile	Office 336 New Asset	204	SF	7	10+ years				
	Lighting - Lay-in	Office 336 New Asset	2		7	10+ years				
	Power Distribution	Office 336 New Asset	6	EA	7	10+ years				
	Walls - Plaster/Drywall	Office 336 New Asset	580	SF	7	10+ years				
	Lighting - Lay-in Power Distribution	Office 336 New Asset Office 336 New Asset	2 6	EA	7 7	10+ years 10+ years				



Catego	ry : Room		Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
<i></i>								
Kitchen	Opilia a di avalia		4 000	05	0	0.40		
	Ceiling - Lay-in	1st Floor	1,088	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years		
	Floor - Tile	1st Floor	200	SF	6	10+ years		
	Floor - Tile Quarry	1st Floor	888	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	15	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years		
	Storage/ Closet	1st Floor	159	SF	5	10+ years		
	Walls - Concrete Block	1st Floor	1,286	SF	6	10+ years		
unch &	Multipurpose Room							
	Ceiling - Lay-in	G19	4,875	SF	6	6-10 years		
	Ceiling - Plaster/Drywall	G19	192	SF	6	10+ years		
	Doors - Steel Doors incl hw	G19	5	ĒA	6	10+ years		
	Doors - Store Front	G19	4	EA	6	10+ years		
	Floor - Concrete	G19	292	SF	5	10+ years		
	Floor - Tile/Sheet	G19	4,775	SF	5	10+ years		
	Lighting - Lay-in	G19	10	EA	6	6-10 years		
	Lighting - Lay-in	G19	2	EA	6	6-10 years		
	Lighting - Pendent/Surface	G19	54	EA	6	6-10 years		
	Walls - Concrete Block	G19	2,095	SF	6	10+ years		
		013	2,000	01	0	TOF years		
<u>/IDF_ID</u>								
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Finishes	2nd Floor	194	SF	7	6-10 years		
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Ductless split system.	
lechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	57	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	228	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	335	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	2,866	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	89	SF	7	10+ years		
	Storage Room	1st Floor	221	SF	7	10+ years		
	Storage Room	1st Floor	83	SF	7	10+ years		
	Storage Room	1st Floor	80	SF	7	10+ years		
	Janitor's Closet	2nd Floor	78	SF	7	10+ years		
	Storage Room	2nd Floor	123	SF	7	10+ years	Storage 218	
	Janitor's Closet	3rd Floor	78	SF	7	10+ years		
	Storage Room	3rd Floor	128	SF	7	10+ years	Storage 324	
	Storage Room	3rd Floor	208	SF	7	10+ years	Oloraye J24	
	Slorage Room		208	0	'	IUT years		



Catego	ry : Room	В	uilding	on			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Restroo	m						
	Accessories	220 Womens	77	SF	7	6-10 years	
	Ceiling - Lay-in	220 Womens	77	SF	7	10+ years	
	Doors - Steel Doors incl hw	220 Womens	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	220 Womens	77	SF	7	10+ years	
	Floor Drain	220 Womens	1	EA	7	6-10 years	
	Lavatory	220 Womens	1	EA	7	6-10 years	
	Lighting - Lay-in	220 Womens	1	EA	7	10+ years	
	Showers	220 Womens	1	EA	7	6-10 years	
	Walls - Concrete Block	220 Womens	70	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	220 Womens	59	SF	7	10+ years	
	Water Closet	220 Womens	1	EA	7	6-10 years	
	Accessories	236 Girls	270	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	236 Girls	270	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	236 Girls	270	SF	7	10+ years	
	Floor Drain	236 Girls	1	EA	7	6-10 years	
	Hand Dryer	236 Girls	3	EA	7	6-10 years	
	Lavatory	236 Girls	3	EA	7	6-10 years	Updated quantity
	Lighting - Pendent/Surface	236 Girls	3	EA	7	10+ years	
	Partitions	236 Girls	6	EA	7	6-10 years	
	Walls - Concrete Block	236 Girls	492	SF	7	10+ years	
	Walls - Structural Glazed Tile	236 Girls	57	SF	7	10+ years	
	Water Closet	236 Girls	6	EA	7	6-10 years	
	Accessories	238 Boys	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	238 Boys	298	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	238 Boys	298	SF	7	10+ years	
	Floor Drain	238 Boys	1	EA	7	6-10 years	
	Hand Dryer	238 Boys	3	EA	7	6-10 years	
	Lavatory	238 Boys	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	238 Boys	3	EA	7	10+ years	
	Partitions	238 Boys	3	EA	7	6-10 years	
	Urinals	238 Boys	3	EA	7	6-10 years	
	Walls - Concrete Block	238 Boys	526	SF	7	10+ years	
	Walls - Structural Glazed Tile	238 Boys	53	SF	7	10+ years	
	Water Closet	238 Boys	3	EA	7	6-10 years	
	Accessories	322 Mens	76	SF	7	6-10 years	
	Ceiling - Lay-in	322 Mens	76	SF	7	6-10 years	
	Doors - Steel Doors incl hw	322 Mens	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	322 Mens	76	SF	7	10+ years	
	Floor Drain	322 Mens	1	EA	7	6-10 years	
	Lavatory	322 Mens	1	EA	6	6-10 years	
	Lighting - Lay-in	322 Mens	1	EA	6	6-10 years	
	Showers	322 Mens	1	EA	7	6-10 years	Updated to match current
							observations



Building : Addition Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Walls - Concrete Block 322 Mens 73 SF 10+ vears 7 Walls - Tile Ceramic/ Porcelain 322 Mens SF 7 10+ vears 54 Water Closet 322 Mens 1 EΑ 6 6-10 years Accessories 332 Girls 250 SF 7 6-10 years SF 7 Ceiling - Plaster/Drywall 332 Girls 250 10+ years SF Floor - Tile Ceramic/ Porcelain 250 7 332 Girls 10+ years Floor Drain 332 Girls ΕA 7 10+ years 1 Hand Dryer 332 Girls 3 ΕA 7 6-10 years Lavatory 332 Girls 3 ΕA 7 6-10 years Updated quantity Lighting - Pendent/Surface 332 Girls 3 FΑ 7 10+ years Updated to match current observations Partitions 332 Girls 6 ΕA 7 6-10 years Walls - Concrete Block 332 Girls 474 SF 7 10+ years SF 7 Walls - Structural Glazed Tile 332 Girls 53 10+ years Water Closet 332 Girls 6 ΕA 7 6-10 years 334 Boys 250 SF 7 Accessories 6-10 years Ceiling - Plaster/Drywall SF 7 334 Boys 247 10+ years SF Ceiling - Plaster/Drywall 334 Boys 3 5 1-2 years Damaged plaster Floor - Tile Ceramic/ Porcelain 334 Boys SF 7 250 10+ vears 334 Boys 6-10 years Floor Drain 1 EΑ 7 Hand Dryer 334 Boys 3 ΕA 7 6-10 years 3 7 Lavatory 334 Boys EΑ 6-10 years 3 Lighting - Pendent/Surface ΕA 7 6-10 years 334 Boys 3 7 Partitions 334 Boys FΑ 6-10 years Urinals 334 Boys 3 ΕA 6 6-10 years SF Walls - Concrete Block 334 Bovs 474 7 10+ vears SF Walls - Structural Glazed Tile 334 Boys 53 7 10+ years Water Closet 334 Boys 3 ΕA 7 6-10 years SF 7 Accessories G03 Mens 62 6-10 years Ceiling - Lay-in G03 Mens 62 SF 7 10+ years Doors - Steel Doors incl hw G03 Mens 1 ΕA 7 10+ vears Floor - Tile Ceramic/ Porcelain G03 Mens 62 SF 7 10+ vears FΑ 7 Floor Drain G03 Mens 6-10 years 1 Hand Drver G03 Mens 1 FΑ 7 6-10 years 7 Lavatory G03 Mens 1 EΑ 6-10 years Lighting - Lay-in ΕA 7 G03 Mens 1 10+ years Walls - Concrete Block SF G03 Mens 162 7 10+ years Water Closet ΕA 7 6-10 years G03 Mens 1 SF Accessories G04 Womens 65 7 6-10 years SF Ceiling - Lav-in G04 Womens 65 7 10+ vears Doors - Steel Doors incl hw G04 Womens 1 ΕA 7 10+ years Floor - Tile Ceramic/ Porcelain 65 SF 7 G04 Womens 10+ vears Floor Drain G04 Womens 1 EA 7 6-10 years 7 Hand Dryer G04 Womens 1 EΑ 6-10 years



Catego	ry : Room	В							
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lavatory	G04 Womens	1	EA	7	6-10 years			
	Lighting - Lay-in	G04 Womens	1	EA	7	10+ years			
	Walls - Concrete Block	G04 Womens	153	SF	7	10+ years			
	Water Closet	G04 Womens	1	EA	7	6-10 years			
						•			

Category : Classroom			Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #215 (Regular Classroom)							
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	953	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	953	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	7	10+ years		
lassroo	m #216 (Regular Classroom)							
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	927	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	927	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,092	SF	7	10+ years		
lassroo	m #217 (Regular Classroom)							
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	868	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	868	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,065	SF	7	10+ years		
lassroo	m #219 (Regular Classroom)							
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	863	SF	7	10+ years		



Category : Classroom			В	Building : Addition					
_	-								
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	863	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,074	SF	7	10+ years			
lassroc	m #221 (Regular Classroom)								
	Casework	2nd Floor	30	LF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	866	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	856	SF	7	10+ years			
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Bubbling		
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,076	SF	7	10+ years			
lassroc	m #223 (Regular Classroom)								
	Casework	2nd Floor	30	LF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	878	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	878	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,085	SF	7	10+ years			
lassroc	m #240 (Regular Classroom)								
	Casework	2nd Floor	30	LF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	830	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	ĒA	7	10+ years			
	Floor - Tile	2nd Floor	830	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,049	SF	7	10+ years			

_Classroom #242 (Regular Classroom)



Catego	ry : Classroom		R	uilding	: Additi		140 S Melvina AVENUE, Chicago, IL 60638
Jaiego	iy. 0103510011			anang	. Adulti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	30	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	902	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	902	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,102	SF	7	10+ years	
Classroo	om #315 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	922	SF	7	6-10 years	
	Doors - Steel Doors incl hw	3rd Floor		ĒA	7	10+ years	
	Floor - Tile	3rd Floor	922	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,088	SF	7	10+ years	
Classroo	om #316 (Regular Classroom)						
	Casework	3rd Floor	30	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	6-10 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	900	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,073	SF	7	10+ years	
Classroo	om #317 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	865	SF	7	6-10 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	865	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,070	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Cracking plaster



Catego	ry : Classroom	Building : Addition							
	up Item - Type sroom #319 (Regular Classroom) Casework Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Lighting - Lay-in Lighting - Pendent/Surface					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
lassroo	m #319 (Regular Classroom)								
21000100	, ,	3rd Floor	30	LF	7	6-10 years			
		3rd Floor	655	SF	7	6-10 years			
		3rd Floor	1	EA	7	10+ years			
		3rd Floor	655	SF	7	10+ years			
		3rd Floor	3	EA	7	6-10 years			
		3rd Floor	5	EA	7	6-10 years			
		3rd Floor	6	EA	7	6-10 years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	939	SF	7	6-10 years			
	Walls - Flaster/Drywall		303	01	,	0-10 years			
Classroo	m #321 (Regular Classroom)								
	Casework	3rd Floor	26	LF	7	6-10 years			
	Ceiling - Lay-in	3rd Floor	750	SF	7	6-10 years			
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	750	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	3	ĒA	7	6-10 years			
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,006	SF	7	10+ years			
laceroo	m #323 (Computer Lab)								
01035100	Casework	3rd Floor	3	LF	6	6-10 years			
	Casework Ceiling - Lay-in	3rd Floor	1,123	SF	7	•			
	Doors - Steel Doors incl hw	3rd Floor		EA	6	6-10 years			
			2			10+ years			
	Floor - Tile	3rd Floor	1,123	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years			
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,194	SF	7	10+ years			
	Wireless System	3rd Floor	1	EA	7	6-10 years			
Classroo	m #330 (Regular Classroom)								
	Ceiling - Lay-in	3rd Floor	374	SF	7	6-10 years			
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	374	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	10+ years			
	Marker Board	3rd Floor	6	LF	7	6-10 years			
	Walls - Concrete Block	3rd Floor	407	SF	7	10+ years			
		3rd Floor	206	SF	7	10+ years			



Catego	ry : Classroom		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #338 (Art Room)								
	Casework	3rd Floor	33	LF	6	6-10 years			
	Ceiling - Exposed	3rd Floor	1,615	SF	7	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years			
	Floor - Tile	3rd Floor	1,615	SF	7	10+ years			
	Kiln	3rd Floor	1	EA	6	10+ years			
	Lighting - Lay-in	3rd Floor	6	EA	6	6-10 years			
	Lighting - Lay-in	3rd Floor	3	EA	6	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	17	EA	6	6-10 years			
	Marker Board	3rd Floor	12	LF	6	6-10 years			
	Storage/ Closet	3rd Floor	302	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	480	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,209	SF	7	10+ years			
	Work Sink	3rd Floor	2	EA	7	6-10 years	Updated quantity		

Category : Interior

Building : Addition

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	222	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	95	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	6-10 years	Quantity updated to match current observations
	Floor - Tile/Sheet	1st Floor	317	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	6-10 years	
	Stairs - Concrete Stairs	1st Floor	42	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,592	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,592	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	41	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	12	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	100	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	513	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,259	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	2,382	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	146	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,528	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	19	EA	7	6-10 years	



Category : Interior Building : Addition							
				U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	38	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	11	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	80	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	513	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	2,259	SF	7	6-10 years	
	Ceiling - Lay-in	Basement	595	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	279	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years	
	Doors - Store Front	Basement	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	Basement	1	EA	7	6-10 years	Quantity updated to match current observations
	Floor - Tile/Sheet	Basement	874	SF	5	10+ years	
	Lighting - Lay-in	Basement	8	EA	6	6-10 years	
	Student Lockers - One Tier	Basement	5	EA	6	6-10 years	
	Walls - Concrete Block	Basement	1,500	SF	6	10+ years	
Stairs							
	Ceiling - Exposed	East (Stair 326)	376	SF	7	10+ years	
	Ceiling - Lay-in	East (Stair 326)	363	SF	7	10+ years	
	Floor - Tile/Sheet	East (Stair 326)	774	SF	7	10+ years	
	Handrails	East (Stair 326)	126	LF	7	10+ years	
	Lighting - Lay-in	East (Stair 326)	6	EA	7	10+ years	
	Lighting - Wall Mounted	East (Stair 326)	3	EA	7	10+ years	
	Stairs - Concrete	East (Stair 326)	289	LF	7	10+ years	
	Walls - Concrete Block	East (Stair 326)	849	SF	7	10+ years	
	Ceiling - Exposed	West (Stair 327)	376	SF	7	10+ years	
	Ceiling - Lay-in	West (Stair 327)	363	SF	7	10+ years	
	Floor - Tile/Sheet	West (Stair 327)	774	SF	7	10+ years	
	Handrails	West (Stair 327)	126	LF	7	10+ years	
	Lighting - Lay-in	West (Stair 327)	6	EA	7	10+ years	
	Lighting - Wall Mounted	West (Stair 327)	3	EA	7	10+ years	
	Stairs - Concrete	West (Stair 327)	289	LF	7	10+ years	
	Walls - Concrete Block	West (Stair 327)	1,432	SF	7	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	Ground Floor to Third Floor	1	EA	7	10+ years	



Category : Site Building : Site Recommend Item - Type Location Quantity UOM Replacement **Comments** Group Rank Civil/Drainage 7 FΑ 6 Civil/ Drainage - Catch Basin Entire Site 10+ years 4 ΕA 6 Civil/ Drainage - Site Drain **Entire Site** 10+ years Civil/ Drainage - Site Manhole Entire Site 19 ΕA 6 10+ years Fencina Fencing - Chain Link LF Entire Site 44 6 10+ years LF Fencing - New Standard Ornamental **Entire Site** 1.286 6 10+ years LF Fencing - New Standard Ornamental Entire Site 20 6 10+ years Repaired. Landscape 2 ΕA 7 Benches Entire Site 10+ years Landscape - Grass Entire Site 44,519 SF 6 10+ years SF Landscape - Grass Entire Site 900 4 1-2 years Bare soil SF Landscape - Hardscape- Concrete Entire Site 11,677 6 10+ years Landscape - Hardscape- Concrete Entire Site SF 1-2 years 175 4 Broken, cracked concrete Landscape - Mulch Entire Site 500 SF 6 6-10 years Parkway trees Entire Site 15 EA 6 10+ years SF Planting Beds/ Area Entire Site 1.950 6 10+ years SF 7 Play Area - Hardscape- Asphalt 5.850 10+ years Entire Site SF Retaining Wall - Concrete **Entire Site** 1.305 6 10+ years Retaining Wall - Concrete **Entire Site** 15 SF 5 1-2 years Broken, cracked, exposed reinforcement, missing pieces **Trash Receptacles** Entire Site 1 ΕA 7 10+ years Parking Lot Concrete Curbs LF North 520 7 10+ years LF Interior Plantings North 3 7 10+ vears SF 7 10+ years Pavers North 11.800 Surface - Concrete SF 7 10+ years North 400 LF Concrete Curbs South 178 7 10+ years Verified linear feet. Most curb is at North Parking lot LF 96 6 Verified dimension Interior Plantings South 10+ years Lighting - Pole Mounted ΕA South 3 6 10+ years Pavers South 17.050 SF 6 10+ years SF Surface - Asphalt South 32.310 6 10+ vears Surface - Asphalt SF South 3,000 4 1-2 years Alligatoring, potholes, large cracks Surface - Concrete 3.400 SF 6 10+ years South 7 Trash Compactor South 1 EΑ 10+ years Trash Enclosure - Masonry South 960 SF 7 10+ years

Sidewalks



Catego	ry : Site		Building : Site						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Sidewalks - Internal Walks	Entire Site	115	LF	6	10+ years			
	Sidewalks - Internal Walks	Entire Site	50	LF	4	1-2 years	Shattered, broken concrete		
	Sidewalks - Perimeter Sidewalks	Entire Site	9,738	SF	6	10+ years			
	Sidewalks - Perimeter Sidewalks	Entire Site	1,050	SF	4	1-2 years	Broken, cracked concrete		
_Signage									
	Flag Pole - Flag Pole	Southeast	1	EA	7	10+ years			
	Marquee - Free Standing Back Lighted	Southeast	1	EA	6	10+ years			

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	A.r.o.o.	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	Area (SF)	Area	Area	Stop	Board
Building : Main	Intended Usage	Room Eocation	Number	Number	(36)	Alea	Alea	Stop	Duaru
Computer Lab	Regular Classroom	2nd Floor	200	202	761	138	18	N	N
Faculty Lounge	Regular Classroom	2nd Floor	202	202	486	138	18	N	Y
Health	Regular Classroom	1st Floor	100	100	408	184	96		1
Kindergarten	Kindergarten	1st Floor	105	105	793	184	24	N	Y
Kindergarten	Kindergarten	1st Floor	103	103	950	253	33	N	Y
Kindergarten	Kindergarten	1st Floor	107	107	1,049	276	36	N	Y
Office	Regular Classroom	Basement	019	019	1,405	132	21	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	701	184	24	N	Y
Regular Classroom	Regular Classroom	1st Floor	102	102	701	184	24	N	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	710	184	24	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	708	184	24	N	Y
Regular Classroom	Regular Classroom	1st Floor	108	108	708	184	24	N	Y
Regular Classroom	Regular Classroom	1st Floor	110	110	701	184	24	N	Y
Regular Classroom	Regular Classroom	1st Floor	111	110	292	92	12	N	Y
Regular Classroom	Regular Classroom	1st Floor	112	112	732	184	24	N	Y
	Regular Classroom	1st Floor	112	112	751	184	24	N	ř Y
Regular Classroom		2nd Floor	201	201	751	184	24	N	Y Y
Regular Classroom	Regular Classroom					184	24		Y Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	702			N	Y Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	565	92	12	N	
Regular Classroom	Regular Classroom	2nd Floor	205	205	704	184	24	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	710	147	41	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	699	184	24	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	703	147	41	N	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	704	184	24	N	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	706	184	24	N	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	701	184	24	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	730	184	24	N	Y
Regular Classroom	Regular Classroom	2nd Floor	213	213	754	184	24	N	Y
Building : Addition									
Art Room	Art Room	3rd Floor	338	307	1,615	830	0	N	Y
Computer Lab	Computer Lab	3rd Floor	323	310	1,123	232	21	N	Ν
Regular Classroom	Office	3rd Floor	330	330	374	72	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	215	214	953	202	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	927	202	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	217	213	868	174	14	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	219	212	863	174	14	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	221	211	866	174	14	N	Ý



Classroom Summary

			_	Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	223	210	878	174	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	240	206	830	174	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	242	207	902	174	14	N	Y
Regular Classroom	Regular Classroom	3rd Floor	315	314	922	202	14	N	Y
Regular Classroom	Regular Classroom	3rd Floor	316	316	900	202	14	N	Y
Regular Classroom	Regular Classroom	3rd Floor	317	313	865	174	14	N	Y
Regular Classroom	Regular Classroom	3rd Floor	319	312	655	145	7	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	321	311	750	145	14	N	N