

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1930	3	11,242
Addition 1	1954	3	44,969
Addition 2	1961	3	14,988
Campus Total			71,199

Catego	Category : Exterior			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	<del>S</del>						
	Exterior Doors - Exterior FRP Door	#3 - SW	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - SW	2	EA	6	10+ years	
	Exterior Stairs - Stone	#3 - SW	21	LF	6	10+ years	
	Exterior Stairs - Stone	#3 - SW	1	LF	5	1-2 years	Cracked stone
	Exterior Doors - Exterior FRP Door	#4 - S	3	EA	6	10+ years	
	Exterior Stairs - Stone	#4 - S	11	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#4.5 - SE	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	South Fire Exits	2	EA	6	10+ years	
Fire Fee							
Fire Esc	•		2		<u> </u>	10	
	Exterior Doors - Exterior Steel Door	SE	2	EA	6	10+ years	
	Fire Escape	SE	48	LF	6	10+ years	
	Paints	SE	48	LF	5	2-5 years	
_Foundat	ion						
	Foundation - Masonry	Entire Building	330	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	11,242	SF	7	10+ years	
Lighting							
Lighting	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	10+ years	
		Entrie Building	0	L/\	0	ior years	



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Roof Sys	stem						
	Coping - Stone	Low NW Roof	50	LF	7	10+ years	
	Downspouts - Interior Downspouts	Low NW Roof	13	LF	7	10+ years	
	Parapet - 16" - 30" Height	Low NW Roof	50	LF	7	10+ years	
	Roof - Metal	Low NW Roof	145	SF	7	10+ years	
	Roof Structure - Concrete	Low NW Roof	145	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Access Ladder - Wood	Main Roof	1	EA	4	2-5 years	Homemade stair
	Coping - Terra Cotta	Main Roof	2	LF	7	10+ years	
	Coping - Terra Cotta	Main Roof	303	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	90	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	185	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	130	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	4,420	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Concrete	Main Roof	4,420	SF	7	10+ years	
Nalls							
	Cornice - Terra Cotta	Entire Building	330	LF	6	10+ years	Verified the terra-cotta is in fair shape. Deteriorated mortar.
	Exterior Walls - Brick	Entire Building	9,197	SF	6	10+ years	•
	Exterior Walls - Brick	Entire Building	1,090	SF	4	1-2 years	Cracked brick, open joints
	Exterior Walls - Stone-Cast	Entire Building	120	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	550	SF	5	10+ years	Deteriorated mortar
	Exterior Walls - Stone-Cast	Entire Building	6	SF	4	1-2 years	Cracked, broken stone
Nindows	3						
	Guard - Guards perforated	Entire Building	210	SF	6	10+ years	
	Lintels - Brick	Entire Building	42	LF	6	10+ years	
	Lintels - Steel	Entire Building	26	LF	6	10+ years	
	Lintels - Steel	Entire Building	10	LF	5	10+ years	
	Lintels - Stone	Entire Building	12	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	390	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
		Location		UOM	Rank	Recommend Boplacomont	Comments
Group	Item - Type		Quantity		Ndlik	Replacement	Comments
-merger	ncy System			= .		0.40	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Electrical Room	2	EA	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Electrical Room	3	EA	4	2-5 years	Outdated units, no spare parts easi available
	Emergency Battery Packs - Corridors and	Electrical Room	4	EA	6	6-10 years	



NICA S							3319 N Clifton AVENUE, Chicago, IL 606
Catego	ry : Electrical		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Jioup	Stairs	Location	Quantity		Marik	Replacement	Comments
	Emergency Battery Packs - Corridors and	Electrical Room	2	EA	6	2-5 years	
	Stairs	Electrical Deam	4		e	6 10 10000	
	Emergency Battery Packs - Gym	Electrical Room	1	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	2,032	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	1,947	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2,675	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	8	EA	6	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	6	2-5 years	
	Exit Signs - Gym	Entire Building	2	EA	6	2-5 years	
	Security System - Intrusion Detection	Entire Building	11,242	SF	5	2-5 years	
	Security System - Initiasion Detection	Entire Building	11,242	Эг	5	2-5 years	
/lain Ser	vice						
	PA System	Entire Building	11,242	SF	5	2-5 years	Served by addition 1
ower Di	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	- 1	EA	6	2-5 years	Deteriorating
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	Deteriorating
		Entre Building		L/(	0	Tor years	
Catego	ry : Fire Protection		В	uilding	: Main	<b>-</b>	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ire Aları	m						
	Fire Alarm Strobe Lights	Entire Building	11,242	SF	3	0-1 year	No strobes
	Fire Alarm_System	Entire Building	11,242	SF	4	2-5 years	Outdated system, no strobe lights
		Entro Ballang	11,212	0.	•	2 0 youro	installed
aterio	ry : Mechanical		B	uilding	• Main		
Jalogo				anang	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy							
	Piping - Condensate Pipe- Steel	Entire Building	100	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	100	LF	6	6-10 years	
leating I	Devices						
	Fin Tube - Electric	3rd Floor	75	LF	5	6-10 years	
	Radiators - Steam	Entire Building	13	EA	5	2-5 years	
	Radiators - Steam	Entire Building	1	EA	4	0-1 year	Leaks steam
		5				- <b>,</b> ·	



	Public Schools						3319 N Clifton AVENUE, Chicago, IL 60657
	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wall Heater - Electric	Entire Building	4	EA	5	2-5 years	
empera	ture Control						
	Electric Thermostat	Entire Building	1	EA	6	2-5 years	
	Pneumatic System	Entire Building	11,242	SF	3	0-1 year	Not operational, served by addition
	Thermostats - Pneumatic	Entire Building	4	EA	5	2-5 years	
atego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
1 0	Domestic Piping-Hot Water Return Lines	Entire Building	11,242	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	11,242	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	11,242	SF	6	2-5 years	
	Fixtures	Ũ				2	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	11,242	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	11,242	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	11,242	SF	6	2-5 years	
	Sanitary Piping	Entire Building	11,242	SF	5	6-10 years	
	Storm Piping	Entire Building	11,242	SF	5	6-10 years	
	Vent Piping	Entire Building	11,242	SF	5	6-10 years	
atego	ry : Room		в	uilding	: Main		
aloge			_	anang	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices		-			-	
	Ceiling - Plaster/Drywall	2nd Floor - Counselor's Office Room 200	380	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Counselor's Office Room	1	EA	6	10+ years	
	Floor - Carpet	200 2nd Floor - Counselor's Office Room	380	SF	6	6-10 years	
	Lighting - Pendent/Surface	200 2nd Floor - Counselor's Office Room	3	EA	6	6-10 years	
	Power Distribution	200 2nd Floor - Counselor's Office Room	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	200 2nd Floor - Counselor's Office Room	870	SF	6	10+ years	
	Ceiling - Plaster/Drywall	200 2nd Floor-Gym Office	118	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor-Gym Office	110	EA	6	6-10 years	Veneer damaged
		Zhu Floor-Gym Oille	I	EA	0	0-10 years	veneer uamayeu



Catego	Category : Room		В	Building : Main					
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Wood	2nd Floor-Gym Office	118	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor-Gym Office	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor-Gym Office	412	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	3rd floor conference	68	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd floor conference	1	EA	7	6-10 years			
	Floor - Tile	3rd floor conference	68	SF	7	6-10 years			
	Lighting - Pendent/Surface	3rd floor conference	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	3rd floor conference	335	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd floor office	142	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd floor office	1	EA	7	10+ years			
	Floor - Tile	3rd floor office	142	SF	7	6-10 years			
	Lighting - Pendent/Surface	3rd floor office	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	3rd floor office	440	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd floor open office	220	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd floor open office	1	EA	7	10+ years			
	Floor - Tile	3rd floor open office	220	SF	7	6-10 years			
	Lighting - Pendent/Surface	3rd floor open office	4	EA	7	6-10 years			
	Walls - Plaster/Drywall	3rd floor open office	538	SF	7	10+ years			
		·				-			
Auditoriu	um & Theater								
	Balcony Seating	Basement	110	EA	7	10+ years			
	Ceiling - Plaster/Drywall	Basement	2,494	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement	7	EA	6	10+ years			
	Floor - Concrete	Basement	462	SF	7	10+ years			
	Floor - Tile/Sheet	Basement	2,032	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement	12	EA	7	6-10 years			
	Lighting - Wall Mounted	Basement	10	EA	7	10+ years			
	Main Floor Seating	Basement	260	EA	7	10+ years			
	Sound System	Basement	1	EA	7	6-10 years			
	Stage	Basement	418	SF	7	10+ years			
	Stage Curtain	Basement	8	EA	7	10+ years			
	Stage Lighting System	Basement	1	EA	7	6-10 years			
	Stage-Stairs - Wood	Basement	8	LF	6	10+ years			
	Stairs - Terrazzo	Basement	33	LF	6	10+ years			
	Walls - Concrete Block	Basement	2,475	SF	6	10+ years			
	Walls - Plaster/Drywall	Basement	2,475	SF	7	10+ years			
						•			
Gymnas									
	Ceiling - Splined	2nd Floor	2,675	SF	6	6-10 years	No max occupancy sign		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Wood	2nd Floor	2,675	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	9	EA	6	6-10 years			
	Scoreboards	2nd Floor	1	EA	7	6-10 years			
	Storage/ Closet	2nd Floor	50	SF	7	10+ years			



3319 N	Clifton	AVENUE,	Chicago,	IL	60657

Catego	ory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	2,139	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,139	SF	6	10+ years	
Mechan	ical/ Service Rooms						
	Janitor's Closet	Basement	81	SF	7	10+ years	
	Storage Room	Basement	400	SF	7	10+ years	
Restroo	m						
	Accessories	Basement-South of Auditorium	88	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-South of Auditorium	88	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-South of Auditorium	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-South of Auditorium	88	SF	6	10+ years	
	Lavatory	Basement-South of Auditorium	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement-South of Auditorium	1	EA	7	6-10 years	
	Partitions	Basement-South of Auditorium	1	EA	7	10+ years	
	Urinals	Basement-South of Auditorium	1	EA	6	1-2 years	Does not work
	Walls - Tile Ceramic/ Porcelain	Basement-South of Auditorium	20	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-South of Auditorium	362	SF	7	10+ years	
	Water Closet	Basement-South of Auditorium	1	EA	7	10+ years	
	Accessories	Basement-South of Auditorium	110	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-South of Auditorium	110	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-South of Auditorium	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-South of Auditorium	110	SF	6	10+ years	
	Lavatory	Basement-South of Auditorium	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement-South of Auditorium	1	EA	7	6-10 years	
	Partitions	Basement-South of Auditorium	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-South of Auditorium	20	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-South of Auditorium	400	SF	7	10+ years	
	Water Closet	Basement-South of Auditorium	2	EA	7	10+ years	

#### **Category : Interior**

Building : Main

	<b>,</b>					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	376	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	38	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	338	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	760	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	625	SF	6	10+ years	
	Doors - Store Front	2nd Floor	2	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	



Catego	ry : Interior		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	63	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	562	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	6	6-10 years	
	Stairs - Terrazzo	2nd Floor	15	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,050	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	946	SF	7	10+ years	
	Doors - Transom Window	Basement	12	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement	2	EA	6	10+ years	
	Floor - Concrete	Basement	946	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	6	EA	7	10+ years	
	Stairs - Terrazzo	Basement	8	LF	6	10+ years	
	Walls - Masonry	Basement	124	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	992	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	124	SF	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	North West	750	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North West	150	SF	6	10+ years	
	Floor - Concrete	North West	200	SF	7	10+ years	
	Floor - Terrazzo	North West	600	SF	6	10+ years	
	Floor - Tile	North West	350	SF	7	6-10 years	
	Handrails	North West	128	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	North West	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	North West	3	EA	6	6-10 years	
	Stairs - Terrazzo	North West	64	LF	6	10+ years	
	Walls - Plaster/Drywall	North West	3,600	SF	6	10+ years	



Category : Exterior			В	Building : Addition 1				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance	2							
	Entrance Control - Audio and Video	#2 - Main - W	1	EA	6	10+ years		
	Exterior Doors - Exterior AMP Door	#2 - Main - W	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	#2 - Main - W	2	EA	6	6-10 years		
	Exterior Stairs - Stone	#2 - Main - W	- 6	LF	5	10+ years		
	Exterior Doors - Exterior FRP Door	#5 - SE	2	EA	6	10+ years		
	Exterior Stairs - Stone	#5 - SE	- 6	LF	6	10+ years		
	Exterior Doors - Exterior FRP Door	#5.5 - Boiler Room - SE	1	EA	6	10+ years		
_Foundat	ion							
	Foundation - Concrete	Entire Building	662	LF	7	10+ years		
	Foundation - Concrete	Entire Building	20	LF	6	10+ years		
	Superstructure - Concrete	Entire Building	44,969	SF	7	10+ years		
Lighting								
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	6	10+ years		
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	10+ years		
_Roof Svs	stem							
	Chimney - Brick Chimney- Stainless Steel	Boiler Room - E Roof	32	LF	7	10+ years		
	Liner	Boller Room - E Rool	32	LF	'	TUT years		
	Chimney - Brick Chimney- Stainless Steel	Boiler Room - E Roof	4	LF	5	6-10 years	Repaired	
	Liner		+	LI	5	0-10 years	Repaired	
	Coping - Stone	Boiler Room - E Roof	112	LF	7	10+ years		
	Downspouts - Interior Downspouts	Boiler Room - E Roof	12	LF	7	10+ years		
	Parapet - 16" - 30" Height	Boiler Room - E Roof	112	LF	7	10+ years		
	Roof - Modified Bitumen	Boiler Room - E Roof	526	SF	7	10+ years		
	Roof Hatch - Metal	Boiler Room - E Roof	1	EA	7	10+ years		
	Roof Structure - Concrete	Boiler Room - E Roof	526	SF	7	10+ years		
	Coping - Metal	Low SE Roof	30	LF	7	10+ years		
	Downspouts - Interior Downspouts	Low SE Roof	10	LF	7	10+ years		
	Roof - Modified Bitumen	Low SE Roof	60	SF	7	10+ years		
	Roof Structure - Concrete	Low SE Roof	60	SF	7	10+ years		
	Access Ladder - Metal	Main Roof	1	ĒA	7	10+ years		
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years		
	Coping - Stone	Main Roof	678	LF	6	10+ years		
	Downspouts - Interior Downspouts	Main Roof	252	LF	6	10+ years		
	Parapet - 16" - 30" Height	Main Roof	678	LF	6	10+ years		
	Roof - Modified Bitumen	Main Roof	14,755	SF	7	10+ years		
	Roof Hatch - Metal	Main Roof	2	EA	7	10+ years	Hatch is working properly	
	Roof Structure - Concrete	Main Roof	14,755	SF	7	10+ years	01 1 2	
	Coping - Stone	Mid S Roof	45	LF	7	10+ years		
			-			2		



2-5 years

Catego	ry : Exterior		В	uilding	: Additie	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	Mid S Roof	20	LF	7	10+ years	
	Parapet - 16" - 30" Height	Mid S Roof	45	LF	7	10+ years	
	Roof - Modified Bitumen	Mid S Roof	118	SF	7	10+ years	
	Roof Structure - Concrete	Mid S Roof	118	SF	7	10+ years	
/alls							
	Exterior Walls - Brick	Entire Building	16,016	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	500	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	150	SF	4	1-2 years	Open joints, cracked wall
	Exterior Walls - Stone-Cast	Entire Building	1,584	SF	5	10+ years	Broken stone
Vindows	s						
	Guard - Guards perforated	Entire Building	1,720	SF	6	10+ years	
	Lintels - Steel	Entire Building	345	LF	6	10+ years	
	Lintels - Steel	Entire Building	5	LF	5	1-2 years	Corroded, deflecting steel
	Lintels - Stone	Entire Building	414	LF	6	10+ years	een eueu, ueneem g ereer
	Windows - Decorative	Entire Building	80	SF	6	10+ years	
	Windows - Louver	Entire Building	30	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,740	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Additie	on 1	
-				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
U	Emergency Battery Packs - Corridors and Stairs	Corridors and Stairs	2	EA	6	2-5 years	
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	UPS - 30 - 60 KW	Electrical Room	- 1	EA	2	0-1 year	Abandoned
	Emergency A/C Power - Corridors and	Entire Building	6,492	SF	6	2-5 years	Abanaonoa
	Stairs Emergency A/C Power - Students Toilets	Entire Building	1,410	SF	6	2-5 years	
		Entire Building	•	EA	6	•	
	Exit Signs - Corridors and Stairs		10		5	2-5 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	2-5 years	
	Security System - Intrusion Detection	Entire Building	44,969	SF	6	2-5 years	
<u>/lain Se</u>				<b></b> .			
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	6-10 years	
	Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	7	10+ years	

Power Distribution

120/208/3PH PA System

44,969

SF

6

Entire Building



Catego	ry : Electrical	B							
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years			
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	2-5 years			
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years			
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	6-10 years			
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years			
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years			
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years			
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	2-5 years			
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	2-5 years	Live front		
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years			
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years			

#### **Category : Fire Protection**

**Building : Addition 1** 

**Building : Addition 1** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Aları	m						
	Fire ALarm Anunciator	Entire Building	1	EA	6	1-2 years	Obsolete parts
	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	Obsolete parts
	Fire Alarm Strobe Lights	Entire Building	44,969	SF	3	0-1 year	No strobes
	Fire Alarm_System	Entire Building	44,969	SF	4	2-5 years	Outdated system, no strobes installed

#### Category : Mechanical

			0			Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	Iling Systems						
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Attic	1	EA	5	2-5 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Basement - Center	1	EA	5	6-10 years	
	Air Intake	Basement - Center	1	EA	4	1-2 years	Intake on roof damaged/deteriorating
	Auxiliaries - Greater than 35000 cfm	Basement - Center	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement - Center	100	LF	5	6-10 years	
	Zone Dampers	Basement - Center	29	EA	5	2-5 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Basement - South	1	EA	5	6-10 years	
	Air Intake	Basement - South	1	EA	5	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Basement - South	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement - South	50	LF	5	2-5 years	
	Zone Dampers	Basement - South	2	EA	5	2-5 years	

Boiler Systems



3319 N Clifton AVENUE, Chicago, IL 60657 **Building : Addition 1** Category : Mechanical Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Boiler Auxiliary- Scotch Marine- Steam Low Entire Building 2 FΑ 5 2-5 vears Pressure Boiler - 101 - 150 HP **Chemical Feed System** Entire Building 1 FΑ 6 6-10 years Combustion Dampers Entire Building 3 ΕA 5 6-10 years 5 Condensate Pump Entire Building 1 ΕA 6-10 years 5 Condensate Pump Entire Building 1 EΑ 2-5 years Dated pump, tank corroding Condensate Pump Entire Building 1 ΕA 5 6-10 years Feed Water Pumps and Tank Entire Building 1 ΕA 4 1-2 years Tank deteriorating Feed Water Pumps and Tank Entire Building 1 ΕA 1 0-1 year Abandoned Non Condensing- Fire Tube- Scotch Marine-Entire Building FΑ 5 2-5 years 1 Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Entire Building 1 EΑ 5 2-5 years Steam- Low Pressure Boiler - 101 - 150 HP LF Piping - Condensate Pipe- Steel Entire Building 500 6 6-10 years Piping - Steam Pipe- Steel Entire Building LF 6-10 years 500 6 Steam Traps FΑ 5 Entire Building 59 2-5 years Gas Booster 2 Gas Booster Boiler Room ΕA 5 2-5 years Heating Devices Unit Heater - Gas Boiler Room 1 ΕA 5 6-10 years Unit Heater - Electric Electrical Room 2 ΕA 6 6-10 years 15 ΕA 5 2-5 years Radiators - Steam Entire Building Wall Heater - Electric Entire Building 7 EΑ 5 2-5 years Wall Heater - Electric 2 ΕA Entire Building 4 0-1 year Bottom cover missing exposing live wires 3 ΕA Cabinet Heaters - With Steam Coil 5 Entire Building 2-5 years Temperature Control Electric Controls 2,500 SF 6 Entire Building 6-10 years Univents controlled manually Electric Thermostat Entire Building 2 ΕA 6 6-10 years Pneumatic System Entire Building 44.969 SF 3 0-1 year Not operational Thermostats - Pneumatic Entire Building 29 FΑ 4 0-1 year Not operational Unit Ventilation Unit Ventilators- Floor Mounted- Steam Entire Building 4 EΑ 6 6-10 years Heating Coils Only Ventilation Exhaust Fans- Indoor - 1501 - 8000 CFM Entire Building ΕA 5 2-5 years 1 Exhaust Fans- Indoor - 500 - 1500 CFM Entire Building 2 EΑ 5 6-10 years Exhaust Fans- Roof Mounted - 1501 - 8000 Entire Building 2 ΕA 5 10+ years



Catego	ry : Mechanical		Building : Addition 1				
Jacogo				ananig	. , taulti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	CFM						
	Roof Mounted Duct Work	Entire Building	40	LF	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No suppression system
		g			-	e i jeu.	
Catego	ry : Plumbing		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	4	1-2 years	Corroding
	Hot Water Storage Tank_Gas - 201 - 500	Boiler Room	1	EA	2	0-1 year	Abandoned
	Gallons					,	
	Hot Water Storage Tank_Gas - Less than	Boiler Room	1	EA	6	6-10 years	
	200 Gallons					•	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	44,969	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	44,969	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	44,969	SF	6	2-5 years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	44,969	SF	6	2-5 years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	44,969	SF	6	2-5 years	
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	44,969	SF	6	2-5 years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	44,969	SF	5	6-10 years	
	Storm Piping	Entire Building	44,969	SF	5	6-10 years	
	Vent Piping	Entire Building	44,969	SF	5	6-10 years	
_							
Pumps	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	6	6-10 years	
	Pumps - Domestic Booster Pump-Simplex Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Basement	1	EA	6 5	6-10 years	
	Pumps - Ejector-Duplex Pumps - Sump-Duplex	Basement	1	EA		•	
	Pumps - Sump-Duplex Pumps - Sump-Simplex	Basement	1	EA	5 5	2-5 years 2-5 years	
		Dasement	1	EA	5	z-5 years	
Category : Room			В	uilding	: Additi	on 1	
-						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices			e –			
	Ceiling - Plaster/Drywall	1st Floor Copy room	75	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Copy room	_1	EA	6	10+ years	
	Floor - Tile	1st Floor Copy room	75	SF	6	10+ years	



Building : Addition 1GroupItem - TypeLocationQuantityUOMRankReplacementCommentsLighting - Pendent/Surface1st Floor Copy room1EA76-10 yearsCommentsPower Distribution1st Floor Copy room4EA610+ yearsStorage/ Closet1st Floor Copy room35SF710+ yearsWalls - Plaster/Drywall1st Floor Copy room200SF710+ yearsAC Unit1st Floor-Main Office1EA76-10 yearsCeiling - Plaster/Drywall1st Floor-Main Office313SF710+ yearsDoors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 yearsCours - Transon Window1st Floor-Main Office5EA76-10 yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 yearsLighting - Pendent/Surface	Building : Addition 1							
GroupItem - TypeLocationQuantityUOMRankReplacementCommentsLighting - Pendent/Surface1st Floor Copy room1EA76-10 yearsPower Distribution1st Floor Copy room4EA610+ yearsStorage/ Closet1st Floor Copy room35SF710+ yearsWalls - Plaster/Drywall1st Floor Copy room200SF710+ yearsAC Unit1st Floor-Main Office1EA76-10 yearsCeiling - Plaster/Drywall1st Floor-Main Office313SF710+ yearsDoors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 years								
Lighting - Pendent/Surface1st Floor Copy room1EA76-10 yearsPower Distribution1st Floor Copy room4EA610+ yearsStorage/ Closet1st Floor Copy room35SF710+ yearsWalls - Plaster/Drywall1st Floor Copy room200SF710+ yearsAC Unit1st Floor-Main Office1EA76-10 yearsCeiling - Plaster/Drywall1st Floor-Main Office313SF710+ yearsDoors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 years								
Power Distribution1st Floor Copy room4EA610+ yearsStorage/ Closet1st Floor Copy room35SF710+ yearsWalls - Plaster/Drywall1st Floor Copy room200SF710+ yearsAC Unit1st Floor-Main Office1EA76-10 yearsCeiling - Plaster/Drywall1st Floor-Main Office313SF710+ yearsDoors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 years								
Storage/ Closet1st Floor Copy room35SF710+ yearsWalls - Plaster/Drywall1st Floor Copy room200SF710+ yearsAC Unit1st Floor-Main Office1EA76-10 yearsCeiling - Plaster/Drywall1st Floor-Main Office313SF710+ yearsDoors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 years								
Walls - Plaster/Drywall1st Floor Copy room200SF710+ yearsAC Unit1st Floor-Main Office1EA76-10 yearsCeiling - Plaster/Drywall1st Floor-Main Office313SF710+ yearsDoors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 years								
AC Unit1st Floor-Main Office1EA76-10 yearsCeiling - Plaster/Drywall1st Floor-Main Office313SF710+ yearsDoors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 years								
Ceiling - Plaster/Drywall1st Floor-Main Office313SF710+ yearsDoors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 years								
Doors - Transom Window1st Floor-Main Office9SF710+ yearsDoors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 years								
Doors - Wood Doors inclu hw1st Floor-Main Office1EA610+ yearsFloor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 yearsQuantity updated to match current								
Floor - Tile1st Floor-Main Office313SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office5EA76-10 yearsQuantity updated to match current								
Lighting - Pendent/Surface 1st Floor-Main Office 5 EA 7 6-10 years Quantity updated to match curre								
	ent							
Lighting - Pendent/Surface 1st Floor-Main Office 1 EA 6 6-10 years Re-lamp fixture								
Power Distribution 1st Floor-Main Office 18 EA 7 10+ years								
Walls - Plaster/Drywall   1st Floor-Main Office   949   SF   7   10+ years								
AC Unit 1st Floor-Principal's Office 1 EA 7 6-10 years								
Ceiling - Plaster/Drywall 1st Floor-Principal's Office 140 SF 7 10+ years								
Doors - Transom Window 1st Floor-Principal's Office 9 SF 7 10+ years								
Doors - Wood Doors inclu hw 1st Floor-Principal's Office 2 EA 6 10+ years								
Floor - Tile 1st Floor-Principal's Office 140 SF 6 10+ years								
Lighting - Pendent/Surface 1st Floor-Principal's Office 2 EA 7 6-10 years								
Power Distribution 1st Floor-Principal's Office 6 EA 6 10+ years								
Storage/ Closet 1st Floor-Principal's Office 67 SF 7 10+ years								
Walls - Plaster/Drywall   1st Floor-Principal's Office   624   SF   7   10+ years								
AC Unit 1st floor- Rm 104 1 EA 7 6-10 years								
Ceiling - Plaster/Drywall 1st floor- Rm 104 339 SF 7 10+ years								
Doors - Side-lite 1st floor- Rm 104 16 SF 7 10+ years								
Doors - Transom Window 1st floor- Rm 104 9 SF 7 10+ years								
Doors - Wood Doors inclu hw 1st floor- Rm 104 2 EA 6 10+ years								
Floor - Tile 1st floor- Rm 104 339 SF 6 10+ years								
Lighting - Pendent/Surface 1st floor- Rm 104 6 EA 7 6-10 years								
Power Distribution 1st floor- Rm 104 6 EA 7 10+ years								
Walls - Plaster/Drywall 1st floor- Rm 104 982 SF 7 10+ years								
Ceiling - Plaster/Drywall 2nd Floor - Teacher's Room 201A 185 SF 7 10+ years								
Doors - Wood Doors inclu hw 2nd Floor - Teacher's Room 201A 2 EA 7 10+ years								
Floor - Tile/Sheet 2nd Floor - Teacher's Room 201A 185 SF 7 6-10 years								
Lighting - Pendent/Surface 2nd Floor - Teacher's Room 201A 2 EA 6 6-10 years								
Power Distribution 2nd Floor - Teacher's Room 201A 4 EA 6 6-10 years								
Storage/ Closet 2nd Floor - Teacher's Room 201A 30 SF 7 10+ years								
Walls - Plaster/Drywall 2nd Floor - Teacher's Room 201A 570 SF 7 10+ years								
Ceiling - Plaster/Drywall Basement Engineers Office 200 SF 7 10+ years								
Doors - Wood Doors inclu hw Basement Engineers Office 1 EA 6 10+ years								
Floor - Tile Basement Engineers Office 198 SF 6 10+ years								
Floor - Tile Basement Engineers Office 2 SF 5 1-2 years Missing tiles								
Lighting - Pendent/Surface Basement Engineers Office 2 EA 6 6-10 years								



Catego	ry : Room		В	uilding	: Additi		STON ONICH AVENUE, ONicago, ie 00007
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Basement Engineers Office	4	EA	6	10+ years	
	Storage/ Closet	Basement Engineers Office	30	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement Engineers Office	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement-Faculty Lounge	503	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-Faculty Lounge	1	EA	6	10+ years	
	Floor - Tile	Basement-Faculty Lounge	503	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-Faculty Lounge	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement-Faculty Lounge	6	EA	7	6-10 years	
	Power Distribution	Basement-Faculty Lounge	4	EA	6	10+ years	
	Storage/ Closet	Basement-Faculty Lounge	6	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement-Faculty Lounge	990	SF	7	10+ years	
	Work SInk	Basement-Faculty Lounge	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Janitor's Room	400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Janitor's Room	1	EA	7	10+ years	
	Floor - Concrete	Janitor's Room	400	SF	7	10+ years	
	Lighting - Pendent/Surface	Janitor's Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Janitor's Room	682	SF	7	10+ years	
	Work SInk	Janitor's Room	1	EA	7	10+ years	
Kitchen							
	Ceiling - Splined	Kitchen	394	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen	2	EA	6	10+ years	
	Floor - Tile	Kitchen	394	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen	10	EA	6	6-10 years	
	Power Distribution	Kitchen	10	EA	6	10+ years	
	Storage/ Closet	Kitchen	130	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen	890	SF	7	10+ years	
Library							
	AC Unit	2nd Floor-East of Gymnasium	2	EA	7	6-10 years	
	Casework	2nd Floor-East of Gymnasium	50	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-East of Gymnasium	1,225	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-East of Gymnasium	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor-East of Gymnasium	1,225	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor-East of Gymnasium	32	EA	6	6-10 years	
	Storage/ Closet	2nd Floor-East of Gymnasium	72	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor-East of Gymnasium	1,825	SF	6	10+ years	
Locker/S	Shower Room						
	Accessories	Basement-Kitchen Locker Room	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Kitchen Locker Room	69	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-Kitchen Locker Room	2	EA	6	10+ years	
	Floor - Tile/Sheet	Basement-Kitchen Locker Room	69	SF	7	10+ years	



Catego	ry : Room		Building : Addition 1					
			_			Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	Basement-Kitchen Locker Room	1	EA	5	1-2 years	Faucet leaks	
	Lighting - Pendent/Surface	Basement-Kitchen Locker Room	2	EA	7	10+ years		
	Partitions	Basement-Kitchen Locker Room	1	EA	7	10+ years		
	Student Lockers - One Tier	Basement-Kitchen Locker Room	4	EA	6	10+ years		
	Walls - Plaster/Drywall	Basement-Kitchen Locker Room	340	SF	6	10+ years		
	Water Closet	Basement-Kitchen Locker Room	1	EA	7	6-10 years	Fixture is working	
Lunch &	Multipurpose Room							
	Ceiling - Plaster/Drywall	004 Fitness Room	1,368	SF	7	10+ years		
	Doors - Wood Doors inclu hw	004 Fitness Room	2	ĒA	6	10+ years		
	Floor - Sport Flooring	004 Fitness Room	1,368	SF	7	10+ years		
	Lighting - Pendent/Surface	004 Fitness Room	10	EA	6	6-10 years		
	Market Board	004 Fitness Room	10	LF	6	6-10 years		
	Walls - Masonry	004 Fitness Room	1,627	SF	7	10+ years		
	Walls - Masonry	004 Fitness Room	100	SF	5	1-2 years	Spalling masonry. Quantity updated to match current observations	
	Ceiling - Splined	Basement	1,665	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years		
	Floor - Tile	Basement	1,665	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	36	EA	7	10+ years		
	Serving Line	Basement	16	LF	7	10+ years		
	Walls - Plaster/Drywall	Basement	1,974	SF	7	10+ years		
	Walls - Plaster/Drywall	Basement	50	SF	6	0-1 year	Cracked plaster and paint	
Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	45	SF	7	10+ years		
	Storage Room	1st Floor	90	SF	7	10+ years		
	Janitor's Closet	2nd Floor	35	SF	7	10+ years		
	Janitor's Closet	2nd Floor	45	SF	5	10+ years	Light does not work	
	Air Intake Plenums	Basement	504	SF	7	10+ years	5	
	Boiler Room	Basement	873	SF	7	10+ years		
	Boiler Room	Basement	1,105	SF	7	10+ years		
	Janitor's Closet	Basement	157	SF	7	10+ years	Quantity updated to match current observations	
	Janitor's Closet	Basement	103	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	925	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	1,068	SF	7	10+ years		
	Storage Room	Basement	209	SF	7	10+ years		
Restroor	n							
	Accessories	1st Floor	288	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	288	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years		



Building : Addition 1 Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile Ceramic/ Porcelain 1st Floor 288 SF 6 10+ vears 2 ΕA 7 Floor Drain 1st Floor 10+ years Lavatorv 1st Floor 2 FΑ 7 10+ years Lighting - Pendent/Surface 5 7 1st Floor ΕA 6-10 years Lighting - Pendent/Surface 1st Floor 1 EΑ 6 6-10 years Re-lamp fixture 7 Partitions 1st Floor 4 EΑ 10+ years 8 ΕA 7 10+ years Urinals 1st Floor SF Walls - Plaster/Drvwall 1st Floor 96 7 10+ years SF Walls - Structural Glazed Tile 1st Floor 859 6 10+ years ΕA 7 Water Closet 1st Floor 4 6-10 years Accessories 1st Floor 250 SF 7 6-10 years Ceiling - Plaster/Drywall 1st Floor 250 SF 7 10+ years Doors - Wood Doors inclu hw 2 ΕA 6 10+ years 1st Floor SF 6 Floor - Tile Ceramic/ Porcelain 1st Floor 250 10+ years Floor Drain ΕA 7 1st Floor 1 10+ years 2 FΑ 7 Lavatory 1st Floor 10+ years 3 7 Lighting - Pendent/Surface 1st Floor ΕA 6-10 years Lighting - Pendent/Surface 1st Floor 2 ΕA 6 6-10 years **Re-lamp fixture** 7 Partitions 1st Floor ΕA 7 10+ vears Walls - Plaster/Drywall 1st Floor 77 SF 7 10+ years Walls - Structural Glazed Tile 1st Floor 698 SF 6 10+ years 7 Water Closet 1st Floor 7 EΑ 10+ years 1st Floor-Copy Room SF 7 Accessories 32 6-10 years SF Ceiling - Plaster/Drywall 1st Floor-Copy Room 22 6 10+ years Ceiling - Plaster/Drywall 1st Floor-Copy Room 10 SF 5 1-2 years Water damage Doors - Wood Doors inclu hw 1st Floor-Copy Room 1 ΕA 6 10+ vears 1st Floor-Copy Room 32 SF Floor - Tile 6 10+ years 1st Floor-Copy Room ΕA 7 6-10 years Lavatory 1 Lighting - Pendent/Surface 1st Floor-Copy Room 1 EΑ 7 6-10 years Lighting - Wall Mounted 1st Floor-Copy Room 1 ΕA 7 6-10 years 1st Floor-Copy Room Partitions ΕA 7 10+ vears 1 Walls - Plaster/Drvwall 1st Floor-Copy Room 210 SF 7 10+ vears 1st Floor-Copy Room FΑ 7 10+ years Water Closet 1 Accessories 1st Floor-Kindergarten Room 101 46 SF 7 6-10 years 1st Floor-Kindergarten Room 101 SF 7 Ceiling - Plaster/Drywall 46 10+ years 1st Floor-Kindergarten Room 101 ΕA Doors - Wood Doors inclu hw 1 6 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor-Kindergarten Room 101 46 7 10+ years 1st Floor-Kindergarten Room 101 ΕA 7 Lavatory 1 10+ years Lighting - Pendent/Surface 1st Floor-Kindergarten Room 101 1 EΑ 7 6-10 years Walls - Plaster/Drvwall SF 1st Floor-Kindergarten Room 101 260 7 10+ vears Water Closet 1st Floor-Kindergarten Room 101 ΕA 7 10+ years 1 1st Floor-Principal's Office Restroom 45 SF 7 6-10 vears Accessories Ceiling - Plaster/Drywall 1st Floor-Principal's Office Restroom 45 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor-Principal's Office Restroom 1 EA 7 10+ years



Catego	ry : Room		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor-Principal's Office Restroom	45	SF	6	10+ years	
	Lavatory	1st Floor-Principal's Office Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	
	Partitions	1st Floor-Principal's Office Restroom	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Principal's Office Restroom	252	SF	6	10+ years	
	Water Closet	1st Floor-Principal's Office Restroom	1	EA	7	10+ years	
	Accessories	2nd Floor	250	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	250	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	250	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	5	1-2 years	Missing covers
	Partitions	2nd Floor	6	EA	7	6-10 years	, i i i i i i i i i i i i i i i i i i i
	Walls - Plaster/Drywall	2nd Floor	77	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	698	SF	6	10+ years	
	Water Closet	2nd Floor	7	EA	6	10+ years	
	Accessories	2nd Floor	288	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	286	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	288	SF	6	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	6	6-10 years	
	Partitions	2nd Floor	4	EA	7	6-10 years	
	Urinals	2nd Floor	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	68	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	877	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	6	SF	5	0-1 year	Hole in tiles
	Water Closet	2nd Floor	4	EA	6	6-10 years	
	Accessories	2nd Floor-Teacher's Lounge	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Teacher's Lounge	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Teacher's Lounge	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor-Teacher's Lounge	35	SF	7	10+ years	
	Lavatory	2nd Floor-Teacher's Lounge	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor-Teacher's Lounge	1	EA	5	1-2 years	Missing cover
	Lighting - Wall Mounted	2nd Floor-Teacher's Lounge	1	EA	6	6-10 years	
	Partitions	2nd Floor-Teacher's Lounge	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor-Teacher's Lounge	220	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor-Teacher's Lounge	12	SF	6	10+ years	
	Water Closet	2nd Floor-Teacher's Lounge	1	EA	6	10+ years	



**Building : Addition 1** Category : Room Recommend Replacement Group Item - Type Location Quantity UOM Rank Comments Accessories **Basement** 288 SF 7 6-10 years Ceiling - Plaster/Drywall 288 SF 7 10+ years Basement Doors - Wood Doors inclu hw Basement 2 ΕA 6 10+ years Floor - Tile Ceramic/ Porcelain 272 SF 6 Basement 10+ years SF Floor - Tile Ceramic/ Porcelain Basement 16 4 0-1 year Missing tiles. Floor Drain 2 ΕA 7 Basement 10+ years 2 ΕA 7 10+ years Lavatory Basement Lighting - Pendent/Surface 6 Basement ΕA 7 6-10 years Partitions Basement 4 ΕA 7 10+ years 4 Urinals Basement ΕA 7 10+ years Walls - Plaster/Drywall SF Basement 96 7 10+ vears SF Walls - Structural Glazed Tile Basement 859 6 10+ years Water Closet ΕA 7 10+ years Basement 4 SF Accessories 7 **Engineers Restroom** 45 6-10 years Ceiling - Plaster/Drywall **Engineers Restroom** 45 SF 7 10+ years Doors - Wood Doors inclu hw ΕA 7 Engineers Restroom 1 10+ years Floor - Tile Ceramic/ Porcelain SF **Engineers Restroom** 45 7 10+ years Lavatorv **Engineers Restroom** 1 ΕA 7 10+ years Lighting - Pendent/Surface Engineers Restroom 1 ΕA 7 6-10 years Lighting - Wall Mounted **Engineers Restroom** 1 EΑ 7 6-10 years Walls - Plaster/Drywall **Engineers Restroom** 160 SF 7 10+ years Water Closet **Engineers Restroom** 1 ΕA 7 10+ years

#### ~ .

Catego	Category : Classroom				Building : Addition 1				
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	om #101 (Kindergarten)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	16	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	1,181	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years			
	Floor - Tile	1st Floor	1,181	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	7	EA	6	6-10 years	Relamp		
	Storage/ Closet	1st Floor	182	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,937	SF	7	10+ years			
Classroo	om #102 (Kindergarten)								
	AC Units	1st Floor	4	EA	7	6-10 years			
	Casework	1st Floor	46	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,043	SF	7	10+ years			
	Doors - Transom Window	1st Floor	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Tile	1st Floor	1,043	SF	6	10+ years			

\_ .. .. . . . . .

.



**Category : Classroom** 

**Building : Addition 1** 

U				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	30	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,518	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classro	om #103 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	694	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	Re-lamp fixture
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
Classro	om #105 (Special Program)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
	Floor - Tile	1st Floor	694	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
Classro	om #107 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
	Floor - Tile	1st Floor	694	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	ĒA	6	6-10 years	Re-lamp fixture
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
Classro	om #108 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
			5		Ū	ie. youro	



Catego	ory : Classroom		B	Building : Addition 1				
3	-			Ŭ		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	694	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	19	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	Re-lamp fixture	
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,080	SF	6	10+ years		
Classroo	om #109 (Kindergarten)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	9	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	694	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	19	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	Re-lamp fixture	
	Marker Board	1st Floor	20	LF	7	6-10 years	·	
	Walls - Plaster/Drywall	1st Floor	734	SF	7	10+ years		
Classroo	om #110 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	9	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	694	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	19	ĒA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	Re-lamp fixture	
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years		
Classroo	om #111 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	9	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
			1	EA	6	10+ years		
		1st Floor			-			
	Doors - Wood Doors inclu hw	1st Floor 1st Floor		SF	6	10+ years		
	Doors - Wood Doors inclu hw Floor - Tile	1st Floor	694	SF EA	6 7	10+ years 10+ vears		
	Doors - Wood Doors inclu hw			-	6 7 6	10+ years 10+ years 6-10 years		



Catego	ry : Classroom		В				
						Recommend	nd
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #112 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	694	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	6-10 years	Re-lamp fixture
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
	,		,			,	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	694	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	90	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
	Walls Thatel/Diywall	21011001	1,000	01	0	Tor years	
Classroo	om #203 (Science)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	694	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
	Work Sink	2nd Floor	1,000	EA	7	10+ years	
		21011001			'	iti years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	- 9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years	
		21011001	•	L/\	U	ioi youio	



Catego	ry : Classroom		В	Building : Addition 1			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	2nd Floor	694	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	6-10 years	Relamp
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
lassroc	m #205 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	694	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	Relamp
	Marker Board	2nd Floor	20	LF	6	6-10 years	Rolamp
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	544	SF	7	10+ years	
	Floor - Tile	2nd Floor	150	SF	5	1-2 years	Cracking tile and worn seal
	Lighting - Pendent/Surface	2nd Floor	19	EA	6	6-10 years	Clacking the and worn sear
	Lighting - Pendent/Surface	2nd Floor	19	EA	6		Polomp
	Marker Board	2nd Floor			-	6-10 years	Relamp
	Walls - Plaster/Drywall	2nd Floor	20 1,080	SF	6 6	6-10 years 10+ years	
	-		1,000	01	0	TOF years	
Classroc	<u>m #207 (Regular Classroom)</u> AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor 2nd Floor		SF			
			694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	694	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	



3319 N	Clifton	AVENUE,	Chicago,	IL	60657

Catego	ategory : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	694	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3	SF	6	10+ years	
Classroo	om #209 (Computer Lab)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	694	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	7	10+ years	
Classro	om #210 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	•	
	Doors - Wood Doors inclu hw	2nd Floor	9	EA	6	10+ years 10+ years	
	Floor - Tile	2nd Floor	694	SF	7		
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	2	EA	6	6-10 years	Delema
		2nd Floor 2nd Floor	18	EA		6-10 years	Relamp
	Lighting - Pendent/Surface	2nd Floor	20	LF	6	6-10 years	
	Marker Board			SF	6 6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	ю	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	694	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	



Catego	ry : Classroom		В	uildina	: Additi		STENCE CINCLE CONCERNE	
ealege			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years		
						,		
Classroo	m #212 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	694	SF	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	Relamp	
	Lighting - Pendent/Surface	2nd Floor	17	EA	6	6-10 years	-	
	Marker Board	2nd Floor	20	LF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years		
Catego	ry : Interior		В	uilding	: Additi	on 1		
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Plaster/Drywall	1st Floor	2,164	SF	7	10+ years		
	Doors - Store Front	1st Floor	2	EA	7	10+ years		
	Doors - Transom Window	1st Floor	12	SF	7	10+ years		
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years		
	Floor - Tile/Sheet	1st Floor	2,164	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	23	EA	7	6-10 years		
	Student Lockers - One Tier	1st Floor	133	EA	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	651	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	1,209	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	2,146	SF	6	10+ years		
	Doors - Store Front	2nd Floor	2	EA	6	10+ years		
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years		
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	1-2 years	Out of order	
					7	6-10 years		
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA		•		
	Floor - Tile/Sheet	2nd Floor	2,164	SF	7	10+ years		
	Floor - Tile/Sheet Lighting - Pendent/Surface	2nd Floor 2nd Floor	2,164 22	SF EA	7 6	10+ years 6-10 years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier	2nd Floor 2nd Floor 2nd Floor	2,164 22 152	SF EA EA	7 6 6	6-10 years 6-10 years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor	2,164 22 152 651	SF EA EA SF	7 6 6	6-10 years 6-10 years 10+ years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	2,164 22 152 651 1,209	SF EA EA SF SF	7 6 6 6	6-10 years 6-10 years 10+ years 10+ years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain Ceiling - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor Basement	2,164 22 152 651 1,209 2,164	SF EA EA SF SF SF	7 6 6 6 7	6-10 years 6-10 years 10+ years 10+ years 10+ years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain Ceiling - Plaster/Drywall Doors - Wood Doors include hw	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor Basement Basement	2,164 22 152 651 1,209	SF EA SF SF EA	7 6 6 6 7 7	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor Basement Basement Basement	2,164 22 152 651 1,209 2,164 6 1	SF EA SF SF EA EA	7 6 6 6 7 7 7	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Concrete	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor Basement Basement Basement Basement	2,164 22 152 651 1,209 2,164 6 1 2,164	SF EA SF SF EA EA SF	7 6 6 7 7 7 7	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor Basement Basement Basement	2,164 22 152 651 1,209 2,164 6 1 2,164 28	SF EA SF SF EA SF EA SF EA	7 6 6 6 7 7 7	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years		
	Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Concrete	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor Basement Basement Basement Basement	2,164 22 152 651 1,209 2,164 6 1 2,164	SF EA SF SF EA EA SF	7 6 6 7 7 7 7	6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years		



Catego	ry : Interior	B	uilding	: Additi			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Stairs							
	Ceiling - Plaster/Drywall	South to Class 101	200	SF	6	10+ years	
	Floor - Terrazzo	South to Class 101	120	SF	7	10+ years	
	Handrails	South to Class 101	72	LF	7	10+ years	
	Lighting - Pendent/Surface	South to Class 101	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	South to Class 101	1	EA	5	1-2 years	Missing cover
	Stairs - Terrazzo	South to Class 101	36	LF	6	10+ years	
	Walls - Plaster/Drywall	South to Class 101	1,080	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair 2 (East)	280	SF	6	10+ years	
	Floor - Concrete	Stair 2 (East)	140	SF	7	10+ years	
	Floor - Terrazzo	Stair 2 (East)	212	SF	7	10+ years	
	Handrails	Stair 2 (East)	128	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	Stair 2 (East)	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Stair 2 (East)	18	EA	6	6-10 years	
	Stairs - Terrazzo	Stair 2 (East)	64	LF	6	10+ years	
	Walls - Plaster/Drywall	Stair 2 (East)	1,820	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stair 2 (East)	900	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair 5 (South East)	120	SF	6	10+ years	
	Floor - Terrazzo	Stair 5 (South East)	64	SF	7	10+ years	
	Handrails	Stair 5 (South East)	44	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair 5 (South East)	2	EA	6	6-10 years	
	Stairs - Terrazzo	Stair 5 (South East)	22	LF	6	10+ years	
	Walls - Plaster/Drywall	Stair 5 (South East)	222	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Stair 5 (South East)	26	SF	6	10+ years	



Catego	ry : Exterior		В	Building : Addition 2				
-				Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance	9							
	Exterior Doors - Exterior FRP Door	#1 - NW	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	#1 - NW	2	EA	6	10+ years		
	Exterior Stairs - Stone	#1 - NW	6	LF	6	10+ years		
	Entrance Control - Audio and Video	#6 - NE	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#6 - NE	2	EA	6	10+ years		
	Exterior Stairs - Concrete	#6 - NE	18	LF	5	10+ years		
	Power Door Operator and Controls	#6 - NE	1	EA	7	10+ years		
	Ramp Handrail - Steel_Ramp Handrail	#6 - NE	7	LF	6	10+ years		
	Ramps - Concrete	#6 - NE	10	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	#6 - NE	12	LF	6	10+ years		
Foundat	ion							
	Foundation - Concrete	Entire Building	275	LF	7	10+ years		
	Superstructure - Concrete	Entire Building	14,988	SF	6	10+ years		
Lighting								
<u>– - 9 9</u>	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	10+ years		
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	10+ years		
Roof Sy	stom							
Root Oy	Access Ladder - Metal	Main Roof	1	EA	7	10+ years		
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years		
	Coping - Stone	Main Roof	275	LF	7	10+ years		
	Downspouts - Interior Downspouts	Main Roof	36	LF	7	10+ years		
	Parapet - 16" - 30" Height	Main Roof	275	LF	7	10+ years		
	Roof - Modified Bitumen	Main Roof	4,996	SF	7	10+ years		
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years		
	Roof Structure - Concrete	Main Roof	4,996	SF	7	10+ years		
Walls								
	Exterior Walls - Brick	Entire Building	6,810	SF	5	10+ years		
	Exterior Walls - Stone-Cast	Entire Building	750	SF	5	10+ years		
Window								
	Curtain wall - Louver	Entire Building	24	SF	6	6-10 years	No damaged lovers observed	
	Guard - Guards perforated	Entire Building	656	SF	6	10+ years		
	Lintels - Steel	Entire Building	123	LF	6	10+ years		
	Lintels - Stone	Entire Building	125	LF	6	10+ years		
	Windows - Decorative	Entire Building	80	SF	6	10+ years		
	Windows - Sash Aluminum Double-pane	Entire Building	1,904	SF	6	10+ years		



ALL A	Schools						3319 N Clifton AVENUE, Chicago, IL 606
Catego	ry : Exterior		В	uilding	: Additie	on 2	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
atego	ry : Electrical		В	uilding	: Additie	on 2	
J	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergei	ncy System						
-	Exit Signs - Corridors and Stairs	Corridors and Stairs	4	EA	6	2-5 years	
	Emergency Battery Packs - Corridors and Stairs	Corridors and Stairs	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Corridors and Stairs	2	EA	6	2-5 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,232	SF	6	2-5 years	
	Emergency A/C Power - Students Toilets	Entire Building	350	SF	6	2-5 years	
	Security System - Intrusion Detection	Entire Building	14,988	SF	5	2-5 years	
Main Se	rvice						
	PA System	Entire Building	14,988	SF	6	2-5 years	
Power D	listribution						
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	2-5 years	
Catego	ry : Fire Protection		Building : Addition 2				
_						Recommend	
Group	ltem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	14,988	SF	3	0-1 year	No strobes
	Fire Alarm_System	Entire Building	14,988	SF	4	2-5 years	Outdated system, no strobe lights installed
Catego	ry : Mechanical		В	uilding	: Additie		
				_		Recommend	•
Group	Item - Type	Location	B Quantity	uilding UOM	: Additio Rank		Comments
Group	Item - Type /stems			UOM	Rank	Recommend Replacement	Comments
Group	Item - Type vstems Condensate Pump	Entire Building		UOM EA	Rank	Recommend Replacement 6-10 years	Comments
Group	Item - Type <u>estems</u> Condensate Pump Condensate Pump		Quantity	UOM EA EA	<b>Rank</b> 5 5	Recommend Replacement 6-10 years 6-10 years	Comments
Group	Item - Type (stems Condensate Pump Condensate Pump Piping - Condensate Pipe- Steel	Entire Building	Quantity 1 1 250	UOM EA EA LF	Rank	Recommend Replacement 6-10 years	Comments
Group	Item - Type <u>estems</u> Condensate Pump Condensate Pump	Entire Building Entire Building	Quantity 1 1	UOM EA EA LF LF	<b>Rank</b> 5 5	Recommend Replacement 6-10 years 6-10 years	Comments
Catego Group Boiler Sy	Item - Type (stems Condensate Pump Condensate Pump Piping - Condensate Pipe- Steel	Entire Building Entire Building Entire Building	Quantity 1 1 250	UOM EA EA LF	<b>Rank</b> 5 5 6	6-10 years 6-10 years 6-10 years 6-10 years	Comments



Catego	ory : Mechanical		В	uilding	: Additi	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
U	Unit Heater - Electric	Electrical Room	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	7	EA	5	2-5 years	
	Cabinet Heaters - With Steam Coil	Entire Building	2	EA	5	2-5 years	
	Cabinet Heaters - With Steam Coil	Entire Building	4	EA	5	2-5 years	
	Fin Tube - Steam	Stairs	10	LF	6	6-10 years	
Tempera	ature Control						
	Electric Controls	Entire Building	6,000	SF	6	6-10 years	Univents controlled manually
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Unit heater
	Electric Thermostat	Entire Building	4	EA	5	2-5 years	Not fully responsive
	Pneumatic System	Entire Building	14,988	SF	3	0-1 year	Not operational, served by addition 1
	Thermostats - Pneumatic	Entire Building	8	EA	4	0-1 year	Not operational
Unit Ver	itilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	8	EA	6	6-10 years	
Ventilati	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	10+ years	

Category	:	Plumbing
----------	---	----------

Building	:	Addition	2	
	-		_	

Jacogo	togory i ramonig		Bullang : / launon 2				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	14,988	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	14,988	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	14,988	SF	6	2-5 years	
	Fixtures	6					
	Domestic Piping-Hot/Cold Water Supply	Entire Building	14,988	SF	6	2-5 years	
	(Horizontal Lines)	C C				-	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	14,988	SF	6	2-5 years	
	(Risers)	-				-	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	14,988	SF	6	2-5 years	
	(from Risers to Fixtures)	-				-	
	Sanitary Piping	Entire Building	14,988	SF	5	6-10 years	
	Storm Piping	Entire Building	14,988	SF	5	6-10 years	
	Vent Piping	Entire Building	14,988	SF	5	6-10 years	
		-				-	



Catego	ry : Plumbing		В	uilding	: Additi		STON ONION AVENUE, ONicago, ie 00007
U	, ,			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Pumps							
	Pumps - Sump-Simplex	Basement	1	EA	5	2-5 years	
0							
Catego	ry : Classroom		В	uilding	: Additi	on 2 Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #113 (Music Room)					-	
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	707	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	707	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	6-10 years	Relamp
	Marker Board	1st Floor	20	LF	7	6-10 years	Rolamp
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
			1,000	0.	•	ior youro	
Classroo	m #114 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	707	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	707	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	19	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	Relamp
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
Classroo	m #115 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	707	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	707	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	5	0-1 year	Out of service
Closeres	m #116 (Art Room)						
Classico	AC Units	1st Floor	0	E۸	7	6 10 years	
			2	EA LF	7	6-10 years	
	Casework	1st Floor	22	LF SF	6 7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	707	SF	1	10+ years	



Group	/ : Classroom Item - Type Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Work Sink p#213 (Regular Classroom)	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 1 690 17 18 2 20 1,080 1	UOM EA SF EA EA LF SF	: Addition Rank 6 6 5 7 6 6 6	Recommend Replacement 10+ years 10+ years 1-2 years 6-10 years 6-10 years	Comments Cracking tiles Relamp
Classroom	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Work Sink	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 690 17 18 2 20 1,080	EA SF EA EA LF	6 6 5 7 6	10+ years 10+ years 1-2 years 6-10 years 6-10 years	Cracking tiles
Classroom	Floor - Tile Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Work Sink	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	690 17 18 2 20 1,080	SF SF EA EA LF	6 5 7 6	10+ years 1-2 years 6-10 years 6-10 years	ç
Classroom	Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Work Sink	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	17 18 2 20 1,080	SF EA EA LF	5 7 6	1-2 years 6-10 years 6-10 years	ç
lassroom	Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Work Sink	1st Floor 1st Floor 1st Floor 1st Floor	18 2 20 1,080	EA EA LF	7 6	6-10 years 6-10 years	ç
Classroom	Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Work Sink 1 #213 (Regular Classroom)	1st Floor 1st Floor 1st Floor	2 20 1,080	EA LF	6	6-10 years	Relamp
lassroom	Marker Board Walls - Plaster/Drywall Work Sink n #213 (Regular Classroom)	1st Floor 1st Floor	20 1,080	LF			Relamp
lassroom	Walls - Plaster/Drywall Work Sink n #213 (Regular Classroom)	1st Floor	1,080		6	0.40	
lassroom	Work Sink			SE	0	6-10 years	
lassroom	a #213 (Regular Classroom)	1st Floor	1		7	10+ years	
				EA	7	10+ years	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	22	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	707	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	707	SF	7	6-10 years	
1	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	24	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
lassroom	n #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	707	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	707	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	Relamp
	Marker Board	2nd Floor	20	LF	6	6-10 years	
,	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
lassroom	n #215 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	22	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	707	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	707	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	Relamp
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
	Work Sink	2nd Floor	1,000	EA	5	0-1 year	Not in use



ears ears ears ears ears ears ears ears
ears ears ears ears ears ears ears ears
ears ears cracking, broken tiles ears ears ears ears ears ears ears ea
ears ears Cracking, broken tiles ears ears ears ears ears ears ears ea
ears Cracking, broken tiles ears ears ears ears ears ears ears ea
ears Cracking, broken tiles ears ears ears ears ears ears ears ea
ears ears ears ears ears ears ears ears
ears ears ears ears ears ears ears ears
ears ears ears ears ears ears ears ears
ears ears ears ears ears ears ears
ears ears ears ears ears ears
ears ears ears ears
ears ears ears ears
ears ears ears
ears ears
ears
ears
mend
ement Comments
ears
ears Water damage
ears
ears
ears Re-lamp fixture
ears
ears
ears
ears Epoxy is peeling
ears
ears
ears
ears
ears
ears



Category : Room			Building : Addition 2							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Mechan	cal/ Service Rooms									
	Storage Room	2nd Floor	234	SF	5	10+ years	Water damage on north wall, calcium buildup			
	Mechanical/ Service Rooms	Basement	137	SF	4	0-1 year	Ceiling is caving/water damaged			
Restroo	n									
	Accessories	1st Floor	175	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor	175	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor	175	SF	6	10+ years				
	Floor Drain	1st Floor	1	EA	7	10+ years				
	Lavatory	1st Floor	2	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	1st Floor	2	EA	5	1-2 years	Missing covors			
	Partitions	1st Floor	4	EA	7	10+ years	Missing covers			
	Walls - Plaster/Drywall	1st Floor	•	SF	7	•				
			256	SF		10+ years				
	Walls - Structural Glazed Tile	1st Floor	378		6	10+ years				
	Water Closet	1st Floor	3	EA	7	10+ years				
	Water Closet	1st Floor	1	EA	4	1-2 years	Out of order			
	Accessories	1st Floor	42	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor	42	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	42	SF	6	10+ years				
	Lavatory	1st Floor	1	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years				
	Lighting - Wall Mounted	1st Floor	1	EA	7	6-10 years				
	Partitions	1st Floor	1	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	243	SF	7	10+ years				
	Water Closet	1st Floor	1	EA	7	10+ years				
	Accessories	2nd Floor	42	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	42	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ vears				
	Floor - Tile	2nd Floor	42	SF	6	6-10 years				
	Lavatory	2nd Floor	1	ĒA	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	Relamp			
	Lighting - Wall Mounted	2nd Floor	1	EA	6	6-10 years	loamp			
	Partitions	2nd Floor	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	2nd Floor	243	SF	6	10+ years				
	Water Closet	2nd Floor	243	EA	6	10+ years				
	Accessories	2nd Floor	175	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	175	SF	6	•				
				-		10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor	175	SF	6	10+ years				
	Floor Drain	2nd Floor	1	EA	7	10+ years				



Category : Room			B	Building : Addition 2					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lavatory	2nd Floor	2	EA	6	6-10 years			
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	3	EA	5	1-2 years	Missing covers		
	Partitions	2nd Floor	4	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	252	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	378	SF	6	10+ years			
	Water Closet	2nd Floor	3	EA	6	10+ years			
	Water Closet	2nd Floor	1	EA	4	1-2 years	Out of order		

**Building : Addition 2** 

#### **Category : Interior**

Recommend Location Item - Type Quantity UOM Rank Replacement Comments Group Corridor Ceiling - Plaster/Drywall 1st Floor 516 SF 7 10+ vears Drinking Fountains - Single Water Cooler ΕA 7 1st Floor 2 6-10 years Floor - Tile/Sheet 496 SF 7 1st Floor 10+ years SF Floor - Tile/Sheet 1st Floor 20 5 1-2 years Cracking and chipping tiles Lighting - Pendent/Surface 6 ΕA 7 1st Floor 10+ years Walls - Plaster/Drywall 1st Floor 322 SF 7 10+ years Walls - Structural Glazed Tile SF 1st Floor 598 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 518 SF 6 10+ years Ceiling - Plaster/Drywall SF 2nd Floor 20 5 1-2 years Cracking Drinking Fountains - Single Fountain 2nd Floor 1 EΑ 7 10+ vears Floor - Tile/Sheet SF 7 10+ years 2nd Floor 518 Floor - Tile/Sheet 2nd Floor 20 SF 5 1-2 years Chipping and cracking tiles ΕA 6 Lighting - Pendent/Surface 2nd Floor 6 6-10 years Walls - Plaster/Drywall 2nd Floor SF 6 188 10+ years SF Walls - Tile Ceramic/ Porcelain 2nd Floor 350 6 10+ years SF Ceiling - Plaster/Drywall Basement 600 7 10+ years SF Floor - Concrete Epoxy/ Painted 650 Discoloration and uneven layers of Basement 4 1-2 years epoxy Lighting - Pendent/Surface Basement 4 EΑ 6 6-10 years Stairs - Concrete Stairs Basement 5 LF 7 10+ years Walls - Plaster/Drywall SF Basement 625 7 10+ years Stairs Ceiling - Plaster/Drywall 300 SF 6 West 10+ years Floor - Concrete West 162 SF 7 10+ years Floor - Terrazzo SF 7 West 450 10+ years Floor - Tile SF West 18 6 10+ years LF Handrails West 128 7 10+ years Lighting - Chandelier, Incandescent West 2 ΕA 6 6-10 years

Lighting - Lay-in

Lighting - Pendent/Surface

1

9

EΑ

EΑ

6

6

6-10 years

6-10 years

West

West



Category : Interior			B	Building : Addition 2					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Stairs - Terrazzo	West	64	LF	6	10+ years			
	Walls - Plaster/Drywall	West	1,768	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	West	952	SF	6	10+ years			



Category : Site			В	uilding			
_			•			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Lighting	East	10	EA	6	10+ years	
	Surface - Synthetic	East	30,232	SF	6	10+ years	
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	7	10+ years	
Fencina							
eneing	Fencing - Chain Link	Entire Site	288	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	925	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	30	LF	5	1-2 years	Corroded fence, corroded posts,
	rending - New Standard Offiamental		50	LI	5	1-2 years	broken, retaining wall. Fence shake
Landsca	ре						
	Benches	Entire Site	37	EA	6	10+ years	
	Landscape - Grass	Entire Site	10,113	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	1,628	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,240	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	880	SF	6	10+ years	
	Parkway trees	Entire Site	33	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	800	SF	6	10+ years	
	Trash Receptacles	Entire Site	7	EA	6	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	5,985	SF	6	10+ years	
Parking	l ot						
	Concrete Curbs	North	400	LF	6	10+ years	
	Interior Plantings	North	80	LF	6	10+ years	
	Lighting - Pole Mounted	North	12	EA	6	10+ years	
	Pavers	North	875	SF	6	10+ years	
	Surface - Asphalt	North	18,150	SF	6	6-10 years	Verified Most of surface in fair
	Surface - Asphalt	North	1,800	SF	4	0-1 year	condition Potholes, alligatored surface, crack
	Trash Enclosure - Chain Links			SF	4		Foundies, anigatored surface, clack
	Vehicular Screening	North North	360 20	LF	6	10+ years 10+ years	
Dioversi	-						
Playgrou	Equipment - Combo 3-12	North	1	EA	6	10+ years	
	Equipment - Pre K 3-5	North	1	EA	6	10+ years	
	Equipment - Swingset	North	1	EA	6		
	Equipment - Swingset	NOIT	Ĭ	EA	U	10+ years	



Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Poured Surface	North	4,622	SF	7	10+ years	
Sidewall	(5						
	Sidewalks - Internal Walks	Entire Site	380	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	13,970	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	125	SF	5	1-2 years	Upheaved, broken, cracked
_Signage							
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site	2	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	3	EA	7	10+ years	

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated ٠
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like ٠ chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



#### **Classroom Summary**

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Addition 2									
Art Room	Regular Classroom	1st Floor	116	116	707	105	52	N	N
Music Room	Regular Classroom	1st Floor	113	113	707	105	52	N	N
Other Instructional Use	Multi Purpose Room	Basement	B 214	NA	720	64	20		
Regular Classroom	Regular Classroom	1st Floor	114	114	707	105	52	N	N
Regular Classroom	Regular Classroom	1st Floor	115	115	707	105	52	N	N
Regular Classroom	Regular Classroom	1st Floor	216	216	707	105	52	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	707	105	52	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	707	105	52	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	707	105	52	N	Y
Building : Addition 1			1	1	I	1	r	1	
Computer Lab	Regular Classroom	2nd Floor	209	209	694	110	55	N	N
Kindergarten	Kindergarten	1st Floor	101	101	1,181	220	72	N	N
Kindergarten	Multi Purpose Room	1st Floor	102	102	1,043	180	90	N	N
Kindergarten	Regular Classroom	1st Floor	109	109	694	168	55	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	694	110	55	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	694	110	55	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	694	110	55	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	694	110	55	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	694	110	55	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	694	110	55	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	694	110	55	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	694	110	55	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	694	110	55	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	694	110	55	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	207	207	694	110	55	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	694	110	55	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	210	210	694	110	55	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	211	211	694	110	55	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	694	110	55	N	Ν
Science	Regular Classroom	2nd Floor	203	203	694	110	55	N	Ν
Special Program	Regular Classroom	1st Floor	105	105	694	110	55	Ν	N