

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1906	3	50,925
Addition	1997	3	51,015
Campus Total			101,940

Category : Exterior Building : Main

Catego	y : Exterior		В	ullaing	: wam		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#10_Exit S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10_Exit S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#10_Exit S	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3 W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 W	14	LF	7	10+ years	Divided out damaged areas
	Exterior Stairs - Concrete	#3 W	6	LF	5	1-2 years	Cracked, spalled
	Exterior Doors - Exterior Steel Door	#4 W	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 W	9	LF	6	10+ years	
	Exterior Stairs - Stone	#4 W	9	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 W	20	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6.5 E	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6.5 E	3	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#6_Exit W	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6_Exit W	6	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7_Exit E	2	EA	6	10+ years	
	Exterior Stairs - Stone	#7_Exit E	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8_Exit E	2	EA	6	10+ years	
	Exterior Stairs - Stone	#8_Exit E	6	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Esca	ape						
	Exterior Doors - Exterior Steel Door	Façade- NE	2	EA	6	6-10 years	
	Fire Escape	Façade- NE	22	LF	7	10+ years	
	Paints	Façade- NE	22	LF	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Façade- SE	2	EΑ	6	6-10 years	
	Fire Escape	Façade- SE	23	LF	6	10+ years	
	Paints	Façade- SE	23	LF	7	6-10 years	
		3				- · · , · · · ·	
Foundati	ion						
	Foundation - Masonry	Entire Building	1,205	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	50,925	SF	7	10+ years	
	•	•				•	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Roof #1	2	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof #1	70	LF	7	10+ years	
	Liner		-			, , , , , ,	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof #1	22	LF	5	0-1 year	Banded, deteriorated mortar
	Liner					, , , , , ,	
	Coping - Stone	Roof #1	544	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #1	120	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof #1	120	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof #1	551	LF	7	10+ years	
	Roof - Modified Bitumen	Roof #1	8,800	SF	7	10+ years	Recalculated quantity
	Roof Hatch - Metal	Roof #1	1	ĒΑ	7	10+ years	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	Roof Structure - Steel with Clay Tile Arch	Roof #1	8,800	SF	7	10+ years	Recalculated quantity
	Access Ladder - Metal	Roof #2	. 1	EA	7	10+ years	, ,
	Coping - Stone	Roof #2	120	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #2	30	LF	7	10+ years	Added
	Downspouts - Interior Downspouts	Roof #2	30	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof #2	120	LF	7	10+ years	
	Roof - Modified Bitumen	Roof #2	3,270	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof #2	3,270	SF	7	10+ years	
	Coping - Metal	Roof #3	225	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #3	30	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof #3	225	LF	7	10+ years	
	Roof - Modified Bitumen	Roof #3	3,092	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof #3	3,092	SF	7	10+ years	
	Coping - Metal	Roof #4	52	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #4	38	LF	7	10+ years	Corrected quantity
	Parapet - 16" - 30" Height	Roof #4	52	LF	7	10+ years	



Stairs

Exit Signs - Auditoium

James Hedges Elementary School 4747 S Winchester AVENUE, Chicago, IL 60609

divided/aggregated.
Location changed for clarification.

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Roof #4	616	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof #4	616	SF	7	10+ years	
	Access Ladder - Metal	Roof 5	1	EA	7	10+ years	Divided out from main roof
	Coping - Stone	Roof 5	40	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 5	40	LF	7	10+ years	Divided out from main roof
	Parapet - Parapet < 16" Height	Roof 5	50	LF	7	10+ years	Divided out from main roof
	Roof - Modified Bitumen	Roof 5	440	SF	7	10+ years	Divided out from main roof
	Roof Structure - Steel with Clay Tile Arch	Roof 5	440	SF	7	10+ years	Divided out from main roof
Walls							
	Cheek-Wall - Stone	Entire Building	73	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	438	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	23,335	SF	6	10+ years	Tuckpointing performed recently
	Exterior Walls - Brick	Entire Building	50	SF	4	1-2 years	Open joints, shifting
	Exterior Walls - Stone-Cut	Entire Building	2,768	SF	5	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	270	SF	6	10+ years	
Vindows	3						
	Guard - Guards perforated	Entire Building	735	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	48	SF	6	10+ years	
	Lintels - Brick	Entire Building	70	LF	6	10+ years	
	Lintels - Steel	Entire Building	270	LF	6	10+ years	
	Lintels - Stone	Entire Building	200	LF	6	10+ years	
	Windows - Louver	Entire Building	60	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,927	SF	5	2-5 years	Many don't work
Catego	ry : Electrical		В	uilding	: Main		
Group	Hom Tuno	Location		UOM	Rank	Recommend	Commonto
Group	Item - Type	Location	Quantity	OOM	Kank	Replacement	Comments
-merger	ncy System						

Caleg	ory . Electrical			unung	. IVIAIII		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerae	ency System						
- 3	Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Serves EM circuits in Main. Rank, Reason and Priority Rep adjusted as the unit dates to 1974 and has exceeded its EUL.
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,360	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,999	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	3	EA	6	6-10 years	Location changed for clarification.
	Emergency Battery Packs - Corridors and	Entire Building	11	EA	6	6-10 years	Quantity changed as total has been

Campus Name: Hedges Page : 3 of 44 Assessment Date: 11/09/2023

EΑ

2

0-1 year

Entire Building



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Corridors and Stairs	Entire Building	21	EA	2	0-1 year	Exit Signs are not equipped with backup batteries and the school has no emergency generator. Quantity changed as total has been divided/aggregated. Exit Signs are not equipped with backup batteries and the school has no emergency generator.
	Security System - CCTV	Entire Building	50,925	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	50,925	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	50,925	SF	6	6-10 years	Served by Addition.
Power D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building Entire Building	1	EA	4	0-1 year 0-1 year	Reason and Priority Rep adjusted as the panel is missing an interior cover plate which exposes live conductors presenting a live front condition. Quantity changed as total has been divided/aggregated. Location changed for clarification. Rank, Reason and Priority Rep changed as
		5 ¢ 8 %	40	- ^	-	40	an open fuse receptacle exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	30 20
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar		Machaniaal Dagas				0.5.400	Compa Main Denal is functional and
	Fire Alarm Panel	Mechanical Room	1	EA	3	2-5 years	Serves Main. Panel is functional and passes inspection but unit is 30-plus years old, employs antiquated



Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fire Alarm_System	Mechanical Room	50,925	SF	4	2-5 years	technology, and has exceeded its EUL. No CPS Asset Tag present. System is functional and passes inspection but system is 30-plus years old, employs antiquated technology, and has exceeded its EUL.

Category : Mechanical **Building: Main**

Calego	ry . Mechanicai			unung	. IVICIII		
^	Name Tama	Landina	0	LIOM	D!-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 15000 - 30000 cfm	Basement	1	EA	5	6-10 years	AHU-1, serves the spaces in Main except for auditorium.
	Air Intake	Basement	1	EA	5	6-10 years	Location changed for clarification. There are no roof air intakes at Ma
	Auxiliaries - 15000 - 30000 cfm	Basement	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	150	LF	5	6-10 years	
	Zone Dampers	Basement	19	EA	5	6-10 years	Location changed for clarification.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Basement	1	EA	5	6-10 years	AHU-2, serves auditorium and associated spaces.
	Air Intake	Basement	1	EA	5	6-10 years	Location changed for clarification. There are no roof air intakes at Ma
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	50	LF	5	6-10 years	
	Zone Dampers	Basement	5	EA	5	6-10 years	Location changed for clarification.
Boiler Sy	ystems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	5	6-10 years	B-2
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	5	6-10 years	B-1
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	6-10 years	

Campus Name: Hedges Page : 5 of 44 Assessment Date: 11/09/2023



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	6-10 years	
	Steam Traps	Boiler Room	15	EA	5	6-10 years	
Heating	Devices						
	Unit Heater - Gas	Basement	1	EA	6	6-10 years	
	Unit Heater - Gas	Basement	1	EA	2	0-1 year	Reason and Priority Rep changed as unit remains nonfunctional and is not needed; it has been deemed to be obsolete and has been abandoned in place.
	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	Quantity changed based on current observations.
	Wall Heater - Electric	Entire Building	3	EA	4	0-1 year	Quantity changed based on current observations. Reason and Priority Rep changed as units are missing front cover which exposes live conductors presenting a live front condition and/or exposes moving mechanical parts presenting a risk of personal injury.
Temper	ature Control						
	DDC System	Entire Building	50,925	SF	4	1-2 years	Main uses its1997-installation, non-hybrid DDC temperature control system. Rank, Reason and Priority Rep established as the system is outdated and ineffective throughout most of the building with many manual adjustments required for appropriate temperature control.
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	Quantity and Location changed as total has been divided/aggregated.
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	total has been divided/agglegated.
	Thermostats - DDC	Entire Building	24	ĒĀ	4	1-2 years	Item Type changed based on review with Building Engineer. Reason and Priority Rep adjusted as there is little if any communication to the control system which is outdated and ineffective throughout most of the building, and many manual adjustments are required for appropriate temperature control.



James Hedges Elementary School

onate?	ry : Mechanical		P	uilding	· Main		S Winchester AVENUE, Chicago, IL 60609
Jaiego	i y . Mechanicai		Б	unung	. IVIAIII	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
entilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Lower Roof	2	EA	5	6-10 years	Not directly accessible in a safe manner at the time of assessment due to unreliable climbing means. Condition verified by Building Engineer.
Catego	ry : Plumbing		В	uilding	: Main		
<u> </u>						Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	4	2-5 years	Unit is fully operational and is leak- free with minor signs of external deterioration; Rank, Reason and Priority Rep adjusted as it is 25 year old and has exceeded its EUL.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	50,925	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	50,925	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	50,925	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	50,925	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	50,925	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	50,925	SF	6	6-10 years	
	Sanitary Piping	Entire Building	50,925	SF	5	6-10 years	
	Storm Piping	Entire Building	50,925	SF	5	6-10 years	
	Vent Piping	Entire Building	50,925	SF	5	6-10 years	
umps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	6	6-10 years	
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	AC Unit	Basement Parent's Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Parent's Room	980	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Parent's Room	1	EΑ	6	10+ years	

Campus Name: Hedges Page : 7 of 44 Assessment Date: 11/09/2023



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Epoxy/ Painted	Basement Parent's Room	980	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement Parent's Room	16	EA	6	6-10 years	
	Power Distribution	Basement Parent's Room	24	EA	6	10+ years	
	Storage/ Closet	Basement Parent's Room	12	SF	7	10+ years	
	Walls - Masonry	Basement Parent's Room	1,600	SF	6	10+ years	
	AC Unit	Basement-010 Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-010 Office	336	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-010 Office	1	EA	6	6-10 years	
	Floor - Tile	Basement-010 Office	336	SF	5	6-10 years	Missing 2 SF.
	Lighting - Pendent/Surface	Basement-010 Office	4	EA	7	6-10 years	
	Power Distribution	Basement-010 Office	10	EA	6	10+ years	
	Storage/ Closet	Basement-010 Office	50	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement-010 Office	758	SF	5	10+ years	
Auditoriu	ım & Theater						
	Balcony Seating	1st Floor-Assembly Hall, between 111/115	98	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Assembly Hall, between 111/115	3,360	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Assembly Hall, between 111/115	8	EA	6	10+ years	
	Floor - Carpet	1st Floor-Assembly Hall, between 111/115	1,008	SF	6	6-10 years	
	Floor - Wood	1st Floor-Assembly Hall, between 111/115	910	SF	6	10+ years	
	Floor - Wood	1st Floor-Assembly Hall, between 111/115	2,352	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Assembly Hall, between 111/115	11	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor-Assembly Hall, between 111/115	12	EA	6	6-10 years	
	Main Floor Seating	1st Floor-Assembly Hall, between 111/115	500	EA	5	6-10 years	
	Sound System	1st Floor-Assembly Hall, between 111/115	1	EA	5	6-10 years	
	Stage	1st Floor-Assembly Hall, between 111/115	785	SF	7	10+ years	
	Stage Curtain	1st Floor-Assembly Hall, between 111/115	3	EA	7	10+ years	
	Stage Lighting System	1st Floor-Assembly Hall, between 111/115	1	EA	5	10+ years	
	Stage-Stairs - Wood	1st Floor-Assembly Hall, between 111/115	10	LF	6	10+ years	
	Stairs - Wood	1st Floor-Assembly Hall, between	18	LF	6	10+ years	

Campus Name: Hedges Page : 8 of 44 Assessment Date: 11/09/2023



Catego	ry : Room		В	uilding	: Main			
	_				_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	111/115 1st Floor-Assembly Hall, between 111/115	5,410	SF	6	10+ years		
_Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	15	SF	5	10+ years		
	Janitor's Closet	2nd Floor	15	SF	5	10+ years		
	Janitor's Closet	3rd Floor	15	SF	5	10+ years		
	Air Intake Plenums	Basement	170	SF	5	10+ years		
	Air Tunnel	Basement	1,472	SF	5	10+ years		
	Boiler Room	Basement	1,260	SF	5	10+ years		
	Coal Room	Basement	960	SF	5	10+ years		
	Mechanical/ Service Rooms	Basement	635	SF	5	10+ years		
	Storage Room	Basement	2,220	SF	5	10+ years		
_Restroor	n							
	Accessories	1st Floor Unisex	115	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor Unisex	115	SF	6	10+ years		
	Doors - Transom Window	1st Floor Unisex	8	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor Unisex	2	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex	110	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex	5	SF	4	1-2 years	Cracked tile	
	Lavatory	1st Floor Unisex	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor Unisex	2	EA	7	10+ years		
	Partitions	1st Floor Unisex	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor Unisex	285	SF	6	10+ years		
	Water Closet	1st Floor Unisex	1	EA	7	10+ years		
	Accessories	2nd Floor-Boy's Restroom, near 211	75	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor-Boy's Restroom, near 211	75	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor-Boy's Restroom, near 211	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Boy's Restroom, near 211	70	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Boy's Restroom, near 211	5	SF	4	1-2 years	Missing tile/crack in floor	
	Floor Drain	2nd Floor-Boy's Restroom, near 211	1	EA	7	6-10 years	-	
	Lavatory	2nd Floor-Boy's Restroom, near 211	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor-Boy's Restroom, near 211	2	EA	7	6-10 years		
	Partitions	2nd Floor-Boy's Restroom, near 211	1	EA	7	6-10 years		
	Urinals	2nd Floor-Boy's Restroom, near 211	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor-Boy's Restroom, near 211	75	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor-Boy's Restroom, near 211	75	SF	7	10+ years		
	Water Closet	2nd Floor-Boy's Restroom, near 211	1	EA	7	6-10 years		
	Accessories	2nd Floor-Girl's Restroom, near 211	90	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor-Girl's Restroom, near 211	90	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor-Girl's Restroom, near 211	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Girl's Restroom, near 211	88	SF	6	10+ years		



Catego	ry : Room		В	Building : Main						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Girl's Restroom, near 211	2	SF	4	1-2 years	Missing tile			
	Floor Drain	2nd Floor-Girl's Restroom, near 211	1	EA	7	6-10 years				
	Lavatory	2nd Floor-Girl's Restroom, near 211	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	2nd Floor-Girl's Restroom, near 211	2	EA	7	10+ years				
	Partitions	2nd Floor-Girl's Restroom, near 211	3	EA	7	6-10 years				
	Walls - Plaster/Drywall	2nd Floor-Girl's Restroom, near 211	95	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Girl's Restroom, near 211	90	SF	7	10+ years				
	Water Closet	2nd Floor-Girl's Restroom, near 211	3	EA	7	6-10 years				
	Accessories	2nd Floor-Staff Restroom, near 211	115	SF	5	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor-Staff Restroom, near 211	115	SF	6	10+ years				
	Doors - Transom Window	2nd Floor-Staff Restroom, near 211	8	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor-Staff Restroom, near 211	1	ĒΑ	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Staff Restroom, near 211	115	SF	6	10+ years				
	Lavatory	2nd Floor-Staff Restroom, near 211	2	ĒΑ	6	6-10 years				
	Lighting - Pendent/Surface	2nd Floor-Staff Restroom, near 211	2	EA	6	6-10 years				
	Partitions	2nd Floor-Staff Restroom, near 211	2	ΕA	5	10+ years				
	Walls - Plaster/Drywall	2nd Floor-Staff Restroom, near 211	285	SF	6	10+ years				
	Water Closet	2nd Floor-Staff Restroom, near 211	2	ĒΑ	7	10+ years				
	Accessories	Basement-010 Office Restroom	45	SF	5	6-10 years				
	Ceiling - Exposed	Basement-010 Office Restroom	45	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Basement-010 Office Restroom	1	ĒΑ	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Basement-010 Office Restroom	45	SF	6	10+ years				
	Lavatory	Basement-010 Office Restroom	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Basement-010 Office Restroom	1	EΑ	6	6-10 years				
	Partitions	Basement-010 Office Restroom	1	EΑ	7	6-10 years				
	Walls - Plaster/Drywall	Basement-010 Office Restroom	80	SF	6	10+ years				
	Walls - Plaster/Drywall	Basement-010 Office Restroom	15	SF	5	1-2 years	Damaged wall			
	Water Closet	Basement-010 Office Restroom	1	EA	7	6-10 years	Damagoa wan			
	Accessories	Basement-Boiler Room Restroom	25	SF	5	6-10 years				
	Ceiling - Exposed	Basement-Boiler Room Restroom	25	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Basement-Boiler Room Restroom	1	EA	6	10+ years				
	Floor - Concrete	Basement-Boiler Room Restroom	25	SF	5	10+ years				
	Lighting - Wall Mounted	Basement-Boiler Room Restroom	1	EA	6	6-10 years				
	Walls - Masonry	Basement-Boiler Room Restroom	80	SF	5	6-10 years				
	Water Closet	Basement-Boiler Room Restroom	1	EA	6	10+ years				
	Accessories	Basement-Boy's Restroom, former	375	SF	5	6-10 years				
	Accessories	Girl's restroom, used as Storage	373	Oi	J	0-10 years				
		now								
	Ceiling - Plaster/Drywall	Basement-Boy's Restroom, former	375	SF	6	10+ years				
	Cenning - Flaster/Drywan	Girl's restroom, used as Storage	3/3	Ji	U	10+ years				
		now								
	Doors - Wood Doors inclu hw	Basement-Boy's Restroom, former	4	EA	6	10+ years				
	Poors - Mood Poors lingin LIM	Girl's restroom, used as Storage	4	EA	O	TOT years				
		now								
		TIOW								



Category : Room			В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Floor - Concrete Epoxy/ Painted	Basement-Boy's Restroom, former	375	SF	7	10+ years	Comments
	The control of the co	Girl's restroom, used as Storage	0.0	٥.	•	.o. you.o	
		now					
	Floor Drain	Basement-Boy's Restroom, former	2	EA	7	10+ years	
		Girl's restroom, used as Storage					
	Lighting - Pendent/Surface	now Basement-Boy's Restroom, former	8	EA	6	6-10 years	
	Lighting - Perident/Surface	Girl's restroom, used as Storage	0	EA	O	0-10 years	
		now					
	Walls - Concrete Block	Basement-Boy's Restroom, former	100	SF	6	6-10 years	
		Girl's restroom, used as Storage				•	
		now					
	Walls - Masonry	Basement-Boy's Restroom, former	760	SF	6	10+ years	
		Girl's restroom, used as Storage now					
	Accessories	Basement-Girl's Restroom, former	375	SF	5	6-10 years	
	7.0000001100	Boy's Toilet near Boiler Room	0,0	O.	J	o ro youro	
	Ceiling - Plaster/Drywall	Basement-Girl's Restroom, former	375	SF	6	10+ years	
	,	Boy's Toilet near Boiler Room				•	
	Doors - Wood Doors inclu hw	Basement-Girl's Restroom, former	2	EA	6	10+ years	
	Flaga Tila Osassia/ Baraslain	Boy's Toilet near Boiler Room	005	0.5	7	40	
	Floor - Tile Ceramic/ Porcelain	Basement-Girl's Restroom, former Boy's Toilet near Boiler Room	335	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Girl's Restroom, former	40	SF	4	0-1 year	Rippling within tile.
	Tiodi Tiio Coramio, Torodiam	Boy's Toilet near Boiler Room	10	O.	•	o i youi	rapping want die.
	Floor Drain	Basement-Girl's Restroom, former	2	EA	7	6-10 years	
		Boy's Toilet near Boiler Room					
	Lavatory	Basement-Girl's Restroom, former	3	EA	6	6-10 years	
	Lighting Developed Overface	Boy's Toilet near Boiler Room	0	_^	0	0.40	
	Lighting - Pendent/Surface	Basement-Girl's Restroom, former Boy's Toilet near Boiler Room	6	EA	6	6-10 years	
	Partitions	Basement-Girl's Restroom, former	12	EA	7	6-10 years	
	T dittions	Boy's Toilet near Boiler Room		_, \	•	o io youio	
	Walls - Structural Glazed Tile	Basement-Girl's Restroom, former	785	SF	7	10+ years	
		Boy's Toilet near Boiler Room					
	Walls - Structural Glazed Tile	Basement-Girl's Restroom, former	50	SF	4	1-2 years	Damaged wall
	Water Closet	Boy's Toilet near Boiler Room Basement-Girl's Restroom, former	40	_^	•	0.40	
	water closet	Basement-Girls Restroom, former Boy's Toilet near Boiler Room	12	EA	6	6-10 years	
	Accessories	Basement-Staff Restroom at Link	98	SF	7	6-10 years	Closed Under Construction
	, 10000001100	between buildings- Closed Under		٠.	•	0 .0 ,00.0	
		Construction					
	Ceiling - Plaster/Drywall	Basement-Staff Restroom at Link	98	SF	7	10+ years	
		between buildings- Closed Under					



Category : Room				uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
O. Gup	nom Type	Construction	Quantity	00	rtariit	rtopiacomoni	Commonic
	Doors - Wood Doors inclu hw	Basement-Staff Restroom at Link	1	EA	7	10+ years	
		between buildings- Closed Under				•	
		Construction					
	Floor - Tile Ceramic/ Porcelain	Basement-Staff Restroom at Link	98	SF	7	10+ years	
		between buildings- Closed Under					
		Construction			_		
	Floor Drain	Basement-Staff Restroom at Link	1	EA	7	6-10 years	
		between buildings- Closed Under					
	Lauratami	Construction	4	_^	7	10	
	Lavatory	Basement-Staff Restroom at Link	1	EA	7	10+ years	
		between buildings- Closed Under Construction					
	Lighting - Pendent/Surface	Basement-Staff Restroom at Link	1	EA	7	10+ years	
	Lighting Tondon Canado	between buildings- Closed Under	·	_, 、	•	ioi youlo	
		Construction					
	Partitions	Basement-Staff Restroom at Link	1	EA	7	6-10 years	
		between buildings- Closed Under				·	
		Construction					
	Showers	Basement-Staff Restroom at Link	1	EA	7	6-10 years	
		between buildings- Closed Under					
		Construction			_		
	Walls - Plaster/Drywall	Basement-Staff Restroom at Link	244	SF	7	10+ years	
		between buildings- Closed Under Construction					
	Water Closet	Basement-Staff Restroom at Link	1	EA	7	10 L VOORO	
	Water Closet	between buildings- Closed Under	ı	EA	1	10+ years	
		Construction					
		Contraction					

Building: Main Category: Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #014 (Art Room)						
	AC Units	Basement	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	980	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Epoxy/ Painted	Basement	980	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	16	EA	6	6-10 years	
	Storage/ Closet	Basement	12	SF	5	10+ years	
	Walls - Masonry	Basement	1,600	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,060	SF	6	10+ years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,060	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EΑ	7	6-10 years	
	Marker Board	1st Floor	26	LF	6	6-10 years	
	Storage/ Closet	1st Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,500	SF	6	10+ years	
Classroc	om #111 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	22	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,040	SF	6	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,040	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1,040	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6		
		1st Floor	170	SF	7	6-10 years	
	Storage/ Closet			SF SF		10+ years	
	Walls - Plaster/Drywall	1st Floor	2,472	SF	6	10+ years	
Classroc	om #112 (Other Instructional Use)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	380	SF	6	10+ years	
	Doors - Side-lite	1st Floor	54	SF	6	10+ years	
	Doors - Transom Window	1st Floor	2	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	380	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	394	SF	6	10+ years	
Classroc	om #114 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,066	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	

Page : 13 of 44 Campus Name: Hedges Assessment Date: 11/09/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	1,066	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	176	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,500	SF	6	10+ years	
Classroo	m #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,110	SF	6	10+ years	
	Doors - Transom Window	1st Floor	, 9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	1,110	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	50	LF	6	6-10 years	
	Storage/ Closet	1st Floor	162	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,490	SF	6	10+ years	
Classroc	m #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,060	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,060	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	6	6-10 years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,500	SF	6	10+ years	
Classroc	m #211 (Regular Classroom)						
Classiuu	AC Units	2nd Floor	1	EA	7	6-10 years	
		2nd Floor 2nd Floor	4	LF	<i>7</i> 6		
	Casework			SF	_	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,040	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,040	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	6	6-10 years	
	Marker Board	2nd Floor	42	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,472	SF	6	10+ years	

Page : 14 of 44 Campus Name: Hedges Assessment Date: 11/09/2023



Catego	ry : Classroom		В	uilding	: Main		. ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #212 (Special Education)						
Classion	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	675	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years 10+ years	
	Floor - Tile	2nd Floor	675	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	_	LF	6	6-10 years	
		2nd Floor 2nd Floor	16	SF			
	Walls - Plaster/Drywall		1,090		6	10+ years	
	Work Sink	2nd Floor	1	EA	5	6-10 years	
Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1.060	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	18	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	1,060	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EΑ	6	6-10 years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,500	SF	6	10+ years	
Classroo	om #215 (Regular Classroom)	0.151				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,110	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	6	6-10 years	
	Marker Board	2nd Floor	25	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,490	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
						•	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,060	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,060	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	17	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,500	SF	6	10+ years	
Classroo	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,040	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,040	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	17,040	EA	6	6-10 years	
	Marker Board	3rd Floor	42	LF	6	6-10 years	
	Storage/ Closet			SF	_	•	
	Walls - Plaster/Drywall	3rd Floor 3rd Floor	187 247	SF	7 6	10+ years 10+ years	
Classes	are #242 (Cooriel Education)						
Classio	om #312 (Special Education)	0.15				0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	665	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Damaged.
	Chalk Board	3rd Floor	26	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	42	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	675	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,090	SF	6	6-10 years	
Classroo	om #314 (Play Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,064	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	18	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	2 55.6 Trood 25576 Mold IIV	3.4	· ·	_, `	J	.o. youro	

Page : 16 of 44 Campus Name: Hedges Assessment Date: 11/09/2023



Catego	ry : Classroom		В	uilding	: Main		o whichester Avervoe, officago, ie oooos
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	1,064	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	17	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	36	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	174	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,500	SF	6	10+ years	
			,,,,,,		-	, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #315 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,100	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	1,100	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	17	EA	6	6-10 years	
	Marker Board	3rd Floor	35	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	208	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,490	SF	6	10+ years	
	Wallo Tidotoli/Diywall	014 1 1001	2, 100	O.	Ü	101 youro	
Catego	ry : Interior		В	uilding	: Main		
0	Hann Toma	Location	Overetite	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Corridor		Ast Elsan	0.040	0.5		40	
	Ceiling - Plaster/Drywall	1st Floor	2,312	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,312	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Stairs - Concrete Stairs	1st Floor	6	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,500	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,312	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,312	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,500	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,130	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,130	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	17	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,227	SF	6	10+ years	
	Ceiling - Exposed	Basement	958	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	2,200	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	42	SF	6	10+ years	
				٥.	ū	,	



Catego	ry : Interior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	Basement	54	SF	6	10+ years	
	Doors - Transom Window	Basement	108	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	12	EA	6	10+ years	
	Floor - Asphalt Floor	Basement	3,050	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	150	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	51	EA	6	6-10 years	
	Stairs - Concrete Stairs	Basement	25	LF	6	10+ years	
	Walls - Masonry	Basement	30	SF	6	10+ years	
	Walls - Masonry	Basement	2,024	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	3,068	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	160	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	1,500	SF	6	10+ years	
Safety							
•	Security Cameras	1st Floor	1	EA	5	6-10 years	
	•					•	
Stairs							
	Ceiling - Plaster/Drywall	Central Stair, at Door #4	390	SF	6	10+ years	
	Floor - Asphalt	Central Stair, at Door #4	165	SF	6	10+ years	
	Handrails	Central Stair, at Door #4	114	LF	5	2-5 years	
	Lighting - Pendent/Surface	Central Stair, at Door #4	6	EA	6	6-10 years	
	Stairs - Asphalt	Central Stair, at Door #4	36	LF	6	10+ years	
	Walls - Plaster/Drywall	Central Stair, at Door #4	420	SF	6	10+ years	
	Ceiling - Plaster/Drywall	N Stair, across from 311	645	SF	6	6-10 years	
	Floor - Asphalt	N Stair, across from 311	440	SF	6	10+ years	
	Handrails	N Stair, across from 311	164	LF	5	2-5 years	
	Lighting - Pendent/Surface	N Stair, across from 311	11	EA	6	6-10 years	
	Stairs - Asphalt	N Stair, across from 311	75	LF	6	10+ years	
	Walls - Plaster/Drywall	N Stair, across from 311	1,336	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S Stair, across from 315	645	SF	6	10+ years	
	Floor - Asphalt	S Stair, across from 315	440	SF	6	10+ years	
	Handrails	S Stair, across from 315	164	LF	5	2-5 years	
	Lighting - Pendent/Surface	S Stair, across from 315	11	EA	6	6-10 years	
	Stairs - Asphalt	S Stair, across from 315	75	LF	6	10+ years	
	Walls - Plaster/Drywall	S Stair, across from 315	1,336	SF	6	10+ years	





Category : Exterior **Building: Addition**

ategory . Exterior		В	unung	. Additi	Recommend	
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance	Location	Quantity	COM	Main	Ropidocilicit	Comments
Entrance Control - Audio and Video	#1 W	1	EA	6	10+ years	
Exterior Doors - Exterior AMP Door	#1 W	2	EA	6	10+ years	
Exterior Doors - Side lite	#1 W	6	EA	6	10+ years	
Exterior Doors - Side lite Exterior Doors - Transom Lite	#1 W	3	EA	6	10+ years	
Exterior Doors - Exterior Steel Door	#1 vv #1.1 N ("2")	1	EA	6	10+ years	
Exterior Stairs - Concrete	#1.1 N (2) #1.1 N ("2")	3	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#11 N	3 1	EA	6	10+ years	
Exterior Stairs - Concrete	#11 N #11 N	3	LF	6	10+ years	
	#11 N #11 N		LF	6		
Ramps - Steel or Aluminum Exterior Doors - Exterior Steel Door	#11 N #11.1 N	6	EA	6	10+ years	
Exterior Stairs - Concrete	#11.1 N #11.1 N	2	LF	6	10+ years	
		0			10+ years	
Exterior Doors - Exterior Steel Door	#11.2 N	1	EA	6	10+ years	
Exterior Stairs - Concrete	#11.2 N	3	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#12 W	1	EA	6	10+ years	
Exterior Stairs - Concrete	#12 W	10	LF	6	10+ years	N
Ramps - Concrete	#12 W	20	LF	7	10+ years	New
Exterior Doors - Exterior Steel Door	#13 W	1	EA	6	10+ years	
Ramps - Concrete	#13 W	20	LF	7	10+ years	New
Exterior Doors - Exterior Steel Door	#14 W	1	EA	6	10+ years	
Exterior Stairs - Concrete	#14 W	10	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#15 W	2	EA	6	10+ years	
Exterior Stairs - Concrete	#15 W	10	LF	6	10+ years	
Ramp Handrail - Steel_Ramp Handr		32	LF	7	10+ years	New
Ramps - Concrete	#15 W	16	LF	7	10+ years	New
Exterior Doors - Exterior Steel Door	#16 S	1	EA	6	10+ years	
Exterior Stairs - Concrete	#16 S	3	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	#17 S	1	EA	6	10+ years	
Exterior Stairs - Concrete	#17 S	3	LF	6	10+ years	
Entrance Control - Audio and Video	#2 W - moved from Main	1	EA	6	10+ years	
Exterior Doors - Exterior AMP Door	#2 W - moved from Main	4	EA	6	10+ years	
Exterior Doors - Side lite	#2 W - moved from Main	3	EA	6	10+ years	
Exterior Doors - Transom Lite	#2 W - moved from Main	2	EΑ	6	10+ years	
Exterior Doors - Exterior Steel Door	Roof	1	EΑ	7	10+ years	
					•	
ındation						
Foundation - Concrete	Entire Building	570	LF	7	10+ years	
Superstructure - Concrete	Entire Building	51,015	SF	7	10+ years	Corrected material
ghting						
Exterior Lighting - Parapet or Roof M	lounted Entire Building	8	EA	6	10+ years	



Category : Exterior			Building : Addition						
				11614	ъ.	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Roof Sys									
	Chimney - Metal Flue	Roof #1	4	LF	7	10+ years			
	Coping - Metal	Roof #1	520	LF	7	10+ years			
	Downspouts - Interior Downspouts	Roof #1	342	LF	7	10+ years			
	Parapet - 16" - 30" Height	Roof #1	375	LF	7	10+ years			
	Parapet - Parapet > 30"	Roof #1	145	LF	7	10+ years			
	Roof - Modified Bitumen	Roof #1	16,493	SF	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Roof #1	16,493	SF	7	10+ years			
	Concrete Topping				_				
	Access Ladder - Metal	Roof #2	1	EA	7	10+ years			
	Coping - Metal	Roof #2	212	LF	7	10+ years			
	Downspouts - Exterior Downspouts	Roof #2	22	LF	7	10+ years			
	Parapet - Parapet < 16" Height	Roof #2	212	LF	7	10+ years			
	Roof - Modified Bitumen	Roof #2	2,389	SF	7	10+ years			
	Roof Hatch - Metal	Roof #2	1	EA	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Roof #2	2,389	SF	7	10+ years			
	Concrete Topping				_				
	Coping - Metal	Roof 3 - moved from main	20	LF	7	10+ years			
	Downspouts - Exterior Downspouts	Roof 3 - moved from main	30	LF	7	10+ years			
	Roof - Metal	Roof 3 - moved from main	540	SF	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Roof 3 - moved from main	540	SF	7	10+ years			
	Concrete Topping				_				
	Coping - Metal	Roof 4	10	LF	7	10+ years			
	Downspouts - Exterior Downspouts	Roof 4	10	LF	6	10+ years			
	Parapet - Parapet < 16" Height	Roof 4	10	LF	7	10+ years			
	Roof - Modified Bitumen	Roof 4	110	SF	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Roof 4	110	SF	7	10+ years			
	Concrete Topping								
Walls									
	Canopy - Metal	Entire Building	86	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	19,700	SF	6	10+ years			
	Exterior Walls - Concrete Block	Entire Building	5,425	SF	6	10+ years			
		G				,			
Windows									
	Guard - Guards perforated	Entire Building	1,200	SF	6	10+ years			
	Lintels - Steel	Entire Building	580	LF	7	10+ years			
	Windows - Decorative	Entire Building	345	SF	6	10+ years			
	Windows - Louver	Entire Building	500	SF	7	10+ years	Not previously assessed		
	Windows - Sash Aluminum Double-pane	Entire Building	3,320	SF	6	10+ years	•		
Catego	ry : Electrical		В	uildina	: Additi	on			
	Item - Type	Location	Quantity	UOM		Recommend	Comments		
Jioup	1.5	20041011	Quantity	00.4	Italik		Commonto		



					Replacement	
rgency System						
Automatic Transfer Switch	Entire Building	1	EA	6	6-10 years	Serves the fire pump and sprinkler system.
Automatic Transfer Switch	Entire Building	1	EA	6	6-10 years	Serves EM circuits in Addition.
Emergency A/C Power - Corridors and	Entire Building	7.476	SF	6	6-10 years	
Stairs	_	, -			-	
Emergency A/C Power - Gym	Entire Building	4,205	SF	6	6-10 years	
Emergency A/C Power - Lunchrooms	Entire Building	2,074	SF	6	6-10 years	
Emergency Battery Packs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	
Emergency Battery Packs - Gym	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep adjusted as the emergency battery pack is damaged.
Exit Signs - Corridors and Stairs	Entire Building	24	EA	2	0-1 year	Exit Signs are not equipped with backup batteries and the building does not have an emergency generator.
Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	Exit Signs are not equipped with backup batteries and the building does not have an emergency generator.
Exit Signs - Lunchroom	Entire Building	3	EA	2	0-1 year	Exit Signs are not equipped with backup batteries and the building does not have an emergency generator.
Security System - CCTV	Entire Building	51,015	SF	6	6-10 years	
Security System - Intrusion Detection	Entire Building	51,015	SF	6	6-10 years	
Service						
Main Electrical Service - 1200 A 277/480/3PH	Electrical Room	1	EA	6	10+ years	
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	Location EM
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	Fire
PA System	Entire Building	51,015	SF	6	6-10 years	Serves Addition and Main.
er Distribution						
Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as open fuse receptacle expose live conductors presenting live front condition.
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	10+ years	Quantity changed to match curren observations.

Campus Name: Hedges Page : 21 of 44 Assessment Date: 11/09/2023



XXII S	chools					4747	S Winchester AVENUE, Chicago, IL 60609
						Replacement	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as the panel is missing part of its enclosure which exposes live conductors and presents a live front
							condition.
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	
Categoi	ry : Fire Protection		В	uilding	: Additio	on	
	Name Toma	Lasatian	0	LIOM	Danila	Recommend	0
Group Fire Aları	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ne Alaff	m Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Annunciator
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves Addition.
	Fire Alarm Strobe Lights	Entire Building	51,015	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	51,015	SF	4	2-5 years	System is functional and passes inspection but Rank, Reason and Priority Rep adjusted based on current observations and the age of
							the equipment; system is 26 years old, employs antiquated technology, and has exceeded its EUL.
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
Pump Ro	oom Assembly						
	Fire Pump - Less than 25hp	Fire Pump Room	1	EA	6	6-10 years	No CPS Asset Tag present.
	Jockey Pump	Fire Pump Room	1	EA	6	6-10 years	No CPS Asset Tag present.
Sprinkler	System						
	Sprinkler Heads	Entire Building	51,015	SF	7	10+ years	
	Sprinkler Piping	Entire Building	51,015	SF SF	6	10+ years	
	Wet Sprinkler System	Entire Building	51,015	SF	6	10+ years	
Categoi	ry : Mechanical		В	uilding	: Addition	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond			•			•	
	Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Roof Mounted - Greater than 200 tons	Entire Building Entire Building	1	EA EA	6 5	6-10 years 2-5 years	ACC-1. Rank, Reason and Priority Rep changed based on current observations and on the age of the equipment; unit is operational but

Campus Name: Hedges Page : 22 of 44 Assessment Date: 11/09/2023



Catego	ry : Mechanical		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
							shows signs of age-related deterioration and hail damage, and in has reached its EUL.		
	Glycol Feed	Entire Building	1	EA	6	6-10 years			
	Pipes - Chilled Water Pipe- Steel	Entire Building	200	LF	6	10+ years			
	Pressure Fill System	Entire Building	1	EA	6	6-10 years			
Air Hand	lling Systems								
	Air Handling Unit- Package Multi Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Penthouse	1	EA	6	6-10 years			
	Air Intake	Penthouse	1	EA	6	6-10 years			
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Penthouse	1	EA	6	6-10 years	AHU-1		
	Air Intake	Penthouse	1	EA	6	6-10 years			
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Penthouse	1	EA	6	6-10 years	AHU-2, serves kitchen, lunchroom and associated spaces.		
	Air Intake	Penthouse	1	EA	6	6-10 years			
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Penthouse	3	EA	6	6-10 years	RF-1 RF-2 RF-3		
Boiler S	vstems								
Í	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Boiler Room	2	EA	6	6-10 years			
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years			
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years			
	Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	6-10 years	B-1 and B-2		
	Water Fill System	Boiler Room	1	EA	5	6-10 years			
Heating	Devices								
	Cabinet Heaters - With Hot Water Coil	1st Floor	5	EA	6	6-10 years	Quantity changed to match current observations.		
	Unit Heater - Hot Water	Entire Building	5	EA	6	6-10 years			
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years			
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years			
	Fin Tube - Hot Water	Entire Building	426	LF	6	6-10 years			
Mechani	cal Plumbing								
	Dual Temperature Pump - Less than 10	Boiler Room	1	EA	6	6-10 years			

Campus Name: Hedges Page : 23 of 44 Assessment Date: 11/09/2023



Catego	ry : Mechanical		В	uilding	: Additi		O WINGHESTER AVENUE, Officago, 12 00005
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Dual Temperature Pump - Less than 10	Boiler Room	1	EΑ	6	6-10 years	
	Hot Water Pump - Less than 10	Entire Building	1	EΑ	6	6-10 years	
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Entire Building	1	EΑ	6	6-10 years	
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	500	LF	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	6-10 years	
	Chilled Water Pump - Less than 10	Penthouse	1	EA	6	6-10 years	
	Chilled Water Pump - Less than 10	Penthouse	1	EA	6	6-10 years	
Tempera	ature Control						
	Electric Thermostat	Entire Building	3	EA	6	6-10 years	
	Electric Thermostat	Entire Building	5	EA	6	6-10 years	Quantity changed to match current
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	observations.
	Pneumatic System	Entire Building	51,015	SF	5	1-2 years	Addition uses the original, 1997-
	Friedinatic System	·	31,013	Si		1-2 years	installation pneumatic temperature control system. Leaks are present throughout most of the system with many manual adjustments required for appropriate temperature control.
	Thermostats - Pneumatic	Entire Building	14	EA	5	1-2 years	Quantity changed as total has been divided/aggregated. Location changed for clarification. Reason and Priority Rep changed as thermostats throughout the building are variably subject to leakage and age-related degradation with many manual adjustments required for appropriate temperature control.
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	28	EA	5	6-10 years	All of the 26-year-old unit ventilators in the building require frequent repairs and are well maintained with regular maintenance. Quantity changed as total has been divided/aggregated.
_Ventilation	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	

Page : 24 of 44 Campus Name: Hedges Assessment Date: 11/09/2023



Category : Mechanical Building : Addition							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	CFM Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	4	EA	6	6-10 years	
	CFM Type I Exhaust Hood- Kitchen	Entire Building	2	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additi		
			0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate		D. 11. D.					
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	4	2-5 years	Unit is leak-free and fully operational but is 25-plus years old and has exceeded its EUL.
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	1	EA	6	10+ years	
Piping							
_т ріпд	Domestic Piping-Hot Water Return Lines	Entire Building	51,015	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	51,015	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	51,015	SF	6	6-10 years	
	Fixtures	ű	,			,	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	51,015	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	51,015	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	51,015	SF	6	6-10 years	
	Sanitary Piping	Entire Building	51,015	SF	6	6-10 years	
	Storm Piping	Entire Building	51,015	SF	6	6-10 years	
	Vent Piping	Entire Building	51,015	SF	6	6-10 years	
D							
Pumps	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Entire Building	1	EΑ	6	6-10 years	
	Pumps - Sump-Duplex	Entire Building	1	EΑ	6	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	ΕA	6	6-10 years	No CPS Asset Tag present. Location
							changed for clarification.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Location changed for clarification. Located at the bottom of the elevator pit and inaccessible at the time of assessment. No CPS Asset Tag available. Condition verified by the Building Engineer.

Page : 25 of 44 Campus Name: Hedges Assessment Date: 11/09/2023



Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices					-	
	Ceiling - Lay-in	1st Kitchen Office	70	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Kitchen Office	1	EA	6	10+ years	
	Floor - Tile	1st Kitchen Office	70	SF	6	10+ years	
	Lighting - Lay-in	1st Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	1st Kitchen Office	6	EA	7	10+ years	
	Walls - Concrete Block	1st Kitchen Office	150	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-Faculty Center	712	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Faculty Center	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Faculty Center	712	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Faculty Center	9	EA	7	6-10 years	
	Power Distribution	1st Floor-Faculty Center	18	EA	7	6-10 years	
	Storage/ Closet	1st Floor-Faculty Center	14	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-Faculty Center	965	SF	6	10+ years	
	Work Sink	1st Floor-Faculty Center	903	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Main Office	734	SF	6	•	
	Doors - Side-lite	1st Floor-Main Office	48	SF	6	10+ years 10+ years	
	Doors - Steel Doors incl hw	1st Floor-Main Office	40	Sr EA	6	10+ years 10+ years	
	Floor - Tile	1st Floor-Main Office	734	SF	6	10+ years	
		1st Floor-Main Office		EA			
	Lighting - Lay-in Power Distribution	1st Floor-Main Office	9 18	EA	6 6	6-10 years	
			22	SF	7	10+ years	
	Storage/ Closet	1st Floor Main Office		SF SF		10+ years	
	Walls - Concrete Block	1st Floor-Main Office	930		6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Main Office	670	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-Vault	175	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor-Vault	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Vault	175	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Vault	3	EΑ	6	6-10 years	
	Power Distribution	1st Floor-Vault	8	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Vault	425	SF	6	10+ years	
	Work SInk	1st Floor-Vault	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor-Gym Office	130	SF	6	10+ years	
	Doors - Side-lite	2nd Floor-Gym Office	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Gym Office	1	EA	6	10+ years	
	Floor - Tile	2nd Floor-Gym Office	130	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor-Gym Office	2	EA	6	6-10 years	
	Power Distribution	2nd Floor-Gym Office	6	EA	6	10+ years	
	Storage/ Closet	2nd Floor-Gym Office	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor-Gym Office	235	SF	6	10+ years	
	Ceiling - Lay-in	301 Office	88	SF	6	10+ years	5 12 42 4
	Ceiling - Lay-in	301 Office	8	SF	4	1-2 years	Bending tile from duct
	Doors - Side-lite	301 Office	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	301 Office	1	EA	6	10+ years	
	Floor - Tile	301 Office	96	SF	6	10+ years	

Page : 26 of 44 Campus Name: Hedges Assessment Date: 11/09/2023



Catego	ry : Room		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	301 Office	2	EA	7	6-10 years	
	Power Distribution	301 Office	4	EA	7	10+ years	
	Walls - Concrete Block	301 Office	170	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor - Social worker	190	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Social worker	1	EA	6	10+ years	
	Floor - Tile	3rd Floor - Social worker	190	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor - Social worker	3	EA	7	6-10 years	
	Power Distribution	3rd Floor - Social worker	8	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor - Social worker	325	SF	6	10+ years	
	Ceiling - Lay-in	Assistant Principal Office	172	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal Office	1	EA	6	10+ years	
	Floor - Tile	Assistant Principal Office	172	SF	6	10+ years	
	Lighting - Lay-in	Assistant Principal Office	4	EA	6	6-10 years	
	Power Distribution	Assistant Principal Office	6	EA	6	10+ years	
	Walls - Concrete Block	Assistant Principal Office	238	SF	6	10+ years	
	Walls - Plaster/Drywall	Assistant Principal Office	238	SF	6	10+ years	
	Ceiling - Lay-in	Conference room in main office	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Conference room in main office	1	EA	7	10+ years	
	Floor - Tile	Conference room in main office	150	SF	7	10+ years	
	Lighting - Lay-in	Conference room in main office	4	EA	7	10+ years	
	Power Distribution	Conference room in main office	4	EA	7	10+ years	
	Walls - Concrete Block	Conference room in main office	80	SF	7	10+ years	
	Walls - Plaster/Drywall	Conference room in main office	160	SF	7	10+ years	
	Ceiling - Lay-in	Counselors Office	165	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselors Office	2	EA	6	10+ years	
	Floor - Tile	Counselors Office	165	SF	6	10+ years	
	Lighting - Lay-in	Counselors Office	4	EA	7	6-10 years	
	Power Distribution	Counselors Office	8	EA	7	10+ years	
	Walls - Concrete Block	Counselors Office	105	SF	6	10+ years	
	Walls - Plaster/Drywall	Counselors Office	365	SF	6	10+ years	
	Ceiling - Lay-in	Engineer's Office- Basement	148	SF	6	10+ years	
	Doors - Steel Doors incl hw	Engineer's Office- Basement	2	EA	6	10+ years	
	Floor - Tile	Engineer's Office- Basement	148	SF	6	10+ years	
	Lighting - Lay-in	Engineer's Office- Basement	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office- Basement	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office- Basement	8	EA	7	10+ years	
	Storage/ Closet	Engineer's Office- Basement	20	SF	7	10+ years	
	Walls - Concrete Block	Engineer's Office- Basement	256	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office- Basement	90	SF	6	10+ years	
	Ceiling - Lay-in	Nurse office in main office	165	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Nurse office in main office	2	EA	6	10+ years	
	Floor - Tile	Nurse office in main office	165	SF	6	10+ years	
	Lighting - Lay-in	Nurse office in main office	2	EA	7	6-10 years	
	Power Distribution	Nurse office in main office	8	EA	6	10+ years	
						,	

Campus Name: Hedges Page : 27 of 44 Assessment Date: 11/09/2023



Category : Room		Building : Addition					
						Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Nurse office in main office	240	SF	6	10+ years	
	Walls - Plaster/Drywall	Nurse office in main office	240	SF	6	10+ years	
	Work SInk	Nurse office in main office	1	EA	7	10+ years	
	Ceiling - Lay-in	Principal's Office	360	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	6	10+ years	
	Floor - Tile	Principal's Office	360	SF	6	10+ years	
	Lighting - Lay-in	Principal's Office	8	EΑ	6	6-10 years	
	Power Distribution	Principal's Office	14	EA	6	10+ years	
	Walls - Concrete Block	Principal's Office	245	SF	6	10+ years	
	Walls - Plaster/Drywall	Principal's Office	485	SF	6	10+ years	
	Ceiling - Lay-in	Work Room in library 306	230	SF	7	10+ years	
	Doors - Side-lite	Work Room in library 306	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Work Room in library 306	1	ĒA	6	10+ years	
	Floor - Tile	Work Room in library 306	230	SF	6	10+ years	
	Lighting - Lay-in	Work Room in library 306	4	EA	7	6-10 years	
	Power Distribution	Work Room in library 306	8	ĒΑ	7	10+ years	
	Walls - Concrete Block	Work Room in library 306	450	SF	6	10+ years	
	Work Sink	Work Room in library 306	1	EA	7	6-10 years	
	Went Chin	Work Recomminatory coo	•	_, ,	•	o io youro	
/mnas							
	Bleacher Seating	2nd Floor	200	EA	6	10+ years	
	Ceiling - Exposed	2nd Floor	4,205	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	10+ years	
	Floor - Tile	2nd Floor	4,205	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	5	1-2 years	Not working
	Lighting - Wall Mounted	2nd Floor	10	EA	7	6-10 years	-
	Scoreboards	2nd Floor	1	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	64	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	5,005	SF	6	10+ years	
tchen							
	Ceiling - Lay-in	1st Floor	962	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Epoxy/ Painted	1st Floor	932	SF	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	30	SF	4	1-2 years	Cracked and damaged flooring
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	5 8
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,214	SF	6	10+ years	
orarv							
y	Ceiling - Lay-in	3rd Floor - 306 Library	1,246	SF	7	10+ years	
	Doors - Side-lite	3rd Floor - 306 Library	12	SF	6	10+ years	



Catego	Category : Room			Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	3rd Floor - 306 Library	2	EΑ	6	10+ years		
	Floor - Tile	3rd Floor - 306 Library	1,246	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor - 306 Library	32	EA	7	6-10 years		
	Walls - Concrete Block	3rd Floor - 306 Library	2,075	SF	6	10+ years		
Locker/S	Shower Room							
	Accessories	Basement	50	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement	50	SF	6	10+ years		
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years		
	Floor - Terrazzo	Basement	25	SF	6	10+ years		
	Floor - Tile/Sheet	Basement	25	SF	7	10+ years		
	Floor Drain	Basement	1	ĒΑ	7	6-10 years		
	Lighting - Pendent/Surface	Basement	1	EA	7	6-10 years		
	Showers	Basement	1	EΑ	7	6-10 years		
	Walls - Concrete Block	Basement	55	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	Basement	50	SF	6	10+ years		
Lunch &	Multipurpose Room							
	Ceiling - Lay-in	1st Floor - Student Dining	2,074	SF	6	10+ years		
	Doors - Side-lite	1st Floor - Student Dining	12	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Student Dining	2	EA	6	10+ years		
	Floor - Tile	1st Floor - Student Dining	2,074	SF	6	10+ years		
	Lighting - Lay-in	1st Floor - Student Dining	24	EA	7	6-10 years		
	Lighting - Lay-in	1st Floor - Student Dining	2	EΑ	5	1-2 years	Not working	
	Serving Line	1st Floor - Student Dining	30	LF	6	10+ years	140t Working	
	Walls - Concrete Block	1st Floor - Student Dining	1,846	SF	6	10+ years		
MDF ID	F							
_	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Finishes	2nd Floor	160	SF	5	10+ years	Ceiling tiles have stains	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	g mad name daming	
Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	22	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	28	SF	7	10+ years		
	Storage Room	1st Floor	14	SF	7	10+ years		
	Janitor's Closet	2nd Floor	22	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	10	SF	7	10+ years		
	Janitor's Closet	3rd Floor	22	SF	7	10+ years		
	Mechanical/ Service Rooms	3rd Floor	10	SF	7	10+ years		
	Storage Room	3rd Floor	20	SF	5	2-5 years	Missing ceiling tiles	
	Mechanical/ Service Rooms	4th Floor	1,678	SF	7	10+ years		
	Storage Room	4th Floor	64	SF	7	10+ years		

Campus Name: Hedges Page : 29 of 44 Assessment Date: 11/09/2023



ategory : Room			В	uilding	: Additi	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Room	Basement	545	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	88	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,180	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	230	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	375	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	320	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	150	SF	7	10+ years	
	Storage Room	Basement	55	SF	7	10+ years	
	Storage Room	Dasement	33	OI .	,	10+ years	
estroor	n						
	Accessories	100/101	48	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	100/101	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	100/101	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	100/101	48	SF	6	10+ years	
	Floor Drain	100/101	1	ĒΑ	7	6-10 years	
	Lavatory	100/101	1	ΕA	6	6-10 years	
	Lighting - Wall Mounted	100/101	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	100/101	94	SF	6	10+ years	
	Water Closet	100/101	1	EA	6	6-10 years	
			· · · · · · · · · · · · · · · · · · ·				
	Accessories	103/105	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103/105	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103/105	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	103/105	36	SF	6	10+ years	
	Floor Drain	103/105	1	EA	7	6-10 years	
	Lavatory	103/105	1	EA	6	6-10 years	
	Lighting - Wall Mounted	103/105	1	EA	6	6-10 years	
	Walls - Concrete Block	103/105	90	SF	6	10+ years	
	Water Closet	103/105	1	EA	6	6-10 years	
	Accessories	1st Floor-Staff Restroom, across	50	SF	7	6-10 years	
		from 105				,	
	Ceiling - Plaster/Drywall	1st Floor-Staff Restroom, across	50	SF	6	10+ years	
		from 105		٥.	·	. c . youro	
	Doors - Wood Doors inclu hw	1st Floor-Staff Restroom, across	1	EA	6	10+ years	
	Doors - Wood Doors Incid IIW	from 105		LA	U	10+ years	
	Floor - Tile		50	SF	e	10	
	Floor - Tile	1st Floor-Staff Restroom, across	50	SF	6	10+ years	
	Elean Danie	from 105	4	^	7	0.40	
	Floor Drain	1st Floor-Staff Restroom, across	1	EA	7	6-10 years	
		from 105					
	Lavatory	1st Floor-Staff Restroom, across	1	EA	6	6-10 years	
		from 105					
	Lighting - Wall Mounted	1st Floor-Staff Restroom, across	1	EA	7	6-10 years	
	-	from 105				-	
	Walls - Concrete Block	1st Floor-Staff Restroom, across	48	SF	6	10+ years	
		from 105	.0	٠.	•	, , , , , , , , , , , , , , , , , , , ,	



Catego	ry : Room		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor-Staff Restroom, across	80	SF	6	10+ years	
		from 105					
	Water Closet	1st Floor-Staff Restroom, across	1	EA	6	6-10 years	
		from 105				•	
	Accessories	Boys 1st Floor	188	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys 1st Floor	188	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys 1st Floor	188	SF	6	10+ years	
	Floor Drain	Boys 1st Floor	1	ĒΑ	7	6-10 years	
	Lavatory	Boys 1st Floor	2	EA	6	6-10 years	
	Lighting - Lay-in	Boys 1st Floor	3	EA	6	10+ years	
	Partitions	Boys 1st Floor	2	EA	7	6-10 years	
	Urinals	Boys 1st Floor	2	EΑ	6	6-10 years	
	Walls - Concrete Block	Boys 1st Floor	415	SF	6	10+ years	
	Water Closet	Boys 1st Floor	2	EA	6	6-10 years	
	Accessories	Boys 2nd Floor	188	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys 2nd Floor	188	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys 2nd Floor	188	SF	6	10+ years	
	Floor Drain	Boys 2nd Floor	1	EA	7	6-10 years	
	Lavatory	Boys 2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Boys 2nd Floor	3	EA	7	6-10 years	
	Partitions	Boys 2nd Floor	2	EA	5	1-2 years	Paint partitions
	Urinals	Boys 2nd Floor	2	EA	6	6-10 years	r aint partitions
	Walls - Concrete Block	Boys 2nd Floor	415	SF	6	10+ years	
	Water Closet	Boys 2nd Floor	2	EA	6	6-10 years	
	Accessories	Boys 3rd Floor	188	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys 3rd Floor	188	SF	6	•	
	Floor - Tile Ceramic/ Porcelain	Boys 3rd Floor	188	SF	6	10+ years	
				EA		10+ years	
	Floor Drain	Boys 3rd Floor	1	EA EA	7 6	6-10 years	
	Lavatory	Boys 3rd Floor	2			6-10 years	
	Lighting - Lay-in Partitions	Boys 3rd Floor	3 2	EA EA	6 5	6-10 years	Daint partitions
		Boys 3rd Floor				1-2 years	Paint partitions
	Urinals	Boys 3rd Floor	2	EA	6	6-10 years	
	Walls - Concrete Block	Boys 3rd Floor	415	SF	6	10+ years	
	Water Closet	Boys 3rd Floor	2	EA	6	6-10 years	
	Accessories	Girls 1st Floor	188	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls 1st Floor	188	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls 1st Floor	188	SF	6	10+ years	
	Floor Drain	Girls 1st Floor	1	EΑ	7	6-10 years	
	Lavatory	Girls 1st Floor	2	EΑ	6	6-10 years	
	Lighting - Lay-in	Girls 1st Floor	3	EΑ	7	10+ years	
	Partitions	Girls 1st Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	Girls 1st Floor	415	SF	6	10+ years	
	Water Closet	Girls 1st Floor	4	EA	6	6-10 years	
	Accessories	Girls 2nd Floor	188	SF	7	6-10 years	



Catego	ry : Room		В	uilding	: Additi	on	· •
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Girls 2nd Floor	188	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls 2nd Floor	188	SF	6	10+ years	
	Floor Drain	Girls 2nd Floor	1	EA	7	6-10 years	
	Lavatory	Girls 2nd Floor	2	EA	6	6-10 years	
	Lighting - Lay-in	Girls 2nd Floor	3	EA	6	6-10 years	
	Partitions	Girls 2nd Floor	4	EA	5	1-2 years	Paint partitions
	Walls - Concrete Block	Girls 2nd Floor	415	SF	6	10+ years	
	Water Closet	Girls 2nd Floor	4	EΑ	6	6-10 years	
	Accessories	Girls 3rd Floor	188	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls 3rd Floor	188	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls 3rd Floor	188	SF	6	10+ years	
	Floor Drain	Girls 3rd Floor	1	EA	7	6-10 years	
	Lavatory	Girls 3rd Floor	2	EA	6	6-10 years	
	Lighting - Lay-in	Girls 3rd Floor	3	EΑ	7	6-10 years	
	Partitions	Girls 3rd Floor	4	EΑ	5	1-2 years	Paint partitions
	Walls - Concrete Block	Girls 3rd Floor	415	SF	6	10+ years	
	Water Closet	Girls 3rd Floor	4	ĒΑ	6	6-10 years	
	Accessories	Men Basement	142	SF	7	6-10 years	
	Ceiling - Lay-in	Men Basement	132	SF	6	10+ years	
	Ceiling - Lay-in	Men Basement	10	SF	4	1-2 years	Water damaged ceiling
	Doors - Steel Doors incl hw	Men Basement	1	EA	6	10+ years	Trater damaged coming
	Floor - Tile	Men Basement	142	SF	6	10+ years	
	Floor Drain	Men Basement	1	EA	7	6-10 years	
	Lavatory	Men Basement	1	EΑ	6	6-10 years	
	Lighting - Lay-in	Men Basement	2	EΑ	7	10+ years	
	Lighting - Wall Mounted	Men Basement	1	EΑ	7	6-10 years	
	Partitions	Men Basement	1	EΑ	7	6-10 years	
	Student Lockers - Two Tiers	Men Basement	14	EΑ	6	6-10 years	
	Walls - Concrete Block	Men Basement	220	SF	6	10+ years	
	Water Closet	Men Basement	1	EA	6	6-10 years	
	Accessories	Restroom in Main Office	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in Main Office	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in Main Office	1	EA	6	10+ years	
	Floor - Tile	Restroom in Main Office	50	SF	6	10+ years	
	Floor Drain	Restroom in Main Office	1	EA	7	6-10 years	
	Lavatory	Restroom in Main Office	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Restroom in Main Office	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Restroom in Main Office	145	SF	6	10+ years	
	Water Closet	Restroom in Main Office	143	EA	6	6-10 years	
	Accessories	Staff 2nd Floor	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff 2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Staff 2nd Floor	1	EA	6	10+ years	
	Floor - Tile	Staff 2nd Floor	36	SF	6	10+ years	
	Floor Drain	Staff 2nd Floor	1	EA	7	6-10 years	
	. ioo. Diam	Otali 2110 i 1001	•	_/ \	,	o io youis	

Page : 32 of 44 Campus Name: Hedges Assessment Date: 11/09/2023



Catego	ry : Room		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Staff 2nd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Staff 2nd Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	Staff 2nd Floor	70	SF	6	10+ years	
	Water Closet	Staff 2nd Floor	1	EA	6	6-10 years	
	Accessories	Staff 3rd Floor	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff 3rd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Staff 3rd Floor	1	EA	6	10+ years	
	Floor - Tile	Staff 3rd Floor	32	SF	6	10+ years	
	Floor - Tile	Staff 3rd Floor	4	SF	4	1-2 years	Curling tile
	Floor Drain	Staff 3rd Floor	1	EA	7	6-10 years	
	Lavatory	Staff 3rd Floor	1	EΑ	6	6-10 years	
	Lighting - Wall Mounted	Staff 3rd Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	Staff 3rd Floor	70	SF	6	10+ years	
	Water Closet	Staff 3rd Floor	1	EΑ	6	6-10 years	
	Accessories	Women's - Basement	186	SF	7	6-10 years	
	Benches	Women's - Basement	2	LF	6	6-10 years	
	Ceiling - Lay-in	Women's - Basement	186	SF	6	10+ years	
	Doors - Steel Doors incl hw	Women's - Basement	1	EA	6	10+ years	
	Floor - Tile	Women's - Basement	186	SF	6	10+ years	
	Floor Drain	Women's - Basement	1	EA	7	6-10 years	
	Lavatory	Women's - Basement	1	EA	6	6-10 years	
	Lighting - Lay-in	Women's - Basement	2	EA	7	6-10 years	
	Lighting - Wall Mounted	Women's - Basement	1	EA	7	10+ years	
	Partitions	Women's - Basement	1	EA	7	6-10 years	
	Student Lockers - Two Tiers	Women's - Basement	16	EA	6	6-10 years	
	Walls - Concrete Block	Women's - Basement	430	SF	6	10+ years	
	Water Closet	Women's - Basement	1	EA	6	6-10 years	

Category : Classroom **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #100 (Kindergarten)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	975	SF	6	10+ years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	975	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	946	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	504	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	

Campus Name: Hedges Page : 33 of 44 Assessment Date: 11/09/2023



Catego	Category : Classroom		В	uilding	on	, 5	
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	m #101 (Kindergarten)						
	Casework	1st Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	967	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water damaged ceiling
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	975	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	630	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	630	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #103 (Pre School)						
	Casework	1st Floor	11	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	895	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	6	6-10 years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,220	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	270	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
_Classroo	om #105 (Pre School)						
	Casework	1st Floor	11	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	895	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor	2	EA	5	1-2 years	Not working
	Storage/ Closet	1st Floor	36	SF	7	10+ years	•
	Walls - Concrete Block	1st Floor	1,220	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	270	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #106 (Special Education)						
	Casework	1st Floor	10	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	568	SF	6	10+ years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
			O .	٥.	Ŭ	. o . youro	



Catego	Category : Classroom		В	uilding	: Additi		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	568	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	6	6-10 years	
	Storage/ Closet	1st Floor	15	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	315	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	525	SF	6	10+ years	
Classroo	m #108 (Special Education)						
	Ceiling - Lay-in	1st Floor	935	SF	6	10+ years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	935	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	6	10+ years	
Classroo	m #200 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	895	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	18	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	640	SF	6	10+ years	
Classroo	m #201 (Other Instructional Use)						
	Casework	2nd Floor	10	LF	6	6 10 2000	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	850	SF	6 6	6-10 years	
	Doors - Side-lite			SF SF	_	10+ years	
		2nd Floor	6		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	18	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	390	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	600	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	



Category : Classroom			В	Building : Addition				
- and go	.,		_			Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #202 (Regular Classroom)		-			•		
	Casework	2nd Floor	10	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	895	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	6	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	895	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	18	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	420	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	640	SF	6	10+ years		
Classroo	om #203 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	935	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	6	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years		
	Floor - Tile	2nd Floor	935	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years		
	Marker Board	2nd Floor	8	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	36	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	856	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	300	SF	6	10+ years		
Classroo	om #204 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	895	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	6	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years		
	Floor - Tile	2nd Floor	895	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	18	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	429	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	640	SF	6	10+ years		
_Classroo	om #205 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	935	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	6	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	935	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years		
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	36	SF	7	10+ years		
						,		

Campus Name: Hedges Page : 36 of 44 Assessment Date: 11/09/2023



Catego	ry : Classroom		Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	6	10+ years	
Classroc	om #206 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	895	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	18	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	440	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	640	SF	6	10+ years	
Classroc	om #208 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	935	SF	6	10+ years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	935	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	11	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	6	10+ years	
Classroo	om #300 (Regular Classroom)						
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	18	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	802	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	268	SF	7	10+ years	
Nooses -	om #301 (Science Classroom)						
Jassioc	,	2nd Floor	10	1.5		0.40	
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	24	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,040	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
Classroo	om #302 (Regular Classroom)						
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
		3rd Floor	11	EA	7	•	
	Lighting - Lay-in Marker Board			LF		6-10 years	
		3rd Floor	12		7	6-10 years	
	Storage/ Closet	3rd Floor	18	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,070	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	935	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	935	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	300	SF	6	10+ years	
Classroo	om #305 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	935	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	935	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor		LF	7		
			8			6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	300	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	6	SF	6	10+ years	
						,	



Catego	ry : Classroom		Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	18	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,060	SF	6	10+ years	
	Walls - Concrete Block	3rd Floor	10	SF	5	1-2 years	Cracks in block wall

Category : Interior **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	2,208	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	132	SF	6	10+ years	
	Doors - Side-lite	1st Floor	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	9	EΑ	6	10+ years	
	Doors - Transom Window	1st Floor	52	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	5	EΑ	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	346	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	1,994	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	30	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	4,500	SF	6	10+ years	
	Walls - Masonry	1st Floor	300	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,255	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	5	EA	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	1,235	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	20	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Lay-in	2nd Floor	22	EΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor	2,025	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	116	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,255	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	5	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	1,255	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	22	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	2,025	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	116	SF	6	10+ years	
	Ceiling - Exposed	Basement	690	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	
	Drinking Fountains - Single Fountain	Basement	1	EA	7	6-10 years	
	Floor - Tile/Sheet	Basement	690	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	7	EA	6	6-10 years	

Campus Name: Hedges Page : 39 of 44 Assessment Date: 11/09/2023



Catego	ry : Interior	В	uilding				
				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Basement	1,200	SF	6	10+ years	
	Walls - Concrete Block	Basement	490	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	1	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	NE	210	SF	6	10+ years	
	Floor - Concrete	NE	166	SF	7	10+ years	
	Floor - Tile	NE	660	SF	6	10+ years	
	Handrails	NE	178	LF	7	10+ years	
	Lighting - Lay-in	NE	5	EA	7	10+ years	
	Lighting - Pendent/Surface	NE	5	EA	7	10+ years	
	Stairs - Concrete	NE	80	LF	6	10+ years	
	Walls - Concrete Block	NE	1,285	SF	6	10+ years	
	Ceiling - Plaster/Drywall	NW	630	SF	6	10+ years	
	Floor - Concrete	NW	58	SF	7	10+ years	
	Floor - Tile	NW	522	SF	6	10+ years	
	Handrails	NW	160	LF	7	10+ years	
	Lighting - Pendent/Surface	NW	5	EA	7	6-10 years	
	Stairs - Concrete	NW	80	LF	6	10+ years	
	Walls - Concrete Block	NW	1,215	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S near Main Office	630	SF	6	10+ years	
	Floor - Concrete	S near Main Office	58	SF	7	10+ years	
	Floor - Tile	S near Main Office	522	SF	6	10+ years	
	Handrails	S near Main Office	160	LF	7	10+ years	
	Lighting - Pendent/Surface	S near Main Office	5	EA	7	6-10 years	
	Stairs - Concrete	S near Main Office	480	LF	6	10+ years	Updated quantity
	Walls - Concrete Block	S near Main Office	1,215	SF	6	10+ years	
Vertical (Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	



Category : Site	Building : Site

Calego	ry . Site	Building . Site							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Civil/Dra									
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	10+ years			
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole	Entire Site	13	EA	6	10+ years			
	Civil/ Dialitage - Site Marinole	Little Site	13	LA	O	10+ years			
Fencing		-							
	Fencing - Chain Link	Entire Site	60	LF . –	6	6-10 years			
	Fencing - Chain Link	Entire Site	295	LF . –	4	0-1 year	Rusting, welded to old fence posts		
	Fencing - Iron and Concrete Post	Entire Site	347	LF . –	6	10+ years			
	Fencing - New Standard Ornamental	Entire Site	100	LF	6	10+ years			
Landsca	ne								
Lanasca	Benches	Entire Site	4	EA	6	10+ years			
	Landscape - Grass	Entire Site	1,380	SF	6	10+ years			
	Landscape - Hardscape- Concrete	Entire Site	2,550	SF	6	10+ years	Reconfigured		
	Parkway trees	Entire Site	15	EA	6	10+ years	rtoooriiigaroa		
	Planting Beds/ Area	Entire Site	150	SF	6	10+ years			
	Play Area - Hardscape- Asphalt	Entire Site	3,000	SF	7	10+ years	Repaved and reconfigured		
	Retaining Wall - Concrete	Entire Site	183	SF	6	10+ years	rtoparoa ana rocomigaroa		
Doubin a l	•					·			
Parking		D. I. I. (N. d)	0.005			40	Б .		
	Surface - Asphalt	Parking Lot- North	6,625	SF	7	10+ years	Repaved		
Playgrou	und								
75	Equipment - Pre K 3-5	SE Site	1	EA	7	10+ years	New		
	Equipment - School Age 5-12	SE Site	1	EA	7	10+ years	New		
	Surface - Poured Surface	SE Site	2,000	SF	7	6-10 years	New		
			_,	-	•	5 10 , 505			
Sidewall									
	Sidewalks - Perimeter Sidewalks	Entire Site	9,900	SF	6	10+ years			
	Sidewalks - Perimeter Sidewalks	Entire Site	500	SF	4	1-2 years	Some areas repaired, cracked,		
							sunken		
0:									
Signage	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years			
	Marquee - Free Standing Back lighted w/	Entire Site	1	EA	6	10+ years			
	LED	Little Oile	1	LA	U	10+ years			
	Monument - Building Mounted Cut Letter	Entire Site	2	EA	6	10+ years			
	Sign	Little Site	2	EA	U	10+ years			
	Sign								



James Hedges Elementary School

4747 S Winchester AVENUE, Chicago, IL 60609

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Hedges Page : 42 of 44 Assessment Date: 11/09/2023





Classroom Summary

j			_	Floor Plan	_	Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Malé Dans Dans	D	04.4	04.4	000	0.4	00	. NI	N.
Art Room	Multi Purpose Room	Basement	014	014	980	64	32	N	N
Other Instructional Use	Office	1st Floor	112	NA	380	36	18	N	N
Other Instructional Use	Regular Classroom	3rd Floor	315	310	1,100	168	84	Y	N
Play Room	Regular Classroom	3rd Floor	314	301	1,064	135	65	N	N
Regular Classroom	Regular Classroom	1st Floor	110	102	1,060	135	65	N	N
Regular Classroom	Regular Classroom	1st Floor	111	109	1,040	168	84	Υ	N
Regular Classroom	Regular Classroom	1st Floor	114	101	1,066	135	65	N	N
Regular Classroom	Regular Classroom	1st Floor	115	110	1,110	168	84	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	202	1,060	108	52	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	209	1,040	168	84	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	214	201	1,060	135	65	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	210	1,110	168	84	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	310	302	1,060	135	65	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	309	1,040	168	84	Υ	N
Special Education	Regular Classroom	3rd Floor	312	303	675	81	39	N	N
Special Education	Special Program	2nd Floor	212	Library	675	81	39	N	N
	<u> </u>	·						•	•
Building : Addition									
Kindergarten	Kindergarten	1st Floor	100	131	975	153	76	N	Υ
Kindergarten	Kindergarten	1st Floor	101	130	975	123	66	N	Υ
Other Instructional Use	Computer Lab	2nd Floor	201	201	850	90	48	N	N
Pre School	Pre School	1st Floor	103	129	895	90	48	N	N
Pre School	Pre School	1st Floor	105	127	895	90	48	N	Υ
Regular Classroom	Regular Classroom	1st Floor	208	203	935	120	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	200	200	895	84	42	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	895	90	48	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	214	935	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	201	895	90	48	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	213	935	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	202	895	90	48	N	Y
Regular Classroom	Regular Classroom	3rd Floor	300	300	895	90	48	N	Y
Regular Classroom	Regular Classroom	3rd Floor	302	302	895	90	48	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	311	935	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	305	312	935	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	895	90	48	N	Y
	Science	3rd Floor				90			Y
Science Classroom			301	301	850	120	48	N	-
Special Education	Regular Classroom	1st Floor	108	112	935		60	N	N Y
Special Education	Special Education	1st Floor	106	111	568	60	30	N	Y



Classroom Summary

-				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board

Campus Name: Hedges Page : 44 of 44 Assessment Date: 11/09/2023