

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1955	1	17,859
Addition	1998	1	10,125
Campus Total			27,984

Catego	Category : Exterior Building : Main						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	9						
	Exterior Doors - Exterior Steel Door	#10	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#10	10	LF	7	10+ years	
	Ramps - Concrete	#10	22	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#2	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2	6	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#3	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#3	10	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#8	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Main Entry #1	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Main Entry #1	2	EA	6	10+ years	
	Exterior Doors - Side lite	Main Entry #1	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Main Entry #1	3	EA	6	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	760	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	10	SF	4	1-2 years	Room 102 and 104 has stepped crack in CMU wall with major separation at juncture of wall and



**Category : Exterior** 

Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments floor slab. 17.859 SF 7 Superstructure - Metal Deck/ Concrete 10+ years Entire Building Topping Liahtina Exterior Lighting - Lighting 2 FΑ 5 Entire Building 6-10 vears Exterior Lighting - Wall Mounted Entire Building 4 FΑ 7 6-10 years Exterior Lighting - Wall Mounted Entire Building 4 FΑ 5 6-10 years Roof System Access Ladder - Metal 2 ΕA 7 10+ years A Main LF Chimney - Brick Chimney- Stainless Steel A Main 15 7 10+ years Liner Chimney - Metal Flue A Main 60 LF 6 10+ vears LF Coping - Metal A Main 583 7 10+ years Coping - Stone A Main 102 LF 7 10+ years LF 7 **Downspouts - Interior Downspouts** A Main 46 10+ years **Downspouts - Interior Downspouts** LF 6 10+ years A Main 8 LF 7 Parapet - 16" - 30" Height 102 A Main 10+ years Parapet - Parapet < 16" Height 583 LF 7 10+ years A Main SF Roof - Asphalt Gravel Ballast A Main 17.659 6 10+ years SF 5 Roof - Asphalt Gravel Ballast 200 1-2 years Soft spots/southwest A Main SF Roof Structure - Steel / Metal Deck/ A Main 17,859 7 10+ years Concrete Topping Walls Canopy - Concrete/ Stucco SF 7 Entire Building 160 10+ vears SF Exterior Walls - Brick Entire Building 6.366 7 10+ vears Exterior Walls - Brick Entire Building 170 SF 4 0-1 year Cracked bricks and mortar Windows Guard - Guards perforated Entire Building 2.264 SF 7 10+ vears Lintels - Steel 409 LF 7 10+ years Entire Building 106 SF Windows - Louver Entire Building 6 10+ years SF Windows - Sash Aluminum Double-pane Entire Building 2,264 6 10+ years **Category : Electrical Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Emergency System Emergency A/C Power - Corridors and 3.030 SF 6 Entire Building 6-10 years Stairs **Emergency Battery Packs - Corridors and** 5 ΕA 6 Entire Building 6-10 years

**Building : Main** 



**Category : Electrical Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Stairs SF Security System - CCTV Entire Building 27.984 6 6-10 vears Security System - Intrusion Detection Entire Building 27,984 SF 6 6-10 years ΕA 2 Exit Signs - Corridors and Stairs Entire Building 9 0-1 year No battery pack or AC generator Main Service PA System Main Office 27.984 SF 6 6-10 years Power Distribution Lighting and Power Panels - 100 A Entire Building 1 ΕA 7 10+ years Lighting and Power Panels - Above 100 A Entire Building ΕA 7 10+ years 4 Main Distribution Panels - 400 - 600 amp Entire Building 1 ΕA 7 10+ years **Category : Fire Protection** Building : Main Recommend Location Rank Group Item - Type Quantity UOM Replacement Comments Fire Alarm Fire ALarm Anunciator Entire Building 1 ΕA 7 6-10 years Panel service, both main in addition building Fire Alarm Panel Entire Building 1 ΕA 6 6-10 years Panel serves both main and addition buildina Fire Alarm Strobe Lights Entire Building 17,859 SF 6 6-10 years Fire Alarm\_System SF Entire Building 27.984 6 6-10 years **Category : Mechanical Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Boiler Systems Boiler Auxiliary- Non Condensing Hot Water Boiler Room 2 ΕA 6 10+ vears - 1001 - 2000 MBH ΕA Chemical Pot Feeder Boiler Room 6 1 10+ vears **Combustion Dampers** Boiler Room 1 ΕA 5 10+ years ΕA 6 6-10 years Glycol Feed System Boiler Room 1 Hot Water Pump Boiler Room 1 EΑ 6 6-10 years Hot Water Pump Boiler Room 1 EΑ 6 6-10 years Non Condensing- Water Tube- Flexible Boiler Room 1 FΑ 6 10+ years B-1; serves main building Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH Non Condensing- Water Tube- Flexible Boiler Room 1 EΑ 6 10+ years B-2; serves main building Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH Water Fill System Boiler Room EΑ 6 6-10 years Pressure feed system through hot 1 water pumps



Catego	ry : Mechanical		В	uilding	: Main	_	
_			•			Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ias Boo	ster						
	Gas Booster	Boiler Room	1	EA	6	6-10 years	
leating l	Devices						
louing	Wall Heater - Electric	1st Floor	1	EA	6	6-10 years	
	Wall Heater - Electric	1st Floor	1	EA	6	6-10 years	
	Wall Heater - Electric	1st Floor	1	EA	5	1-2 years	Damaged
	Cabinet Heaters - With Hot Water Coil	1st Floor	5	EA	6	6-10 years	Damagoa
	Fin Tube - Hot Water	Entire Building	190	LF	6	6-10 years	
/lechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	200	LF	7	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	7	10+ years	2022 installation
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	7	10+ years	2022 installation
omnora	ture Control						
етрега	Electric Controls	Entire Building	27,984	SF	6	6-10 years	In univents. No DDC, no pneumati
		-				-	system
Init Ven	illation						
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	2	EA	6	6-10 years	Operational, per Engineer
	Heating Coils Only Unit Ventilators- Floor Mounted- Hot Water	Entire Building	10	EA	6	6-10 years	
	Heating Coils Only	Ŭ				,	
entilatio	n						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	2	EA	6	6-10 years	
	CFM Exhaust Fans- Roof Mounted - 500 - 1500	Roof	2	EA	6	6-10 years	
	CFM Exhaust Fans- Roof Mounted - Less than	Roof	1	EA	6	6-10 years	
	500 CFM	RUUI	I	EA	0	0-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
3.5			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate							
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping	Domostic Bining Hot Water Datum Lines	Entiro Duilding	47.050	<u>ور</u>	6	10, 10, 10, 20, 20, 20, 20, 20, 20, 20, 20, 20, 2	
	Domestic Piping-Hot Water Return Lines	Entire Building	17,859	SF	6	10+ years	
	Jame <sup>.</sup> Hovne		Page : 4 of 22				Assessment Date: 04/30/



Catego	ry : Plumbing		B	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	17,859	SF	6	10+ years	
	Sanitary Piping Storm Piping Vent Piping	Entire Building Entire Building Entire Building	17,859 17,859 17,859	SF SF SF	6 6 6	10+ years 10+ years 10+ years	Could stand to be cleaned

Catego	Category : Room			uilding			
Crown	Hom Tune	Location	Quantity	UOM	Rank	Recommend	Comments
Group	Item - Type	Location	Quantity		Rank	Replacement	Comments
Administ	rative Suites/Offices			05	0	10	
	Ceiling - Splined	111-Teacher's Resource Room	188	SF	6	10+ years	
	Doors - Wood Doors inclu hw	111-Teacher's Resource Room	1	EA	6	10+ years	
	Floor - Tile	111-Teacher's Resource Room	188	SF	6	10+ years	
	Lighting - Pendent/Surface	111-Teacher's Resource Room	8	EA	7	6-10 years	
	Walls - Concrete Block	111-Teacher's Resource Room	396	SF	7	10+ years	
	Walls - Plaster/Drywall	111-Teacher's Resource Room	132	SF	7	10+ years	
	Work SInk	111-Teacher's Resource Room	1	EA	7	6-10 years	
	AC Unit	111A	1	EA	7	6-10 years	
	Ceiling - Splined	111A	94	SF	6	10+ years	
	Doors - Wood Doors inclu hw	111A	1	EA	7	10+ years	
	Floor - Tile	111A	94	SF	6	10+ years	
	Lighting - Pendent/Surface	111A	2	EA	7	6-10 years	
	Walls - Concrete Block	111A	180	SF	7	10+ years	
	AC Unit	Assistant Principal's Office	1	EA	7	2-5 years	
	Ceiling - Lay-in	Assistant Principal's Office	113	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal's Office	1	EA	7	10+ years	
	Floor - Tile	Assistant Principal's Office	113	SF	7	6-10 years	
	Lighting - Lay-in	Assistant Principal's Office	2	EA	7	6-10 years	
	Walls - Concrete Block	Assistant Principal's Office	192	SF	7	10+ years	
	Walls - Plaster/Drywall	Assistant Principal's Office	192	SF	7	10+ years	
	AC Unit	Main Office	1	EA	5	2-5 years	
	Ceiling - Lay-in	Main Office	285	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	Main Office	285	SF	7	10+ years	
	Lighting - Lay-in	Main Office	6	EA	7	6-10 years	
	Storage/ Closet	Main Office	52	SF	7	10+ years	
	Walls - Concrete Block	Main Office	654	SF	7	10+ years	
	AC Unit	Principals Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principals Office	210	SF	6	10+ years	
	Doors - Steel Doors incl hw	Principals Office	1	EA	7	10+ years	
	Floor - Tile	Principals Office	210	SF	7	6-10 years	
	Lighting - Lay-in	Principals Office	4	EA	7	6-10 years	
	Walls - Concrete Block	Principals Office	210	SF	7	10+ years	



# Thomas Hoyne Elementary School 8905 S Crandon AVENUE, Chicago, IL 60617

Catego	Category : Room		В	uilding	: Main				
Ŭ	•			J		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Mechan	cal/ Service Rooms								
	Boiler Room	1st Floor	740	SF	7	10+ years			
	Janitor's Closet	1st Floor	45	SF	7	10+ years			
	Storage Room	1st Floor	59	SF	7	10+ years			
	Storage Room	1st Floor	31	SF	7	10+ years			
	Clorage Room		01	01	,	for yourd			
Restroo	n								
	Accessories	102A	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	102A	30	SF	7	10+ years			
	Doors - Wood Doors inclu hw	102A	1	ËA	6	1-2 years	Missing knob, paint chipping		
	Floor - Tile	102A	30	SF	7	6-10 years			
	Lavatory	102A	1	EA	7	10+ years			
	Lighting - Lay-in	102A	1	EA	7	6-10 years			
	Walls - Concrete Block	102A	165	SF	6	10+ years			
	Water Closet	102A	1	EA	7	10+ years			
	Accessories	102A	23	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	103A	23	SF	7	10+ years			
	Doors - Wood Doors inclu hw	103A	23	EA	7	10+ years			
	Floor - Tile	103A 103A	23	SF	5		Tilo orocka throughout		
		103A 103A	23	EA	5	1-2 years	Tile cracks throughout		
	Lavatory					10+ years			
	Lighting - Lay-in	103A	1	EA	7	10+ years			
	Walls - Concrete Block	103A	142	SF	7	10+ years			
	Water Closet	103A	1	EA	7	10+ years			
	Accessories	104A	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	104A	30	SF	7	10+ years			
	Doors - Wood Doors inclu hw	104A	1	EA	7	10+ years			
	Floor - Tile	104A	30	SF	7	6-10 years			
	Lavatory	104A	1	EA	7	10+ years			
	Lighting - Pendent/Surface	104A	1	EA	7	6-10 years			
	Walls - Concrete Block	104A	198	SF	7	10+ years			
	Water Closet	104A	1	EA	7	10+ years			
	Accessories	105A	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	105A	30	SF	7	10+ years			
	Doors - Wood Doors inclu hw	105A	1	EA	7	10+ years			
	Floor - Tile	105A	30	SF	7	6-10 years			
	Lavatory	105A	1	EA	6	10+ years			
	Lighting - Lay-in	105A	1	EA	7	6-10 years			
	Walls - Concrete Block	105A	165	SF	7	10+ years			
	Water Closet	105A	1	EA	7	10+ years			
	Accessories	106A	17	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	106A	17	SF	7	10+ years			
	Doors - Wood Doors inclu hw	106A	1	EA	7	10+ years			
						,			
						•			
	Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	106A 106A 106A	1 17 1	EA SF EA	7 7 7	10+ years 6-10 years 6-10 years			



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Plaster/Drvwall 106A 119 SF 10+ vears 7 Water Closet 106A ΕA 7 1 10+ years Accessories 107A 30 SF 7 6-10 years Ceiling - Plaster/Drywall 30 SF 7 107A 10+ years Doors - Wood Doors inclu hw 107A 1 EΑ 7 10+ years SF Floor - Tile 7 107A 30 6-10 years 107A ΕA 7 10+ years Lavatory 1 Lighting - Lay-in 107A 1 ΕA 7 6-10 years Walls - Concrete Block 107A 165 SF 7 10+ years Water Closet EΑ 7 10+ years 107A 1 Accessories 108A 27 SF 7 10+ vears Ceiling - Plaster/Drywall 108A 27 SF 7 10+ years Doors - Wood Doors inclu hw ΕA 7 108A 1 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 108A 27 10+ years Floor Drain ΕA 7 108A 1 10+ years Hand Dryer FΑ 7 108A 1 10+ years Lavatorv 108A 1 ΕA 7 10+ years Lighting - Pendent/Surface 108A 1 ΕA 7 10+ years Walls - Plaster/Drvwall SF 108A 56 7 10+ vears Walls - Structural Glazed Tile SF 108A 100 7 10+ years Water Closet 108A 1 ΕA 7 10+ years SF 7 Accessories 110A 30 6-10 years SF 7 Ceiling - Plaster/Drywall 110A 30 10+ years Doors - Wood Doors inclu hw 7 1 FΑ 10+ years 110A Floor - Tile 30 SF 7 6-10 years 110A Lavatorv 110A 1 ΕA 6 10+ vears 7 Lighting - Lay-in 110A 1 ΕA 6-10 years Walls - Concrete Block 165 SF 7 10+ years 110A Water Closet ΕA 110A 1 7 10+ years Accessories 112A 28 SF 7 6-10 years SF Ceiling - Plaster/Drywall 112A 28 7 10+ vears Doors - Wood Doors inclu hw 112A 1 EΑ 6 10+ vears SF Floor - Tile 112A 26 6 6-10 years Floor - Tile 112A 2 SF 5 1-2 vears Cracked tiles 7 Lavatory 112A 1 EΑ 6-10 years Lighting - Lay-in ΕA 7 112A 1 6-10 years Walls - Concrete Block SF 112A 159 6 10+ years Water Closet 112A ΕA 7 1 10+ years SF Accessories **Boiler Room** 70 7 6-10 years Ceiling - Plaster/Drvwall SF **Boiler Room** 70 7 10+ vears Doors - Wood Doors inclu hw **Boiler Room** 1 ΕA 7 10+ years 70 SF 7 6-10 vears Floor - Concrete Boiler Room Reaccessed: surface crack typ Lavatory Boiler Room EΑ 7 10+ years 1 7 Lighting - Pendent/Surface Boiler Room 1 EΑ 6-10 years



Group

**Building : Main** Category : Room Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Concrete Block SF Boiler Room 252 7 10+ years Water Closet **Boiler Room** ΕA 7 10+ years 1 Accessories Boys Toilet 207 SF 7 6-10 years Ceiling - Plaster/Drywall Boys Toilet 207 SF 7 10+ years Doors - Wood Doors inclu hw Boys Toilet 1 EΑ 7 10+ years SF Floor - Tile Ceramic/ Porcelain **Boys Toilet** 207 6 10+ years Floor Drain Boys Toilet ΕA 4 1-2 years Missing drain grill 1 Lavatory **Boys Toilet** 2 ΕA 7 6-10 years Lighting - Pendent/Surface Boys Toilet 2 ΕA 7 6-10 years Partitions 7 Boys Toilet 1 ΕA 10+ years 2 Urinals Bovs Toilet ΕA 7 10+ vears Walls - Concrete Block Boys Toilet 488 SF 5 10+ years Walls - Concrete Block **Boys Toilet** 25 SF 5 1-2 years Mortar cracks 7 Water Closet ΕA Boys Toilet 1 10+ years Accessories **Girls Toilet** 238 SF 7 6-10 years Ceiling - Plaster/Drywall **Girls Toilet** 238 SF 7 10+ years Doors - Wood Doors inclu hw ΕA 7 **Girls Toilet** 1 10+ years SF Floor - Tile Ceramic/ Porcelain **Girls Toilet** 238 7 10+ years ΕA Floor Drain **Girls Toilet** 7 10+ years 1 Lavatory Girls Toilet 2 FΔ 7  $10 \pm v_{ears}$ 

Lavalory	Gins Tollet	2	EA	1	TU+ years		
Lighting - Lay-in	Girls Toilet	1	EA	7	6-10 years		
Lighting - Pendent/Surface	Girls Toilet	2	EA	7	6-10 years		
Partitions	Girls Toilet	3	EA	7	10+ years		
Walls - Concrete Block	Girls Toilet	576	SF	7	10+ years		
Water Closet	Girls Toilet	2	EA	7	10+ years		
Water Closet	Girls Toilet	1	EA	4	1-2 years	Not working	
Accessories	Staff Toilet @ Principals Office	27	SF	7	6-10 years		
Ceiling - Plaster/Drywall	Staff Toilet @ Principals Office	27	SF	7	10+ years		
Doors - Wood Doors inclu hw	Staff Toilet @ Principals Office	1	EA	7	10+ years		
Floor - Tile	Staff Toilet @ Principals Office	27	SF	6	10+ years		
Lavatory	Staff Toilet @ Principals Office	1	EA	7	10+ years		
Lighting - Pendent/Surface	Staff Toilet @ Principals Office	1	EA	7	6-10 years		
Partitions	Staff Toilet @ Principals Office	1	EA	7	10+ years		
Walls - Concrete Block	Staff Toilet @ Principals Office	161	SF	7	10+ years		
Water Closet	Staff Toilet @ Principals Office	1	EA	7	10+ years		

Category : Classroom		Bu	uilding	: Main		
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #101 (Regular Classroom)	Location	Quantity		Kdlik	Replacement	Comments
Ceiling - Lay-in	1st Floor	633	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	633	SF	7	6-10 years	
Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	



**Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments LF Marker Board 1st Floor 24 6-10 years 7 Student Lockers - One Tier 1st Floor 9 ΕA 7 10+ years Walls - Concrete Block 1st Floor 869 SF 7 10+ years Classroom #102 (Regular Classroom) AC Units 1st Floor 2 FΑ 7 6-10 years Casework 1st Floor 40 LF 7 10+ years SF Ceiling - Plaster/Drywall 1st Floor 869 7 10+ years LF Chalk Board 1st Floor 20 4 2-5 years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 7 10+ years Floor - Tile 869 SF 7 6-10 years 1st Floor Lighting - Pendent/Surface 1st Floor 18 EΑ 7 6-10 years Student Lockers - One Tier 1st Floor 11 ΕA 7 10+ years SF Walls - Concrete Block 1st Floor 870 7 10+ years Classroom #103 (Regular Classroom) Ceiling - Lay-in 1st Floor SF 7 896 10+ years Chalk Board LF 2-5 years 1st Floor 12 4 Doors - Wood Doors inclu hw FΑ 7 1st Floor 10+ years 1 Floor - Tile 1st Floor 896 SF 7 6-10 years Lighting - Lay-in 1st Floor 11 EΑ 7 6-10 years LF Marker Board 1st Floor 12 7 6-10 years Student Lockers - One Tier 1st Floor 11 ΕA 7 10+ years 1,091 SF 7 Walls - Concrete Block 1st Floor 10+ years Classroom #104 (Regular Classroom) AC Units 1st Floor 2 ΕA 7 6-10 vears LF Casework 1st Floor 21 7 10+ years Ceiling - Plaster/Drywall 1st Floor 869 SF 7 10+ years LF Chalk Board 1st Floor 20 4 2-5 years Doors - Wood Doors inclu hw ΕA 7 10+ years 1st Floor 1 SF 7 Floor - Tile 1st Floor 869 6-10 years Lighting - Pendent/Surface 1st Floor FΑ 7 6-10 years 18 LF Marker Board 1st Floor 15 7 6-10 years Student Lockers - One Tier 1st Floor ΕA 7 11 10+ years Walls - Concrete Block 1st Floor 978 SF 7 10+ vears Classroom #105 (Science Classroom) AC Units 1st Floor 2 ΕA 7 6-10 years 1st Floor 38 LF Casework 6 10+ years SF Ceiling - Splined 1st Floor 963 6 10+ years Chalk Board 1st Floor 20 LF 4 2-5 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	1st Floor	963	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	11	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	1,055	SF	7	10+ years	
Classroo	m #106 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Splined	1st Floor	1,181	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	.,	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,181	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,169	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
			2	LI		e re youre	
Classroo	m #107 (Regular Classroom)		_			- / -	
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	38	LF	6	10+ years	
	Ceiling - Splined	1st Floor	982	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	982	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	19	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	19	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	11	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	792	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	264	SF	7	10+ years	
Classroo	m #108 (Pre School)						
	Casework	1st Floor	21	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	839	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	839	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	25	LF	7	6-10 years	
	Storage/ Closet	1st Floor	18	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	11	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	482	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	482	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	



<b>Group</b> Classroom	y : Classroom Item - Type	Location		uilding		Recommend	
Classroom	Item - Type	Location					
		Location	Quantity	UOM	Rank	Replacement	Comments
	n #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Splined	1st Floor	575	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	575	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	190	SF	7	10+ years	
lassroom	n #110 (Regular Classroom)						
	Casework	1st Floor	43	LF	6	10+ years	
	Ceiling - Splined	1st Floor	979	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	Covered
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Obvered
	Floor - Tile	1st Floor	969	SF	7	6-10 years	
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Large crack across center
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	Large clack across center
	Storage/ Closet	1st Floor	16	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	11	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,019	SF	7	10+ years	
	Walls - Concrete block		1,019	SF	1	10+ years	
	n #112 (Other Instructional Use)						
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Splined	1st Floor	358	SF	6	10+ years	
	Ceiling - Splined	1st Floor	2	SF	5	1-2 years	Damaged tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	355	SF	7	6-10 years	
	Floor - Tile	1st Floor	5	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	-
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	16	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	171	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	171	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroom	n #113 (Computer Lab)						
	Casework	1st Floor	48	LF	6	10+ years	
	Ceiling - Splined	1st Floor	636	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		US S Crandon AVENUE, Chicago, IL 6061
caloge			_	anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	636	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	651	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	217	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	m #114 (Regular Classroom)						
	Casework	1st Floor	74	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	868	SF	6	10+ years	
	Ceiling - Splined	1st Floor	2	SF	5	1-2 years	Missing tiles
	Chalk Board	1st Floor	4	LF	4	2-5 years	incomg mee
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	870	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	979	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Catego	ry : Interior		в	uilding	• Main		
Julige	.,		_	anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	North Corridor	93	SF	6	10+ years	
	Ceiling - Splined	North Corridor	1,649	SF	6	10+ years	
	Doors - Steel Doors incl hw	North Corridor	4	EA	7	10+ years	
	Doors - Wood Doors include hw	North Corridor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	North Corridor	2	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	North Corridor	84	SF	7	10+ years	
	Floor - Tile/Sheet	North Corridor	1,658	SF	7	10+ years	
	Lighting - Pendent/Surface	North Corridor	19	EA	7	6-10 years	
	Walls - Concrete Block	North Corridor	1,904	SF	7	10+ years	
	Walls - Masonry	North Corridor	180	SF	7	10+ years	
Safety							
, –	Camera Viewing Station	1st Floor	1	EA	7	0-1 year	No working cameras or viewing station
	Security Cameras	1st Floor	5	EA	4	0-1 year	No cameras working, all outdoor



Catego	ry : Exterior		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#4	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#5	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#6	2	EA	7	10+ years	
	Entrance Control - Audio	#7	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#7	2	EA	7	10+ years	
	Power Door Operator and Controls	#7	1	EA	7	6-10 years	
Foundati	on						
<u> </u>	Foundation - Concrete	Entire Building	421	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	10,125	SF	7	10+ years	
	Topping						
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	Roof B	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof B	70	LF	6	10+ years	
	Coping - Stone	Roof B	251	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof B	42	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof B	176	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof B	75	LF	7	10+ years	
	Roof - Modified Bitumen	Roof B	6,500	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof B	100	SF	5	2-5 years	
	Roof Hatch - Metal	Roof B	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof B	6,600	SF	7	10+ years	
	Concrete Topping					-	
	Access Ladder - Metal	Roof C	1	EA	5	1-2 years	Length of Ladder is not sufficient. Object is needed to access the ladde
	Coping - Stone	Roof C	244	LF	7	10+ years	Object is needed to access the ladde
	Downspouts - Interior Downspouts	Roof C	44	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof C	244	LF	7	10+ years	
	Roof - Modified Bitumen	Roof C	3,375	SF	7	6-10 years	
	Roof - Modified Bitumen	Roof C	150	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Roof C	3,525	SF	7	10+ years	
	Concrete Topping		0,020	0	ı	ior years	
Walls							
	Canopy - Metal	Entire Building	30	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	5,695	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	516	SF	7	10+ years	



**Category : Exterior Building : Addition** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Windows **Clerestory - Glass Double-Pane Entire Building** 54 SF 6 10+ years 315 SF 7 Guard - Guards perforated Entire Building 10+ years Lintels - Steel 120 LF 7 10+ years Entire Building Entire Building SF Windows - Decorative 180 6 10+ years Windows - Louver Entire Building 63 SF 6 10+ years SF Windows - Sash Aluminum Double-pane Entire Building 315 6 10+ years **Category : Electrical Building : Addition** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Emergency System Security System - CCTV 1st Floor 10,125 SF 6 6-10 years SF Security System - Intrusion Detection 1st Floor 10,125 6 6-10 years Automatic Transfer Switch 6 Electrical Room EΑ 10+ years 1 SF 6 Emergency A/C Power - Corridors and Entire Building 2,225 6-10 years Stairs Emergency A/C Power - Multipurpose Entire Building 3.098 SF 6 6-10 years Room **Emergency Battery Packs - Corridors and** Entire Building 4 EΑ 6 6-10 years Stairs Emergency Battery Packs - Multipurpose Entire Building 2 ΕA 6 6-10 years Room **Emergency Battery Packs - Students Toilets** 2 ΕA 6 Entire Building 6-10 years Exit Signs - Corridors and Stairs 4 ΕA 6-10 years Entire Building 6 Exit Signs - Multipurpose Room Entire Building 2 ΕA 6 6-10 years Main Service Electrical Room Independent Electrical Service for 1 ΕA 6 6-10 years emergency power Main Electrical Service - 1000 A Electrical Room 1 EΑ 6 6-10 years 120/240/3PH Power Distribution Lighting and Power Panels - Above 100 A Entire Building 6 EΑ 7 10+ years Main Distribution Panels - 400 - 600 amp Entire Building ΕA 7 10+ years 1 **Category : Fire Protection Building : Addition** Recommend Location Item - Type UOM Rank **Replacement** Comments Group Quantity Fire Alarm



Category : Fire Protection			В	uilding			
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	10,125	SF	6	6-10 years	
Sprinkler	r System						
	Sprinkler Heads	Entire Building	10,125	SF	7	10+ years	
	Sprinkler Piping	Entire Building	10,125	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	10,125	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Additi	on	
Crown	Itom Type	Leastion	Quantity		Denk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Roof Mounted - 31-50 tons	Roof	1	EA	6	6-10 years	Unit functional. Rusty covers over fans
Air Hand	lling Systems						
	Air Handling Unit-Package Single Zone-	Boiler Room	1	EA	6	6-10 years	
	Indoor- Hot Water and DX Cooling Coils -						
	8001-12000 cfm						
	Air Intake	Boiler Room	1	EA	6	6-10 years	
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	4	EA	6	6-10 years	Located in ceiling, above tiles
	Make Up Air Unit- Roof Mounted- Gas Heating - 6000 - 10,000 cfm	Gym Roof	1	EA	6	6-10 years	
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating Coil - 5 - 10 tons	Gym Roof	1	EA	6	6-10 years	
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating Coil - 5 - 10 tons	Gym Roof	1	EA	6	6-10 years	
Boiler Sy	vstems						
,	Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	Needs painting, cleaning
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	Glycol is manually fed into the syste
	Hot Water Pump	Boiler Room	1	EA	6	6-10 years	P-2
	Hot Water Pump	Boiler Room	1	EA	6	6-10 years	P-1
	Non Condensing- Flexible Tube-	Boiler Room	2	EA	6	6-10 years	Serve 1998 addition
	Atmospheric- Hot Water Boiler - 500 - 1000 MBH		2		0	0 10 96413	
	Water Fill System	Boiler Room	1	EA	6	6-10 years	Pressure fill system through hot wat

Gas Booster



Category : Mechanical			В	uilding	on		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Booster	Boiler Room	1	EA	6	6-10 years	
leating	Devices						
	Radiator Panels - Hot Water	1st Floor	2	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	1st Floor	- 1	EA	6	6-10 years	
	Unit Heater - Hot Water	Mechanical Room	1	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Mechanical Room	100	LF	6	6-10 years	
<u>Fempera</u>	ature Control						
·	DDC System	Entire Building	10,125	SF	6	0-1 year	Software recently upgraded, not working correctly. Being addressed
	Electric Thermostat	Entire Building	2	EA	7	10+ years	Multipurpose room. Not previously assessed.
	Thermostats - DDC	Entire Building	8	EA	6	6-10 years	
/entilatio							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	6-10 years	
	Roof Mounted Duct Work	Roof	50	LF	6	2-5 years	Ductwork is functional, but severel rusted
Catego	ry : Plumbing		В	uilding			
	· · ·		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	7	10+ years	2020 install
	Gas Heater - Less than 150000 BTU/HR	Kitchen- 1st Floor	1	EA	6	6-10 years	
						-	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	10,125	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	10,125	SF	6	10+ years	
	(Horizontal Lines)	5				-	
	Sanitary Piping	Entire Building	10,125	SF	7	10+ years	
	Storm Piping	Entire Building	10,125	SF	7	10+ years	
	Vent Piping	Entire Building	10,125	SF	7	10+ years	
-	ry : Room		В	uildina	: Additi	on	
	Item - Type						

Chicago Public Schools						s Hoyne Elementary Scho 905 S Crandon AVENUE, Chicago, IL 60
					Replacement	
dministrative Suites/Offices						
Ceiling - Exposed	Gym Office/Gym Storage 123	562	SF	7	10+ years	
Doors - Steel Doors incl hw	Gym Office/Gym Storage 123	2	EA	7	10+ years	
Floor - Tile	Gym Office/Gym Storage 123	562	SF	6	10+ years	
Lighting - Pendent/Surface	Gym Office/Gym Storage 123	6	EA	7	6-10 years	
Power Distribution	Gym Office/Gym Storage 123	6	EA	7	10+ years	
Walls - Concrete Block	Gym Office/Gym Storage 123	1,124	SF	7	10+ years	
Ceiling - Lay-in	Kitchen Office	68	SF	7	10+ years	
Doors - Side-lite	Kitchen Office	30	SF	7	10+ years	
Doors - Steel Doors incl hw	Kitchen Office	1	EA	7	10+ years	
Floor - Tile	Kitchen Office	68	SF	7	10+ years	
Lighting - Lay-in	Kitchen Office	1	EA	7	6-10 years	
Walls - Concrete Block	Kitchen Office	279	SF	7	10+ years	
ivmnasia						
Ceiling - Exposed	1st Floor	3,189	SF	7	10+ years	No occupancy signage
Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	···· ····· ···· ··· ··· ··· ··· ··· ··
Floor - Tile	1st Floor	3,174	SF	7	10+ years	
Floor - Tile	1st Floor	15	SF	4	1-2 years	Damaged tiles
Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	Damagea mee
Scoreboards	1st Floor	1	EA	7	6-10 years	
Storage/ Closet	1st Floor	600	SF	7	10+ years	
Walls - Concrete Block	1st Floor	4,447	SF	7	10+ years	
itchen						
Ceiling - Lay-in	1st Floor	756	SF	7	10+ years	
Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
Floor - Tile/Sheet	1st Floor	756	SF	7	10+ years	
Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
Storage/ Closet	1st Floor	75	SF	7	-	
Walls - Concrete Block	1st Floor	996	SF	7	10+ years 10+ years	
Walls - Concrete Block	13(1100)	330	51	I	10+ years	
Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
Finishes	1st Floor	150	SF	7	10+ years	
Other Cooling Unit	1st Floor	1	EA	7	6-10 years	Central air
lechanical/ Service Rooms						
Janitor's Closet	1st Floor	33	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	751	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	145	SF	7	10+ years	
estroom						
Accessories	1st Floor	67	SF	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	67	SF	7	10+ years	



Replacement Doors - Steel Doors incl hw 1st Floor ΕA 1 7 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 67 SF 7 10+ years 10+ years Floor Drain 1st Floor 1 ΕA 7 1 ΕA 7 10+ years Lavatory 1st Floor Lighting - Pendent/Surface 7 1st Floor 1 ΕA 6-10 years Walls - Concrete Block SF 7 1st Floor 290 10+ years Water Closet 1st Floor ΕA 7 1 10+ years SF Accessories Boys Toilet 223 7 6-10 years SF Ceiling - Plaster/Drywall Boys Toilet 223 7 10+ years Floor - Tile Boys Toilet SF 7 30 10+ years Floor - Tile Ceramic/ Porcelain Boys Toilet SF 193 6 10+ years Floor Drain **Boys Toilet** 1 ΕA 7 10+ years Lavatory **Boys Toilet** 2 ΕA 7 10+ years Lighting - Pendent/Surface 2 **Boys Toilet** ΕA 7 6-10 years Partitions **Boys Toilet** 1 ΕA 7 10+ years Urinals Boys Toilet 2 ΕA 7 10+ years Walls - Concrete Block SF Bovs Toilet 520 7 10+ years Boys Toilet ΕA Water Closet 1 7 10+ years **Girls Toilet** 265 SF 7 6-10 years Accessories Ceiling - Plaster/Drywall SF 7 **Girls Toilet** 295 10+ years Floor - Tile Girls Toilet 30 SF 7 10+ years Floor - Tile Ceramic/ Porcelain SF **Girls Toilet** 265 7 10+ years Floor Drain **Girls Toilet** 2 ΕA 7 10+ years 2 ΕA 7 Lavatory **Girls Toilet** 10+ years Lighting - Lay-in **Girls Toilet** 3 ΕA 7 6-10 years 6 Partitions **Girls Toilet** ΕA 7 10+ years Walls - Concrete Block **Girls Toilet** 630 SF 7 10+ years ΕA Water Closet **Girls Toilet** 6 7 10+ years

### **Category : Classroom**

### **Building : Addition**

roup Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
lassroom #115 (Regular Classroom)						
Casework	1st Floor	29	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	860	SF	6	10+ years	
Chalk Board	1st Floor	12	LF	4	2-5 years	
Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	860	SF	6	6-10 years	
Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
Marker Board	1st Floor	12	LF	7	6-10 years	
Storage/ Closet	1st Floor	20	SF	7	10+ years	
Walls - Concrete Block	1st Floor	1,033	SF	7	10+ years	
lassroom #116 (Regular Classroom)						
Casework	1st Floor	30	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	861	SF	6	10+ years	



Catego	ry : Classroom	B	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	861	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,033	SF	7	10+ years	

# **Category : Interior**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	1,112	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	77	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,112	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	5	1-2 years	Missing cover
	Walls - Concrete Block	1st Floor	1,458	SF	7	10+ years	C C



Category : Site			В	Building : Site				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Civil/Drai								
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years		
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	10+ years		
Fencina								
0	Fencing - Chain Link	Entire Site	282	LF	7	10+ years		
	Fencing - New Standard Ornamental	Entire Site	255	LF	7	10+ years		
Landsca	De							
	Benches	Entire Site	7	EA	7	10+ years		
	Landscape - Grass	Entire Site	10,674	SF	7	10+ years		
	Landscape - Hardscape- Concrete	Entire Site	1,150	SF	7	10+ years		
	Landscape - Hardscape- Concrete	Entire Site	680	SF	7	10+ years		
	Parkway trees	Entire Site	16	EA	7	10+ years		
	Planting Beds/ Area	Entire Site	3,445	SF	7	10+ years		
	Play Area - Hardscape- Asphalt	Entire Site	2,288	SF	7	10+ years		
	Play Area - Synthetic Turf	Entire Site	800	SF	7	10+ years		
	Trash Receptacles	Entire Site	3	EA	6	6-10 years		
Parking I	ot							
	Concrete Curbs	East	203	LF	7	10+ years		
	Surface - Asphalt	East	5,606	SF	7	10+ years		
	Trash Enclosure - Chain Links	East	192	SF	7	10+ years		
	Vehicular Screening	East	120	LF	7	10+ years		
Playgrou	nd							
,0	Equipment - School Age 5-12	East	1	EA	7	10+ years		
	Surface - Poured Surface	East	1,950	SF	7	10+ years		
	Equipment - School Age 5-12	West	1	EA	7	6-10 years		
	Surface - Poured Surface	West	1,435	SF	7	6-10 years		
Sidewalk	S							
	Sidewalks - Internal Walks	Entire Site	850	LF	7	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	5,131	SF	7	10+ years		
<b>.</b> .						-		
Signage								
	Flag Pole - Flag Pole	Northwest	1	EA	7	10+ years		
	Marquee - Free Standing Back Lighted	Northwest	1	EA	7	10+ years		
	Monument - Building Mounted Cut Letter Sign	Northwest	1	EA	7	10+ years		



<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



# **Classroom Summary**

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		-							
Computer Lab	Computer Lab	1st Floor	113	112	636	120	60	N	Y
Kindergarten	Kindergarten	1st Floor	106	106	1,181	180	70	N	Y
Other Instructional Use	Office	1st Floor	112	112	360	60	30	N	N
Pre School	Kindergarten	1st Floor	108	108	839	140	70	N	Y
Regular Classroom	Kindergarten	1st Floor	110	110	979	180	90	N	Y
Regular Classroom	Regular Classroom	1st Floor	101	101	633	120	60	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	869	180	90	N	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	896	120	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	869	180	90	N	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	982	180	70	N	Y
Regular Classroom	Regular Classroom	1st Floor	109	109	575	120	50	N	Y
Regular Classroom	Regular Classroom	1st Floor	114	114	870	180	90	N	Y
Science Classroom	Kindergarten	1st Floor	105	105	963	180	70	N	Y
Building : Addition									
Regular Classroom	Regular Classroom	1st Floor	115	115	860	120	60	Y	Y
Regular Classroom	Regular Classroom	1st Floor	116	116	861	120	60	Y	Y