

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1913	3	90,864
Addition	1936	3	19,579
Campus Total			110,443

Catego	ry : Exterior	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	#1 - N	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	#1 - N	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#1 - N	96	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	#2 - N	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#2 - N	1	EA	7	10+ years	
	Exterior Stairs - Concrete	#2 - N	86	LF	7	10+ years	
	Exterior Stairs - Concrete	#2 - N	10	LF	5	0-1 year	Cracked.
	Entrance Control - Audio and Video	#3 - E	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#3 - E	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	#3 - E	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#3 - E	280	LF	5	1-2 years	Cracked stairs
	Exterior Doors - Exterior Steel Door	#3.1 - SE	1	EA	7	10+ years	
	Entrance Control - Audio and Video	#4 - S	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#4 - S	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#4 - S	40	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#4 - S	108	LF	7	10+ years	
	Ramps - Concrete	#4 - S	54	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#4 - S	18	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#4.1 - S	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#4.2 - S	1	EA	7	10+ years	
	Ramps - Concrete	#4.2 - S	9	LF	7	10+ years	
	Entrance Control - Audio and Video	#7 - W	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#7 - W	4	EA	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	#7 - W	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#7 - W	200	LF	5	0-1 year	Cracking
	Power Door Operator and Controls	#7 - W	200	EA	7	6-10 years	Cracitaly
	Ramp Handrail - Steel_Ramp Handrail	#7 - W	84	LF	7	10+ years	
	Ramps - Concrete	#7 - W	42	LF	7	10+ years	
	Ramps - Obliciete	$\pi r = \mathbf{v}$	72	LI	1	TOF years	
Foundat	ion						
TUIIuai	Foundation - Concrete	Entire Building	792	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	90,864	SF	7 7	10+ years	
	Superstructure - Steel with Clay The Arch	Entire Building	90,004	SF	1	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	18	EA	7	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	East Roof	2	EA	7	10+ years	
	Coping - Stone	East Roof	233	LF	5	10+ years	
	Downspouts - Exterior Downspouts	East Roof	27	LF	7	10+ years	
	Parapet - 16" - 30" Height	East Roof	239	LF	4	0-1 year	Tilting parapet
	Parapet - Parapet > 30"	East Roof	239	LF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	East Roof	8,636	SF	6	2-5 years	
	Roof Hatch - Metal	East Roof	. 1	EA	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	East Roof	8,636	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	-,	ĒA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	39	LF	6	6-10 years	
	Liner				Ũ	e re youre	
	Coping - Stone	Main Roof	53	LF	5	2-5 years	
	Downspouts - Interior Downspouts	Main Roof	78	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	53	LF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	Main Roof	8,705	SF	6	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	8,705	SF	7	10+ years	
	Access Ladder - Metal	North Roof	2	ËA	7	10+ years	
	Access Ladder - Metal	North Roof	- 1	EA	7	10+ years	
	Coping - Metal	North Roof	250	LF	5	0-1 year	Rusted
	Downspouts - Exterior Downspouts	North Roof	200	LF	6	10+ years	Rusteu
	Parapet - 16" - 30" Height	North Roof	83	LF	7	•	
	Parapet - To - 30 Height Parapet - Parapet < 16" Height	North Roof		LF	7	10+ years 10+ years	
	Roof - EPDM/ Synthetic Rubber			SF		2-5 years	
		North Roof	7,317		6		
	Roof Hatch - Metal	North Roof	1	EA	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	North Roof	7,317	SF	7	10+ years	
	Coping - Stone	South Roof	22	LF	5	2-5 years	
	Coping - Terra Cotta	South Roof	22	LF	7	10+ years	
	Downspouts - Exterior Downspouts	South Roof	18	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	South Roof	22	LF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	South Roof	1,220	SF	6	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	South Roof	1,220	SF	7	10+ years	
	Access Ladder - Metal	West Roof	1	EA	7	10+ years	
	Coping - Stone	West Roof	233	LF	6	10+ years	
	Downspouts - Exterior Downspouts	West Roof	32	LF	7	10+ years	
	Parapet - 16" - 30" Height	West Roof	186	LF	7	10+ years	
	Parapet - Parapet > 30"	West Roof	47	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	West Roof	8,635	SF	6	2-5 years	
	Roof Hatch - Metal	West Roof	1	EA	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	West Roof	8,635	SF	7	10+ years	
alls							
	Canopy - Concrete/ Stucco	Entire Building	590	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	590	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	76	SF	7	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	605	LF	7	10+ years	
	Cornice - Metal Projecting	Entire Building	800	LF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	33,662	SF	7	10+ years	
	Exterior Walls - Concrete Block	Entire Building	275	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,750	SF	5	2-5 years	
	Exterior Walls - Stone-Cast	Entire Building	6,755	SF	7	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	3,155	SF	7	10+ years	
indows	3						
	Curtain wall - Louver	Entire Building	48	SF	7	10+ years	
	Curtain wall - Louver	Entire Building	80	SF	5	0-1 year	Bent louvers/rust/corrosion - straighten/scrape/paint
	Guard - Guards perforated	Entire Building	3.346	SF	7	10+ years	Survey Survey Secure
	Guard - Guards wire guard	Entire Building	24	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,179	LF	7	10+ years	
	Skylite - Glass Single-Pane	Entire Building	312	SF	7	6-10 years	
	Windows - Casement Steel	Entire Building	210	SF	5	0-1 year	Rust at mental frame/trim
	Windows - Sash Aluminum Double-pane	Entire Building	10,625	SF	7	10+ years	
atego	ry : Electrical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System		Quantity		Kunk	Replacement	Commente
nerûer	Security System - CCTV	Entire Building	90,864	SF	7	6-10 years	
					7		
	Security System - Intrusion Detection	Entire Building	90,864	SF	6	6-10 years	Location observed for elevification
	Exit Signs - Auditoium	Entire Building	14	EA	6	6-10 years	Location changed for clarification



Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments Auditorium occupies space on
							multiple floors. Quantity changed to match current observations.
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Location changed for clarification.
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	17	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	9,880	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	22,868	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2,874	SF	6	6-10 years	Location changed for clarification.
	Emergency A/C Power - Students Toilets	Entire Building	1,815	SF	6	6-10 years	
Main Se							
	PA System	Entire Building	90,864	SF	7	6-10 years	Serves Main and Addition. Rank adjusted based on system upgrade since previous assessment.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Rank, Reason and Priority Rep changed as open breaker slot exposes live conductors presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as open fuse receptacles expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Rank adjusted based on current observations.
	Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Less than 400 amp	Entire Building Entire Building	3 1	EA EA	7 7	10+ years 10+ years	Location changed for clarification.
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar							



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	Serves Main and Addition. No CPS Asset Tag present.
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	Serves Main and Addition. Rank adjusted as panel has been replaced since previous assessment.
	Fire Alarm Strobe Lights	Entire Building	90,864	SF	7	6-10 years	Rank adjusted as system has been replaced since previous assessment.
	Fire Alarm_System	Entire Building	90,864	SF	7	6-10 years	Serves Main and Addition. Rank adjusted as system has been replaced since previous assessment.

Catego	Category : Mechanical			uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Location	Quantity		IVALIK	Replacement	Comments
	Iling Systems Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 45001 - 60000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	AHU-1. Serves east and west sections of Main.
	Air Intake	Mechanical Room - AHU-1	1	EA	6	6-10 years	
	Auxiliaries - 45001 - 60000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room - AHU-1	200	LF	6	10+ years	
	Zone Dampers	Mechanical Room - AHU-1	52	EA	5	6-10 years	Location changed for clarification.
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	5	6-10 years	AHU-2, serves auditorium and associated spaces.
	Air Intake	Mechanical Room - AHU-2	1	EA	6	6-10 years	Location changed for clarification.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room - AHU-2	100	LF	6	10+ years	
Boiler Sy	/stems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room - B-1	1	EA	5	6-10 years	
	Chemical Feeder	Boiler Room - B-1	1	EA	5	6-10 years	Serves both boilers, B-1 and B-2.
	Combustion Dampers	Boiler Room - B-1	1	EA	5	6-10 years	
	Condensate Pump	Boiler Room - B-1	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room - B-1	1	EA	5	6-10 years	B-1, serves Main and Addition.
	Piping - Condensate Pipe- Steel	Boiler Room - B-1	200	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room - B-1	200	LF	5	6-10 years	
	Steam Traps	Boiler Room - B-1	25	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Rank changed as steam traps have been upgraded throughout the system since previous



Catego	ry : Mechanical		В	uilding	: Main		W Waveland AVENUE, Chicago, IL 60613
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-							assessment.
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room - B-2	1	EA	5	6-10 years	
	Pressure Boiler - 201 - 300 HP						
	Combustion Dampers	Boiler Room - B-2	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room - B-2	1	EA	5	6-10 years	Serves both B-1 and B-2.
	Feed Water Pumps and Tank	Boiler Room - B-2	1	EA	5	6-10 years	Serves both B-1 and B-2. No CPS
	Nen Candensing, Fire Tube, Castel Marine	Deiler Deere B 0	4		~	0.40	Asset Tag(s) present.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Boiler Room - B-2	1	EA	5	6-10 years	B-2, serves Main and Addition.
	Piping - Condensate Pipe- Steel	Boiler Room - B-2	200	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room - B-2	200	LF	5	6-10 years	
	Steam Traps	Boiler Room - B-2	35	EA	5	6-10 years	
	Oleani haps			LA	5		
Gas Boo	ster						
	Gas Booster	Boiler Room	2	EA	6	6-10 years	Priority Rep adjusted based on
						•	current observations and on the age
							of the equipment.
_Heating							
	Fin Tube - Steam	1st Floor	6	LF	6	6-10 years	Located in student restroom on 1st
						0.40	floor.
	Wall Heater - Electric	Entire Building	14	EA	6	6-10 years	Priority Rep adjusted based on
							current observations and on the age of the equipment.
	Wall Heater - Electric	Entire Building	2	EA	4	0-1 year	Rank, Reason and Priority Rep
		Entite Building	2	LA	4	0-i yeai	changed as units are missing front
							cover which exposes live conductors
							presenting a live front condition.
	Radiators - Steam	Entire Building	6	EA	5	6-10 years	procenting a new nem contaition.
	PTAC - Electric Heating and Self Contained	Entire Building	4	EA	6	6-10 years	Located in four office spaces.
	Cooling	5			-	,	
	-						
Tempera	ature Control						
	Pneumatic System	Entire Building	90,864	SF	5	6-10 years	Air leaks in nonmetallic sections of
				- •	~	0.40	lines.
	Thermostats - Pneumatic	Entire Building	37	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	4	EA	4	1-2 years	Thermostats are of an older design
							and are leaking, are contaminated
							with oil, and cannot be refurbished.
Ventilati	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	Quantity changed as total has been
	CFM	5			-	,	divided/aggregated.



						851	W Waveland AVENUE, Chicago, IL 60613
Catego	ry : Mechanical		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	5	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	3	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
	, · · · · · · · · · · · · · · · · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate						•	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	Rank and Priority Rep changed as unit was replaced since previous assessment. Serves Main and Addition.
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Serves Main and Addition.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	90,864	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	90,864	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	90,864	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	90,864	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	90,864	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	90,864	SF	6	6-10 years	
	Sanitary Piping	Entire Building	90,864	SF	6	6-10 years	
	Storm Piping	Entire Building	90,864	SF	6	6-10 years	
	Vent Piping	Entire Building	90,864	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	5	2-5 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	
Catego	ry : Room		R	uilding	: Main		
541090	· · · · · · · · · · · · · · · · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	1st Floor - Admin Office	385	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Admin Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Admin Office	2	EA	7	10+ years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Wood 1st Floor - Admin Office 385 SF 10+ vears 7 ΕA 7 Lighting - Pendent/Surface 1st Floor - Admin Office 6 10+ years Lighting - Pendent/Surface 1st Floor - Admin Office 1 EΑ 5 1-2 years Not working Storage/ Closet SF 7 1st Floor - Admin Office 65 10+ years SF 7 Walls - Plaster/Drywall 1st Floor - Admin Office 770 10+ years SF Ceiling - Plaster/Drywall 7 1st Floor - Main Office 385 10+ years Doors - Side-lite 1st Floor - Main Office SF 7 10+ years 9 9 SF Doors - Transom Window 1st Floor - Main Office 7 10+ years Doors - Wood Doors inclu hw 1st Floor - Main Office 1 EΑ 7 10+ years SF Floor - Wood 385 7 10+ years 1st Floor - Main Office Lighting - Pendent/Surface 1st Floor - Main Office 7 ΕA 7 10+ vears Storage/ Closet 1st Floor - Main Office 130 SF 7 10+ years Walls - Plaster/Drywall 1st Floor - Main Office 770 SF 7 10+ years 7 AC Unit 2nd Floor 2 EΑ 6-10 years Ceiling - Plaster/Drywall 2nd Floor SF 7 1,094 10+ years Doors - Transom Window SF 7 2nd Floor 24 10+ years Doors - Wood Doors inclu hw ΕA 7 2nd Floor 3 10+ years SF Floor - Tile 2nd Floor 1.094 7 10+ years Lighting - Pendent/Surface 2nd Floor 15 ΕA 7 10+ vears Storage/ Closet 2nd Floor 75 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,308 SF 7 10+ years 2nd Floor - 238 7 AC Unit 1 EΑ 6-10 years Ceiling - Plaster/Drywall SF 7 2nd Floor - 238 334 10+ years Doors - Transom Window SF 2nd Floor - 238 62 7 10+ years Doors - Wood Doors inclu hw 3 ΕA 7 2nd Floor - 238 10+ years SF Floor - Tile 2nd Floor - 238 334 7 10+ vears ΕA Lighting - Pendent/Surface 2nd Floor - 238 4 7 10+ years **Power Distribution** 2nd Floor - 238 4 ΕA 7 10+ years SF Walls - Plaster/Drywall 2nd Floor - 238 618 7 10+ years AC Unit Admin Office - Assistant Principal's ΕA 7 6-10 years 1 Office Ceiling - Plaster/Drvwall Admin Office - Assistant Principal's 156 SF 7 10+ vears Office Doors - Side-lite Admin Office - Assistant Principal's SF 7 10 10+ years Office Admin Office - Assistant Principal's Doors - Wood Doors inclu hw EΑ 7 10+ years 1 Office Floor - Wood Admin Office - Assistant Principal's SF 7 156 10+ years Office Lighting - Pendent/Surface Admin Office - Assistant Principal's 3 ΕA 7 10+ years Office Admin Office - Assistant Principal's FΑ 7 Power Distribution 4 10+ years Office Walls - Plaster/Drywall Admin Office - Assistant Principal's 350 SF 7 10+ years



Catego	ry : Room		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-		Office				-	
	AC Unit	Admin Office - Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Admin Office - Principal's Office	156	SF	7	10+ years	
	Doors - Side-lite	Admin Office - Principal's Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Admin Office - Principal's Office	1	EA	7	10+ years	
	Floor - Wood	Admin Office - Principal's Office	156	SF	7	10+ years	
	Lighting - Pendent/Surface	Admin Office - Principal's Office	3	EA	7	10+ years	
	Power Distribution	Admin Office - Principal's Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Admin Office - Principal's Office	550	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Engineer's Office	378	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	Basement - Engineer's Office	378	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - Engineer's Office	4	EA	7	10+ years	
	Power Distribution	Basement - Engineer's Office	4	EA	7	10+ years	
	Walls - Masonry	Basement - Engineer's Office	434	SF	6	10+ years	
	Walls - Metal Panel	Basement - Engineer's Office	300	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym Office - 231	139	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym Office - 231	1	EA	7	10+ years	
	Floor - Tile	Gym Office - 231	131	SF	7	10+ years	
	Floor - Tile	Gym Office - 231	8	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	Gym Office - 231	3	EA	7	10+ years	
	Power Distribution	Gym Office - 231	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym Office - 231	160	SF	6	10+ years	
	Ceiling - Lay-in	Kitchen Manager's Office	102	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Manager's Office	1	EA	7	10+ years	
	Floor - Tile/Sheet	Kitchen Manager's Office	102	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Manager's Office	2	EA	7	10+ years	
	Power Distribution	Kitchen Manager's Office	4	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Manager's Office	117	SF	7	10+ years	
	AC Unit	Main Office - Counselor's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office - Counselor's Office	156	SF	7	10+ years	
	Doors - Side-lite	Main Office - Counselor's Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office - Counselor's Office	1	EA	7	10+ years	
	Floor - Wood	Main Office - Counselor's Office	156	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office - Counselor's Office	3	EA	7	10+ years	
	Power Distribution	Main Office - Counselor's Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office - Counselor's Office	550	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office - Counselor's Office	2	SF	5	1-2 years	Damaged wall from door
	AC Unit	Main Office - Support Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office - Support Office	156	SF	7	10+ years	
	Doors - Side-lite	Main Office - Support Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office - Support Office	1	EA	7	10+ years	
	Floor - Wood	Main Office - Support Office	156	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office - Support Office	3	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main			
	,			J		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Power Distribution	Main Office - Support Office	2	EA	7	10+ years		
	Walls - Plaster/Drywall	Main Office - Support Office	350	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Teacher's Lounge - 230	895	SF	7	10+ years		
	Doors - Transom Window	Teacher's Lounge - 230	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Teacher's Lounge - 230	3	EA	7	10+ years		
	Floor - Tile	Teacher's Lounge - 230	895	SF	7	10+ years		
	Lighting - Pendent/Surface	Teacher's Lounge - 230	18	EA	7	10+ years		
	Power Distribution	Teacher's Lounge - 230	8	EA	7	10+ years		
	Walls - Plaster/Drywall	Teacher's Lounge - 230	1,029	SF	7	10+ years		
	Work SInk	Teacher's Lounge - 230	1	EA	7	10+ years		
Auditoriu	ım & Theater							
	Balcony Seating	Room 135	200	EA	7	10+ years		
	Ceiling - Plaster/Drywall	Room 135	7,986	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Room 135	16	EA	7	10+ years		
	Floor - Wood	Room 135	7,951	SF	7	10+ years		
	Floor - Wood	Room 135	35	SF	4	1-2 years	Random areas of damaged floor	
	Lighting - Metal Halide/ High Pressure	Room 135	27	EA	5	1-2 years	Lights may be exhausted took seve	
	Sodium			_ / `	Ũ	1 2 youro	minutes for lights to warm up	
	Lighting - Metal Halide/Sodium Vapor	Room 135	21	EA	7	10+ years	minuted for lights to warm up	
	Lighting - Pendent/Surface	Room 135	10	EA	7	10+ years		
	Lighting - Wall Mounted	Room 135	12	EA	7	10+ years		
	Main Floor Seating	Room 135	590	EA	7	10+ years		
	Sound System	Room 135	1	EA	7	10+ years		
	Stage	Room 135	876	SF	7	10+ years		
	Stage Curtain	Room 135	8	EA	7	10+ years		
	Stage Lighting System	Room 135	2	EA	7	10+ years		
	Stage-Stairs - Wood	Room 135	40	LF	7	10+ years		
	Stairs - Asphalt	Room 135	40 96	LF	7	10+ years		
	Walls - Plaster/Drywall	Room 135	9,184	SF	7	10+ years		
		K00III 135	9,104	5	1	10+ years		
Gymnas	ia Ceiling - Plaster/Drywall	2nd Floor	3,012	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor		SF			Water demogra	
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	10 12	SF	4	0-1 year	Water damage Cracked	
	Doors - Transom Window	2nd Floor	40	SF	4 7	0-1 year	CIACKEU	
				EA		10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	4		7	10+ years		
	Floor - Wood	2nd Floor	3,034	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	10+ years		
	Scoreboards	2nd Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	3,449	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	40	SF	4	0-1 year	Damaged	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Kitchen							
	Ceiling - Lay-in	Room 105	1,343	SF	7	10+ years	
	Doors - Steel Doors incl hw	Room 105	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Room 105	1	EA	7	10+ years	
	Floor - Tile/Sheet	Room 105	1,333	SF	7	10+ years	
	Floor - Tile/Sheet	Room 105	10	SF	4	1-2 years	Floor separating
	Lighting - Lay-in	Room 105	15	EA	7	10+ years	
	Storage/ Closet	Room 105	262	SF	7	10+ years	
	Walls - Concrete Block	Room 105	772	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 105	772	SF	7	10+ years	
Library							
	AC Unit	3rd Floor	4	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,450	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Carpet	3rd Floor	1,450	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	28	EA	7	10+ years	
	Storage/ Closet	3rd Floor	104	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,382	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	6	10+ years	
MDF ID	F						
_	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	
	Finishes	3rd Floor	369	SF	7	10+ years	
	Window AC Unit	3rd Floor	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	4	SF	7	6-10 years	
	Janitor's Closet	1st Floor	4	SF	5	6-10 years	
	Storage Room	1st Floor	97	SF	5	6-10 years	
	Storage Room	1st Floor	127	SF	5	6-10 years	
	Mechanical/ Service Rooms	2nd Floor	54	SF	5	10+ years	
	Storage Room	2nd Floor	267	SF	7	10+ years	
	Storage Room	2nd Floor	30	SF	4	0-1 year	Water damage
	Mechanical/ Service Rooms	3rd Floor	55	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	55	SF	5	10+ years	
	Storage Room	3rd Floor	108	SF	5	10+ years	
	Boiler Room	Basement	1,574	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	518	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	548	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	430	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	150	SF	5	1-2 years	Damaged brick wall



Catego	Category : Room		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	Basement	81	SF	7	10+ years	
estroor	n						
	Accessories	1.5 staff RR G	67	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1.5 staff RR G	57	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1.5 staff RR G	10	SF	5	1-2 years	Damaged plaster ceiling
	Doors - Wood Doors inclu hw	1.5 staff RR G	1	EA	6	6-10 years	3 F
	Floor - Tile	1.5 staff RR G	64	SF	7	10+ years	
	Floor - Tile	1.5 staff RR G	3	SF	4	1-2 years	Damaged around water closet
	Lavatory	1.5 staff RR G	1	EA	7	10+ years	Bainagea aleana Mater elecet
	Lighting - Pendent/Surface	1.5 staff RR G	2	EA	7	6-10 years	
	Partitions	1.5 staff RR G	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1.5 staff RR G	120	SF	7	10+ years	
	Water Closet	1.5 staff RR G	120	EA	7	10+ years	
	Accessories	1st Floor	260	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	260	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	258	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	200	SF	4	•	Domogod tilo
	Floor Drain	1st Floor	2	EA	4 7	1-2 years	Damaged tile
						10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	10+ years	
	Partitions	1st Floor	3	EA	7	10+ years	
	Urinals	1st Floor	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	245	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	200	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	254	SF	7	10+ years	
	Water Closet	1st Floor	3	EA	7	10+ years	
	Accessories	1st Floor	260	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	235	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	25	SF	5	1-2 years	Peeling water damaged ceiling
	Floor - Tile Ceramic/ Porcelain	1st Floor	260	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	10+ years	
	Partitions	1st Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	161	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	300	SF	7	10+ years	
	Water Closet	1st Floor	10	EA	7	10+ years	
	Accessories	1st Floor - Men	115	SF	7	6-10 years	Updated quantity
	Ceiling - Exposed	1st Floor - Men	115	SF	7	10+ years	Updated quantity
	Doors - Wood Doors inclu hw	1st Floor - Men	1	EA	7	10+ years	,
	Floor - Tile	1st Floor - Men	115	SF	7	10+ years	Updated quantity
	Lavatory	1st Floor - Men	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men	2	EA	7	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Partitions 1st Floor - Men ΕA 10+ vears 7 1 ΕA 7 Urinals 1st Floor - Men 1 10+ years Walls - Concrete Block 1st Floor - Men 25 SF 7 10+ years SF 7 Walls - Plaster/Drywall 1st Floor - Men 152 10+ years Updated quantity SF 5 Walls - Plaster/Drywall 1st Floor - Men 35 1-2 years Cracked plaster 7 ΕA Water Closet 1st Floor - Men 1 10+ years Accessories 1st Floor - Women 125 SF 7 6-10 years Updated quantity SF Ceiling - Exposed 1st Floor - Women 125 7 10+ years Doors - Wood Doors inclu hw 1st Floor - Women 1 EΑ 7 10+ years SF Updated quantity Floor - Tile 1st Floor - Women 123 7 10+ years SF Floor - Tile 1st Floor - Women 2 4 1-2 vears Damaged. Lavatory 1st Floor - Women 1 EΑ 7 10+ years Lighting - Pendent/Surface 1st Floor - Women 3 ΕA 7 10+ years 2 ΕA 7 Partitions 1st Floor - Women 10+ years Walls - Plaster/Drywall 177 SF 7 1st Floor - Women 10+ years Updated quantity Water Closet 2 FΑ 7 1st Floor - Women 10+ years 335 SF 7 Accessories 2nd Floor 6-10 years SF Ceiling - Plaster/Drywall 2nd Floor 335 6 10+ years Floor - Tile Ceramic/ Porcelain SF 2nd Floor 335 7 10+ vears Floor Drain 2nd Floor 1 EΑ 7 10+ years Lavatorv 2nd Floor 3 ΕA 7 10+ years Lighting - Pendent/Surface 7 2nd Floor 4 EΑ 10+ years 5 ΕA 7 Partitions 2nd Floor 10+ years SF 7 Walls - Plaster/Drywall 2nd Floor 195 10+ years Walls - Structural Glazed Tile 200 SF 7 2nd Floor 10+ years Walls - Structural Glazed Tile SF 2nd Floor 233 7 10+ vears ΕA Water Closet 2nd Floor 5 7 10+ years 2nd Floor 329 SF 7 6-10 years Accessories Ceiling - Plaster/Drywall SF 2nd Floor 329 6 6-10 years Floor - Tile Ceramic/ Porcelain 2nd Floor 320 SF 7 10+ years SF Floor - Tile Ceramic/ Porcelain 2nd Floor 9 4 0-1 vear Missing Floor Drain 2nd Floor 1 ΕA 7 10+ vears 3 7 2nd Floor FΑ 10+ years Lavatory Lighting - Pendent/Surface 2nd Floor 5 FΑ 7 10+ years 2 Partitions 7 2nd Floor ΕA 10+ years ΕA 7 Urinals 2nd Floor 4 10+ years SF Walls - Plaster/Drywall 2nd Floor 245 7 10+ years Walls - Structural Glazed Tile SF 7 2nd Floor 200 10+ years SF Walls - Structural Glazed Tile 2nd Floor 354 7 10+ years Water Closet ΕA 2nd Floor 2 7 10+ vears SF Accessories 2nd Floor - Next to Gym 260 7 6-10 years 2nd Floor - Next to Gvm SF Ceiling - Plaster/Drywall 260 6 10+ vears peelina Floor - Tile Ceramic/ Porcelain 2nd Floor - Next to Gym 260 SF 6 10+ years Floor Drain 2nd Floor - Next to Gym ΕA 7 1 10+ years



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments 2nd Floor - Next to Gvm Lavatorv 2 ΕA 10+ vears 7 Lighting - Pendent/Surface 2nd Floor - Next to Gvm 5 ΕA 7 10+ years Partitions 2nd Floor - Next to Gvm 6 FΑ 7 10+ years 2nd Floor - Next to Gym SF 7 Walls - Masonry 200 10+ years SF Walls - Plaster/Drywall 2nd Floor - Next to Gym 215 7 10+ years SF Walls - Plaster/Drywall 2nd Floor - Next to Gym 20 6 10+ years Walls - Plaster/Drywall 2nd Floor - Next to Gym SF 5 0-1 year 10 Water damage SF 7 Walls - Structural Glazed Tile 2nd Floor - Next to Gym 254 10+ years Water Closet 2nd Floor - Next to Gym 6 EΑ 7 10+ years SF Accessories 2nd Floor - Office 58 7 6-10 years Ceiling - Plaster/Drvwall SF 2nd Floor - Office 48 7 10+ vears Ceiling - Plaster/Drywall 2nd Floor - Office 10 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor - Office ΕA 7 10+ years 1 Floor - Tile SF 2nd Floor - Office 58 6 10+ years 2nd Floor - Office ΕA Lavatory 1 6 10+ years Lighting - Pendent/Surface FΑ 7 2nd Floor - Office 1 10+ years 7 Partitions 2nd Floor - Office 1 EΑ 10+ vears Walls - Plaster/Drywall 2nd Floor - Office 100 SF 7 10+ years Walls - Plaster/Drvwall SF 2nd Floor - Office 10 6 10+ vears Water Closet 2nd Floor - Office 1 EΑ 7 10+ years Accessories 3rd Floor 329 SF 7 6-10 years SF Ceiling - Plaster/Drywall 3rd Floor 329 5 1-2 years Damaged. SF 7 Floor - Tile Ceramic/ Porcelain 3rd Floor 323 10+ years SF Floor - Tile Ceramic/ Porcelain 3rd Floor 6 4 0-1 year Broken Floor Drain 1 ΕA 7 10+ years 3rd Floor Lavatorv 3rd Floor 3 FΑ 7 10+ vears Lighting - Pendent/Surface 3rd Floor 4 ΕA 7 10+ years Partitions 3rd Floor 2 ΕA 7 10+ years ΕA Urinals 3rd Floor 4 7 10+ years Walls - Plaster/Drywall 3rd Floor 245 SF 7 10+ years Walls - Structural Glazed Tile SF 3rd Floor 200 7 10+ vears SF Walls - Structural Glazed Tile 3rd Floor 354 7 10+ vears 2 FΑ 7 Water Closet 3rd Floor 6-10 years Accessories 3rd Floor 335 SF 7 6-10 years Ceiling - Plaster/Drywall SF 7 3rd Floor 335 10+ years Floor - Tile Ceramic/ Porcelain 333 SF 7 3rd Floor 10+ years SF Floor - Tile Ceramic/ Porcelain 3rd Floor 2 4 1-2 years Broken 3 ΕA 7 3rd Floor 10+ years Lavatory Lighting - Pendent/Surface 3rd Floor 4 ΕA 7 10+ years 5 ΕA Partitions 3rd Floor 7 10+ vears SF Walls - Plaster/Drywall 3rd Floor 193 7 10+ years Walls - Structural Glazed Tile SF 7 3rd Floor 193 10+ vears Water Closet 3rd Floor 5 EΑ 7 10+ years SF 7 Accessories Floor 2.5 67 6-10 years



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drywall Floor 2.5 57 SF 10+ vears 7 Ceiling - Plaster/Drywall Floor 2.5 SF 5 0-1 year 10 Water damage Doors - Wood Doors inclu hw Floor 2.5 1 EΑ 6 10+ years Floor - Tile Floor 2.5 59 SF 7 10+ years SF Floor - Tile Floor 2.5 8 4 0-1 year Chipped Floor 2.5 ΕA 7 Lavatory 1 10+ years Lighting - Pendent/Surface Floor 2.5 2 ΕA 7 10+ years Partitions Floor 2.5 1 ΕA 7 10+ years SF Walls - Plaster/Drywall Floor 2.5 120 6 10+ years ΕA Water Closet Floor 2.5 7 10+ years 1 Accessories In Kitchen Area 54 SF 7 6-10 years Ceiling - Lay-in In Kitchen Area 54 SF 7 10+ years Doors - Steel Doors incl hw 1 ΕA 7 10+ years In Kitchen Area SF 7 Floor - Tile/Sheet In Kitchen Area 54 10+ years Floor Drain ΕA 7 In Kitchen Area 1 10+ years FΑ 7 Lavatory In Kitchen Area 1 10+ years 7 Lighting - Lay-in In Kitchen Area 1 ΕA 10+ years SF Walls - Plaster/Drywall In Kitchen Area 29 7 10+ years Walls - Plaster/Drywall 2 SF In Kitchen Area 5 1-2 vears Hole in wall Walls - Tile Ceramic/ Porcelain SF In Kitchen Area 31 6 10+ years Water Closet In Kitchen Area 1 ΕA 7 10+ years SF 7 Accessories In Room 111 & 112 81 6-10 years SF 7 Ceiling - Lay-in In Room 111 & 112 81 10+ years 7 Doors - Steel Doors incl hw In Room 111 & 112 FΑ 10+ years 1 Floor - Tile Ceramic/ Porcelain 81 SF 7 6-10 years In Room 111 & 112 Lavatorv In Room 111 & 112 1 ΕA 7 10+ vears Lighting - Lay-in In Room 111 & 112 1 ΕA 7 6-10 years Walls - Plaster/Drywall 82 SF 7 10+ years In Room 111 & 112 Walls - Tile Ceramic/ Porcelain SF In Room 111 & 112 84 7 10+ years Water Closet In Room 111 & 112 1 ΕA 7 10+ years

Category : Classroom

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #101 (Kindergarten)					-	
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	780	SF	6	10+ years	
Doors - Transom Window	1st Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Wood	1st Floor	780	SF	7	6-10 years	
Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Not working
Marker Board	1st Floor	17	LF	7	6-10 years	-
Storage/ Closet	1st Floor	110	SF	7	6-10 years	

Building : Main



Category : Classroom			В	uilding	: Main		
3	-			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Plaster/Drywall	1st Floor	910	SF	7	10+ years	
Classroc	om #104 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	780	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	6	6-10 years	
	Storage/ Closet	1st Floor	68	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	910	SF	6	10+ years	
lassroc	om #107 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	780	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	68	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	910	SF	7	10+ years	
	om #108 (Kindergarten)						
21922100	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	4 7	•	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	7	10+ years	
	Floor - Wood	1st Floor	780	SF	7	10+ years	
		1st Floor		EA	7	6-10 years	
	Lighting - Pendent/Surface		12			6-10 years	Notworking
	Lighting - Pendent/Surface	1st Floor 1st Floor	2	EA	5	1-2 years	Not working
	Marker Board		15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	720	SF	7	10+ years	
Classroc	om #109/009 (Other Instructional Use)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
					7		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	



Category : Classroom		В	uilding	: Main			
Ū						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	850	SF	7	10+ years	
Classroo	om #111 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,120	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	ĒA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	104	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,236	SF	7	10+ years	
lassroo	om #112 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,026	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,026	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	12	LA	7	6-10 years	
	Storage/ Closet	1st Floor	56	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,476	SF	7	10+ years	
	Walls - Plastel/Drywall		1,470	эг	1	10+ years	
lassroc	om #201 (Regular Classroom)	Ou d Els an				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	760	SF	7	6-10 years	
	Floor - Wood	2nd Floor	20	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	224	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	910	SF	7	10+ years	
lassroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	



	ry : Classroom		D	uilding	: wain		
	•			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	767	SF	7	10+ years	
	Floor - Wood	2nd Floor	13	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	128	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	732	SF	7	10+ years	
Classroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	780	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	720	SF	7	10+ years	
Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	780	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	880	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
Classroc	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	760	SF	7	6-10 years	
	Floor - Wood	2nd Floor	20	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
		211011001	0	SF	,	101 yours	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassror	om #206 (Dance Room)						
21003100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LA	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	,	
	Floor - Wood Doors Inclu nw	2nd Floor		SF	7	10+ years	
			765		-	6-10 years	Chinned
	Floor - Wood	2nd Floor	15	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Wall Mirrors	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	880	SF	7	10+ years	
lassror	om #207 (Regular Classroom)						
2.000.00	AC Units	2nd Floor	1	EA	7	6-10 years	-
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
			9	EA		,	
	Doors - Wood Doors inclu hw	2nd Floor		SF	7	10+ years	
	Floor - Wood	2nd Floor	780		7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	128	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	910	SF	7	10+ years	
Classroc	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	770	SF	7	6-10 years	
	Floor - Wood	2nd Floor	10	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	10	EA	4 6	6-10 years	Chipped
				LF	6 7		
	Marker Board	2nd Floor	16			6-10 years	
	Storage/ Closet	2nd Floor	128	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	732	SF	7	10+ years	
Classroo	om #209 (Regular Classroom)						
Classroo	om #209 (Regular Classroom) AC Units	2nd Floor	1	EA	7	6-10 years	
Classroc	AC Units	2nd Floor 2nd Floor	-			6-10 years 10+ years	
Classroo	AC Units Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
Classroo	AC Units		-				



Category : Classroom		B	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	18	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	152	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	732	SF	7	10+ years	
lassroo	m #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	9 1	EA	7	10+ years	
	Floor - Wood	2nd Floor	780	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	14				
				SF	7	6-10 years	
	Storage/ Closet	2nd Floor	128		7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	732	SF	7	10+ years	
lassroo	m #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	740	SF	7	6-10 years	
	Floor - Wood	2nd Floor	40	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	128	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	732	SF	7	10+ years	
lassroo	m #212 (Regular Classroom)						
1000100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	592	SF	7	10+ years	
	Doors - Transom Window	2nd Floor		SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	9	EA	7	10+ years 10+ years	
	Floor - Wood Doors Inclu nw	2nd Floor		SF	7		
			580			6-10 years	Chinand
	Floor - Wood	2nd Floor	12	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	11	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	48	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	534	SF	7	10+ years	
lassroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
						10+ years	



Catego	ry : Classroom		R	uilding	• Main	031	W Waveland AVENUE, Chicago, IL 60613
oalego				unung	. Mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ereup	Ceiling - Plaster/Drywall	3rd Floor	6	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	trater damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	776	SF	7	6-10 years	
	Floor - Wood	3rd Floor	4	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	6	6-10 years	
	Marker Board	3rd Floor	11	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	975	SF	7	10+ years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	7	6-10 years	
	Floor - Wood	3rd Floor	5	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	732	SF	7	10+ years	
Classroc	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	765	SF	7	6-10 years	
	Floor - Wood	3rd Floor	15	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	732	SF	7	10+ years	
lassroo	om #304 (Science)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	32	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	7	6-10 years	
	Floor - Wood	3rd Floor	20	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	880	SF	6	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
lassroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	766	SF	7	6-10 years	
	Floor - Wood	3rd Floor	14	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	880	SF	7	10+ years	
lassroo	m #306 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	7	6-10 years	
	Floor - Wood	3rd Floor	20	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	Onipped
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	880	SF	7	10+ years	
lassroo	m #309 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	9 3	EA	7	10+ years	
	Floor - Wood Doors Inclu IIW	3rd Floor		SF	7	6-10 years	
	Floor - Wood	3rd Floor	6	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	EA	4 6	6-10 years	Chipped
	Walls - Plaster/Drywall	3rd Floor 3rd Floor	750	SF	6 6	10+ years	
lassroo	m #310 (Art Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	



Category : Classroom

Recommend

							Recommend	
	Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	-	Ceiling - Plaster/Drywall	3rd Floor	780	SF	7	10+ years	
		Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
		Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
		Floor - Wood	3rd Floor	758	SF	7	6-10 years	
		Floor - Wood	3rd Floor	22	SF	4	1-2 years	Chipped
		Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
		Marker Board	3rd Floor	16	LF	7	6-10 years	
		Storage/ Closet	3rd Floor	120	SF	7	10+ years	
		Walls - Masonry	3rd Floor	155	SF	7	10+ years	
		Walls - Plaster/Drywall	3rd Floor	690	SF	7	10+ years	
		Work Sink	3rd Floor	1	EA	7	10+ years	
				•	L /(lor youro	
_	Classroo	m #311 (Music Room)						
		AC Units	3rd Floor	1	EA	7	6-10 years	
		Ceiling - Plaster/Drywall	3rd Floor	780	SF	7	10+ years	
		Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
		Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
		Floor - Wood	3rd Floor	762	SF	7	6-10 years	
		Floor - Wood	3rd Floor	18	SF	4	1-2 years	Chipped
		Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	Chipped
		Marker Board	3rd Floor	16	LF	7	6-10 years	
		Sound Panels	3rd Floor	1	EA	7	6-10 years	
		Storage/ Closet	3rd Floor	120	SF	7	10+ years	
		Walls - Plaster/Drywall	3rd Floor	732	SF	7	10+ years	
		Walls - Flaster/Drywall	51411601	152	01	'	TO+ years	
_	Classroo	m #312 (Other Instructional Use)						
		AC Units	3rd Floor	1	EA	7	6-10 years	
		Ceiling - Plaster/Drywall	3rd Floor	624	SF	7	10+ years	
		Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
		Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
		Floor - Wood	3rd Floor	620	SF	7	6-10 years	
		Floor - Wood	3rd Floor	4	SF	4	1-2 years	Chipped
		Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
		Marker Board	3rd Floor	16	LF	7	6-10 years	
		Storage/ Closet	3rd Floor	40	SF	7	10+ years	
		Walls - Plaster/Drywall	3rd Floor	628	SF	7	10+ years	
				020	•		let jeare	
-	Classroo	m #331 (Computer Lab)						
		AC Units	3rd Floor	2	EA	7	6-10 years	
		Casework	3rd Floor	8	LF	7	10+ years	
		Ceiling - Plaster/Drywall	3rd Floor	899	SF	7	10+ years	
		Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Water damage
		Doors - Transom Window	3rd Floor	9	SF	7	10+ years	

Building : Main



Catego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	900	SF	7	6-10 years	
	Floor - Tile	3rd Floor	4	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,039	SF	7	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	

Category : Interior

Catego	ry : Interior		В	uilding	: Main		
Creation	How Two	Leastion	Quentitu		Denk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	Cailing Diaster/Drawell	1st Floor	7 500	SF	7	10	
	Ceiling - Plaster/Drywall	1st Floor	7,508 4	EA	7 7	10+ years	
	Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor	-	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	7,448 60	SF	4	6-10 years	Cracked tile
	Lighting - Pendent/Surface	1st Floor	44	EA	4 7	1-2 years	Cracked life
	Walls - Plaster/Drywall	1st Floor	8,634	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	7,508	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	7,508	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	7,260	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor 2nd Floor	28	SF	4	6-10 years 1-2 years	Cracked
	Floor - Wood	2nd Floor	160	SF	5	10+ years	Clacked
	Floor - Wood	2nd Floor	60	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	44	EA	7	6-10 years	Chipped
	Walls - Plaster/Drywall	2nd Floor	8,634	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	7,508	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4,500	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	7,470	SF	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	38	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	44	EA	7	6-10 years	Ordeked
	Student Lockers - Two Tiers	3rd Floor	192	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	8,624	SF	7	10+ years	
Sofoty							
Safety	Comera Viewing Station	Entire huilding	4		7	6 10 years	
	Camera Viewing Station Security Cameras	Entire building	1	EA EA	7 7	6-10 years	
	Security Cameras	Entire building	0	EA	1	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	North	1,233	SF	7	10+ years	
	Floor - Asphalt	North	1,233	SF	7	10+ years	
	Handrails	North	435	LF	7	10+ years	
	Lighting - Lay-in	North	12	EA	7	6-10 years	



Catego	ry : Interior		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Asphalt	North	103	LF	7	10+ years	
	Walls - Plaster/Drywall	North	1,419	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North East	1,191	SF	7	10+ years	
	Floor - Asphalt	North East	1,191	SF	7	10+ years	
	Handrails	North East	372	LF	7	10+ years	
	Lighting - Lay-in	North East	12	EA	7	6-10 years	
	Stairs - Asphalt	North East	103	LF	7	10+ years	
	Walls - Plaster/Drywall	North East	1,370	SF	7	10+ years	
	Ceiling - Exposed	Southeast	800	SF	7	10+ years	
	Floor - Asphalt	Southeast	600	SF	7	10+ years	
	Handrails	Southeast	130	LF	7	10+ years	
	Lighting - Pendent/Surface	Southeast	6	EA	7	10+ years	
	Stairs - Asphalt	Southeast	448	LF	7	10+ years	
	Walls - Plaster/Drywall	Southeast	1,200	SF	7	10+ years	
/ertical (Conveyance						
	Elevator - Hydraulic Elevator	1st to 3rd floors	1	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	on		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	#5 - S	2	EA	7	10+ years	
	Exterior Doors - Side lite	#5 - S	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#5 - S	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#5 - S	36	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	#6 - W	2	EA	6	10+ years	
	Exterior Doors - Side lite	#6 - W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 - W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 - W	105	LF	4	0-1 year	Chipped/cracking
oundati	on						
	Foundation - Concrete	Entire Building	300	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	19,579	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	7	6-10 years	
Roof Sys	stem						
,	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	
	Access Ladder - Wood	Main Roof	1	EA	5	2-5 years	Cannot access wooden ladder
	Coping - Stone	Main Roof	321	LF	7	10+ years	
	Coping - Stone	Main Roof	6	LF	7	10+ years	Repaired
	Downspouts - Interior Downspouts	Main Roof	82	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	161	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	160	LF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	Main Roof	6,217	SF	6	2-5 years	
	Roof Hatch - Metal	Main Roof	1	EA	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	6,217	SF	7	10+ years	
Nalls							
	Cheek-Wall - Concrete	Entire Building	24	SF	7	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	265	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	3,360	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	234	SF	7	10+ years	
Windows	3						
	Curtain wall - Louver	Entire Building	88	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	1,086	SF	7	10+ years	
	Lintels - Steel	Entire Building	325	LF	7	10+ years	
				SF			



Catego	ry : Electrical		В	uilding	: Additi		
_			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	Serve Addition and Main. Quantity changed to match current observations.
	Security System - CCTV	Entire Building	19,579	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	19,579	SF	5	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EA	6	6-10 years	Quantity changed to match current observations. All exit signs in lunchroom are legible as required.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	5 1
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,762	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,417	SF	6	6-10 years	
Main Se							
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves Addition and Main.
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	Serves Addition and Main. Locatio changed for clarification.
	PA System	Entire Building	19,579	SF	7	6-10 years	Served by Main. Rank adjusted based on system upgrade since previous assessment.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front condition.
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	19,579	SF	7	6-10 years	Rank adjusted as system has beer replaced since previous assessme
	Fire Alarm_System	Entire Building	19,579	SF	7	6-10 years	Rank adjusted as system has beer replaced since previous assessme

replaced since previous assessment. FACP and Annunciator Panel are in



Category : Fire Protection		Building : Addition							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	item - Type	Location	Quantity		Nank	Replacement	Comments		

Category : Mechanical

Category : Mechanical			В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 8001 - 15000 cfm	AHU-3	1	EA	5	6-10 years	AHU-3, serves Addition.
	Air Intake	AHU-3	1	EA	6	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	AHU-3	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	AHU-3	4	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	AHU-3	100	LF	6	10+ years	
	Zone Dampers	AHU-3	12	EA	6	6-10 years	Location changed for clarification.
Boiler Sy	ystems						
	Piping - Condensate Pipe- Steel	Basement	400	LF	5	6-10 years	Condensate is piped back to Main.
	Piping - Steam Pipe- Steel	Basement	400	LF	5	6-10 years	Steam is piped in from Main.
	Steam Traps	Basement	10	EA	5	6-10 years	
	Vacuum Pump	Basement	1	EA	5	6-10 years	
Heating	Devices						
-	Radiators - Steam	Entire Building	3	EA	5	6-10 years	
Tempera	ature Control						
	Pneumatic System	Entire Building	19,579	SF	5	6-10 years	Served by pneumatic system in Main Air leaks in nonmetallic sections of lines.
	Thermostats - Pneumatic	Entire Building	8	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	3	EA	4	1-2 years	Rank, Reason and Priority Rep changed based on current observations that the thermostats are of an older design and are leaking, are contaminated with oil, and canno be refurbished.
Ventilatio							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	



Catego	ry : Plumbing		В	uilding	: Additi		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Electric Heater - Less than 20 KW	1st Floor	1	EA	5	6-10 years	Located in dishwasher room.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	19,579	SF	6	6-10 years	Domestic hot and cold water piped i
	Domastic Dining Hat Water from Disors to	Entiro Building	10 570	SF	6	6 10 vooro	from Main.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	19,579	эг	0	6-10 years	Domestic hot and cold water piped i from Main.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	19,579	SF	6	6-10 years	Domestic hot and cold water piped i
	(Horizontal Lines)			•	Ū		from Main.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	19,579	SF	6	6-10 years	Domestic hot and cold water piped i
	(from Risers to Fixtures)	C C					from Main.
	Sanitary Piping	Entire Building	19,579	SF	6	6-10 years	
	Storm Piping	Entire Building	19,579	SF	6	6-10 years	
	Vent Piping	Entire Building	19,579	SF	6	6-10 years	
Dumpo							
Pumps	Pumps - Ejector-Simplex	Mechanical Room	1	EA	6	6-10 years	
						,	
Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	Nurse - 327	147	SF	7	10+ years	
	Doors - Transom Window	Nurse - 327	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Nurse - 327	1	EA	7	10+ years	
	Floor - Tile	Nurse - 327	147	SF	7	10+ years	
	Lighting - Pendent/Surface	Nurse - 327	2	EA	7	10+ years	
	Power Distribution	Nurse - 327	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Nurse - 327	169	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor - Dish Room	258	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Dish Room	16	SF	4	1-2 years	Cracked ceiling tile
	Doors - Steel Doors incl hw	1st Floor - Dish Room	1	EA	7	10+ years	
			-	SF	7		
	Floor - Tile	1st Floor - Dish Room	274			10+ years	
	Lighting - Lay-in	1st Floor - Dish Room	4	EA	7	10+ years	N
	Lighting - Pendent/Surface	1st Floor - Dish Room	2	EA	5	1-2 years	Not working
	Walls - Concrete Block	1st Floor - Dish Room	502	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Dish Room	242	SF	7	10+ years	
	Multinum en Denne						
Lunch &	Multipurpose Room						



851 W Waveland AVENUE, Chicago, IL 60613 **Building : Addition** Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drywall Room 113 1.744 SF 10+ vears 7 Doors - Side-lite Room 113 8 SF 7 10+ years Doors - Steel Doors incl hw Room 113 3 EΑ 7 10+ years Doors - Transom Window Room 113 12 SF 7 10+ years 1,744 SF Floor - Tile/Sheet Room 113 7 10+ years 7 Lighting - Pendent/Surface Room 113 24 EΑ 10+ years Serving Line Room 113 18 LF 7 10+ years SF Walls - Plaster/Drywall Room 113 2.005 7 10+ years SF Ceiling - Plaster/Drywall Room 114 1.744 7 10+ years SF Doors - Side-lite Room 114 8 7 10+ years Doors - Steel Doors incl hw Room 114 3 ΕA 7 10+ vears Doors - Transom Window Room 114 12 SF 7 10+ years Floor - Tile Room 114 1,564 SF 7 10+ years SF 7 Floor - Tile Room 114 180 10+ years Lighting - Pendent/Surface Room 114 24 ΕA 7 10+ years 18 LF Serving Line Room 114 7 10+ years SF Walls - Plaster/Drywall Room 114 2.005 7 10+ years Mechanical/ Service Rooms Janitor's Closet 1st Floor 27 SF 5 10+ years SF Janitor's Closet 2nd Floor 34 5 10+ years Janitor's Closet 3rd Floor 30 SF 5 10+ vears Locked. Restroom Accessories In the nurses office 64 SF 7 6-10 years SF Ceiling - Plaster/Drywall In the nurses office 58 7 10+ years SF Ceiling - Plaster/Drywall In the nurses office 6 5 0-1 year Water damage Doors - Wood Doors inclu hw ΕA 7 In the nurses office 1 10+ years Floor - Tile Ceramic/ Porcelain In the nurses office 62 SF 7 10+ years 2 SF Floor - Tile Ceramic/ Porcelain In the nurses office 4 0-1 year Missing tiles ΕA 7 Lavatory In the nurses office 1 10+ years 2 Lighting - Pendent/Surface In the nurses office EΑ 7 10+ years Partitions 2 ΕA 7 In the nurses office 10+ years Walls - Plaster/Drywall In the nurses office 75 SF 6 10+ years Water Closet In the nurses office 2 ΕA 6 10+ years **Category : Classroom Building : Addition** Recommend

Group	Item - Type m #213 (Regular Classroom)	Location	Quantity	UOM	Rank	Replacement	Comments
_0///00	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	796	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	796	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	918	SF	7	10+ years	
loooro	m #214 (Begular Classroom)						
lassroo	om #214 (Regular Classroom)		4		7	0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	796	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	796	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	918	SF	7	10+ years	
lassror	om #215 (Regular Classroom)						
1000100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	796	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	•	
						10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA SF	7	10+ years	
	Floor - Wood		792		7	6-10 years	Obiers a d
	Floor - Wood	2nd Floor	4	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	918	SF	7	10+ years	
lassroo	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	796	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	796	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
				SF	7	-	
	Storage/ Closet	2nd Floor	24	35	1	10+ years	



Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	918	SF	7	10+ years	
laceroe	om #313 (Regular Classroom)						
1022100	AC Units	3rd Floor	1	EA	7	6.10	
			1		7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	796	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	796	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	918	SF	7	10+ years	
lassroc	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	796	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
			793	SF	7	•	
	Floor - Wood	3rd Floor		SF		6-10 years	Object and
	Floor - Wood	3rd Floor	3		4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	918	SF	7	10+ years	
lassroc	om #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	796	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years	
	Floor - Wood	3rd Floor	796	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	918	SF	7	10+ years	
laseror	om #316 (Regular Classroom)						
1033100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor		SF			
			796	SF LF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	



Catego	ry : Classroom		В	uilding	: Additie	on		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Wood	3rd Floor	796	SF	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	24	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	918	SF	7	10+ years		

Category : Interior

Catego	ry : Interior		В	uilding	: Additi	on	
	·					Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor				~-			
	Ceiling - Plaster/Drywall	1st Floor	1,630	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	58	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	2	SF	4	1-2 years	Damaged tile at door
	Floor - Tile Quarry	1st Floor	50	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,490	SF	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	30	SF	4	1-2 years	Cracked flooring
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,874	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	200	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,630	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,620	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	10	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,874	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,630	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,630	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,874	SF	7	10+ years	
Safety							
	Security Cameras	1st Floor	7	EA	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	North West	789	SF	7	10+ years	
	Floor - Terrazzo	North West	789	SF	7	10+ years	
	Handrails	North West	210	LF	7	10+ years	
	Lighting - Lay-in	North West	6	EA	7	6-10 years	
	Stairs - Terrazzo	North West	648	LF	7	10+ years	Updated quantity



851 W Waveland AVENUE, Chicago, IL 60613 **Building : Addition Category : Interior** Recommend Item - Type Quantity UOM Location **Replacement** Comments Group Rank Walls - Plaster/Drywall 10+ years North West 210 SF 7 Ceiling - Plaster/Drywall South 789 SF 7 10+ years Floor - Terrazzo SF 10+ years South 789 7 LF South 210 10+ years Handrails 7 Lighting - Lay-in 7 6-10 years South 6 ΕA Stairs - Terrazzo LF 7 10+ years Updated quantity South 648 Walls - Plaster/Drywall South 906 SF 7 10+ years



Category : Site		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Lighting	Southeast of site	2	EA	7	6-10 years	
	Surface - Asphalt	Southeast of site	6,870	SF	4	0-1 year	Large cracking throughout
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	12	EA	7	10+ years	
encina							
	Fencing - Guard Rail	Entire Site	67	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,837	LF	7	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	425	LF	4	0-1 year	Missing and broken Pieces of
						- ,	wooden fence
andsca	•	Frating Oile		F ^	-	10	
	Benches	Entire Site	8	EA	7	10+ years	
	Landscape - Grass	Entire Site	6,825	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	4,050	SF	6	10+ years	
	Parkway trees	Entire Site	24	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	5,255	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	17,550	SF	7	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
Parking I	at						
	Concrete Curbs	Parking Lot- South	815	LF	6	10+ years	
	Interior Plantings	Parking Lot- South	800	LF	6	10+ years	
	Lighting - Pole Mounted	Parking Lot- South	4	EA	7	6-10 years	
	Surface - Asphalt	Parking Lot- South	17,550	SF	4	0-1 year	Broken, cracks and crumbling
	Sunace - Aspinan	r arking Lot- South	17,550	Эг	4	0-i yeai	throughout
	Trash Compactor	Parking Lot- South	1	EA	7	6-10 years	
	Trash Enclosure - Masonry	Parking Lot- South	4,050	SF	7	10+ years	
	Vehicular Screening	Parking Lot- South	365	LF	7	10+ years	
		-				-	
Playgrou					_	10	
	Equipment - Pre K 3-5	South Courtyard	1	EA	7	10+ years	
	Equipment - School Age 5-12	South Courtyard	1	EA	7	10+ years	
	Surface - Poured Surface	South Courtyard	7,006	SF	7	10+ years	
	Surface - Poured Surface	South Courtyard	100	SF	4	0-1 year	Worn, minor cracks.
Sidewalk	(S						
	Sidewalks - Internal Walks	Entire Site	565	LF	6	10+ years	



Catego	ry : Site		Building : Site						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Sidewalks - Perimeter Sidewalks	Entire Site	9,185	SF	7	10+ years			
_Signage									
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	10+ years			
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years			
	Monument - Building Mounted Cut Letter	Entire Site	2	EA	7	10+ years			
	Sign					-			
	Monument - Sign	Entire Site	1	EA	7	10+ years			

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					(0.7		7	0.00	200.0
Art Room	Regular Classroom	3rd Floor	310	310	780	138	18	Y	N
Computer Lab	Computer Lab	3rd Floor	331	312A	904	54	20	N	Y
Dance Room	Regular Classroom	2nd Floor	206	206	780	117	48	N	N
Kindergarten	Regular Classroom	1st Floor	101	101	780	130	60	N	N
Kindergarten	Regular Classroom	1st Floor	104	104	780	138	60	N	N
Kindergarten	Regular Classroom	1st Floor	107	107	780	130	60	N	N
Kindergarten	Regular Classroom	1st Floor	108	108	780	138	60	N	N
Music Room	Regular Classroom	3rd Floor	311	311	780	138	18	Y	N
Other Instructional Use	Regular Classroom	1st Floor	109/009	109	780	72	30	N	N
Other Instructional Use	Regular Classroom	3rd Floor	312	312	624	124	48	N	N
Pre School	Pre School	1st Floor	111	110/111	1,120	138	60	N	N
Pre School	Pre School	1st Floor	112	112	1,026	72	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	780	130	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	780	138	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	780	138	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	780	138	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	780	138	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	780	130	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	780	138	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	780	138	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	780	138	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	780	138	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	592	130	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	780	117	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	780	138	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	780	138	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	780	138	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	780	117	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	800	138	18	N	N
Science	Regular Classroom	3rd Floor	304	304	780	138	60	N	Y
Building : Addition				•	•				
Regular Classroom	Regular Classroom	2nd Floor	213	213	796	144	14	Y	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	796	144	14	Y	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	796	144	14	Y	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	796	144	14	Y	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	796	144	14	Y	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	796	144	14	Y	N



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	315	315	796	144	14	Y	N
Regular Classroom	Regular Classroom	3rd Floor	316	316	796	144	75	N	Ν