

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1970	3	159,500
Campus Total			159,500

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Door 1 - West north	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 1 - West north	4	EA	6	10+ years	Changed to match current observations
	Exterior Doors - Transom Lite	Door 1 - West north	4	EA	7	10+ years	
	Power Door Operator and Controls	Door 1 - West north	1	EA	7	6-10 years	
	Exterior Doors - Exterior Stainless Steel Door	Door 10 - Pool northeast	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	Door 10 - Pool northeast	3	LF	6	10+ years	
	Exterior Doors - Exterior Stainless Steel Door	Door 11 - Pool southeast	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	Door 11 - Pool southeast	3	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 12 - Gym south 2nd floor	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 12 - Gym south 2nd floor	92	LF	6	10+ years	
	Exterior Stairs - Concrete	Door 12 - Gym south 2nd floor	8	LF	5	1-2 years	Cracking
	Exterior Doors - Exterior Steel Door	Door 2 - North	2	EA	6	6-10 years	Changed to match current observations
	Exterior Doors - Side lite	Door 2 - North	6	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 2 - North	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 3 - East north	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 3 - East north	1	EA	7	10+ years	
	Exterior Stairs - Steel or Aluminum	Door 3 - East north	3	LF	7	10+ years	
	Entrance Control - Audio and Video	Door 4 - East center	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 4 - East center	4	EA	6	10+ years	Changed to match current observations

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Doors - Transom Lite	Door 4 - East center	4	EA	6	10+ years	
	Power Door Operator and Controls	Door 4 - East center	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 5 - Southwest	2	EA	5	2-5 years	
	Exterior Doors - Side lite	Door 5 - Southwest	6	EA	5	6-10 years	
	Exterior Doors - Transom Lite	Door 5 - Southwest	1	EA	5	6-10 years	
	Exterior Doors - Overhead Rolling/ Garage Door	Door 6 - South center	1	EA	6	6-10 years	
	Exterior Doors - Side lite	Door 6 - South center	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 6 - South center	25	LF	5	0-1 year	Deteriorating/cracking
	Exterior Doors - Exterior Steel Door	Door 6.5 - Southeast	1	EA	4	0-1 year	Corroded
	Exterior Doors - Side lite	Door 6.5 - Southeast	2	EA	5	2-5 years	
	Exterior Doors - Transom Lite	Door 6.5 - Southeast	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Door 7 - West south	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 7 - West south	4	EA	6	10+ years	Changed to match current observations
	Exterior Doors - Transom Lite	Door 7 - West south	4	EA	6	10+ years	
	Power Door Operator and Controls	Door 7 - West south	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 8	2	EA	6	10+ years	
	Exterior Doors - Side lite	Door 8	6	EA	6	10+ years	Quantity changed to match current observations
	Exterior Doors - Transom Lite	Door 8	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 9 - Gym north 2nd floor	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 9 - Gym north 2nd floor	100	LF	6	6-10 years	

Foundation

Foundation - Concrete	Entire Building	1,116	LF	7	10+ years
Superstructure - Concrete	Entire Building	159,500	SF	7	10+ years

Lighting

Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	6	6-10 years
Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	6-10 years
Exterior Lighting - Wall Mounted	Entire Building	20	EA	6	6-10 years

Roof System

Access Ladder - Metal	Roof 1	2	EA	7	10+ years	
Coping - Metal	Roof 1	1,151	LF	6	10+ years	
Downspouts - Interior Downspouts	Roof 1	270	LF	6	10+ years	
Parapet - Parapet < 16" Height	Roof 1	767	LF	7	10+ years	
Parapet - Parapet > 30"	Roof 1	384	LF	6	10+ years	
Roof - Modified Bitumen	Roof 1	47,040	SF	4	0-1 year	Bubbling/open seems throughout
Roof Hatch - Metal	Roof 1	2	EA	5	10+ years	
Roof Structure - Concrete	Roof 1	47,040	SF	7	10+ years	
Access Ladder - Metal	Roof 2	1	EA	7	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Coping - Metal	Roof 2	338	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 2	24	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 2	338	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	5,045	SF	4	0-1 year	Bubbling/cracking/soft spots
	Roof Structure - Concrete	Roof 2	5,045	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	2	EA	7	10+ years	Changed to match current observations
	Chimney - Metal Flue	Roof 3	10	LF	6	10+ years	
	Coping - Metal	Roof 3	130	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	30	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 3	30	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	2,650	SF	4	1-2 years	Bubbling/open seems/soft spots throughout
	Roof Hatch - Metal	Roof 3	1	EA	5	10+ years	
	Roof Structure - Concrete	Roof 3	2,650	SF	7	10+ years	

Walls

Exterior Walls - Brick	Entire Building	50,914	SF	6	10+ years	
Exterior Walls - Brick	Entire Building	680	SF	4	0-1 year	Cracking/open joints
Exterior Walls - Brick	Entire Building	36	SF	3	0-1 year	Displaced/missing/falling

Windows

Guard - Guards perforated	Entire Building	2,908	SF	5	6-10 years	
Lintels - Steel	Entire Building	1,580	LF	6	10+ years	
Skylite - Lexan	Entire Building	1,780	SF	6	10+ years	
Skylite - Lexan	Entire Building	180	SF	5	0-1 year	Cracking
Windows - Sash Aluminum Double-pane	Entire Building	9,828	SF	6	10+ years	

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergency System							
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	159,500	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	159,500	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	36	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	4	0-1 year	Lettering worn on signs
	Exit Signs - Gym	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Pool	Entire Building	3	EA	4	1-2 years	Pool decommissioned. Not in use.
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	30,184	SF	6	6-10 years	

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Emergency A/C Power - Gym	Entire Building	4,450	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	8,595	SF	6	6-10 years	
	Emergency A/C Power - Pool	Entire Building	3,854	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,843	SF	6	6-10 years	
	Emergency Generator- Outdoor- Natural Gas - 101 - 150 KW	Site South	1	EA	6	6-10 years	
Main Service							
	PA System	Entire Building	159,500	SF	6	6-10 years	
	Main Electrical Service - 1600 A	Roof	1	EA	4	1-2 years	Corroded shell
	277/480/3PH						
	Main Electrical Service - 800 A and 277/480/3PH	Roof	8	EA	4	1-2 years	Corroded shell
	Main Electrical Service - 800 A and Less than 277/480/3PH	Roof	1	EA	4	1-2 years	Corroded shell
Power Distribution							
	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	4	0-1 year	Panel door missing
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	24	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	4	1-2 years	Panel door missing
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	4	1-2 years	Panel door missing
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	6	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	6-10 years	

Category : Fire Protection
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alarm</u>							
	Fire ALarm Anunciator	1st Floor	3	EA	7	6-10 years	
	Fire Alarm Panel	1st Floor	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	1st Floor	159,500	SF	7	6-10 years	
	Fire Alarm_System	1st Floor	159,500	SF	6	6-10 years	
	Fire Pump Controller	1st Floor	1	EA	6	6-10 years	
<u>Pump Room Assembly</u>							
	Fire Pump - 25-50 hp	Pump Room	1	EA	6	6-10 years	
	Jockey Pump	Pump Room	1	EA	6	6-10 years	
<u>Sprinkler System</u>							
	Sprinkler Heads	Entire Building	159,500	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	159,500	SF	6	6-10 years	
	Wet Sprinkler System	Entire Building	159,500	SF	6	6-10 years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Air Conditioning</u>							
	Condensing Unit- Roof Mounted - 11-20 tons	Roofs	1	EA	6	6-10 years	Serves the pool area.
	Condensing Unit- Roof Mounted - 5-10 tons	Roofs	1	EA	6	6-10 years	Serves the MDF room.
<u>Air Handling Systems</u>							
	Dehumidification Unit- Outdoor- Gas Heating- DX Cooling with Remote Mounted Compressor - 4001 - 8000 cfm	Lower Roof	1	EA	6	6-10 years	
	Dehumidification Unit- Outdoor- Gas Heating- DX Cooling with Remote Mounted Compressor - 4001 - 8000 cfm	Lower Roof	1	EA	3	0-1 year	Problem controlling the burner
	Zone Dampers	Roof	155	EA	6	6-10 years	Internal to the multi-zone RTU's. Not directly accessible in a safe manner at the time of assessment.
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-1C	1	EA	3	0-1 year	RTU-1C, 6 zones. Does not work.
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-1E	1	EA	6	6-10 years	RTU-1E, 6 zones.
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-1N	1	EA	3	0-1 year	RTU-1N, 10 zones. Compressor three is bad
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating Coils - 10 - 20 tons	Roof - RTU-1S	1	EA	3	0-1 year	RTU-1S, 1 zone. Burner actuator bad

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-1W	1	EA	6	6-10 years	RTU-1W, 6 zones
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-2C	1	EA	6	6-10 years	RTU-2C, 7 zones
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-2E	1	EA	3	0-1 year	RTU-2E, 6 zones. Contactor one not connected. May be in need of new compressor, per engineer.
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-2N	1	EA	3	0-1 year	RTU-2N, 9 zones. Contactor and compressor, number two
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-2S	1	EA	6	6-10 years	RTU-2S, 8 zones
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-2W	1	EA	3	0-1 year	RTU-2W, 6 zones. Bad compressor and contactor
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-3C	1	EA	6	6-10 years	RTU-3C, 8 zones
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 10 - 20 tons	Roof - RTU-3E	1	EA	6	6-10 years	RTU-3E, 5 zones.
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-3N	1	EA	6	6-10 years	RTU-3N, 10 zones
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-3S	1	EA	3	0-1 year	RTU-3S, 10 zones. Compressor three bad
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 10 - 20 tons	Roof - RTU-3W	1	EA	6	6-10 years	RTU-3W, 6 zones.
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-4C	1	EA	3	0-1 year	RTU-4C, 6 zones. Compressor, one, and two are bad. Burner actuator bad
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 10 - 20 tons	Roof - RTU-4E	1	EA	6	6-10 years	RTU-4E, 5 zones.
	Roof Top Unit-Single Zone-Roof Mounted-Gas Heating and DX Cooling Coil - 11 - 20 tons	Roof - RTU-4W	1	EA	6	6-10 years	RTU-4W, 6 zones.
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-5E	1	EA	6	6-10 years	RTU-5E, 6 zones
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 21 - 30 tons	Roof - RTU-5W	1	EA	6	6-10 years	RTU-5W, 6 zones
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-6E	1	EA	3	0-1 year	RTU-6E, 7 zones. In need of a new compressor
	Roof Top Unit-Multi Zone-Roof Mounted-Gas Heating and DX Cooling - 31 - 45 tons	Roof - RTU-6W	1	EA	3	0-1 year	RTU-6W, 7 zones. Low refrigerant charge

Boiler Systems

Combustion Dampers	Mechanical Room	2	EA	6	6-10 years
--------------------	-----------------	---	----	---	------------

Heating Devices

Cabinet Heaters - With Electric Coil	Entire Building	15	EA	6	6-10 years
--------------------------------------	-----------------	----	----	---	------------

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Cabinet Heaters - With Electric Coil	Entire Building	1	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	3	EA	6	6-10 years	Per engineer, and observation could only locate three units.
	Fin Tube - Electric	Entire Building	4	LF	6	6-10 years	
	Fin Tube - Electric	Entire Building	114	LF	6	6-10 years	
	Unit Heater - Electric	Mechanical Room	1	EA	6	6-10 years	

Temperature Control

	DDC System	Entire Building	159,500	SF	6	6-10 years	MDF Room
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	
	Electric Thermostat	Entire Building	4	EA	6	6-10 years	
	Electric Thermostat	Entire Building	3	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	155	EA	6	6-10 years	

Ventilation

	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	13	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	3	0-1 year	Non-operable. No power going to them. Issue is currently under investigation, per Engineer . Serves kitchen. Operational but severely rusted/corroded, old
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	4	0-1 year	
	Roof Mounted Duct Work	Entire Building	210	LF	7	6-10 years	
	Roof Mounted Duct Work	Entire Building	30	LF	7	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Gas Heater - Greater than 600000 BTU/HR	Mechanical Room	1	EA	7	10+ years	Nonoperable, out of commission. Work order was put in and has been looked at.
	Gas Heater - Greater than 600000 BTU/HR	Mechanical Room	1	EA	4	0-1 year	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Mechanical Room	1	EA	6	6-10 years	

Piping

	Domestic Piping-Hot Water Return Lines	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	159,500	SF	6	6-10 years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	159,500	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	159,500	SF	6	6-10 years	
	Sanitary Piping	Entire Building	159,500	SF	6	6-10 years	
	Storm Piping	Entire Building	159,500	SF	6	6-10 years	
	Vent Piping	Entire Building	159,500	SF	6	6-10 years	

Pool Systems

Pool Drain Piping	Basement	50	LF	4	1-2 years	Not in service
Pool Filtration System including Pump	Basement	1	EA	4	1-2 years	Not in service
Pool Hot Water Heater - Gas Fired	Basement	1	EA	6	1-2 years	Not in service
Pool Supply and Return Piping	Basement	100	LF	4	1-2 years	Not in service

Pumps

Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	7	6-10 years	
Pumps - Ejector-Duplex	Entire Building	1	EA	6	2-5 years	
Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Located at the bottom of the elevator pit.

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administrative Suites/Offices							
	Ceiling - Lay-in	108C Auditorium Support	124	SF	5	1-2 years	All tiles damaged
	Doors - Transom Window	108C Auditorium Support	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	108C Auditorium Support	1	EA	6	10+ years	
	Floor - Tile	108C Auditorium Support	124	SF	6	10+ years	
	Lighting - Lay-in	108C Auditorium Support	2	EA	7	6-10 years	
	Lighting - Lay-in	108C Auditorium Support	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	108C Auditorium Support	1	EA	6	6-10 years	
	Power Distribution	108C Auditorium Support	6	EA	7	10+ years	
	Storage/ Closet	108C Auditorium Support	98	SF	5	10+ years	
	Walls - Concrete Block	108C Auditorium Support	275	SF	6	10+ years	
	Ceiling - Lay-in	180B - Dressing Rm Off Stage	124	SF	6	2-5 years	
	Doors - Transom Window	180B - Dressing Rm Off Stage	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	180B - Dressing Rm Off Stage	1	EA	6	10+ years	
	Floor - Tile	180B - Dressing Rm Off Stage	124	SF	6	10+ years	
	Lighting - Lay-in	180B - Dressing Rm Off Stage	3	EA	7	6-10 years	
	Power Distribution	180B - Dressing Rm Off Stage	6	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	180B - Dressing Rm Off Stage	98	SF	5	10+ years	
	Walls - Concrete Block	180B - Dressing Rm Off Stage	275	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr- Asst Principal in Main Office (Director of Operations)	135	SF	6	10+ years	
	Doors - Transom Window	1st Flr- Asst Principal in Main Office (Director of Operations)	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr- Asst Principal in Main Office (Director of Operations)	1	EA	6	10+ years	
	Floor - Tile	1st Flr- Asst Principal in Main Office (Director of Operations)	135	SF	6	10+ years	
	Lighting - Lay-in	1st Flr- Asst Principal in Main Office (Director of Operations)	3	EA	6	6-10 years	
	Power Distribution	1st Flr- Asst Principal in Main Office (Director of Operations)	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr- Asst Principal in Main Office (Director of Operations)	226	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr- Main Office	568	SF	5	2-5 years	
	Ceiling - Lay-in	1st Flr- Main Office	18	SF	4	0-1 year	Damaged tiles
	Doors - Side-lite	1st Flr- Main Office	100	SF	6	10+ years	
	Doors - Transom Window	1st Flr- Main Office	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr- Main Office	2	EA	6	10+ years	
	Floor - Tile	1st Flr- Main Office	586	SF	6	10+ years	
	Lighting - Lay-in	1st Flr- Main Office	12	EA	7	6-10 years	
	Power Distribution	1st Flr- Main Office	18	EA	7	10+ years	
	Storage/ Closet	1st Flr- Main Office	4	SF	5	10+ years	
	Storage/ Closet	1st Flr- Main Office	101	SF	5	10+ years	
	Storage/ Closet	1st Flr- Main Office	27	SF	5	10+ years	
	Walls - Masonry	1st Flr- Main Office	242	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Flr- Main Office	728	SF	6	10+ years	
	Ceiling - Lay-in	1st Flr- Operations manager in Main Office	127	SF	5	2-5 years	
	Ceiling - Lay-in	1st Flr- Operations manager in Main Office	8	SF	4	0-1 year	Water damaged
	Doors - Transom Window	1st Flr- Operations manager in Main Office	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr- Operations manager in Main Office	1	EA	6	10+ years	
	Floor - Tile	1st Flr- Operations manager in Main Office	135	SF	6	10+ years	
	Lighting - Lay-in	1st Flr- Operations manager in Main Office	3	EA	6	6-10 years	
	Power Distribution	1st Flr- Operations manager in Main Office	9	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr- Operations manager in Main	226	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Office					
	Ceiling - Lay-in	1st Flr- Principal Office in Main	212	SF	5	2-5 years	
		Office (Operation Manager)					
	Ceiling - Lay-in	1st Flr- Principal Office in Main	12	SF	4	0-1 year	Water damage
		Office (Operation Manager)					
	Doors - Transom Window	1st Flr- Principal Office in Main	21	SF	6	10+ years	
		Office (Operation Manager)					
	Doors - Wood Doors inclu hw	1st Flr- Principal Office in Main	4	EA	6	10+ years	
		Office (Operation Manager)					
	Floor - Tile	1st Flr- Principal Office in Main	224	SF	6	10+ years	
		Office (Operation Manager)					
	Lighting - Lay-in	1st Flr- Principal Office in Main	5	EA	7	6-10 years	
		Office (Operation Manager)					
	Power Distribution	1st Flr- Principal Office in Main	8	EA	7	10+ years	
		Office (Operation Manager)					
	Storage/ Closet	1st Flr- Principal Office in Main	94	SF	7	10+ years	
		Office (Operation Manager)					
	Walls - Plaster/Drywall	1st Flr- Principal Office in Main	448	SF	6	10+ years	
		Office (Operation Manager)					
	Ceiling - Lay-in	1st floor Assistant Eng. office	83	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor Assistant Eng. office	20	SF	4	1-2 years	Missing or damaged tiles
	Doors - Wood Doors inclu hw	1st floor Assistant Eng. office	1	EA	6	10+ years	
	Floor - Tile	1st floor Assistant Eng. office	103	SF	6	10+ years	
	Lighting - Lay-in	1st floor Assistant Eng. office	2	EA	6	6-10 years	
	Power Distribution	1st floor Assistant Eng. office	4	EA	7	10+ years	
	Walls - Concrete Block	1st floor Assistant Eng. office	240	SF	6	10+ years	
	Ceiling - Lay-in	1st floor Chief engineer office	136	SF	6	10+ years	
	Ceiling - Lay-in	1st floor Chief engineer office	4	SF	4	0-1 year	Damaged tiles
	Doors - Transom Window	1st floor Chief engineer office	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor Chief engineer office	2	EA	6	10+ years	
	Floor - Carpet	1st floor Chief engineer office	140	SF	6	6-10 years	
	Lighting - Lay-in	1st floor Chief engineer office	1	EA	7	6-10 years	
	Lighting - Lay-in	1st floor Chief engineer office	1	EA	6	6-10 years	
	Lighting - Lay-in	1st floor Chief engineer office	1	EA	5	0-1 year	Missing cover
	Power Distribution	1st floor Chief engineer office	4	EA	7	10+ years	
	Walls - Concrete Block	1st floor Chief engineer office	280	SF	6	10+ years	
	Ceiling - Lay-in	1st floor custodian's office	196	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor custodian's office	24	SF	4	1-2 years	Water damage
	Doors - Transom Window	1st floor custodian's office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor custodian's office	1	EA	6	10+ years	
	Floor - Tile	1st floor custodian's office	220	SF	6	10+ years	
	Lighting - Lay-in	1st floor custodian's office	3	EA	7	6-10 years	
	Power Distribution	1st floor custodian's office	4	EA	7	10+ years	
	Walls - Concrete Block	1st floor custodian's office	440	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	345 Office	243	SF	6	10+ years	
	Doors - Steel Doors incl hw	345 Office	1	EA	6	10+ years	
	Floor - Carpet	345 Office	243	SF	7	10+ years	
	Lighting - Pendent/Surface	345 Office	2	EA	7	6-10 years	
	Power Distribution	345 Office	4	EA	7	10+ years	
	Walls - Concrete Block	345 Office	523	SF	7	10+ years	
	Walls - Plaster/Drywall	345 Office	100	SF	6	10+ years	
	Ceiling - Lay-in	Gym office A	80	SF	6	10+ years	
	Ceiling - Lay-in	Gym office A	10	SF	4	0-1 year	Missing tiles
	Doors - Wood Doors inclu hw	Gym office A	1	EA	6	10+ years	
	Floor - Tile	Gym office A	90	SF	6	10+ years	
	Lighting - Lay-in	Gym office A	3	EA	7	6-10 years	
	Power Distribution	Gym office A	6	EA	6	10+ years	
	Walls - Concrete Block	Gym office A	180	SF	6	10+ years	
	Ceiling - Lay-in	Gym office B	75	SF	6	10+ years	
	Ceiling - Lay-in	Gym office B	15	SF	4	0-1 year	Missing and damaged
	Doors - Wood Doors inclu hw	Gym office B	1	EA	6	10+ years	
	Floor - Tile	Gym office B	90	SF	6	10+ years	
	Lighting - Lay-in	Gym office B	3	EA	7	6-10 years	
	Power Distribution	Gym office B	6	EA	6	10+ years	
	Walls - Concrete Block	Gym office B	165	SF	6	10+ years	
	Walls - Concrete Block	Gym office B	15	SF	4	0-1 year	Missing cmu
	Ceiling - Lay-in	Librarian Occupational Therapist	120	SF	6	6-10 years	
	Ceiling - Lay-in	Librarian Occupational Therapist	6	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	Librarian Occupational Therapist	1	EA	7	6-10 years	
	Floor - Carpet	Librarian Occupational Therapist	126	SF	6	6-10 years	
	Lighting - Lay-in	Librarian Occupational Therapist	3	EA	7	6-10 years	
	Power Distribution	Librarian Occupational Therapist	6	EA	7	6-10 years	
	Walls - Concrete Block	Librarian Occupational Therapist	80	SF	7	10+ years	
	Walls - Masonry	Librarian Occupational Therapist	80	SF	6	10+ years	
	Walls - Metal Panel	Librarian Occupational Therapist	80	SF	7	10+ years	
	Ceiling - Lay-in	Library Multilingual	122	SF	6	10+ years	
	Ceiling - Lay-in	Library Multilingual	5	SF	4	1-2 years	Loose tile
	Ceiling - Lay-in	Library Multilingual	5	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	Library Multilingual	1	EA	6	10+ years	
	Floor - Carpet	Library Multilingual	132	SF	6	6-10 years	
	Lighting - Lay-in	Library Multilingual	2	EA	7	6-10 years	
	Power Distribution	Library Multilingual	6	EA	7	10+ years	
	Walls - Concrete Block	Library Multilingual	80	SF	6	10+ years	
	Walls - Masonry	Library Multilingual	120	SF	6	10+ years	
	Walls - Plaster/Drywall	Library Multilingual	80	SF	6	10+ years	
	Ceiling - Lay-in	Library Nurse Office	340	SF	6	10+ years	
	Ceiling - Lay-in	Library Nurse Office	12	SF	4	0-1 year	Damaged.
	Doors - Steel Doors incl hw	Library Nurse Office	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Transom Window	Library Nurse Office	9	SF	6	10+ years	
	Floor - Tile	Library Nurse Office	352	SF	6	10+ years	
	Lighting - Lay-in	Library Nurse Office	8	EA	6	6-10 years	
	Power Distribution	Library Nurse Office	10	EA	7	10+ years	
	Walls - Concrete Block	Library Nurse Office	480	SF	6	10+ years	
	Work Sink	Library Nurse Office	1	EA	7	10+ years	
	Ceiling - Lay-in	Library Speech Therapist	195	SF	6	10+ years	
	Ceiling - Lay-in	Library Speech Therapist	5	SF	4	1-2 years	Water damage
	Doors - Side-lite	Library Speech Therapist	100	SF	6	10+ years	
	Doors - Steel Doors incl hw	Library Speech Therapist	1	EA	6	10+ years	
	Doors - Transom Window	Library Speech Therapist	12	SF	6	10+ years	
	Floor - Carpet	Library Speech Therapist	200	SF	6	6-10 years	
	Lighting - Lay-in	Library Speech Therapist	5	EA	7	6-10 years	
	Power Distribution	Library Speech Therapist	12	EA	7	10+ years	
	Walls - Concrete Block	Library Speech Therapist	120	SF	6	10+ years	
	Walls - Plaster/Drywall	Library Speech Therapist	200	SF	6	10+ years	
	Ceiling - Lay-in	RM 308A - Community Office	238	SF	6	10+ years	
	Doors - Side-lite	RM 308A - Community Office	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	RM 308A - Community Office	1	EA	6	10+ years	
	Doors - Transom Window	RM 308A - Community Office	9	SF	6	10+ years	
	Floor - Tile	RM 308A - Community Office	238	SF	6	10+ years	
	Lighting - Lay-in	RM 308A - Community Office	2	EA	7	6-10 years	
	Power Distribution	RM 308A - Community Office	8	EA	7	10+ years	
	Walls - Concrete Block	RM 308A - Community Office	340	SF	6	10+ years	
	Walls - Metal Panel	RM 308A - Community Office	110	SF	6	10+ years	
	Ceiling - Lay-in	RM 331 Assistant Principals Office	180	SF	6	10+ years	
	Doors - Steel Doors incl hw	RM 331 Assistant Principals Office	1	EA	6	10+ years	
	Floor - Tile	RM 331 Assistant Principals Office	180	SF	6	10+ years	
	Lighting - Lay-in	RM 331 Assistant Principals Office	4	EA	7	6-10 years	
	Power Distribution	RM 331 Assistant Principals Office	8	EA	7	10+ years	
	Walls - Concrete Block	RM 331 Assistant Principals Office	200	SF	6	10+ years	
	Walls - Plaster/Drywall	RM 331 Assistant Principals Office	200	SF	6	10+ years	
	Ceiling - Lay-in	Rm 100A- Attendance Office	94	SF	5	2-5 years	
	Doors - Transom Window	Rm 100A- Attendance Office	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 100A- Attendance Office	1	EA	6	10+ years	
	Floor - Tile	Rm 100A- Attendance Office	94	SF	7	10+ years	
	Lighting - Lay-in	Rm 100A- Attendance Office	1	EA	7	6-10 years	
	Lighting - Lay-in	Rm 100A- Attendance Office	1	EA	6	6-10 years	
	Power Distribution	Rm 100A- Attendance Office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 100A- Attendance Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 100A- Attendance Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 107A- CPD Office	75	SF	5	2-5 years	
	Ceiling - Lay-in	Rm 107A- CPD Office	18	SF	4	0-1 year	Damaged tiles and grid
	Doors - Side-lite	Rm 107A- CPD Office	9	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Transom Window	Rm 107A- CPD Office	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 107A- CPD Office	1	EA	6	10+ years	
	Floor - Tile	Rm 107A- CPD Office	93	SF	6	10+ years	
	Lighting - Lay-in	Rm 107A- CPD Office	2	EA	6	6-10 years	
	Power Distribution	Rm 107A- CPD Office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 107A- CPD Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 107A- CPD Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 108A- Business Manager Office	210	SF	6	2-5 years	
	Ceiling - Lay-in	Rm 108A- Business Manager Office	6	SF	4	0-1 year	Tile warping
	Doors - Side-lite	Rm 108A- Business Manager Office	9	SF	6	10+ years	
	Doors - Transom Window	Rm 108A- Business Manager Office	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 108A- Business Manager Office	1	EA	6	10+ years	
	Floor - Tile	Rm 108A- Business Manager Office	216	SF	6	10+ years	
	Lighting - Lay-in	Rm 108A- Business Manager Office	5	EA	6	6-10 years	
	Power Distribution	Rm 108A- Business Manager Office	12	EA	7	10+ years	
	Walls - Concrete Block	Rm 108A- Business Manager Office	215	SF	6	10+ years	
	Walls - Metal Panel	Rm 108A- Business Manager Office	215	SF	6	10+ years	
	Ceiling - Lay-in	Rm 137- Student Services Office	349	SF	6	10+ years	
	Doors - Transom Window	Rm 137- Student Services Office	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 137- Student Services Office	2	EA	6	10+ years	
	Floor - Carpet	Rm 137- Student Services Office	112	SF	6	6-10 years	
	Floor - Tile	Rm 137- Student Services Office	237	SF	6	10+ years	
	Lighting - Lay-in	Rm 137- Student Services Office	8	EA	7	6-10 years	
	Power Distribution	Rm 137- Student Services Office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 137- Student Services Office	565	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 137- Student Services Office	200	SF	6	10+ years	
	Ceiling - Lay-in	Rm 137A- Program Manager's office	96	SF	6	6-10 years	
	Ceiling - Lay-in	Rm 137A- Program Manager's office	24	SF	4	1-2 years	Damaged tiles
	Doors - Steel Doors incl hw	Rm 137A- Program Manager's office	1	EA	6	10+ years	
	Floor - Carpet	Rm 137A- Program Manager's office	120	SF	4	0-1 year	Torn carpet
	Lighting - Lay-in	Rm 137A- Program Manager's office	3	EA	7	6-10 years	
	Power Distribution	Rm 137A- Program Manager's office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 137A- Program Manager's office	130	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 137A- Program Manager's office	130	SF	6	10+ years	
	Ceiling - Lay-in	Rm 137B- Post Secondary office	120	SF	5	2-5 years	
	Doors - Steel Doors incl hw	Rm 137B- Post Secondary office	1	EA	6	10+ years	
	Floor - Carpet	Rm 137B- Post Secondary office	120	SF	6	6-10 years	
	Lighting - Lay-in	Rm 137B- Post Secondary office	3	EA	7	6-10 years	
	Power Distribution	Rm 137B- Post Secondary office	4	EA	7	10+ years	
	Walls - Concrete Block	Rm 137B- Post Secondary office	130	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 137B- Post Secondary office	130	SF	6	10+ years	
	Ceiling - Lay-in	Rm 137C- Counselors office	120	SF	5	2-5 years	
	Doors - Steel Doors incl hw	Rm 137C- Counselors office	1	EA	6	10+ years	
	Floor - Carpet	Rm 137C- Counselors office	120	SF	6	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Lay-in	Rm 137C- Counselors office	3	EA	7	6-10 years	
	Power Distribution	Rm 137C- Counselors office	4	EA	6	10+ years	
	Walls - Concrete Block	Rm 137C- Counselors office	130	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 137C- Counselors office	130	SF	6	10+ years	
	Ceiling - Lay-in	Rm 207- Office	88	SF	6	10+ years	
	Ceiling - Lay-in	Rm 207- Office	5	SF	4	0-1 year	Missing tile
	Doors - Side-lite	Rm 207- Office	9	SF	6	10+ years	
	Doors - Transom Window	Rm 207- Office	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 207- Office	1	EA	6	10+ years	
	Floor - Tile	Rm 207- Office	93	SF	6	10+ years	
	Lighting - Lay-in	Rm 207- Office	2	EA	7	6-10 years	
	Power Distribution	Rm 207- Office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 207- Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 207- Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 208A- Group Teacher/Student Room	216	SF	6	10+ years	
	Doors - Side-lite	Rm 208A- Group Teacher/Student Room	9	SF	6	10+ years	
	Doors - Transom Window	Rm 208A- Group Teacher/Student Room	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 208A- Group Teacher/Student Room	1	EA	6	10+ years	
	Floor - Tile	Rm 208A- Group Teacher/Student Room	216	SF	6	6-10 years	
	Lighting - Lay-in	Rm 208A- Group Teacher/Student Room	5	EA	7	6-10 years	
	Power Distribution	Rm 208A- Group Teacher/Student Room	12	EA	7	10+ years	
	Walls - Concrete Block	Rm 208A- Group Teacher/Student Room	215	SF	6	10+ years	
	Walls - Metal Panel	Rm 208A- Group Teacher/Student Room	215	SF	6	10+ years	
	Ceiling - Lay-in	Rm 221- KIPP Main Office	229	SF	6	10+ years	
	Doors - Side-lite	Rm 221- KIPP Main Office	9	SF	6	10+ years	
	Doors - Transom Window	Rm 221- KIPP Main Office	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 221- KIPP Main Office	1	EA	6	10+ years	
	Floor - Tile	Rm 221- KIPP Main Office	224	SF	6	10+ years	
	Floor - Tile	Rm 221- KIPP Main Office	5	SF	4	1-2 years	Damaged tiles
	Lighting - Lay-in	Rm 221- KIPP Main Office	6	EA	7	6-10 years	
	Power Distribution	Rm 221- KIPP Main Office	6	EA	7	10+ years	
	Storage/ Closet	Rm 221- KIPP Main Office	95	SF	7	10+ years	
	Walls - Concrete Block	Rm 221- KIPP Main Office	220	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 221- KIPP Main Office	220	SF	6	10+ years	
	Ceiling - Lay-in	Rm 221.1 - Conference Room	118	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	Rm 221.1 - Conference Room	1	EA	6	10+ years	
	Floor - Tile	Rm 221.1 - Conference Room	118	SF	6	10+ years	
	Lighting - Lay-in	Rm 221.1 - Conference Room	4	EA	7	6-10 years	
	Power Distribution	Rm 221.1 - Conference Room	18	EA	7	10+ years	
	Walls - Concrete Block	Rm 221.1 - Conference Room	113	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 221.1 - Conference Room	110	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 221.1 - Conference Room	3	SF	5	1-2 years	Drywall cracks
	Ceiling - Lay-in	Rm 221.2 - Work Room	118	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 221.2 - Work Room	1	EA	6	10+ years	
	Floor - Tile	Rm 221.2 - Work Room	118	SF	6	10+ years	
	Lighting - Lay-in	Rm 221.2 - Work Room	4	EA	7	6-10 years	
	Power Distribution	Rm 221.2 - Work Room	12	EA	7	10+ years	
	Walls - Concrete Block	Rm 221.2 - Work Room	113	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 221.2 - Work Room	110	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 221.2 - Work Room	3	SF	5	1-2 years	Drywall cracks
	Ceiling - Lay-in	Rm 228- Vacant Office	83	SF	6	10+ years	
	Ceiling - Lay-in	Rm 228- Vacant Office	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	Rm 228- Vacant Office	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	Rm 228- Vacant Office	1	EA	6	10+ years	
	Doors - Transom Window	Rm 228- Vacant Office	13	SF	6	10+ years	
	Floor - Carpet	Rm 228- Vacant Office	93	SF	6	6-10 years	
	Lighting - Lay-in	Rm 228- Vacant Office	2	EA	7	6-10 years	
	Power Distribution	Rm 228- Vacant Office	8	EA	7	10+ years	
	Walls - Concrete Block	Rm 228- Vacant Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 228- Vacant Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 231-Asst Principal Office	216	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 231-Asst Principal Office	1	EA	6	10+ years	
	Floor - Tile	Rm 231-Asst Principal Office	216	SF	6	10+ years	
	Lighting - Lay-in	Rm 231-Asst Principal Office	2	EA	7	6-10 years	
	Lighting - Lay-in	Rm 231-Asst Principal Office	2	EA	6	6-10 years	
	Power Distribution	Rm 231-Asst Principal Office	14	EA	7	10+ years	
	Walls - Concrete Block	Rm 231-Asst Principal Office	215	SF	6	10+ years	
	Walls - Metal Panel	Rm 231-Asst Principal Office	215	SF	6	10+ years	
	Ceiling - Lay-in	Rm 236	211	SF	6	10+ years	
	Ceiling - Lay-in	Rm 236	5	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	Rm 236	9	SF	6	10+ years	
	Doors - Transom Window	Rm 236	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 236	1	EA	6	10+ years	
	Floor - Tile	Rm 236	216	SF	6	10+ years	
	Lighting - Lay-in	Rm 236	5	EA	7	6-10 years	
	Power Distribution	Rm 236	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 236	215	SF	6	10+ years	
	Walls - Metal Panel	Rm 236	215	SF	6	10+ years	
	Ceiling - Lay-in	Rm 236A- Dean's Office	133	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	Rm 236A- Dean's Office	11	SF	6	10+ years	
	Doors - Steel Doors incl hw	Rm 236A- Dean's Office	1	EA	6	10+ years	
	Doors - Transom Window	Rm 236A- Dean's Office	13	SF	6	10+ years	
	Floor - Carpet	Rm 236A- Dean's Office	133	SF	6	6-10 years	
	Lighting - Lay-in	Rm 236A- Dean's Office	3	EA	7	6-10 years	
	Power Distribution	Rm 236A- Dean's Office	12	EA	6	10+ years	
	Walls - Concrete Block	Rm 236A- Dean's Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 236A- Dean's Office	113	SF	6	10+ years	
	Ceiling - Lay-in	Rm 239- Conference Rm	211	SF	6	10+ years	
	Ceiling - Lay-in	Rm 239- Conference Rm	5	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	Rm 239- Conference Rm	9	SF	6	10+ years	
	Doors - Transom Window	Rm 239- Conference Rm	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 239- Conference Rm	1	EA	6	10+ years	
	Floor - Tile	Rm 239- Conference Rm	216	SF	6	10+ years	
	Lighting - Lay-in	Rm 239- Conference Rm	4	EA	7	6-10 years	
	Power Distribution	Rm 239- Conference Rm	14	EA	7	10+ years	
	Walls - Concrete Block	Rm 239- Conference Rm	430	SF	6	10+ years	
	Ceiling - Lay-in	Rm 239A- Diverse Learner's Coordinator Office	128	SF	6	10+ years	
	Ceiling - Lay-in	Rm 239A- Diverse Learner's Coordinator Office	5	SF	4	1-2 years	Damaged tile
	Doors - Steel Doors incl hw	Rm 239A- Diverse Learner's Coordinator Office	1	EA	6	10+ years	
	Doors - Transom Window	Rm 239A- Diverse Learner's Coordinator Office	13	SF	6	10+ years	
	Floor - Tile	Rm 239A- Diverse Learner's Coordinator Office	133	SF	6	10+ years	
	Lighting - Lay-in	Rm 239A- Diverse Learner's Coordinator Office	3	EA	7	6-10 years	
	Power Distribution	Rm 239A- Diverse Learner's Coordinator Office	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 239A- Diverse Learner's Coordinator Office	113	SF	6	10+ years	
	Walls - Metal Panel	Rm 239A- Diverse Learner's Coordinator Office	113	SF	6	10+ years	
Auditorium & Theater							
	Ceiling - Plaster/Drywall	1st Floor	2,990	SF	6	10+ years	
	Floor - Carpet	1st Floor	1,475	SF	6	2-5 years	No occupancy signage
	Floor - Tile	1st Floor	1,515	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	136	EA	6	6-10 years	
	Main Floor Seating	1st Floor	160	EA	5	10+ years	
	Sound System	1st Floor	1	EA	5	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Stage	1st Floor	1	SF	6	10+ years	
	Stage Lift	1st Floor	1	EA	5	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Tile	1st Floor	5	LF	7	10+ years	
	Stairs - Wood	1st Floor	12	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	874	SF	6	10+ years	
	Walls - Masonry	1st Floor	234	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	440	SF	6	10+ years	
Clinic							
	Ceiling - Lay-in	Rm 100- Nurse	470	SF	6	2-5 years	
	Doors - Transom Window	Rm 100- Nurse	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 100- Nurse	1	EA	6	10+ years	
	Floor - Tile/Sheet	Rm 100- Nurse	470	SF	5	10+ years	
	Lighting - Lay-in	Rm 100- Nurse	11	EA	7	6-10 years	
	Walls - Concrete Block	Rm 100- Nurse	645	SF	6	10+ years	
	Walls - Metal Panel	Rm 100- Nurse	215	SF	6	10+ years	
Gymnasia							
	Ceiling - Plaster/Drywall	2nd Floor	4,400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	4	0-1 year	Large holes
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	4,450	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	24	EA	7	6-10 years	
	Scoreboards	2nd Floor	2	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	506	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	6,580	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	1,251	SF	6	10+ years	
Kitchen							
	Ceiling - Splined	1st Floor	1,710	SF	7	6-10 years	
	Ceiling - Splined	1st Floor	50	SF	4	1-2 years	Damaged tiles
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	1,760	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	20	EA	7	6-10 years	
	Serving Line	1st Floor	20	LF	6	10+ years	
	Storage/ Closet	1st Floor	270	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,700	SF	6	10+ years	
Library							
	Casework	2nd Floor	200	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	440	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	0-1 year	Water damage

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	4,490	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	60	SF	6	10+ years	
	Floor - Carpet	2nd Floor	4,870	SF	6	6-10 years	
	Floor - Carpet	2nd Floor	25	SF	4	0-1 year	Torn
	Floor - Tile	2nd Floor	45	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	113	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	283	SF	5	0-1 year	Water damage throughout ceiling
	Walls - Concrete Block	2nd Floor	1,150	SF	6	10+ years	
	Walls - Masonry	2nd Floor	2,250	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	1,800	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	

Locker/Shower Room

Accessories	1st Floor- Pool Unisex Locker Rm	99	SF	5	6-10 years	
Benches, ped mounted	1st Floor- Pool Unisex Locker Rm	4	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor- Pool Unisex Locker Rm	99	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor- Pool Unisex Locker Rm	1	EA	6	10+ years	
Floor - Concrete Epoxy/ Painted	1st Floor- Pool Unisex Locker Rm	99	SF	5	10+ years	
Floor Drain	1st Floor- Pool Unisex Locker Rm	1	EA	7	10+ years	
Lavatory	1st Floor- Pool Unisex Locker Rm	1	EA	6	10+ years	
Lighting - Lay-in	1st Floor- Pool Unisex Locker Rm	2	EA	7	6-10 years	
Showers	1st Floor- Pool Unisex Locker Rm	1	EA	5	6-10 years	
Student Lockers - One Tier	1st Floor- Pool Unisex Locker Rm	4	EA	6	10+ years	
Walls - Structural Glazed Tile	1st Floor- Pool Unisex Locker Rm	200	SF	6	10+ years	
Walls - Tile Ceramic/ Porcelain	1st Floor- Pool Unisex Locker Rm	65	SF	6	10+ years	
Water Closet	1st Floor- Pool Unisex Locker Rm	1	EA	6	6-10 years	
Accessories	1st Flr- Pool Boys locker room	1,197	SF	7	6-10 years	
Benches, ped mounted	1st Flr- Pool Boys locker room	5	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Flr- Pool Boys locker room	1,180	SF	6	10+ years	
Ceiling - Plaster/Drywall	1st Flr- Pool Boys locker room	17	SF	4	0-1 year	Hole in ceiling
Doors - Steel Doors incl hw	1st Flr- Pool Boys locker room	3	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	1st Flr- Pool Boys locker room	1,197	SF	6	10+ years	
Floor Drain	1st Flr- Pool Boys locker room	6	EA	7	10+ years	
Lavatory	1st Flr- Pool Boys locker room	1	EA	6	10+ years	
Lighting - Lay-in	1st Flr- Pool Boys locker room	9	EA	7	6-10 years	
Lighting - Lay-in	1st Flr- Pool Boys locker room	4	EA	6	6-10 years	
Lighting - Pendent/Surface	1st Flr- Pool Boys locker room	1	EA	6	6-10 years	
Partitions	1st Flr- Pool Boys locker room	1	EA	7	10+ years	
Partitions	1st Flr- Pool Boys locker room	1	EA	5	1-2 years	Door damaged
Showers	1st Flr- Pool Boys locker room	16	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Student Lockers - One Tier	1st Flr- Pool Boys locker room	48	EA	6	10+ years	
	Student Lockers - Two Tier	1st Flr- Pool Boys locker room	30	EA	6	10+ years	
	Urinals	1st Flr- Pool Boys locker room	2	EA	6	10+ years	
	Walls - Concrete Block	1st Flr- Pool Boys locker room	1,525	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Flr- Pool Boys locker room	72	SF	6	10+ years	
	Water Closet	1st Flr- Pool Boys locker room	2	EA	3	1-2 years	Toilets missing
	Accessories	1st flr Pool Girls locker room	1,197	SF	5	6-10 years	
	Benches, ped mounted	1st flr Pool Girls locker room	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st flr Pool Girls locker room	1,187	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st flr Pool Girls locker room	10	SF	4	0-1 year	Hole in ceiling
	Doors - Steel Doors incl hw	1st flr Pool Girls locker room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr Pool Girls locker room	1,197	SF	6	10+ years	
	Floor Drain	1st flr Pool Girls locker room	6	EA	7	10+ years	
	Hand Dryer	1st flr Pool Girls locker room	8	EA	7	6-10 years	
	Lavatory	1st flr Pool Girls locker room	1	EA	6	10+ years	
	Lighting - Lay-in	1st flr Pool Girls locker room	16	EA	7	6-10 years	
	Lighting - Lay-in	1st flr Pool Girls locker room	5	EA	6	6-10 years	
	Partitions	1st flr Pool Girls locker room	2	EA	5	10+ years	
	Showers	1st flr Pool Girls locker room	16	EA	7	10+ years	
	Storage/ Closet	1st flr Pool Girls locker room	36	SF	4	0-1 year	Ceiling demolished
	Student Lockers - One Tier	1st flr Pool Girls locker room	48	EA	6	10+ years	
	Student Lockers - Two Tier	1st flr Pool Girls locker room	30	EA	6	10+ years	
	Walls - Concrete Block	1st flr Pool Girls locker room	1,495	SF	6	10+ years	
	Walls - Concrete Block	1st flr Pool Girls locker room	30	SF	4	0-1 year	Missing blocks
	Walls - Tile Ceramic/ Porcelain	1st flr Pool Girls locker room	72	SF	6	10+ years	
	Water Closet	1st flr Pool Girls locker room	2	EA	6	10+ years	
	Accessories	2nd floor gym boys locker room	620	SF	7	6-10 years	
	Benches, ped mounted	2nd floor gym boys locker room	25	LF	6	10+ years	
	Ceiling - Lay-in	2nd floor gym boys locker room	580	SF	6	10+ years	
	Ceiling - Lay-in	2nd floor gym boys locker room	10	SF	4	0-1 year	Missing tiles
	Ceiling - Plaster/Drywall	2nd floor gym boys locker room	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd floor gym boys locker room	2	EA	6	10+ years	
	Doors - Steel Doors incl hw	2nd floor gym boys locker room	1	EA	5	1-2 years	Damaged closer
	Floor - Tile Ceramic/ Porcelain	2nd floor gym boys locker room	30	SF	6	10+ years	
	Floor - Tile/Sheet	2nd floor gym boys locker room	590	SF	7	10+ years	
	Floor Drain	2nd floor gym boys locker room	1	EA	7	10+ years	
	Hand Dryer	2nd floor gym boys locker room	1	EA	7	6-10 years	
	Lavatory	2nd floor gym boys locker room	1	EA	6	10+ years	
	Lighting - Lay-in	2nd floor gym boys locker room	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd floor gym boys locker room	1	EA	6	6-10 years	
	Student Lockers - One Tier	2nd floor gym boys locker room	49	EA	6	6-10 years	
	Student Lockers - One Tier	2nd floor gym boys locker room	1	EA	5	1-2 years	Missing doir
	Walls - Concrete Block	2nd floor gym boys locker room	1,120	SF	6	10+ years	
	Water Closet	2nd floor gym boys locker room	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Accessories	2nd floor gym girls locker room	620	SF	7	6-10 years	
	Benches, ped mounted	2nd floor gym girls locker room	40	LF	6	10+ years	
	Ceiling - Lay-in	2nd floor gym girls locker room	590	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor gym girls locker room	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd floor gym girls locker room	2	EA	6	10+ years	
	Doors - Steel Doors incl hw	2nd floor gym girls locker room	1	EA	5	1-2 years	Damaged closer and hardware
	Floor - Tile Ceramic/ Porcelain	2nd floor gym girls locker room	30	SF	6	10+ years	
	Floor - Tile/Sheet	2nd floor gym girls locker room	590	SF	7	10+ years	
	Floor Drain	2nd floor gym girls locker room	1	EA	7	10+ years	
	Hand Dryer	2nd floor gym girls locker room	1	EA	7	6-10 years	
	Lavatory	2nd floor gym girls locker room	1	EA	6	10+ years	
	Lighting - Lay-in	2nd floor gym girls locker room	9	EA	7	6-10 years	
	Lighting - Lay-in	2nd floor gym girls locker room	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd floor gym girls locker room	1	EA	7	6-10 years	
	Student Lockers - One Tier	2nd floor gym girls locker room	50	EA	6	10+ years	
	Walls - Concrete Block	2nd floor gym girls locker room	1,120	SF	6	10+ years	
	Water Closet	2nd floor gym girls locker room	1	EA	6	10+ years	

Lunch & Multipurpose Room

	Ceiling - Lay-in	122 Cafeteria	735	SF	6	10+ years	
	Doors - Steel Doors incl hw	122 Cafeteria	2	EA	6	10+ years	
	Floor - Tile	122 Cafeteria	735	SF	6	10+ years	
	Lighting - Lay-in	122 Cafeteria	20	EA	6	6-10 years	
	Serving Line	122 Cafeteria	32	LF	6	10+ years	
	Walls - Concrete Block	122 Cafeteria	380	SF	6	10+ years	
	Walls - Masonry	122 Cafeteria	490	SF	6	10+ years	
	Ceiling - Lay-in	1st floor- House 1	1,689	SF	6	10+ years	
	Ceiling - Lay-in	1st floor- House 1	30	SF	4	0-1 year	Water damaged
	Doors - Side-lite	1st floor- House 1	800	SF	6	10+ years	
	Floor - Tile	1st floor- House 1	1,719	SF	6	10+ years	
	Lighting - Lay-in	1st floor- House 1	32	EA	7	6-10 years	
	Serving Line	1st floor- House 1	18	LF	6	10+ years	
	Walls - Concrete Block	1st floor- House 1	790	SF	6	10+ years	
	Walls - Metal Panel	1st floor- House 1	640	SF	6	10+ years	
	Ceiling - Lay-in	2nd floor- House 2	1,709	SF	6	10+ years	
	Ceiling - Lay-in	2nd floor- House 2	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd floor- House 2	800	SF	6	10+ years	
	Floor - Tile	2nd floor- House 2	1,719	SF	6	10+ years	
	Lighting - Lay-in	2nd floor- House 2	32	EA	7	6-10 years	
	Serving Line	2nd floor- House 2	18	LF	6	10+ years	
	Walls - Concrete Block	2nd floor- House 2	790	SF	6	10+ years	
	Walls - Metal Panel	2nd floor- House 2	640	SF	6	10+ years	
	Ceiling - Lay-in	2nd floor- House 3	1,719	SF	6	10+ years	
	Doors - Side-lite	2nd floor- House 3	800	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	2nd floor- House 3	1,719	SF	6	10+ years	
	Lighting - Lay-in	2nd floor- House 3	32	EA	7	6-10 years	
	Serving Line	2nd floor- House 3	18	LF	6	10+ years	
	Walls - Concrete Block	2nd floor- House 3	790	SF	6	10+ years	
	Walls - Metal Panel	2nd floor- House 3	640	SF	6	10+ years	
	Ceiling - Lay-in	3rd floor- House 4	1,699	SF	6	10+ years	
	Ceiling - Lay-in	3rd floor- House 4	20	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd floor- House 4	800	SF	6	10+ years	
	Floor - Tile	3rd floor- House 4	1,719	SF	6	10+ years	
	Lighting - Lay-in	3rd floor- House 4	32	EA	7	6-10 years	
	Serving Line	3rd floor- House 4	18	LF	6	10+ years	
	Walls - Concrete Block	3rd floor- House 4	790	SF	6	10+ years	
	Walls - Metal Panel	3rd floor- House 4	640	SF	6	10+ years	
	Ceiling - Lay-in	3rd floor- House 5	1,699	SF	6	10+ years	
	Ceiling - Lay-in	3rd floor- House 5	20	SF	4	0-1 year	Water damaged tiles
	Doors - Side-lite	3rd floor- House 5	800	SF	6	10+ years	
	Floor - Tile	3rd floor- House 5	1,719	SF	6	10+ years	
	Lighting - Lay-in	3rd floor- House 5	32	EA	7	6-10 years	
	Serving Line	3rd floor- House 5	18	LF	6	10+ years	
	Walls - Concrete Block	3rd floor- House 5	790	SF	6	10+ years	
	Walls - Metal Panel	3rd floor- House 5	640	SF	6	10+ years	

MDF_IDF

AC Unit	MDF RM in Library Storage	1	EA	7	6-10 years	
Ceiling - Lay-in	MDF RM in Library Storage	126	SF	4	0-1 year	Water damage and missing tiles
Doors - Steel Doors incl hw	MDF RM in Library Storage	1	EA	6	10+ years	
Floor - Tile	MDF RM in Library Storage	126	SF	6	10+ years	
Lighting - Lay-in	MDF RM in Library Storage	3	EA	7	6-10 years	
Other Cooling Unit	MDF RM in Library Storage	1	EA	7	6-10 years	Split ductless
Power Distribution	MDF RM in Library Storage	12	EA	7	10+ years	
Walls - Concrete Block	MDF RM in Library Storage	125	SF	6	10+ years	
Walls - Plaster/Drywall	MDF RM in Library Storage	125	SF	6	10+ years	

Mechanical/ Service Rooms

Janitor's Closet	1st Floor	43	SF	5	10+ years	
Janitor's Closet	1st Floor	23	SF	5	10+ years	
Mechanical/ Service Rooms	1st Floor	41	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	929	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	36	SF	5	10+ years	
Storage Room	1st Floor	105	SF	5	10+ years	
Storage Room	1st Floor	280	SF	5	10+ years	
Storage Room	1st Floor	72	SF	5	10+ years	
Storage Room	1st Floor	1,006	SF	5	10+ years	Missing ceiling tiles
Vaults	1st Floor	65	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Janitor's Closet	2nd Floor	21	SF	7	10+ years	
	Janitor's Closet	2nd Floor	43	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	20	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	
	Storage Room	2nd Floor	798	SF	7	10+ years	
	Janitor's Closet	3rd Floor	36	SF	5	10+ years	
	Janitor's Closet	3rd Floor	36	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	196	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	47	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	30	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	30	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	56	SF	5	10+ years	
	Storage Room	3rd Floor	220	SF	5	10+ years	Ceiling water damage
	Storage Room	3rd Floor	365	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement- Under Pool area only	748	SF	5	10+ years	

Pool & Natatorium

	Ceiling - Plaster/Drywall	1st Floor	3,854	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	3,854	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	40	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	2-5 years	
	Pool Basin	1st Floor	1,840	SF	5	1-2 years	Pool not functioning
	Pool Deck Drains	1st Floor	10	EA	5	1-2 years	Drains not functioning
	Storage/ Closet	1st Floor	51	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	3,000	SF	6	10+ years	

Prep Room

	Casework	306A	20	LF	6	10+ years	
	Ceiling - Lay-in	306A	211	SF	6	10+ years	
	Doors - Steel Doors incl hw	306A	1	EA	6	10+ years	
	Floor - Tile	306A	211	SF	6	10+ years	
	Lighting - Lay-in	306A	4	EA	7	6-10 years	
	Walls - Concrete Block	306A	130	SF	7	10+ years	
	Walls - Plaster/Drywall	306A	430	SF	6	10+ years	
	Work Sink	306A	1	EA	7	6-10 years	
	Casework	330A	9	LF	6	10+ years	
	Ceiling - Lay-in	330A	182	SF	6	10+ years	
	Doors - Steel Doors incl hw	330A	1	EA	6	10+ years	
	Floor - Tile	330A	182	SF	6	10+ years	
	Lighting - Lay-in	330A	4	EA	6	6-10 years	Relamp lights
	Walls - Concrete Block	330A	90	SF	7	10+ years	
	Walls - Plaster/Drywall	330A	300	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Restroom							
	Accessories	105A - 1st floor boys north	180	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	105A - 1st floor boys north	180	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	105A - 1st floor boys north	180	SF	7	10+ years	
	Floor Drain	105A - 1st floor boys north	1	EA	7	10+ years	
	Hand Dryer	105A - 1st floor boys north	2	EA	7	6-10 years	
	Lavatory	105A - 1st floor boys north	3	EA	6	10+ years	
	Lighting - Lay-in	105A - 1st floor boys north	5	EA	6	6-10 years	
	Partitions	105A - 1st floor boys north	2	EA	7	10+ years	
	Urinals	105A - 1st floor boys north	3	EA	6	10+ years	
	Walls - Concrete Block	105A - 1st floor boys north	360	SF	6	10+ years	
	Water Closet	105A - 1st floor boys north	2	EA	6	10+ years	
	Accessories	105C - 1st floor girls north	180	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	105C - 1st floor girls north	180	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	105C - 1st floor girls north	180	SF	7	10+ years	
	Floor Drain	105C - 1st floor girls north	1	EA	7	10+ years	
	Hand Dryer	105C - 1st floor girls north	2	EA	7	6-10 years	
	Lavatory	105C - 1st floor girls north	3	EA	6	10+ years	
	Lighting - Lay-in	105C - 1st floor girls north	5	EA	6	6-10 years	
	Partitions	105C - 1st floor girls north	4	EA	5	10+ years	
	Walls - Concrete Block	105C - 1st floor girls north	320	SF	6	10+ years	
	Water Closet	105C - 1st floor girls north	4	EA	6	10+ years	
	Accessories	132D - 1st floor kitchen women (not in use, now storage)	150	SF	7	6-10 years	
	Ceiling - Lay-in	132D - 1st floor kitchen women (not in use, now storage)	75	SF	7	10+ years	
	Ceiling - Lay-in	132D - 1st floor kitchen women (not in use, now storage)	75	SF	5	1-2 years	Damaged or missing tiles
	Doors - Wood Doors inclu hw	132D - 1st floor kitchen women (not in use, now storage)	2	EA	6	10+ years	
	Floor - Tile	132D - 1st floor kitchen women (not in use, now storage)	85	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	132D - 1st floor kitchen women (not in use, now storage)	65	SF	6	10+ years	
	Floor Drain	132D - 1st floor kitchen women (not in use, now storage)	1	EA	7	10+ years	
	Lavatory	132D - 1st floor kitchen women (not in use, now storage)	1	EA	6	10+ years	
	Lighting - Lay-in	132D - 1st floor kitchen women (not in use, now storage)	3	EA	6	6-10 years	
	Partitions	132D - 1st floor kitchen women (not in use, now storage)	1	EA	7	10+ years	
	Student Lockers - One Tier	132D - 1st floor kitchen women (not in use, now storage)	16	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Concrete Block	132D - 1st floor kitchen women (not in use, now storage)	170	SF	6	10+ years	
	Walls - Masonry	132D - 1st floor kitchen women (not in use, now storage)	130	SF	6	10+ years	
	Water Closet	132D - 1st floor kitchen women (not in use, now storage)	1	EA	6	10+ years	
	Accessories	132F - 1st floor kitchen men	65	SF	7	6-10 years	
	Ceiling - Lay-in	132F - 1st floor kitchen men	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	132F - 1st floor kitchen men	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	132F - 1st floor kitchen men	65	SF	6	10+ years	
	Floor Drain	132F - 1st floor kitchen men	1	EA	7	10+ years	
	Lavatory	132F - 1st floor kitchen men	1	EA	6	10+ years	
	Lighting - Lay-in	132F - 1st floor kitchen men	1	EA	7	6-10 years	
	Partitions	132F - 1st floor kitchen men	1	EA	5	10+ years	
	Student Lockers - One Tier	132F - 1st floor kitchen men	11	EA	6	10+ years	
	Walls - Concrete Block	132F - 1st floor kitchen men	130	SF	6	10+ years	
	Water Closet	132F - 1st floor kitchen men	1	EA	6	10+ years	
	Accessories	136A - 1st flr Women's	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	136A - 1st flr Women's	245	SF	6	10+ years	
	Doors - Transom Window	136A - 1st flr Women's	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	136A - 1st flr Women's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	136A - 1st flr Women's	242	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	136A - 1st flr Women's	3	SF	4	1-2 years	Missing or damaged tiles
	Floor Drain	136A - 1st flr Women's	1	EA	7	10+ years	
	Hand Dryer	136A - 1st flr Women's	1	EA	7	6-10 years	
	Lighting - Lay-in	136A - 1st flr Women's	7	EA	6	6-10 years	
	Partitions	136A - 1st flr Women's	5	EA	5	10+ years	
	Walls - Concrete Block	136A - 1st flr Women's	440	SF	6	10+ years	
	Water Closet	136A - 1st flr Women's	5	EA	6	10+ years	
	Accessories	181 Boys (By Main Office)	245	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	181 Boys (By Main Office)	245	SF	6	10+ years	
	Doors - Transom Window	181 Boys (By Main Office)	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	181 Boys (By Main Office)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	181 Boys (By Main Office)	245	SF	6	10+ years	
	Floor Drain	181 Boys (By Main Office)	1	EA	7	10+ years	
	Hand Dryer	181 Boys (By Main Office)	2	EA	7	6-10 years	
	Lavatory	181 Boys (By Main Office)	4	EA	6	10+ years	
	Lighting - Lay-in	181 Boys (By Main Office)	7	EA	6	6-10 years	
	Partitions	181 Boys (By Main Office)	3	EA	5	10+ years	
	Urinals	181 Boys (By Main Office)	3	EA	6	10+ years	
	Walls - Concrete Block	181 Boys (By Main Office)	440	SF	6	10+ years	
	Water Closet	181 Boys (By Main Office)	3	EA	6	10+ years	
	Accessories	181A - Unisex ADA RR	76	SF	7	6-10 years	
	Ceiling - Lay-in	181A - Unisex ADA RR	76	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	181A - Unisex ADA RR	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	181A - Unisex ADA RR	76	SF	6	10+ years	
	Floor Drain	181A - Unisex ADA RR	1	EA	7	10+ years	
	Hand Dryer	181A - Unisex ADA RR	1	EA	7	6-10 years	
	Lavatory	181A - Unisex ADA RR	1	EA	6	10+ years	
	Lighting - Pendent/Surface	181A - Unisex ADA RR	2	EA	6	6-10 years	
	Walls - Concrete Block	181A - Unisex ADA RR	93	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	181A - Unisex ADA RR	57	SF	6	10+ years	
	Water Closet	181A - Unisex ADA RR	1	EA	6	10+ years	
	Accessories	1st Flr- In Nurse's Office	18	SF	5	6-10 years	
	Ceiling - Lay-in	1st Flr- In Nurse's Office	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Flr- In Nurse's Office	1	EA	6	10+ years	
	Floor - Tile	1st Flr- In Nurse's Office	18	SF	6	10+ years	
	Lavatory	1st Flr- In Nurse's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Flr- In Nurse's Office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Flr- In Nurse's Office	36	SF	6	10+ years	
	Water Closet	1st Flr- In Nurse's Office	1	EA	6	10+ years	
	Accessories	1st Flr- In Principal's Office	18	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Flr- In Principal's Office	18	SF	6	10+ years	
	Doors - Transom Window	1st Flr- In Principal's Office	1	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr- In Principal's Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Flr- In Principal's Office	18	SF	7	10+ years	
	Lavatory	1st Flr- In Principal's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Flr- In Principal's Office	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Flr- In Principal's Office	36	SF	6	10+ years	
	Water Closet	1st Flr- In Principal's Office	1	EA	6	10+ years	
	Accessories	1st floor chief engineer restroom	15	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor chief engineer restroom	15	SF	4	0-1 year	Damaged tiles
	Doors - Wood Doors inclu hw	1st floor chief engineer restroom	1	EA	6	10+ years	
	Floor - Tile	1st floor chief engineer restroom	15	SF	6	10+ years	
	Floor Drain	1st floor chief engineer restroom	1	EA	7	10+ years	
	Lavatory	1st floor chief engineer restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st floor chief engineer restroom	1	EA	6	6-10 years	
	Walls - Concrete Block	1st floor chief engineer restroom	30	SF	6	10+ years	
	Water Closet	1st floor chief engineer restroom	1	EA	6	10+ years	
	Accessories	1st floor custodian office	65	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor custodian office	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor custodian office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor custodian office	60	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor custodian office	5	SF	4	0-1 year	Missing tiles
	Floor Drain	1st floor custodian office	1	EA	7	10+ years	
	Lavatory	1st floor custodian office	1	EA	6	10+ years	
	Lighting - Lay-in	1st floor custodian office	1	EA	6	6-10 years	
	Partitions	1st floor custodian office	1	EA	5	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Student Lockers - One Tier	1st floor custodian office	11	EA	6	10+ years	
	Walls - Concrete Block	1st floor custodian office	130	SF	6	10+ years	
	Water Closet	1st floor custodian office	1	EA	6	10+ years	
	Accessories	2nd Floor	200	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	200	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	200	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	4	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	3	EA	7	10+ years	
	Urinals	2nd Floor	3	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	450	SF	6	10+ years	
	Water Closet	2nd Floor	3	EA	7	10+ years	
	Accessories	2nd Flr-By-Gym Unisex 2 (Storage)	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Flr-By-Gym Unisex 2 (Storage)	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr-By-Gym Unisex 2 (Storage)	44	SF	6	10+ years	
	Floor Drain	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	7	10+ years	
	Lavatory	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	6	10+ years	
	Lighting - Lay-in	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	7	6-10 years	
	Partitions	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	5	1-2 years	Damaged
	Walls - Concrete Block	2nd Flr-By-Gym Unisex 2 (Storage)	88	SF	6	10+ years	
	Water Closet	2nd Flr-By-Gym Unisex 2 (Storage)	1	EA	4	1-2 years	Out of order
	Accessories	2nd floor boys north	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys north	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys north	180	SF	6	10+ years	
	Floor Drain	2nd floor boys north	1	EA	7	10+ years	
	Hand Dryer	2nd floor boys north	2	EA	7	10+ years	
	Lavatory	2nd floor boys north	3	EA	6	10+ years	
	Lighting - Lay-in	2nd floor boys north	5	EA	7	6-10 years	
	Partitions	2nd floor boys north	2	EA	7	10+ years	
	Urinals	2nd floor boys north	4	EA	7	10+ years	
	Walls - Concrete Block	2nd floor boys north	360	SF	6	10+ years	
	Water Closet	2nd floor boys north	2	EA	7	10+ years	
	Accessories	2nd floor boys south	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys south	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys south	180	SF	6	10+ years	
	Floor Drain	2nd floor boys south	1	EA	7	10+ years	
	Hand Dryer	2nd floor boys south	2	EA	7	6-10 years	
	Lavatory	2nd floor boys south	3	EA	6	10+ years	Qty updated
	Lighting - Pendent/Surface	2nd floor boys south	5	EA	7	6-10 years	
	Partitions	2nd floor boys south	3	EA	7	10+ years	
	Urinals	2nd floor boys south	2	EA	7	10+ years	Qty updated
	Walls - Concrete Block	2nd floor boys south	360	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	2nd floor boys south	3	EA	7	10+ years	
	Accessories	2nd floor girls South	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls South	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls South	180	SF	6	10+ years	
	Floor Drain	2nd floor girls South	1	EA	7	10+ years	
	Hand Dryer	2nd floor girls South	2	EA	7	6-10 years	
	Lavatory	2nd floor girls South	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor girls South	5	EA	7	6-10 years	Qty updated
	Partitions	2nd floor girls South	4	EA	7	10+ years	
	Walls - Concrete Block	2nd floor girls South	320	SF	6	10+ years	
	Water Closet	2nd floor girls South	4	EA	7	10+ years	
	Accessories	2nd floor girls north	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls north	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls north	180	SF	6	10+ years	
	Floor Drain	2nd floor girls north	1	EA	7	10+ years	
	Hand Dryer	2nd floor girls north	2	EA	7	6-10 years	
	Lavatory	2nd floor girls north	3	EA	6	10+ years	
	Lighting - Lay-in	2nd floor girls north	5	EA	7	6-10 years	
	Partitions	2nd floor girls north	5	EA	7	10+ years	
	Walls - Concrete Block	2nd floor girls north	320	SF	6	10+ years	
	Water Closet	2nd floor girls north	5	EA	7	10+ years	
	Accessories	2nd flr Womens (By 239)	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd flr Womens (By 239)	245	SF	6	10+ years	
	Doors - Transom Window	2nd flr Womens (By 239)	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr Womens (By 239)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr Womens (By 239)	245	SF	6	10+ years	
	Floor Drain	2nd flr Womens (By 239)	1	EA	7	10+ years	
	Hand Dryer	2nd flr Womens (By 239)	1	EA	7	6-10 years	
	Lavatory	2nd flr Womens (By 239)	4	EA	6	10+ years	
	Lighting - Lay-in	2nd flr Womens (By 239)	7	EA	7	6-10 years	
	Partitions	2nd flr Womens (By 239)	5	EA	7	10+ years	
	Walls - Concrete Block	2nd flr Womens (By 239)	440	SF	6	10+ years	
	Water Closet	2nd flr Womens (By 239)	5	EA	7	10+ years	
	Accessories	2nd flr-By Gym -Unisex restroom 1	44	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd flr-By Gym -Unisex restroom 1	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr-By Gym -Unisex restroom 1	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr-By Gym -Unisex restroom 1	44	SF	6	10+ years	
	Floor Drain	2nd flr-By Gym -Unisex restroom 1	1	EA	7	10+ years	
	Lavatory	2nd flr-By Gym -Unisex restroom 1	1	EA	6	10+ years	
	Lighting - Lay-in	2nd flr-By Gym -Unisex restroom 1	1	EA	6	6-10 years	
	Walls - Concrete Block	2nd flr-By Gym -Unisex restroom 1	88	SF	6	10+ years	
	Water Closet	2nd flr-By Gym -Unisex restroom 1	1	EA	6	10+ years	
	Accessories	3rd floor boys north	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys north	180	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	3rd floor boys north	180	SF	6	10+ years	
	Floor Drain	3rd floor boys north	1	EA	7	10+ years	
	Hand Dryer	3rd floor boys north	2	EA	7	6-10 years	
	Lavatory	3rd floor boys north	3	EA	6	10+ years	
	Lighting - Lay-in	3rd floor boys north	4	EA	7	6-10 years	
	Lighting - Lay-in	3rd floor boys north	1	EA	5	0-1 year	Missing cover
	Partitions	3rd floor boys north	2	EA	7	10+ years	
	Urinals	3rd floor boys north	4	EA	7	10+ years	
	Walls - Concrete Block	3rd floor boys north	360	SF	6	10+ years	
	Water Closet	3rd floor boys north	2	EA	7	10+ years	
	Accessories	3rd floor boys south	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys south	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys south	180	SF	6	10+ years	
	Floor Drain	3rd floor boys south	1	EA	7	10+ years	
	Hand Dryer	3rd floor boys south	2	EA	7	6-10 years	
	Lavatory	3rd floor boys south	3	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor boys south	5	EA	7	6-10 years	
	Partitions	3rd floor boys south	2	EA	7	10+ years	
	Urinals	3rd floor boys south	2	EA	7	10+ years	
	Walls - Concrete Block	3rd floor boys south	360	SF	6	10+ years	
	Water Closet	3rd floor boys south	2	EA	7	10+ years	
	Accessories	3rd floor girls South	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor girls South	180	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor girls South	180	SF	6	10+ years	
	Floor Drain	3rd floor girls South	1	EA	7	10+ years	
	Hand Dryer	3rd floor girls South	2	EA	7	6-10 years	
	Lavatory	3rd floor girls South	3	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor girls South	5	EA	7	6-10 years	
	Partitions	3rd floor girls South	4	EA	7	10+ years	
	Walls - Concrete Block	3rd floor girls South	320	SF	6	10+ years	
	Water Closet	3rd floor girls South	4	EA	7	10+ years	
	Accessories	3rd floor girls north	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor girls north	180	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd floor girls north	180	SF	7	10+ years	
	Floor Drain	3rd floor girls north	1	EA	7	10+ years	
	Hand Dryer	3rd floor girls north	2	EA	7	6-10 years	
	Lavatory	3rd floor girls north	3	EA	6	10+ years	
	Lighting - Lay-in	3rd floor girls north	4	EA	7	6-10 years	
	Lighting - Lay-in	3rd floor girls north	1	EA	5	0-1 year	Missing cover
	Partitions	3rd floor girls north	5	EA	5	1-2 years	Vandalized
	Walls - Concrete Block	3rd floor girls north	320	SF	6	10+ years	
	Water Closet	3rd floor girls north	5	EA	7	10+ years	
	Accessories	3rd floor mens west	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor mens west	245	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Transom Window	3rd floor mens west	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor mens west	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor mens west	245	SF	6	10+ years	
	Floor Drain	3rd floor mens west	1	EA	7	10+ years	
	Hand Dryer	3rd floor mens west	1	EA	7	6-10 years	
	Lavatory	3rd floor mens west	4	EA	6	10+ years	
	Lighting - Lay-in	3rd floor mens west	7	EA	7	6-10 years	
	Partitions	3rd floor mens west	3	EA	7	10+ years	
	Urinals	3rd floor mens west	3	EA	7	10+ years	
	Walls - Concrete Block	3rd floor mens west	454	SF	6	10+ years	
	Water Closet	3rd floor mens west	3	EA	7	10+ years	
	Accessories	3rd floor womens east	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor womens east	245	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd floor womens east	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor womens east	245	SF	6	10+ years	
	Floor Drain	3rd floor womens east	1	EA	7	10+ years	
	Hand Dryer	3rd floor womens east	1	EA	7	6-10 years	
	Lavatory	3rd floor womens east	4	EA	6	10+ years	
	Lighting - Lay-in	3rd floor womens east	5	EA	7	6-10 years	
	Lighting - Lay-in	3rd floor womens east	2	EA	4	0-1 year	Missing cover
	Partitions	3rd floor womens east	5	EA	7	10+ years	
	Walls - Concrete Block	3rd floor womens east	440	SF	6	10+ years	
	Water Closet	3rd floor womens east	5	EA	7	10+ years	
	Accessories	Gym office A restroom	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym office A restroom	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym office A restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym office A restroom	30	SF	6	10+ years	
	Floor Drain	Gym office A restroom	1	EA	7	10+ years	
	Lavatory	Gym office A restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Gym office A restroom	1	EA	6	6-10 years	
	Student Lockers - One Tier	Gym office A restroom	1	EA	6	10+ years	
	Walls - Concrete Block	Gym office A restroom	60	SF	6	10+ years	
	Water Closet	Gym office A restroom	1	EA	4	1-2 years	Out of order
	Accessories	Gym office B restroom	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym office B restroom	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym office B restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym office B restroom	30	SF	6	10+ years	
	Floor Drain	Gym office B restroom	1	EA	7	10+ years	
	Lavatory	Gym office B restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Gym office B restroom	1	EA	5	1-2 years	Damaged
	Walls - Concrete Block	Gym office B restroom	60	SF	6	10+ years	
	Water Closet	Gym office B restroom	1	EA	4	1-2 years	Out of order
	Accessories	Inside 108C	18	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Inside 108C	18	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	Inside 108C	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 108C	18	SF	6	10+ years	
	Lavatory	Inside 108C	1	EA	6	10+ years	
	Lighting - Wall Mounted	Inside 108C	1	EA	7	6-10 years	
	Walls - Concrete Block	Inside 108C	36	SF	6	10+ years	
	Water Closet	Inside 108C	1	EA	6	10+ years	
	Accessories	Inside 180B - Dressing Rm off stage	18	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Inside 180B - Dressing Rm off stage	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Inside 180B - Dressing Rm off stage	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 180B - Dressing Rm off stage	18	SF	6	10+ years	
	Lavatory	Inside 180B - Dressing Rm off stage	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Inside 180B - Dressing Rm off stage	1	EA	6	6-10 years	
	Walls - Concrete Block	Inside 180B - Dressing Rm off stage	36	SF	6	10+ years	
	Water Closet	Inside 180B - Dressing Rm off stage	1	EA	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #101 (Regular Classroom)</u>							
	Casework	1st Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	829	SF	5	2-5 years	
	Ceiling - Lay-in	1st Floor	6	SF	4	0-1 year	Damaged tiles
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	455	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	610	SF	6	10+ years	
<u>Classroom #102 (Regular Classroom)</u>							
	Ceiling - Lay-in	1st Floor	835	SF	5	2-5 years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	115	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	950	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #103 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	835	SF	5	2-5 years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	135	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	340	SF	6	10+ years	
Classroom #104 105 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	750	SF	6	6-10 years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	750	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	400	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	200	SF	7	10+ years	
Classroom #106 (Faculty Lounge)							
	Casework	1st Floor	55	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	995	SF	5	2-5 years	
	Ceiling - Lay-in	1st Floor	40	SF	4	1-2 years	Water damaged
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,035	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Science Lab Elements	1st Floor	24	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	645	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	645	SF	6	10+ years	
	Work Sink	1st Floor	4	EA	5	0-1 year	Not functioning
Classroom #108 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	835	SF	5	2-5 years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	455	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	340	SF	6	10+ years	
Classroom #109 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	817	SF	5	2-5 years	
	Ceiling - Lay-in	1st Floor	18	SF	4	0-1 year	Damaged tiles
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	135	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	340	SF	6	10+ years	
Classroom #110 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	835	SF	5	2-5 years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	115	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	950	SF	6	10+ years	
Classroom #111 (Regular Classroom)							
	Casework	1st Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	823	SF	6	2-5 years	
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	Damaged tiles
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	835	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	455	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Metal Panel	1st Floor	610	SF	6	10+ years	
Classroom #121 (Other Instructional Use)							
	Ceiling - Lay-in	1st Floor	2,013	SF	7	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years	
	Floor - Carpet	1st Floor	2,013	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	40	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	152	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	800	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,000	SF	6	10+ years	
Classroom #132 (Computer Lab)							
	Ceiling - Lay-in	1st Floor	1,195	SF	7	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Floor - Tile	1st Floor	1,195	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	24	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	2	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,300	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,140	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroom #134 (Store Room)							
	Ceiling - Lay-in	1st Floor	2,058	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Floor - Tile	1st Floor	2,038	SF	6	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Damaged tiles
	Lighting - Lay-in	1st Floor	36	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Wall Mirrors	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	6	SF	6	10+ years	
	Walls - Concrete Block	1st Floor	3,619	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #135 (Office)							
	Casework	1st Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	750	SF	7	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Floor - Tile	1st Floor	750	SF	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,270	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #200 (Office)							
	Ceiling - Lay-in	2nd Floor	660	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	670	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	380	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	500	SF	6	10+ years	
Classroom #201 (Regular Classroom)							
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Water stain
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	17	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	610	SF	6	10+ years	
Classroom #202 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	17	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	5	1-2 years	Loose fixture
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	950	SF	6	10+ years	
Classroom #203 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
<hr/>							
Classroom #204 (Regular Classroom)							
	Casework	2nd Floor	18	LF	6	10+ years	Water damage
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	885	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	610	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
<hr/>							
Classroom #205 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	610	SF	6	10+ years	Damaged tiles Water damage
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Floor - Tile	2nd Floor	620	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	845	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	820	SF	7	10+ years	
<hr/>							
Classroom #206 (Art Room)							
	Casework	2nd Floor	54	LF	6	10+ years	Water damage
	Ceiling - Lay-in	2nd Floor	1,030	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Eye Wash Station	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,035	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	645	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	645	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	7	10+ years	

Classroom #208 (Regular Classroom)

	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	435	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	

Classroom #209 (Regular Classroom)

	Ceiling - Lay-in	2nd Floor	825	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	17	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	

Classroom #210 (Regular Classroom)

	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Water stain
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	950	SF	6	10+ years	
Classroom #211 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Loose tile
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	610	SF	6	10+ years	
Classroom #212 (Fitness Room)							
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,170	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	0-1 year	Water damage
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,180	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	25	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	840	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	249	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroom #222 (Other Instructional Use)							
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	610	SF	6	10+ years	
Classroom #223 (Vacant)							
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	950	SF	6	10+ years	
Classroom #224 (Other Instructional Use)							
	Ceiling - Lay-in	2nd Floor	815	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	20	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
Classroom #225 (Other Instructional Use)							
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroom #226 (Other Instructional Use)							
	Ceiling - Lay-in	2nd Floor	630	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Damaged tile
	Doors - Transom Window	2nd Floor	7	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	635	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	430	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Metal Panel	2nd Floor	430	SF	6	10+ years	
Classroom #230 (Science Lab Level 3)							
	Casework	2nd Floor	54	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,035	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,035	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Science Lab Elements	2nd Floor	24	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	645	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	645	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	7	10+ years	
Classroom #232 (Special Education)							
	Ceiling - Lay-in	2nd Floor	825	SF	6	10+ years	Damaged tiles
	Ceiling - Lay-in	2nd Floor	10	SF	4	1-2 years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	532	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	266	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	266	SF	6	10+ years	
Classroom #233 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	532	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	266	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	266	SF	6	10+ years	
Classroom #234 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	2nd Floor	5	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	266	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	799	SF	6	10+ years	
<hr/>							
Classroom #235 (Regular Classroom)							
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	610	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	455	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
<hr/>							
Classroom #300 (Faculty Lounge)							
	Ceiling - Lay-in	3rd Floor	945	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	Damaged tile Loose tile Water damage
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	
	Doors - Side-lite	3rd Floor	80	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	960	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	13	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	5	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	81	SF	7	10+ years	Locked
	Walls - Concrete Block	3rd Floor	1,100	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	1,100	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
<hr/>							
Classroom #301 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,099	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	1,090	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	10	SF	4	1-2 years	Missing base trim
Classroom #302 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	835	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,100	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	1,100	SF	6	10+ years	
Classroom #303 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,100	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	1,100	SF	6	10+ years	
Classroom #304 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	825	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,100	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Metal Panel	3rd Floor	1,100	SF	6	10+ years	
Classroom #305 (Other Instructional Use)							
	Ceiling - Lay-in	3rd Floor	620	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	620	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	845	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	820	SF	6	10+ years	
Classroom #306 (Science Lab Level 3)							
	Casework	3rd Floor	65	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,053	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	3rd Floor	3	EA	6	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,073	SF	6	10+ years	
	Gas Line	3rd Floor	8	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	19	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	5	0-1 year	Loose fixture
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	910	SF	6	10+ years	
	Work Sink	3rd Floor	9	EA	7	6-10 years	
Classroom #308 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	15	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	435	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
Classroom #309 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	830	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	Water damage

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	330	SF	6	10+ years	
Classroom #310 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	15	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	950	SF	6	10+ years	
Classroom #311 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	825	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	610	SF	6	10+ years	
Classroom #312 (Music Room)							
	Ceiling - Lay-in	3rd Floor	1,046	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	3rd Floor	5	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	45	SF	6	10+ years	
	Floor - Tile	3rd Floor	1,066	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	22	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	178	SF	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	3rd Floor	5	SF	5	1-2 years	Damaged tiles
	Walls - Concrete Block	3rd Floor	1,800	SF	6	10+ years	
<hr/> Classroom #322 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	Water damage
	Ceiling - Lay-in	3rd Floor	15	SF	4	0-1 year	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	610	SF	6	10+ years	
<hr/> Classroom #323 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	825	SF	6	10+ years	Water damage
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	950	SF	6	10+ years	
<hr/> Classroom #324 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	Water damage
	Ceiling - Lay-in	3rd Floor	15	SF	4	0-1 year	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
<hr/> Classroom #325 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	823	SF	6	10+ years	Water damage
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	270	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
Classroom #326 (Regular Classroom)							
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	600	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year	Damaged tiles
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	620	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	430	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	340	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroom #330 (Science Lab Level 3)							
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,020	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	Missing tile
	Doors - Steel Doors incl hw	3rd Floor	3	EA	6	10+ years	
	Eye Wash Station	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,035	SF	6	10+ years	
	Gas Line	3rd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	645	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	645	SF	6	10+ years	
	Work Sink	3rd Floor	4	EA	7	6-10 years	
Classroom #332 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	825	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	1-2 years	Damaged tiles

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,000	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,000	SF	6	10+ years	
Classroom #333 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	825	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	135	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	570	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	340	SF	6	10+ years	
Classroom #334 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage
	Ceiling - Lay-in	3rd Floor	5	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	3rd Floor	9	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	115	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	950	SF	6	10+ years	
Classroom #335 (Regular Classroom)							
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	827	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	455	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	610	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Work Sink	3rd Floor	1	EA	4	0-1 year	Missing faucet
Classroom #336 (Office)							
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Tile	3rd Floor	828	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	17	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	5	0-1 year	Loose fixture
	Walls - Concrete Block	3rd Floor	1,118	SF	6	10+ years	
	Walls - Concrete Block	3rd Floor	10	SF	5	1-2 years	Cracks
	Walls - Metal Panel	3rd Floor	400	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	9,200	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	166	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	1st Floor	1,280	SF	6	10+ years	
	Doors - Side-lite	1st Floor	54	SF	6	10+ years	
	Doors - Store Front	1st Floor	8	EA	6	10+ years	
	Doors - Transom Window	1st Floor	56	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	12	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	
	Floor - Concrete	1st Floor	216	SF	7	10+ years	
	Floor - Tile Quarry	1st Floor	740	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	9,640	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	50	SF	4	1-2 years	Damaged tiles
	Lighting - Lay-in	1st Floor	154	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	8	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	153	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	5,000	SF	6	10+ years	
	Walls - Masonry	1st Floor	7,350	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	3,120	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	9,100	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	120	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	148	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	20	EA	6	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	9,100	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	116	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	280	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	2,712	SF	6	10+ years	
	Walls - Masonry	2nd Floor	1,850	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	5,215	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	280	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8,514	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	120	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	148	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	16	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	8,514	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	107	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	280	EA	6	10+ years	
	Walls - Concrete Block	3rd Floor	220	SF	6	10+ years	
	Walls - Masonry	3rd Floor	1,850	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	5,215	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,650	SF	6	10+ years	

Safety

Camera Viewing Station	1st Floor	3	EA	7	6-10 years	
Security Cameras	1st Floor	19	EA	7	6-10 years	
Security Cameras	1st Floor	10	EA	7	6-10 years	

Stairs

Ceiling - Plaster/Drywall	East	780	SF	6	10+ years	
Floor - Concrete Epoxy/ Painted	East	460	SF	5	0-1 year	Finish is worn
Handrails	East	120	LF	7	10+ years	
Lighting - Pendent/Surface	East	8	EA	7	6-10 years	Qty updated
Lighting - Wall Mounted	East	2	EA	7	6-10 years	
Stairs - Concrete	East	315	LF	6	10+ years	
Walls - Concrete Block	East	1,100	SF	6	10+ years	
Walls - Masonry	East	890	SF	6	10+ years	
Ceiling - Lay-in	In Pool/Gym Wing	103	SF	6	10+ years	
Floor - Asphalt	In Pool/Gym Wing	52	SF	5	10+ years	
Handrails	In Pool/Gym Wing	48	LF	7	10+ years	
Lighting - Wall Mounted	In Pool/Gym Wing	3	EA	7	6-10 years	
Stairs - Asphalt	In Pool/Gym Wing	124	LF	6	10+ years	
Walls - Concrete Block	In Pool/Gym Wing	236	SF	6	10+ years	
Ceiling - Lay-in	NW Stairs Adj to Library	200	SF	6	10+ years	
Floor - Tile	NW Stairs Adj to Library	16	SF	6	10+ years	
Handrails	NW Stairs Adj to Library	48	LF	7	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Lay-in	NW Stairs Adj to Library	7	EA	6	6-10 years	
	Stairs - Rubber	NW Stairs Adj to Library	124	LF	6	10+ years	
	Walls - Masonry	NW Stairs Adj to Library	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North	790	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	North	460	SF	5	0-1 year	Finish is worn
	Handrails	North	120	LF	7	10+ years	
	Lighting - Pendent/Surface	North	10	EA	7	6-10 years	
	Stairs - Concrete	North	315	LF	7	10+ years	Finish is worn in spots
	Walls - Concrete Block	North	1,100	SF	6	10+ years	
	Walls - Masonry	North	890	SF	6	10+ years	
	Ceiling - Lay-in	SE stairs adj. to Library	200	SF	6	10+ years	
	Ceiling - Lay-in	SE stairs adj. to Library	48	SF	5	1-2 years	Damaged tiles
	Floor - Tile	SE stairs adj. to Library	16	SF	6	10+ years	
	Handrails	SE stairs adj. to Library	48	LF	7	10+ years	
	Lighting - Lay-in	SE stairs adj. to Library	7	EA	6	6-10 years	
	Stairs - Rubber	SE stairs adj. to Library	124	LF	6	10+ years	
	Walls - Masonry	SE stairs adj. to Library	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	790	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	South	460	SF	5	0-1 year	Finish is worn
	Handrails	South	120	LF	7	10+ years	
	Lighting - Pendent/Surface	South	9	EA	7	6-10 years	
	Lighting - Pendent/Surface	South	3	EA	6	6-10 years	
	Stairs - Concrete	South	315	LF	6	10+ years	
	Walls - Concrete Block	South	1,100	SF	6	10+ years	
	Walls - Masonry	South	890	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	780	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	West	460	SF	5	0-1 year	Finish worn.
	Handrails	West	120	LF	5	1-2 years	Loose
	Lighting - Pendent/Surface	West	6	EA	7	6-10 years	
	Lighting - Wall Mounted	West	1	EA	7	6-10 years	
	Stairs - Concrete	West	315	LF	7	6-10 years	
	Walls - Concrete Block	West	1,100	SF	6	10+ years	
	Walls - Masonry	West	890	SF	6	10+ years	

Vertical Conveyance

Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	Ceiling panels missing
-------------------------------	-----------	---	----	---	-----------	------------------------

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Athletic							
	Surface - Asphalt	Site South	9,400	SF	4	0-1 year	Large cracking
	Surface - Natural	South site	147,500	SF	5	2-5 years	
Civil/Drainage							
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	Sinking/slowly draining
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	5	0-1 year	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	17	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	16	EA	6	10+ years	
Fencing							
	Fencing - Chain Link	Entire Site	1,670	LF	6	10+ years	Missing top rail/brokrm Bending Rusting throughout.
	Fencing - Chain Link	Entire Site	240	LF	5	1-2 years	
	Fencing - New Standard Ornamental	Entire Site	30	LF	5	1-2 years	
	Fencing - New Standard Ornamental	Entire Site	502	LF	4	0-1 year	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	63	LF	6	10+ years	
Landscape							
	Benches	Entire Site	5	EA	6	6-10 years	Cracking/holes/sinking
	Landscape - Grass	Entire Site	16,330	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	20,920	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	5,800	SF	4	0-1 year	
	Landscape - Hardscape- Pavers	Entire Site	240	SF	6	10+ years	
	Parkway trees	Entire Site	42	EA	7	10+ years	Exposed rebar
	Planting Beds/ Area	Entire Site	2,910	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	619	SF	5	10+ years	
	Retaining Wall - Concrete	Entire Site	26	SF	4	0-1 year	
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
Parking Lot							
	Surface - Asphalt	Parking Lot- South	34,900	SF	4	0-1 year	Extensive cracking/potholes
	Trash Enclosure - Chain Links	Parking Lot- South	912	SF	5	10+ years	
	Concrete Curbs	Parking Lot- West	363	LF	6	10+ years	
	Interior Plantings	Parking Lot- West	20	LF	6	10+ years	
	Surface - Asphalt	Parking Lot- West	6,315	SF	6	10+ years	
	Vehicular Screening	Parking Lot- West	291	LF	6	10+ years	
Playground							
	Equipment - Combo 3-12	West	1	EA	6	6-10 years	6-10 years
	Surface - Poured Surface	West	1,838	SF	6	6-10 years	

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Sidewalks</u>							
	Sidewalks - Perimeter Sidewalks	Entire Site	3,700	SF	7	10+ years	Newly replaced
	Sidewalks - Perimeter Sidewalks	Entire Site	13,000	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	25	SF	4	0-1 year	Cracking
<u>Signage</u>							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	
	Monument - Sign	Entire Site	1	EA	7	6-10 years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Building : Main									
Art Room	Science Lab Level 3	2nd Floor	206		1,035	0	0	N	N
Computer Lab	Regular Classroom	1st Floor	132	132	1,195	100	10	Y	N
Faculty Lounge	Computer Lab	3rd Floor	300	300	960	184	36	Y	N
Faculty Lounge	Science Lab Level 3	1st Floor	106		1,035	0	0	N	N
Fitness Room	Computer Lab	2nd Floor	212		1,180	368	72	Y	N
Music Room	Music Room	3rd Floor	312	321	1,066	368	72	Y	N
Office	Regular Classroom	1st Floor	135	135	750	64	24	Y	N
Office	Regular Classroom	2nd Floor	200	200	670	184	35	Y	N
Office	Regular Classroom	3rd Floor	336	336	828	230	45	Y	N
Other Instructional Use	Regular Classroom	1st Floor	121	121/123	2,013	124	24	Y	N
Other Instructional Use	Regular Classroom	2nd Floor	222		835	184	36	Y	N
Other Instructional Use	Regular Classroom	2nd Floor	224		835	184	36	Y	N
Other Instructional Use	Regular Classroom	2nd Floor	225		835	184	36	Y	N
Other Instructional Use	Regular Classroom	2nd Floor	226		635	184	36	Y	
Other Instructional Use	Regular Classroom	3rd Floor	305	305	620	276	54	Y	N
Regular Classroom	Art Room	2nd Floor	204		835	460	90	Y	N
Regular Classroom	Regular Classroom	1st Floor	101		835	184	36	Y	N
Regular Classroom	Regular Classroom	1st Floor	102		835	184	36	Y	N
Regular Classroom	Regular Classroom	1st Floor	103		835	184	36	Y	N
Regular Classroom	Regular Classroom	1st Floor	104 105	105	750	350	150	Y	N
Regular Classroom	Regular Classroom	1st Floor	108		835	184	36	Y	N
Regular Classroom	Regular Classroom	1st Floor	109		835	184	36	Y	N
Regular Classroom	Regular Classroom	1st Floor	110		835	184	36	Y	N
Regular Classroom	Regular Classroom	1st Floor	111		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	202		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	203		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	205		620	276	54	Y	
Regular Classroom	Regular Classroom	2nd Floor	208		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	209		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	210		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	211		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	233		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	234		835	184	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	235		835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	835	184	36	Y	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Regular Classroom	Regular Classroom	3rd Floor	304	304	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	323	323	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	324	324	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	325	325	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	326	326	620	276	54	Y	N
Regular Classroom	Regular Classroom	3rd Floor	332	332	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	333	333	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	334	334	835	184	36	Y	N
Regular Classroom	Regular Classroom	3rd Floor	335	335	835	184	36	Y	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	230		1,035	0	0	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	306	306	1,073	0	0	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	330	330	1,035	0	0	N	N
Special Education	Regular Classroom	2nd Floor	232		835	184	36	Y	N
Store Room	Regular Classroom	1st Floor	134	134	2,058	60	12	Y	N
Vacant	Regular Classroom	2nd Floor	223		835	184	36	Y	N