

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1923	4	77,725
Branch	1960	3	38,925
Campus Total			116,650

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	"RAD" - Roof Access Doors	8	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	"RAD" - Roof Access Doors	1	EA	4	0-1 year	Corroded, holes, missing hardware
	Entrance Control - Audio and Video	#1 Main - S	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#1 Main - S	6	EA	6	6-10 years	
	Exterior Doors - Side lite	#1 Main - S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 Main - S	15	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#11 - E	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#11 - E	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2 Exit - Basement South	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 Exit - Basement South	88	LF	4	0-1 year	Spalling, missing concrete
	Stair Handrail - Steel_Stair Handrail	#2 Exit - Basement South	56	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3 Basement - North	1	EA	4	0-1 year	Corroded, damaged hardware
	Exterior Stairs - Concrete	#3 Basement - North	3	LF	4	0-1 year	Broken
	Exterior Stairs - Steel or Aluminum	#3 Basement - North	88	LF	4	0-1 year	Corroded
	Stair Handrail - Steel_Stair Handrail	#3 Basement - North	56	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#4 Fire Escape Exit - W	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#4 Fire Escape Exit - W	5	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 - W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 - W	12	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#6 Exit - N	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6 Exit - N	3	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#7 - N	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#7 - N	6	LF	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Doors - Exterior Steel Door	#8 Exit - N	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#8 Exit - N	3	LF	6	10+ years	
	Entrance Control - Audio and Video	#9 - E	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#9 - E	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	#9 - E	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 - E	18	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	4.5 Fire Escape Exit - W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	4.5 Fire Escape Exit - W	4	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	8.5 Fire Escape - North	1	EA	6	10+ years	
	Exterior Stairs - Concrete	8.5 Fire Escape - North	4	LF	4	0-1 year	Cracked, spalling
Fire Escape							
	Exterior Doors - Exterior Steel Door	North Façade	1	EA	6	6-10 years	
	Fire Escape	North Façade	84	LF	5	2-5 years	Bent, racked, blocked by debris
	Paints	North Façade	84	LF	5	2-5 years	
	Swing Stairs	North Façade	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	West Façade	3	EA	6	10+ years	
	Fire Escape	West Façade	56	LF	6	10+ years	
	Paints	West Façade	56	LF	5	2-5 years	
Foundation							
	Foundation - Concrete	Entire Building	650	LF	7	10+ years	
	Foundation - Concrete	Entire Building	56	LF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	77,725	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	14	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	6	6-10 years	
Roof System							
	Coping - Metal	Roof #1	50	LF	6	10+ years	
	Coping - Stone	Roof #1	117	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #1	240	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof #1	70	LF	5	6-10 years	
	Parapet - Parapet > 30"	Roof #1	117	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #1	5,454	SF	4	0-1 year	Soft spots, bubbling
	Roof Structure - Steel with Clay Tile Arch	Roof #1	5,454	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #2	67	LF	6	10+ years	
	Coping - Clay Tile	Roof #2	151	LF	6	10+ years	
	Coping - Stone	Roof #2	94	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #2	156	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof #2	245	LF	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Roof - Modified Bitumen	Roof #2	5,019	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof #2	250	SF	4	1-2 years	Bubbling, separating seams
	Roof Structure - Steel with Clay Tile Arch	Roof #2	5,269	SF	7	10+ years	
	Coping - Metal	Roof #3	20	LF	6	10+ years	
	Coping - Stone	Roof #3	99	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof #3	38	LF	6	10+ years	Combined roof 3 and 10
	Parapet - Parapet < 16" Height	Roof #3	99	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #3	788	SF	6	6-10 years	Patched
	Roof Structure - Steel with Clay Tile Arch	Roof #3	788	SF	7	10+ years	
	Coping - Stone	Roof #4	296	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #4	248	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof #4	296	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #4	5,953	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof #4	5,953	SF	7	10+ years	
	Access Ladder - Metal	Roof #5	1	EA	7	10+ years	
	Coping - Clay Tile	Roof #5	353	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #5	156	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof #5	353	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #5	3,071	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof #5	3,071	SF	7	10+ years	
	Access Ladder - Metal	Roof #6	1	EA	7	10+ years	
	Coping - Stone	Roof #6	12	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #6	24	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof #6	12	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #6	1,100	SF	4	0-1 year	Cracking seams, deteriorated
	Roof Hatch - Metal	Roof #6	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof #6	1,100	SF	7	10+ years	
	Access Ladder - Metal	Roof #7	1	EA	4	0-1 year	Corroded
	Coping - Clay Tile	Roof #7	175	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #7	86	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof #7	175	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #7	1,570	SF	6	6-10 years	Unsafe access, roof in similar condition per engineer
	Roof Structure - Steel with Clay Tile Arch	Roof #7	1,570	SF	7	10+ years	
	Coping - Clay Tile	Roof #8	38	LF	6	10+ years	
	Coping - Stone	Roof #8	62	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #8	84	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof #8	100	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #8	524	SF	6	6-10 years	Combined roof 8 and 9
	Roof Structure - Steel with Clay Tile Arch	Roof #8	524	SF	7	10+ years	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	468	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	40,655	SF	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Walls - Brick	Entire Building	600	SF	5	2-5 years	
	Exterior Walls - Brick	Entire Building	2,000	SF	4	0-1 year	Efflorescence, stepped cracking, defacing brick
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,045	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,825	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	25	SF	4	0-1 year	Cracks, loose
	Exterior Walls - Terra Cotta	Entire Building	60	SF	6	10+ years	

Windows

	Clerestory - Glass Double-Pane	Entire Building	240	SF	7	10+ years	
	Curtain wall - Louver	Entire Building	360	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	220	SF	4	1-2 years	Corroded, bent
	Guard - Guards perforated	Entire Building	2,100	SF	6	10+ years	
	Lintels - Brick	Entire Building	17	LF	6	10+ years	
	Lintels - Concrete	Entire Building	216	LF	6	10+ years	
	Lintels - Steel	Entire Building	224	LF	6	10+ years	
	Lintels - Stone	Entire Building	175	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,368	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,578	SF	4	0-1 year	Loose, discolored

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Emergency System</u>							
	Automatic Transfer Switch	Electrical Room	2	EA	6	10+ years	
	Security System - CCTV	Entire Building	77,725	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	77,725	SF	5	6-10 years	
	Exit Signs - Auditorium	Entire Building	14	EA	4	2-5 years	Over 20 years old, deteriorating
	Exit Signs - Corridors and Stairs	Entire Building	22	EA	4	2-5 years	Over 20 years old, deteriorating
	Exit Signs - Gym	Entire Building	2	EA	4	2-5 years	Over 20 years old, deteriorating
	Exit Signs - Pool	Entire Building	5	EA	4	2-5 years	Over 20 years old, deteriorating
	Emergency A/C Power - Auditorium and Aisle Lighting	Entire Building	4,351	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	9,026	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,001	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	940	SF	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	10+ years	
	Emergency Generator- Outdoor- Natural Gas - Below 60 KW	Site West	1	EA	6	10+ years	

Main Service

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	77,725	SF	5	6-10 years	

Power Distribution

Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	17	EA	6	10+ years	
Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	

Category : Fire Protection
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarm							
	Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	77,725	SF	4	0-1 year	No strobes in classrooms
	Fire Alarm_System	Entire Building	77,725	SF	5	6-10 years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Handling Systems							
	Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 8001-12000 cfm	Basement - AHU1	1	EA	6	10+ years	AHU1, serves auditorium.
	Air Intake	Basement - AHU1	1	EA	6	10+ years	
	Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 8001-12000 cfm	Basement - AHU2	1	EA	6	10+ years	AHU-2, serves basement
	Air Intake	Basement - AHU2	1	EA	6	10+ years	
	Air Handling Unit- Package Multi Zone-Indoor- Steam Coils - 15001-20000 cfm	Basement - AHU3	1	EA	6	10+ years	AHU-3, serves 1st and 2nd floors.
	Air Intake	Basement - AHU3	1	EA	6	10+ years	
	Zone Dampers	Basement - AHU3	15	EA	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Entire Building	3	EA	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Entire Building	2	EA	6	10+ years	
	Air Handling Unit- Package Multi Zone-Indoor- Steam Coils - 10001-15000 cfm	Penthouse - AHU4	1	EA	6	10+ years	AHU-4, serves third and fourth floors.
	Air Intake	Penthouse - AHU4	1	EA	6	10+ years	
	Zone Dampers	Penthouse - AHU4	15	EA	6	10+ years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 8001-12000 cfm	Penthouse - AHU5	1	EA	6	10+ years	AHU-5, serves gym
	Air Intake	Penthouse - AHU5	1	EA	6	10+ years	
Boiler Systems							
	Boiler Auxiliary- Steam Boiler - 50 - 75 HP	Basement	2	EA	6	6-10 years	
	Chemical Feed System	Basement	1	EA	6	6-10 years	
	Combustion Dampers	Basement	2	EA	6	10+ years	
	Condensate Pump	Basement	1	EA	6	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Basement	1	EA	5	6-10 years	
	Non Condensing- Water Tube- Flexible	Basement	1	EA	6	6-10 years	
	Tube- Force Draft- Steam Boiler - 50 - 75 HP						
	Non Condensing- Water Tube- Flexible	Basement	1	EA	5	6-10 years	Tube to be replaced
	Tube- Force Draft- Steam Boiler - 50 - 75 HP						
	Piping - Condensate Pipe- Steel	Basement	400	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Basement	400	LF	5	10+ years	Some unused sections deteriorating
	Steam Traps	Basement	120	EA	5	6-10 years	
	Steam Traps	Basement	20	EA	4	0-1 year	Not in use/deteriorated
Heating Devices							
	Cabinet Heaters - With Steam Coil	221	2	EA	5	6-10 years	
	Unit Heater - Steam	Boiler Room	2	EA	6	6-10 years	
	Radiators - Steam	Entire Building	7	EA	6	10+ years	
	Radiators - Steam	Entire Building	25	EA	6	10+ years	
	Radiators - Steam	Entire Building	66	EA	6	10+ years	
	Radiators - Steam	Entire Building	22	EA	6	10+ years	
	Radiators - Steam	Entire Building	10	EA	6	10+ years	
	Fin Tube - Steam	Entire Building	80	LF	6	6-10 years	
	Fin Tube - Steam	Entire Building	46	LF	6	6-10 years	
	Fin Tube - Steam	Entire Building	8	LF	6	6-10 years	
	Fin Tube - Steam	Entire Building	20	LF	6	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	4	1-2 years	Deteriorated
Temperature Control							
	DDC System	Entire Building	77,725	SF	6	6-10 years	
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	55	EA	6	2-5 years	
Ventilation							

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	5	6-10 years	
	Roof Mounted Duct Work	Entire Building	30	LF	6	10+ years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Hot Water

	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
--	-------------------------------------	-------------	---	----	---	------------	--

Piping

	Domestic Piping-Hot Water Return Lines	Entire Building	77,725	SF	4	1-2 years	Old galvanized piping throughout
	Domestic Piping-Hot Water Return Risers	Entire Building	77,725	SF	4	1-2 years	Old galvanized piping throughout
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	77,725	SF	4	1-2 years	Old galvanized piping throughout
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	77,725	SF	4	1-2 years	Old galvanized piping throughout
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	77,725	SF	4	1-2 years	Old galvanized piping throughout
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	77,725	SF	4	1-2 years	Old galvanized piping throughout
	Sanitary Piping	Entire Building	77,725	SF	5	2-5 years	Old galvanized piping throughout
	Storm Piping	Entire Building	77,725	SF	5	2-5 years	Old galvanized piping throughout
	Vent Piping	Entire Building	77,725	SF	5	2-5 years	Old galvanized piping throughout

Pool Systems

	Pool Drain Piping	Basement	100	LF	3	0-1 year	Decommissioned/abandoned
	Pool Filtration System including Pump	Basement	1	EA	3	0-1 year	Decommissioned/abandoned
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	2	0-1 year	Decommissioned/abandoned
	Pool Hot Water Heater - Steam Heat Exchanger	Basement	1	EA	3	0-1 year	Decommissioned/abandoned
	Pool Supply and Return Piping	Basement	200	LF	3	0-1 year	Decommissioned/abandoned

Pumps

	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	2	0-1 year	Abandoned
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	5	6-10 years	For irrigation system
	Pumps - Ejector-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Pumps - Sump-Simplex	Basement	1	EA	5	2-5 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Administrative Suites/Offices

	AC Unit	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	238	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	238	SF	6	10+ years	10 SQUARE FEET OF DAMAGE.
	Lighting - Lay-in	1st Floor	6	EA	6	6-10 years	
	Storage/ Closet	1st Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	392	SF	6	10+ years	20 SQUARE FEET OF DAMAGE.
	Work Sink	1st Floor	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Floor 1.5	259	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Floor 1.5	30	SF	4	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	Floor 1.5	1	EA	7	10+ years	
	Floor - Tile	Floor 1.5	289	SF	6	10+ years	
	Lighting - Pendent/Surface	Floor 1.5	4	EA	7	6-10 years	
	Power Distribution	Floor 1.5	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Floor 1.5	327	SF	6	10+ years	
	Walls - Plaster/Drywall	Floor 1.5	5	SF	5	1-2 years	Damaged wall
	Ceiling - Exposed	Former Engineer's Office basement	1,206	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Former Engineer's Office basement	1	EA	7	10+ years	
	Floor - Concrete	Former Engineer's Office basement	1,206	SF	7	10+ years	
	Lighting - Pendent/Surface	Former Engineer's Office basement	4	EA	6	6-10 years	
	Power Distribution	Former Engineer's Office basement	10	EA	6	6-10 years	
	Storage/ Closet	Former Engineer's Office basement	10	SF	7	10+ years	
	Storage/ Closet	Former Engineer's Office basement	120	SF	7	10+ years	
	Walls - Concrete Block	Former Engineer's Office basement	650	SF	7	10+ years	
	Walls - Plaster/Drywall	Former Engineer's Office basement	736	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym Office	177	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym Office	4	SF	4	1-2 years	Damaged ceiling
	Doors - Side-lite	Gym Office	16	SF	4	1-2 years	Missing glazing
	Doors - Wood Doors inclu hw	Gym Office	1	EA	7	10+ years	
	Floor - Tile	Gym Office	181	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym Office	2	EA	7	6-10 years	
	Power Distribution	Gym Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym Office	192	SF	6	10+ years	
	Walls - Plaster/Drywall	Gym Office	6	SF	5	1-2 years	Damaged wall
	Walls - Plaster/Drywall	Gym Office	10	SF	4	1-2 years	Hole
	AC Unit	Main office suite	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main office suite	864	SF	6	10+ years	
	Doors - Steel Doors incl hw	Main office suite	1	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	Main office suite	4	EA	6	6-10 years	
	Floor - Tile	Main office suite	864	SF	4	1-2 years	Cracked throughout
	Lighting - Pendent/Surface	Main office suite	9	EA	6	6-10 years	
	Walls - Plaster/Drywall	Main office suite	1,188	SF	6	10+ years	
	Work Sink	Main office suite	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Men's Teacher's Lounge 1.5 Floor	292	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Men's Teacher's Lounge 1.5 Floor	30	SF	5	1-2 years	Cracking ceiling
	Doors - Wood Doors inclu hw	Men's Teacher's Lounge 1.5 Floor	1	EA	7	10+ years	
	Floor - Carpet	Men's Teacher's Lounge 1.5 Floor	322	SF	6	6-10 years	
	Lighting - Pendent/Surface	Men's Teacher's Lounge 1.5 Floor	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	Men's Teacher's Lounge 1.5 Floor	1	EA	5	1-2 years	Not working
	Power Distribution	Men's Teacher's Lounge 1.5 Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Men's Teacher's Lounge 1.5 Floor	370	SF	6	10+ years	
	AC Unit	Principal Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal Office	225	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal Office	1	EA	7	10+ years	
	Floor - Tile	Principal Office	225	SF	7	10+ years	
	Lighting - Pendent/Surface	Principal Office	4	EA	7	6-10 years	
	Power Distribution	Principal Office	8	EA	7	10+ years	
	Storage/ Closet	Principal Office	25	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal Office	585	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Women's Teacher's Lounge, Floor 1.5	322	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women's Teacher's Lounge, Floor 1.5	1	EA	7	10+ years	
	Floor - Tile	Women's Teacher's Lounge, Floor 1.5	300	SF	6	10+ years	
	Floor - Tile	Women's Teacher's Lounge, Floor 1.5	22	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	Women's Teacher's Lounge, Floor 1.5	5	EA	7	6-10 years	
	Power Distribution	Women's Teacher's Lounge, Floor 1.5	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Women's Teacher's Lounge, Floor 1.5	370	SF	6	10+ years	
	Walls - Plaster/Drywall	Women's Teacher's Lounge, Floor 1.5	10	SF	5	1-2 years	Damaged wall
Auditorium & Theater							
	Balcony Seating	1st Floor	150	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	4,351	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	8	EA	6	10+ years	
	Floor - Concrete	1st Floor	2,175	SF	7	10+ years	
	Floor - Tile	1st Floor	2,176	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Chandelier, Incandescent	1st Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Main Floor Seating	1st Floor	434	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	806	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	8	LF	6	10+ years	
	Stairs - Terrazzo	1st Floor	80	LF	7	2-5 years	
	Stairs - Wood	1st Floor	6	LF	6	10+ years	
	Storage/ Closet	1st Floor	300	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,753	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,251	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	500	SF	6	10+ years	

Gymnasia

	Ceiling - Plaster/Drywall	1st Floor	4,001	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	10+ years	
	Floor - Wood	1st Floor	3,981	SF	6	10+ years	
	Floor - Wood	1st Floor	20	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	1st Floor	15	EA	7	10+ years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	4,601	SF	6	10+ years	

Locker/Shower Room

	Accessories	Basement	1,900	SF	5	2-5 years	
	Benches, ped mounted	Basement	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,700	SF	6	2-5 years	
	Ceiling - Plaster/Drywall	Basement	200	SF	4	1-2 years	Damaged throughout
	Doors - Wood Doors inclu hw	Basement	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	900	SF	6	10+ years	
	Floor - Tile Quarry	Basement	900	SF	6	10+ years	
	Floor - Tile Quarry	Basement	100	SF	4	1-2 years	Broken and buckling
	Floor Drain	Basement	4	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	23	EA	6	6-10 years	
	Partitions	Basement	4	EA	5	1-2 years	Missing doors
	Showers	Basement	16	EA	5	2-5 years	Not in service
	Storage/ Closet	Basement	100	SF	5	10+ years	
	Student Lockers - One Tier	Basement	66	EA	6	10+ years	
	Urinals	Basement	3	EA	6	10+ years	
	Walls - Masonry	Basement	400	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Masonry	Basement	1,100	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	296	SF	6	10+ years	
	Water Closet	Basement	4	EA	6	6-10 years	
	Accessories	Basement	2,000	SF	5	2-5 years	
	Benches, ped mounted	Basement	30	LF	6	2-5 years	
	Ceiling - Plaster/Drywall	Basement	1,400	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	600	SF	4	1-2 years	Significant damage
	Doors - Wood Doors inclu hw	Basement	4	EA	6	10+ years	
	Floor - Concrete	Basement	1,000	SF	5	2-5 years	
	Floor - Terrazzo	Basement	1,000	SF	6	10+ years	
	Floor Drain	Basement	15	EA	7	10+ years	
	Hand Dryer	Basement	4	EA	7	6-10 years	
	Lavatory	Basement	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	25	EA	5	0-1 year	Lights not fully powered from breaker
	Partitions	Basement	30	EA	5	2-5 years	
	Showers	Basement	10	EA	4	1-2 years	Not in use
	Student Lockers - One Tier	Basement	64	EA	6	10+ years	
	Walls - Masonry	Basement	1,500	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	350	SF	6	10+ years	
	Water Closet	Basement	4	EA	6	6-10 years	

MDF_IDF

Doors - Wood Doors inclu hw	Floor 2.5	1	EA	7	10+ years	
Finishes	Floor 2.5	203	SF	5	10+ years	Floor worn and crumbling walls
Other Cooling Unit	Floor 2.5	1	EA	7	6-10 years	PTAC.

Mechanical/ Service Rooms

Janitor's Closet	1st Floor	50	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	200	SF	5	10+ years	
Storage Room	1st Floor	80	SF	7	2-5 years	
Storage Room	1st Floor	500	SF	7	10+ years	
Storage Room	1st Floor	65	SF	7	2-5 years	
Storage Room	1st Floor	65	SF	7	2-5 years	
Storage Room	1st Floor	220	SF	7	10+ years	
Janitor's Closet	2nd Floor	34	SF	5	10+ years	
Janitor's Closet	2nd Floor	34	SF	5	2-5 years	No lights
Janitor's Closet	3rd Floor	48	SF	5	2-5 years	
Janitor's Closet	3rd Floor	46	SF	5	2-5 years	No lights
Storage Room	3rd Floor	450	SF	7	10+ years	
Storage Room	3rd Floor	100	SF	7	10+ years	
Janitor's Closet	4th Floor	80	SF	5	10+ years	
Janitor's Closet	4th Floor	80	SF	5	10+ years	
Mechanical/ Service Rooms	4th Floor	88	SF	7	10+ years	
Storage Room	4th Floor	67	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Air Tunnel	Basement	1,355	SF	5	10+ years	
	Boiler Room	Basement	1,440	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	21	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	906	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	356	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,336	SF	5	10+ years	
	Storage Room	Basement	306	SF	7	10+ years	
	Storage Room	Basement	698	SF	7	10+ years	
	Storage Room	Basement	760	SF	7	10+ years	
	Storage Room	Basement	1,157	SF	7	10+ years	
	Storage Room	Basement	156	SF	5	10+ years	
	Janitor's Closet	Floor 1.5	34	SF	5	2-5 years	
	Storage Room	Floor 1.5	274	SF	7	10+ years	
	Janitor's Closet	Floor 2.5	50	SF	7	2-5 years	
	Storage Room	Floor 2.5	220	SF	7	2-5 years	
	Storage Room	Floor 2.5	214	SF	7	10+ years	

Pool & Natatorium

Accessories	Basement	3,255	SF	7	2-5 years
Bleachers Seating/Plank Seating	Basement	48	EA	6	2-5 years
Ceiling - Plaster/Drywall	Basement	3,255	SF	6	2-5 years
Doors - Steel Doors incl hw	Basement	4	EA	6	2-5 years
Floor - Concrete	Basement	555	SF	5	2-5 years
Floor - Tile Ceramic/ Porcelain	Basement	2,700	SF	6	2-5 years
Lighting - Pendent/Surface	Basement	60	EA	6	2-5 years
Pool Basin	Basement	1,740	SF	6	2-5 years
Pool Deck	Basement	960	SF	6	2-5 years
Pool Deck Drains	Basement	8	EA	7	2-5 years
Storage/ Closet	Basement	550	SF	5	2-5 years
Walls - Plaster/Drywall	Basement	1,000	SF	6	2-5 years
Walls - Plaster/Drywall	Basement	300	SF	6	2-5 years
Walls - Tile Ceramic/ Porcelain	Basement	2,600	SF	6	2-5 years

Restroom

Accessories	1st Floor	140	SF	7	6-10 years
Ceiling - Plaster/Drywall	1st Floor	140	SF	6	10+ years
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years
Floor - Tile Ceramic/ Porcelain	1st Floor	140	SF	6	10+ years
Hand Dryer	1st Floor	1	EA	7	6-10 years
Lavatory	1st Floor	2	EA	7	10+ years
Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years
Partitions	1st Floor	1	EA	7	10+ years
Urinals	1st Floor	3	EA	7	10+ years
Walls - Plaster/Drywall	1st Floor	161	SF	6	10+ years

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Structural Glazed Tile	1st Floor	50	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	140	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	140	SF	6	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Partitions	1st Floor	4	EA	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	161	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	40	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	7	6-10 years	
	Accessories	2nd Floor	140	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	130	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	10	SF	4	1-2 years	Damaged tile
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Partitions	2nd Floor	1	EA	5	1-2 years	Missing door
	Urinals	2nd Floor	2	EA	5	1-2 years	Water running
	Walls - Plaster/Drywall	2nd Floor	40	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	121	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	140	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	140	SF	6	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Partitions	2nd Floor	3	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	40	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	121	SF	6	10+ years	
	Water Closet	2nd Floor	3	EA	7	10+ years	
	Accessories	3rd Floor	140	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	2-5 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	140	SF	6	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	7	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Partitions	3rd Floor	1	EA	4	1-2 years	Stone partition separating at seems
	Urinals	3rd Floor	2	EA	5	1-2 years	Water running tank components may have failed
	Walls - Plaster/Drywall	3rd Floor	121	SF	6	10+ years	Water damaged
	Walls - Plaster/Drywall	3rd Floor	40	SF	5	1-2 years	
	Water Closet	3rd Floor	1	EA	6	10+ years	
	Accessories	3rd Floor	140	SF	5	2-5 years	
	Ceiling - Lay-in	3rd Floor	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	140	SF	6	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	6	6-10 years	
	Partitions	3rd Floor	3	EA	5	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	40	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	121	SF	6	10+ years	
	Water Closet	3rd Floor	3	EA	6	10+ years	
	Accessories	Basement	50	SF	7	2-5 years	
	Ceiling - Plaster/Drywall	Basement	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	50	SF	4	1-2 years	Worn, chipping, cracking throughout
	Lavatory	Basement	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	
	Partitions	Basement	1	EA	5	10+ years	
	Walls - Plaster/Drywall	Basement	110	SF	5	1-2 years	Damaged throughout
	Water Closet	Basement	1	EA	7	10+ years	
	Accessories	Basement	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	50	SF	6	10+ years	
	Lavatory	Basement	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	
	Partitions	Basement	1	EA	5	10+ years	
	Walls - Plaster/Drywall	Basement	90	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	20	SF	5	1-2 years	Water damaged wall
	Water Closet	Basement	1	EA	7	10+ years	
	Accessories	Men's Room on Floor 1.5	255	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's Room on Floor 1.5	255	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Men's Room on Floor 1.5	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's Room on Floor 1.5	255	SF	6	10+ years	
	Hand Dryer	Men's Room on Floor 1.5	1	EA	7	6-10 years	
	Lavatory	Men's Room on Floor 1.5	5	EA	7	10+ years	
	Lighting - Pendent/Surface	Men's Room on Floor 1.5	2	EA	6	2-5 years	
	Partitions	Men's Room on Floor 1.5	2	EA	5	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Urinals	Men's Room on Floor 1.5	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Men's Room on Floor 1.5	73	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Men's Room on Floor 1.5	220	SF	6	10+ years	
	Water Closet	Men's Room on Floor 1.5	2	EA	7	10+ years	
	Accessories	Principal Office	47	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal Office	47	SF	5	1-2 years	Cracking ceiling
	Doors - Wood Doors inclu hw	Principal Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Principal Office	47	SF	6	10+ years	
	Lavatory	Principal Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Principal Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Principal Office	96	SF	6	10+ years	
	Water Closet	Principal Office	1	EA	7	6-10 years	
	Accessories	Woman's across from Gym	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Woman's across from Gym	120	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Woman's across from Gym	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Woman's across from Gym	120	SF	6	10+ years	
	Hand Dryer	Woman's across from Gym	1	EA	7	6-10 years	
	Lavatory	Woman's across from Gym	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Woman's across from Gym	2	EA	6	10+ years	
	Walls - Plaster/Drywall	Woman's across from Gym	100	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Woman's across from Gym	95	SF	7	10+ years	
	Water Closet	Woman's across from Gym	1	EA	7	10+ years	
	Accessories	Women's Room, Floor 1.5	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's Room, Floor 1.5	220	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women's Room, Floor 1.5	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Room, Floor 1.5	200	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Room, Floor 1.5	20	SF	4	1-2 years	Cracked tile
	Lavatory	Women's Room, Floor 1.5	5	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's Room, Floor 1.5	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	Women's Room, Floor 1.5	1	EA	5	1-2 years	Not working
	Partitions	Women's Room, Floor 1.5	5	EA	5	10+ years	
	Walls - Masonry	Women's Room, Floor 1.5	50	SF	6	10+ years	
	Walls - Plaster/Drywall	Women's Room, Floor 1.5	253	SF	6	10+ years	
	Water Closet	Women's Room, Floor 1.5	5	EA	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #02 (Office)							
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	12	LF	6	10+ years	
	Ceiling - Lay-in	Basement	25	SF	4	0-1 year	Missing.
	Ceiling - Plaster/Drywall	Basement	704	SF	6	10+ years	
	Chalk Board	Basement	15	LF	4	2-5 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years	
	Floor - Tile	Basement	754	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	50	SF	6	10+ years	
	Lighting - Lay-in	Basement	6	EA	6	10+ years	
	Storage/ Closet	Basement	10	SF	5	6-10 years	
	Walls - Plaster/Drywall	Basement	1,508	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroom #021 (Vacant)							
	Ceiling - Plaster/Drywall	Basement	350	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	350	SF	6	10+ years	
	Lighting - Lay-in	Basement	7	EA	7	6-10 years	
	Walls - Masonry	Basement	200	SF	5	1-2 years	Damaged walls throughout
	Walls - Plaster/Drywall	Basement	500	SF	6	2-5 years	
	Walls - Plaster/Drywall	Basement	200	SF	5	1-2 years	Extension damage to walls throughout
Classroom #025 (Store Room)							
	Casework	Basement	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	824	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	724	SF	6	6-10 years	
	Floor - Tile	Basement	100	SF	4	1-2 years	Damaged and missing tile
	Lighting - Pendent/Surface	Basement	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement	1,242	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	30	SF	5	1-2 years	Damaged wall
	Work Sink	Basement	1	EA	7	6-10 years	
Classroom #03 (Store Room)							
	Ceiling - Lay-in	Basement	50	SF	4	0-1 year	Missing tiles.
	Ceiling - Plaster/Drywall	Basement	1,138	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	1,148	SF	6	10+ years	
	Floor - Tile	Basement	40	SF	4	1-2 years	Missing tiles
	Lighting - Lay-in	Basement	13	EA	6	6-10 years	
	Storage/ Closet	Basement	8	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	2,000	SF	6	10+ years	
Classroom #121 (Multi Purpose Room)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	905	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	1st Floor	775	SF	6	10+ years	
	Floor - Tile	1st Floor	130	SF	4	1-2 years	Damaged and broken tile
	Lighting - Lay-in	1st Floor	17	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	28	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,522	SF	6	10+ years	
Classroom #122 (Library)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,058	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,058	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Not working
	Storage/ Closet	1st Floor	72	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,986	SF	6	10+ years	
Classroom #123 (Multi Purpose Room)							
	Ceiling - Plaster/Drywall	1st Floor	964	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	964	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,462	SF	6	10+ years	
Classroom #221 (Science Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	78	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	832	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	832	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	220	SF	5	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	1,151	SF	6	10+ years	
	Work Sink	2nd Floor	7	EA	7	6-10 years	
Classroom #222 (Other Instructional Use)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	780	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	18	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,204	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	6	2-5 years	
Classroom #223 (Store Room)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	768	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years	
Classroom #224 (Other Instructional Use)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	774	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	774	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	11	EA	6	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,332	SF	6	10+ years	
Classroom #225 (Store Room)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	488	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	486	SF	6	10+ years	
	Floor - Tile	2nd Floor	2	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	2nd Floor	8	EA	6	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	625	SF	6	10+ years	
Classroom #226 (Other Instructional Use)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	545	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	535	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	658	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #227 (Vacant)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	790	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	790	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	124	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,292	SF	6	10+ years	
Classroom #229 (Office)							
	Ceiling - Plaster/Drywall	2nd Floor	476	SF	6	10+ years	Damaged plaster ceiling
	Ceiling - Plaster/Drywall	2nd Floor	8	SF	4	1-2 years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	484	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	572	SF	6	10+ years	
Classroom #321 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	627	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	627	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	87	SF	7	10+ years	
	Storage/ Closet	3rd Floor	58	SF	5	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	725	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	4	1-2 years	Not in use no water
Classroom #322 (Store Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	768	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	96	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,173	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	15	SF	5	1-2 years	Damaged wall

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #323 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	758	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	743	SF	6	6-10 years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Cracking at transition strip
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,238	SF	6	10+ years	
Classroom #324 (Office)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	365	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	2-5 years	Damaged ceiling
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile	3rd Floor	375	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	704	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Cracking walls
Classroom #325 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	761	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	741	SF	6	10+ years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Damaged buckling flooring
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,450	SF	6	10+ years	
Classroom #326 (Store Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	568	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	568	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	3rd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	998	SF	6	10+ years	
Classroom #327 (Band Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	824	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	3	SF	4	1-2 years	Falling tile/ missing
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Carpet	3rd Floor	827	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Risers	3rd Floor	20	LF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	10+ years	
Classroom #328 (Store Room)							
	Ceiling - Lay-in	3rd Floor	100	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	245	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	1-2 years	Damaged ceiling
	Chalk Board	3rd Floor	3	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	355	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	410	SF	6	10+ years	
Classroom #329 (Office)							
	Ceiling - Plaster/Drywall	3rd Floor	484	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	484	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	6-10 years	
	Marker Board	3rd Floor	34	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	557	SF	6	10+ years	
Classroom #330 (Store Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	573	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	30	SF	4	1-2 years	Damaged ceiling
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile	3rd Floor	603	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	682	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	4	1-2 years	Damaged plaster
Classroom #421 (Play Room)							
	AC Units	4th Floor	1	EA	7	2-5 years	
	Ceiling - Splined	4th Floor	648	SF	6	10+ years	
	Doors - Steel Doors incl hw	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	628	SF	6	6-10 years	
	Floor - Tile	4th Floor	20	SF	4	1-2 years	Damaged chipped tile
	Lighting - Pendent/Surface	4th Floor	9	EA	6	6-10 years	
	Marker Board	4th Floor	11	LF	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,224	SF	6	10+ years	

Classroom #422 (Play Room)

	AC Units	4th Floor	2	EA	7	6-10 years	
	Ceiling - Splined	4th Floor	638	SF	6	10+ years	
	Ceiling - Splined	4th Floor	10	SF	4	1-2 years	Area of damaged / missing tile
	Doors - Steel Doors incl hw	4th Floor	1	EA	6	10+ years	
	Floor - Tile	4th Floor	628	SF	6	10+ years	
	Floor - Tile	4th Floor	20	SF	4	1-2 years	Damaged chipped tile
	Lighting - Pendent/Surface	4th Floor	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,080	SF	6	10+ years	
	Walls - Plaster/Drywall	4th Floor	8	SF	5	1-2 years	Cracks in wall

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,983	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	278	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	4,261	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	47	EA	7	6-10 years	
	Stairs - Concrete Stairs	1st Floor	18	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,580	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,021	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	1,021	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,174	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,021	SF	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	7	6-10 years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Terrazzo	3rd Floor	1,021	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,174	SF	6	10+ years	
	Ceiling - Lay-in	4th Floor	545	SF	7	10+ years	
	Drinking Fountains - Single Fountain	4th Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	4th Floor	545	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	627	SF	6	10+ years	
	Ceiling - Lay-in	Basement	1,134	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,234	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	10	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Basement	2	EA	7	6-10 years	
	Floor - Tile Quarry	Basement	720	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	1,540	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	108	SF	7	2-5 years	
	Lighting - Lay-in	Basement	22	EA	7	6-10 years	
	Student Lockers - Two Tiers	Basement	44	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	2,980	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Floor 1.5	294	SF	6	10+ years	
	Floor - Terrazzo	Floor 1.5	294	SF	6	10+ years	
	Lighting - Pendent/Surface	Floor 1.5	5	EA	7	6-10 years	
	Walls - Plaster/Drywall	Floor 1.5	333	SF	6	10+ years	
	Walls - Plaster/Drywall	Floor 1.5	5	SF	5	1-2 years	Damaged wall
	Ceiling - Plaster/Drywall	Floor 2.5	342	SF	6	10+ years	
	Floor - Terrazzo	Floor 2.5	342	SF	7	10+ years	
	Lighting - Pendent/Surface	Floor 2.5	5	EA	7	6-10 years	
	Walls - Plaster/Drywall	Floor 2.5	338	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire Building	3	EA	7	6-10 years	
	Security Cameras	Entire Building	20	EA	7	6-10 years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	1.5-2.5	200	SF	7	10+ years	
	Floor - Terrazzo	1.5-2.5	60	SF	7	10+ years	
	Handrails	1.5-2.5	85	LF	7	10+ years	
	Lighting - Pendent/Surface	1.5-2.5	4	EA	7	10+ years	
	Stairs - Terrazzo	1.5-2.5	120	LF	7	10+ years	
	Walls - Plaster/Drywall	1.5-2.5	220	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	80	SF	7	10+ years	
	Floor - Terrazzo	Basement	110	SF	7	10+ years	
	Handrails	Basement	60	LF	7	10+ years	
	Lighting - Pendent/Surface	Basement	2	EA	7	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Stairs - Terrazzo	Basement	120	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement	120	SF	7	10+ years	
	Ceiling - Plaster/Drywall	East	1,147	SF	6	10+ years	
	Floor - Terrazzo	East	1,147	SF	6	10+ years	
	Handrails	East	206	LF	7	10+ years	
	Lighting - Pendent/Surface	East	7	EA	6	6-10 years	
	Lighting - Pendent/Surface	East	2	EA	5	0-1 year	Not working
	Stairs - Terrazzo	East	736	LF	6	10+ years	Updated quantity
	Stairs - Terrazzo	East	8	LF	4	0-1 year	Damaged treads
	Walls - Plaster/Drywall	East	1,318	SF	6	10+ years	Cracking plaster
	Ceiling - Plaster/Drywall	North East	200	SF	7	10+ years	
	Floor - Terrazzo	North East	60	SF	7	10+ years	
	Handrails	North East	85	LF	7	10+ years	
	Lighting - Pendent/Surface	North East	4	EA	7	10+ years	
	Stairs - Terrazzo	North East	120	LF	7	10+ years	
	Walls - Plaster/Drywall	North East	220	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West	1,218	SF	6	10+ years	
	Floor - Terrazzo	West	1,218	SF	6	10+ years	
	Handrails	West	218	LF	7	10+ years	
	Handrails	West	6	LF	4	1-2 years	Missing spindles in railing
	Lighting - Lay-in	West	2	EA	5	1-2 years	Not working
	Lighting - Pendent/Surface	West	7	EA	6	6-10 years	
	Stairs - Terrazzo	West	732	LF	6	2-5 years	
	Stairs - Terrazzo	West	6	LF	4	1-2 years	Missing tread cover
	Walls - Plaster/Drywall	West	218	SF	6	10+ years	

Category : Exterior
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Entrance Control - Audio	#1 Main - W	1	EA	7	10+ years	
	Entrance Control - Audio and Video	#1 Main - W	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#1 Main - W	4	EA	6	6-10 years	
	Exterior Doors - Side lite	#1 Main - W	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 Main - W	5	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1 Main - W	24	LF	7	10+ years	
	Ramps - Concrete	#1 Main - W	18	LF	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 - W	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - W	1	EA	6	10+ years	
	Exterior Doors - Side lite	#3 - W	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3 - W	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 - W	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#4 - W	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#5 - W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 - W	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 - N	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#6 - N	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 - N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 - N	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7 - N	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#7 - N	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#7 - N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 - N	12	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#8 Exit - E	2	EA	6	6-10 years	
Foundation							
	Foundation - Concrete	Entire Building	610	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	38,925	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	7	6-10 years	Led upgrade
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	6-10 years	
Roof System							
	Access Ladder - Metal	1 - Main Roof	1	EA	7	10+ years	
	Coping - Metal	1 - Main Roof	463	LF	6	10+ years	
	Downspouts - Interior Downspouts	1 - Main Roof	84	LF	6	10+ years	
	Parapet - Parapet < 16" Height	1 - Main Roof	463	LF	6	10+ years	
	Roof - Modified Bitumen	1 - Main Roof	11,002	SF	4	0-1 year	Bubbling, seam separation, deteriorated
	Roof Hatch - Metal	1 - Main Roof	1	EA	7	10+ years	

Category : Exterior
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Roof Structure - Concrete	1 - Main Roof	11,002	SF	7	10+ years	
	Chimney - Metal Flue	North Roof	14	LF	6	10+ years	
	Coping - Metal	North Roof	218	LF	6	10+ years	
	Downspouts - Interior Downspouts	North Roof	26	LF	6	10+ years	
	Parapet - Parapet < 16" Height	North Roof	218	LF	6	10+ years	
	Roof - Modified Bitumen	North Roof	5,382	SF	4	0-1 year	Bubbling, cracking seams
	Roof Structure - Concrete	North Roof	5,382	SF	7	10+ years	
	Coping - Metal	West Roof	32	LF	6	10+ years	
	Coping - Stone	West Roof	36	LF	6	10+ years	
	Downspouts - Interior Downspouts	West Roof	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	West Roof	36	LF	6	10+ years	
	Roof - Modified Bitumen	West Roof	670	SF	5	2-5 years	
	Roof Structure - Concrete	West Roof	670	SF	7	10+ years	

Walls

Canopy - Concrete/ Stucco	Entire Building	32	SF	6	10+ years	
Exterior Walls - Brick	Entire Building	10,650	SF	6	10+ years	
Exterior Walls - Brick	Entire Building	800	SF	5	2-5 years	
Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	2,000	SF	6	10+ years	

Windows

Curtain wall - Glazed Double Pane	Entire Building	4,850	SF	4	1-2 years	Windows have bad balancers
Curtain wall - Insulated Panel	Entire Building	2,012	SF	6	6-10 years	
Guard - Guards perforated	Entire Building	2,240	SF	6	10+ years	
Lintels - Concrete	Entire Building	10	LF	4	0-1 year	Spalling, exposed rebar
Lintels - Steel	Entire Building	988	LF	6	10+ years	
Windows - Sash Aluminum Double-pane	Entire Building	684	SF	6	6-10 years	
Windows - Sash Aluminum Double-pane	Entire Building	36	SF	4	1-2 years	Windows have bad balancers

Category : Electrical
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergency System							
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	9,044	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,536	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,227	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	21	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	8	EA	6	6-10 years	

Category : Electrical
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	4	2-5 years	Over 20 years old, deteriorating
	Exit Signs - Lunchroom	Entire Building	2	EA	4	2-5 years	Over 20 years old, deteriorating
	Security System - CCTV	Entire Building	38,925	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	38,925	SF	6	6-10 years	

Main Service

Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
PA System	Entire Building	38,925	SF	5	6-10 years	

Power Distribution

Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	12	EA	7	10+ years	
Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	

Category : Fire Protection
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alarm</u>							
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building	38,925	SF	7	10+ years	
	Fire Alarm_System	Entire Building	38,925	SF	7	10+ years	New system

Category : Mechanical
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Boiler Systems</u>							
	Boiler Auxiliary- Steam Boiler - 50 - 75 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Steam Boiler - 50 - 75 HP	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Steam Boiler - 50 - 75 HP	Boiler Room	1	EA	5	6-10 years	Tube to be replaced
	Piping - Condensate Pipe- Steel	Boiler Room	200	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	200	LF	6	10+ years	
	Steam Traps	Boiler Room	150	EA	5	6-10 years	

Category : Mechanical
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Vacuum Pump	Boiler Room	1	EA	5	2-5 years	Basin corroding
Heating Devices							
	Duct Heater - Electric	117	1		6	10+ years	
	Unit Heater - Electric	Boiler Room	1	EA	6	6-10 years	
	Wall Heater - Electric	Electrical Room	1	EA	6	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	2	EA	5	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	3	EA	5	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	6	EA	5	6-10 years	
	Fin Tube - Steam	Entire Building	250	LF	5	6-10 years	
	Fin Tube - Steam	Entire Building	250	LF	5	6-10 years	
	Fin Tube - Steam	Entire Building	250	LF	5	2-5 years	Some covers falling off
Temperature Control							
	DDC System	Entire Building	38,925	SF	2	0-1 year	Not operational
	Electric Thermostat	Entire Building	2	EA	6	10+ years	
	Thermostats - DDC	Entire Building	27	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	11	EA	4	1-2 years	Old and not in use
	Thermostats - DDC	Entire Building	8	EA	4	1-2 years	Old and not in use
	Thermostats - DDC	Entire Building	8	EA	4	1-2 years	Old and not in use
Unit Ventilation							
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	11	EA	5	6-10 years	
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	8	EA	5	6-10 years	
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	8	EA	5	6-10 years	
	Unit Ventilators- Ceiling Mounted- Steam Heating Coils Only	Kitchen Storage Room	1	EA	2	0-1 year	Old and not in use
Ventilation							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	3	0-1 year	Old and not used
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	5	2-5 years	Excessive vibration
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	5	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	5	6-10 years	

Category : Mechanical
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Category : Plumbing
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Hot Water

	Gas Heater - 150000 - 300000 BTU/HR	1st Floor	1	EA	6	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	1st Floor	1	EA	2	0-1 year	Decommissioned/abandoned

Piping

	Domestic Piping-Hot Water Return Lines	Entire Building	38,925	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	38,925	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	38,925	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	38,925	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	38,925	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	38,925	SF	6	10+ years	
	Sanitary Piping	Entire Building	38,925	SF	5	6-10 years	
	Storm Piping	Entire Building	38,925	SF	5	6-10 years	
	Vent Piping	Entire Building	38,925	SF	5	6-10 years	

Category : Room
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Administrative Suites/Offices

	Ceiling - Splined	Dean's office	183	SF	6	10+ years	
	Doors - Side-lite	Dean's office	90	SF	7	10+ years	
	Doors - Transom Window	Dean's office	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Dean's office	1	EA	7	10+ years	
	Floor - Tile	Dean's office	183	SF	6	10+ years	
	Lighting - Pendent/Surface	Dean's office	4	EA	7	6-10 years	
	Power Distribution	Dean's office	4	EA	7	10+ years	
	Walls - Concrete Block	Dean's office	213	SF	6	10+ years	
	Ceiling - Exposed	Kitchen Manager's Office	142	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Manager's Office	1	EA	7	10+ years	
	Floor - Tile	Kitchen Manager's Office	142	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen Manager's Office	2	EA	6	6-10 years	
	Power Distribution	Kitchen Manager's Office	4	EA	6	10+ years	
	Walls - Concrete Block	Kitchen Manager's Office	163	SF	6	10+ years	
	AC Unit	Principals office 1st floor	1	EA	7	6-10 years	
	Ceiling - Splined	Principals office 1st floor	1,470	SF	6	10+ years	

Category : Room
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	Principals office 1st floor	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principals office 1st floor	1	EA	7	10+ years	
	Floor - Tile	Principals office 1st floor	1,465	SF	6	10+ years	
	Floor - Tile	Principals office 1st floor	5	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	Principals office 1st floor	30	EA	7	6-10 years	
	Storage/ Closet	Principals office 1st floor	352	SF	7	10+ years	
	Walls - Concrete Block	Principals office 1st floor	2,060	SF	6	10+ years	
	Work Slnk	Principals office 1st floor	1	EA	7	10+ years	
Kitchen							
	Ceiling - Splined	1st Floor	576	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	556	SF	6	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	423	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	662	SF	6	10+ years	
Lunch & Multipurpose Room							
	Ceiling - Plaster/Drywall	1st Floor	257	SF	6	10+ years	
	Ceiling - Splined	1st Floor	2,279	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	2,526	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	2,187	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	729	SF	6	10+ years	
	Ceiling - Splined	Servery	1,076	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Servery	3	EA	6	10+ years	
	Floor - Tile	Servery	1,066	SF	6	10+ years	
	Floor - Tile	Servery	10	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Pendent/Surface	Servery	19	EA	7	6-10 years	
	Serving Line	Servery	44	LF	7	10+ years	
	Storage/ Closet	Servery	175	SF	7	10+ years	
	Walls - Structural Glazed Tile	Servery	1,273	SF	6	10+ years	
MDF_IDE							
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Finishes	3rd Floor	143	SF	7	10+ years	
	Other Cooling Unit	3rd Floor	1	EA	7	6-10 years	PTAC
Mechanical/ Service Rooms							
	Boiler Room	1st Floor	425	SF	7	10+ years	

Category : Room
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Janitor's Closet	1st Floor	75	SF	5	2-5 years	
	Mechanical/ Service Rooms	1st Floor	80	SF	7	10+ years	
	Vaults	1st Floor	84	SF	7	10+ years	
	Janitor's Closet	2nd Floor	26	SF	5	10+ years	
	Storage Room	2nd Floor	110	SF	7	10+ years	
	Storage Room	2nd Floor	110	SF	7	2-5 years	
	Janitor's Closet	3rd Floor	26	SF	7	10+ years	
	Storage Room	3rd Floor	110	SF	5	2-5 years	

Restroom

	Accessories	1st Floor	177	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	177	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	177	SF	6	10+ years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Partitions	1st Floor	3	EA	7	10+ years	
	Urinals	1st Floor	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	204	SF	6	10+ years	
	Water Closet	1st Floor	3	EA	7	10+ years	
	Accessories	1st Floor	232	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	232	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	232	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Partitions	1st Floor	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	267	SF	6	10+ years	
	Water Closet	1st Floor	5	EA	7	10+ years	
	Accessories	1st floor womens	81	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor womens	36	SF	6	10+ years	
	Ceiling - Splined	1st floor womens	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor womens	2	EA	7	10+ years	
	Floor - Tile	1st floor womens	43	SF	6	10+ years	
	Floor - Tile	1st floor womens	2	SF	4	1-2 years	Cracking tile
	Floor - Tile Ceramic/ Porcelain	1st floor womens	36	SF	6	10+ years	
	Floor Drain	1st floor womens	1	EA	7	10+ years	
	Lavatory	1st floor womens	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor womens	2	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st floor womens	220	SF	6	10+ years	
	Water Closet	1st floor womens	1	EA	7	10+ years	
	Accessories	2nd Floor	177	SF	5	2-5 years	
	Ceiling - Lay-in	2nd Floor	127	SF	6	10+ years	

Category : Room
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Splined	2nd Floor	50	SF	7	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	177	SF	6	10+ years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	3	EA	7	6-10 years	
	Partitions	2nd Floor	3	EA	7	10+ years	
	Urinals	2nd Floor	2	EA	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	196	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	8	SF	4	1-2 years	Damaged behind toilet
	Water Closet	2nd Floor	3	EA	6	6-10 years	
	Accessories	2nd Floor	232	SF	7	2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor	232	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	232	SF	6	10+ years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	
	Partitions	2nd Floor	5	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	267	SF	6	10+ years	
	Water Closet	2nd Floor	5	EA	6	6-10 years	
	Accessories	3rd Floor	177	SF	7	6-10 years	
	Ceiling - Splined	3rd Floor	177	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	175	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	2	SF	4	1-2 years	Damaged tile
	Lavatory	3rd Floor	2	EA	6	6-10 years	
	Lighting - Lay-in	3rd Floor	2	EA	7	6-10 years	
	Partitions	3rd Floor	3	EA	7	10+ years	
	Urinals	3rd Floor	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	204	SF	6	10+ years	
	Water Closet	3rd Floor	3	EA	7	10+ years	
	Accessories	3rd Floor	232	SF	7	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	232	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	232	SF	6	10+ years	
	Lavatory	3rd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	6	6-10 years	
	Partitions	3rd Floor	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	264	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	3	SF	4	1-2 years	Damaged wall
	Water Closet	3rd Floor	5	EA	7	6-10 years	
	Accessories	In Kitchen Area	76	SF	7	6-10 years	
	Ceiling - Splined	In Kitchen Area	74	SF	6	10+ years	
	Ceiling - Splined	In Kitchen Area	2	SF	4	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	In Kitchen Area	2	EA	7	10+ years	

Category : Room
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	In Kitchen Area	76	SF	6	10+ years	
	Lavatory	In Kitchen Area	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Kitchen Area	2	EA	6	6-10 years	
	Lighting - Wall Mounted	In Kitchen Area	1	EA	6	6-10 years	
	Student Lockers - One Tier	In Kitchen Area	11	EA	7	10+ years	
	Walls - Structural Glazed Tile	In Kitchen Area	87	SF	6	10+ years	
	Water Closet	In Kitchen Area	1	EA	6	10+ years	
	Accessories	Men's Room, 1st Floor	89	SF	7	6-10 years	
	Ceiling - Splined	Men's Room, 1st Floor	89	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Men's Room, 1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's Room, 1st Floor	89	SF	6	10+ years	
	Floor Drain	Men's Room, 1st Floor	1	EA	7	10+ years	
	Lavatory	Men's Room, 1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Men's Room, 1st Floor	1	EA	7	6-10 years	
	Partitions	Men's Room, 1st Floor	1	EA	7	10+ years	
	Urinals	Men's Room, 1st Floor	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Men's Room, 1st Floor	102	SF	6	10+ years	
	Water Closet	Men's Room, 1st Floor	1	EA	7	10+ years	
	Accessories	Men's Room, 2nd Floor	35	SF	5	2-5 years	
	Ceiling - Splined	Men's Room, 2nd Floor	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Men's Room, 2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's Room, 2nd Floor	35	SF	6	10+ years	
	Lavatory	Men's Room, 2nd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Men's Room, 2nd Floor	1	EA	7	6-10 years	
	Partitions	Men's Room, 2nd Floor	2	EA	7	6-10 years	
	Urinals	Men's Room, 2nd Floor	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Men's Room, 2nd Floor	40	SF	6	10+ years	
	Water Closet	Men's Room, 2nd Floor	2	EA	6	6-10 years	
	Accessories	Room 112	32	SF	7	6-10 years	
	Ceiling - Lay-in	Room 112	32	SF	6	10+ years	
	Doors - Transom Window	Room 112	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 112	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 112	32	SF	6	10+ years	
	Lavatory	Room 112	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 112	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 112	30	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Room 112	30	SF	6	10+ years	
	Water Closet	Room 112	1	EA	7	10+ years	
	Accessories	Room 117	80	SF	7	6-10 years	
	Ceiling - Lay-in	Room 117	76	SF	6	10+ years	
	Ceiling - Lay-in	Room 117	4	SF	4	1-2 years	Missing tile
	Doors - Wood Doors inclu hw	Room 117	1	EA	7	10+ years	
	Floor - Tile	Room 117	80	SF	6	10+ years	
	Floor Drain	Room 117	1	EA	7	10+ years	

Category : Room
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	Room 117	1	EA	7	10+ years	
	Lighting - Lay-in	Room 117	1	EA	7	6-10 years	
	Walls - Concrete Block	Room 117	70	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Room 117	0	SF	6	10+ years	
	Water Closet	Room 117	1	EA	7	10+ years	
	Accessories	Women's Room, 3rd Floor	35	SF	5	2-5 years	
	Ceiling - Splined	Women's Room, 3rd Floor	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women's Room, 3rd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Room, 3rd Floor	35	SF	6	10+ years	
	Lavatory	Women's Room, 3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's Room, 3rd Floor	1	EA	7	6-10 years	
	Partitions	Women's Room, 3rd Floor	2	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Women's Room, 3rd Floor	40	SF	6	10+ years	
	Water Closet	Women's Room, 3rd Floor	2	EA	7	10+ years	

Category : Classroom
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #112 (Pre School)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,417	SF	6	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,417	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	34	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,518	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	180	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroom #116 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	775	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	670	SF	6	10+ years	

Category : Classroom
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #117 (Pre School)</u>							
	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,162	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Stained tile
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,170	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,345	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
<u>Classroom #118 (Kindergarten)</u>							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Splined	1st Floor	775	SF	6	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	763	SF	6	10+ years	
	Floor - Tile	1st Floor	12	SF	4	1-2 years	Cracking tile
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	670	SF	6	10+ years	
<u>Classroom #212 (Other Instructional Use)</u>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	771	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	4	SF	4	1-2 years	Missing and damaged tile
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	771	SF	6	10+ years	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	670	SF	6	10+ years	
<u>Classroom #214 (Regular Classroom)</u>							

Category : Classroom
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	775	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	773	SF	7	10+ years	
	Floor - Tile	2nd Floor	2	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	670	SF	6	10+ years	

Classroom #215 (Regular Classroom)

AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	6	LF	6	6-10 years	
Ceiling - Splined	2nd Floor	775	SF	6	10+ years	
Chalk Board	2nd Floor	12	LF	4	2-5 years	
Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
Floor - Tile	2nd Floor	761	SF	7	10+ years	
Floor - Tile	2nd Floor	14	SF	4	1-2 years	Damaged and missing tile
Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
Marker Board	2nd Floor	16	LF	7	6-10 years	
Storage/ Closet	2nd Floor	4	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	891	SF	6	10+ years	

Classroom #216 (Regular Classroom)

AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	6	LF	6	6-10 years	
Ceiling - Splined	2nd Floor	775	SF	6	10+ years	
Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Tile	2nd Floor	765	SF	6	10+ years	
Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged tile
Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
Marker Board	2nd Floor	16	LF	7	6-10 years	
Storage/ Closet	2nd Floor	36	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	670	SF	6	10+ years	

Classroom #217 (Regular Classroom)

Category : Classroom
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	775	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	891	SF	6	10+ years	
Classroom #218 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	775	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	670	SF	6	10+ years	
Classroom #219 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	775	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	765	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	891	SF	6	10+ years	
Classroom #220 (Faculty Lounge)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	

Category : Classroom
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Splined	2nd Floor	775	SF	6	10+ years	Cracked and damaged tile
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	6	10+ years	
	Floor - Tile	2nd Floor	25	SF	4	1-2 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	670	SF	6	10+ years	
Classroom #312 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	Cracked and damaged tile
	Ceiling - Splined	3rd Floor	775	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Floor - Tile	3rd Floor	765	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	670	SF	6	10+ years	
Classroom #314 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	Damaged flooring
	Ceiling - Splined	3rd Floor	775	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Floor - Tile	3rd Floor	755	SF	6	10+ years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	780	SF	6	10+ years	
Classroom #315 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	775	SF	6	6-10 years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	

Category : Classroom
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	3rd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	891	SF	6	10+ years	
Classroom #316 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	775	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Floor - Tile	3rd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	670	SF	6	10+ years	
Classroom #317 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	775	SF	6	6-10 years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Floor - Tile	3rd Floor	765	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Damaged floor
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	891	SF	6	10+ years	
Classroom #318 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	775	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Floor - Tile	3rd Floor	755	SF	6	10+ years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	

Category : Classroom
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	3rd Floor	36	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	670	SF	6	10+ years	

Classroom #319 (Regular Classroom)

	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	775	SF	6	6-10 years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Floor - Tile	3rd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	891	SF	6	10+ years	

Classroom #320 (Other Instructional Use)

	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	775	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Floor - Tile	3rd Floor	770	SF	6	10+ years	
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	670	SF	6	10+ years	

Category : Interior
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Corridor</u>							
	Ceiling - Splined	1st Floor	2,716	SF	7	10+ years	
	Ceiling - Splined	1st Floor	20	SF	4	1-2 years	Damaged tile
	Doors - Wood Doors include hw	1st Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	384	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	2,352	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	86	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,145	SF	6	10+ years	

Category : Interior
Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Structural Glazed Tile	1st Floor	1	SF	4	1-2 years	Damaged wall
	Ceiling - Splined	2nd Floor	2,345	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	20	SF	4	1-2 years	Damaged tile
	Doors - Wood Doors include hw	2nd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	2-5 years	
	Floor - Tile/Sheet	2nd Floor	2,335	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	30	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	86	EA	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	2,720	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	2,365	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	2,365	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	19	EA	6	6-10 years	
	Student Lockers - One Tier	3rd Floor	86	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor	2,720	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	
	Security Cameras	Entire Building	15	EA	7	6-10 years	
Stairs							
	Ceiling - Splined	East	789	SF	6	2-5 years	
	Floor - Asphalt	East	389	SF	6	10+ years	
	Floor - Tile	East	350	SF	7	6-10 years	
	Floor - Tile	East	50	SF	4	1-2 years	Damaged tile
	Handrails	East	180	LF	7	10+ years	
	Lighting - Pendent/Surface	East	18	EA	7	6-10 years	
	Stairs - Asphalt	East	336	LF	6	10+ years	
	Walls - Structural Glazed Tile	East	639	SF	6	10+ years	
	Walls - Structural Glazed Tile	East	639	SF	6	10+ years	
	Ceiling - Splined	West	789	SF	6	2-5 years	
	Floor - Asphalt	West	399	SF	6	10+ years	
	Floor - Tile	West	390	SF	7	6-10 years	
	Handrails	West	180	LF	7	10+ years	
	Lighting - Pendent/Surface	West	18	EA	7	6-10 years	
	Stairs - Asphalt	West	336	LF	6	10+ years	Updated quantity
	Walls - Structural Glazed Tile	West	639	SF	6	10+ years	
	Walls - Structural Glazed Tile	West	639	SF	6	10+ years	

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Civil/Drainage</u>							
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	5	2-5 years	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	10+ years	
<u>Fencing</u>							
	Fencing - Chain Link	North Coutyard, North and Entire site	131	LF	7	10+ years	Replaced
	Fencing - New Standard Ornamental	North Coutyard, North and Entire site	906	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	North Coutyard, North and Entire site	556	LF	6	6-10 years	
	Fencing - Wood Fencing w/ Steel Frame	North Coutyard, North and Entire site	110	LF	5	2-5 years	Areas fixed
<u>Landscape</u>							
	Benches	Entire Site	15	EA	6	10+ years	Replaced
	Landscape - Grass	Entire Site	16,606	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	3,550	SF	6	10+ years	
	Landscape - Mulch	Entire Site	50	SF	6	6-10 years	
	Parkway trees	Entire Site	26	EA	6	10+ years	
	Parkway trees	Entire Site	2	EA	4	0-1 year	Missing trees
	Planting Beds/ Area	Entire Site	15,355	SF	6	10+ years	
	Play Area - Hardscape- Pavers	Entire Site	9,800	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	530	SF	6	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
<u>Parking Lot</u>							
	Concrete Curbs	Northeast Courtyard	566	LF	7	10+ years	
	Interior Plantings	Northeast Courtyard	250	LF	7	10+ years	
	Surface - Asphalt	Northeast Courtyard	17,404	SF	5	2-5 years	
	Trash Enclosure - Wood	Northeast Courtyard	601	SF	4	1-2 years	Broken slats
<u>Playground</u>							
	Equipment - Combo 3-12	North of annex	1	EA	6	6-10 years	
	Surface - Poured Surface	North of annex	906	SF	4	0-1 year	Vegetation growth
<u>Sidewalks</u>							
	Sidewalks - Internal Walks	Entire Site	265	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	17,000	SF	6	10+ years	

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	550	SF	4	0-1 year	Cracked.
Signage							
	Flag Pole - Building Mounted Flag Pole	South Courtyard	2	EA	6	10+ years	
	Flag Pole - Flag Pole	South Courtyard	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	South Courtyard	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	South Courtyard	1	EA	6	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Building : Main									
Band Room	Regular Classroom	3rd Floor	327	307	827	129	64	N	N
Library	Regular Classroom	1st Floor	122	102	1,058	120	50	N	N
Multi Purpose Room	Regular Classroom	1st Floor	121	101	905	72	36	N	N
Multi Purpose Room	Regular Classroom	1st Floor	123	103	964	72	36	N	Y
Office	Regular Classroom	2nd Floor	229	208	484	96	12	N	N
Office	Regular Classroom	3rd Floor	324	304	375	18	3	N	N
Office	Regular Classroom	3rd Floor	329	309	484	96	12	N	N
Office	Regular Classroom	Basement	02	02	754	45	0	N	N
Other Instructional Use	Regular Classroom	2nd Floor	222	202	780	84	12	N	N
Other Instructional Use	Regular Classroom	2nd Floor	224	204	774	54	3	N	N
Other Instructional Use	Regular Classroom	2nd Floor	226	206	545	144	18	N	N
Play Room	Regular Classroom	4th Floor	421	401	648	18	18	N	N
Play Room	Regular Classroom	4th Floor	422	402	648	18	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	321	301	627	84	6	N	N
Regular Classroom	Regular Classroom	3rd Floor	323	303	763	72	9	N	Y
Regular Classroom	Regular Classroom	3rd Floor	325	305	761	18	12	N	Y
Science Classroom	Regular Classroom	2nd Floor	221	201	832	132	66	N	N
Store Room	Regular Classroom	2nd Floor	223	203	768	84	12	N	Y
Store Room	Regular Classroom	2nd Floor	225	205	488	117	12	N	N
Store Room	Regular Classroom	3rd Floor	322	302	768	174	6	N	N
Store Room	Regular Classroom	3rd Floor	326	306	568	69	6	N	Y
Store Room	Regular Classroom	3rd Floor	328	308	355	20	10	N	N
Store Room	Regular Classroom	3rd Floor	330	310	603	56	9	N	N
Store Room	Regular Classroom	Basement	025	04	824	0	0	N	N
Store Room	Regular Classroom	Basement	03	03	1,188	0	0	N	N
Vacant	Art Room	Basement	021	01	350	0	0	N	N
Vacant	Regular Classroom	2nd Floor	227	207	790	72	9	N	N

Building : Branch									
Faculty Lounge	Regular Classroom	2nd Floor	220	220	775	110	103	N	N
Kindergarten	Regular Classroom	1st Floor	118	118	775	150	75	Y	Y
Other Instructional Use	Kindergarten	2nd Floor	212	212	775	110	103	N	Y
Other Instructional Use	Regular Classroom	3rd Floor	320	320	775	110	103	N	N
Pre School	Kindergarten	1st Floor	117	117	1,170	210	105	N	Y
Pre School	Pre School	1st Floor	112	112	1,417	94	47	N	Y
Regular Classroom	Regular Classroom	1st Floor	116	116	775	150	75	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	775	110	103	N	Y
Regular Classroom	Regular Classroom	2nd Floor	215	215	775	207	103	N	Y

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Regular Classroom	Regular Classroom	2nd Floor	216	216	775	110	103	N	Y
Regular Classroom	Regular Classroom	2nd Floor	217	217	775	207	103	N	Y
Regular Classroom	Regular Classroom	2nd Floor	218	218	775	110	103	N	Y
Regular Classroom	Regular Classroom	2nd Floor	219	219	775	207	103	N	Y
Regular Classroom	Regular Classroom	3rd Floor	312	312	775	110	103	N	Y
Regular Classroom	Regular Classroom	3rd Floor	314	314	775	110	103	N	Y
Regular Classroom	Regular Classroom	3rd Floor	315	315	775	207	103	N	Y
Regular Classroom	Regular Classroom	3rd Floor	316	316	775	110	103	N	Y
Regular Classroom	Regular Classroom	3rd Floor	317	317	775	207	103	N	Y
Regular Classroom	Regular Classroom	3rd Floor	318	318	775	110	103	N	Y
Regular Classroom	Special Program	3rd Floor	319	319	775	207	103	N	Y