

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1960 | 1 | 22,579 |
| Addition | 2020 | 1 | 9,600 |
| Campus Total | | | 32,179 |

Category : Exterior

Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|---------------------------------------|---------------------|----------|-----|------|-----------------------|--------------------------|
| Entrance | | | | | | | |
| | Entrance Control - Audio and Video | #1 - Main - N | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #1 - Main - N | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #1 - Main - N | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #1 - Main - N | 2 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #1 - Main - N | 14 | LF | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #1 - Main - N | 2 | LF | 5 | 1-2 years | Cracked Landing |
| | Power Door Operator and Controls | #1 - Main - N | 1 | EA | 7 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | #1 - Main - N | 48 | LF | 6 | 10+ years | |
| | Ramps - Concrete | #1 - Main - N | 22 | LF | 6 | 6-10 years | |
| | Ramps - Concrete | #1 - Main - N | 2 | LF | 5 | 1-2 years | Broken curb |
| | Stair Handrail - Steel_Stair Handrail | #1 - Main - N | 11 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #5 - E. | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #5 - E. | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Stone | #5 - E. | 2 | LF | 6 | 10+ years | |
| | Exterior Stairs - Stone | #5 - E. | 1 | LF | 5 | 1-2 years | Cracked, broken |
| | Exterior Doors - Exterior Steel Door | #5.5 - SE courtyard | 1 | EA | 6 | 2-5 years | Surface rust throughout |
| | Ramps - Concrete | #5.5 - SE courtyard | 12 | LF | 6 | 10+ years | |
| | Entrance Control - Audio and Video | #6 - SE | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #6 - SE | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #6 - SE | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #6 - SE | 2 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #6 - SE | 17 | LF | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #6 - SE | 1 | LF | 5 | 1-2 years | Cracked, broken concrete |

Category : Exterior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------------|----------|----------|-----|------|-----------------------|--|
| | Power Door Operator and Controls | #6 - SE | 1 | EA | 7 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | #6 - SE | 40 | LF | 6 | 10+ years | |
| | Ramps - Concrete | #6 - SE | 20 | LF | 6 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | #6 - SE | 14 | LF | 6 | 10+ years | |
| | Entrance Control - Audio and Video | #7 - S. | 1 | EA | 6 | 10+ years | Locked |
| | Exterior Doors - Exterior FRP Door | #7 - S. | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #7 - S. | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #7 - S. | 2 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #7 - S. | 16 | LF | 6 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | #7 - S. | 5 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #8 - SW | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #8 - SW | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #8 - SW | 7 | LF | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #8 - SW | 1 | LF | 5 | 1-2 years | Spalled concrete with exposed rebar |
| | Exterior Stairs - Stone | #8 - SW | 3 | LF | 6 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | #8 - SW | 4 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #9 - NW. | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #9 - NW. | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #9 - NW. | 7 | LF | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #9 - NW. | 1 | LF | 5 | 1-2 years | Broken and concrete with exposed reinforcement |
| | Exterior Stairs - Stone | #9 - NW. | 3 | LF | 6 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | #9 - NW. | 4 | LF | 6 | 10+ years | |

Foundation

| | | | | | | | |
|--|---------------------------|-----------------|--------|----|---|-----------|---|
| | Foundation - Concrete | Entire Building | 762 | LF | 7 | 10+ years | |
| | Foundation - Concrete | Entire Building | 20 | LF | 5 | 1-2 years | Foundation settlement in the east corner, right |
| | Superstructure - Concrete | Entire Building | 22,579 | SF | 7 | 10+ years | |

Lighting

| | | | | | | | |
|--|----------------------------------|-----------------|----|----|---|-----------|--|
| | Exterior Lighting - Wall Mounted | Entire Building | 14 | EA | 7 | 10+ years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 17 | EA | 6 | 10+ years | |

Roof System

| | | | | | | | |
|--|--|-----------|--------|----|---|-----------|--|
| | Access Ladder - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| | Chimney - Brick Chimney- Stainless Steel Liner | Main Roof | 33 | LF | 6 | 10+ years | |
| | Coping - Metal | Main Roof | 741 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Main Roof | 100 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | Main Roof | 20,059 | SF | 4 | 0-1 year | Blistering, soft spots, worn surfaces, pooling |
| | Roof - Modified Bitumen | Main Roof | 650 | SF | 6 | 10+ years | Patched areas |

Category : Exterior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------|-----------------|----------|-----|------|-----------------------|---|
| | Roof Hatch - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| | Roof Structure - Concrete | Main Roof | 20,709 | SF | 7 | 10+ years | |
| | Coping - Metal | W. Pitched roof | 224 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | W. Pitched roof | 5,172 | SF | 5 | 2-5 years | Blistering throughout, confirmed surface is in fair condition |
| | Roof - Modified Bitumen | W. Pitched roof | 200 | SF | 4 | 1-2 years | Large Blistering areas |
| | Roof Structure - Concrete | W. Pitched roof | 5,372 | SF | 7 | 10+ years | |

Walls

| | | | | | | |
|---|-----------------|-------|----|---|-----------|-----------------------|
| Canopy - Concrete/ Stucco | Entire Building | 290 | SF | 6 | 10+ years | |
| Exterior Walls - Brick | Entire Building | 7,005 | SF | 6 | 10+ years | |
| Exterior Walls - Brick | Entire Building | 1 | SF | 3 | 1-2 years | Broken, missing brick |
| Exterior Walls - Prefabricated Metal Panel Wall | Entire Building | 240 | SF | 6 | 10+ years | |

Windows

| | | | | | | |
|---|-----------------|-------|----|---|-----------|---------------|
| Guard - Guards perforated | Entire Building | 234 | SF | 6 | 10+ years | |
| Windows - Casement Aluminum Double-pane | Entire Building | 2,468 | SF | 6 | 10+ years | |
| Windows - Decorative | Entire Building | 16 | SF | 5 | 1-2 years | Broken Window |
| Windows - Insulated Panel | Entire Building | 678 | SF | 6 | 10+ years | |
| Windows - Louver | Entire Building | 85 | SF | 6 | 10+ years | |

Category : Electrical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------|--|-----------------|----------|-----|------|-----------------------|----------|
| <u>Emergency System</u> | | | | | | | |
| | Emergency Battery Packs - Corridors and Stairs | 1st Floor | 13 | EA | 7 | 6-10 years | |
| | Emergency Battery Packs - Lunchrooms | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | 1st Floor | 7 | EA | 6 | 6-10 years | |
| | Exit Signs - Lunchroom | 1st Floor | 2 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 22,579 | SF | 7 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 22,579 | SF | 6 | 6-10 years | |

Main Service

| | | | | | | |
|--|----------------|--------|----|---|------------|-------------------------|
| Independent Electrical Service for emergency power | Fire Pump Room | 1 | EA | 6 | 10+ years | Supplies fire pump only |
| PA System | Main Office | 22,579 | SF | 6 | 6-10 years | |

Power Distribution

| | | | | | | |
|-----------------------------------|-----------------|---|----|---|------------|--|
| Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 6 | 6-10 years | |
|-----------------------------------|-----------------|---|----|---|------------|--|

Category : Electrical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---|-----------------|----------|-----|------|-----------------------|-----------------------------|
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 4 | 0-1 year | Open fuse slots |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 4 | 10+ years | Missing spare breaker cover |
| | Lighting and Power Panels - Above 100 A | Entire Building | 4 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 4 | 10+ years | Missing spare breaker cover |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 1 | EA | 7 | 10+ years | |

Category : Fire Protection
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---------------------------|----------------------------|-----------------|----------|-----|------|-----------------------|----------|
| <u>Fire Alarm</u> | | | | | | | |
| | Fire ALarm Anunciator | Entire Building | 1 | EA | 7 | 6-10 years | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 7 | 6-10 years | |
| | Fire Alarm Strobe Lights | Entire Building | 22,579 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 22,579 | SF | 6 | 6-10 years | |
| | Fire Pump Controller | Entire Building | 1 | EA | 7 | 6-10 years | |
| <u>Pump Room Assembly</u> | | | | | | | |
| | Fire Pump - Less than 25hp | Fire Pump Room | 1 | EA | 6 | 10+ years | |
| | Jockey Pump | Fire Pump Room | 1 | EA | 6 | 10+ years | |

Sprinkler System

| | | | | | | | |
|--|------------------|-----------------|-------|----|---|-----------|-------------------------|
| | Sprinkler Piping | Entire Building | 1,000 | SF | 6 | 10+ years | Piping to Addition only |
|--|------------------|-----------------|-------|----|---|-----------|-------------------------|

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------------|---|----------|----------|-----|------|-----------------------|----------|
| <u>Air Conditioning</u> | | | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | 6-10 years | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | 6-10 years | |
| <u>Air Handling Systems</u> | | | | | | | |
| | Fan Coil Unit- Celing Mounted - Electric | 109 | 1 | EA | 6 | 10+ years | |
| | Roof Top Unit-Single Zone-Roof Mounted-Gas Heating and DX Cooling Coil - 11 - 20 tons | Roof | 1 | EA | 6 | 10+ years | |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------------------|--|-----------------|----------|-----|------|-----------------------|--|
| Boiler Systems | | | | | | | |
| | Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH | Boiler Room | 2 | EA | 6 | 10+ years | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | 10+ years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 1 | EA | 6 | 10+ years | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 1 | EA | 6 | 10+ years | |
| | Water Fill System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| Gas Booster | | | | | | | |
| | Gas Booster | Boiler Room | 1 | EA | 5 | 6-10 years | |
| Heating Devices | | | | | | | |
| | Wall Heater - Electric | Entire Building | 4 | EA | 5 | 2-5 years | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 11 | EA | 6 | 6-10 years | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 1 | EA | 6 | 10+ years | |
| | Unit Heater - Electric | Entire Building | 1 | EA | 6 | 10+ years | |
| | Unit Heater - Gas | Entire Building | 1 | EA | 6 | 10+ years | |
| | Unit Heater - Hot Water | Entire Building | 1 | EA | 6 | 10+ years | |
| Mechanical Plumbing | | | | | | | |
| | Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hydronic Supply and Return - Copper | Entire Building | 200 | LF | 6 | 10+ years | |
| | Hydronic Supply and Return - Steel | Entire Building | 100 | LF | 6 | 10+ years | |
| Temperature Control | | | | | | | |
| | Electric Thermostat | Entire Building | 1 | EA | 7 | 6-10 years | |
| | Electric Thermostat | Entire Building | 3 | EA | 6 | 10+ years | For FCUs and lunchroom RTU |
| | Electric Thermostat | Entire Building | 1 | EA | 6 | 10+ years | |
| | Electric Thermostat | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Hybrid Pneumatic/DDC System | Entire Building | 22,579 | SF | 6 | 6-10 years | |
| | Thermostats - Pneumatic | Entire Building | 18 | EA | 6 | 2-5 years | |
| | Thermostats - Pneumatic | Entire Building | 11 | EA | 5 | 2-5 years | For cabinet heaters and in main office |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------|---|-----------------|----------|-----|------|-----------------------|----------|
| <u>Unit Ventilation</u> | | | | | | | |
| | Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only | Entire Building | 18 | EA | 6 | 6-10 years | |
| <u>Ventilation</u> | | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 3 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 4 | EA | 5 | 6-10 years | |
| | Roof Mounted Duct Work | Entire Building | 30 | LF | 7 | 10+ years | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EA | 7 | 10+ years | |

Category : Plumbing
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|------------------|---|-----------------|----------|-----|------|-----------------------|-----------|
| <u>Hot Water</u> | | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 6 | 10+ years | |
| <u>Piping</u> | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 22,579 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 22,579 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 22,579 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 22,579 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 22,579 | SF | 7 | 10+ years | Renovated |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 22,579 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 22,579 | SF | 7 | 10+ years | |
| | Sanitary Piping | Entire Building | 22,579 | SF | 7 | 10+ years | |
| | Storm Piping | Entire Building | 22,579 | SF | 7 | 10+ years | |
| | Vent Piping | Entire Building | 22,579 | SF | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------------------------|---------------------------|------------------------|----------|-----|------|-----------------------|----------|
| <u>Administrative Suites/Offices</u> | | | | | | | |
| | AC Unit | 108 Counselor's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 108 Counselor's Office | 380 | SF | 6 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------|-----------------------------|------------------------|----------|-----|------|-----------------------|-------------------------|
| | Doors - Wood Doors inclu hw | 108 Counselor's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 108 Counselor's Office | 380 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 108 Counselor's Office | 8 | EA | 7 | 6-10 years | |
| | Power Distribution | 108 Counselor's Office | 8 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 108 Counselor's Office | 500 | SF | 6 | 10+ years | |
| | AC Unit | 109 Counselor office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 109 Counselor office | 201 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 109 Counselor office | 4 | SF | 4 | 0-1 year | Water damage |
| | Floor - Tile | 109 Counselor office | 205 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 109 Counselor office | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | 109 Counselor office | 6 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 109 Counselor office | 418 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 109 Counselor office | 140 | SF | 7 | 10+ years | |
| | AC Unit | 110 Main Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 110 Main Office | 450 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 110 Main Office | 30 | SF | 7 | 10+ years | Not previously assessed |
| | Doors - Store Front | 110 Main Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 110 Main Office | 450 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 110 Main Office | 7 | EA | 7 | 6-10 years | |
| | Power Distribution | 110 Main Office | 8 | EA | 6 | 10+ years | |
| | Storage/ Closet | 110 Main Office | 180 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 110 Main Office | 450 | SF | 6 | 10+ years | |
| | AC Unit | 111A Kitchen office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 111A Kitchen office | 96 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 111A Kitchen office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | 111A Kitchen office | 96 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 111A Kitchen office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 111A Kitchen office | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 111A Kitchen office | 133 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 111A Kitchen office | 127 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 112 Principal's Office | 211 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 112 Principal's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 112 Principal's Office | 211 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 112 Principal's Office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 112 Principal's Office | 4 | EA | 6 | 10+ years | |
| | Storage/ Closet | 112 Principal's Office | 21 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 112 Principal's Office | 211 | SF | 6 | 10+ years | |
| Kitchen | | | | | | | |
| | Ceiling - Lay-in | 111 Kitchen | 750 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 111 Kitchen | 4 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | 111 Kitchen | 750 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 111 Kitchen | 11 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 111 Kitchen | 220 | SF | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------------------------|-----------------------------------|-------------------|----------|-----|------|-----------------------|-------------------------|
| | Walls - Vinyl Coated Gypsum Panel | 111 Kitchen | 990 | SF | 7 | 10+ years | |
| Lunch & Multipurpose Room | | | | | | | |
| | Ceiling - Plaster/Drywall | 113 Cafeteria | 2,631 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 113 Cafeteria | 4 | EA | 6 | 10+ years | |
| | Floor - Tile | 113 Cafeteria | 2,411 | SF | 6 | 10+ years | |
| | Floor - Tile Quarry | 113 Cafeteria | 220 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 113 Cafeteria | 19 | EA | 6 | 6-10 years | |
| | Serving Line | 113 Cafeteria | 15 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | 113 Cafeteria | 1,641 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 113 Cafeteria | 550 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 113 Cafeteria | 1,641 | SF | 6 | 10+ years | |
| MDF_IDE | | | | | | | |
| | Doors - Steel Doors incl hw | 1st Floor in 119A | 1 | EA | 6 | 10+ years | |
| | Finishes | 1st Floor in 119A | 132 | SF | 7 | 10+ years | |
| | Other Cooling Unit | 1st Floor in 119A | 1 | EA | 7 | 6-10 years | Ductless split |
| | Window AC Unit | 1st Floor in 119A | 1 | EA | 7 | 6-10 years | |
| Mechanical/ Service Rooms | | | | | | | |
| | Boiler Room | 1st Floor | 935 | SF | 5 | 10+ years | |
| | Janitor's Closet | 1st Floor | 37 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 182 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 112 | SF | 7 | 10+ years | |
| Restroom | | | | | | | |
| | Accessories | 1st Floor | 367 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 367 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 367 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor | 4 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 5 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor | 7 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | 715 | SF | 7 | 10+ years | Renovated, recalculated |
| | Water Closet | 1st Floor | 7 | EA | 6 | 10+ years | |
| | Accessories | 1st Floor | 364 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 364 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 364 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor | 4 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 4 | EA | 7 | 6-10 years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|------------------------------------|----------|-----|------|-----------------------|--------------|
| | Partitions | 1st Floor | 3 | EA | 7 | 10+ years | Reconfigured |
| | Urinals | 1st Floor | 3 | EA | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | 715 | SF | 7 | 10+ years | Renovated |
| | Water Closet | 1st Floor | 3 | EA | 6 | 10+ years | Reconfigured |
| | Accessories | 1st flr inside classroom #117 | 38 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st flr inside classroom #117 | 38 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st flr inside classroom #117 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st flr inside classroom #117 | 38 | SF | 6 | 10+ years | |
| | Lavatory | 1st flr inside classroom #117 | 1 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 1st flr inside classroom #117 | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st flr inside classroom #117 | 76 | SF | 6 | 10+ years | |
| | Water Closet | 1st flr inside classroom #117 | 1 | EA | 6 | 10+ years | |
| | Accessories | In Boiler Room | 25 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | In Boiler Room | 25 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | In Boiler Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | In Boiler Room | 25 | SF | 7 | 10+ years | |
| | Lavatory | In Boiler Room | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | In Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | In Boiler Room | 1 | EA | 5 | 6-10 years | |
| | Walls - Concrete Block | In Boiler Room | 60 | SF | 7 | 10+ years | |
| | Water Closet | In Boiler Room | 1 | EA | 7 | 10+ years | |
| | Accessories | In Principal's Office | 28 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | In Principal's Office | 28 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | In Principal's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | In Principal's Office | 28 | SF | 6 | 10+ years | |
| | Lavatory | In Principal's Office | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | In Principal's Office | 1 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | In Principal's Office | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | In Principal's Office | 56 | SF | 6 | 10+ years | |
| | Water Closet | In Principal's Office | 1 | EA | 6 | 10+ years | |
| | Accessories | Unisex staff across from 112 | 35 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Unisex staff across from 112 | 35 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex staff across from 112 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Unisex staff across from 112 | 35 | SF | 6 | 10+ years | |
| | Lavatory | Unisex staff across from 112 | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Unisex staff across from 112 | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Unisex staff across from 112 | 70 | SF | 6 | 10+ years | |
| | Water Closet | Unisex staff across from 112 | 1 | EA | 6 | 10+ years | |
| | Accessories | women's staff restroom next to 115 | 76 | SF | 7 | 6-10 years | |
| | | Meter Room | | | | | |
| | Ceiling - Plaster/Drywall | women's staff restroom next to 115 | 76 | SF | 6 | 10+ years | |
| | | Meter Room | | | | | |
| | Doors - Wood Doors inclu hw | women's staff restroom next to 115 | 1 | EA | 6 | 10+ years | |
| | | Meter Room | | | | | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|----------------------------|---|----------|-----|------|-----------------------|----------|
| | Floor - Tile | women's staff restroom next to 115 Meter Room | 76 | SF | 6 | 10+ years | |
| | Lavatory | women's staff restroom next to 115 Meter Room | 2 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | women's staff restroom next to 115 Meter Room | 1 | EA | 6 | 6-10 years | |
| | Partitions | women's staff restroom next to 115 Meter Room | 2 | EA | 5 | 10+ years | |
| | Walls - Concrete Block | women's staff restroom next to 115 Meter Room | 198 | SF | 6 | 10+ years | |
| | Water Closet | women's staff restroom next to 115 Meter Room | 2 | EA | 6 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|---------------|
| <u>Classroom #100 (Regular Classroom)</u> | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 56 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 809 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 809 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 18 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 864 | SF | 6 | 10+ years | |
| <u>Classroom #101 (Regular Classroom)</u> | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 56 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 852 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 844 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 8 | SF | 5 | 1-2 years | Chipping tile |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 18 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 864 | SF | 6 | 10+ years | |
| <u>Classroom #102 (Regular Classroom)</u> | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 25 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 812 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|--------------------------------|
| | Floor - Tile | 1st Floor | 810 | SF | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 2 | SF | 5 | 0-1 year | Chipping |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 41 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,105 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroom #103 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 25 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 812 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 802 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 10 | SF | 5 | 1-2 years | Chipping and broken tile edges |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 41 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,055 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroom #105 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 56 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 852 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 852 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 18 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 897 | SF | 6 | 10+ years | |
| Classroom #107 (Computer Lab) | | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 5 | 2-5 years | Moved from Rooms |
| | Casework | 1st Floor | 72 | LF | 6 | 10+ years | Moved from Rooms |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,100 | SF | 6 | 10+ years | Moved from Rooms |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | Moved from Rooms |
| | Floor - Tile | 1st Floor | 1,100 | SF | 6 | 10+ years | Moved from Rooms |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 7 | 6-10 years | Moved from Rooms |
| | Storage/ Closet | 1st Floor | 30 | SF | 7 | 10+ years | Moved from Rooms |
| | Walls - Concrete Block | 1st Floor | 1,382 | SF | 7 | 10+ years | Moved from Rooms |
| | Wireless System | 1st Floor | 1 | EA | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|--------------------|
| <u>Classroom #117 (Regular Classroom)</u> | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 62 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,100 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | Corrected quantity |
| | Floor - Tile | 1st Floor | 1,100 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 36 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,375 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| <u>Classroom #119 (Regular Classroom)</u> | | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 25 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 894 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 894 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 41 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,117 | SF | 6 | 10+ years | |
| | Wireless System | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| <u>Classroom #120 (Regular Classroom)</u> | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 25 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 812 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 812 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 41 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,055 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| <u>Classroom #121 (Regular Classroom)</u> | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 25 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 812 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 20 | LF | 4 | 2-5 years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|-----------|----------|-----|------|-----------------------|----------|
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 806 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 6 | SF | 5 | 1-2 years | Chipping |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 41 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,055 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |

Classroom #122 (Regular Classroom)

| | | | | | | | |
|--|-----------------------------|-----------|-------|----|---|------------|--|
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 25 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 852 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 852 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 41 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,107 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |

Classroom #123 (Music Room)

| | | | | | | | |
|--|-----------------------------|-----------|-------|----|---|------------|------------------------------|
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 25 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 852 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 852 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 160 | SF | 5 | 10+ years | Water damage on ceiling tile |
| | Walls - Concrete Block | 1st Floor | 1,107 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |

Category : Interior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------|--------------------------------------|-----------|----------|-----|------|-----------------------|---------------------------|
| <u>Corridor</u> | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 3,646 | SF | 6 | 10+ years | |
| | Doors - Wood Doors include hw | 1st Floor | 8 | EA | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | 1st Floor | 4 | EA | 7 | 10+ years | Corrected type and number |

Category : Interior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---------------|-----------------------------|--------------------------|----------|-----|------|-----------------------|--|
| | Floor - Tile/Sheet | 1st Floor | 3,646 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 30 | EA | 7 | 6-10 years | |
| | Student Lockers - Two Tiers | 1st Floor | 120 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 6,636 | SF | 6 | 10+ years | |
| Safety | | | | | | | |
| | Camera Viewing Station | Entire Building and Site | 1 | EA | 7 | 6-10 years | Quantity updated to match current observations |
| | Security Cameras | Entire Building and Site | 10 | EA | 7 | 6-10 years | |

Category : Exterior
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------|--|-----------------|----------|-----|------|-----------------------|----------|
| <u>Entrance</u> | | | | | | | |
| | Exterior Doors - Exterior Steel Door | #2 | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #3 | 2 | EA | 6 | 10+ years | |
| | Entrance Control - Audio and Video | #4 | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Store Front | #4 | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | #4 | 2 | EA | 7 | 10+ years | |
| <u>Foundation</u> | | | | | | | |
| | Foundation - Concrete | Entire Building | 365 | LF | 7 | 10+ years | |
| | Superstructure - Steel | Entire Building | 247,000 | SF | 7 | 10+ years | |
| <u>Lighting</u> | | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 10 | EA | 7 | 10+ years | |
| <u>Roof System</u> | | | | | | | |
| | Access Ladder - Metal | Gym high roof | 1 | EA | 7 | 10+ years | |
| | Coping - Metal | Gym high roof | 330 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Gym high roof | 120 | LF | 7 | 10+ years | |
| | Parapet - 16" - 30" Height | Gym high roof | 330 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | Gym high roof | 6,500 | SF | 6 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/Concrete Topping | Gym high roof | 6,500 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | Low Roof | 1 | EA | 7 | 10+ years | |
| | Coping - Metal | Low Roof | 191 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Low Roof | 32 | LF | 7 | 10+ years | |
| | Parapet - 16" - 30" Height | Low Roof | 165 | LF | 7 | 10+ years | |
| | Parapet - Parapet < 16" Height | Low Roof | 26 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | Low Roof | 3,250 | SF | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/Concrete Topping | Low Roof | 3,250 | SF | 7 | 10+ years | |
| <u>Walls</u> | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 9,539 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 74 | SF | 7 | 10+ years | |
| <u>Windows</u> | | | | | | | |
| | Lintels - Steel | Entire Building | 169 | LF | 7 | 10+ years | |
| | Windows - Casement Aluminum Double-pane | Entire Building | 781 | SF | 7 | 10+ years | |

Category : Electrical
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---------------------------|--|-----------------|----------|-----|------|-----------------------|----------------|
| <u>Emergency System</u> | | | | | | | |
| | Emergency Battery Packs - Corridors and Stairs | 1st Floor | 3 | EA | 7 | 6-10 years | |
| | Emergency Battery Packs - Gym | 1st Floor | 8 | EA | 7 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Exit Signs - Gym | 1st Floor | 3 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 9,600 | SF | 7 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 9,600 | SF | 7 | 6-10 years | |
| <u>Main Service</u> | | | | | | | |
| | Main Electrical Service - 1600 A 120/208/3PH | Electrical Room | 1 | EA | 7 | 10+ years | |
| | PA System | Entire Building | 9,600 | SF | 6 | 10+ years | Served by Main |
| <u>Power Distribution</u> | | | | | | | |
| | Lighting and Power Panels - Above 100 A | Electrical Room | 4 | EA | 7 | 10+ years | |

Category : Fire Protection
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------|--------------------------|-----------------|----------|-----|------|-----------------------|------------------|
| <u>Fire Alarm</u> | | | | | | | |
| | Fire Alarm Strobe Lights | Entire Building | 9,600 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 9,600 | SF | 6 | 6-10 years | |
| <u>Sprinkler System</u> | | | | | | | |
| | Sprinkler Heads | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Sprinkler Piping | Entire Building | 9,600 | SF | 6 | 10+ years | Served from main |

Category : Mechanical
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------------|---|-------------------------|----------|-----|------|-----------------------|----------|
| <u>Air Handling Systems</u> | | | | | | | |
| | Roof Top Unit-Single Zone-Roof Mounted-Gas Heating and DX Cooling Coil - 31 - 45 tons | Lower Roof | 1 | EA | 7 | 10+ years | |
| | Roof Top Unit-Single Zone-Roof Mounted-Gas Heating and DX Cooling Coil - 5 - 10 tons | Lower Roof | 1 | EA | 7 | 10+ years | |
| | VAV Box | VAV Boxes Above Ceiling | 3 | EA | 7 | 10+ years | |
| <u>Heating Devices</u> | | | | | | | |

Category : Mechanical
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------------|-----------------|----------|-----|------|-----------------------|----------|
| | Wall Heater - Electric | Electrical Room | 1 | EA | 6 | 6-10 years | |
| | Radiator Panels - Hot Water | Restrooms | 4 | EA | 6 | 10+ years | |
| | Cabinet Heaters - With Hot Water Coil | South Vestibule | 1 | EA | 6 | 10+ years | |

Mechanical Plumbing

| | | | | | | | |
|--|-------------------------------------|-----------------|-----|----|---|-----------|--|
| | Hydronic Supply and Return - Copper | Entire Building | 100 | LF | 7 | 10+ years | |
|--|-------------------------------------|-----------------|-----|----|---|-----------|--|

Temperature Control

| | | | | | | | |
|--|---------------------|-----------------|-------|----|---|-----------|--|
| | DDC System | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Electric Thermostat | Entire Building | 1 | EA | 6 | 10+ years | |
| | Thermostats - DDC | Entire Building | 3 | EA | 7 | 10+ years | |
| | Thermostats - DDC | Entire Building | 2 | EA | 7 | 10+ years | |

Ventilation

| | | | | | | | |
|--|---|------------|----|----|---|-----------|--|
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Lower Roof | 3 | EA | 6 | 10+ years | |
| | Roof Mounted Duct Work | Lower Roof | 24 | LF | 7 | 10+ years | |

Category : Plumbing
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------|---|-----------------|----------|-----|------|-----------------------|----------|
| Piping | Domestic Piping-Hot Water Return Lines | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Sanitary Piping | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Storm Piping | Entire Building | 9,600 | SF | 7 | 10+ years | |
| | Vent Piping | Entire Building | 9,600 | SF | 7 | 10+ years | |

Category : Room
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------------|------------------|----------------------|----------|-----|------|-----------------------|----------|
| Administrative Suites/Offices | Ceiling - Lay-in | 124 Teacher's Lounge | 328 | SF | 7 | 10+ years | |

Category : Room
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|----------------------|----------|-----|------|-----------------------|----------|
| | Doors - Wood Doors inclu hw | 124 Teacher's Lounge | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 124 Teacher's Lounge | 328 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 124 Teacher's Lounge | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 124 Teacher's Lounge | 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 124 Teacher's Lounge | 660 | SF | 7 | 10+ years | |
| | Work Sink | 124 Teacher's Lounge | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | 126A Gym Office | 95 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 126A Gym Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 126A Gym Office | 95 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 126A Gym Office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 126A Gym Office | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 126A Gym Office | 200 | SF | 7 | 10+ years | |

Gymnasium

| | | | | | |
|-----------------------------|---------------|-------|----|---|------------|
| Bleacher Seating | 126 Gymnasium | 80 | EA | 7 | 10+ years |
| Ceiling - Exposed | 126 Gymnasium | 5,580 | SF | 7 | 10+ years |
| Doors - Steel Doors incl hw | 126 Gymnasium | 6 | EA | 7 | 10+ years |
| Doors - Wood Doors inclu hw | 126 Gymnasium | 2 | EA | 7 | 10+ years |
| Floor - Wood | 126 Gymnasium | 5,580 | SF | 7 | 10+ years |
| Lighting - Pendent/Surface | 126 Gymnasium | 18 | EA | 7 | 6-10 years |
| Scoreboards | 126 Gymnasium | 1 | EA | 7 | 6-10 years |
| Storage/ Closet | 126 Gymnasium | 216 | SF | 7 | 10+ years |
| Walls - Plaster/Drywall | 126 Gymnasium | 8,100 | SF | 7 | 10+ years |

Mechanical/ Service Rooms

| | | | | | |
|---------------------------|-----------|-----|----|---|-----------|
| Mechanical/ Service Rooms | 1st Floor | 195 | SF | 7 | 10+ years |
|---------------------------|-----------|-----|----|---|-----------|

Restroom

| | | | | | |
|---------------------------------|----------------|-----|----|---|------------|
| Accessories | Boy's Near 124 | 216 | SF | 7 | 6-10 years |
| Ceiling - Plaster/Drywall | Boy's Near 124 | 216 | SF | 7 | 10+ years |
| Floor - Tile Ceramic/ Porcelain | Boy's Near 124 | 216 | SF | 7 | 10+ years |
| Floor Drain | Boy's Near 124 | 1 | EA | 7 | 10+ years |
| Hand Dryer | Boy's Near 124 | 1 | EA | 7 | 6-10 years |
| Lavatory | Boy's Near 124 | 2 | EA | 7 | 10+ years |
| Lighting - Lay-in | Boy's Near 124 | 4 | EA | 7 | 6-10 years |
| Partitions | Boy's Near 124 | 2 | EA | 7 | 10+ years |
| Urinals | Boy's Near 124 | 1 | EA | 7 | 10+ years |
| Walls - Concrete Block | Boy's Near 124 | 53 | SF | 7 | 10+ years |
| Walls - Plaster/Drywall | Boy's Near 124 | 53 | SF | 7 | 10+ years |
| Walls - Tile Ceramic/ Porcelain | Boy's Near 124 | 422 | SF | 7 | 10+ years |
| Water Closet | Boy's Near 124 | 2 | EA | 7 | 10+ years |
| Accessories | Girls Near 124 | 216 | SF | 7 | 6-10 years |
| Ceiling - Plaster/Drywall | Girls Near 124 | 216 | SF | 7 | 10+ years |

Category : Room
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|-----------------|----------|-----|------|-----------------------|----------|
| | Floor - Tile Ceramic/ Porcelain | Girls Near 124 | 216 | SF | 7 | 10+ years | |
| | Floor Drain | Girls Near 124 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Girls Near 124 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Girls Near 124 | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Girls Near 124 | 4 | EA | 7 | 6-10 years | |
| | Partitions | Girls Near 124 | 3 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Girls Near 124 | 106 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Girls Near 124 | 422 | SF | 7 | 10+ years | |
| | Water Closet | Girls Near 124 | 3 | EA | 7 | 10+ years | |
| | Accessories | Unisex Near 124 | 54 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Unisex Near 124 | 54 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex Near 124 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Unisex Near 124 | 54 | SF | 7 | 10+ years | |
| | Floor Drain | Unisex Near 124 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Unisex Near 124 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Unisex Near 124 | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Unisex Near 124 | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Unisex Near 124 | 60 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Unisex Near 124 | 110 | SF | 7 | 10+ years | |
| | Water Closet | Unisex Near 124 | 1 | EA | 7 | 10+ years | |

Category : Classroom
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|----------|
| <u>Classroom #125 (Science Classroom)</u> | | | | | | | |
| | Casework | 1st Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 877 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Eye Wash Station | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 877 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 1st Floor | 887 | SF | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 100 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,062 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |

Category : Interior
Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------|-----------------------------|-----------|----------|-----|------|-----------------------|----------|
| <u>Corridor</u> | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 660 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | 10+ years | |

Category : Interior

Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|--|-----------|----------|-----|------|-----------------------|----------|
| | Drinking Fountains - Single Water Cooler | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 660 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 10 | EA | 7 | 6-10 years | |
| | Student Lockers - Two Tiers | 1st Floor | 27 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,670 | SF | 7 | 10+ years | |

Category : Site
Building : Site

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------|-----------------------------------|--------------------|----------|-----|------|-----------------------|----------------------------------|
| <u>Civil/Drainage</u> | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 15 | EA | 7 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 10 | EA | 7 | 10+ years | |
| <u>Fencing</u> | | | | | | | |
| | Fencing - Chain Link | Entire Site | 350 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 1,200 | LF | 6 | 10+ years | |
| <u>Landscape</u> | | | | | | | |
| | Benches | Entire Site | 2 | EA | 6 | 10+ years | |
| | Landscape - Grass | Entire Site | 111,900 | SF | 6 | 10+ years | Consolidated numbers |
| | Landscape - Grass | Entire Site | 200 | SF | 4 | 0-1 year | Bare soil |
| | Lighting - Pole Mounted | Entire Site | 9 | EA | 7 | 10+ years | |
| | Lighting - Pole Mounted | Entire Site | 4 | EA | 6 | 10+ years | |
| | Lighting - Pole Mounted | Entire Site | 4 | EA | 5 | 0-1 year | Broken, missing lamps and covers |
| | Parkway trees | Entire Site | 3 | EA | 7 | 10+ years | |
| | Parkway trees | Entire Site | 1 | EA | 6 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 2,800 | SF | 6 | 10+ years | |
| | Play Area - Hardscape- Asphalt | Entire Site | 14,704 | SF | 6 | 10+ years | |
| | Trash Receptacles | Entire Site | 4 | EA | 7 | 10+ years | |
| | Walking Path - Hardscape- Asphalt | Entire Site | 10,778 | SF | 7 | 10+ years | |
| <u>Parking Lot</u> | | | | | | | |
| | Concrete Curbs | Parking Lot- South | 734 | LF | 6 | 10+ years | |
| | Interior Plantings | Parking Lot- South | 20 | LF | 6 | 10+ years | |
| | Lighting - Pole Mounted | Parking Lot- South | 4 | EA | 6 | 10+ years | |
| | Surface - Asphalt | Parking Lot- South | 13,569 | SF | 6 | 10+ years | |
| | Surface - Asphalt | Parking Lot- South | 500 | SF | 4 | 0-1 year | Potholes, cracks, disintegrating |
| | Trash Enclosure - Chain Links | Parking Lot- South | 850 | SF | 6 | 10+ years | |
| | Vehicular Screening | Parking Lot- South | 235 | LF | 6 | 10+ years | |
| <u>Playground</u> | | | | | | | |
| | Equipment - Combo 3-12 | East | 2 | EA | 7 | 10+ years | |
| | Surface - Poured Surface | East | 4,897 | SF | 6 | 10+ years | |
| | Equipment - Combo 3-12 | North | 1 | EA | 4 | 1-2 years | Worn, broken parts, corroding |
| | Surface - Poured Surface | North | 1,952 | SF | 7 | 10+ years | |
| <u>Sidewalks</u> | | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 914 | LF | 6 | 10+ years | |
| | Sidewalks - Internal Walks | Entire Site | 10 | LF | 4 | 0-1 year | Cracked sidewalks, settlement |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 3,837 | SF | 6 | 10+ years | |

Category : Site
Building : Site

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------|---|-------------------------------------|----------|-----|------|-----------------------|----------|
| Signage | | | | | | | |
| | Flag Pole - Flag Pole | Roof - West, Site West, West Facade | 1 | EA | 6 | 10+ years | |
| | Marquee - Free Standing Back lighted w/ LED | Roof - West, Site West, West Facade | 1 | EA | 6 | 10+ years | |
| | Monument - Building Mounted Cut Letter Sign | Roof - West, Site West, West Facade | 1 | EA | 6 | 10+ years | |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Glazed Window Area | Operable Window Area | Window Stop | Smart-Board |
|----------------------------|-------------------|---------------|-------------|------------------------|-----------|--------------------|----------------------|-------------|-------------|
| Building : Main | | | | | | | | | |
| Computer Lab | Library | 1st Floor | 107 | 109 | 1,100 | 300 | 40 | N | |
| Music Room | Regular Classroom | 1st Floor | 123 | 101 | 852 | 121 | 52 | N | Y |
| Regular Classroom | Computer Lab | 1st Floor | 119 | 105 | 894 | 64 | 30 | N | Y |
| Regular Classroom | Kindergarten | 1st Floor | 117 | 107 | 1,100 | 300 | 40 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 100 | 112 | 809 | 240 | 32 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 101 | 115 | 852 | 240 | 32 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 110 | 812 | 121 | 52 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 113 | 812 | 121 | 52 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 105 | 111 | 852 | 240 | 32 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 120 | 104 | 812 | 121 | 52 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 121 | 103 | 812 | 121 | 52 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 122 | 102 | 852 | 121 | 52 | N | Y |
| Building : Addition | | | | | | | | | |
| Science Classroom | Science Classroom | 1st Floor | 125 | A101 | 877 | 52 | 8 | | |