

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1896	4	82,022
Addition	2003	2	57,687
Campus Total			139,709

Category: Exterior **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Entrance Entrance Control - Audio #1 W 1 EΑ 7 6-10 years Exterior Doors - Exterior FRP Door #1 W 3 EΑ 7 10+ years Exterior Doors - Transom Lite #1 W 2 EΑ 7 10+ years LF Exterior Stairs - Concrete #1 W 15 5 0-1 year Cracking Exterior Doors - Exterior Steel Door EΑ 6 10+ years #10 E 1 Exterior Doors - Exterior Steel Door #11 Exit E EΑ 6 10+ years Corroded at the frame Exterior Doors - Exterior Wood Door #12 E FΑ 5 0-1 year 1 2 Exterior Doors - Exterior Steel Door FΑ 5 0-1 vear Rustina #13 # 6 FΑ 7 Exterior Doors - Exterior Steel Door #14 Exit W 10+ years Exterior Doors - Transom Lite #14 Exit W 3 FΑ 7 10+ years LF Exterior Stairs - Concrete #14 Exit W 21 7 10+ years Exterior Doors - Exterior Steel Door #2 Exit W 6 EΑ 5 0-1 year Rotting frame Exterior Doors - Transom Lite #2 Exit W 3 EΑ 6 10+ years Exterior Stairs - Concrete #2 Exit W 21 LF 7 10+ years Exterior Doors - Exterior Steel Door #9 E 2 EΑ 5 0-1 vear Rusted Foundation Foundation - Masonry **Entire Building** 773 LF 6 10+ years Superstructure - Steel with Clay Tile Arch **Entire Building** 82,022 SF 7 10+ years Liahtina Exterior Lighting - Parapet or Roof Mounted 12 EΑ 7 **Entire Building** 10+ years



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	7	10+ years	
Roof Sys							
	Access Ladder - Metal	Roof #1	3	EA	7	10+ years	
	Coping - Terra Cotta	Roof #1	803	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof #1	604	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof #1	120	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof #1	98	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof #1	560	LF	7	10+ years	
	Roof - Modified Bitumen	Roof #1	20,326	SF	6	10+ years	
	Roof Hatch - Metal	Roof #1	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof #1	20,326	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #2	85	LF	5	0-1 year	Open joints throughout
	Coping - Terra Cotta	Roof #2	245	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #2	99	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof #2	201	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof #2	265	LF	7	10+ years	
	Roof - Modified Bitumen	Roof #2	2,267	SF	6	2-5 years	
	Roof - Modified Bitumen	Roof #2	570	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof #2	2,837	SF	7	10+ years	
			_,			, , , , , , , , , , , , , , , , , , , ,	
Walls	F. C. W.H. D. L.	F & D 3 P	100	05		0.10	B : 1
	Exterior Walls - Brick	Entire Building	100	SF	7	6-10 years	Repaired
	Exterior Walls - Brick	Entire Building	29,470	SF	6	10+ years	
	Exterior Walls - Concrete Block	Entire Building	200	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	2,000	SF	6	10+ years	
	Wall	Fating Building	4.045	0.	0	40	
	Exterior Walls - Terra Cotta	Entire Building	4,345	SF	6	10+ years	
Windows	3						
	Guard - Guards wire guard	Entire Building	2,603	SF	7	10+ years	
	Lintels - Steel	Entire Building	387	LF	7	10+ years	
	Lintels - Stone	Entire Building	18	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	539	LF	7	10+ years	
	Windows - Casement Steel Double-pane	Entire Building	8,387	SF	7	10+ years	
	Windows - Louver	Entire Building	24	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ncy System						
	Automatic Transfer Switch	Basement	1	EA	6	10+ years	Location changed for clarification
			•		-	,	

Campus Name: Moos Page : 2 of 47 Assessment Date: 02/26/2024



Catego	ry : Electrical		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments Serves Main and Addition.
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,431	SF	6	6-10 years	Location changed for clarification as the auditorium occupies space on multiple floors of the building.
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,800	SF	6	6-10 years	,
	Emergency A/C Power - Gym Exit Signs - Auditoium	Entire Building Entire Building	3,236 6	SF EA	6 6	6-10 years 6-10 years	Location changed for clarification.
	Exit Signs - Auditoium	Entire Building	3	EA	2	0-1 year	Location changed for clarification as the auditorium occupies space on multiple floors of the building. Quantity changed as total has been divided/aggregated. Signs have no backup batteries and the school has no emergency generator.
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	3 7 3
	Exit Signs - Corridors and Stairs	Entire Building	15	EA	2	0-1 year	Signs have no backup batteries and the school has no emergency generator.
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	Quantity changed to match current observations.
	Security System - CCTV	Entire Building	82,022	SF	6	6-10 years	Rank, Reason and Priority Rep changed as the CCTV system has been upgraded since previous assessment.
	Security System - Intrusion Detection	Entire Building	82,022	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	3	EA	6	6-10 years	Location changed for clarification as the auditorium occupies space on multiple floors of the building. Quantity changed to match current observations.
Main Se	rvice						
	Independent Electrical Service for emergency power	Basement	1	EA	6	6-10 years	Location changed for clarification. Serves Main and Addition.
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Serves Main.
	Main Electrical Service - Greater than 3000 A 120/240/3PH	Electrical Room	1	EA	7	10+ years	Serves Main and Addition.
	PA System	Entire Building	82,022	SF	5	6-10 years	Served by Addition.
_Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations and as total has been

Campus Name: Moos Page: 3 of 47 Assessment Date: 02/26/2024



Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	divided/aggregated.  Open fuse receptacles and a missing interior cover plate expose live conductors presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Quantity changed as total has been divided/aggregated. Rank, Reason and Priority Rep changed as an open breaker slot exposes live conductors presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Open fuse receptacles expose live conductors presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Missing interior cover plate exposes live conductors presenting a live front condition. Quantity changed to match current observations and as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	10+ years	Quantity changed to match current observations and as total has been divided/aggregated. Some panels secured shut for safety reasons with condition verified by Building Engineer.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	Quantity changed to match current observations.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years	25kva wall-mounted unit adjacent to Panel EM-2 near Room 025.

**Category : Fire Protection** 

**Building: Main** Recommend Group Item - Type Quantity Replacement Comments Location UOM Rank Fire Alarm EΑ Fire Alarm Panel **Entire Building** 6 6-10 years Serves Main and Addition. 1 Fire Alarm Strobe Lights Entire Building 82,022 SF 10+ years 6 Entire Building SF 6-10 years Fire Alarm\_System 82,022 6



Catego	ry : Mechanical		В	uilding	: Main			
						Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Air Hand	lling Systems							
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	Mechanical Room	1	EA	5	6-10 years		
	Air Intake	Mechanical Room	1	EA	6	10+ years		
	Auxiliaries - 30001 - 45000 cfm	Mechanical Room	1	EA	5	6-10 years		
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	200	LF	6	6-10 years	Rank and Priority Rep adjusted based on current observations and per review with Building Engineer that the system is not in need of rebalancing.	
	Zone Dampers	Mechanical Room	34	EA	6	6-10 years	Quantity changed to match current observations. Location changed for clarification.	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room - Serves auditorium	1	EA	5	6-10 years	Serves auditorium. No CPS Asset Tag present.	
	Air Intake	Mechanical Room - Serves auditorium	1	EA	6	10+ years	Location changed for clarification.	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room - Serves auditorium	1	EA	5	6-10 years		
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - Serves auditorium	100	LF	6	6-10 years	Rank adjusted based on current observations and per review with Building Engineer that the system is not in need of rebalancing.	
Boiler Sv	vstems							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years		
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years		
	Combustion Dampers	Boiler Room	2	EA	6	10+ years		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years		
	Feed Water Pumps and Tank	Boiler Room	1	EA	4	2-5 years	Rank, Reason and Priority Rep changed as the tank is uninsulated and and leak-free but shows considerable signs of corrosion, and pump seals have minor leaks; the system appears to have reached the end of its anticipated service life.	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years	B-2	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years	B-1	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years		

Campus Name: Moos Page : 5 of 47 Assessment Date: 02/26/2024



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type Piping - Steam Pipe- Steel	Location Boiler Room	Quantity	UOM LF	Rank	Replacement	Comments
	Steam Traps	Boiler Room	400 16	EA	5 5	6-10 years 6-10 years	
	Vacuum Pump	Boiler Room	10	EA	6	6-10 years	
	vacuum i ump	Bollet Room	'	LA	U	0-10 years	
Gas Boo	oster						
	Gas Booster	Mechanical Room	2	EA	6	10+ years	
_Heating_	Devices						
	Radiators - Steam	Entire Building	9	EA	5	6-10 years	
	Unit Heater - Steam	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep
							adjusted based on current
							observations and per review with
							Building Engineer that the equipment
							is fully operational and not in need of
							substantial repair as of the time of assessment.
	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	Quantity and Priority Rep changed to
	Wall Heater - Liectric	Littile Ballating	0	LA	U	0-10 years	match current observations.
	Wall Heater - Electric	Entire Building	3	EA	4	0-1 year	Quantity and Priority Rep adjusted
		g	_		•	- · / · · ·	based on current observations.
							Missing cover exposes live
							conductors presenting a live front
							condition.
_Tempera	ature Control						
•	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep
		C				•	adjusted based on current
							observations and per review with
							Building Engineer that the thermostat
							is fully operational although the
					_		casing is missing.
	Hybrid Pneumatic/DDC System Thermostats - DDC	Entire Building	82,022	SF EA	5	6-10 years	Overetity showered as total has been
	Inermostats - DDC	Entire Building	37	EA	6	6-10 years	Quantity changed as total has been divided/aggregated based on current
							observations and per review with
							Building Engineer that system
							upgrades have been completed since
							previous assessment.
							•
_Ventilatio							
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	3	EA	6	6-10 years	
	CFM						



Ceiling - Exposed

#### Bernhard Moos Elementary School 1711 N California AVENUE, Chicago, IL 60647

Peeling paint throughout

Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves Main.
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	82,022	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	82,022	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	82,022	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	82,022	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	82,022	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	82,022	SF	6	6-10 years	
	Sanitary Piping	Entire Building	82,022	SF	6	6-10 years	
	Storm Piping	Entire Building	82,022	SF	6	6-10 years	
	Vent Piping	Entire Building	82,022	SF	6	6-10 years	
umps							
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	7	6-10 years	Rank adjusted based on current observations and per review with Building Engineer that the pump motor assembly has been replace since previous assessment.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present.
atego	ry : Room		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	002-Teachers Lounge	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	002-Teachers Lounge	891	SF	7	10+ years	
	Doors - Wood Doors inclu hw	002-Teachers Lounge	1	ĒΑ	7	10+ years	
	Floor - Tile	002-Teachers Lounge	885	SF	6	10+ years	
	Floor - Tile	002-Teachers Lounge	6	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	002-Teachers Lounge	24	EA	7	6-10 years	
	Lighting - Pendent/Surface	002-Teachers Lounge	2	EA	5	1-2 years	Not working
	Power Distribution	002-Teachers Lounge	12	EA	7	10+ years	
	Walls - Masonry	002-Teachers Lounge	238	SF	7	10+ years	
	Walls - Plaster/Drywall	002-Teachers Lounge	955	SF	7	10+ years	
	AC Unit		955	EA	7		
		012 Engineer's office		SF		6-10 years	
	Ceiling - Exposed	012 Engineer's office	400	SF SF	7	10+ years	Decling point throughout
	LOUIDA EVOCCA						

Campus Name: Moos Page : 7 of 47 Assessment Date: 02/26/2024

200

SF

5

1-2 years

012 Engineer's office



Category : Room			Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	012 Engineer's office	2	EA	6	6-10 years			
	Floor - Tile	012 Engineer's office	600	SF	6	10+ years			
	Lighting - Pendent/Surface	012 Engineer's office	9	EA	7	6-10 years			
	Power Distribution	012 Engineer's office	8	EA	7	10+ years			
	Walls - Masonry	012 Engineer's office	700	SF	7	10+ years			
	Walls - Plaster/Drywall	012 Engineer's office	100	SF	7	10+ years			
	Ceiling - Lay-in	020 Security	170	SF	6	6-10 years			
	Ceiling - Lay-in	020 Security	10	SF	4	1-2 years	Damaged tile		
	Doors - Wood Doors inclu hw	020 Security	1	EA	7	10+ years			
	Floor - Tile	020 Security	180	SF	7	10+ years			
	Lighting - Lay-in	020 Security	2	EA	7	6-10 years			
	Power Distribution	020 Security	6	EA	7	10+ years			
	Walls - Plaster/Drywall	020 Security	416	SF	7	10+ years			
	Ceiling - Exposed	023 work room	475	SF	6	10+ years			
	Doors - Steel Doors incl hw	023 work room	_1	EA	7	10+ years			
	Floor - Tile Quarry	023 work room	475	SF	7	10+ years			
	Lighting - Pendent/Surface	023 work room	6	EA	7	6-10 years			
	Power Distribution	023 work room	6	EA	7	10+ years			
	Walls - Masonry	023 work room	750	SF	6	10+ years			
	Work SInk	023 work room	3	EA	7	10+ years			
	Ceiling - Plaster/Drywall	035-Work Room	585	SF	6	2-5 years	Peeling paint		
	Floor - Tile Quarry	035-Work Room	585	SF	7	10+ years			
	Lighting - Pendent/Surface	035-Work Room	8	EA	7	6-10 years			
	Power Distribution	035-Work Room	4	EA	7	10+ years			
	Walls - Masonry	035-Work Room	154	SF	7	10+ years			
	Walls - Plaster/Drywall	035-Work Room	619	SF	7	10+ years			
	Ceiling - Plaster/Drywall	105-Conference Room	400	SF	7	10+ years			
	Doors - Transom Window	105-Conference Room	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	105-Conference Room	1	EA	7	10+ years			
	Floor - Wood	105-Conference Room	400	SF	7	10+ years			
	Lighting - Pendent/Surface	105-Conference Room	8	EA	7	6-10 years			
	Power Distribution	105-Conference Room	8	EA	7	10+ years			
	Walls - Plaster/Drywall	105-Conference Room	960	SF	7	10+ years			
	AC Unit	308-Teachers Resource Room	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	308-Teachers Resource Room	891	SF	7	10+ years			
	Doors - Transom Window	308-Teachers Resource Room	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	308-Teachers Resource Room	1	EA	7	10+ years			
	Floor - Wood	308-Teachers Resource Room	891	SF	7	10+ years			
	Lighting - Pendent/Surface	308-Teachers Resource Room	15	EA	7	6-10 years			
	Power Distribution	308-Teachers Resource Room	12	EA	7	10+ years			
	Walls - Plaster/Drywall	308-Teachers Resource Room	1,193	SF	7	10+ years			
	AC Unit	Basement-001	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement-001	960	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement-001	1	EA	7	10+ years			



Catego	ry : Room		В	uilding	: Main		<u> </u>
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Basement-001	960	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-001	16	EA	7	6-10 years	
	Power Distribution	Basement-001	1	EA	7	10+ years	
	Walls - Masonry	Basement-001	760	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement-001	450	SF	7	10+ years	
	AC Unit	Office 010	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Office 010	756	SF	7	10+ years	
	Doors - Steel Doors incl hw	Office 010	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Office 010	2	EA	7	10+ years	
	Floor - Tile	Office 010	750	SF	7	10+ years	
	Floor - Tile	Office 010	6	SF	4	0-1 year	Damaged.
	Lighting - Pendent/Surface	Office 010	18	EA	7	6-10 years	ŭ
	Power Distribution	Office 010	8	EA	7	10+ years	
	Walls - Masonry	Office 010	791	SF	7	10+ years	
	Walls - Plaster/Drywall	Office 010	198	SF	7	10+ years	
	Ceiling - Lay-in	RM 104-Main Office	466	SF	7	10+ years	
	Doors - Side-lite	RM 104-Main Office	66	SF	7	10+ years	
	Doors - Transom Window	RM 104-Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	RM 104-Main Office	1	ĒΑ	7	10+ years	
	Floor - Tile Quarry	RM 104-Main Office	36	SF	7	10+ years	
	Floor - Wood	RM 104-Main Office	430	SF	7	10+ years	
	Lighting - Lay-in	RM 104-Main Office	7	EA	7	6-10 years	
	Power Distribution	RM 104-Main Office	6	EΑ	7	10+ years	
	Storage/ Closet	RM 104-Main Office	60	SF	7	10+ years	
	Walls - Plaster/Drywall	RM 104-Main Office	1,040	SF	7	10+ years	
	•		,			,	
Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	116	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,432	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	7	10+ years	
	Floor - Tile	1st Floor	687	SF	7	10+ years	
	Floor - Wood	1st Floor	2,745	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
	Main Floor Seating	1st Floor	324	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	437	SF	7	10+ years	
	Stage Curtain	1st Floor	6	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	6	LF	7	10+ years	
	Stairs - Wood	1st Floor	6	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,922	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,615	SF	7	10+ years	
			_,0.0	-	•	,	



Catego	ry : Room		В	uilding	: Main		<u>.</u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Gymnas	ia						
	Ceiling - Plaster/Drywall	3rd Floor	3,236	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Sport Flooring	3rd Floor	3,236	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	5,127	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement	1,325	SF	7	10+ years	
	Floor - Tile	Basement	1,325	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	32	ĒΑ	7	6-10 years	
	Serving Line	Basement	12	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement	698	SF	7	10+ years	
	Wallo Flacton Diywall	Basement	000	O.	•	101 youro	
_MDF_ID							
	Doors - Steel Doors incl hw	Inside 207	1	EA	7	10+ years	
	Finishes	Inside 207	60	SF	7	10+ years	
	Window AC Unit	Inside 207	1	EA	7	10+ years	
_Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	20	SF	5	10+ years	
	Janitor's Closet	3rd Floor	40	SF	7	10+ years	
	Janitor's Closet	4th Floor	40	SF	7	10+ years	
	Boiler Room	Basement-Boiler Room	1,002	SF	5	10+ years	
	Janitor's Closet	Basement-Boiler Room	40	SF	7	10+ years	
	Janitor's Closet	Basement-Boiler Room	40	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement-Boiler Room	2,000	SF	5	10+ years	
	Storage Room	Basement-Boiler Room	1,035	SF	5	10+ years	
_Restroor	n						
	Accessories	1st Floor Boys	323	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boys	323	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	323	SF	6	10+ years	
	Floor Drain	1st Floor Boys	1	EA	7	10+ years	
	Hand Dryer	1st Floor Boys	2	EA	7	10+ years	
	Lavatory	1st Floor Boys	2	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	8	EA	7	6-10 years	
	Partitions	1st Floor Boys	4	EA	7	10+ years	
	Urinals	1st Floor Boys	3	EΑ	7	10+ years	
	Urinals	1st Floor Boys	1	EΑ	5	1-2 years	Out of service
	Walls - Concrete Block	1st Floor Boys	329	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Boys	329	SF	7	10+ years	
	Water Closet	1st Floor Boys	4	EA	7	10+ years	
			·		-	- ,	

Campus Name: Moos Page : 10 of 47 Assessment Date: 02/26/2024



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor Girls	323	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	323	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	323	SF	7	10+ years	
	Floor Drain	1st Floor Girls	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girls	2	EA	7	10+ years	
	Lavatory	1st Floor Girls	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Girls	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor Girls	3	EA	5	1-2 years	Missing covers
	Partitions	1st Floor Girls	7	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Girls	329	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Girls	329	SF	7	10+ years	
	Water Closet	1st Floor Girls	7	EA	7	10+ years	
	Accessories	1st Floor staff women	218	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor staff women	218	SF	7	10+ years	
	Doors - Transom Window	1st Floor staff women	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor staff women	1	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor staff women	154	SF	7	10+ years	
	Floor - Tile	1st Floor staff women	64	SF	7	10+ years	
	Lavatory	1st Floor staff women	1	EA	5	1-2 years	Sink leaking
	Lighting - Pendent/Surface	1st Floor staff women	5	EA	7	6-10 years	Ciril loaking
	Partitions	1st Floor staff women	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor staff women	362	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor staff women	100	SF	6	10+ years	
	Water Closet	1st Floor staff women	1	EA	7	10+ years	
	Accessories	2nd Floor Boys	323	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boys	323	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys	323	SF	7	10+ years	
	Floor Drain	2nd Floor Boys	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Boys	2	EA	7	10+ years	
	Lavatory	2nd Floor Boys	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Boys	8	EA	7	6-10 years	
	Partitions	2nd Floor Boys	4	EA	7	10+ years	
	Urinals	2nd Floor Boys	4	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Boys	329	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Boys	329	SF	7	10+ years	
	Water Closet	2nd Floor Boys	4	EA	7	10+ years	
	Accessories	2nd Floor Boys 2nd Floor Girls	323	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls 2nd Floor Girls	319	SF	7		
	Ceiling - Plaster/Drywall	2nd Floor Girls 2nd Floor Girls	319	SF SF	4	10+ years 1-2 years	Water damage
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls 2nd Floor Girls	323	SF	7	,	vvalei uaillaye
	Floor - Tile Ceramic/ Porceiain	2nd Floor Girls 2nd Floor Girls	323	Sr EA	7 7	10+ years	
				EA	7 7	10+ years	
	Hand Dryer	2nd Floor Girls 2nd Floor Girls	2			10+ years	
	Lighting Rendent/Surface		3 8	EA EA	7 7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls	8	ĽA	,	6-10 years	



Catego	ry : Room	-	Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	2nd Floor Girls	7	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor Girls	329	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor Girls	329	SF	7	10+ years			
	Water Closet	2nd Floor Girls	7	EA	7	10+ years			
	Accessories	2nd Floor staff unisex	218	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor staff unisex	218	SF	7	10+ years			
	Doors - Transom Window	2nd Floor staff unisex	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor staff unisex	1	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	2nd Floor staff unisex	154	SF	7	10+ years			
	Floor - Tile	2nd Floor staff unisex	64	SF	7	10+ years			
	Lavatory	2nd Floor staff unisex	1	ĒΑ	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor staff unisex	4	ΕA	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor staff unisex	1	EA	5	0-1 year	Missing cover		
	Partitions	2nd Floor staff unisex	1	ΕA	7	10+ years	g cove.		
	Walls - Plaster/Drywall	2nd Floor staff unisex	362	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd Floor staff unisex	100	SF	6	10+ years			
	Water Closet	2nd Floor staff unisex	1	EA	7	10+ years			
	Accessories	3rd Floor Boys	323	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor Boys	323	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor Boys	323	SF	7	10+ years			
	Floor Drain	3rd Floor Boys	1	EA	7	•			
	Hand Dryer		2	EA	7	10+ years			
		3rd Floor Boys				10+ years			
	Lavatory	3rd Floor Boys	2	EΑ	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor Boys	8	EΑ	7	6-10 years			
	Partitions	3rd Floor Boys	4	EΑ	7	10+ years			
	Urinals	3rd Floor Boys	3	EΑ	7	10+ years	Net weeking		
	Urinals	3rd Floor Boys	1	EA	5	1-2 years	Not working		
	Walls - Concrete Block	3rd Floor Boys	329	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor Boys	329	SF	7	10+ years			
	Water Closet	3rd Floor Boys	4	EA	7	10+ years			
	Accessories	3rd Floor Girls	323	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor Girls	323	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor Girls	323	SF	7	10+ years			
	Floor Drain	3rd Floor Girls	1	EA	7	10+ years			
	Hand Dryer	3rd Floor Girls	2	EA	7	10+ years			
	Lavatory	3rd Floor Girls	3	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor Girls	8	EA	7	6-10 years			
	Partitions	3rd Floor Girls	7	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor Girls	329	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor Girls	329	SF	7	10+ years			
	Water Closet	3rd Floor Girls	7	EA	7	10+ years			
	Accessories	3rd Floor staff unisex	218	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor staff unisex	218	SF	7	10+ years			
	Doors - Transom Window	3rd Floor staff unisex	9	SF	7	10+ years			
						•			

Campus Name: Moos Page : 12 of 47 Assessment Date: 02/26/2024



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	3rd Floor staff unisex	1	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	3rd Floor staff unisex	154	SF	7	10+ years			
	Floor - Tile	3rd Floor staff unisex	64	SF	7	10+ years			
	Lavatory	3rd Floor staff unisex	1	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor staff unisex	4	EA	7	6-10 years			
	Lighting - Pendent/Surface	3rd Floor staff unisex	1	EA	5	0-1 year	Missing cover		
	Partitions	3rd Floor staff unisex	1	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor staff unisex	362	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	3rd Floor staff unisex	100	SF	6	10+ years			
	Water Closet	3rd Floor staff unisex	1	EA	7	10+ years			
	Accessories	In boiler room	15	SF	5	2-5 years			
	Ceiling - Plaster/Drywall	In boiler room	15	SF	5	1-2 years	Damaged ceiling		
	Doors - Wood Doors inclu hw	In boiler room	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	In boiler room	15	SF	7	2-5 years			
	Lavatory	In boiler room	1	EA	7	10+ years			
	Lighting - Wall Mounted	In boiler room	1	EA	7	2-5 years			
	Walls - Masonry	In boiler room	40	SF	5	1-2 years	Poor wall condition throughout		
	Walls - Tile Ceramic/ Porcelain	In boiler room	20	SF	7	10+ years			
	Water Closet	In boiler room	1	EA	7	10+ years			
	Accessories	Main office	60	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Main office	60	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Main office	1	EA	7	10+ years			
	Floor - Wood	Main office	60	SF	7	6-10 years			
	Lavatory	Main office	1	EA	7	10+ years			
	Lighting - Chandelier, Incandescent	Main office	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Main office	150	SF	7	10+ years			
	Water Closet	Main office	1	EA	7	10+ years			

Category : Classroom **Building: Main** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	m #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	37	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	891	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	5	1-2 years	Not working
	Marker Board	1st Floor	24	LF	7	6-10 years	-
	Storage/ Closet	1st Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,193	SF	7	10+ years	

Campus Name: Moos Page : 13 of 47 Assessment Date: 02/26/2024



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #101 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	6	LF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	891	SF	7	10+ years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years			
	Floor - Wood	1st Floor	891	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	15	ĒΑ	7	6-10 years			
	Marker Board	1st Floor	35	LF	7	6-10 years			
	Storage/ Closet	1st Floor	115	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,193	SF	7	10+ years			
Classroo	om #102 (Regular Classroom)								
_1000100	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	6	LF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	891	SF	7	10+ years			
	Doors - Transom Window	1st Floor	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years			
	Floor - Tile	1st Floor	881	SF	7	6-10 years			
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Damaged tile		
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	Damaged tile		
	Marker Board	1st Floor	42	LF	7	-			
	Storage/ Closet	1st Floor	115	SF	5	6-10 years	Peeling paint		
	Walls - Plaster/Drywall	1st Floor	1,193	SF	7	10+ years	reeling paint		
	walls - Flastel/Drywall	151 11001	1,193	SF	,	10+ years			
Classroo	m #103 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	6	LF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	891	SF	7	10+ years			
	Chalk Board	1st Floor	4	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	27	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Floor - Tile	1st Floor	891	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Not working		
	Marker Board	1st Floor	35	LF	7	6-10 years			
	Storage/ Closet	1st Floor	115	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,193	SF	7	10+ years			
Classroo	m #106 (Regular Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	6	LF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	891	SF	7	10+ years			



Catego	Category : Classroom		В	uilding	: Main		•		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	1st Floor	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Floor - Wood	1st Floor	891	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years			
	Marker Board	1st Floor	32	LF	7	6-10 years			
	Storage/ Closet	1st Floor	115	SF	5	10+ years	Peeling paint		
	Walls - Plaster/Drywall	1st Floor	1,193	SF	7	10+ years			
Classroo	om #107 (Regular Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	6	LF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	784	SF	7	10+ years			
	Doors - Transom Window	1st Floor	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years			
	Floor - Wood	1st Floor	784	SF	7	•			
	Lighting - Pendent/Surface	1st Floor	_	EA	7	10+ years			
			14			6-10 years	Not consider a		
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Not working		
	Marker Board	1st Floor	40	LF	7	6-10 years			
	Storage/ Closet	1st Floor	115	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,116	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	4	SF	5	1-2 years	Minor wall damage		
Classroo	om #108 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	10	LF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	861	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	30	SF	6	10+ years	Peeling paint		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	•		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Wood	1st Floor	891	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Not working		
	Marker Board	1st Floor	35	LF	7	6-10 years	Tiot Working		
	Walls - Plaster/Drywall	1st Floor	1,193	SF	7	10+ years			
Classroo	om #109 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	10	LF	7	10+ years			
	Casework Ceiling - Plaster/Drywall	1st Floor	851	SF	6	10+ years 10+ years			
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	1st Floor		SF SF			Dealing point		
	Doors - Transom Window		40	SF SF	6	10+ years	Peeling paint		
		1st Floor	9		7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Wood	1st Floor	891	SF	7	10+ years			

Campus Name: Moos Page : 15 of 47 Assessment Date: 02/26/2024



Catego	ry : Classroom		B	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Marker Board	1st Floor	35	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,190	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3	SF	5	1-2 years	Damaged plaster wall
Classroc	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	891	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	35	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,189	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4	SF	5	1-2 years	Damaged.
Classroc	om #201 (Art Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	891	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	ĒA	7	6-10 years	
	Marker Board	2nd Floor	35	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,193	SF	7	10+ years	
	Work Sink	2nd Floor	2	ĒΑ	7	10+ years	
Classroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	891	SF	7	10+ years	
	Chalk Board	2nd Floor	1	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,193	SF	7	10+ years	

Campus Name: Moos Page : 16 of 47 Assessment Date: 02/26/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #203 (Science)						
<u> </u>	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	891	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Eve Wash Station	2nd Floor	<u>-</u> 1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	35	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,193	SF	7	10+ years	
	Work Sink	2nd Floor	2	ĒΑ	7	10+ years	
Classra	om #204 (Music Boom)						
Classroo	om #204 (Music Room) AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	1,026	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,026	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,921	SF	7	10+ years	
Classro	om #206 (Regular Classroom)						
Classice	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	891	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	34	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,193	SF	7	10+ years	
Classra	om #207 (Regular Classroom)						
_Ciassio		2nd Floor	4	Г^	7	6.10	
	AC Units	2nd Floor 2nd Floor	1	EA LF	7	6-10 years	
	Casework Ceiling - Plaster/Drywall		6	SF	7 7	10+ years	
	Cening - Flaster/Drywall	2nd Floor	891	SF	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	891	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,193	SF	7	10+ years	
Classroo	om #208 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	891	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,203	SF	7	10+ years	
01	(1000 (P)						
_Classroo	om #209 (Play Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	891	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,193	SF	7	10+ years	
Classroo	om #300 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	891	SF	7	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	1	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,193	SF	7	10+ years	
	,	<del></del>	.,	-· -	-	- <b>,</b>	

Campus Name: Moos Page : 18 of 47 Assessment Date: 02/26/2024



Catego	ry : Classroom		В	uilding	: Main		TN Camornia AVENCE, Chicago, IE 00047
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #301 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	891	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	ĒA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,193	SF	7	10+ years	
		0.0.1.00.	1,100	•	•	.o. you.o	
Classroo	om #302 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	891	SF	7	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	 1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,193	SF	7	10+ years	
			.,			, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #303 (Science Lab Level 1)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	32	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	891	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,193	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	14	LF	7	10+ years	
	Cacowork	314 1 1001	14	LI	,	TOT years	



Catego	ry : Classroom		В	uilding	: Main		TN Callottia AVENCE, Chicago, le 00047
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	891	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,193	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	891	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	•	
				SF EA		10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	SF	7 7	10+ years	
	Floor - Wood	3rd Floor	891			10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,193	SF	7	10+ years	
_Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	891	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	891	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,193	SF	7	10+ years	
_Classroo	om #309 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	891	SF	5	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu hw	3rd Floor	891	SF	7	10+ years 10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	

Campus Name: Moos Page : 20 of 47 Assessment Date: 02/26/2024



Catego	ry : Classroom		Βι	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Marker Board	3rd Floor	35	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,193	SF	7	10+ years		

Category : Interior			В	uilding			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	2,924	SF	6	10+ years	
	Doors - Transom Window	1st Floor	4	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EΑ	7	6-10 years	
	Floor - Asphalt Floor	1st Floor	2,924	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	28	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	4,050	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	37	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,924	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	5	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	2,924	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	28	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,050	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	37	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,924	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	2	ĒΑ	7	10+ years	
	Doors - Transom Window	3rd Floor	4	SF	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	ĒΑ	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	2	ΕA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	2,924	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	28	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,050	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	37	SF	7	10+ years	
	Ceiling - Exposed	Basement	2,426	SF	6	10+ years	
	Ceiling - Lay-in	Basement	606	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EΑ	7	10+ years	
	Doors - Wood Doors include hw	Basement	4	EΑ	7	10+ years	
	Floor - Tile/Sheet	Basement	3,032	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement	32	EA	7	6-10 years	
	Student Lockers - One Tier	Basement	5	EΑ	7	10+ years	
	Walls - Masonry	Basement	713	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,784	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	1,070	SF	7	10+ years	

Safety

Campus Name: Moos Page : 21 of 47 Assessment Date: 02/26/2024



Category : Interior			В	uilding	: Main		
						Recommend	
∂roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Metal Detector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	12	EA	7	6-10 years	
airs							
	Ceiling - Plaster/Drywall	Behind auditorium stage north	100	SF	6	10+ years	
	Floor - Rubber Floor	Behind auditorium stage north	20	SF	6	10+ years	
	Handrails	Behind auditorium stage north	12	LF	5	10+ years	
	Lighting - Pendent/Surface	Behind auditorium stage north	1	EA	7	6-10 years	
	Stairs - Rubber	Behind auditorium stage north	39	LF	6	10+ years	
	Walls - Plaster/Drywall	Behind auditorium stage north	250	SF	4	0-1 year	Damaged.
	Ceiling - Plaster/Drywall	Behind auditorium stage south	100	SF	4	0-1 year	Water damage.
	Floor - Wood	Behind auditorium stage south	20	SF	5	10+ years	
	Handrails	Behind auditorium stage south	20	LF	5	10+ years	
	Stairs - Wood	Behind auditorium stage south	45	LF	5	10+ years	
	Walls - Plaster/Drywall	Behind auditorium stage south	250	SF	4	0-1 year	Water damage.
	Ceiling - Plaster/Drywall	North Stair	648	SF	7	10+ years	
	Floor - Asphalt	North Stair	583	SF	7	10+ years	
	Floor - Terrazzo	North Stair	65	SF	7	10+ years	
	Handrails	North Stair	176	LF	7	10+ years	
	Lighting - Lay-in	North Stair	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	North Stair	12	EA	7	6-10 years	
	Stairs - Asphalt	North Stair	84	LF	7	10+ years	
	Walls - Plaster/Drywall	North Stair	1,323	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South Staiirs	648	SF	7	10+ years	
	Floor - Asphalt	South Staiirs	583	SF	7	10+ years	
	Floor - Terrazzo	South Staiirs	65	SF	7	10+ years	
	Handrails	South Staiirs	176	LF	7	10+ years	
	Lighting - Pendent/Surface	South Staiirs	14	EA	7	6-10 years	
	Stairs - Asphalt	South Staiirs	83	LF	7	10+ years	
	Walls - Plaster/Drywall	South Staiirs	1,323	SF	7	10+ years	

Campus Name: Moos Page : 22 of 47 Assessment Date: 02/26/2024





Category : Exterior **Building: Addition** 

			Ŭ		Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance	2004	Quantity	<b>O</b> 0	rtaint	replacement	
Entrance Control - Audio	#3 W	1	ΕΛ	7	6 10 veers	
		1	EΑ	7	6-10 years	
Exterior Doors - Store Front	#3 W	3	EΑ	7	10+ years	
Exterior Doors - Transom Lite	#3 W	3	EΑ	7	10+ years	
Exterior Doors - Store Front	#4 W	3	EA	7	10+ years	
Exterior Doors - Transom Lite	#4 W	3	EA	7	10+ years	
Exterior Doors - Exterior Steel Door	#5_Exit W	2	EΑ	6	10+ years	
Exterior Doors - Exterior Steel Door	#6 N	2	EA	6	10+ years	
Exterior Doors - Exterior Steel Door	#7 N	1	EA	6	10+ years	
Entrance Control - Audio	#8 E	1	EA	7	6-10 years	
Exterior Doors - Store Front	#8 E	2	EA	7	10+ years	
Exterior Doors - Transom Lite	#8 E	2	EA	7	10+ years	
Exterior Doors - Exterior Steel Door	#8.1 E	2	EA	6	10+ years	
oundation						
Foundation - Concrete	Entire Building	652	LF	7	10+ years	
Superstructure - Metal Deck/ Concrete	Entire Building	57,687	SF	7	10+ years	
Topping	g	0.,00.	•	•	. o . y cano	
. oppg						
ghting						
Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	7	6-10 years	
Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	6-10 years	
oof System						
Access Ladder - Metal	Roof #1	2	EA	7	10+ years	
Access Ladder - Metal	Roof #1	1	EA	7	10+ years	
Coping - Stone	Roof #1	156	LF	7	10+ years	
Downspouts - Interior Downspouts	Roof #1	160	LF	7	10+ years	
Parapet - 16" - 30" Height	Roof #1	10	LF	7	10+ years	
Parapet - Parapet > 30"	Roof #1	146	LF	7	10+ years	
Roof - Modified Bitumen	Roof #1	2,278	SF	7	10+ years	
Roof Hatch - Metal	Roof #1	2,270	EA	7	10+ years	
Roof Structure - Steel / Metal Deck/	Roof #1	2,278	SF	7	10+ years	
Concrete Topping	11001 # 1	2,270	Oi	,	10+ years	
Access Ladder - Metal	Roof #2	2	EA	7	10+ years	
Coping - Stone	Roof #2	388	LF	7	•	
Downspouts - Interior Downspouts	Roof #2 Roof #2	240	LF LF	7	10+ years	
Parapet - Parapet > 30"	Roof #2	388	LF	7	10+ years	
Roof - Modified Bitumen					10+ years	
	Roof #2	12,020	SF	7	10+ years	
Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof #2	12,020	SF	7	10+ years	
Access Ladder - Metal	Roof #3	1	EA	7	10+ years	
ACCOS Educio Metal	1301 #0	'		'	TOT years	



Catego	ory : Exterior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chimney - Metal Flue	Roof #3	10	LF	7	10+ years	
	Coping - Stone	Roof #3	295	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof #3	200	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof #3	64	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof #3	231	LF	7	10+ years	
	Roof - Modified Bitumen	Roof #3	7,655	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof #3	7,655	SF	7	10+ years	
	Concrete Topping	NOOI NO	7,000	O.	•	101 youro	
Nalls							
	Exterior Walls - Brick	Entire Building	19,677	SF	7	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	4,136	SF	7	10+ years	
Vindow	s						
	Curtain wall - Louver	Entire Building	12	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	1,860	SF	7	10+ years	
	Lintels - Steel	Entire Building	777	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,502	SF	7	10+ years	
Catego	ory : Electrical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>-merge</u>	ncy System						
-merge	ncy System Emergency A/C Power - Corridors and Stairs	Entire Building	10,711	SF	6	6-10 years	
-merge	Emergency A/C Power - Corridors and Stairs	C				•	
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms	Entire Building	4,668	SF	6	6-10 years	
:merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets	Entire Building Entire Building	4,668 1,797	SF SF	6 6	6-10 years 6-10 years	
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms	Entire Building	4,668	SF	6	6-10 years	
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs	Entire Building Entire Building Entire Building	4,668 1,797	SF SF	6 6	6-10 years 6-10 years 6-10 years	
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms	Entire Building Entire Building Entire Building Entire Building	4,668 1,797 42	SF SF EA	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs	Entire Building Entire Building Entire Building	4,668 1,797 42	SF SF EA	6 6 6	6-10 years 6-10 years 6-10 years	Quantity changed as total has beer
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets	Entire Building Entire Building Entire Building Entire Building Entire Building	4,668 1,797 42 4 6	SF SF EA EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Quantity changed as total has beer divided/aggregated. Arrow on sign face directs building
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	4,668 1,797 42 4 6 28	SF SF EA EA EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Quantity changed as total has been divided/aggregated. Arrow on sign face directs building
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	4,668 1,797 42 4 6 28	SF SF EA EA EA EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Quantity changed as total has beer divided/aggregated. Arrow on sign face directs building evacuees away from Exit #4 rather
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs  Exit Signs - Corridors and Stairs	Entire Building	4,668 1,797 42 4 6 28	SF SF EA EA EA EA	6 6 6 6 6 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year	Quantity changed as total has beer divided/aggregated. Arrow on sign face directs building evacuees away from Exit #4 rather
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs  Exit Signs - Corridors and Stairs  Exit Signs - Lunchroom	Entire Building	4,668 1,797 42 4 6 28	SF SF EA EA EA EA	6 6 6 6 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-10 years	Quantity changed as total has been divided/aggregated. Arrow on sign face directs building evacuees away from Exit #4 rather
-merge	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs  Exit Signs - Corridors and Stairs  Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection	Entire Building	4,668 1,797 42 4 6 28 1	SF SF EA EA EA EA SF	6 6 6 6 5 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year	Quantity changed as total has been divided/aggregated. Arrow on sign face directs building evacuees away from Exit #4 rather

Campus Name: Moos Page : 24 of 47 Assessment Date: 02/26/2024



Catego	ry : Electrical		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PA System	Entire Building	57,687	SF	6	6-10 years	Serves Main and Addition.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	10+ years	Quantity changed to match current observations and as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	19	EA	7	10+ years	Quantity changed to match current observations and as total has been divided/aggregated. Some panels secured shut for safety reasons with condition verified by Building Engineer.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	7	10+ years	Quantity changed to match current observations.
Catego	ry : Fire Protection		В	uildina	: Additio	on	
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m		•				
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	Serves Main and Addition. No CPS Asset Tag present.
	Fire Alarm Strobe Lights	Entire Building	57,687	SF	6	10+ years	• .
	Fire Alarm_System	Entire Building	57,687	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
Pump Re	oom Assembly						
r ump ixi	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	10+ years	
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	
	oconcy i amp	Wednamear reem	·	_, 、	Ŭ	.o. youro	
Sprinkler	r Svstem						
	Sprinkler Heads	Entire Building	57,687	SF	7	10+ years	
	Sprinkler Piping	Entire Building	57,687	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	57,687	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Addition		
0	Itama Tuma	Laatian	0	LICAS	Devil	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	4	2-5 years	Component of a ductless split syster serving MDF Room. Original to the building. Rank, Reason and Priority

Campus Name: Moos Page : 25 of 47 Assessment Date: 02/26/2024



Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Rep adjusted based on current observations that the equipment is functional but is 22 years old and has exceeded its anticipated service life.
	Chemical Pot Feeder	Roof	1	EA	5	6-10 years	
	Chiller-Air Cooled-Screw Type-Roof Mounted - 101 - 200 tons	Roof	1	EA	4	2-5 years	CPS Asset Tag not legible. Original to the building. Rank, Reason and Priority Rep adjusted based on current observations that the equipment is functional but is 22 years old and has exceeded its anticipated service life.
	Glycol Feed	Roof	1	EA	6	10+ years	
	Pipes - Chilled Water Pipe- Copper	Roof	200	LF	6	10+ years	
	Pressure Fill System	Roof	1	EA	6	6-10 years	
Air Hand	lling Systems						
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	27	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	2	EA	6	6-10 years	RF-1, RF-3
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-2
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	AHU-1, serves 1st floor. No CPS Asset Tag present.
	Air Intake	Mechanical Room - AHU-1	1	EA	6	6-10 years	
	VAV Box	Mechanical Room - AHU-1	10	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-2	1	EA	5	6-10 years	AHU-2, serves 2nd floor.
	Air Intake	Mechanical Room - AHU-2	1	EA	6	6-10 years	
	VAV Box	Mechanical Room - AHU-2	5	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room - AHU-3	1	EA	5	6-10 years	AHU-3, serves lunchroom, kitchen, and associated spaces.
	Air Intake	Mechanical Room - AHU-3	1	EA	6	6-10 years	
Boiler Sy	vstems						
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	2	EA	5	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	5	6-10 years	B-2

Campus Name: Moos Page : 26 of 47 Assessment Date: 02/26/2024



Category : Mechanical			В	uilding	: Additi		
<b>0</b>	Name Tame	Laadian	0	11014	Danila	Recommend	0
Group	Item - Type Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Location	Quantity	UOM	Rank	Replacement	Comments
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	5	6-10 years	B-1
	Water Fill System	Boiler Room	1	EA	6	10+ years	
Sas Boo	ester						
	Gas Booster	Mechanical Room	1	EA	6	10+ years	
leating	Devices						
Ū	Radiator Panels - Hot Water	1st Floor	15	EA	5	6-10 years	Quantity changed to match current observations. Ceiling-mounted in student restrooms and in select 1st-floor offices.
	Radiator Panels - Hot Water	1st Floor	1	EA	5	1-2 years	Ceiling-mounted in 2nd-floor Girls restroom; panel has a damaged mounting means.
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	Located in a closet inside Room 006A. Quantity changed as total habeen divided/aggregated.
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	Located in Storage Rooms 120 and 220.
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	
lechani	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	500	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	100	LF	6	10+ years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	Serves boilers. Item Type changed for clarification. No CPS Asset Tag present. Rank adjusted based on current observations and per review with Building Engineer that no repa are needed as of the time of assessment.
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	Serves boilers. Item Type changed for clarification. No CPS Asset Tag present. Rank adjusted based on current observations and per review with Building Engineer that no repart needed as of the time of

Campus Name: Moos Page : 27 of 47 Assessment Date: 02/26/2024



Catego	ry : Mechanical		В	uilding	: Additi	on	
			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	assessment. Circulation pump associated with AHU-3. No CPS Asset Tag present. Rank adjusted based on current observations and per review with
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Building Engineer that no repairs are needed as of the time of assessment. Circulation pump associated with AHU-1. No CPS Asset Tag present. Rank adjusted based on current observations and per review with Building Engineer that no repairs are
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	needed as of the time of assessment. Circulation pump associated with AHU-2. No CPS Asset Tag present. Rank adjusted based on current observations and per review with Building Engineer that no repairs are needed as of the time of assessment.
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	5	6-10 years	No CPS Asset Tag present.
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	5	6-10 years	No CPS Asset Tag present.
Tompore	ature Control						
теттрета	DDC System	Entire Building	57,687	SF	5	6-10 years	
	Electric Thermostat	Entire Building	57,007	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	43	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
Ventilation	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Located in Mechanical Room.  Quantity changed based on current observations and per review with Building Engineer.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Item Type changed to match current observations. Location changed for clarification.
	Type I Exhaust Hood- Kitchen	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	Quantity changed to match current observations.

Campus Name: Moos Page : 28 of 47 Assessment Date: 02/26/2024



Catego	ry : Plumbing	В	Building : Addition				
_	<u> </u>					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Electric Heater - Greater than 50 KW	1st Floor	1	EA	5	6-10 years	Location changed for clarification.
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	Serve Addition.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	57,687	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	57,687	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	57,687	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	57,687	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	57,687	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	57,687	SF	6	10+ years	
	Sanitary Piping	Entire Building	57,687	SF	6	10+ years	
	Storm Piping	Entire Building	57,687	SF	6	10+ years	
	Vent Piping	Entire Building	57,687	SF	6	10+ years	
Pumps							
-	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Elevator pit sump pump. Not directly accessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer.

Category : Room **Building: Addition** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Adminis	trative Suites/Offices					•	
	Ceiling - Lay-in	002A - Business Office	433	SF	7	10+ years	
	Ceiling - Lay-in	002A - Business Office	4	SF	4	1-2 years	Missing tile
	Doors - Side-lite	002A - Business Office	70	SF	7	10+ years	
	Doors - Steel Doors incl hw	002A - Business Office	1	EA	7	10+ years	
	Floor - Carpet	002A - Business Office	309	SF	7	6-10 years	
	Floor - Carpet	002A - Business Office	10	SF	4	1-2 years	Ripped carpet
	Floor - Terrazzo	002A - Business Office	118	SF	7	10+ years	
	Lighting - Lay-in	002A - Business Office	10	EA	7	10+ years	
	Power Distribution	002A - Business Office	6	EA	7	10+ years	
	Walls - Concrete Block	002A - Business Office	445	SF	7	10+ years	
	Walls - Plaster/Drywall	002A - Business Office	223	SF	7	10+ years	
	Ceiling - Lay-in	002B - Counseling	168	SF	7	10+ years	
	Celling - Lay-III	002B - Counselling	100	SF	1	10+ years	

Campus Name: Moos Page : 29 of 47 Assessment Date: 02/26/2024



Catego	ry : Room	Building : Addition					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	002B - Counseling	1	EA	7	10+ years	
	Floor - Carpet	002B - Counseling	168	SF	7	6-10 years	
	Lighting - Lay-in	002B - Counseling	2	EA	7	10+ years	
	Power Distribution	002B - Counseling	10	EA	7	10+ years	
	Walls - Plaster/Drywall	002B - Counseling	10	SF	7	10+ years	
	Walls - Plaster/Drywall	002B - Counseling	409	SF	7	10+ years	
	Ceiling - Lay-in	002C - Principal	168	SF	7	10+ years	
	Doors - Wood Doors inclu hw	002C - Principal	1	EA	7	10+ years	
	Floor - Carpet	002C - Principal	168	SF	7	6-10 years	
	Lighting - Lay-in	002C - Principal	2	EA	7	10+ years	
	Power Distribution	002C - Principal	10	EA	7	10+ years	
	Walls - Concrete Block	002C - Principal	89	SF	7	10+ years	
	Walls - Plaster/Drywall	002C - Principal	330	SF	7	10+ years	
	Ceiling - Lay-in	002D - Vault/Workroom (signage 002C)	200	SF	7	10+ years	
	Ceiling - Lay-in	002D - Vault/Workroom (signage 002C)	4	SF	4	1-2 years	Scrapped tile
	Doors - Steel Doors incl hw	002D - Vault/Workroom (signage 002C)	1	EA	7	10+ years	
	Floor - Tile	002D - Vault/Workroom (signage 002C)	204	SF	7	10+ years	
	Lighting - Lay-in	002D - Vault/Workroom (signage 002C)	4	EA	7	10+ years	
	Power Distribution	002D - Vault/Workroom (signage 002C)	12	EA	7	10+ years	
	Walls - Concrete Block	002D - Vault/Workroom (signage 002C)	585	SF	7	10+ years	
	Work Slnk	002D - Vault/Workroom (signage 002C)	1	EA	7	10+ years	
	Ceiling - Lay-in	004A - Student Services	149	SF	7	10+ years	
	Doors - Wood Doors inclu hw	004A - Student Services	1	EA	7	10+ years	
	Floor - Tile	004A - Student Services	149	SF	7	10+ years	
	Lighting - Lay-in	004A - Student Services	2	EA	7	10+ years	
	Power Distribution	004A - Student Services	2	EA	7	10+ years	
	Walls - Concrete Block	004A - Student Services	173	SF	7	10+ years	
	Walls - Plaster/Drywall	004A - Student Services	208	SF	7	10+ years	
	Work SInk	004A - Student Services	1	ĒΑ	7	10+ years	
	Ceiling - Lay-in	004B - Assistant Principal	570	SF	7	10+ years	
	Doors - Side-lite	004B - Assistant Principal	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	004B - Assistant Principal	2	ĒΑ	7	10+ years	
	Floor - Tile	004B - Assistant Principal	570	SF	7	10+ years	
	Lighting - Lay-in	004B - Assistant Principal	6	ĒΑ	6	10+ years	
	Lighting - Lay-in	004B - Assistant Principal	1	EA	5	1-2 years	Not working
	Power Distribution	004B - Assistant Principal	22	EA	7	10+ years	3

Campus Name: Moos Page : 30 of 47 Assessment Date: 02/26/2024



Catego	ry : Room		В	uilding	: Addition		
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	004B - Assistant Principal	205	SF	7	10+ years	
	Walls - Plaster/Drywall	004B - Assistant Principal	605	SF	7	10+ years	
	Ceiling - Lay-in	111A	104	SF	7	10+ years	
	Ceiling - Plaster/Drywall	111A	62	SF	7	10+ years	
	Doors - Side-lite	111A	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	111A	2	EA	7	10+ years	
	Floor - Tile	111A	166	SF	7	10+ years	
	Lighting - Lay-in	111A	2	EA	7	10+ years	
	Lighting - Lay-in	111A	1	EA	5	1-2 years	Missing cover
	Power Distribution	111A	12	EA	7	10+ years	3
	Storage/ Closet	111A	50	SF	7	10+ years	
	Walls - Concrete Block	111A	280	SF	7	10+ years	
	Walls - Plaster/Drywall	111A	280	SF	7	10+ years	
	Work Sink	111A	1	EA	7	10+ years	
	Ceiling - Lay-in	218 - Staff Lounge	344	SF	7	10+ years	
	Ceiling - Lay-in	218 - Staff Lounge	22	SF	4	0-1 year	Water damage
			94	SF		-	water damage
	Ceiling - Plaster/Drywall	218 - Staff Lounge	-		7	10+ years	
	Doors - Wood Doors inclu hw	218 - Staff Lounge	1	EA	7	10+ years	
	Floor - Tile	218 - Staff Lounge	460	SF	7	10+ years	
	Lighting - Lay-in	218 - Staff Lounge	6	EA	7	10+ years	
	Power Distribution	218 - Staff Lounge	20	EA	7	10+ years	
	Walls - Concrete Block	218 - Staff Lounge	582	SF	7	10+ years	
	Walls - Plaster/Drywall	218 - Staff Lounge	228	SF	7	10+ years	
	Work SInk	218 - Staff Lounge	1	EA	7	10+ years	
	Ceiling - Lay-in	310	513	SF	7	10+ years	
	Ceiling - Lay-in	310	8	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	310	1	EA	7	10+ years	•
	Floor - Tile	310	521	SF	7	10+ years	
	Lighting - Lay-in	310	6	ĒΑ	7	10+ years	
	Power Distribution	310	12	EA	7	10+ years	
	Walls - Concrete Block	310	851	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Manager	70	SF	7	10+ years	
	Doors - Side-lite	Kitchen Manager	36	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Manager	1	EA	7	10+ years	
	Floor - Carpet	Kitchen Manager	70	SF	7	10+ years	
		•	_	EA	7	•	
	Lighting - Lay-in	Kitchen Manager	1			10+ years	
	Power Distribution	Kitchen Manager	4	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Manager	220	SF	7	10+ years	
	Ceiling - Lay-in	Mail Room in Business Office	156	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Mail Room in Business Office	3	EA	7	10+ years	
	Floor - Carpet	Mail Room in Business Office	156	SF	7	6-10 years	
	Lighting - Lay-in	Mail Room in Business Office	2	EA	7	10+ years	
	Power Distribution	Mail Room in Business Office	4	EA	7	10+ years	
	Storage/ Closet	Mail Room in Business Office	24	SF	7	10+ years	

Campus Name: Moos Page : 31 of 47 Assessment Date: 02/26/2024



Catego	ory : Room		В	uilding	: Additi	on	,
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Mail Room in Business Office	235	SF	7	10+ years	
	Walls - Plaster/Drywall	Mail Room in Business Office	235	SF	7	10+ years	
<u>Kitchen</u>		_					
	Ceiling - Lay-in	Basement	1,088	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	1,088	SF	7	10+ years	
	Lighting - Lay-in	Basement	20	EA	7	10+ years	
	Storage/ Closet	Basement	130	SF	7	10+ years	
	Walls - Concrete Block	Basement	1,022	SF	7	10+ years	
Library							
	Casework	111	206	LF	7	10+ years	
	Ceiling - Lay-in	111	1,900	SF	7	10+ years	
	Doors - Side-lite	111	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	111	2	EA	7	10+ years	
	Floor - Carpet	111	1,885	SF	7	6-10 years	
	Floor - Carpet	111	15	SF	4	1-2 years	Ripped.
	Lighting - Lay-in	111	29	ĒΑ	7	10+ years	11
	Storage/ Closet	111	200	SF	5	1-2 years	Damaged ceiling tile
	Walls - Concrete Block	111	1,204	SF	7	10+ years	Damagea coming me
	Walls - Plaster/Drywall	111	320	SF	7	10+ years	
Lunch 8	Multipurpose Room						
LUITOITO	Ceiling - Exposed	Basement 008 + 046	3.420	SF	7	10+ years	
	Ceiling - Exposed Ceiling - Lay-in	Basement 008 + 046	-, -	SF	7	10+ years	
			1,248			•	
	Doors - Steel Doors incl hw	Basement 008 + 046	14	EA	7	10+ years	
	Floor - Tile/Sheet	Basement 008 + 046	4,668	SF	7	10+ years	
	Lighting - Lay-in	Basement 008 + 046	12	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Basement 008 + 046	16	EA	7	10+ years	
	Serving Line	Basement 008 + 046	46	LF	7	10+ years	
	Storage/ Closet	Basement 008 + 046	153	SF	7	10+ years	
	Walls - Concrete Block	Basement 008 + 046	6,500	SF	7	10+ years	
	Walls - Concrete Block	Basement 008 + 046	2,124	SF	7	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	121	1	EA	7	10+ years	
	Finishes	121	75	SF	7	10+ years	
	Other Cooling Unit	121	1	EA	7	6-10 years	Ceiling mounted FCU.
Mechani	ical/ Service Rooms						
_ IVICOI ICIT	Janitor's Closet	1st Floor	14	SF	7	10+ years	
	Janitor's Closet	1st Floor	25	SF	7	•	
	Jailitui 5 Ciuset	191 11001	25	SF	,	10+ years	

Campus Name: Moos Page : 32 of 47 Assessment Date: 02/26/2024



	Catego	ry : Room		В	uilding	: Additi	on	
Mechanical/Service Rooms         1st Floor         144         SF         7         10+ years           Mechanical/Service Rooms         1st Floor         148         SF         7         10+ years           Mechanical/ Service Rooms         1st Floor         178         SF         7         10+ years           Mechanical/ Service Rooms         2nd Floor         3,038         SF         7         10+ years           Mechanical/ Service Rooms         2nd Floor         83         SF         7         10+ years           Mechanical/ Service Rooms         2nd Floor         18         SF         7         10+ years           Storage Room         3rd Floor         18         SF         7         10+ years           Janitor's Closet         3rd Floor         18         SF         7         10+ years           Storage Room         3rd Floor         201         SF         7         10+ years           Storage Room         3rd Floor         201         SF         7         10+ years           Janitor's Closet         Basement         25         SF         7         10+ years           Mechanical/ Service Rooms         Basement         513         SF         7         10+ years </th <th>_</th> <th></th> <th></th> <th></th> <th>_</th> <th></th> <th></th> <th></th>	_				_			
Mechanical/ Service Rooms         1st Floor         144         SF         7         10+ years           Mechanical/ Service Rooms         1st Floor         25         SF         7         10+ years           Janitor's Closet         2nd Floor         3,038         SF         7         10+ years           Mechanical/ Service Rooms         2nd Floor         83         SF         7         10+ years           Mechanical/ Service Rooms         2nd Floor         20         SF         7         10+ years           Storage Room         2nd Floor         20         SF         7         10+ years           Janitor's Closet         3rd Floor         38         SF         7         10+ years           Mechanical/ Service Rooms         3rd Floor         38         SF         7         10+ years           Mechanical/ Service Rooms         3rd Floor         38         SF         7         10+ years           Mechanical/ Service Rooms         3rd Floor         47         SF         7         10+ years           Mechanical/ Service Rooms         Basement         25         SF         7         10+ years           Mechanical/ Service Rooms         Basement         513         SF         7         <	Group			Quantity		Rank		Comments
Mechanical/ Service Rooms         1st Floor         178         SF         7         10+ years           Janitor's Closet         2nd Floor         25         SF         7         10+ years           Mechanical/ Service Rooms         2nd Floor         83         SF         7         10+ years           Mechanical/ Service Room         2nd Floor         83         SF         7         10+ years           Janitor's Closet         3rd Floor         18         SF         5         10+ years           Janitor's Closet         3rd Floor         18         SF         7         10+ years           Storage Room         3rd Floor         201         SF         7         10+ years           Storage Room         3rd Floor         201         SF         7         10+ years           Janitor's Closet         Basement         25         SF         7         10+ years           Janitor's Closet         Basement         25         SF         7         10+ years           Mechanical/ Service Rooms         Basement         25         SF         7         10+ years           Storage Room         Basement         25         SF         7         10+ years           Storage R		Mechanical/ Service Rooms	1st Floor	117		7	10+ years	
Janitor's Closet		Mechanical/ Service Rooms	1st Floor	144		7	10+ years	
Mechanical/ Service Rooms         2nd Floor         3,038         SF         7         10+ years           Mechanical/ Service Rooms         2nd Floor         200         SF         7         10+ years           Janitor's Closet         3rd Floor         18         SF         5         10+ years           Mechanical/ Service Rooms         3rd Floor         38         SF         7         10+ years           Storage Room         3rd Floor         201         SF         7         10+ years           Mechanical/ Service Rooms         3rd Floor         201         SF         7         10+ years           Janitor's Closet         Basement         25         SF         7         10+ years           Mechanical/ Service Rooms         Basement         25         SF         7         10+ years           Storage Room         Basement         42         SF         7         10+ years           Storage Room         Basement         25         SF         7         10+ years           Storage Room         Basement         25         SF         7         10+ years           Storage Room         0014         42         SF         7         10+ years           Storage Ro		Mechanical/ Service Rooms	1st Floor	178			10+ years	
Mechanical Service Rooms		Janitor's Closet	2nd Floor	25		7	10+ years	
Storage Room			2nd Floor	3,038		7	10+ years	
Janitor's Closet   3rd Floor   18   SF   5   10 + ýears		Mechanical/ Service Rooms	2nd Floor	83	SF	7	10+ years	
Mechanical/ Service Rooms   3rd Floor   38   SF   7   10+ years		Storage Room		200		7	10+ years	
Storage Room   3rd Floor   47   SF   7   10+ years		Janitor's Closet	3rd Floor	18		5	10+ years	
Mechanical/ Service Rooms		Mechanical/ Service Rooms	3rd Floor	38	SF	7	10+ years	
Janitor's Closet   Basement   25   SF   7   10+ years		Storage Room	3rd Floor	201	SF	7	10+ years	
Janitor's Closet   Basement   25   SF   7   10+ years			4th Floor	47	SF	7	10+ years	
Restroom			Basement		SF	7		
Restroom		Mechanical/ Service Rooms	Basement		SF	7		
Accessories         001A         42         SF         7         6-10 years           Ceiling - Lay-in         001A         42         SF         7         10+ years           Doors - Wood Doors inclu hw         001A         1         EA         6         10+ years           Floor - Tile         001A         42         SF         7         10+ years           Floor Drain         001A         1         EA         7         10+ years           Lavatory         001A         1         EA         7         10+ years           Lighting - Lay-in         001A         89         SF         7         10+ years           Walls - Structural Glazed Tile         001A         89         SF         7         10+ years           Water Closet         001A         1         EA         7         10+ years           Ceiling - Lay-in         003A         42         SF         7         6-10 years           Ceilor - Tile         003A         42         SF         6         10+ years           Floor Train         003A         42         SF         6         10+ years           Layatory         003A         1         EA         7		Storage Room	Basement	80	SF	7		
Accessories         001A         42         SF         7         6-10 years           Ceiling - Lay-in         001A         42         SF         7         10+ years           Doors - Wood Doors inclu hw         001A         1         EA         6         10+ years           Floor - Tile         001A         42         SF         7         10+ years           Floor Drain         001A         1         EA         7         10+ years           Lavatory         001A         1         EA         7         10+ years           Lighting - Lay-in         001A         89         SF         7         10+ years           Waler Closet         001A         89         SF         7         10+ years           Water Closet         001A         1         EA         7         10+ years           Celling - Lay-in         003A         42         SF         7         6-10 years           Color - Tile         003A         42         SF         6         10+ years           Floor Train         003A         42         SF         6         10+ years           Layatory         003A         1         EA         7         10+ years	Postroor	m.						
Ceiling - Lay-in         001A         42         SF         7         10+ years           Doors - Wood Doors inclu hw         001A         1         EA         6         10+ years           Floor - Tile         001A         42         SF         7         10+ years           Floor Drain         001A         1         EA         7         10+ years           Lavatory         001A         1         EA         7         10+ years           Lighting - Lay-in         001A         89         SF         7         10+ years           Water Closet         001A         1         EA         7         10+ years           Accessories         003A         42         SF         7         6-10 years           Ceiling - Lay-in         003A         42         SF         7         10+ years           Doors - Wood Doors inclu hw         003A         42         SF         7         10+ years           Floor - Tile         003A         42         SF         6         10+ years           Floor Drain         003A         1         EA         7         10+ years           Layatory         003A         1         EA         7         1	Resilooi		001 A	42	SF	7	6-10 years	
Doors - Wood Doors inclu hw         001A         1         EA         6         10+ years           Floor - Tile         001A         42         SF         7         10+ years           Floor Drain         001A         1         EA         7         10+ years           Lavatory         001A         1         EA         7         10+ years           Lighting - Lay-in         001A         89         SF         7         10+ years           Walls - Structural Glazed Tile         001A         89         SF         7         10+ years           Water Closet         001A         1         EA         7         10+ years           Accessories         003A         42         SF         7         6-10 years           Ceiling - Lay-in         003A         42         SF         7         10+ years           Floor - Tile         003A         1         EA         7         10+ years           Floor Drain         003A         42         SF         6         10+ years           Floor Drain         003A         1         EA         7         10+ years           Lighting - Lay-in         003A         1         EA         7								
Floor - Tile								
Floor Drain								
Lavatory       001A       1       EA       7       10+ years         Lighting - Lay-in       001A       1       EA       7       10+ years         Walls - Structural Glazed Tile       001A       89       SF       7       10+ years         Water Closet       001A       1       EA       7       10+ years         Accessories       003A       42       SF       7       6-10 years         Ceiling - Lay-in       003A       42       SF       7       10+ years         Floor - Tile       003A       42       SF       6       10+ years         Floor Drain       003A       42       SF       6       10+ years         Layatory       003A       1       EA       7       10+ years         Lighting - Lay-in       003A       1       EA       7       10+ years         Walls - Structural Glazed Tile       003A       89       SF       7       10+ years         Water Closet       003A       42       SF       7       10+ years         Water Closet       003A       1       EA       7       10+ years         Ceiling - Lay-in       005A       42       SF       7								
Lighting - Lay-in       001A       1       EA       7       10+ years         Walls - Structural Glazed Tile       001A       89       SF       7       10+ years         Water Closet       001A       1       EA       7       10+ years         Accessories       003A       42       SF       7       6-10 years         Ceiling - Lay-in       003A       42       SF       6       10+ years         Floor - Tile       003A       42       SF       6       10+ years         Floor Drain       003A       42       SF       6       10+ years         Lavatory       003A       1       EA       7       10+ years         Lighting - Lay-in       003A       1       EA       7       10+ years         Walls - Structural Glazed Tile       003A       89       SF       7       10+ years         Water Closet       003A       1       EA       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       6-10 years         Doors - Wood Doors inclu hw       005A       1       EA <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Walls - Structural Glazed Tile       001A       89       SF       7       10+ years         Water Closet       001A       1       EA       7       10+ years         Accessories       003A       42       SF       7       6-10 years         Ceiling - Lay-in       003A       42       SF       7       10+ years         Ploor - Tile       003A       1       EA       7       10+ years         Floor Drain       003A       42       SF       6       10+ years         Lavatory       003A       1       EA       7       10+ years         Lighting - Lay-in       003A       1       EA       7       10+ years         Water Closet       003A       89       SF       7       10+ years         Water Closet       003A       1       EA       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       005A       1       EA       6       10+ years		•		· · · · · · · · · · · · · · · · · · ·				
Water Closet       001A       1       EA       7       10+ years         Accessories       003A       42       SF       7       6-10 years         Ceiling - Lay-in       003A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       003A       1       EA       7       10+ years         Floor - Tile       003A       42       SF       6       10+ years         Floor Drain       003A       1       EA       7       10+ years         Lavatory       003A       1       EA       7       10+ years         Lighting - Lay-in       003A       1       EA       7       10+ years         Walls - Structural Glazed Tile       003A       89       SF       7       10+ years         Water Closet       003A       1       EA       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       005A       1       EA       6       10+ years				•				
Accessories       003A       42       SF       7       6-10 years         Ceiling - Lay-in       003A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       003A       1       EA       7       10+ years         Floor - Tile       003A       42       SF       6       10+ years         Floor Drain       003A       1       EA       7       10+ years         Lavatory       003A       1       EA       7       10+ years         Lighting - Lay-in       003A       1       EA       7       10+ years         Water Closet       003A       89       SF       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       005A       1       EA       6       10+ years							•	
Ceiling - Lay-in       003A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       003A       1       EA       7       10+ years         Floor - Tile       003A       42       SF       6       10+ years         Floor Drain       003A       1       EA       7       10+ years         Lavatory       003A       1       EA       7       10+ years         Lighting - Lay-in       003A       1       EA       7       10+ years         Water Closet       003A       89       SF       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       005A       1       EA       6       10+ years								
Doors - Wood Doors inclu hw         003A         1         EA         7         10+ years           Floor - Tile         003A         42         SF         6         10+ years           Floor Drain         003A         1         EA         7         10+ years           Lavatory         003A         1         EA         7         10+ years           Lighting - Lay-in         003A         1         EA         7         10+ years           Water Closet         003A         89         SF         7         10+ years           Accessories         003A         1         EA         7         10+ years           Accessories         005A         42         SF         7         6-10 years           Ceiling - Lay-in         005A         42         SF         7         10+ years           Doors - Wood Doors inclu hw         005A         1         EA         6         10+ years								
Floor - Tile       003A       42       SF       6       10+ years         Floor Drain       003A       1       EA       7       10+ years         Lavatory       003A       1       EA       7       10+ years         Lighting - Lay-in       003A       1       EA       7       10+ years         Water Closet       003A       89       SF       7       10+ years         Accessories       003A       1       EA       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       005A       1       EA       6       10+ years								
Floor Drain       003A       1       EA       7       10+ years         Lavatory       003A       1       EA       7       10+ years         Lighting - Lay-in       003A       1       EA       7       10+ years         Walls - Structural Glazed Tile       003A       89       SF       7       10+ years         Water Closet       003A       1       EA       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       005A       1       EA       6       10+ years								
Lavatory       003A       1 EA 7 10+ years         Lighting - Lay-in       003A       1 EA 7 10+ years         Walls - Structural Glazed Tile       003A       89 SF 7 10+ years         Water Closet       003A       1 EA 7 10+ years         Accessories       005A       42 SF 7 6-10 years         Ceiling - Lay-in       005A       42 SF 7 10+ years         Doors - Wood Doors inclu hw       005A       1 EA 6 10+ years					_			
Lighting - Lay-in       003A       1       EA       7       10+ years         Walls - Structural Glazed Tile       003A       89       SF       7       10+ years         Water Closet       003A       1       EA       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       005A       1       EA       6       10+ years								
Walls - Structural Glazed Tile       003A       89       SF       7       10+ years         Water Closet       003A       1       EA       7       10+ years         Accessories       005A       42       SF       7       6-10 years         Ceiling - Lay-in       005A       42       SF       7       10+ years         Doors - Wood Doors inclu hw       005A       1       EA       6       10+ years		•						
Water Closet       003A       1 EA 7 10+ years         Accessories       005A       42 SF 7 6-10 years         Ceiling - Lay-in       005A       42 SF 7 10+ years         Doors - Wood Doors inclu hw       005A       1 EA 6 10+ years								
Accessories         005A         42 SF 7 6-10 years           Ceiling - Lay-in         005A         42 SF 7 10+ years           Doors - Wood Doors inclu hw         005A         1 EA 6 10+ years								
Ceiling - Lay-in 005A 42 SF 7 10+ years Doors - Wood Doors inclu hw 005A 1 EA 6 10+ years								
Doors - Wood Doors inclu hw 005A 1 EA 6 10+ years							-	
Floor Drain 005A 1 EA 7 10+ years					_			
Lavatory 005A 1 EA 7 10+ years								
Lighting - Lay-in 005A 1 EA 7 10+ years				•			•	
Walls - Structural Glazed Tile 005A 89 SF 7 10+ years							•	
Water Closet 005A 1 EA 7 10+ years							•	
Accessories 006A 42 SF 7 6-10 years								
7.000000.100		, 1000001100	000/1	72	J.	,	o io youis	

Campus Name: Moos Page : 33 of 47 Assessment Date: 02/26/2024



Catego	Category : Room		В	uilding	: Additi	on	. 5 :
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	006A	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	006A	1	EΑ	6	10+ years	
	Floor - Tile	006A	40	SF	7	10+ years	
	Floor - Tile	006A	2	SF	4	1-2 years	Broken tiles
	Floor Drain	006A	1	EA	7	10+ years	
	Lavatory	006A	1	EA	7	10+ years	
	Lighting - Lay-in	006A	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	006A	89	SF	7	10+ years	
	Water Closet	006A	1	EA	7	10+ years	
	Accessories	1st Floor	323	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	309	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	14	SF	4	1-2 years	Water stained and cracked ceiling
	Floor - Terrazzo	1st Floor	323	SF	7	10+ years	3
	Floor Drain	1st Floor	2	ĒΑ	7	10+ years	
	Hand Dryer	1st Floor	2	EΑ	7	6-10 years	
	Lavatory	1st Floor	3	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor	3	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	5	1-2 years	Not working
	Partitions	1st Floor	2	EA	7	10+ years	Not working
	Urinals	1st Floor	1	EA	7	10+ years	
	Urinals	1st Floor	1	EA	5	1-2 years	Out of service
	Walls - Structural Glazed Tile	1st Floor	1,258	SF	7	10+ years	Out of service
	Water Closet	1st Floor	1,230	EA	7	10+ years	
	Accessories	1st Floor - Unisex	50	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Unisex	50	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Unisex	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Unisex	50	SF	6	10+ years	
	Floor Drain	1st Floor - Unisex	1	EA	7	•	
			1			10+ years	
	Lavatory	1st Floor - Unisex	·	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor - Unisex	1	EA SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Unisex	137		7	10+ years	
	Water Closet	1st Floor - Unisex	1	EA	7	10+ years	
	Accessories	1st Floor Girls	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	220	SF	7	10+ years	
	Floor - Terrazzo	1st Floor Girls	220	SF	7	10+ years	
	Floor Drain	1st Floor Girls	2	EΑ	7	10+ years	
	Hand Dryer	1st Floor Girls	2	EA	7	6-10 years	
	Lavatory	1st Floor Girls	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Girls	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Girls	1	EA	5	1-2 years	Not working
	Partitions	1st Floor Girls	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girls	482	SF	7	10+ years	
	Water Closet	1st Floor Girls	4	EA	7	10+ years	
	Accessories	2nd Floor	323	SF	7	6-10 years	

Page : 34 of 47 Campus Name: Moos Assessment Date: 02/26/2024



Catego	Category : Room		В	uilding	: Additi	on	. 5
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	323	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	323	SF	7	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	4	EA	7	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	658	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor Girls	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls	208	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Girls	12	SF	5	1-2 years	Water damage
	Floor - Terrazzo	2nd Floor Girls	220	SF	7	10+ years	
	Floor Drain	2nd Floor Girls	2	ĒΑ	7	10+ years	
	Hand Dryer	2nd Floor Girls	2	ĒΑ	7	6-10 years	
	Lavatory	2nd Floor Girls	3	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor Girls	4	EΑ	7	10+ years	
	Partitions	2nd Floor Girls	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girls	782	SF	7	10+ years	
	Water Closet	2nd Floor Girls	3	EA	7	10+ years	
	Water Closet	2nd Floor Girls	1	EA	4	1-2 years	Not in service locked door
	Accessories	3rd Floor	323	SF	7	6-10 years	140t iii del vide locked deel
	Ceiling - Plaster/Drywall	3rd Floor	323	SF	6	10+ years	
	Floor - Terrazzo	3rd Floor	323	SF	7	10+ years	
	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	4	EA	7	10+ years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	558	SF	7	10+ years	
	Water Closet	3rd Floor	1	EA	7	10+ years	
	Water Closet	3rd Floor	1	EA	4	1-2 years	Not working
	Accessories	3rd Floor	220	SF	7	6-10 years	Not working
	Ceiling - Plaster/Drywall	3rd Floor	220	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor	220	SF	7	10+ years	
	Floor Drain	3rd Floor	220	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	4	EA	7	10+ years	
	Partitions	3rd Floor	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	482	SF	7	•	
	Water Closet	3rd Floor	402	SF EA	7	10+ years	
	vvaldi Olusci	SIU FIOOI	4	EA	′	10+ years	

Campus Name: Moos Page : 35 of 47 Assessment Date: 02/26/2024



Catego	tegory : Room			uilding			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	3rd Floor	50	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Concrete	3rd Floor	50	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	137	SF	7	10+ years	
	Accessories	Kitchen - Men	45	SF	7	6-10 years	
	Ceiling - Lay-in	Kitchen - Men	45	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen - Men	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen - Men	45	SF	7	10+ years	
	Floor Drain	Kitchen - Men	1	EA	7	10+ years	
	Lavatory	Kitchen - Men	1	EA	7	10+ years	
	Lighting - Lay-in	Kitchen - Men	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Kitchen - Men	90	SF	7	10+ years	
	Water Closet	Kitchen - Men	1	EA	7	10+ years	
	Accessories	Kitchen - Women	45	SF	7	6-10 years	
	Ceiling - Lay-in	Kitchen - Women	45	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen - Women	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen - Women	45	SF	7	10+ years	
	Floor Drain	Kitchen - Women	1	EA	7	10+ years	
	Lavatory	Kitchen - Women	1	EA	7	10+ years	
	Lighting - Lay-in	Kitchen - Women	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Kitchen - Women	90	SF	7	10+ years	
	Water Closet	Kitchen - Women	1	EA	7	10+ years	
	Accessories	Mail Room	49	SF	7	6-10 years	
	Ceiling - Lay-in	Mail Room	49	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Mail Room	1	EA	7	10+ years	
	Floor - Tile	Mail Room	47	SF	7	10+ years	
	Floor - Tile	Mail Room	2	SF	4	1-2 years	Damaged tile
	Floor Drain	Mail Room	1	EA	7	10+ years	
	Lavatory	Mail Room	1	EA	7	10+ years	
	Lighting - Lay-in	Mail Room	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Mail Room	100	SF	7	10+ years	
	Water Closet	Mail Room	1	EΑ	7	10+ years	
	Accessories	Unisex 2nd Floor Staff	50	SF	7	6-10 years	
	Ceiling - Lay-in	Unisex 2nd Floor Staff	50	SF	7	10+ years	
	Doors - Steel Doors incl hw	Unisex 2nd Floor Staff	1	EA	7	10+ years	
	Floor - Tile	Unisex 2nd Floor Staff	50	SF	7	10+ years	
	Floor Drain	Unisex 2nd Floor Staff	1	EA	7	10+ years	
	Lavatory	Unisex 2nd Floor Staff	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex 2nd Floor Staff	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Unisex 2nd Floor Staff	137	SF	7	10+ years	
	Water Closet	Unisex 2nd Floor Staff	1	ĒΑ	7	10+ years	
			·		-	· ,	

Page : 36 of 47 Campus Name: Moos Assessment Date: 02/26/2024



Catego	ry : Classroom		В	uilding	on	-	
	<del></del>		0	11014		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	m #001 (Pre School)						
	Casework	Basement	30	LF	7	10+ years	
	Ceiling - Lay-in	Basement	1,102	SF	7	10+ years	
	Doors - Side-lite	Basement	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Tile	Basement	1,102	SF	7	10+ years	
	Lighting Lay-in	Basement	17	EA	7	10+ years	
	Marker Board	Basement	24	LF	7	6-10 years	
	Storage/ Closet	Basement	40	SF	7	10+ years	
	Walls - Concrete Block	Basement	822	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	240	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	m #003 (Pre School)						
	Casework	Basement	30	LF	7	10+ years	
	Ceiling - Lay-in	Basement	1,102	SF	7	10+ years	
	Doors - Side-lite	Basement	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Tile	Basement	1,102	SF	7	10+ years	
	Lighting - Lay-in	Basement	15	EA	7	10+ years	
	Lighting - Lay-in	Basement	2	EA	5	1-2 years	Not working
	Marker Board	Basement	24	LF	7	6-10 years	•
	Storage/ Closet	Basement	40	SF	7	10+ years	
	Walls - Concrete Block	Basement	582	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	480	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	m #005 (Pre School)						
	Casework	Basement	30	LF	7	10+ years	
	Ceiling - Lay-in	Basement	1,102	SF	7	10+ years	
	Doors - Side-lite	Basement	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Tile	Basement	1,102	SF	7	10+ years	
	Lighting - Lay-in	Basement	17	EA	7	10+ years	
	Marker Board	Basement	24	LF	7	6-10 years	
	Storage/ Closet	Basement	40	SF	7	10+ years	
	Walls - Concrete Block	Basement	898	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	240	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	m #006 (Office)						
UassiUU	Casework	Basement	8	LF	7	10+ years	
	Ceiling - Lay-in	Basement	994	SF	7	10+ years 10+ years	
	Cenning - Lay-III	Dascinelli	994	JI.	,	10+ years	



Type - Lay-in - Side-lite - Wood Doors inclu hw Tile g - Lay-in Board e/ Closet Concrete Block Plaster/Drywall	Location  Basement Basement Basement Basement Basement Basement Basement Basement	Quantity 108 10 2 1,102 17 24 167	UOM SF SF EA SF EA LF	Rank 4 7 7 7 7	Recommend Replacement 1-2 years 10+ years 10+ years	Comments Warping tiles
- Lay-in - Side-lite - Wood Doors inclu hw Tile g - Lay-in Board e/ Closet Concrete Block Plaster/Drywall	Basement Basement Basement Basement Basement Basement Basement Basement Basement	108 10 2 1,102 17 24 167	SF SF EA SF EA	4 7 7 7	1-2 years 10+ years 10+ years 10+ years	
- Side-lite - Wood Doors inclu hw Tile g - Lay-in Board e/ Closet Concrete Block Plaster/Drywall	Basement Basement Basement Basement Basement Basement Basement Basement	10 2 1,102 17 24 167	SF EA SF EA	7 7 7	10+ years 10+ years 10+ years	Warping tiles
- Wood Doors inclu hw Tile g - Lay-in Board e/ Closet Concrete Block Plaster/Drywall	Basement Basement Basement Basement Basement Basement Basement	2 1,102 17 24 167	EA SF EA	7 7	10+ years 10+ years	
Tile g - Lay-in Board e/ Closet Concrete Block Plaster/Drywall	Basement Basement Basement Basement Basement	1,102 17 24 167	SF EA	7	10+ years	
g - Lay-in Board e/ Closet Concrete Block Plaster/Drywall	Basement Basement Basement Basement	17 24 167	EA			
Board e/ Closet Concrete Block Plaster/Drywall	Basement Basement Basement	24 167		7	40	
Board e/ Closet Concrete Block Plaster/Drywall	Basement Basement	167	IF		10+ years	
e/ Closet Concrete Block Plaster/Drywall	Basement Basement		LI	7	6-10 years	
Concrete Block Plaster/Drywall	Basement		SF	7	10+ years	
Plaster/Drywall		628	SF	7	10+ years	
	Basement	510	SF	7	10+ years	
	Basement	1	ĒΑ	7	10+ years	
(Office)						
ork	2nd Floor	38	LF	7	10+ years	
- Lay-in	2nd Floor	822	SF	7	10+ years	
- Lay-in	2nd Floor	2	SF	4	1-2 years	Stained tile
- Side-lite	2nd Floor	10	SF	7	10+ years	Ctairied the
- Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
Tile	2nd Floor	824	SF	7	10+ years	
g - Lay-in	2nd Floor	13	EA	7	•	
g - Lay-in					10+ years	Not working
g - Lay-in Board	2nd Floor 2nd Floor	1 24	EA LF	5 7	1-2 years	Not working
					6-10 years	
Concrete Block	2nd Floor	742	SF	7	10+ years	
Plaster/Drywall	2nd Floor	240	SF	7	10+ years	
(Regular Classroom)						
ork	2nd Floor	38	LF	7	10+ years	
- Lay-in	2nd Floor	824	SF	7	10+ years	
- Side-lite	2nd Floor	10	SF	7	10+ years	
- Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Tile	2nd Floor	824	SF	7	10+ years	
g - Lay-in	2nd Floor	13	EΑ	7	10+ years	
g - Lay-in	2nd Floor	1	EA	5	1-2 years	Missing cover
Board	2nd Floor	24	LF	7	6-10 years	•
Concrete Block	2nd Floor	502	SF	7	10+ years	
Plaster/Drywall	2nd Floor	470	SF	7	10+ years	
Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
(Kindergarten)						
,	2nd Floor	38	LF	7	10+ years	
ork	2nd Floor			7		
						Stained tile
- Lay-in						
	2nd Floor					
`	k Lay-in Lay-in	k 2nd Floor Lay-in 2nd Floor Lay-in 2nd Floor	k       2nd Floor       38         Lay-in       2nd Floor       812         Lay-in       2nd Floor       12	k       2nd Floor       38 LF         Lay-in       2nd Floor       812 SF         Lay-in       2nd Floor       12 SF	k       2nd Floor       38 LF 7         Lay-in       2nd Floor       812 SF 7         Lay-in       2nd Floor       12 SF 4	k       2nd Floor       38       LF       7       10+ years         Lay-in       2nd Floor       812       SF       7       10+ years         Lay-in       2nd Floor       12       SF       4       1-2 years

Campus Name: Moos Page : 38 of 47 Assessment Date: 02/26/2024



Catego	ry : Classroom		В	Building : Addition				
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	2nd Floor	824	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	11	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	3	EA	5	1-2 years	Missing covers	
	Marker Board	2nd Floor	24	LF	7	6-10 years	3	
	Walls - Concrete Block	2nd Floor	502	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	460	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	20	SF	6	10+ years		
Classroo	om #114 (Kindergarten)							
	Casework	2nd Floor	38	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	824	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	•		
	Floor - Tile	2nd Floor 2nd Floor	824	SF	7	10+ years 10+ years		
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years		
				LF	7			
	Marker Board	2nd Floor	24	SF		6-10 years		
	Walls - Concrete Block	2nd Floor	502		7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	480	SF	7	10+ years		
Classroo	om #115 (Kindergarten)							
	Casework	2nd Floor	38	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	824	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	824	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	742	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	240	SF	7	10+ years		
Classroo	om #116 (Regular Classroom)							
	Casework	1st Floor	38	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	824	SF	7	10+ years		
	Doors - Side-lite	1st Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	824	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	742	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	240	SF	7	10+ years		
Classro	om #210 (Regular Classroom)							
O1000100	Casework	3rd Floor	20	LF	7	101 2000		
	Casework	3ra Floor	38	LF	7	10+ years		

Campus Name: Moos Page : 39 of 47 Assessment Date: 02/26/2024



Catego	ry : Classroom		В	Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Ceiling - Lay-in	3rd Floor	824	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	824	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	742	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	240	SF	7	10+ years		
Classroc	nm #211 (Regular Classroom)							
	Casework	3rd Floor	38	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	809	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	15	SF	4	0-1 year	Water damage	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	water damage	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years		
	Floor - Tile	3rd Floor	824	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years		
	Marker Board	3rd Floor	20	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	742	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	240	SF	7	10+ years		
Classroo	om #212 (Regular Classroom)							
	Casework	3rd Floor	38	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	820	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	4	SF	4	0-1 year	Water damage	
	Doors - Side-lite	3rd Floor	10	SF	7	•	water damage	
	Doors - Side-lite Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years		
	Floor - Tile	3rd Floor	824	SF	7	10+ years		
			_		-	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	502	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	480	SF	7	10+ years		
Classroc	om #213 (Regular Classroom)	. —						
	Casework	3rd Floor	38	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	824	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	824	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	742	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	240	SF	7	10+ years		

Campus Name: Moos Page : 40 of 47 Assessment Date: 02/26/2024



Catego	ategory : Classroom		В	uilding	: Additi		TN Camornia AVENCE, Cincago, IE 00047
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #214 (Regular Classroom)						
	Casework	3rd Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	824	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	824	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	502	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	480	SF	7	10+ years	
Classroo	om #215 (Regular Classroom)						
	Casework	3rd Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	824	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	824	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	742	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	240	SF	7	10+ years	
Classroo	om #216 (Regular Classroom)						
	Casework	3rd Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	816	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	Trator damago
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	824	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	742	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	240	SF	7	10+ years	
Classroo	om #217 (Regular Classroom)						
	Casework	3rd Floor	38	LF	7	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	810	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	14	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	Water damage
	Doors - Side-life Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	
	Floor - Tile	3rd Floor	824	SF	7	10+ years 10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	•	
	Lighting - Lay-III	314 F1001	14	EA	1	10+ years	



Category : Classroom

# Bernhard Moos Elementary School 1711 N California AVENUE, Chicago, IL 60647

**Building: Addition** 

oup	Item - Type	Location				Recommend	
oup	item - Type			LICA	Dank	Danlacamant	Comments
	Mankan Danad		Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	742	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	240	SF	7	10+ years	
tegor	y : Interior		В				
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	1st Floor	2,593	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	114	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	10	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	5	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	2,707	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	106	ĒΑ	7	10+ years	
	Stairs - Terrazzo	1st Floor	60	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,420	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,593	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	84	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	4	1-2 years	Missing drywall
	Doors - Steel Doors incl hw	2nd Floor	8	EA	7	10+ years	mooning dry wan
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	2,707	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	106	EA	7	10+ years	
	Stairs - Terrazzo	2nd Floor	60	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	4,420	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	2,941	SF	7	,	
		3rd Floor		SF	7	10+ years	
	Ceiling - Plaster/Drywall		114		7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	8	EΑ		10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EΑ	7	10+ years	Darler
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	5	1-2 years	Broken
	Floor - Terrazzo	3rd Floor	3,055	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	104	EA	7	10+ years	
	Stairs - Terrazzo	3rd Floor	96	LF	7	10+ years	
	Walls - Concrete Block	3rd Floor	4,650	SF	7	10+ years	
	Ceiling - Lay-in	4th Floor	530	SF	7	10+ years	
	Doors - Steel Doors incl hw	4th Floor	6	EA	7	10+ years	
	Floor - Terrazzo	4th Floor	530	SF	7	10+ years	
	Lighting Lay-in	4th Floor	14	EA	7	10+ years	
	Stairs - Terrazzo	4th Floor	84	LF	7	10+ years	
	Walls - Concrete Block	4th Floor	1,220	SF	7	10+ years	
afety							
•	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	7	6-10 years	

Campus Name: Moos Page: 42 of 47 Assessment Date: 02/26/2024



Categor	ry : Interior	B	uilding	on			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security Cameras	Entire Building	4	EA	7	6-10 years	
	Security Cameras	Entire Building	6	EΑ	7	6-10 years	
	Security Cameras	Entire Building	5	EA	7	6-10 years	
	Security Cameras	Entire Building	9	EA	7	6-10 years	
Stairs							
	Ceiling - Exposed	North	240	SF	7	10+ years	
	Ceiling - Lay-in	North	1,030	SF	7	10+ years	
	Floor - Terrazzo	North	970	SF	7	10+ years	
	Handrails	North	122	LF	7	10+ years	
	Lighting - Lay-in	North	18	EA	7	10+ years	
	Lighting - Wall Mounted	North	4	EA	7	10+ years	
	Stairs - Terrazzo	North	350	LF	7	10+ years	
	Walls - Concrete Block	North	2,720	SF	7	10+ years	
	Ceiling - Exposed	South	240	SF	7	10+ years	
	Ceiling - Lay-in	South	1,638	SF	7	10+ years	
	Ceiling - Lay-in	South	12	SF	4	0-1 year	Water damage
	Floor - Terrazzo	South	1,294	SF	7	10+ years	
	Handrails	South	182	LF	7	10+ years	
	Lighting - Lay-in	South	19	EA	7	10+ years	
	Lighting - Wall Mounted	South	6	EA	7	10+ years	
	Stairs - Terrazzo	South	532	LF	7	10+ years	
	Walls - Structural Glazed Tile	South	2,720	SF	7	10+ years	
√ertical C	Conveyance						
	Elevator - Hydraulic Elevator	Entire Building	1	EA	7	10+ years	



Category : Site	Building : Site

ategory : Site		В	uilding			
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
inage						
	Entire Site	4	EA	7	10+ vears	
	Entire Site	1				Sinking
	Entire Site	18	EA	7		g
3					,	
Fencing - New Standard Ornamental	Entire Site	1,373	LF	7	10+ years	
						0 1:
				-		Cracking
				-		
					•	
Trash Receptacies	Entire Site	3	EA	,	10+ years	
	North East	496	LF	6	6-10 years	
	North East			6		
Surface - Asphalt	North East			4		Cracking and alligatored surface
Surface - Concrete	North East	1,226	SF	4	0-1 year	Significant damage - Cracking and deterioration
Trash Enclosure - Masonry	North Fast	627	SF	7	10+ vears	301011011011
	South East	75	LF	6		
	South East	4,555	SF	4		Cracking
Vehicular Screening	South East	80	LF	7	10+ years	3
ind						
	Northwest	1	FΔ	5	0-1 year	Crack in surface
		2 209				Ordon in Sundoe
Canado i Garda Gariado	140111111111111111111111111111111111111	2,203	0.	,	101 years	
Sidewalks - Perimeter Sidewalks	Entire Site	15,090	SF	7	10+ years	
Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ vears	
2.6 2.2 2.12.9 2.22	2	·		-	,	
	Item - Type Inage Civil/ Drainage - Catch Basin Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole  Fencing - New Standard Ornamental  Pe Benches Landscape - Grass Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Landscape - Hardscape- Pavers Landscape - Mulch Parkway trees Planting Beds/ Area Trash Receptacles  Ot Concrete Curbs Interior Plantings Surface - Asphalt Surface - Concrete  Trash Enclosure - Masonry Vehicular Screening Concrete Curbs Interior Plantings Surface - Asphalt Surface - Cancrete	Item - Type	Item - Type         Location         Quantity           inage         Civil/ Drainage - Catch Basin         Entire Site         4           Civil/ Drainage - Catch Basin         Entire Site         1           Entire Site         18         1           Fencing - New Standard Ornamental         Entire Site         1,373           Be         Benches         Entire Site         2           Landscape - Grass         Entire Site         28,751           Landscape - Hardscape- Concrete         Entire Site         15,364           Landscape - Hardscape- Concrete         Entire Site         400           Landscape - Hardscape- Pavers         Entire Site         400           Landscape - Hardscape- Pavers         Entire Site         400           Landscape - Hardscape- Pavers         Entire Site         48           Planting Beds/ Area         Entire Site         48           Planting Beds/ Area         Entire Site         48           Planting Beds/ Area         Entire Site         3           Ot         Concrete Curbs         North East         496           Interior Plantings         North East         19,422           Surface - Asphalt         North East         19,422           Vehicular S	Location   Quantity   UOM   Inage   Civit/ Drainage - Catch Basin   Entire Site   4 EA   EA   Civit/ Drainage - Catch Basin   Entire Site   1 EA   EA   EA   Civit/ Drainage - Catch Basin   Entire Site   1 EA   EA   EA   EA   EA   EA   EA	Location	Leasting



Categ	ory : Site	Building : Site						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	6-10 years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years		
	Monument - Sign	Entire Site	1	EA	7	10+ years		

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Moos Page: 45 of 47 Assessment Date: 02/26/2024

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary									
				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	2nd Floor	201	201	891	109	54	N	N
Music Room	Music Room	2nd Floor	204	204	1,026	94	36	N	N
Office	Regular Classroom	3rd Floor	300	300	891	109	54	N	N
Other Instructional Use	Regular Classroom	2nd Floor	208	208	891	62	24	N	N
Other Instructional Use	Regular Classroom	3rd Floor	301	301	891	109	54	N	Υ
Other Instructional Use	Regular Classroom	3rd Floor	302	302	891	109	54	N	N
Play Room	Regular Classroom	2nd Floor	209	209	891	62	24	N	N
Regular Classroom	Regular Classroom	1st Floor	100	100	891	109	54	N	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	891	109	54	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	891	78	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	891	62	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	891	78	60	N	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	784	62	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	891	62	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	891	62	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	200	200	891	109	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	891	109	54	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	891	78	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	891	62	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	891	94	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	891	78	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	891	62	24	N	N
Science	Regular Classroom	2nd Floor	203	203	891	62	24	N	N
Science Lab Level 1	Regular Classroom	3rd Floor	303	303	891	62	24	N	N
Vacant	Regular Classroom	3rd Floor	309	309	891	62	24	N	N
Building : Addition				•					
Kindergarten	Regular Classroom	2nd Floor	113	2-16	824	114	12	Υ	Υ
Kindergarten	Regular Classroom	2nd Floor	114	2-04	824	114	12	Υ	Υ
Kindergarten	Regular Classroom	2nd Floor	115	2-15	824	114	12	Υ	Υ
Office	Kindergarten	Basement	006	006A	1,102	152	16	Υ	Υ
Office	Regular Classroom	2nd Floor	110	2-02	824	114	12	Y	N
Pre School	Kindergarten	Basement	001	001A	1,102	152	16	Y	Υ
Pre School	Kindergarten	Basement	003	003A	1,102	152	16	Y	Υ
Pre School	Kindergarten	Basement	005	005A	1,102	152	16	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	116	2-05	824	114	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	112	2-03	824	114	12	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	210	3-02	824	114	12	Y	N



**Classroom Summary** 

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	211	3-16	824	114	12	Y	N
Regular Classroom	Regular Classroom	3rd Floor	212	3-03	824	114	12	Y	N
Regular Classroom	Regular Classroom	3rd Floor	213	3-15	824	114	12	Y	N
Regular Classroom	Regular Classroom	3rd Floor	214	3-04	824	114	12	Y	N
Regular Classroom	Regular Classroom	3rd Floor	215	3-14	824	114	12	Y	N
Regular Classroom	Regular Classroom	3rd Floor	216	3-05	824	114	12	Y	N
Regular Classroom	Regular Classroom	3rd Floor	217	3-13	824	114	12	Υ	N

Campus Name: Moos Page : 47 of 47 Assessment Date: 02/26/2024