

## **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1914	3	167,503
Addition	1964	2	101,977
Modular		1	580
Campus Total			270,060

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	1						
	Exterior Doors - Exterior FRP Door	Door 11 - Southwest	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 11 - Southwest	2	EΑ	7	10+ years	
	Exterior Stairs - Stone	Door 11 - Southwest	15	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 12 - Northwest	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 12 - Northwest	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 12 - Northwest	31	LF	7	10+ years	
	Ramps - Concrete	Door 12 - Northwest	25	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 12 - Northwest	15	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 12.1 - North courtyard	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 12.1 - North courtyard	1	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 12.1 - North courtyard	40	LF	6	10+ years	
	Ramps - Concrete	Door 12.1 - North courtyard	40	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	Door 12.2 - North courtyard	1	EA	6	10+ years	
	Door					•	
	Exterior Doors - Exterior FRP Door	Door 12.3 - North courtyard	1	EA	7	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	Door 12.4 - North	1	EA	6	10+ years	
	Door					•	
	Exterior Doors - Overhead Rolling/ Garage	Door 12.5 - North	1	EΑ	6	10+ years	
	Door					•	
	Exterior Doors - Exterior Steel Door	Door 12.6 - North	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 12.7 - Fire escape 2nd floor	1	EA	7	10+ years	New door and frame
	Exterior Doors - Transom Lite	Door 12.7 - Fire escape 2nd floor	1	EA	7	10+ years	New
		•				,	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Wood Door	Door 12.8 - Fire escape 2nd floor	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 12.9 - Fire escape 3rd floor	1	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	Door 12.9 - Fire escape 3rd floor	1	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 13 - North center	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 13 - North center	3	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 13.5 - Northeast	2	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 13.5 - Northeast	35	LF	7	10+ years	
	Ramps - Concrete	Door 13.5 - Northeast	27	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 14 - Northeast	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 14 - Northeast	1	EA	6	10+ years	
	Exterior Stairs - Stone	Door 14 - Northeast	30	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 15 - East center auditorium	6	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 15 - East center auditorium	3	EA	7	10+ years	
	Exterior Stairs - Stone	Door 15 - East center auditorium	84	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 16 - Southeast	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 16 - Southeast	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 16 - Southeast	36	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 16 - Southeast	10	LF	7	10+ years	
	Ramps - Concrete	Door 16 - Southeast	40	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 16 - Southeast	20	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 17 - Southeast	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 17 - Southeast	1	EΑ	7	10+ years	
	Exterior Stairs - Stone	Door 17 - Southeast	20	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 18 - South center	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 18 - South center	1	EΑ	7	10+ years	
	Exterior Stairs - Stone	Door 18 - South center	10	LF	7	10+ years	
	Entrance Control - Audio and Video	Door 19 - Southwest	1	EΑ	7	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 19 - Southwest	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 19 - Southwest	3	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 19 - Southwest	20	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 19 - Southwest	20	LF	7	10+ years	
	Ramps - Concrete	Door 19 - Southwest	20	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 19 - Southwest	5	LF	6	10+ years	
_Fire Esc	ane						
	Exterior Doors - Exterior Steel Door	North courtyard	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	North courtyard	1	EA	6	6-10 years	No signage from corridor, through boys locker
	Exterior Doors - Transom Lite	North courtyard	1	EA	6	10+ years	DOYS IOCKEI
	Fire Escape	North courtyard	50	LF	6	10+ years	
	Paints	North courtyard	50	LF	5	2-5 years	
_Foundat	ion						
	Foundation - Concrete	Entire Building	925	LF	7	10+ years	
		2 = 29	3_0	<b></b> •	•	121 , 50.0	



Catego	ry : Exterior		B	uilding	: Main		
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Superstructure - Steel with Clay Tile Arch	Entire Building	167,503	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	14	EA	7	6-10 years	
		•				•	
Roof Sys	stem						
•	Access Ladder - Metal	Roof 1	5	EA	7	10+ years	
	Access Ladder - Wood	Roof 1	1	EA	4	1-2 years	Broken rung
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	60	LF	7	10+ years	ŭ
	Liner						
	Coping - Metal	Roof 1	150	LF	7	10+ years	
	Coping - Stone	Roof 1	36	LF	7	10+ years	
	Coping - Terra Cotta	Roof 1	1,450	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 1	648	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 1	1,093	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 1	543	LF	7	10+ years	
	Roof - Metal	Roof 1	200	SF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	47,611	SF	7	10+ years	
	Roof Hatch - Metal	Roof 1	3	EΑ	7	10+ years	
	Roof Hatch - Metal	Roof 1	1	EΑ	5	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	47,811	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 2	40	LF	7	10+ years	Not previously assessed
	Liner						
	Coping - Terra Cotta	Roof 2	185	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 2	32	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 2	185	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 2	2,413	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	2,413	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	1	EA	7	10+ years	
	Coping - Stone	Roof 3	100	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	1,085	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	4,441	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 3	4,441	SF	7	10+ years	
	Coping - Stone	Roof 4	100	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4	17	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 4	100	LF	7	10+ years	
	Roof - PVC Membrane	Roof 4	1,342	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 4	1,342	SF	7	10+ years	
	Concrete Topping	Doof C	•		7	40	Not must develve assessed
	Chimney - Metal Flue	Roof 5	8	LF	7	10+ years	Not previously assessed
	Coping - Stone	Roof 5	10	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 5	25	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Roof 5	1,300	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 5	1,300	SF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 6	12	LF	6	6-10 years	Not previously assessed
	Downspouts - Interior Downspouts	Roof 6	30	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 6	1,338	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 6	1,338	SF	7	10+ years	Corrected roofing
Valls							
	Cheek-Wall - Concrete	Entire Building	10	SF	7	10+ years	
	Cornice - Cast Stone	Entire Building	100	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	43,211	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,948	SF	7	10+ years	Combined quantities
	Exterior Walls - Stone-Cut	Entire Building	2,355	SF	7	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	4,849	SF	7	10+ years	
Vindow	3						
	Guard - Guards perforated	Entire Building	3,375	SF	7	10+ years	
	Lintels - Steel	Entire Building	1,048	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	548	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	15,203	SF	7	10+ years	
atego	ry : Electrical		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merge	ncy System						
-	Emergency Generator- Indoor- Natural Gas - 60 - 100 KW	Basement	1	EA	7	10+ years	
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	167 503	SF	5	2-5 vears	

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
-	Emergency Generator- Indoor- Natural Gas - 60 - 100 KW	Basement	1	EA	7	10+ years	
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	167,503	SF	5	2-5 years	
	Security System - Intrusion Detection	Entire Building	167,503	SF	5	2-5 years	
	Exit Signs - Auditoium	Entire Building	17	EΑ	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	2	EA	5	0-1 year	The backstage left and backstage right egress doors are not provided with Exit Signs.
	Exit Signs - Corridors and Stairs	Entire Building	51	EA	6	6-10 years	•
	Exit Signs - Gym	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Pool	Entire Building	3	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	7,655	SF	7	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	24,581	SF	7	10+ years	



Catana			-		- N/ - '		1744 W Pryor AVENUE, Chicago, IL 60643
Catego	ry : Electrical		В	uilding	: Main		
C	Itama Tuma	Lacation	O	HOM	Dank	Recommend	Comments
Group	Item - Type Emergency A/C Power - Gym	Location Entire Building	Quantity	UOM SF	Rank 7	Replacement 10+ years	Comments
	Emergency A/C Power - Multipurpose	Entire Building Entire Building	5,561 1,258	SF SF	7	10+ years 10+ years	
	Room	Little Ballaling	1,230	OI.	,	10+ years	
	Emergency A/C Power - Pool	Entire Building	2,980	SF	7	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,737	SF	7	10+ years	
	Emergency Battery Packs - Gym	Gym	1	ĒΑ	6	6-10 years	
	, , ,	,				,	
_Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Basement	1	EA	6	6-10 years	Considerable oxidation on the enclosure, especially bottom left, and to a lesser degree, bottom middle; oxidation is very evident but it is observed to be substantially superficial and not presenting a hazard, and it does not interfere with the electrical function of the panel.
	Main Electrical Service - 800 A and 120/208/3PH	Basement	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Basement	1	EA	6	10+ years	
	PA System	Entire Building	167,503	SF	4	0-1 year	Served by Addition. Antiquated system with frequent faults and random electrical disturbances. Unreliable safety features in that a call from a classroom will not always signal the office, presenting a potential life safety issue. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	7	10+ years	
	Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building	18 21	EA EA	6 6	6-10 years 6-10 years	
	Lighting and Power Panels - Above 100 A  Lighting and Power Panels - Above 100 A	Entire Building Entire Building	21	EA	4	1-2 years	Previously documented as
		·					deteriorated and failing/damaged; inaccessible at the time of assessment.
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Horizontal opening in the interior cover plate exposes live conductors presenting a live front condition.
	Main Distribution Panels - Greater than 600	Entire Building	3	EA	7	10+ years	



Catego	ry : Electrical		В	uilding	: Main		Traa W Flyor AVENUE, Gilleago, IE 60045
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	amp Main Distribution Panels - Less than 400	Entire Building	3	EA	7	10+ years	
	amp	Little Ballaling	3	LA	,	10+ years	
	Main Distribution Panels - Less than 400	Entire Building	6	EA	7	10+ years	
	amp	·				•	
Catego	ry : Fire Protection		B	uilding	: Main		
carege	.,		_	· · · · · · · · · · · · · · · · · · ·		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	167,503	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	167,503	SF	7	6-10 years	
Catego	ry : Mechanical		P	uilding	· Main		
Jaiogo	i y i inconanical		-	ananig	· Wani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	-						
7 111 00110	Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	7	10+ years	Location changed for clarification. No
	tons					, , , , , , , , , , , , , , , , , , , ,	CPS Asset Tag present.
	Condensing Unit- Roof Mounted - 5-10	Roof	1	EA	6	6-10 years	CU-1. No CPS Asset Tag present.
	tons						Component of a ductless split syster
	Our description Heit Deaf Manufed Land	Deet		_^	7	40	serving the MDF Room.
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	
	than 5 tons						
Air Hand	lling Systems						
	Air Handling Unit- Built Up- Single Zone w/	Basement - AHU2	1	EA	6	10+ years	AHU-2, serves NE spaces of building.
	Air Tunnel- Dual Temperature Coils - 25001						
	- 35000 cfm	D ( ALUIO		_^		0.40	
	Application 25004 25000 of the	Basement - AHU2	1	EΑ	6	6-10 years	
	Auxiliaries - 25001 - 35000 cfm Reheat Boxes - Reheat Boxes with Hot	Basement - AHU2 Basement - AHU2	6	EA EA	6 6	10+ years 10+ years	
	Water Coil	Basement - Al 102	Ü	LA	O	10+ years	
	Return Duct Work - Indoor- Vertical Shaft	Basement - AHU2	200	LF	6	10+ years	
	and Ducts					, , , , , ,	
	Zone Dampers	Basement - AHU2	27	EA	6	10+ years	
	Air Handling Unit- Built Up- Single Zone w/	Basement - AHU4	1	EA	6	10+ years	AHU-4, serves south spaces of
	Air Tunnel- Dual Temperature Coils -						building.
	Greater than 35000 cfm	Pagement AULIA	4	<b>-</b> ^	6	6 10 40000	
	Air Intake Auxiliaries - Greater than 35000 cfm	Basement - AHU4 Basement - AHU4	1	EA EA	6 6	6-10 years	
	Reheat Boxes - Reheat Boxes with Hot	Basement - AHU4	13	EA	6	10+ years 10+ years	
	Water Coil	Eddoment /1104	13	L/ \	J	ioi youis	



Catego	ry : Mechanical		В	uilding	: Main		, , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement - AHU4	250	LF	6	10+ years	
	Zone Dampers	Basement - AHU4	51	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone- Dual Temperature Coils - 25001 - 35000 cfm	Basement- AHU1	1	EA	6	10+ years	AHU-1, serves west spaces of building.
	Air Intake	Basement- AHU1	1	EA	6	10+ years	
	Auxiliaries - 25001 - 35000 cfm	Basement- AHU1	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement- AHU1	100	LF	6	10+ years	
	Air Handling Unit- Built Up- Single Zone- Dual Temperature Coils - 15001 - 25000 cfm	Basement- AHU3	1	EA	6	10+ years	AHU-3, serves auditorium.
	Air Intake	Basement- AHU3	1	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Basement- AHU3	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement- AHU3	100	LF	6	10+ years	
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating & DX Cooling w/ Remote Mounted Compressor - 11 - 20 tons	Lower Roof	1	EA	7	10+ years	No CPS Asset Tag present.
	Outdoor Return Fans- inline Centrifugal - 10001 - 20000 CFM	Main Roof	1	EA	6	6-10 years	REF-2. Item Type, Rank, Reason and Priority Rep changed to match current observations.
	Outdoor Return Fans- inline Centrifugal - 10001 - 20000 CFM	Main Roof	1	EA	6	10+ years	REF-1A
	Outdoor Return Fans- inline Centrifugal - 10001 - 20000 CFM	Main Roof	1	EA	6	10+ years	REF-3
	Outdoor Return Fans- inline Centrifugal - 10001 - 20000 CFM	Main Roof	1	EA	6	6-10 years	REF-1B. Rank, Reason and Priority Rep adjusted based on current observations.
	Outdoor Return Fans- inline Centrifugal - Greater than 20000 CFM	Main Roof	1	EA	6	10+ years	REF-4.
_Heating_	Devices						
	Wall Heater - Electric	Entire Building	16	EA	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	125	LF	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	14	EA	6	6-10 years	
_Mechani	cal Plumbing						
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	Associated with AHU-1. No CPS Asset Tag present.
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	Associated with AHU-2. No CPS Asset Tag present.
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	Associated with AHU-3.
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	Associated with AHU-4.
	Hydronic Supply and Return - Copper	Entire Building	375	LF	6	10+ years	



Catego	ry : Mechanical		B	uilding	: Main		_
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hydronic Supply and Return - Steel	Entire Building	375	LF	6	10+ years	
_Tempera	ature Control						
	DDC System	Entire Building	167,503	SF	7	10+ years	
	Electric Thermostat	Entire Building	21	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	85	EA	7	6-10 years	
Unit Ver	ntilation						
	Unit Ventilators- Ceiling Mounted- Dual Temperature Coils (Hot/Chilled) Water	1st Floor	1	EA	6	6-10 years	Rank adjusted as leakage noted in previous assessment has been repaired.
	Unit Ventilators- Ceiling Mounted- Dual Temperature Coils (Hot/Chilled) Water	1st Floor	1	EA	6	6-10 years	repaired.
_Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	Quantity changed based on current observations.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	1-2 years	Housing shows signs of minor damage. Not directly accessible at the time of assessment due to lack of safe ladder arrangement.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	6	EA	6	6-10 years	Quantity changed based on current observations.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	3	1-2 years	Units are missing major enclosure parts.
	Roof Mounted Duct Work	Entire Building	440	LF	6	6-10 years	Lineal footage changed based on physical measurement performed at the time of assessment. Two areas
	Roof Mounted Duct Work	Entire Building	24	LF	6	6-10 years	of damage to outer wrap.  Lineal footage confirmed by physical measurement at the time of assessment.
	Roof Mounted Duct Work	Entire Building	80	LF	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	80	LF	6	6-10 years	assessment.



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er -		·			<u>-</u>	
	Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA	6	6-10 years	
Piping							
1 0	Domestic Piping-Hot Water Return Lines	Entire Building	167,503	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	167,503	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	167,503	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	167,503	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	167,503	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	167,503	SF	6	10+ years	
	Sanitary Piping	Entire Building	167,503	SF	6	10+ years	
	Storm Piping	Entire Building	167,503	SF	6	10+ years	
	Vent Piping	Entire Building	167,503	SF	6	10+ years	
Pool Sys	tems						
	Pool Drain Piping	Basement	50	LF	6	10+ years	
	Pool Filtration System including Pump	Basement	1	EA	6	10+ years	
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	6	10+ years	
	Pool Supply and Return Piping	Basement	100	LF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	6	6-10 years	Field irrigation pump.
	Pumps - Sump-Duplex	Basement	1	EA	6	10+ years	No CPS Asset Tag(s) present.
	Pumps - Sump-Duplex	Basement	1	EA	6	10+ years	No CPS Asset Tag(s) present.
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	Located at the bottom of the elevator pit and not accessible at the time of
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	assessment. No CPS Asset Tag present.
Catego	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	1st Floor - 128A	108	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - 128A	1	EA	6	10+ years	
	Floor - Concrete	1st Floor - 128A	108	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - 128A	2	EA	6	10+ years	
	Power Distribution	1st Floor - 128A	6	EA	7	10+ years	
					-	- <b>,</b>	



Category: Room **Building: Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Walls - Concrete Block 1st Floor - 128A 265 SF 10+ vears 6 Ceiling - Plaster/Drywall 325 SF 6 1st Floor - 145 10+ years Doors - Wood Doors inclu hw 1st Floor - 145 FΑ 6 10+ years 1 Floor - Carpet 325 SF 1st Floor - 145 4 1-2 years Carpet ripped and stained Lighting - Pendent/Surface 1st Floor - 145 EΑ 6 10+ years Power Distribution 6 7 1st Floor - 145 EΑ 10+ years Storage/ Closet 1st Floor - 145 50 SF 7 10+ years Walls - Plaster/Drywall SF 1st Floor - 145 418 6 10+ years Work SInk 1st Floor - 145 1 EΑ 7 10+ years Ceiling - Plaster/Drywall SF 1st Floor - 149 325 6 10+ years 1st Floor - 149 Doors - Wood Doors inclu hw EΑ 6 10+ years 1 Floor - Carpet 1st Floor - 149 325 SF 6 6-10 years Lighting - Pendent/Surface EΑ 6 10+ years 1st Floor - 149 4 6 EΑ 7 Power Distribution 1st Floor - 149 10+ years Storage/ Closet 50 SF 7 1st Floor - 149 10+ years Walls - Plaster/Drywall 418 SF 1st Floor - 149 6 2-5 years EΑ 7 Work SInk 1st Floor - 149 1 10+ years AC Unit 1st Floor -Office 132A 1 EΑ 7 6-10 years Not window AC SF Ceiling - Lav-in 1st Floor -Office 132A 197 6 10+ vears Doors - Steel Doors incl hw 1st Floor -Office 132A 1 EΑ 7 10+ years Floor - Wood 1st Floor -Office 132A 197 SF 7 10+ years 1st Floor -Office 132A 10+ years Lighting - Lay-in 4 EΑ 6 6 EΑ 7 Power Distribution 1st Floor -Office 132A 10+ years SF Storage/ Closet 1st Floor -Office 132A 50 7 10+ years Walls - Plaster/Drywall 473 SF 7 1st Floor -Office 132A 10+ years SF Ceiling - Plaster/Drywall 1st Floor- 148A 152 7 10+ years Doors - Wood Doors inclu hw 1st Floor- 148A EΑ 6 10+ years 1 Floor - Carpet 1st Floor- 148A 152 SF 6 6-10 years Lighting - Pendent/Surface 1st Floor- 148A 2 EΑ 6 6-10 years Power Distribution 1st Floor- 148A 8 EΑ 7 6-10 years Walls - Plaster/Drywall 1st Floor- 148A 325 SF 7 10+ vears SF Ceiling - Plaster/Drywall 1st Floor- Office 105 375 7 10+ years Doors - Transom Window SF 7 1st Floor- Office 105 32 10+ years Doors - Wood Doors inclu hw 1st Floor- Office 105 FΑ 7 10+ years 1 375 SF 7 Floor - Tile 1st Floor- Office 105 10+ years Lighting - Pendent/Surface EΑ 7 1st Floor-Office 105 9 6-10 years Power Distribution 1st Floor- Office 105 8 EΑ 7 6-10 years Storage/ Closet 1st Floor- Office 105 SF 18 7 10+ years 1st Floor- Office 105 SF Walls - Plaster/Drywall 483 7 10+ years Ceiling - Plaster/Drywall SF 1st Floor-110 365 6 10+ years SF Doors - Transom Window 1st Floor-110 32 6 10+ years Doors - Wood Doors inclu hw FΑ 6 1st Floor-110 10+ years 1 Floor - Tile 1st Floor-110 365 SF 6 10+ years EΑ Lighting - Pendent/Surface 1st Floor-110 5 10+ years



Catego	ry : Room		Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Power Distribution	1st Floor-110	8	EA	7	10+ years				
	Storage/ Closet	1st Floor-110	58	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor-110	737	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor-110	30	SF	5	1-2 years	Water damaged walls			
	Ceiling - Plaster/Drywall	1st Floor-112 Nurse's Office	300	SF	7	10+ years				
	Doors - Transom Window	1st Floor-112 Nurse's Office	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-112 Nurse's Office	1	EA	6	10+ years				
	Floor - Tile	1st Floor-112 Nurse's Office	250	SF	7	6-10 years				
	Floor - Tile	1st Floor-112 Nurse's Office	50	SF	4	1-2 years	Cracked tiles throughout			
	Lighting - Pendent/Surface	1st Floor-112 Nurse's Office	1	EA	7	10+ years	<b>G</b>			
	Lighting - Pendent/Surface	1st Floor-112 Nurse's Office	2	EA	5	1-2 years	Missing lens			
	Power Distribution	1st Floor-112 Nurse's Office	8	EA	7	10+ years	3 - 1			
	Walls - Plaster/Drywall	1st Floor-112 Nurse's Office	770	SF	7	10+ years				
	Work Slnk	1st Floor-112 Nurse's Office	1	ĒΑ	7	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-122A	120	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-122A	1	ĒΑ	6	10+ years				
	Floor - Carpet	1st Floor-122A	120	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st Floor-122A	4	EA	6	10+ years				
	Power Distribution	1st Floor-122A	8	EΑ	7	10+ years				
	Walls - Plaster/Drywall	1st Floor-122A	250	SF	6	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-134	359	SF	7	10+ years				
	Doors - Transom Window	1st Floor-134	32	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-134	1	EA	6	10+ years				
	Floor - Carpet	1st Floor-134	359	SF	5	2-5 years				
	Lighting - Pendent/Surface	1st Floor-134	6	EA	7	10+ years				
	Power Distribution	1st Floor-134	8	EΑ	7	10+ years				
	Storage/ Closet	1st Floor-134	58	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor-134	967	SF	6	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-142A	120	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-142A	1	EA	7	10+ years				
	Floor - Tile	1st Floor-142A	120	SF	7	10+ years				
	Lighting - Pendent/Surface	1st Floor-142A	4	EA	6	6-10 years				
	Power Distribution	1st Floor-142A	8	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor-142A	250	SF	7	10+ years				
	Work Sink	1st Floor-142A	2	EA	7	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-144 Business Manager's	380	SF	7	10+ years				
		Office				•				
	Doors - Transom Window	1st Floor-144 Business Manager's Office	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-144 Business Manager's Office	1	EA	6	10+ years				
	Floor - Carpet	1st Floor-144 Business Manager's Office	380	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st Floor-144 Business Manager's	6	EA	6	6-10 years				



Category : Room			Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
		Office								
	Power Distribution	1st Floor-144 Business Manager's	14	EA	7	6-10 years				
		Office								
	Walls - Plaster/Drywall	1st Floor-144 Business Manager's	790	SF	6	10+ years				
		Office								
	Ceiling - Plaster/Drywall	1st Floor-146	359	SF	7	10+ years				
	Doors - Side-lite	1st Floor-146	40	SF	7	10+ years				
	Doors - Transom Window	1st Floor-146	48	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-146	1	EA	7	10+ years				
	Floor - Carpet	1st Floor-146	359	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st Floor-146	6	EA	7	6-10 years				
	Power Distribution	1st Floor-146	8	EA	7	6-10 years				
	Storage/ Closet	1st Floor-146	58	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor-146	767	SF	7	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-146A	254	SF	7	10+ years				
	Doors - Transom Window	1st Floor-146A	32	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-146A	1	EA	7	10+ years				
	Floor - Carpet	1st Floor-146A	254	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st Floor-146A	6	EA	7	6-10 years				
	Power Distribution	1st Floor-146A	8	EA	7	6-10 years				
	Storage/ Closet	1st Floor-146A	125	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor-146A	550	SF	6	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-157 Dean's Office Suite	1,130	SF	7	10+ years				
	Doors - Transom Window	1st Floor-157 Dean's Office Suite	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-157 Dean's Office Suite	2	EA	7	10+ years				
	Floor - Wood	1st Floor-157 Dean's Office Suite	1,130	SF	7	10+ years				
	Lighting - Pendent/Surface	1st Floor-157 Dean's Office Suite	20	EA	7	6-10 years				
	Power Distribution	1st Floor-157 Dean's Office Suite	36	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor-157 Dean's Office Suite	770	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor-157 Dean's Office Suite	1,995	SF	6	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-157A Office	316	SF	7	10+ years				
	Doors - Transom Window	1st Floor-157A Office	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-157A Office	1	EA	7	10+ years				
	Floor - Wood	1st Floor-157A Office	316	SF	7	10+ years				
	Lighting - Pendent/Surface	1st Floor-157A Office	4	EA	7	6-10 years				
	Power Distribution	1st Floor-157A Office	8	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor-157A Office	745	SF	7	10+ years				
	Work Sink	1st Floor-157A Office	1	ĒΑ	7	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-Engineer's Office	375	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-Engineer's Office	1	ĒΑ	7	10+ years				
	Floor - Concrete Epoxy/ Painted	1st Floor-Engineer's Office	375	SF	4	1-2 years	Floor finish faded			
	Lighting - Pendent/Surface	1st Floor-Engineer's Office	2	EA	7	6-10 years				
	Power Distribution	1st Floor-Engineer's Office	18	EΑ	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor-Engineer's Office	775	SF	7	10+ years				
		. c. i loci Eliginoci e eliloc	. 7 0	٥.	•	10. 100.0				



Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Ceiling - Plaster/Drywall 202a gym office 246 SF 10+ vears 7 Doors - Wood Doors inclu hw 202a gym office EΑ 7 10+ years 1 Floor - Tile 202a gym office 246 SF 7 10+ years Lighting - Pendent/Surface 202a gym office EΑ 7 4 6-10 years 40 SF Storage/ Closet 202a gym office 7 10+ years SF Walls - Plaster/Drywall 202a gym office 550 6 10+ years Work SInk 202a gym office EΑ 7 6-10 years 1 Ceiling - Plaster/Drywall SF 2nd Floor 610 7 10+ years Doors - Steel Doors incl hw 2nd Floor 1 EΑ 7 10+ years SF Floor - Tile/Sheet 2nd Floor 610 7 10+ years Lighting - Pendent/Surface 2nd Floor 9 EΑ 7 10+ years Power Distribution 2nd Floor 6 EΑ 7 10+ years Storage/ Closet 2nd Floor 200 SF 7 10+ years SF 7 Walls - Plaster/Drywall 2nd Floor 1,200 10+ years Ceiling - Plaster/Drywall SF 300 ROTC Office 430 6 10+ years Doors - Wood Doors inclu hw FΑ 6 300 ROTC Office 1 10+ years Floor - Tile SF 300 ROTC Office 414 6 6-10 years SF Floor - Tile 300 ROTC Office 16 4 1-2 years Damaged tiles Lighting - Pendent/Surface 300 ROTC Office 3 EΑ 6 6-10 years Power Distribution 300 ROTC Office 6 EΑ 7 10+ years Walls - Plaster/Drywall 300 ROTC Office 827 SF 6 10+ years Ceiling - Lay-in SF 7 10+ years 308B 335 Doors - Steel Doors incl hw 308B 1 EΑ 6 10+ years 330 SF Floor - Tile 308B 6 6-10 years Floor - Tile 308B SF 1-2 years Cracked and damaged tiles 5 Lighting - Lav-in 308B 10 EΑ 6 6-10 years 5 Lighting - Lay-in 308B 2 EΑ 1-2 years Missing lens cover Power Distribution 308B 6 EΑ 7 10+ years SF Walls - Plaster/Drywall 308B 760 6 10+ years Ceiling - Plaster/Drywall 318 390 SF 6 10+ years Doors - Steel Doors incl hw 318 EΑ 6 10+ years 1 Floor - Concrete Epoxy/ Painted 318 390 SF 5 10+ years Lighting - Pendent/Surface FΑ 318 6 6-10 years 4 Power Distribution 318 6 FΑ 7 10+ years SF Walls - Plaster/Drywall 318 848 6 10+ years Ceiling - Plaster/Drywall SF 7 Basement 026 150 10+ years SF Basement 026 Doors - Side-lite 12 7 10+ years Doors - Wood Doors inclu hw Basement 026 1 EΑ 7 10+ years Floor - Concrete Epoxy/ Painted Basement 026 150 SF 7 10+ years Lighting - Pendent/Surface Basement 026 2 EΑ 7 6-10 years Power Distribution Basement 026 4 EΑ 7 10+ years 30 SF 7 Storage/ Closet 10+ years Basement 026 Walls - Concrete Block Basement 026 300 SF 7 10+ years SF Ceiling - Exposed Basement next to boiler room 144 7 10+ years



Category : Room			В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
J J .	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Basement next to boiler room	1	EΑ	6	10+ years	
	Floor - Tile	Basement next to boiler room	144	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement next to boiler room	2	EA	7	6-10 years	
	Power Distribution	Basement next to boiler room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement next to boiler room	280	SF	5	1-2 years	Water damage and peeling paint
	·					•	throughout
	Ceiling - Plaster/Drywall	Faculty Lounge 212	1,155	SF	6	10+ years	· ·
	Doors - Wood Doors inclu hw	Faculty Lounge 212	2	EA	6	10+ years	
	Floor - Tile	Faculty Lounge 212	1,155	SF	7	10+ years	
	Lighting - Pendent/Surface	Faculty Lounge 212	16	EA	7	10+ years	
	Storage/ Closet	Faculty Lounge 212	70	SF	7	10+ years	
	Walls - Plaster/Drywall	Faculty Lounge 212	1,704	SF	6	10+ years	
	Work SInk	Faculty Lounge 212	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym Office 206A	260	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Office 206A	1	EA	6	10+ years	
	Floor - Terrazzo	Gym Office 206A	260	SF	7	10+ years	
	Lighting - Pendent/Surface	Gym Office 206A	1	EA	7	6-10 years	
	Power Distribution	Gym Office 206A	8	EA	7	10+ vears	
	Walls - Plaster/Drywall	Gym Office 206A	362	SF	7	10+ years	
	Ceiling - Lay-in	Office 226	382	SF	7	10+ years	
	Doors - Steel Doors incl hw	Office 226	1	EA	6	10+ years	
	Floor - Tile	Office 226	382	SF	7	10+ years	
	Lighting - Lay-in	Office 226	8	EA	7	10+ years	
	Power Distribution	Office 226	10	EA	7	10+ years	
	Storage/ Closet	Office 226	130	SF	7	10+ years	
	Walls - Plaster/Drywall	Office 226	838	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 220	504	SF	6	10+ years	
	Doors - Steel Doors incl hw	Room 220	1	EΑ	6	10+ years	
	Doors - Transom Window	Room 220	12	SF	6	10+ years	
	Floor - Tile	Room 220	504	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 220	9	EA	6	10+ years	
	Power Distribution	Room 220	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 220	1,080	SF	6	10+ years	
_Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	290	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	9,635	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	9	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	6,553	SF	7	10+ years	
	Floor - Tile	1st Floor	882	SF	7	10+ years	
	Floor - Wood	1st Floor	2,200	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	9	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Wall Mounted	1st Floor	12	EA	7	6-10 years			
	Main Floor Seating	1st Floor	515	EA	7	10+ years			
	Sound System	1st Floor	1	EA	7	10+ years			
	Stage	1st Floor	2,200	SF	7	10+ years			
	Stage Curtain	1st Floor	16	EA	7	10+ years			
	Stage Lift	1st Floor	1	EA	7	10+ years			
	Stage Lighting System	1st Floor	1	EA	7	10+ years			
	Stage-Stairs - Tile	1st Floor	12	LF	7	10+ years			
	Stairs - Asphalt	1st Floor	150	LF	7	10+ years			
	Stairs - Terrazzo	1st Floor	50	LF	7	10+ years			
	Walls - Concrete Block	1st Floor	6,610	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	6,610	SF	6	10+ years			
Gymnasi	ia Balcony Seating	Gym 202/204	129	EA	7	10+ years			
		Gym 202/204 Gym 202/204		SF		•			
	Ceiling - Plaster/Drywall		5,561		7	10+ years			
	Doors - Wood Doors inclu hw	Gym 202/204	2	EA	6	6-10 years			
	Floor - Wood	Gym 202/204	5,561	SF	7	10+ years			
	Lighting - Pendent/Surface	Gym 202/204	17	EA	7	6-10 years			
	Scoreboards	Gym 202/204	1	EA	7	6-10 years			
	Storage/ Closet	Gym 202/204	310	SF	7	10+ years			
	Walls - Plaster/Drywall	Gym 202/204	3,275	SF	7	10+ years			
	Walls - Structural Glazed Tile	Gym 202/204	2,193	SF	7	10+ years			
Locker/S	Shower Room								
	Accessories	1st Floor	602	SF	7	6-10 years			
	Benches, ped mounted	1st Floor	16	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	502	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	100	SF	6	1-2 years	Peeling paint from ceiling		
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	6	10+ years	. comig paint nom coming		
	Floor - Concrete Epoxy/ Painted	1st Floor	602	SF	7	10+ years			
	Floor Drain	1st Floor	5	EA	7	6-10 years			
	Hand Dryer	1st Floor	2	EA	7	6-10 years			
	Lavatory	1st Floor	2	EA	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	7	EA	6	6-10 years			
	Partitions	1st Floor	2	EA	7	10+ years			
		1st Floor	10	EA	7	-			
	Showers Student Leekers One Tier					10+ years			
	Student Lockers - One Tier	1st Floor 1st Floor	4	EA EA	7	10+ years			
	Student Lockers - Two Tier		78		7	10+ years			
	Walls - Concrete Block	1st Floor	1,205	SF	7	10+ years			
	Water Closet	1st Floor	2	EA	7	10+ years			
	Accessories	1st Floor-Men's Locker Room, in Natatorium	550	SF	7	10+ years			
	Benches, ped mounted	1st Floor-Men's Locker Room, in	16	LF	7	10+ years			



**Building: Main** Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Natatorium SF Ceiling - Plaster/Drywall 1st Floor-Men's Locker Room, in 550 7 10+ years Natatorium 2 Doors - Steel Doors incl hw 1st Floor-Men's Locker Room, in EΑ 6 10+ years Natatorium SF Floor - Concrete Epoxy/ Painted 1st Floor-Men's Locker Room, in 550 7 10+ years Natatorium Floor Drain 1st Floor-Men's Locker Room, in 5 EΑ 7 10+ years Natatorium Hand Dryer 1st Floor-Men's Locker Room, in 2 FΑ 7 6-10 years Natatorium Lavatory 1st Floor-Men's Locker Room, in 2 EΑ 7 10+ years Natatorium Lighting - Pendent/Surface 1st Floor-Men's Locker Room, in 8 EΑ 7 10+ years Natatorium 1st Floor-Men's Locker Room, in FΑ 10+ years **Partitions** 1 7 Natatorium Showers 1st Floor-Men's Locker Room, in 9 FΑ 7 10+ years Natatorium Student Lockers - One Tier 1st Floor-Men's Locker Room, in 4 EΑ 7 10+ years Natatorium Student Lockers - Two Tier 1st Floor-Men's Locker Room, in 42 EΑ 7 10+ years Natatorium Urinals 1st Floor-Men's Locker Room, in FΑ 7 10+ years Natatorium Walls - Concrete Block 1st Floor-Men's Locker Room, in 1.040 SF 7 10+ years Natatorium Water Closet 1st Floor-Men's Locker Room, in EΑ 1 7 10+ years Natatorium Accessories 2nd Floor 2,150 SF 7 6-10 years LF Benches, ped mounted 2nd Floor 75 7 10+ years SF Ceiling - Plaster/Drywall 2nd Floor 2.150 7 10+ years Doors - Wood Doors inclu hw FΑ 2nd Floor 3 6 10+ years Floor - Terrazzo 2nd Floor 2.100 SF 7 10+ years SF Floor - Terrazzo 2nd Floor 50 4 1-2 years Cracking 5 EΑ 7 Floor Drain 2nd Floor 10+ years 2 Hand Dryer 2nd Floor EΑ 7 6-10 years 7 Lavatory 2nd Floor 4 EΑ 10+ years Lighting - Pendent/Surface 2nd Floor 13 EΑ 7 6-10 years Lighting - Pendent/Surface 2nd Floor 1 EΑ 5 1-2 years Not working **Partitions** 2nd Floor 2 EΑ 7 10+ years 2nd Floor FΑ 7 Showers 8 10+ years Student Lockers - Two Tier 2nd Floor 152 EΑ 10+ years SF Walls - Concrete Block 2nd Floor 3,725 7 10+ years



Category : Room		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	2,150	SF	7	6-10 years	
	Benches, ped mounted	2nd Floor	75	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor	50	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,100	SF	7	10+ years	
	Floor Drain	2nd Floor	5	EA	7	10+ years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Showers	2nd Floor	8	EA	7	10+ years	
	Student Lockers - Two Tier	2nd Floor	154	EA	7	10+ years	
	Urinals	2nd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	3,725	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	1st Floor - Room 151	1,258	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Room 151	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Room 151	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Room 151	1,258	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Room 151	20	EA	7	6-10 years	
	Walls - Metal Panel	1st Floor - Room 151	773	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Room 151	773	SF	7	10+ years	
MDF IDI	E						
_	Doors - Wood Doors inclu hw	1st Floor-124B MDF	1	EA	7	10+ years	
	Finishes	1st Floor-124B MDF	300	SF	7	6-10 years	
	Other Cooling Unit	1st Floor-124B MDF	1	EA	7	6-10 years	Ductless split system.
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	8	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	205	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	114	SF	7	10+ years	
	Storage Room	1st Floor	580	SF	7	10+ years	
	Storage Room	1st Floor	850	SF	7	10+ years	
	Storage Room	1st Floor	66	SF	7	10+ years	
	Vaults	1st Floor	400	SF	7	10+ years	
	Janitor's Closet	2nd Floor	20	SF	5	2-5 years	
	Mechanical/ Service Rooms	2nd Floor	45	SF	7	10+ years	
	Storage Room	2nd Floor	610	SF	5	2-5 years	
	Janitor's Closet	3rd Floor	20	SF	5	2-5 years	
	Janitor's Closet	3rd Floor	195	SF	5	2-5 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	3rd Floor	360	SF	5	2-5 years	
	Air Tunnel	Basement	3,000	SF	5	10+ years	
	Crawl Space - Unfinished	Basement	5,000	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	2,500	SF	7	10+ years	
	Storage Room	Basement	500	SF	7	10+ years	
<u>'001 &amp; N</u>	Natatorium						
	Accessories	1st Floor	2,980	SF	7	6-10 years	
	Bleachers Seating/Plank Seating	1st Floor	6	EA	7	10+ years	
	Ceiling - Lay-in	1st Floor	2,972	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Broken and damaged tiles
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	2,980	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	25	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Pool Basin	1st Floor	1,675	SF	7	10+ years	
	Pool Deck	1st Floor	1,305	SF	7	10+ years	
	Pool Deck Drains	1st Floor	12	EΑ	7	10+ years	
	Storage/ Closet	1st Floor	85	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,210	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,210	SF	7	10+ years	
Prep Ro	om						
TCP IXO	Casework	309A inside science lab 309	20	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	309A inside science lab 309	155	SF	7	10+ years	
	Doors - Transom Window	309A inside science lab 309	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	309A inside science lab 309	1	EA	7	10+ years	
	Floor - Tile	309A inside science lab 309	155	SF	7	6-10 years	
	Lighting - Pendent/Surface	309A inside science lab 309	3	EA	7	6-10 years	
			350	SF	7		
	Walls - Plaster/Drywall	309A inside science lab 309				10+ years	
	Work Sink	309A inside science lab 309	1	EA	7	6-10 years	
	Casework	336 serves 355/357	40	LF	6	10+ years	
	Ceiling - Plaster/Drywall	336 serves 355/357	327	SF	6	10+ years	
	Doors - Transom Window	336 serves 355/357	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	336 serves 355/357	2	EA	6	10+ years	
	Floor - Tile/Sheet	336 serves 355/357	327	SF	5	10+ years	
	Lighting - Pendent/Surface	336 serves 355/357	2	EA	7	10+ years	
	Walls - Plaster/Drywall	336 serves 355/357	925	SF	6	10+ years	
	Work Sink	336 serves 355/357	1	EA	7	6-10 years	



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor - Restroom inside 145	152	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Restroom inside 145	152	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Restroom inside 145	1	EA	6	10+ years	
	Floor - Terrazzo	1st Floor - Restroom inside 145	152	SF	7	10+ years	
	Floor Drain	1st Floor - Restroom inside 145	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Restroom inside 145	2	EA	7	6-10 years	
	Partitions	1st Floor - Restroom inside 145	1	EA	7	10+ years	
	Showers	1st Floor - Restroom inside 145	1	EA	4	1-2 years	Appears not to be used
	Urinals	1st Floor - Restroom inside 145	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Restroom inside 145	193	SF	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - Restroom inside 145	80	SF	7	10+ years	
	Water Closet	1st Floor - Restroom inside 145	1	ĒΑ	7	10+ years	
	Accessories	1st Floor - Restroom inside 146A	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Restroom inside 146A	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Restroom inside 146A	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor - Restroom inside 146A	56	SF	7	10+ years	
	Lavatory	1st Floor - Restroom inside 146A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Restroom inside 146A	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Restroom inside 146A	120	SF	7	10+ years	
	Water Closet	1st Floor - Restroom inside 146A	120	EA	7	10+ years	
	Accessories	1st Floor - Restroom inside 149	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Restroom inside 149	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Restroom inside 149	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Restroom inside 149	52	SF	7	10+ years	
	Floor Drain	1st Floor - Restroom inside 149	1	EA	7	•	
		1st Floor - Restroom inside 149	1	EA	7	10+ years 6-10 years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor - Restroom inside 149	89	SF	6	2-5 years	
	Water Closet						
		1st Floor - Restroom inside 149	1	EA SF	7	10+ years	
	Accessories	1st Floor-112 Nurse's Office	50	SF	7	6-10 years	
	Osilian Disaton/Duranell	Restroom	50	0.5	7	40	
	Ceiling - Plaster/Drywall	1st Floor-112 Nurse's Office	50	SF	7	10+ years	
	B W IB : I I	Restroom	4	_ ^	•	40	
	Doors - Wood Doors inclu hw	1st Floor-112 Nurse's Office	1	EA	6	10+ years	
		Restroom		0.5	_	4.0	
	Floor - Terrazzo	1st Floor-112 Nurse's Office	50	SF	7	10+ years	
		Restroom			_		
	Floor Drain	1st Floor-112 Nurse's Office	1	EA	7	10+ years	
		Restroom			_		
	Lavatory	1st Floor-112 Nurse's Office	1	EA	7	10+ years	
		Restroom					
	Lighting - Pendent/Surface	1st Floor-112 Nurse's Office	1	EA	7	6-10 years	
		Restroom					
	Partitions	1st Floor-112 Nurse's Office	1	EA	7	10+ years	
		Restroom					



Category: Room **Building: Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments SF Walls - Masonry 1st Floor-112 Nurse's Office 90 10+ years 7 Restroom Walls - Plaster/Drywall 1st Floor-112 Nurse's Office 88 SF 7 10+ years Restroom Walls - Plaster/Drywall 1st Floor-112 Nurse's Office 2 SF 5 1-2 years Water damaged walls Restroom Water Closet 1st Floor-112 Nurse's Office 1 EΑ 7 10+ years Restroom Accessories 1st Floor-Boy's Restroom 235 SF 7 6-10 years SF Ceiling - Plaster/Drywall 1st Floor-Boy's Restroom 235 10+ years 6 Doors - Wood Doors inclu hw 1st Floor-Boy's Restroom EΑ 6 10+ years 1 Floor - Terrazzo 1st Floor-Boy's Restroom 235 SF 6 10+ years Floor Drain 1st Floor-Boy's Restroom EΑ 7 1 10+ years 7 Hand Dryer 1st Floor-Boy's Restroom 1 EΑ 6-10 years 1st Floor-Boy's Restroom 3 EΑ Lavatory 6 10+ years Lighting - Pendent/Surface 1st Floor-Boy's Restroom 4 FΑ 6 6-10 years 2 **Partitions** 1st Floor-Boy's Restroom EΑ 7 10+ years Urinals 1st Floor-Boy's Restroom 4 EΑ 6 10+ years SF Walls - Concrete Block 1st Floor-Boy's Restroom 110 6 10+ years SF Walls - Plaster/Drywall 1st Floor-Boy's Restroom 138 6 10+ years Water Closet 1st Floor-Boy's Restroom 2 EΑ 6 10+ years SF 7 Accessories 1st Floor-Girls' Restroom 235 6-10 years SF 1st Floor-Girls' Restroom 7 Ceiling - Plaster/Drywall 235 10+ years 7 Doors - Wood Doors inclu hw 1st Floor-Girls' Restroom FΑ 10+ years 1 Floor - Terrazzo 235 SF 7 1st Floor-Girls' Restroom 10+ years Floor Drain 1st Floor-Girls' Restroom 1 FΑ 7 10+ years Hand Dryer 1st Floor-Girls' Restroom 1 EΑ 7 6-10 years 2 EΑ 7 Lavatory 1st Floor-Girls' Restroom 10+ years Lighting - Pendent/Surface 1st Floor-Girls' Restroom 4 EΑ 7 6-10 years **Partitions** 1st Floor-Girls' Restroom 5 EΑ 7 10+ years Walls - Concrete Block 1st Floor-Girls' Restroom 80 SF 7 10+ years SF Walls - Plaster/Drywall 1st Floor-Girls' Restroom 218 7 10+ years FΑ 7 Water Closet 1st Floor-Girls' Restroom 5 10+ years Accessories 1st Floor-Men's Auditorium 130 SF 7 6-10 years Restroom SF Ceiling - Plaster/Drywall 1st Floor-Men's Auditorium 130 7 10+ years Restroom Doors - Wood Doors inclu hw 1st Floor-Men's Auditorium 1 EΑ 7 10+ years Restroom SF Floor - Terrazzo 1st Floor-Men's Auditorium 130 7 10+ years Restroom Floor Drain 1st Floor-Men's Auditorium FΑ 7 10+ years Restroom Lavatory 1st Floor-Men's Auditorium 3 EΑ 7 10+ years



**Building: Main** Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Restroom EΑ Lighting - Pendent/Surface 1st Floor-Men's Auditorium 3 7 6-10 years Restroom **Partitions** 1st Floor-Men's Auditorium EΑ 7 10+ years Restroom Urinals 1st Floor-Men's Auditorium 1 EΑ 7 10+ years Restroom Walls - Concrete Block 1st Floor-Men's Auditorium 84 SF 7 10+ years Restroom SF Walls - Masonry 1st Floor-Men's Auditorium 152 7 10+ years Restroom Walls - Plaster/Drywall 1st Floor-Men's Auditorium 152 SF 7 10+ years Restroom 1st Floor-Men's Auditorium Water Closet 1 EΑ 7 10+ years Restroom 1st Floor-Unisex Natatorium SF Accessories 202 7 6-10 years Restroom **Benches** 1st Floor-Unisex Natatorium 4 LF 7 10+ years Restroom Ceiling - Plaster/Drywall 1st Floor-Unisex Natatorium 202 SF 7 10+ years Restroom 2 Doors - Steel Doors incl hw 1st Floor-Unisex Natatorium EΑ 7 10+ years Restroom SF Floor - Concrete 1st Floor-Unisex Natatorium 202 7 10+ years Restroom Floor Drain 1st Floor-Unisex Natatorium 2 FΑ 7 10+ years Restroom 1st Floor-Unisex Natatorium EΑ Lavatory 1 7 10+ years Restroom Lighting - Pendent/Surface 1st Floor-Unisex Natatorium 2 EΑ 7 10+ years Restroom Showers 1st Floor-Unisex Natatorium FΑ 7 1 10+ years Restroom Student Lockers - One Tier 1st Floor-Unisex Natatorium FΑ 7 10+ years Restroom Walls - Concrete Block 1st Floor-Unisex Natatorium 416 SF 7 10+ years Restroom Water Closet 1st Floor-Unisex Natatorium 1 EΑ 7 10+ years Restroom SF Accessories 1st Floor-Women's Auditorium 130 7 6-10 years Restroom 1st Floor-Women's Auditorium SF Ceiling - Plaster/Drywall 130 7 10+ years Restroom Doors - Wood Doors inclu hw 1st Floor-Women's Auditorium EΑ 10+ years



Catego	ry : Room		Building : Main							
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor Townson	Restroom	400	0.5	7	40				
	Floor - Terrazzo	1st Floor-Women's Auditorium	130	SF	7	10+ years				
	Floor Drain	Restroom 1st Floor-Women's Auditorium	1	EA	7	10+ years				
	1 1001 Drain	Restroom	'	LA	,	10+ years				
	Lavatory	1st Floor-Women's Auditorium	3	EA	7	10+ years				
		Restroom	· ·		•	.o. you.o				
	Lighting - Pendent/Surface	1st Floor-Women's Auditorium	3	EA	7	6-10 years				
		Restroom				•				
	Partitions	1st Floor-Women's Auditorium	2	EA	7	10+ years				
		Restroom								
	Walls - Concrete Block	1st Floor-Women's Auditorium	83	SF	7	10+ years				
	W. II. O	Restroom		0.5		4.0				
	Walls - Concrete Block	1st Floor-Women's Auditorium	1	SF	4	1-2 years	Missing mortar			
	Walla Macanny	Restroom 1st Floor-Women's Auditorium	152	SF	5	1 2 voore	Holes and dirty			
	Walls - Masonry	Restroom	132	SF	5	1-2 years	Holes and diffy			
	Walls - Plaster/Drywall	1st Floor-Women's Auditorium	152	SF	7	10+ years				
	Walls Tlastel/Drywall	Restroom	102	O.	,	TOT years				
	Water Closet	1st Floor-Women's Auditorium	2	EA	7	10+ years				
		Restroom				, , , , , , , , , , , , , , , , , , , ,				
	Accessories	1st Floor-Women's Restroom 152A	122	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom 152A	122	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom 152A	1	EA	7	10+ years				
	Floor - Terrazzo	1st Floor-Women's Restroom 152A	122	SF	7	10+ years				
	Floor Drain	1st Floor-Women's Restroom 152A	1	EA	7	10+ years				
	Hand Dryer	1st Floor-Women's Restroom 152A	1	EA	7	6-10 years				
	Lavatory	1st Floor-Women's Restroom 152A	1	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor-Women's Restroom 152A	3	EA	7	6-10 years				
	Partitions	1st Floor-Women's Restroom 152A	1	EA	7	10+ years				
	Walls - Metal Panel	1st Floor-Women's Restroom 152A	84	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor-Women's Restroom 152A	154	SF	7	10+ years				
	Water Closet	1st Floor-Women's Restroom 152A	104	EA	7	10+ years				
	Accessories	2nd Boys' across 212	359	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Boys' across 212 2nd Boys' across 212	339	SF	6	10+ years				
				SF			Matar dama a			
	Ceiling - Plaster/Drywall	2nd Boys' across 212	20		5	1-2 years	Water damage			
	Doors - Wood Doors inclu hw	2nd Boys' across 212	1	EA	6	10+ years				
	Floor - Terrazzo	2nd Boys' across 212	359	SF	7	10+ years				
	Floor Drain	2nd Boys' across 212	1	EA	7	10+ years				
	Hand Dryer	2nd Boys' across 212	1	EA	7	6-10 years				
	Lavatory	2nd Boys' across 212	2	EA	6	10+ years				
	Lighting - Pendent/Surface	2nd Boys' across 212	3	EA	7	6-10 years				
	Partitions	2nd Boys' across 212	3	EA	7	10+ years				
	Urinals	2nd Boys' across 212	4	EA	6	10+ years				



roup	Item - Type Walls - Concrete Block	Location				Recommend	
roup	Walls - Concrete Block	Location	• •••				
			Quantity	UOM	Rank	Replacement	Comments
	Malla Diagtar/Dmm.call	2nd Boys' across 212	541	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Boys' across 212	292	SF	6	10+ years	
	Water Closet	2nd Boys' across 212	3	EA	6	6-10 years	
	Accessories	2nd Floor	50	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Concrete	2nd Floor	50	SF	7	2-5 years	
	Lavatory	2nd Floor	1	ĒΑ	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	1	EΑ	6	2-5 years	
	Urinals	2nd Floor	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	6	2-5 years	
	Water Closet	2nd Floor	1	EA	7	6-10 years	
	Accessories	2nd Floor Men's Faculty 210A	217	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Men's Faculty 210A  2nd Floor Men's Faculty 210A	217	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Men's Faculty 210A  2nd Floor Men's Faculty 210A	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor Men's Faculty 210A 2nd Floor Men's Faculty 210A	200	SF	6	•	
				SF	4	10+ years	Large areals in floor
	Floor - Terrazzo	2nd Floor Men's Faculty 210A	17			1-2 years	Large crack in floor
	Floor Drain	2nd Floor Men's Faculty 210A	1	EΑ	7	10+ years	
	Lavatory	2nd Floor Men's Faculty 210A	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Men's Faculty 210A	3	EA	7	6-10 years	
	Partitions (Partitions	2nd Floor Men's Faculty 210A	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Men's Faculty 210A	445	SF	6	10+ years	
	Water Closet	2nd Floor Men's Faculty 210A	1	EA	6	10+ years	
	Accessories	2nd Girls' adjacent 207	357	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Girls' adjacent 207	357	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Girls' adjacent 207	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Girls' adjacent 207	337	SF	7	10+ years	
	Floor - Terrazzo	2nd Girls' adjacent 207	20	SF	4	1-2 years	Cracks in floor
	Floor Drain	2nd Girls' adjacent 207	1	EA	7	10+ years	
	Hand Dryer	2nd Girls' adjacent 207	1	EA	7	6-10 years	
	Lavatory	2nd Girls' adjacent 207	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Girls' adjacent 207	3	EA	7	6-10 years	
	Partitions	2nd Girls' adjacent 207	6	EA	7	10+ years	
	Walls - Concrete Block	2nd Girls' adjacent 207	234	SF	7	10+ years	
	Walls - Metal Panel	2nd Girls' adjacent 207	210	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Girls' adjacent 207	244	SF	7	10+ years	
	Water Closet	2nd Girls' adjacent 207	6	EA	7	6-10 years	
	Accessories	2nd adjacent 201 Women	244	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	2nd adjacent 201 Women	244	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd adjacent 201 Women	1	EΑ	7	10+ years	
	Floor - Terrazzo	2nd adjacent 201 Women	244	SF	7	10+ years	
	Floor Drain	2nd adjacent 201 Women	1	EA	7	10+ years	
	Hand Dryer	2nd adjacent 201 Women	1	EA	7	6-10 years	
	Lavatory	2nd adjacent 201 Women	2	EA	6	6-10 years	



Category : Room			Building : Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	2nd adjacent 201 Women	3	EA	7	6-10 years		
	Partitions	2nd adjacent 201 Women	2	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd adjacent 201 Women	843	SF	7	10+ years		
	Water Closet	2nd adjacent 201 Women	2	EA	6	6-10 years		
	Accessories	2ndFloor - Restroom inside Gym office	56	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2ndFloor - Restroom inside Gym office	56	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2ndFloor - Restroom inside Gym office	1	EA	7	10+ years		
	Floor - Concrete	2ndFloor - Restroom inside Gym office	30	SF	7	10+ years		
	Floor - Terrazzo	2ndFloor - Restroom inside Gym office	26	SF	7	10+ years		
	Floor Drain	2ndFloor - Restroom inside Gym office	1	EA	7	10+ years		
	Lavatory	2ndFloor - Restroom inside Gym office	1	EA	7	10+ years		
	Lighting - Pendent/Surface	2ndFloor - Restroom inside Gym office	2	EA	7	6-10 years		
	Urinals	2ndFloor - Restroom inside Gym office	1	EA	7	10+ years		
	Walls - Concrete Block	2ndFloor - Restroom inside Gym office	120	SF	7	10+ years		
	Water Closet	2ndFloor - Restroom inside Gym office	1	EA	7	10+ years		
	Accessories	3rd 354A adjacent 301 Women	244	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd 354A adjacent 301 Women	244	SF	6	10+ years		
	Doors - Transom Window	3rd 354A adjacent 301 Women	6	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd 354A adjacent 301 Women	1	EA	6	10+ years		
	Floor - Terrazzo	3rd 354A adjacent 301 Women	244	SF	6	10+ years		
	Floor Drain	3rd 354A adjacent 301 Women	1	EA	7	10+ years		
	Hand Dryer	3rd 354A adjacent 301 Women	1	EA	7	6-10 years		
	Lavatory	3rd 354A adjacent 301 Women	2	EA	6	10+ years		
	Lighting - Pendent/Surface	3rd 354A adjacent 301 Women	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	3rd 354A adjacent 301 Women	2	EA	5	1-2 years	Did not work	
	Partitions	3rd 354A adjacent 301 Women	2	EA	7	10+ years		
	Walls - Concrete Block	3rd 354A adjacent 301 Women	74	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd 354A adjacent 301 Women	429	SF	6	10+ years		
	Water Closet	3rd 354A adjacent 301 Women	2	ĒΑ	6	10+ years		
	Accessories	3rd across 310	359	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd across 310	359	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd across 310	1	EA	6	10+ years		
	Floor - Terrazzo	3rd across 310	359	SF	6	10+ years		
						-		



**Building: Main** Category : Room

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	3rd across 310	1	EA	7	10+ years	
	Hand Dryer	3rd across 310	1	EA	7	6-10 years	
	Lavatory	3rd across 310	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd across 310	3	EA	7	6-10 years	
	Partitions	3rd across 310	3	EA	7	10+ years	
	Urinals	3rd across 310	4	EΑ	7	10+ years	
	Walls - Concrete Block	3rd across 310	541	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd across 310	292	SF	6	10+ years	
	Water Closet	3rd across 310	3	EA	7	6-10 years	
	Accessories	3rd adjacent 307	357	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd adjacent 307	357	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd adjacent 307	1	EΑ	6	10+ years	
	Floor - Terrazzo	3rd adjacent 307	357	SF	6	10+ years	
	Floor Drain	3rd adjacent 307	1	EA	7	10+ years	
	Hand Dryer	3rd adjacent 307	1	EΑ	7	6-10 years	
	Lavatory	3rd adjacent 307	2	EA	7	10+ years	
	Lavatory	3rd adjacent 307	1	EΑ	5	1-2 years	Running water
	Lighting - Pendent/Surface	3rd adjacent 307	3	EA	6	10+ years	-
	Partitions	3rd adjacent 307	6	EA	7	10+ years	
	Walls - Concrete Block	3rd adjacent 307	234	SF	6	10+ years	
	Walls - Metal Panel	3rd adjacent 307	210	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd adjacent 307	444	SF	6	10+ years	
	Water Closet	3rd adjacent 307	6	EA	7	6-10 years	
	Accessories	Basement office	60	SF	5	1-2 years	In overall poor shape
	Ceiling - Plaster/Drywall	Basement office	60	SF	5	1-2 years	Water damaged
	Doors - Wood Doors inclu hw	Basement office	1	EA	6	10+ years	· ·
	Floor - Tile	Basement office	60	SF	6	6-10 years	
	Lavatory	Basement office	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement office	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement office	160	SF	5	1-2 years	Water damaged walls
	Water Closet	Basement office	1	EA	4	0-1 year	In overall poor shape
	Accessories	Restroom in 202a	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in 202a	40	SF	5	0-1 year	Hole
	Doors - Side-lite	Restroom in 202a	1	SF	6	6-10 years	
	Floor - Terrazzo	Restroom in 202a	40	SF	6	10+ years	
	Lighting - Lay-in	Restroom in 202a	1	ĒΑ	6	6-10 years	
	Walls - Concrete Block	Restroom in 202a	50	SF	6	10+ years	
	Walls - Plaster/Drywall	Restroom in 202a	50	SF	6	10+ years	
	Water Closet	Restroom in 202a	1	ĒΑ	6	6-10 years	

Category : Classroom **Building: Main** 

		Recommend
Group Item - Type	Location	Quantity UOM Rank Replacement Comments
Classroom #026 (Store Room)		



Catego	Category : Classroom		В	uilding	: Main		1744 W I Tyol AVENUE, Officago, IE 00040
J -				3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement	1,970	SF	6	10+ years	Peeling paint throughout.
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Concrete	Basement	1,970	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	48	EA	7	6-10 years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Storage/ Closet	Basement	50	SF	7	10+ years	
	Walls - Masonry	Basement	1,800	SF	7	10+ years	
	Work Sink	Basement	1	ĒΑ	5	1-2 years	Water running
Classro	om #101 (Band Room)						
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,022	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	1,022	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
				LF	7	,	
	Marker Board Risers	1st Floor	24 3	LF	7	6-10 years	
		1st Floor		SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,256	SF	,	10+ years	
Classroo	om #102 (Weight)						
	Ceiling - Plaster/Drywall	1st Floor	2,214	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	1st Floor	2,214	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	30	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,662	SF	7	10+ years	
_Classroo	om #103 (Music Room)						
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	978	SF	7	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	978	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,428	SF	7	10+ years	
	vvalis - Flastel/Diywali	151 F1001	1,420	Si	,	10+ years	
_Classroo	om #106 (Band Room)						
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Splined	1st Floor	2,385	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	1,153	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor - Terrazzo	1st Floor	40	SF	4	1-2 years	Cracks in floor
	Floor - Tile	1st Floor	1,192	SF	7	10+ years	
	Instrument Storage Casework	1st Floor	75	LF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	58	EA	7	10+ years	
	Risers	1st Floor	2	LF	7	10+ years	
	Sound Panels	1st Floor	2	EA	7	10+ years	
	Storage/ Closet	1st Floor	220	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,758	SF	7	10+ years	
Classroo	m #120 (Faculty Lounge)						
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	980	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	980	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	78	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,775	SF	7	10+ years	
	Work Sink	1st Floor	1,773	EA	7	10+ years	
_Classroo	m #122 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	660	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile	1st Floor	660	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,424	SF	7	10+ years	
_Classroo	m #126 (Other Instructional Use)						
	Ceiling - Plaster/Drywall	1st Floor	2,060	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2,000	EA	7	10+ years	
	Floor - Carpet	1st Floor	880	SF	7	6-10 years	
	Floor - Tile	1st Floor	1,180	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	42	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	170	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	740	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,755	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	m #128 auto shop (Store Room)						



atego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	1st Floor	810	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	5	2-5 years	
	Walls - Concrete Block	1st Floor	1,815	SF	7	10+ years	
	Walls - Masonry	1st Floor	100	SF	7	10+ years	
	Work Sink	1st Floor	2	ĒΑ	7	10+ years	
lassroo	om #130 (Computer Lab)						
	Ceiling - Plaster/Drywall	1st Floor	868	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	868	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,405	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,403	SF	4	1-2 years	Wall damaged
	walls - Flastel/Drywall	151 11001	2	Si	4	1-2 years	vvali damaged
lassroo	om #132 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	1,176	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Sport Flooring	1st Floor	100	SF	5	2-5 years	
	Floor - Wood	1st Floor	1,076	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	19	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet	1st Floor	32	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,922	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
lassroo	om #153 (Regular Classroom)						
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,112	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,092	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Broken and damaged tiles
	Lighting - Pendent/Surface	1st Floor	24	EA	6	6-10 years	Diokon and damaged thes
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,083	SF	7	10+ years	
laseroo	m #155 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	581	SF	7	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
			10		4	/ VE(II)	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	581	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,145	SF	7	10+ years	
Classroc	om #201 (Regular Classroom)						
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,022	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	. <u>-</u> 1	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,022	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	10+ years	
	Marker Board	2nd Floor 2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,421	SF	7	•	
	walls - Flastel/Drywall	2110 11001	1,421	SF	,	10+ years	
lassroc	om #203 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	728	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	628	SF	6	6-10 years	
	Floor - Tile	2nd Floor	100	SF	4	1-2 years	Cracks through
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,206	SF	7	10+ years	
lassroc	om #207 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	787	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	777	SF	6	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Broken and damaged tile
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	Broken and damaged the
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,371	SF	6	10+ years	
lacerca	om #208 (Regular Classroom)						
uassiuc	, ,	2nd Floor	40	LF		10	
	Casework	2nd Floor	48		6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	663	SF	6	6-10 years	



Category : Classroom			Building : Main				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Chipped tiles
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
Classroo	m #209 (Office)						
	Ceiling - Lay-in	2nd Floor	523	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	400	SF	6	6-10 years	
	Floor - Tile	2nd Floor	123	SF	4	1-2 years	Cracks throughout tile
	Lighting - Pendent/Surface	2nd Floor	8	ĒΑ	7	6-10 years	3
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	354	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	735	SF	6	10+ years	
Classroo	m #210 (Regular Classroom)						
0.000100	Casework	2nd Floor	4	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	665	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	665	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	,	
	Walls - Plaster/Drywall	2nd Floor	1,266	SF	6	6-10 years 10+ years	
Classras	m #211 (Regular Classroom)						
Classion		0	00			40	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	702	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	702	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	354	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,043	SF	6	10+ years	
Classroo	m #222 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	662	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	662	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
						<b>,</b>	



Catego	ory : Classroom		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,023	SF	6	10+ years	
Classro	om #224 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	599	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	599	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,192	SF	6	10+ years	
Classro	om #226 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	605	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	· <u>-</u> 1	EA	7	10+ years	
	Floor - Wood	2nd Floor	605	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	5	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	10+ years	
Classro	om #228 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	876	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	876	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,508	SF	6	10+ years	
Classro	om #230 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	511	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	511	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,186	SF	6	10+ years	
Classro	om #251 (Regular Classroom)						
	Casework	2nd Floor	20	LF	6	10+ years	
	535511	2.13 . 155.	20		Ü	, 54.0	



Category : Classroom		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	1,116	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,116	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	22	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	63	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,459	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #253 (Regular Classroom)						
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	6-10 years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Cracked and damaged tiles
					•	·	throughout
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	5	1-2 years	Not working
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,394	SF	6	10+ years	
Classroo	om #255 (Regular Classroom)						
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	599	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	499	SF	7	6-10 years	
	Floor - Tile	2nd Floor	100	SF	4	1-2 years	Damaged and cracked tiles
	Lighting - Pendent/Surface	2nd Floor	10	ĒΑ	7	6-10 years	g
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,192	SF	6	10+ years	
Classroo	om #256 (Regular Classroom)						
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	599	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	539	SF	6	6-10 years	
	Floor - Tile	2nd Floor	60	SF	4	1-2 years	Cracks throughout
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	Oracks unoughout
	Marker Board	2nd Floor		LF	6	6-10 years	
			22	1 -		6 10 40000	



Category : Classroom		Building : Main					
3						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Walls - Plaster/Drywall	2nd Floor	1,192	SF	6	10+ years	
Classroo	m #257 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	599	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	599	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	10	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,192	SF	6	10+ years	
Classroo	m #259 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	919	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	769	SF	7	10+ years	
	Floor - Tile	2nd Floor	150	SF	4	1-2 years	Damaged flooring
	Lighting - Pendent/Surface	2nd Floor	15	ĒΑ	7	6-10 years	gg
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,415	SF	6	10+ years	
Classroo	m #301 (Regular Classroom)						
	Casework	3rd Floor	21	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,035	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	1,035	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	24	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,265	SF	6	10+ years	
Classroo	m #302 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	11	ĒΑ	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,270	SF	6	10+ years	
Classroo	m #303 (Regular Classroom)						
	,	3rd Floor		LF	6	10+ years	



Catego	Category : Classroom		Building : Main				, , , , , , , , , , , , , , , , , , , ,
_				_		Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	728	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	500	SF	6	6-10 years	
	Floor - Tile	3rd Floor	228	SF	4	1-2 years	Cracked and damaged
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,206	SF	6	10+ years	
Classroo	om #304 (Special Program)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	461	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	461	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EΑ	6	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	107	SF	5	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
Classroo	om #306 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	841	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	841	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	24	EA	6	10+ years	
	Storage/ Closet	3rd Floor	150	SF	5	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	978	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #307 (Regular Classroom)						
Ciassiul	Casework	3rd Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	806	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	7	10+ years	
		3rd Floor	•	SF	7		
	Floor - Tile		806			6-10 years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall	3rd Floor 3rd Floor	14 1,260	EA SF	7 6	10+ years	
	walls - Plaster/Drywall	310 11001	1,200	SF	О	10+ years	
Classroo	om #308A (Regular Classroom)						
	Casework	3rd Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	673	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	573	SF	6	6-10 years	



Category : Classroom			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd Floor	100	SF	4	1-2 years	Chipped and damaged
	Lighting - Lay-in	3rd Floor	10	EA	7	10+ years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	
Classroo	om #308B (Regular Classroom)						
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	669	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	4	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	643	SF	6	6-10 years	
	Floor - Tile	3rd Floor	30	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	Cracked and damaged tile
	Lighting - Lay-in	3rd Floor	2	EA	7	10+ years	
			15	LF	7		
	Marker Board	3rd Floor			-	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #309 (Science Lab Level 1)						
	Casework	3rd Floor	71	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	950	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile	3rd Floor	950	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	10+ years	Couldn't find right switch
	Science Lab Shower	3rd Floor	1	EΑ	7	6-10 years	o a a a a a a a a a a a a a a a a a a a
	Storage/ Closet	3rd Floor	65	SF	5	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	1,074	SF	6	10+ years	
	Work Sink	3rd Floor	5	EA	7	10+ years	
Classroo	om #310 (Regular Classroom)						
CidosiUL	Ceiling - Lay-in	3rd Floor	504	SF	6	10+ years	
	Doors - Transom Window			SF SF			
		3rd Floor	6		6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	504	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	_16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	790	SF	6	10+ years	
Classroo	om #312 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	500	SF	6	10+ years	
	3 - 3	<del></del>		=	-	· ,	



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	494	SF	6	6-10 years	
	Floor - Tile	3rd Floor	6	SF	4	1-2 years	Broken and damaged at door
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	790	SF	6	10+ years	
Classroo	om #320 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	479	SF	6	10+ years	
	Chalk Board	3rd Floor	33	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	479	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	ĒΑ	6	10+ years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,023	SF	6	10+ years	
Classro	om #322 (Regular Classroom)						
Olassio	Casework	2nd Floor	6	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	650	SF	6	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Boots inclu tiw	2nd Floor	650	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	10+ years	
	Marker Board	2nd Floor	7	LF	6		
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,153	SF	7	6-10 years 10+ years	
	•					Ţ	
Classroo	om #324 (Counseling Room)						
	Ceiling - Lay-in	3rd Floor	335	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	335	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	6	10+ years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	785	SF	6	10+ years	
Classroo	om #326 (Science)						
	Casework	3rd Floor	93	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,127	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		•
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Eye Wash Station	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	1,127	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	10+ years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,580	SF	6	10+ years	
	Work Sink	3rd Floor	5	EA	7	10+ years	
Classroo	om #328 (Regular Classroom)						
	Casework	Mechanical Room	9	LF	6	10+ years	
	Ceiling - Lay-in	Mechanical Room	880	SF	6	10+ years	
	Floor - Tile	Mechanical Room	760	SF	6	10+ years	
	Floor - Tile	Mechanical Room	120	SF	4	1-2 years	Cracks and chips
	Lighting - Lay-in	Mechanical Room	21	EA	6	10+ years	Oracks and criips
	Walls - Plaster/Drywall	Mechanical Room	1,040	SF	7	10+ years	
	walls - Flastel/Drywall	Wechanical Room	1,040	SF	,	10+ years	
Classroo	om #330 (Regular Classroom)						
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	369	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	205	SF	6	10+ years	
	Floor - Tile	3rd Floor	524	SF	6	10+ years	
	Floor - Tile	3rd Floor	50	SF	4	1-2 years	Cracking and damaged tiles
	Lighting - Lay-in	3rd Floor	9	EΑ	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	954	SF	6	10+ years	
Classroo	om #351 (Art Room)						
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1.116	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	1,106	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Missing minor damage
	Lighting - Pendent/Surface	3rd Floor	22	EA	6	10+ years	Wildsing Millor damage
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	363	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor 3rd Floor	1,459	SF SF	6		
			•			10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #355 (Science)						
	Casework	3rd Floor	80	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		1744 W T Tyol AVENUE, Officago, IE 0004.
Julogo	, y . C. (a.c.) C. (iii		_	uag	····	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile	3rd Floor	1,200	SF	6	10+ years	
	Gas Line	3rd Floor	12	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	23	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	Drain
	Storage/ Closet	3rd Floor	88	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,235	SF	6	10+ years	
	Work Sink	3rd Floor	5	EA	7	10+ years	
lassroo	m #357 (Laboratory/Shop)						
	Casework	3rd Floor	138	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,200	SF	7	10+ years	
	Gas Line	3rd Floor	6	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	24	EA	7	10+ years	
	Science Lab Elements	3rd Floor	96	SF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	6-10 years	
	Science Lab Fulle Flood Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Storage/ Closet	3rd Floor	90	SF	5	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,662	SF	6	10+ years	
	Work Sink	3rd Floor	5	EA	7	10+ years	
assroo	m #359 (Regular Classroom)						
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	863	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	663	SF	6	10+ years	
	Floor - Tile	3rd Floor	200	SF	4	1-2 years	Cracks and chipped tile
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years	Cracic and ompped mo
	Walls - Plaster/Drywall	3rd Floor	1,367	SF	7	10+ years	
atego	ry : Interior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor	Coiling Lovin	1 ot Floor	0.447	C.E.		10	
	Ceiling - Lay-in	1st Floor	8,117	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,328	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	27	EΑ	7	10+ years	



Category : Interior **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Wood Doors include hw 1st Floor 6 EΑ 10+ vears 7 Drinking Fountains - Single Fountain 2 EΑ 7 1st Floor 10+ years Floor - Terrazzo 1st Floor 4.000 SF 7 10+ years Floor - Tile/Sheet SF 7 1st Floor 5,445 10+ years 7 Lighting - Lay-in 1st Floor 60 EΑ 6-10 years Lighting - Pendent/Surface 7 1st Floor 8 EΑ 6-10 years Stairs - Terrazzo 36 LF 7 1st Floor 10+ years Student Lockers - One Tier 1st Floor 630 EΑ 7 10+ years Walls - Masonry 1st Floor 325 SF 7 10+ years SF Walls - Plaster/Drywall 1st Floor 16.519 7 10+ years SF Walls - Structural Glazed Tile 1st Floor 400 7 10+ years Ceiling - Plaster/Drywall 1st Floor-Auditorium Lobby 813 SF 7 10+ years EΑ 7 Doors - Wood Doors include hw 1st Floor-Auditorium Lobby 10 10+ years 7 Drinking Fountains - Single Fountain 1st Floor-Auditorium Lobby 2 EΑ 10+ years Floor - Terrazzo SF 7 1st Floor-Auditorium Lobby 678 10+ years Floor - Tile Quarry SF 7 1st Floor-Auditorium Lobby 135 10+ years EΑ 7 Lighting - Chandelier, Incandescent 1st Floor-Auditorium Lobby 5 6-10 years Lighting - Pendent/Surface 1st Floor-Auditorium Lobby 3 EΑ 7 6-10 years Walls - Plaster/Drywall SF 1st Floor-Auditorium Lobby 998 7 10+ vears Walls - Structural Glazed Tile SF 1st Floor-Auditorium Lobby 775 7 10+ years Walls - Tile Ceramic/ Porcelain 1st Floor-Auditorium Lobby 998 SF 7 10+ years 2nd Floor SF 10+ years Ceiling - Lay-in 6,516 6 SF Ceiling - Lay-in 2nd Floor 3 4 1-2 years Does not fit. Doors - Transom Window SF 2nd Floor 30 6 10+ years Doors - Wood Doors include hw 3 EΑ 6 10+ years 2nd Floor Drinking Fountains - Single Fountain 2nd Floor 4 EΑ 7 10+ years Floor - Terrazzo SF 2nd Floor 2,135 7 10+ years Floor - Tile/Sheet 2nd Floor 4,384 SF 5 10+ years Lighting - Lay-in 2nd Floor 74 EΑ 6 6-10 years Student Lockers - One Tier 2nd Floor 187 EΑ 6 10+ years Student Lockers - One Tier 2nd Floor 2 EΑ 4 1-2 years Damaged locker Walls - Plaster/Drywall 2nd Floor 7.230 SF 6 10+ years SF Ceiling - Lay-in 3rd Floor 6.519 6 10+ years Doors - Transom Window 36 SF 6 10+ years 3rd Floor Doors - Wood Doors include hw 3rd Floor 4 EΑ 6 10+ years 2 EΑ 7 Drinking Fountains - Single Fountain 3rd Floor 10+ years 2 Drinking Fountains - Single Water Cooler 3rd Floor EΑ 7 10+ years Floor - Terrazzo SF 3rd Floor 2,555 6 10+ years SF Floor - Tile/Sheet 3rd Floor 3.964 7 6-10 years Lighting - Lav-in 3rd Floor 74 EΑ 7 10+ vears Student Lockers - One Tier 3rd Floor 538 EΑ 6 10+ years SF 6 Walls - Plaster/Drywall 3rd Floor 7.776 10+ years Walls - Plaster/Drywall 3rd Floor 300 SF 6 10+ years SF 7 Ceiling - Exposed **Basement** 122 10+ years



Catego	Category : Interior		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Concrete Epoxy/ Painted	Basement	106	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	2	EA	7	10+ years		
	Walls - Concrete Block	Basement	641	SF	7	10+ years		
Cofot.								
Safety	Comera Viewing Station	4 of Eleca	2	ΕΛ	7	0.40		
	Camera Viewing Station	1st Floor	2	EΑ	7	6-10 years		
	Metal Detector	1st Floor	4	EA	7	6-10 years		
	Security Cameras	1st Floor	15	EA	7	6-10 years		
Stairs								
	Ceiling - Lay-in	#1 Stair	420	SF	6	10+ years		
	Ceiling - Plaster/Drywall	#1 Stair	144	SF	6	10+ years		
	Floor - Terrazzo	#1 Stair	288	SF	6	10+ years		
	Handrails	#1 Stair	142	LF	7	10+ years		
	Lighting - Pendent/Surface	#1 Stair	4	EΑ	6	10+ years		
	Lighting - Wall Mounted	#1 Stair	1	EA	6	10+ years		
	Stairs - Terrazzo	#1 Stair	56	LF	6	10+ years		
	Walls - Plaster/Drywall	#1 Stair	955	SF	6	10+ years		
	Ceiling - Lay-in	#2 Stair	335	SF	6	10+ years		
	Ceiling - Plaster/Drywall	#2 Stair	134	SF	6	10+ years		
	Floor - Terrazzo	#2 Stair	286	SF	6	10+ years		
	Handrails	#2 Stair	124	LF	5	10+ years		
	Lighting - Pendent/Surface	#2 Stair	5	EΑ	6	10+ years		
	Lighting - Wall Mounted	#2 Stair	1	EA	6	10+ years		
	Stairs - Terrazzo	#2 Stair	56	LF	6	10+ years		
	Walls - Plaster/Drywall	#2 Stair	840	SF	6	10+ years		
	Ceiling - Plaster/Drywall	#3 Stair	340	SF	5	1-2 years	Water damage	
	Ceiling - Splined	#3 Stair	30	SF	7	10+ years	ŭ	
	Ceiling - Splined	#3 Stair	107	SF	6	6-10 years		
	Floor - Tile	#3 Stair	322	SF	7	10+ years		
	Handrails	#3 Stair	106	LF	5	10+ years		
	Lighting - Pendent/Surface	#3 Stair	1	EA	6	10+ years		
	Lighting - Wall Mounted	#3 Stair	1	EA	5	1-2 years	Missing cover	
	Stairs - Rubber	#3 Stair	56	LF	6	6-10 years	g cover	
	Walls - Plaster/Drywall	#3 Stair	954	SF	6	10+ years		
	Ceiling - Lay-in	#4 Stair	420	SF	6	10+ years		
	Ceiling - Plaster/Drywall	#4 Stair	134	SF	6	10+ years		
	Floor - Terrazzo	#4 Stair	288	SF	6	10+ years		
	Handrails	#4 Stair	142	LF	5	10+ years		
	Lighting - Pendent/Surface	#4 Stair	4	EA	6	10+ years		
	Lighting - Wall Mounted	#4 Stair	1	EA	6	10+ years		
	Stairs - Terrazzo	#4 Stair	56	LF	6	10+ years		
	Walls - Plaster/Drywall	#4 Stair	955	SF	6	10+ years		
	Ceiling - Lay-in	#4 Stair	420	SF	6	10+ years		
	Oching - Lay-III	#J Stall	420	SI-	U	TOT YEARS		



Catego	Category : Interior			uilding	: Main		·
_	•			Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	#5 Stair	144	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	#5 Stair	288	SF	5	10+ years	
	Handrails	#5 Stair	142	LF	5	10+ years	
	Lighting - Pendent/Surface	#5 Stair	4	EA	6	10+ years	
	Lighting - Wall Mounted	#5 Stair	1	EA	7	10+ years	
	Stairs - Asphalt	#5 Stair	56	LF	6	10+ years	
	Walls - Plaster/Drywall	#5 Stair	955	SF	6	10+ years	
	Ceiling - Lay-in	#6 Stair	210	SF	6	10+ years	
	Ceiling - Plaster/Drywall	#6 Stair	275	SF	6	10+ years	
	Floor - Terrazzo	#6 Stair	232	SF	6	10+ years	
	Floor - Tile	#6 Stair	175	SF	7	10+ years	
	Handrails	#6 Stair	128	LF	7	10+ years	
	Lighting - Pendent/Surface	#6 Stair	5	EΑ	7	10+ years	
	Lighting - Wall Mounted	#6 Stair	1	EΑ	6	10+ years	
	Stairs - Terrazzo	#6 Stair	60	LF	6	10+ years	
	Walls - Plaster/Drywall	#6 Stair	955	SF	6	10+ years	
	Ceiling - Lay-in	#7 Stair	420	SF	6	10+ years	
	Ceiling - Plaster/Drywall	#7 Stair	144	SF	6	10+ years	
	Floor - Terrazzo	#7 Stair	288	SF	6	10+ years	
	Handrails	#7 Stair	142	LF	5	10+ years	
	Lighting - Pendent/Surface	#7 Stair	4	EΑ	6	10+ years	
	Lighting - Wall Mounted	#7 Stair	1	EΑ	6	10+ years	
	Stairs - Terrazzo	#7 Stair	56	LF	6	10+ years	
	Walls - Plaster/Drywall	#7 Stair	955	SF	6	10+ years	
Vertical	Conveyance						
<u>voi nodi</u>	Elevator - Hydraulic Elevator	Main building	1	EA	7	10+ years	
	Wheelchair Lift - Platform Lift	Main building	1	EA	7	10+ years	
	Whosionali Elit i lationii Elit	Main ballang	·	L/\	,	ioi youis	



Category : Exterior			В	uilding			
	<del></del>		0	11014		Recommend	•
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ell Equ	ipment						
	Cell Equipment - Antenna	South courtyard of addition	1	EA	7	6-10 years	Inaccessible.
	Cell Equipment - Cabinets	South courtyard of addition	1	EA	7	6-10 years	Inaccessible.
htrono							
ntrance	Entrance Control - Audio and Video	Door 1 - North	1	EA	7	6-10 years	
	Exterior Doors - Side lite	Door 1 - North	4	EA	7	10+ years	
	Exterior Doors - Store Front	Door 1 - North	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 1 - North	2	EA	7	10+ years	
	Power Door Operator and Controls	Door 1 - North	1	EA	7	6-10 years	
	Exterior Doors - Store Front	Door 10 - Northwest	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 10 - Northwest	1	EA	7	10+ years	
	Exterior Doors - Store Front	Door 2 - North west	2	EA	7	10+ years	
	Exterior Doors - Store Front  Exterior Doors - Transom Lite	Door 2 - North west	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 2 - North west	17	LF	7		
			17	EA	7	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	Door 2.9 - Service court	'	EA	,	10+ years	
	Exterior Doors - Exterior Steel Door	Door 3 - Service court	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 3 - Service court	1	EA	6	10+ years	Not previously assessed
	Exterior Doors - Exterior FRP Door	Door 3.2 - Yard Storage	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 3.2 - Yard Storage	1	EA	7	10+ years	Not previously assessed
	Exterior Doors - Exterior FRP Door	Door 3.5 - service court	1	EA	6	10+ years	
	Exterior Doors - Store Front	Door 4 - Service court	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 4 - Service court	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 4 - Service court	8	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 5 - Southeast	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 5 - Southeast	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 5.2 - Chiller	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 6 - South center	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 7 - Southwest	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 7 - Southwest	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 7 - Southwest	6	LF	6	10+ years	
	Exterior Doors - Side lite	Door 8 - West courtyard	4	ĒΑ	7	10+ years	
	Exterior Doors - Store Front	Door 8 - West courtyard	2	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 9 - West courtyard	2	EA	6	10+ years	
	Exterior Doors - Side lite	Door 9 - West courtyard	2	EΑ	7	10+ years	
	Exterior Doors - Transom Lite	Door 9 - West courtyard	1	ĒΑ	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 9.1 - Elevator Machine	1	EA	7	10+ years	
oundati	ion						
Junual	Foundation - Concrete	Entire Building	1,540	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	101,977	SF	7	10+ years	



Category : Exterior			В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
1:10							
_Lighting_	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	7	6-10 years	
	Exterior Lighting - Parapet of Roof Mounted  Exterior Lighting - Wall Mounted	Entire Building	51	EA	7	6-10 years	
	Exterior Eighting - Wall Woulded	Little Ballaling	31	LA	,	0-10 years	
Roof Sys	stem						
	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Coping - Stone	Roof 1	594	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	12	LF	7	10+ years	Moved from roof 5
	Downspouts - Interior Downspouts	Roof 1	123	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 1	594	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 1	17,921	SF	6	6-10 years	
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years	
	Roof Structure - Concrete	Roof 1	17,921	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	´ 1	EA	7	10+ years	
	Coping - Stone	Roof 2	445	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 2	72	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 2	445	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 2	10,880	SF	7	6-10 years	Corrected quantity
	Roof - Modified Bitumen	Roof 2	1,000	SF	4	0-1 year	Ponding, soft spots
	Roof Hatch - Metal	Roof 2	1	EA	7	10+ years	
	Roof Structure - Concrete	Roof 2	11,880	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	´ 1	EA	7	10+ years	Not previously assessed
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 3	62	LF	6	10+ years	,
	Liner					·	
	Chimney - Metal Flue	Roof 3	16	LF	7	10+ years	
	Coping - Stone	Roof 3	908	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 3	180	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 3	227	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 3	681	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	20,190	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	1,000	SF	5	0-1 year	Ponding
	Roof Hatch - Metal	Roof 3	1	ĒΑ	7	10+ years	3
	Roof Structure - Concrete	Roof 3	21,190	SF	7	10+ years	
	Access Ladder - Metal	Roof 4	1	ĒΑ	7	10+ years	Not previously assessed
	Coping - Stone	Roof 4	168	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4	36	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 4	168	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 4	3,434	SF	6	10+ years	
	Roof Structure - Concrete	Roof 4	3,434	SF	7	10+ years	
_Walls							
	Canopy - Concrete/ Stucco	Entire Building	58	SF	7	10+ years	



0-1	F.d'				: Additi		1744 W FIYOI AVENUE, CIlicago, IL 60643
Catego	ry : Exterior		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	43,491	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	4	1-2 years	Protruding brick, open joints
	Exterior Walls - Concrete Block	Entire Building	595	SF	7	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	10,470	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	803	SF	7	10+ years	
Windows	3						
	Curtain wall - Glazed Double Pane	Entire Building	1,914	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	24	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	5,916	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	2,088	SF	7	10+ years	
	Lintels - Concrete	Entire Building	1,211	LF	7	10+ years	
	Lintels - Steel	Entire Building	60	LF	7	10+ years	
	Windows - Decorative	Entire Building	32	SF	6	10+ years	
	Windows - Louver	Entire Building	650	SF	7	10+ years	

Category : Electrical Building : Addition

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	101,977	SF	5	2-5 years	
	Security System - Intrusion Detection	Entire Building	101,977	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	24	EA	7	6-10 years	
	Exit Signs - Gym	Entire Building	8	EA	6	6-10 years	Quantity changed to match current observations. There are four in each of the two gyms. Exit Signs upgraded since last assessment as no signs have faded lettering. Rank, Reason and Priority Rep changed based on current observations.
	Exit Signs - Lunchroom	Entire Building	2	EA	7	6-10 years	There are two means of egress in the lunchroom, and both have appropriately placed Exit Signs that are legible and properly illuminated. Quantity changed to match current observations.
	Exit Signs - Multipurpose Room	Entire Building	2	EA	7	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,198	SF	7	10+ years	
	Emergency A/C Power - Gym	Entire Building	13,345	SF	7	10+ years	Mens and Womens gyms.
	Emergency A/C Power - Lunchrooms	Entire Building	6,876	SF	7	10+ years	•
	Emergency A/C Power - Students Toilets	Entire Building	1,502	SF	7	10+ years	



Catego	ry : Electrical		В	uilding	: Additi	on .	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Basement	1	EA	7	10+ years	
	PA System	Entire Building	101,977	SF	4	0-1 year	Also serves Main. Antiquated system with frequent faults and random electrical disturbances. Unreliable safety features in that a call from a classroom will not always signal the office, presenting a potential life safety issue. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel. Open fuse receptacles expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	ĒĀ	6	6-10 years	Quantity and Rank changed to match current observations. Panels are of various ages but none of them present a live-front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Located in the IDF Room inside the library. Open breaker slots expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	0-1 year	Unable to access the interior of the panel but per review with the Building Engineer, cover panels are missing exposing live conductors and presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Location changed for clarification.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Legalieri oriarigoa for olarinoation.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	Panel 1PA. Panel door is fixed in a
	Main Distribution Lanets - 400 - 000 amp	Little Ballating	'		U	o io years	i and it is a and add is inca ill a



Catego	ry : Electrical		B	uilding	: Additio	on	
	<b>,</b> 1 = 100 10		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cloup	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	locked position. Rank, Reason and Priority Rep are estimated. Panel 2S1. Panel is missing an interior cover piece which exposes live terminals presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Panel 1PB. Panel is missing some interior cover pieces which expose live terminals presenting a live front condition.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	4	0-1 year	Missing interior cover plate exposes live terminals presenting a live front condition.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	condition.
Catego	ry : Fire Protection		В	uilding	: Additi	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarr		Entire Duilding	4	ГΛ		0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	101,977	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	101,977	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Additi		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Condi							
	Chemical Pot Feeder	Entire Building	2	EA	6	10+ years	Serves boiler system and chiller system.
	Chiller-Water Cooled- Cetrifugal - 201-300 tons	Entire Building	1	EA	6	6-10 years	CH-2. Chillers have undergone repairs since last assessment and are functioning as intended. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Chiller-Water Cooled- Cetrifugal - 201-300 tons	Entire Building	1	EA	6	6-10 years	CH-1. Chillers have undergone repairs since last assessment and artunctioning as intended. Rank,



Category : Mechanical		В	uilding	: Additi	on		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments  Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Cooling Tower - Open Cell	Entire Building	1	EA	6	10+ years	por review with Ballating Engineer.
	Cooling Tower - Open Cell	Entire Building	1	EA	6	10+ years	
	Glycol Feed	Entire Building	1	EA	6	10+ years	Serves boiler system and chiller system. Glycol feed upgraded since last assessment. Rank adjusted based on current observations and per review with Building Engineer.
	Pipes - Chilled Water Pipe- Steel	Entire Building	260	LF	6	10+ years	Condenser water supply and return piping between cooling towers and chillers via the CWP-1 and CWP-2 pumps in Boiler Room.
Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	Boiler Room	1	EA	6	6-10 years	F-6. Return fan serving the locker rooms and associated spaces. Misdocumented as 500-1500 cfm indoor exhaust fan in previous assessment.
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - Less than 6000 cfm	Boiler Room - S1 - serves locker rooms	1	EA	5	6-10 years	S-1, serves locker rooms and associated spaces. Located above return fan F-6 and to the left of S-2.
	Air Intake	Boiler Room - S1 - serves locker rooms	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 6000- 10000 cfm	Boiler Room - S2 - serves womens gym	1	EA	5	6-10 years	S-2. Serves womens gym and associated spaces.
	Air Intake	Boiler Room - S2 - serves womens gym	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 10001- 15000 cfm	Boiler Room - S3 - serves mens gym	1	EA	6	6-10 years	S-3, serves mens gym and associated spaces. Housing damage repaired since last assessment. Rank adjusted based on current observations and per review with Building Engineer.
	Air Intake	Boiler Room - S3 - serves mens gym	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 15001- 20000 cfm	Bsmt. Mech, Room - AHU6 - serves lunchroom	1	EA	6	10+ years	AHU6 - Serves Lunchroom
	Air Intake	Bsmt. Mech, Room - AHU6 - serves lunchroom	1	EA	6	10+ years	



Catego	Category : Mechanical			uilding	: Additi	on	1744 W Flyor Avenue, onleage, ie 00045
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 10001- 15000 cfm	Bsmt. Mech. Room - AHU5 - serves Library/Offices	1	EA	6	10+ years	AHU5 - Serves Library/Offices
	Air Intake	Bsmt. Mech. Room - AHU5 - serves Library/Offices	1	EA	6	10+ years	
	VAV Box	Bsmt. Mech. Room - AHU5 - serves Library/Offices	8	EA	6	6-10 years	Leaks repaired since last assessment. Rank adjusted based on current observations and per review with Building Engineer.
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 15001- 20000 cfm	Bsmt. Mech. Room - AHU7 - serves link classrooms	1	EA	6	10+ years	AHU7 - Serves Link Classrooms
	Air Intake	Bsmt. Mech. Room - AHU7 - serves link classrooms	1	EA	6	10+ years	Per review with Building Engineer, partial blockage of air intake resolved since last assessment. Rank adjusted based on current observations.
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Main Roof	1	EA	6	6-10 years	
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Less than 5 tons	Main Roof	1	EA	6	6-10 years	Fan vibration resolved since last assessment. Rank adjusted based on current observations.
Boiler Sy	estems						
,	Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP	Boiler Room	4	EA	6	10+ years	Serves Addition and Main.
	Chemical Pot Feeder	Boiler Room	2	EA	6	10+ years	Serves boiler system and chiller system.
	Condensing- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	4	EA	6	10+ years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	Serves boiler system and chiller system.
	Piping - Dual Temperature Pipes- Copper	Boiler Room	50	LF	6	10+ years	Piping replaced since last assessment. Quantity, Rank, Reason and Priority Rep changed to match current observations. Missing insulation.
	Piping - Dual Temperature Pipes- Copper	Boiler Room	950	LF	6	10+ years	Quantity changed as total has been divided/aggregated.
_Heating_							
	Fin Tube - Electric Fin Tube - Hot Water	Entire Building Entire Building	40 60	LF LF	6 6	6-10 years 6-10 years	Covers have been replaced as



Catego	Category : Mechanical				: Additi		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							necessary since last assessment. Rank, Reason and Priority Rep
							adjusted based on current
							observations and per review with
							Building Engineer.
	Cabinet Heaters - With Hot Water Coil	Entire Building	20	EA	6	6-10 years	Quantity changed as total has been
		Ç				•	divided/aggregated.
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	3	EA	6	6-10 years	
Mechan	ical Plumbing						
	Condenser Pump - 10 - 20 HP	Boiler Room	2	EA	6	10+ years	CWP-1 and CWP-2
	Dual Temperature Pump - 21 - 50 HP	Entire Building	1	EA	6	10+ years	DTP-1
	Dual Temperature Pump - 21 - 50 HP	Entire Building	1	EA	6	10+ years	DTP-2
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Associated with AHU-5. Misidentified
							as hot water pump in previous
					_		assessment.
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Associated with AHU-6. Misidentified
							as hot water pump in previous
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	6-10 years	assessment. Associated with AHU-7. Misidentified
	Dual Temperature Fump - Less than To	Entire Ballaing	'	LA	O	0-10 years	as hot water pump in previous
							assessment
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Associated with S-1. Misidentified as
	·	•				•	hot water pump in previous
							assessment.
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Associated with S-3. Dataplate
							inaccessible at the time of
							assessment due to high location. No
							CPS Asset Tag present.  Misidentified as hot water pump in
							previous assessment.
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Associated with S-2. Misidentified as
	·	g	·		•	5 . c , c c	hot water pump in previous
							assessment.
	Hydronic Supply and Return - Steel	Entire Building	120	LF	7	10+ years	Hydronic piping associated with the
							boiler systems. Location changed for
							clarification.
_Tempera	ature Control						
•	DDC System	Entire Building	101,977	SF	6	10+ years	
	Electric Thermostat	Entire Building	3	EA	7	6-10 years	
	Electric Thermostat	Entire Building	6	EA	7	6-10 years	



**Building: Addition** Category : Mechanical Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Thermostats - DDC **Entire Building** 65 FΑ 6-10 years Unit Ventilation Unit Ventilators- Floor Mounted- Dual 42 EΑ **Entire Building** 6 6-10 years Temperature Coils (Hot/Chilled) Water Unit Ventilators- Ceiling Mounted- Dual Room 263 FΑ 6 10+ years Located in the classroom across the Temperature Coils (Hot/Chilled) Water corridor from Boiler Room Ventilation Exhaust Fans- Indoor - 500 - 1500 CFM **Entire Building** 1 EΑ 6 Item Type changed to match current 6-10 years observations and per review with Building Engineer. Exhaust Fans- Indoor - 500 - 1500 CFM EΑ 6 Fan was operating as intended at the **Entire Building** 1 6-10 years time of assessment without undue noise. Rank adjusted based on current observations. Exhaust Fans- Indoor - Less than 500 CFM **Entire Building** EΑ 6 6-10 years Exhaust Fans- Roof Mounted - 1501 - 8000 EΑ 6 **Entire Building** 6-10 years CFM Exhaust Fans- Roof Mounted - 1501 - 8000 7 FΑ 6 **Entire Building** 6-10 years CFM Exhaust Fans- Roof Mounted - 500 - 1500 **Entire Building** 7 EΑ 6 6-10 years CFM Exhaust Fans- Roof Mounted - 500 - 1500 **Entire Building** 5 EΑ 6 6-10 years CFM Exhaust Fans- Roof Mounted - Greater than **Entire Building** 1 EΑ 6 10+ years 8000 CFM EΑ Exhaust Fans- Roof Mounted - Less than 2 6 **Entire Building** 6-10 years 500 CFM Exhaust Fans- Roof Mounted - Less than **Entire Building** FΑ 6 6-10 years 500 CFM LF Roof Mounted Duct Work **Entire Building** 114 6 10+ years Quantity changed based on current observations as confirmed by physical measurement at the time of assessment. Type II Exhaust Hood- Warming Kitchen 2 EΑ 6-10 years **Entire Building** 6 Category: Plumbing **Building: Addition** Recommend Location Replacement Comments Group Item - Type Quantity UOM Rank Hot Water 2 FΑ 6 Gas Heater - Greater than 600000 BTU/HR Boiler Room 6-10 years 5 Hot Water Storage Tank Gas - 201 - 500 Boiler Room 1 EΑ 6-10 years



Catego	ry : Plumbing		В	uilding	: Additi	on	
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gallons						
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	101,977	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	101,977	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	101,977	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	101,977	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	101,977	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	101,977	SF	6	10+ years	
	Sanitary Piping	Entire Building	101,977	SF	6	10+ years	
	Storm Piping	Entire Building	101,977	SF	6	10+ years	
	Vent Piping	Entire Building	101,977	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Located in the ComEd vault and inaccessible at the time of assessment. Condition verified by the building engineer.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Located at the bottom of the elevator pit and inaccessible at the time of assessment.

Category : Room Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Splined	121B	104	SF	6	10+ years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Doors - Wood Doors inclu hw	121B	1	EA	7	10+ years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Floor - Tile	121B	104	SF	7	10+ years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Lighting - Pendent/Surface	121B	2	EA	7	6-10 years	No one has code or keys for the door except the coach, could not gain



Power Distribution

Walls - Concrete Block

## **Building: Addition** Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments entry. Assessed from previous year. 6 EΑ 7 No one has code or keys for the door Power Distribution 121B 10+ years except the coach, could not gain entry. Assessed from previous year. Walls - Concrete Block 121B 278 SF 7 10+ years No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year. SF Ceiling - Lay-in 123 Main Office 1.210 6 10+ years Doors - Side-lite 123 Main Office 210 SF 7 10+ years SF Doors - Transom Window 123 Main Office 7 10+ years 4 Doors - Wood Doors inclu hw 123 Main Office EΑ 6 10+ years Floor - Tile 123 Main Office 1.210 SF 6 6-10 years Lighting - Lay-in EΑ 6 6-10 years 123 Main Office 13 7 Power Distribution 123 Main Office 12 EΑ 6-10 years SF 7 Walls - Masonry 123 Main Office 1,042 10+ years Work SInk FΑ 123 Main Office 1 7 10+ years SF Ceiling - Lay-in 123A 144 6 10+ years SF Doors - Side-lite 123A 60 7 10+ years Doors - Wood Doors inclu hw 123A 1 EΑ 7 10+ years Floor - Tile/Sheet 123A 144 SF 6 6-10 years Lighting - Lay-in 123A 2 EΑ 7 6-10 years 7 Power Distribution 123A 6 EΑ 6-10 years SF 7 Storage/ Closet 123A 4 10+ years SF Walls - Concrete Block 123A 358 7 10+ years Ceiling - Splined 123B 126 SF 6 10+ years Doors - Wood Doors inclu hw 123B 1 EΑ 6 10+ years SF 7 Floor - Tile 123B 126 10+ years Lighting - Pendent/Surface 123B EΑ 7 6-10 years 2 Power Distribution 123B 6 EΑ 7 6-10 years Walls - Concrete Block 123B 348 SF 7 10+ years 10+ years Work SInk 123B EΑ 7 1 Ceiling - Splined 123C 144 SF 6 10+ years Doors - Wood Doors inclu hw FΑ 7 123C 10+ years Floor - Tile 123C 144 SF 7 10+ years 7 6-10 years Lighting - Pendent/Surface 123C 4 EΑ 6 EΑ 7 Power Distribution 123C 6-10 years SF Walls - Concrete Block 123C 332 7 10+ years SF Ceiling - Splined 125B 104 4 0-1 year Damaged and stained tiles SF Doors - Transom Window 125B 12 7 10+ years Doors - Wood Doors inclu hw 125B 1 EΑ 6 10+ years Floor - Tile 125B 104 SF 6 10+ years 125B FΑ 6 Lighting - Pendent/Surface 10+ years 1

6

216

EΑ

SF

7

7

10+ years

10+ years

125B

125B



Category : Room Building : Addition

Catego	ry:Room		Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Splined	125D Girls Gym	74	SF	6	10+ years		
	Ceiling - Splined	125D Girls Gym	30	SF	4	0-1 year	Water damaged	
	Doors - Side-lite	125D Girls Gym	15	SF	7	10+ years		
	Doors - Wood Doors inclu hw	125D Girls Gym	1	EA	7	10+ years		
	Floor - Tile	125D Girls Gym	104	SF	7	10+ years		
	Lighting - Pendent/Surface	125D Girls Gym	2	EA	7	6-10 years		
	Power Distribution	125D Girls Gym	6	EA	7	10+ years		
	Walls - Concrete Block	125D Girls Gym	278	SF	7	10+ years		
	Ceiling - Splined	135A/135B	689	SF	4	0-1 year	Water damage throughout.	
	Doors - Transom Window	135A/135B	320	SF	7	10+ years		
	Doors - Wood Doors inclu hw	135A/135B	1	EA	6	10+ years		
	Floor - Tile	135A/135B	689	SF	6	10+ years		
	Lighting - Pendent/Surface	135A/135B	12	EA	7	6-10 years		
	Power Distribution	135A/135B	12	EA	7	10+ years		
	Walls - Concrete Block	135A/135B	868	SF	6	10+ years		
	Ceiling - Splined	135D Media Center/ Office	538	SF	6	10+ years		
	Doors - Side-lite	135D Media Center/ Office	50	SF	7	10+ years		
	Doors - Wood Doors inclu hw	135D Media Center/ Office	1	EΑ	6	10+ years		
	Floor - Tile	135D Media Center/ Office	538	SF	6	10+ years		
	Lighting - Lay-in	135D Media Center/ Office	6	EA	7	6-10 years		
	Power Distribution	135D Media Center/ Office	12	EΑ	7	10+ years		
	Walls - Concrete Block	135D Media Center/ Office	638	SF	7	10+ years		
	Walls - Concrete Block	135D Media Center/ Office	10	SF	7	10+ years		
	Ceiling - Splined	139B Kitchen Office	40	SF	6	10+ years		
	Doors - Side-lite	139B Kitchen Office	140	SF	7	10+ years		
	Doors - Wood Doors inclu hw	139B Kitchen Office	1	EΑ	7	10+ years		
	Floor - Tile	139B Kitchen Office	40	SF	7	10+ years		
	Lighting - Pendent/Surface	139B Kitchen Office	1	EA	7	6-10 years		
	Power Distribution	139B Kitchen Office	2	EΑ	7	10+ years		
	Walls - Concrete Block	139B Kitchen Office	120	SF	7	10+ years		
	Ceiling - Splined	141	1,247	SF	6	10+ years		
	Doors - Side-lite	141	8	SF	7	10+ years		
	Doors - Transom Window	141	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	141	5	EA	7	10+ years		
	Floor - Carpet	141	563	SF	6	6-10 years		
	Floor - Tile	141	684	SF	7	10+ years		
	Lighting - Lay-in	141	16	EA	7	6-10 years		
	Power Distribution	141	18	EA	7	6-10 years		
	Storage/ Closet	141	20	SF	7	10+ years		
	Walls - Concrete Block	141	1,404	SF	7	10+ years		
	Walls - Masonry	141	96	SF	7	10+ years		
	Walls - Plaster/Drywall	141	376	SF	7	10+ years		
	Ceiling - Splined	151 Teachers lounge/Dinning	688	SF	6	10+ years		
	Ceiling - Splined	151 Teachers lounge/Dinning	10	SF	4	1-2 years	Broken tiles	
	- 9 -1	3				,		



Category : Room Building : Addition

Catego	ry : Room	Building : Addition							
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Side-lite	151 Teachers lounge/Dinning	24	SF	7	10+ years			
	Doors - Transom Window	151 Teachers lounge/Dinning	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	151 Teachers lounge/Dinning	1	EA	7	10+ years			
	Floor - Tile	151 Teachers lounge/Dinning	698	SF	7	10+ years			
	Lighting - Lay-in	151 Teachers lounge/Dinning	7	EA	7	6-10 years			
	Power Distribution	151 Teachers lounge/Dinning	6	EA	7	10+ years			
	Walls - Plaster/Drywall	151 Teachers lounge/Dinning	739	SF	7	10+ years			
	Ceiling - Splined	227	430	SF	6	10+ years			
	Doors - Wood Doors inclu hw	227	1	EA	6	10+ years			
	Floor - Tile	227	430	SF	6	10+ years			
	Lighting - Pendent/Surface	227	12	EA	6	6-10 years			
	Power Distribution	227	6	EA	7	10+ years			
	Storage/ Closet	227	150	SF	7	10+ years			
	Walls - Concrete Block	227	827	SF	6	10+ years			
	Ceiling - Lay-in	265 Engineer	144	SF	6	10+ years			
	Doors - Side-lite	265 Engineer	24	SF	7	10+ years			
	Doors - Wood Doors inclu hw	265 Engineer	1	EA	7	10+ years			
	Floor - Tile	265 Engineer	144	SF	6	10+ years			
	Lighting - Pendent/Surface	265 Engineer	4	ĒΑ	7	6-10 years			
	Power Distribution	265 Engineer	6	EA	7	6-10 years			
	Storage/ Closet	265 Engineer	350	SF	7	10+ years			
	Walls - Concrete Block	265 Engineer	348	SF	7	10+ years			
	Ceiling - Exposed	267A	589	SF	7	10+ years			
	Doors - Wood Doors inclu hw	267A	2	ĒΑ	6	10+ years			
	Floor - Concrete Epoxy/ Painted	267A	589	SF	5	10+ years			
	Lighting - Pendent/Surface	267A	4	EA	7	6-10 years			
	Power Distribution	267A	8	EA	7	6-10 years			
	Walls - Concrete Block	267A	1,261	SF	7	10+ years			
	Ceiling - Splined	Office 327	420	SF	6	10+ years			
	Ceiling - Splined	Office 327	10	SF	4	0-1 year	Water stained tiles		
	Doors - Steel Doors incl hw	Office 327	1	ĒΑ	6	10+ years			
	Floor - Tile	Office 327	430	SF	6	6-10 years			
	Lighting - Pendent/Surface	Office 327	12	EA	7	6-10 years			
	Power Distribution	Office 327	6	EA	7	10+ years			
	Storage/ Closet	Office 327	94	SF	7	6-10 years			
	Walls - Concrete Block	Office 327	827	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Receiving	120	SF	7	10+ years			
	Doors - Side-lite	Receiving	16	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Receiving	1	ĒΑ	7	10+ years			
	Floor - Tile	Receiving	110	SF	7	10+ years			
	Floor - Tile	Receiving	10	SF	4	1-2 years	Paint peeling		
	Lighting - Pendent/Surface	Receiving	2	EΑ	7	6-10 years	r <b>3</b>		
	Power Distribution	Receiving	4	EΑ	7	10+ years			
	Walls - Concrete Block	Receiving	200	SF	7	10+ years			
			_50	٥.	•	,			



**Building: Addition** Category: Room Recommend Item - Type Location Quantity UOM Rank Replacement Comments Group Gvmnasia Ceiling - Plaster/Drywall 1st Floor Girls Gym Room 125 5,627 SF 7 10+ years Doors - Transom Window 1st Floor Girls Gym Room 125 SF 7 18 10+ years Doors - Wood Doors inclu hw 1st Floor Girls Gym Room 125 EΑ 7 10+ years 1st Floor Girls Gvm Room 125 SF 7 Floor - Wood 5.627 10+ years Lighting - Pendent/Surface 1st Floor Girls Gvm Room 125 FΑ 7 6-10 years 32 Sound System 1st Floor Girls Gym Room 125 1 FΑ 7 6-10 years SF Storage/ Closet 1st Floor Girls Gvm Room 125 190 7 10+ years Walls - Concrete Block 1st Floor Girls Gym Room 125 SF 7,600 7 10+ years Bleacher Seating 1st Floor Men's Gym Room 121/123 192 EΑ 7 10+ years Ceiling - Plaster/Drywall 1st Floor Men's Gym Room 121/123 7,518 SF 7 10+ years Ceiling - Plaster/Drywall 1st Floor Men's Gym Room 121/123 SF 200 6 0-1 year Peeling paint SF Doors - Transom Window 1st Floor Men's Gym Room 121/123 18 7 10+ years Doors - Wood Doors inclu hw 3 EΑ 7 1st Floor Men's Gym Room 121/123 10+ years Floor - Wood 1st Floor Men's Gym Room 121/123 7.718 SF 7 10+ years Lighting - Pendent/Surface 1st Floor Men's Gym Room 121/123 40 FΑ 7 6-10 years Scoreboards 1st Floor Men's Gym Room 121/123 2 EΑ 7 6-10 years 1st Floor Men's Gym Room 121/123 Sound System 1 EΑ 7 6-10 years Storage/ Closet 1st Floor Men's Gym Room 121/123 SF 7 300 10+ years Walls - Concrete Block SF 1st Floor Men's Gym Room 121/123 881 10+ years Kitchen Ceiling - Splined SF 1st Floor 1.361 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EΑ 7 10+ years 1st Floor SF 7 Floor - Tile Quarry 1.361 10+ years Lighting - Pendent/Surface 1st Floor 27 EΑ 7 6-10 years Storage/ Closet SF 1st Floor 100 5 10+ years Walls - Structural Glazed Tile 1st Floor 1.190 SF 7 10+ years \_Librarv LF 7 Casework 1st Floor - Room 135 244 10+ years Ceiling - Splined 3.357 SF 6 1st Floor - Room 135 10+ years Doors - Wood Doors inclu hw 1st Floor - Room 135 2 EΑ 7 10+ years SF Floor - Tile 1st Floor - Room 135 3.307 7 10+ years SF Floor - Tile 1st Floor - Room 135 50 4 1-2 years Cracked 7 6-10 years Lighting - Lay-in 1st Floor - Room 135 75 EΑ Walls - Masonry 1st Floor - Room 135 1,596 SF 7 10+ years Walls - Plaster/Drywall 1st Floor - Room 135 SF 7 488 10+ years Walls - Plaster/Drywall 488 SF 6 1st Floor - Room 135 10+ years Locker/Shower Room 7 Accessories 121 Men's Locker 2,558 SF 6-10 years



1744 W Pryor AVENUE, Chicago, IL 6

Catego	ry : Room		Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Benches, ped mounted	121 Men's Locker	2	LF	7	10+ years		
	Ceiling - Exposed	121 Men's Locker	2,558	SF	7	10+ years		
	Doors - Wood Doors inclu hw	121 Men's Locker	2	EA	7	10+ years		
	Floor - Concrete	121 Men's Locker	2,202	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	121 Men's Locker	356	SF	7	10+ years		
	Floor Drain	121 Men's Locker	7	EΑ	7	10+ years		
	Lavatory	121 Men's Locker	1	EA	7	10+ years		
	Lighting - Pendent/Surface	121 Men's Locker	27	EA	7	6-10 years		
	Partitions	121 Men's Locker	1	EΑ	7	10+ years		
	Showers	121 Men's Locker	8	EΑ	7	10+ years		
	Student Lockers - Two Tier	121 Men's Locker	146	EA	7	10+ years		
	Urinals	121 Men's Locker	1	EΑ	7	10+ years		
	Walls - Concrete Block	121 Men's Locker	2,980	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	121 Men's Locker	700	SF	7	10+ years		
	Water Closet	121 Men's Locker	1	EA	7	10+ years		
	Accessories	125 F Women's Locker	2,900	SF	7	6-10 years		
	Benches, ped mounted	125 F Women's Locker	5	LF	7	10+ years		
	Ceiling - Exposed	125 F Women's Locker	2,900	SF	7	10+ years		
	Doors - Steel Doors incl hw	125 F Women's Locker	1	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	125 F Women's Locker	2,000	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	125 F Women's Locker	900	SF	6	10+ years		
	Floor Drain	125 F Women's Locker	5	EA	7	10+ years		
	Hand Dryer	125 F Women's Locker	7	EA	7	6-10 years		
	Lavatory	125 F Women's Locker	3	EA	7	10+ years		
	Lighting - Pendent/Surface	125 F Women's Locker	32	EA	7	6-10 years		
	Partitions	125 F Women's Locker	2	EA	7	10+ years		
	Showers	125 F Women's Locker	12	EA	7	10+ years		
	Student Lockers - One Tier	125 F Women's Locker	900	EA	7	10+ years		
	Walls - Concrete Block	125 F Women's Locker	3,700	SF	7	10+ years		
	Walls - Structural Glazed Tile	125 F Women's Locker	200	SF	7	10+ years		
	Water Closet	125 F Women's Locker	2	EA	7	10+ years		
Lunch &	Multipurpose Room							
	Ceiling - Splined	139 Servery	1,548	SF	6	10+ years		
	Doors - Store Front	139 Servery	3	EA	7	10+ years		
	Doors - Transom Window	139 Servery	24	SF	7	10+ years		
	Floor - Tile Quarry	139 Servery	1,548	SF	7	10+ years		
	Lighting - Lay-in	139 Servery	26	EA	7	6-10 years		
	Serving Line	139 Servery	90	LF	7	6-10 years		
	Walls - Structural Glazed Tile	139 Servery	1,401	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st floor 119	5,328	SF	7	10+ years		
	Doors - Transom Window	1st floor 119	800	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st floor 119	4	ĒΑ	7	10+ years		
	Floor - Tile	1st floor 119	5,328	SF	7	10+ years		
	-	- · · · · · ·	-,0		-	- <b>,</b>		



**Building: Addition** Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Lighting - Pendent/Surface 1st floor 119 90 EΑ 6-10 years 7 Lighting - Pendent/Surface 8 EΑ 5 0-1 vear 1st floor 119 Does not work. Serving Line 1st floor 119 40 LF 7 10+ years Walls - Masonry SF 7 1st floor 119 3.264 10+ years Mechanical/ Service Rooms Janitor's Closet 1st Floor 4 SF 7 10+ years SF Janitor's Closet 1st Floor 60 5 10+ years SF 7 Mechanical/ Service Rooms 1st Floor 60 10+ years SF Vaults 1st Floor 64 7 6-10 years Boiler Room 2nd Floor 4.200 SF 7 10+ years Janitor's Closet 2nd Floor 60 SF 7 10+ years SF Janitor's Closet 2nd Floor 60 7 10+ years SF Mechanical/ Service Rooms 2nd Floor 2.350 7 10+ years 2nd Floor SF 7 Storage Room 200 10+ years Storage Room 2nd Floor 589 SF 7 10+ years SF Storage Room 2nd Floor 107 7 10+ years SF Janitor's Closet 3rd Floor 60 7 10+ years SF 7 Janitor's Closet 3rd Floor 60 10+ years Storage Room 3rd Floor 120 SF 7 10+ years SF Crawl Space - Unfinished Basement 1.587 7 10+ years Mechanical/ Service Rooms **Basement** 3.160 SF 7 10+ years Prep Room Ceiling - Lay-in 331 serves 331/337 324 SF 7 10+ years Doors - Steel Doors incl hw 331 serves 331/337 2 EΑ 6 10+ years SF Floor - Tile/Sheet 331 serves 331/337 324 5 0-1 year Reseal flooring EΑ 6 Lighting - Pendent/Surface 331 serves 331/337 3 10+ years Walls - Concrete Block 331 serves 331/337 448 SF 6 10+ years Work Sink 331 serves 331/337 1 FΑ 7 10+ years 6 1 F 7 Casework 347A serves labs 341and 347 6-10 years SF Ceiling - Splined 347A serves labs 341and 347 324 6 6-10 years Doors - Transom Window SF 7 347A serves labs 341and 347 65 10+ years Doors - Wood Doors inclu hw 347A serves labs 341and 347 2 EΑ 7 10+ years Floor - Tile 347A serves labs 341and 347 324 SF 7 10+ years Lighting - Pendent/Surface 8 FΑ 7 6-10 years 347A serves labs 341and 347 Walls - Concrete Block 200 SF 7 347A serves labs 341and 347 10+ years Walls - Plaster/Drywall 347A serves labs 341and 347 248 SF 7 10+ years Work Sink EΑ 7 347A serves labs 341and 347 6-10 years Restroom Accessories 109A Mens near Main Office 74 SF 7 6-10 years SF Ceiling - Lay-in 109A Mens near Main Office 64 6 10+ years





Catego	ry : Room		В	uilding	: Addition	on	1744 W FIYOI AVENUE, CIIICAGO, IL 00043
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	109A Mens near Main Office	10	SF	5	0-1 year	Stained and damaged tiles
	Doors - Transom Window	109A Mens near Main Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109A Mens near Main Office	_1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	109A Mens near Main Office	74	SF	7	10+ years	
	Hand Dryer	109A Mens near Main Office	1	EA	7	6-10 years	
	Lavatory	109A Mens near Main Office	1	EA	7	10+ years	
	Lighting - Lay-in	109A Mens near Main Office	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	109A Mens near Main Office	189	SF	7	10+ years	
	Water Closet	109A Mens near Main Office	_1	EA	7	10+ years	
	Accessories	109B Women Near Main Office	74	SF	7	6-10 years	
	Ceiling - Splined	109B Women Near Main Office	74	SF	6	10+ years	
	Doors - Transom Window	109B Women Near Main Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109B Women Near Main Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	109B Women Near Main Office	74	SF	7	10+ years	
	Lavatory	109B Women Near Main Office	1	EA	7	10+ years	
	Lighting - Lay-in	109B Women Near Main Office	1	EΑ	7	6-10 years	
	Partitions	109B Women Near Main Office	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	109B Women Near Main Office	189	SF	7	10+ years	
	Water Closet	109B Women Near Main Office	1	EA	7	10+ years	No sus bas and an law for the days
	Accessories	121 Men's Gym Office Restroom	58	SF	7	6-10 years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Ceiling - Splined	121 Men's Gym Office Restroom	58	SF	6	10+ years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Doors - Transom Window	121 Men's Gym Office Restroom	1	SF	6	2-5 years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Floor - Tile Ceramic/ Porcelain	121 Men's Gym Office Restroom	58	SF	7	10+ years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Floor Drain	121 Men's Gym Office Restroom	1	EA	7	10+ years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Lavatory	121 Men's Gym Office Restroom	1	EA	7	10+ years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Lighting - Pendent/Surface	121 Men's Gym Office Restroom	1	EA	7	6-10 years	No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.
	Showers	121 Men's Gym Office Restroom	1	EA	7	10+ years	No one has code or keys for the door except the coach, could not gain
	Student Lockers - One Tier	121 Men's Gym Office Restroom	5	EA	7	10+ years	entry. Assessed from previous year. No one has code or keys for the door



Catego	ry : Room		Building : Addition					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	121 Men's Gym Office Restroom	110	SF	7	10+ years	except the coach, could not gain entry. Assessed from previous year. No one has code or keys for the door except the coach, could not gain	
	Walls - Concrete Block	121 Men's Gym Office Restroom	10	SF	5	0-1 year	entry. Assessed from previous year. Cracked. No one has code or keys for the door except the coach, could not gain entry. Assessed from	
	Water Closet	121 Men's Gym Office Restroom	1	EA	7	10+ years	previous year.  No one has code or keys for the door except the coach, could not gain entry. Assessed from previous year.	
	Accessories	123 G Women	159	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	123 G Women	159	SF	7	10+ years		
	Doors - Steel Doors incl hw	123 G Women	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	123 G Women	159	SF	7	10+ years		
	Floor Drain	123 G Women	1	EA	7	10+ years		
	Hand Dryer	123 G Women	2	EA	7	6-10 years		
	Lavatory	123 G Women	3	EA	7	10+ years		
	Lighting - Pendent/Surface	123 G Women	3	EA	7	6-10 years		
	Partitions	123 G Women	4	EA	7	10+ years		
	Walls - Structural Glazed Tile	123 G Women	308	SF	7	10+ years		
	Water Closet	123 G Women	4	EA	7	10+ years		
	Accessories	123A Women's Gym Office	58	SF	7	6-10 years		
	Ceiling - Lay-in	123A Women's Gym Office	58	SF	6	10+ years		
	Doors - Wood Doors inclu hw	123A Women's Gym Office	1	EA	7	10+ years		
	Floor - Tile	123A Women's Gym Office	58	SF	4	0-1 year	Missing and separating.	
	Lavatory	123A Women's Gym Office	1	ĒΑ	7	10+ years	3	
	Lighting - Lay-in	123A Women's Gym Office	1	EA	7	6-10 years		
	Showers	123A Women's Gym Office	1	EA	7	10+ years		
	Student Lockers - One Tier	123A Women's Gym Office	8	EΑ	7	10+ years		
	Walls - Concrete Block	123A Women's Gym Office	100	SF	7	10+ years		
	Water Closet	123A Women's Gym Office	1	EA	7	10+ years		
	Accessories	123F	159	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	123F	159	SF	7	10+ years		
	Doors - Steel Doors incl hw	123F	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	123F	159	SF	7	10+ years		
	Floor Drain	123F	100	EA	7	10+ years		
	Hand Dryer	123F	1	EA	7	6-10 years		
	Lavatory	123F	3	EA	7	10+ years		
	Lighting - Pendent/Surface	123F	3	EA	7	6-10 years		
	Partitions	123F	2	EA	7	10+ years		
	Urinals	123F	2	EA	7	10+ years		
	Walls - Structural Glazed Tile	123F	308	SF	7	10+ years		
	vvans - Structural Glazeu Tile	1201	300	SI-	,	TOT YEARS		

Assessment Date: 08/22/2023



Campus Name: Morgan Park HS

**Building: Addition** Category : Room Recommend UOM Group Item - Type Location Quantity Rank Replacement Comments 2 Water Closet 123F EA 7 10+ years

Accessories	137 Door 3 Dock Women`	100	SF	7	6-10 years	
Ceiling - Exposed	137 Door 3 Dock Women`	100	SF	7	10+ years	
Doors - Wood Doors inclu hw	137 Door 3 Dock Women`	1	EA	7	10+ years	
Floor - Concrete Epoxy/ Painted	137 Door 3 Dock Women`	100	SF	4	0-1 year	Peeling sealant
Lavatory	137 Door 3 Dock Women`	2	EA	7	10+ years	Ü
Lighting - Pendent/Surface	137 Door 3 Dock Women`	1	EA	7	6-10 years	
Partitions	137 Door 3 Dock Women`	1	EA	7	10+ years	
Student Lockers - One Tier	137 Door 3 Dock Women`	1	EA	7	10+ years	
Student Lockers - Two Tiers	137 Door 3 Dock Women`	4	EA	7	10+ years	
Walls - Concrete Block	137 Door 3 Dock Women`	260	SF	7	10+ years	
Water Closet	137 Door 3 Dock Women`	1	ĒΑ	7	6-10 years	
Accessories	139 Kitchen Men	82	SF	7	6-10 years	
Ceiling - Exposed	139 Kitchen Men	82	SF	7	10+ years	
Doors - Wood Doors inclu hw	139 Kitchen Men	1	EΑ	6	10+ years	
Floor - Concrete Epoxy/ Painted	139 Kitchen Men	82	SF	7	10+ years	
Floor Drain	139 Kitchen Men	1	EA	7	10+ years	
Lavatory	139 Kitchen Men	1	EA	7	10+ years	
Lighting - Pendent/Surface	139 Kitchen Men	1	EA	7	6-10 years	
Partitions	139 Kitchen Men	1	EA	7	10+ years	
Urinals	139 Kitchen Men	1	EA	7	10+ years	
Walls - Concrete Block	139 Kitchen Men	130	SF	7	10+ years	
Water Closet	139 Kitchen Men	1	EA	7	10+ years	
Accessories	139 Kitchen Women	82	SF	7	6-10 years	
Ceiling - Exposed	139 Kitchen Women	82	SF	7	10+ years	
Doors - Wood Doors inclu hw	139 Kitchen Women	1	EA	6	10+ years	
Floor - Concrete Epoxy/ Painted	139 Kitchen Women	82	SF	7	10+ years	
Floor Drain	139 Kitchen Women	1	EA	7	10+ years	
	139 Kitchen Women	1	EA	7	•	
Lavatory Lighting - Pendent/Surface	139 Kitchen Women	1	EA	7	10+ years	
Partitions	139 Kitchen Women	1	EA	7	6-10 years	
Student Lockers - One Tier	139 Kitchen Women	7	EA	7	10+ years	
Walls - Concrete Block		130	SF		10+ years	
Water Closet	139 Kitchen Women		EA	7	10+ years	
	139 Kitchen Women 144B Door 3 Dock Men	1 100	SF	7 7	10+ years	
Accessories			SF SF		6-10 years	
Ceiling - Exposed	144B Door 3 Dock Men	100		7	10+ years	
Doors - Wood Doors inclu hw	144B Door 3 Dock Men	1	EA	7	10+ years	
Floor - Concrete	144B Door 3 Dock Men	100	SF	7	10+ years	
Lavatory	144B Door 3 Dock Men	1	EΑ	7	10+ years	
Lighting - Pendent/Surface	144B Door 3 Dock Men	1	EΑ	7	6-10 years	
Partitions	144B Door 3 Dock Men	1	EA	7	10+ years	
Urinals	144B Door 3 Dock Men	1	EA	7	10+ years	
Walls - Concrete Block	144B Door 3 Dock Men	260	SF	7	10+ years	
Water Closet	144B Door 3 Dock Men	1	EΑ	7	10+ years	

Page : 60 of 81



Category : Room Building : Addition
Recommend

_				_		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	150A Mens Toilet Boys Gym	158	SF	7	6-10 years	
	Ceiling - Lay-in	150A Mens Toilet Boys Gym	148	SF	6	10+ years	
	Ceiling - Lay-in	150A Mens Toilet Boys Gym	10	SF	5	0-1 year	Water stained and missing tiles
	Doors - Wood Doors inclu hw	150A Mens Toilet Boys Gym	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	150A Mens Toilet Boys Gym	158	SF	7	10+ years	
	Floor Drain	150A Mens Toilet Boys Gym	1	EA	7	10+ years	
	Lavatory	150A Mens Toilet Boys Gym	3	EA	7	10+ years	
	Lighting - Lay-in	150A Mens Toilet Boys Gym	2	EA	6	6-10 years	
	Partitions	150A Mens Toilet Boys Gym	2	EA	7	10+ years	
	Urinals	150A Mens Toilet Boys Gym	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	150A Mens Toilet Boys Gym	340	SF	7	10+ years	
	Water Closet	150A Mens Toilet Boys Gym	2	EA	7	10+ years	
	Accessories	150B Women Toilet Girls Gym	158	SF	7	6-10 years	
	Ceiling - Lay-in	150B Women Toilet Girls Gym	158	SF	6	10+ years	
	Doors - Wood Doors inclu hw	150B Women Toilet Girls Gym	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	150B Women Toilet Girls Gym	158	SF	7	10+ years	
	Floor Drain	150B Women Toilet Girls Gym	1	EA	7	10+ years	
	Lavatory	150B Women Toilet Girls Gym	3	EA	7	10+ years	
	Lighting - Lay-in	150B Women Toilet Girls Gym	2	EA	5	0-1 year	Does not work.
	Partitions	150B Women Toilet Girls Gym	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	150B Women Toilet Girls Gym	340	SF	7	10+ years	
	Water Closet	150B Women Toilet Girls Gym	4	ĒΑ	7	10+ years	
	Accessories	215A women restroom	41	SF	7	6-10 years	
	Ceiling - Lay-in	215A women restroom	41	SF	4	0-1 year	Missing and water damage tiles
	Doors - Wood Doors inclu hw	215A women restroom	2	EA	6	10+ years	samg and nater damage mee
	Floor - Tile Ceramic/ Porcelain	215A women restroom	41	SF	6	6-10 years	
	Lavatory	215A women restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	215A women restroom	1	EA	6	6-10 years	
	Partitions	215A women restroom	1	EA	5	6-10 years	Repaint partition
	Walls - Concrete Block	215A women restroom	81	SF	6	10+ years	repaire partition
	Water Closet	215A women restroom	1	EA	6	6-10 years	
	Accessories	215B Men's staff	78	SF	7	6-10 years	
	Ceiling - Lay-in	215B Men's staff	78	SF	6	10+ years	
	Doors - Steel Doors incl hw	215B Men's staff	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	215B Men's staff	78	SF	6	10+ years	
	Lavatory	215B Men's staff	1	EA	6	10+ years	
	Lighting - Lay-in	215B Men's staff	1	EA	6	6-10 years	
	Partitions	215B Men's staff	1	EA	7	10+ years	
	Urinals	215B Men's staff	1	EA	6	10+ years 10+ years	
	Walls - Concrete Block	215B Men's staff	159	SF	6		
	Water Closet			SF EA	-	10+ years	
		215B Men's staff	1	SF	6	10+ years	
	Accessories	223A Boys	296		7	6-10 years	
	Ceiling - Plaster/Drywall	223A Boys	296	SF	6	10+ years	Danair daar
	Doors - Steel Doors incl hw	223A Boys	1	EA	6	0-1 year	Repair door



Category : Room

Building : Addition

Recommend

Group Item - Type

Location

Quantity UOM Rank Replacement Comments

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	223A Boys	296	SF	6	6-10 years	
	Floor Drain	223A Boys	1	EA	7	10+ years	
	Hand Dryer	223A Boys	1	EA	7	6-10 years	
	Lavatory	223A Boys	3	EA	6	10+ years	
	Lighting - Pendent/Surface	223A Boys	4	EA	6	6-10 years	
	Partitions	223A Boys	3	EA	7	10+ years	
	Urinals	223A Boys	4	EA	6	10+ years	
	Walls - Structural Glazed Tile	223A Boys	690	SF	6	10+ years	
	Water Closet	223A Boys	3	EA	6	10+ years	
	Accessories	223D Girls	296	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	223D Girls	296	SF	6	10+ years	
	Doors - Steel Doors incl hw	223D Girls	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	223D Girls	296	SF	6	10+ years	
	Floor Drain	223D Girls	1	EA	7	10+ years	
	Hand Dryer	223D Girls	2	EA	5	0-1 year	Repair or replace hand dryers
	Lavatory	223D Girls	3	EA	6	10+ years	
	Lighting - Pendent/Surface	223D Girls	4	EA	6	6-10 years	
	Partitions	223D Girls	7	EA	7	10+ years	
	Walls - Structural Glazed Tile	223D Girls	690	SF	6	10+ years	
	Water Closet	223D Girls	7	EA	6	10+ years	
	Accessories	265/267 Engineer	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	265/267 Engineer	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	265/267 Engineer	1	EA	6	10+ years	
	Floor - Tile	265/267 Engineer	25	SF	7	10+ years	
	Lavatory	265/267 Engineer	1	EA	7	10+ years	
	Lighting - Pendent/Surface	265/267 Engineer	1	EA	7	6-10 years	
	Walls - Concrete Block	265/267 Engineer	48	SF	7	10+ years	
	Water Closet	265/267 Engineer	1	EA	7	10+ years	
	Accessories	315A	143	SF	7	6-10 years	
	Ceiling - Lay-in	315A	80	SF	6	10+ years	
	Ceiling - Splined	315A	63	SF	6	10+ years	
	Doors - Wood Doors inclu hw	315A	2	EA	6	10+ years	
	Floor - Tile	315A	80	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	315A	63	SF	6	10+ years	
	Lavatory	315A	1	EA	6	10+ years	
	Lighting - Lay-in	315A	2	EA	5	1-2 years	Light fixtures are not working
	Lighting - Pendent/Surface	315A	1	EA	6	10+ years	
	Partitions	315A	1	EA	7	10+ years	
	Urinals	315A	1	EA	7	10+ years	
	Walls - Concrete Block	315A	224	SF	6	10+ years	
	Water Closet	315A	1	EA	6	10+ years	
	Accessories	325A Girls	296	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	325A Girls	296	SF	6	10+ years	
	Doors - Steel Doors incl hw	325A Girls	1	EA	6	10+ years	



Category : Room Ruilding : Addition

Calego	ry : Room	Building : Addition						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile Ceramic/ Porcelain	325A Girls	296	SF	6	10+ years		
	Floor Drain	325A Girls	1	EA	7	10+ years		
	Hand Dryer	325A Girls	2	EA	7	6-10 years		
	Lavatory	325A Girls	2	EΑ	6	10+ years		
	Lighting - Pendent/Surface	325A Girls	4	EA	6	6-10 years		
	Partitions	325A Girls	7	EA	7	10+ years		
	Walls - Structural Glazed Tile	325A Girls	690	SF	6	10+ years		
	Water Closet	325A Girls	7	EA	6	10+ years		
	Accessories	325B Boys	296	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	325B Boys	296	SF	6	10+ years		
	Doors - Steel Doors incl hw	325B Boys	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	325B Boys	296	SF	6	10+ years		
	Floor Drain	325B Boys	1	EA	7	10+ years		
	Hand Dryer	325B Boys	1	EA	7	6-10 years		
	Lavatory	325B Boys	3	EA	6	10+ years		
	Lighting - Pendent/Surface	325B Boys	4	EA	6	10+ years		
	Partitions	325B Boys	3	EA	7	10+ years		
	Urinals	325B Boys	4	EA	6	10+ years		
	Walls - Structural Glazed Tile	325B Boys	690	SF	6	10+ years		
	Water Closet	325B Boys	3	EA	6	6-10 years		
	Accessories	Ass't principal office	25	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Ass't principal office	25	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Ass't principal office	1	EA	7	10+ years		
	Floor - Tile	Ass't principal office	25	SF	7	10+ years		
	Lavatory	Ass't principal office	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Ass't principal office	1	EA	7	6-10 years		
	Walls - Concrete Block	Ass't principal office	50	SF	7	10+ years		
	Water Closet	Ass't principal office	1	EA	7	10+ years		

Category : Classroom Building : Addition

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #215 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	758	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	758	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	974	SF	7	10+ years	

Classroom #217 (Regular Classroom)



1744 W Pryor AVENUE, Chicago, IL 60643 **Building: Addition** Category: Classroom Recommend Location Group Item - Type Quantity **UOM** Rank Replacement Comments LF Casework 2nd Floor 16 10+ vears 7 Ceiling - Lav-in 2nd Floor 758 SF 7 10+ years Doors - Side-lite 2nd Floor 8 SF 7 10+ years Doors - Wood Doors inclu hw EΑ 7 2nd Floor 1 10+ years SF Floor - Tile 2nd Floor 758 7 10+ years Lighting - Pendent/Surface 7 2nd Floor 20 EΑ 6-10 years Marker Board 2nd Floor 20 LF 7 6-10 years SF Walls - Concrete Block 2nd Floor 974 10+ years Classroom #219 (Regular Classroom) 2nd Floor 16 LF 7 10+ years Casework Ceiling - Lay-in 2nd Floor 758 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor EΑ 7 1 10+ years SF Floor - Tile 2nd Floor 758 7 10+ years Lighting - Pendent/Surface 2nd Floor EΑ 7 6-10 years 20 Marker Board 2nd Floor 20 LF 7 6-10 years SF Storage/ Closet 2nd Floor 125 5 2-5 years Walls - Concrete Block SF 7 2nd Floor 974 10+ years Classroom #221 (Regular Classroom) LF Casework 2nd Floor 16 7 10+ years SF Ceiling - Lay-in 2nd Floor 758 7 6-10 years LF Chalk Board 2nd Floor 15 4 2-5 years Doors - Wood Doors inclu hw EΑ 7 2nd Floor 1 10+ years Floor - Tile 2nd Floor 758 SF 7 10+ years Lighting - Pendent/Surface 2nd Floor 20 EΑ 7 6-10 years LF Marker Board 2nd Floor 20 7 6-10 years 2nd Floor SF 7 Storage/ Closet 15 10+ years Walls - Concrete Block 2nd Floor 974 SF 7 10+ years Classroom #223 (Regular Classroom) 2nd Floor LF Casework 16 6 6-10 years Ceiling - Lay-in 2nd Floor 758 SF 7 6-10 years Doors - Transom Window SF 2nd Floor 8 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years Floor - Tile 2nd Floor 758 SF 7 10+ years Lighting - Pendent/Surface 6-10 years 2nd Floor 20 EΑ 6 Marker Board 2nd Floor 20 LF 6 6-10 years Storage/ Closet 2nd Floor 15 SF 7 10+ years Walls - Concrete Block 974 SF 6 2nd Floor 10+ years Classroom #225 (Regular Classroom) 2nd Floor LF Casework 4 6 6-10 years



**Building: Addition** Category: Classroom Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Ceiling - Lay-in 2nd Floor 758 SF 6-10 years 7 Doors - Wood Doors inclu hw 2nd Floor EΑ 1 6 10+ years Floor - Tile 2nd Floor 758 SF 7 6-10 years Lighting - Pendent/Surface 2nd Floor 20 EΑ 6 6-10 years 1 F Marker Board 2nd Floor 16 6 6-10 years SF 7 Storage/ Closet 2nd Floor 20 10+ years Walls - Concrete Block 974 SF 7 2nd Floor 10+ years Classroom #229 (Regular Classroom) 2nd Floor AC Units 1 EΑ 7 6-10 years Ceiling - Lay-in 2nd Floor 803 SF 7 10+ years Chalk Board 2nd Floor 10 LF 4 2-5 years Doors - Side-lite 2nd Floor SF 10+ years 24 6 Doors - Wood Doors inclu hw 2nd Floor 2 EΑ 7 10+ years Floor - Tile 2nd Floor 793 SF 7 10+ years Floor - Tile 2nd Floor 10 SF 1-2 years Missing tile FΑ Lighting - Lay-in 2nd Floor 10 6 6-10 years 7 Marker Board 2nd Floor 10 LF 6-10 years SF Walls - Concrete Block 2nd Floor 775 7 10+ years Classroom #231 (Regular Classroom) 2nd Floor LF Casework 16 6 6-10 years SF Ceiling - Lay-in 2nd Floor 758 7 6-10 years Doors - Side-lite 2nd Floor 8 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 7 10+ years Floor - Tile 2nd Floor 758 SF 7 6-10 years Lighting - Pendent/Surface 2nd Floor 20 EΑ 6 6-10 years Marker Board 2nd Floor 20 LF 6 6-10 years Storage/ Closet 2nd Floor 20 SF 7 10+ years Walls - Concrete Block SF 2nd Floor 974 10+ years Classroom #233 (Regular Classroom) Casework 2nd Floor 16 LF 7 10+ years SF Ceiling - Lay-in 2nd Floor 758 7 10+ years SF Doors - Side-lite 2nd Floor 8 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 7 10+ years SF Floor - Tile 2nd Floor 758 7 10+ years Lighting - Pendent/Surface 2nd Floor 20 EΑ 7 6-10 years Storage/ Closet 2nd Floor 15 SF 7 10+ years Walls - Concrete Block 974 SF 7 2nd Floor 10+ years Classroom #235 (Regular Classroom) 2nd Floor LF Casework 16 6 6-10 years



Category : Classroom		В	uildina	: Additi	on	, , , , , , , , , , , , , , , , , , , ,	
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Lay-in	2nd Floor	758	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	758	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	974	SF	6	10+ years	
Classroo	om #237 (Regular Classroom)						
	Casework	2nd Floor	16	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	758	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	758	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor 2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor 2nd Floor	974	SF	6		
	Walls - Concrete Block	Ziid Flooi	974	SF	0	10+ years	
Classroo	om #239 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	758	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	758	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	974	SF	7	10+ years	
Classroo	om #241 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	758	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	758	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
				LF			
	Marker Board	2nd Floor	20	SF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	974	5F	7	10+ years	



Category : Classroom		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #243 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	758	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	758	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	974	SF	7	10+ years	
Classroo	m #245 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	758	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	758	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	974	SF	7	10+ years	
Classroo	m #247 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	758	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	758	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	974	SF	7	10+ years	
Classroo	m #315 (Regular Classroom)						
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	758	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	758	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	10+ years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	974	SF	6	10+ years	
Classroo	m #317 (Regular Classroom)						



Category : Classroom		В	Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Casework	3rd Floor	16	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Missing tile	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	758	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	10+ years		
	Storage/ Closet	3rd Floor	15	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	974	SF	6	10+ years		
Classroo	m #319 (Regular Classroom)							
	Casework	3rd Floor	16	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	967	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	3rd Floor	967	SF	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	25	ĒΑ	6	10+ years		
	Marker Board	3rd Floor	34	LF	6	6-10 years		
	Walls - Concrete Block	3rd Floor	1,082	SF	6	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroo	m #321 (Regular Classroom)							
Classico	Casework	3rd Floor	4	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	758	SF	7	10+ years		
	Chalk Board	3rd Floor	50	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor		SF	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	758 20	EA	6	10+ years		
	Storage/ Closet	3rd Floor	15	SF	7			
	Walls - Concrete Block	3rd Floor	974	SF SF	6	10+ years 10+ years		
	Walls - Coliciete block	SIU FIOOI	974	SF	b	10+ years		
_Classroo	m #323 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	16	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	758	SF	7	10+ years		
	Chalk Board	3rd Floor	8	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	758	SF	6	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	10+ years		
	Storage/ Closet	3rd Floor	15	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	974	SF	7	10+ years		
_Classroo	m #325 (Regular Classroom)							



Category : Classroom		В	uilding	: Additi	on	-	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	758	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	758	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	974	SF	6	10+ years	
_Classroo	om #331 (Science)						
	Casework	3rd Floor	90	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,314	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	40	SF	4	0-1 year	Missing or damaged tiles
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	3
	Eye Wash Station	3rd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	3rd Floor	1,354	SF	7	10+ years	
	Gas Line	3rd Floor	8	ĒΑ	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	6	10+ years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Science Lab Elements	3rd Floor	58	SF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	ĒΑ	6	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Storage/ Closet	3rd Floor	130	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	700	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	500	SF	6	10+ years	
	Work Sink	3rd Floor	10	ĒΑ	7	10+ years	
Classroo	om #337 (Science)						
	Casework	3rd Floor	154	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,164	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Eye Wash Station	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	1,164	SF	6	6-10 years	
	Gas Line	3rd Floor	2	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	18	EΑ	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Science Lab Elements	3rd Floor	58	SF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	6-10 years	
	Science Lab Shower	3rd Floor	; 1	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	94	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	982	SF	6	10+ years	
	Work Sink	3rd Floor	5	EA	7	10+ years	
	TOTA OFFICE	014 1 1001	3	_/ \	,	ioi youis	



Category : Classroom		В					
	_				_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #339 (Regular Classroom)						
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	758	SF	6	10+ years	
	Chalk Board	3rd Floor	50	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	758	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	10+ years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	974	SF	6	10+ years	
Classroo	m #341 (Science)						
	Casework	3rd Floor	82	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	1,164	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	1,164	SF	7	10+ years	
	Gas Line	3rd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	30	EA	6	10+ years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	100	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	982	SF	6	10+ years	
	Work Sink	3rd Floor	5	EA	7	10+ years	
Classroo	m #347 (Science)						
	Casework	3rd Floor	130	LF	7	10+ years	
	Ceiling - Splined	3rd Floor	1,354	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	16	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Eye Wash Station	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,354	SF	7	10+ years	
	Gas Line	3rd Floor	15	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	6	10+ years	
	Science Lab Elements	3rd Floor	27	SF	7	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Storage/ Closet	3rd Floor	100	SF	4	0-1 year	Ceiling tiles have water stains/missing ceiling tiles
	Walls - Concrete Block	3rd Floor	1,200	SF	6	10+ years	stains/missing centry thes
	Work Sink	3rd Floor	1,200	EA	7	10+ years	
	WORK OHIK	310 1 1001	O	LA	,	IUT YEAIS	



Category : Classroom Building : Addition

Recommend

Group Item - Type

Location

Quantity

UOM

Rank

Replacement

Comments

Category : Interior Building : Addition

Catego	ry : Interior		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
<u>Corridor</u>									
	Ceiling - Lay-in	1st Floor	3,756	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	4	EΑ	7	10+ years			
	Doors - Transom Window	1st Floor	24	SF	7	10+ years			
	Drinking Fountains - Single Water Cooler	1st Floor	2	EΑ	7	10+ years			
	Floor - Tile/Sheet	1st Floor	3,756	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	21	EΑ	7	10+ years			
	Student Lockers - One Tier	1st Floor	113	EΑ	7	10+ years			
	Walls - Masonry	1st Floor	2,164	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Floor	60	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	3,111	SF	7	10+ years			
	Drinking Fountains - Single Fountain	2nd Floor	2	EΑ	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	3,107	SF	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	4	SF	4	0-1 year	Chipped tiles		
	Lighting - Lay-in	2nd Floor	2	EΑ	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	29	EΑ	7	6-10 years			
	Student Lockers - One Tier	2nd Floor	263	EΑ	7	10+ years			
	Walls - Concrete Block	2nd Floor	1,200	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,000	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	3,101	SF	6	6-10 years			
	Ceiling - Lay-in	3rd Floor	10	SF	4	1-2 years	Water damage.		
	Drinking Fountains - Single Water Cooler	3rd Floor	2	EΑ	7	10+ years	•		
	Floor - Tile/Sheet	3rd Floor	3,111	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	31	EΑ	7	10+ years			
	Student Lockers - One Tier	3rd Floor	273	EΑ	6	10+ years			
	Walls - Concrete Block	3rd Floor	1,200	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	3rd Floor	1,000	SF	6	10+ years			
	Ceiling - Lay-in	Boiler Room Corridor	720	SF	6	10+ years			
	Floor - Tile/Sheet	Boiler Room Corridor	720	SF	7	10+ years			
	Lighting - Lay-in	Boiler Room Corridor	8	EΑ	7	6-10 years			
	Walls - Concrete Block	Boiler Room Corridor	1,814	SF	7	10+ years			
	Ceiling - Exposed	Door 3 Dock Corridor	550	SF	7	10+ years			
	Doors - Steel Doors incl hw	Door 3 Dock Corridor	2	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	Door 3 Dock Corridor	550	SF	7	10+ years			
	Lighting - Pendent/Surface	Door 3 Dock Corridor	4	EA	7	6-10 years			
	Walls - Concrete Block	Door 3 Dock Corridor	993	SF	7	10+ years			
Safety									
-	Camera Viewing Station	1st Floor	4	EA	7	6-10 years			
	Metal Detector	1st Floor	2	EA	7	10+ years			
						•			



Category : Interior Building : Addition

Category : Interior			Building : Addition							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Security Cameras	1st Floor	21	EA	7	6-10 years				
<u>Stairs</u>										
	Ceiling - Lay-in	North Stair Tower	283	SF	6	6-10 years				
	Ceiling - Plaster/Drywall	North Stair Tower	155	SF	6	10+ years				
	Ceiling - Splined	North Stair Tower	281	SF	6	6-10 years				
	Floor - Tile	North Stair Tower	610	SF	6	10+ years				
	Handrails	North Stair Tower	96	LF	7	10+ years				
	Lighting - Lay-in	North Stair Tower	2	EA	7	6-10 years				
	Lighting - Pendent/Surface	North Stair Tower	5	EA	6	6-10 years				
	Stairs - Rubber	North Stair Tower	45	LF	6	6-10 years				
	Walls - Concrete Block	North Stair Tower	110	SF	6	10+ years				
	Walls - Masonry	North Stair Tower	1,428	SF	6	10+ years				
	Walls - Plaster/Drywall	North Stair Tower	150	SF	6	10+ years				
	Ceiling - Lay-in	South Stair Tower	283	SF	6	6-10 years				
	Ceiling - Plaster/Drywall	South Stair Tower	155	SF	6	10+ years				
	Ceiling - Splined	South Stair Tower	281	SF	6	6-10 years				
	Floor - Tile	South Stair Tower	610	SF	6	6-10 years				
	Handrails	South Stair Tower	96	LF	7	10+ years				
	Lighting - Lay-in	South Stair Tower	2	EA	6	6-10 years				
	Lighting - Pendent/Surface	South Stair Tower	5	EA	6	6-10 years				
	Stairs - Rubber	South Stair Tower	45	LF	6	6-10 years				
	Walls - Concrete Block	South Stair Tower	110	SF	6	10+ years				
	Walls - Masonry	South Stair Tower	1,428	SF	6	10+ years				
	Walls - Plaster/Drywall	South Stair Tower	150	SF	6	10+ years				
	Ceiling - Lay-in	Stair 8 Gym	600	SF	6	10+ years				
	Floor - Tile	Stair 8 Gym	18	SF	7	10+ years				
	Handrails	Stair 8 Gym	40	LF	7	10+ years				
	Lighting - Lay-in	Stair 8 Gym	1	EA	7	6-10 years				
	Stairs - Tile	Stair 8 Gym	20	LF	7	10+ years				
	Walls - Concrete Block	Stair 8 Gym	1,500	SF	7	10+ years				
	Ceiling - Lay-in	Stair 9 Gym	600	SF	6	10+ years				
	Floor - Tile	Stair 9 Gym	18	SF	7	10+ years				
	Handrails	Stair 9 Gym	40	LF	7	10+ years				
	Lighting - Lay-in	Stair 9 Gym	1	EA	7	6-10 years				
	Stairs - Tile	Stair 9 Gym	20	LF	7	10+ years				
	Walls - Concrete Block	Stair 9 Gym	1,500	SF	7	10+ years				
	Ceiling - Exposed	Stairs down to basement	600	SF	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Stairs down to basement	600	SF	7	10+ years				
	Handrails	Stairs down to basement	39	LF	7	10+ years				
	Lighting - Pendent/Surface	Stairs down to basement	2	EA	7	10+ years				
	Stairs - Concrete	Stairs down to basement	37	LF	7	10+ years				
	Walls - Concrete Block	Stairs down to basement	800	SF	7	10+ years				
	Trails Colloidte Block	Otalia down to basement	000	01	,	TOT years				





Category : Interior	Building : Addition						
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments					
Vertical Conveyance							
Elevator - Hydraulic Elevator	1st Floor	1 EA 6 6-10 years					

Campus Name: Morgan Park HS Page: 73 of 81 Assessment Date: 08/22/2023



Category : Exterior Building : Modular

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	1		-			·	
	Exterior Doors - Exterior Steel Door	Center	1	EA	7	10+ years	Blocked off
	Exterior Doors - Exterior Steel Door	North	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	South	1	EA	7	10+ years	
	Exterior Stairs - Wood	South	24	LF	7	10+ years	
	Ramp Handrail - Wood_Ramp Handrail	South	125	LF	7	10+ years	
	Ramps - Concrete	South	12	LF	7	10+ years	
	Ramps - Wood Ramp	South	50	LF	7	10+ years	
	Stair Handrail - Wood_Stair Handrail	South	30	LF	7	10+ years	
_Foundati	on						
	Foundation - Masonry	Entire Building	125	LF	7	10+ years	
	Superstructure - Steel	Entire Building	575	SF	7	10+ years	
Roof Sys	stem						
,	Roof - Metal	Main Roof	575	SF	6	10+ years	No roof access
	Roof Structure - Steel / Metal Deck/	Main Roof	575	SF	7	10+ years	
	Concrete Topping					•	
_Walls							
	Canopy - Metal	Entire Building	24	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,250	SF	7	10+ years	

Category : Electrical Building : Modular

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	4	0-1 year	Exit Sign above the middle egress door is inappropriate since the door is unable to be opened; it is blocked on the interior with a refrigerator, and blocked on the exterior with a fixed railing.
Dower D	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	Exit Signs are of an obsolete design and are not functional.
_Power D	vistribution						
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	





Category : Mechanical			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Heating	Devices						
ŭ	Cabinet Heaters - With Electric Coil	1st Floor	1	EA	7	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	2	0-1 year	Vintage units are nonfunctional.
_Tempera	ature Control						
	Electric Thermostat	1st Floor	1	EA	6	6-10 years	

**Category : Classroom Building: Modular** 

J				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #Drivers Ed trai (Other Instructional Use)						
	AC Units	1st Floor	2	EA	7	2-5 years	
	Casework	1st Floor	12	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	570	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	570	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	630	SF	7	6-10 years	



Category : Site Building : Site

Jacogo	ry . Oite			ununig	. 5.10	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	item - Type	Location	Quantity	OCIVI	Naiik	Replacement	Comments
_Athletic							
	Lighting	North	5	EA	7	10+ years	
	Metal Bleachers	North	400	LF	7	10+ years	Replaced
	Scoreboard	North	1	EA	7	10+ years	
	Surface - Synthetic including exc & retention	North	82,000	SF	7	10+ years	Replaced
	Sand Pit	North of Football	700	SF	7	10+ years	
	Surface - Synthetic	North of Football	9,000	SF	7	10+ years	
	Lighting	Northeast	4	EA	7	10+ years	New
	Surface - Synthetic including exc & retention	Northeast	43,490	SF	7	10+ years	Replaced
	Surface - Synthetic including exc & retention	Northeast	10	SF	4	0-1 year	Damaged.
	Lighting	Northwest	4	EA	4	1-2 years	Does not work.
	Surface - Asphalt	Northwest	17,000	SF	4	0-1 year	Cracks throughout. 1/2 of tennis courts became part of drivers ed lot.
	Surface - Natural	Northwest Practice field	94,000	SF	6	10+ years	
	Surface - Synthetic	Pole Vault -South of Football	9,700	SF	7	10+ years	
	Dug out	Southeast	4	EA	6	10+ years	Corrected quantity
	Lighting	Southeast	5	EA	4	0-1 year	Not working
	Surface - Natural	Southeast	151,983	SF	7	10+ years	Repaired
_Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	24	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	2	EΑ	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	39	EA	7	10+ years	
_Fencing							
· ·	Fencing - Chain Link	Entire Site	3,300	LF	6	10+ years	Recalculated all fencing quantities
	Fencing - Chain Link	Entire Site	525	LF	6	2-5 years	Recalculated all fencing quantities
	Fencing - Guard Rail	Entire Site	25	LF	6	10+ years	3 1
	Fencing - New Standard Ornamental	Entire Site	3,500	LF	7	10+ years	Recalculated all fencing quantities
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	140	LF	7	10+ years	Recalculated all fencing quantities
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	240	LF	6	6-10 years	Recalculated all fencing quantities
Landsca	pe						
'	Benches	Entire Site	12	EA	6	10+ years	
	Landscape - Grass	Entire Site	207,689	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	56,291	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	839	SF	5	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	100	SF	4	0-1 year	Crumbling
	Parkway trees	Entire Site	30	EΑ	7	10+ years	New trees on south
	Planting Beds/ Area	Entire Site	9,856	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	792	SF	7	10+ years	
	Retaining Wall - Masonry	Entire Site	100	SF	6	6-10 years	
	- ,					-	



Category : Site		Building : Site							
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Trash Receptacles	Entire Site	17	EA	7	10+ years	Combined quantities		
Parking	Lot								
·	Concrete Curbs	East: drive and loading Staff only	730	LF	7	10+ years			
	Surface - Asphalt	East: drive and loading Staff only	7,100	SF	6	10+ years			
	Surface - Asphalt	East: drive and loading Staff only	300	SF	4	1-2 years	Potholes		
	Surface - Concrete	East: drive and loading Staff only	1,680	SF	7	10+ years			
	Trash Compactor	East: drive and loading Staff only	. 1	EA	7	10+ years			
	Trash Enclosure - Chain Links	East: drive and loading Staff only	520	SF	7	10+ years			
	Surface - Asphalt	North East- Loading Area / Parking	14,000	SF	7	10+ years	Repaved		
	Concrete Curbs	Northwest Drivers Ed	800	ĹF	7	10+ years	Lot expanded		
	Lighting - Pole Mounted	Northwest Drivers Ed	5	EA	7	10+ years	New		
	Surface - Asphalt	Northwest Drivers Ed	31,300	SF	7	10+ years	Lot expanded and repaved		
	Vehicular Screening	Northwest Drivers Ed	230	LF	7	10+ years	New		
	Concrete Curbs	Southwest - Main Parking Lot	2,450	LF	7	10+ years	New		
	Interior Plantings	Southwest - Main Parking Lot	350	LF	7	10+ years			
	Lighting - Pole Mounted	Southwest - Main Parking Lot	8	EA	7	10+ years			
	Surface - Asphalt	Southwest - Main Parking Lot	747,000	SF	7	10+ years	Reconfigured and rebuilt		
	Surface - Concrete	Southwest - Main Parking Lot	57,964	SF	5	10+ years			
	Vehicular Screening	Southwest - Main Parking Lot	560	LF	7	10+ years			
Sidewall	ks								
<u> </u>	Sidewalks - Internal Walks	Entire Site	353	LF	6	10+ years			
	Sidewalks - Internal Walks	Entire Site	100	LF	4	1-2 years	Crumbling, cracked, poor drainage		
	Sidewalks - Perimeter Sidewalks	Entire Site	55,900	SF	7	10+ years	3, 1 11 11, 11 11 11 11		
	Sidewalks - Perimeter Sidewalks	Entire Site	50	SF	4	1-2 years	Heaved, cracked, sunken		
Signage									
	Flag Pole - Flag Pole	West and South	1	EA	7	10+ years			
	Marquee - Free Standing Back lighted w/	West and South	1	EA	7	6-10 years			
	Monument - Building Mounted Cut Letter Sign	West and South	2	EA	7	10+ years			

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Definitions** 

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Morgan Park HS Page: 78 of 81 Assessment Date: 08/22/2023



**Classroom Summary** 

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	intollada coago	Noom Location	Hambon	Traine or	(0.)	700	71.00	Clop	
Art Room	Art Room	3rd Floor	351	342	1,116	240	16	N	N
Band Room	Band Room	1st Floor	106	106	2,385	150	75	N	N
Band Room	Regular Classroom	1st Floor	101	101	1,022	216	18	N	N
Computer Lab	Regular Classroom	1st Floor	130	130	868	156	12	N	Y
Computer Lab	Regular Classroom	1st Floor	132	132	1,176	104	8	N	N
Counseling Room	Regular Classroom	3rd Floor	324	324	335	50	3	N	N
Faculty Lounge	Regular Classroom	1st Floor	120	120	980	150	75	N	N
Laboratory/Shop	Science	3rd Floor	357	357	1,200	240	24	N	N
Music Room	Regular Classroom	1st Floor	103	103	978	216	75	N	N
Office	Regular Classroom	2nd Floor	209	248	523	114	9	N	N
Other Instructional Use	Regular Classroom	1st Floor	126	126	2,060	0	0	N	N
Regular Classroom	Regular Classroom	1st Floor	122	122	660	150	75	N	N
Regular Classroom	Regular Classroom	1st Floor	153	153	1,112	150	74	N	N
Regular Classroom	Regular Classroom	1st Floor	155	155	581	110	7	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	1,022	216	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	252	728	220	8	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	250	787	108	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	673	124	8	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	665	108	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	246	702	25	2	N	N
Regular Classroom	Regular Classroom	2nd Floor	222	222	662	100	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	224	224	599	100	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	605	186	16	.,	
Regular Classroom	Regular Classroom	2nd Floor	228	228	876	81	7	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	230	230	511	54	5	N	N
Regular Classroom	Regular Classroom	2nd Floor	251	242	1,116	240	16	N	N
Regular Classroom	Regular Classroom	2nd Floor	253	240	840	186	16	N	N
Regular Classroom	Regular Classroom	2nd Floor	255	238	599	100	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	256	236	599	100	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	257	234	599	186	16	N	N
Regular Classroom	Regular Classroom	2nd Floor	259	259	919	162	15	N	N
Regular Classroom	Regular Classroom	2nd Floor	322	322	650	120	8	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	354	1,035	240	16	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	850	210	14	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	352	728	120	8	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	841	150	9	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	806	120	8	N	N
Regular Classroom	Regular Classroom	3rd Floor	308A	308B	673	124	8	N	N

Campus Name: Morgan Park HS Page: 79 of 81 Assessment Date: 08/22/2023



Regular Classroom

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	308B	308A	673	124	8		
Regular Classroom	Regular Classroom	3rd Floor	310	310	504	90	6	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	500	90	6	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	479	75	5	N	N
Regular Classroom	Regular Classroom	3rd Floor	330	330	574	60	8	N	N
Regular Classroom	Regular Classroom	3rd Floor	359	359	863	180	12	N	N
Regular Classroom	Regular Classroom	Mechanical Room	328	328	880	150	10	N	N
Science	Regular Classroom	3rd Floor	355	340	1,200	272	16	N	N
Science	Science	3rd Floor	326	321	1,127	210	14	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	309	348	950	150	8	N	N
Special Program	Regular Classroom	3rd Floor	304	304	461	70	15	N	N
Store Room	Autoshop	1st Floor	128 auto shop	128	810	0	0		
Store Room	Fitness Room	Basement	026		1,970	0	0		
Weight	Weight	1st Floor	102	102	2,214	150	75	N	N
Building : Modular		14.5			570				
Other Instructional Use	Other Instructional Use	1st Floor	Drivers Ed trai	Drivers Ed Trai	570	0	0	N	N
Building : Addition									
Regular Classroom	Computer Lab	3rd Floor	323	323	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	221	221	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	223	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	225	225	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	229	268	803	160	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	233	233	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	235	235	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	237	237	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	239	239	758	136	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	241	241	758	136	28	N	N
			0.40			400		†	

243

245

247

315

317

319

321

243

245

247

315

317

319

321

758

758

758

758

758

967

758

136

136

102

136

136

170

136

28

28

21

28

28

35

28

Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν

2nd Floor

2nd Floor

2nd Floor

3rd Floor

3rd Floor

3rd Floor

3rd Floor

Regular Classroom

Regular Classroom Regular Classroom

Regular Classroom

Regular Classroom

Regular Classroom

Regular Classroom



**Classroom Summary** 

Olassi com caminary									
Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	325	325	758	136	28	N	N
Regular Classroom	Regular Classroom	3rd Floor	339	339	758	136	28	N	N
Regular Classroom	Science Lab Level 1	2nd Floor	231	231	758	136	28	N	N
Science	Science	3rd Floor	331	331	1,354	238	49	N	N
Science	Science	3rd Floor	337	337	1,164	204	42	N	N
Science	Science	3rd Floor	341	341	1,164	204	42	N	N
Science	Science	3rd Floor	347	347	1 354	204	42	N	N