

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1884	3	47,355
Addition	1910	3	36,291
Campus Total			83,646

			Building : Main				
			Recommend				
Quantity	UOM	Rank	Replacement	Comments			
1	EA	6	6-10 years				
2	EA	6	6-10 years				
2	EA	6	6-10 years				
2	EA	6	6-10 years				
1	EA	7	6-10 years				
21	LF	6	6-10 years				
25	LF	6	10+ years				
1	EA	5	1-2 years	Rust damage			
cape) 1	EA	6	6-10 years				
cape) 1	EA	6	10+ years				
cape) 1	EA	6	6-10 years				
cape) 4	LF	7	10+ years				
ape) 1	EA	6	6-10 years				
ape) 1	EA	6	10+ years				
ape) 6	EA	6	6-10 years				
ape) 4	LF	7	10+ years				
1	EA	6	6-10 years				
2	EA	6	6-10 years				
2	EA	6	6-10 years				
2	EA	6	6-10 years				
1	EA	6	6-10 years				
1	EA	6	6-10 years				
2	EA	6	10+ years	Changed to match current			
	1 2 2 2 1 2 2 1 25 1 25 1 25 1 25 1 25	1 EA 2 EA cape) 1 EA cape) 1 EA ape) 1 EA ape) 4 LF ape) 4 LF 1 EA 2 2 EA 1 3 EA 1	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	1 EA 6 6-10 years 2 EA 7 6-10 years 2 EA 7 6-10 years 2 EA 6 6-10 years 25 LF 6 10+ years 25 LF 6 10+ years cape) 1 EA 6 6-10 years cape) 1 EA 6 6-10 years cape) 1 EA 6 6-10 years ape) 1 EA 6 6-10 years ape) 4 LF 7 10+ years ape) 4 LF 7 10+ years 2 EA 6 6-10 years 2 EA 6 <td< td=""></td<>			



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations
	Exterior Doors - Exterior Steel Door	R1 (Roof Door)	1	EA	7	10+ years	Newly added
	Exterior Stairs - Concrete	R1 (Roof Door)	3	LF	7	10+ years	Newly added
Fire Esc	ape						
	Exterior Doors - Exterior Steel Door	Facade - SW	2	EA	6	10+ years	
	Exterior Doors - Side lite	Facade - SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Facade - SW	2	EA	6	10+ years	
	Fire Escape	Facade - SW	77	LF	6	6-10 years	
	Paints	Facade - SW	77	LF	5	10+ years	
Foundat	ion						
	Foundation - Masonry	Entire Building	476	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	47,355	SF	7	10+ years	
ighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	16	EA	7	6-10 years	New lighting Quantity changed to match current observations
Roof Sys	stem						
-	Access Ladder - Metal	Roof #1	2	EA	7	10+ years	Added to match current observatio
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #1	85	LF	5	6-10 years	
	Coping - Terra Cotta	Roof #1	266	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #1	45	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof #1	266	LF	7	10+ years	
	Roof - Modified Bitumen	Roof #1	4,392	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof #1	4,392	SF	6	10+ years	
	Access Ladder - Metal	Roof #2	1	ĒA	7	10+ years	
	Coping - Terra Cotta	Roof #2	158	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #2	125	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof #2	128	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof #2	30	LF	7	10+ years	
	Roof - Modified Bitumen	Roof #2	3,225	SF	7	10+ years	
	Roof Hatch - Metal	Roof #2	0,220	EA	7	10+ years	
	Roof Structure - Heavy Timber	Roof #2	3,225	SF	6	10+ years	
	Access Ladder - Metal	Roof #3	0,220	EA	7	10+ years	
	Coping - Terra Cotta	Roof #3	168	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #3	125	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof #3	125	LF	6 7	•	
	Parapet - 16 - 30 Height Parapet - Parapet < 16" Height			LF	7	10+ years	
		Roof #3	30			10+ years	
	Roof - Modified Bitumen	Roof #3	3,000	SF	7	10+ years	
	Roof Hatch - Metal	Roof #3	1	EA	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
Ŭ				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Roof Structure - Heavy Timber	Roof #3	3,000	SF	7	10+ years	
	Access Ladder - Metal	Roof #4	1	EA	7	10+ years	Added to match current observation
	Coping - Metal	Roof #4	100	LF	7	10+ years	
	Coping - Terra Cotta	Roof #4	298	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof #4	150	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof #4	125	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof #4	103	LF	7	10+ years	
	Roof - Metal	Roof #4	1,330	SF	6	6-10 years	Quantity changed to match current
			1,000	01	Ū	o ro youro	observations
	Roof - Modified Bitumen	Roof #4	3,418	SF	7	10+ years	0030174110113
	Roof Structure - Heavy Timber	Roof #4	4,748	SF	7	10+ years	
	Rool Structure - Heavy Himber	R001 #4	4,740	3F	'	TOT years	
Walls							
	Cornice - Metal Projecting	Entire Building	1,510	LF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	19,131	SF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	60	SF	4	1-2 years	Open joints/Cracking
	Exterior Walls - Stone-Cut	Entire Building	3,145	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	630	SF	6	10+ years	
		g		•	Ū	. e . yeu.e	
Windows							
	Guard - Guards perforated	Entire Building	1,700	SF	6	6-10 years	
	Lintels - Brick	Entire Building	11	LF	6	10+ years	
	Lintels - Steel	Entire Building	168	LF	6	10+ years	
	Lintels - Stone	Entire Building	440	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,202	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Security System - CCTV	Entire Building	47,355	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	47,355	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	17	EA	6	6-10 years	
	Stairs Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	6,591	SF	6	10+ years	
	Stairs			SF	U	IUT years	
	Emergency A/C Power - Students Toilets	Entire Building	1,080	SF	6	10+ years	
	Automatic Transfer Switch	Mechanical Room	· 1	EA	7	10+ years	
				EA	5	,	



Calego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
1ain Se	rvice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	47,355	SF	7	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Ala	m						
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Entire Building	47,355	SF	6	10+ years	
	Fire Alarm_System	Entire Building	47,355	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
		Ū.				-	
Pump R	com Assembly						
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	7	6-10 years	
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	
Sprinkle	System						
Sprinkle	5	Entire Building	47,355	SF	6	10+ vears	
Sprinkle	Combination Wet and Dry Sprinkler System		47,355 47,355			10+ years 1-2 years	Sprinkle head over 40 years old
Sprinkle	5	Entire Building Entire Building Entire Building	47,355 47,355 47,355	SF SF SF	6 4 6	10+ years 1-2 years 10+ years	Sprinkle head over 40 years old
	Combination Wet and Dry Sprinkler System Sprinkler Heads Sprinkler Piping	Entire Building	47,355 47,355	SF SF	4 6	1-2 years	Sprinkle head over 40 years old
	Combination Wet and Dry Sprinkler System Sprinkler Heads	Entire Building	47,355 47,355	SF	4 6	1-2 years	Sprinkle head over 40 years old
Catego	Combination Wet and Dry Sprinkler System Sprinkler Heads Sprinkler Piping	Entire Building	47,355 47,355	SF SF	4 6	1-2 years 10+ years	Sprinkle head over 40 years old
Catego Group	Combination Wet and Dry Sprinkler System Sprinkler Heads Sprinkler Piping ry : Mechanical	Entire Building Entire Building	47,355 47,355 B	SF SF uilding	4 6 : Main	1-2 years 10+ years Recommend	· ·
Catego Group	Combination Wet and Dry Sprinkler System Sprinkler Heads Sprinkler Piping ry : Mechanical Item - Type	Entire Building Entire Building	47,355 47,355 B	SF SF uilding	4 6 : Main	1-2 years 10+ years Recommend	· ·



Catego	ry : Mechanical		В	uilding	: Main		
3				U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Fan Coil Unit- Celing Mounted - Electric	206 Conference Room B	1	EA	7	10+ years	206 Conference Room B
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Zone Dampers	Mechanical Room	22	EA	7	10+ years	
	Zone Dampers	Mechanical Room	5	EA	7	10+ years	
Boiler Sy	vetems						
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	6	10+ years	
	Pressure Boiler - 76 - 100 HP						
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	1	EA	6	10+ years	
	Condensate Pump	Boiler Room	1	EA	6	10+ years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	7	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	6	10+ years	
	Steam Traps	Boiler Room	25	EA	5	6-10 years	
Heating	Devices						
	Unit Heater - Electric	Boiler Room	1	EA	7	10+ years	
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Radiators - Steam	Entire Building	3	EA	6	10+ years	
	Radiators - Steam	Entire Building	5	EA	5	6-10 years	
	Fin Tube - Electric	Entire Building	10	LF	5	2-5 years	
Tompor	ature Control						
тепфек	DDC System	Entire Building	47,355	SF	5	6-10 years	
	Electric Thermostat	Entire Building	47,355	EA	5 6	6-10 years	
	Thermostats - DDC	Entire Building	27	EA	6	6-10 years	
			21	LA	0	0-10 years	
Ventilati							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	7	10+ years	



NUR S	Schools					1	231 S Damen AVENUE, Chicago, IL 6060
Catego	ry : Mechanical		B	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Exhaust Fans- Roof Mounted - Less than	Entire Building	2	EA	7	10+ years	
	500 CFM	-				-	
	Roof Mounted Duct Work	Entire Building	120	LF	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
	· · · · ·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate						•	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	2-5 years	
					0	2 0 yours	
Dinina							
Piping	Demestic Diving List Mater Datum Li	Entine Duildin -	17 055	0-	^	10	
	Domestic Piping-Hot Water Return Lines	Entire Building	47,355	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	47,355	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	47,355	SF	6	10+ years	
	Fixtures		17.055	05	•	10	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	47,355	SF	6	10+ years	
	(Horizontal Lines)	Factors Dudidia a	47.055	05	0	10	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	47,355	SF	6	10+ years	
	(Risers)		17.055	05	•	10	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	47,355	SF	6	10+ years	
	(from Risers to Fixtures)	Factors Dudidia a	47.055	05	0	10	
	Sanitary Piping	Entire Building	47,355	SF	6	10+ years	
	Storm Piping	Entire Building	47,355	SF	5	6-10 years	
	Vent Piping	Entire Building	47,355	SF	6	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	7	10+ years	
	Pumps - Sump-Simplex	Boiler Room	1	EA	6	6-10 years	
						,	
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	102B Basement	110	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	102B Basement	1	EA	7	10+ years	
	Floor - Tile	102B Basement	110	SF	6	6-10 years	Area over tile floor
	Lighting - Pendent/Surface	102B Basement	2	EA	7	6-10 years	
	Power Distribution	102B Basement	4	EA	7	10+ years	
	Walls - Plaster/Drywall	102B Basement	200	SF	6	6-10 years	
	Walls - Plaster/Drywall	102B Basement	30	SF	5	1-2 years	Peeling paint
	AC Unit	203- Staff Lounge	1	EA	7	6-10 years	<u> </u>
	Ceiling - Plaster/Drywall	203- Staff Lounge	328	SF	6	6-10 years	
	g · · · · · · · · · · · · · · · · ·		320	0.	Ŭ	e .e jouro	



Catego	ry : Room		В	uilding	: Main		
-	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	203- Staff Lounge	2	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	203- Staff Lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	203- Staff Lounge	330	SF	7	6-10 years	New floor
	Lighting - Pendent/Surface	203- Staff Lounge	4	EA	7	6-10 years	
	Power Distribution	203- Staff Lounge	18	EA	7	10+ years	
	Walls - Plaster/Drywall	203- Staff Lounge	608	SF	6	6-10 years	
	Work SInk	203- Staff Lounge	1	EA	7	10+ years	
	AC Unit	206	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	206	390	SF	7	6-10 years	
	Doors - Transom Window	206	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	206	2	EA	7	10+ years	
	Floor - Tile	206	390	SF	7	6-10 years	
	Lighting - Pendent/Surface	206	8	EA	7	6-10 years	
	Power Distribution	206	10	EA	7	10+ years	
	Walls - Plaster/Drywall	206	808	SF	7	10+ years	
	AC Unit	206A Conference Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	206A Conference Room	320	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	206A Conference Room	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	206A Conference Room	320	SF	6	6-10 years	
	Lighting - Pendent/Surface	206A Conference Room	8	EA	7	6-10 years	
	Power Distribution	206A Conference Room	10	EA	7	10+ years	
	Walls - Plaster/Drywall	206A Conference Room	696	SF	7	10+ years	
	Ceiling - Plaster/Drywall	206B Conference Room	281	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	206B Conference Room	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	206B Conference Room	281	SF	6	6-10 years	
	Lighting - Pendent/Surface	206B Conference Room	6	EA	7	6-10 years	
	Power Distribution	206B Conference Room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	206B Conference Room	896	SF	7	10+ years	
	Ceiling - Plaster/Drywall	302B	144	SF	6	6-10 years	
	Doors - Transom Window	302B	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	302B	1	EA	7	10+ years	
	Floor - Wood	302B	144	SF	5	2-5 years	
	Lighting - Pendent/Surface	302B	1	EA	7	6-10 years	
	Power Distribution	302B	4	EA	7	10+ years	
	Storage/ Closet	302B	8	SF	7	10+ years	
	Walls - Plaster/Drywall	302B	180	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	302B	144	SF	6	6-10 years	
	AC Unit	308B	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	308B	144	SF	7	6-10 years	
	Doors - Transom Window	308B	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	308B	1	EA	7	10+ years	
	Floor - Wood	308B	144	SF	7	10+ years	
	Lighting - Pendent/Surface	308B	1	EA	7	6-10 years	
	Power Distribution	308B	4	EA	7	10+ years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Storage/ Closet 308B 8 SF 10+ vears 7 Walls - Plaster/Drvwall 308B 180 SF 7 10+ years Walls - Vinyl Coated Gypsum Panel 308B 144 SF 7 10+ years Ceiling - Plaster/Drywall SF 402B 134 6 6-10 years SF 5 Ceiling - Plaster/Drywall 402B 10 1-2 years Peeling paint SF Doors - Transom Window 402B 6 6 6-10 years Doors - Wood Doors inclu hw 402B ΕA 6 6-10 years 1 SF Floor - Wood 402B 144 5 2-5 years Lighting - Pendent/Surface 402B 1 EΑ 7 6-10 years Power Distribution 402B 4 EΑ 7 10+ vears Storage/ Closet 402B 8 SF 7 10+ vears Walls - Plaster/Drywall 402B 170 SF 6 6-10 years Walls - Plaster/Drywall 402B SF 4 1-2 years 10 Panel separating from wall SF Walls - Vinyl Coated Gypsum Panel 402B 144 6 6-10 years AC Unit ΕA 7 6-10 years 403b 1 Ceiling - Plaster/Drywall 380 SF 7 403b 6-10 years SF Ceiling - Plaster/Drvwall 403b 4 5 1-2 years Peeling paint SF Doors - Transom Window 403b 6 6 6-10 years Doors - Wood Doors inclu hw 403b EΑ 7 10+ vears 1 Floor - Wood 403b 384 SF 6 6-10 years Lighting - Pendent/Surface 403b 6 ΕA 7 6-10 years 7 10+ years Power Distribution 403b 6 EΑ SF Walls - Plaster/Drvwall 403b 395 6 6-10 years SF Walls - Vinyl Coated Gypsum Panel 403b 296 6 6-10 years Ceiling - Plaster/Drywall Engineer's Office 106 SF 6 6-10 years SF Ceiling - Plaster/Drvwall Engineer's Office 10 4 1-2 vears Water damage Doors - Wood Doors inclu hw 6 **Engineer's Office** EA 6-10 years 1 Floor - Tile Engineer's Office 116 SF 6 6-10 years Lighting - Pendent/Surface 7 Engineer's Office 2 EΑ 6-10 years **Power Distribution** Engineer's Office 4 ΕA 7 10+ years Walls - Plaster/Drywall Engineer's Office 282 SF 6 6-10 years AC Unit Main office (204) 2 EΑ 7 6-10 vears SF Ceiling - Plaster/Drywall Main office (204) 785 6 6-10 years Doors - Transom Window Main office (204) SF 6 6-10 years 6 Doors - Wood Doors inclu hw Main office (204) 1 EΑ 6 6-10 years SF 7 Floor - Tile Ceramic/ Porcelain Main office (204) 785 6-10 years New floor Lighting - Pendent/Surface Main office (204) 8 EΑ 7 6-10 years **Power Distribution** Main office (204) 8 ΕA 7 10+ years Walls - Plaster/Drywall Main office (204) 1,844 SF 6 6-10 years Kitchen Ceiling - Plaster/Drywall SF Basement 1,030 6 6-10 years Doors - Wood Doors inclu hw **Basement** 2 ΕA 6 6-10 years SF Floor - Tile **Basement** 1,025 6 6-10 years



Catego	ry : Room		В	uilding	: Main		231 S Damen AVENUE, Chicago, IL 60606
- 0 -	-			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Basement	5	SF	4	1-2 years	Cracks in tiles
	Lighting - Pendent/Surface	Basement	8	EA	7	6-10 years	
	Storage/ Closet	Basement	86	SF	7	10+ years	
	Walls - Concrete Block	Basement	396	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Basement	900	SF	6	6-10 years	
unch &	Multipurpose Room						
	AC Unit	104 Multipurpose	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	104 Multipurpose	756	SF	5	1-2 years	Cracked paint throughout
	Doors - Wood Doors inclu hw	104 Multipurpose	1	EA	6	6-10 years	Cracked paint throughout
	Floor - Tile	104 Multipurpose	756	SF	6	6-10 years	
		· · ·	750	EA	7	•	
	Lighting - Pendent/Surface	104 Multipurpose	-			6-10 years	
	Walls - Masonry	104 Multipurpose	970	SF	6	6-10 years	
MDF_ID							
	Doors - Transom Window	4th Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Finishes	4th Floor	200	SF	7	10+ years	
	Window AC Unit	4th Floor	1	EA	7	6-10 years	
	Doors - Transom Window	Adjacent 208	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Adjacent 208	1	EA	7	10+ years	
	Finishes	Adjacent 208	200	SF	7	10+ years	
	Other Cooling Unit	Adjacent 208	1	EA	7	6-10 years	Ductless split system.
	Window AC Unit	Adjacent 208	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Storage Room	2nd Floor	60	SF	7	10+ years	
	Storage Room	2nd Floor	175	SF	7	10+ years	
	Storage Room	3rd Floor	140	SF	7	10+ years	
	Boiler Room	Basement	1,660	SF	7	10+ years	
	Coal Room	Basement	455	SF	7	10+ years	
	Janitor's Closet	Basement	200	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,096	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	372	SF	7	10+ years	
	Storage Room	Basement	63	SF	7	10+ years	
	Vaults	Basement	370	SF	7	10+ years	
Jaatraar	_						
Restroor	Accessories	102B Basement	38	SF	7	6 10 years	
		102B Basement		SF		6-10 years	
	Ceiling - Exposed		38		6	6-10 years	
	Doors - Transom Window	102B Basement	1	SF	6	6-10 years	
	Floor - Tile	102B Basement	38	SF	4	1-2 years	Cracked and missing tiles througho
	Lavatory	102B Basement	1	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	102B Basement	1	EA	7	6-10 years	
	Lighting - Wall Mounted	102B Basement	1	EA	7	6-10 years	
	Partitions	102B Basement	1	EA	5	2-5 years	
	Walls - Plaster/Drywall	102B Basement	40	SF	6	6-10 years	
	Walls - Plaster/Drywall	102B Basement	10	SF	5	1-2 years	Water Damaged
	Water Closet	102B Basement	1	EA	7	10+ years	
	Accessories	2nd Floor	144	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	144	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	144	SF	7	6-10 years	New floor
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	310	SF	6	6-10 years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	3rd Floor	144	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	144	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	144	SF	7	6-10 years	New floor
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years	
	Partitions	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	310	SF	6	6-10 years	
	Water Closet	3rd Floor	1	EA	7	10+ years	
	Accessories	Basement Women's adjacent Boiler	650	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Women's adjacent Boiler	650	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement Women's adjacent Boiler	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Women's adjacent Boiler	650	SF	6	6-10 years	
	Floor Drain	Basement Women's adjacent Boiler	1	EA	7	10+ years	
	Hand Dryer	Basement Women's adjacent Boiler	2	EA	7	6-10 years	
	Lavatory	Basement Women's adjacent Boiler	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Women's adjacent Boiler	10	EA	7	6-10 years	
	Partitions	Basement Women's adjacent Boiler	7	EA	7	10+ years	
	Student Lockers - Two Tiers	Basement Women's adjacent Boiler	36	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement Women's adjacent Boiler	600	SF	6	6-10 years	
	Walls - Structural Glazed Tile	Basement Women's adjacent Boiler	416	SF	6	6-10 years	
	Water Closet	Basement Women's adjacent Boiler	7	EA	7	10+ years	
	Accessories	Boiler Room	18	SF	7	6-10 years	
	Ceiling - Exposed	Boiler Room	18	SF	6	6-10 years	



Catego	ory : Room		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	Boiler Room	1	EA	6	6-10 years	
	Floor - Tile	Boiler Room	18	SF	5	2-5 years	
	Lavatory	Boiler Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Boiler Room	1	EA	7	6-10 years	
	Walls - Masonry	Boiler Room	55	SF	6	6-10 years	
	Water Closet	Boiler Room	1	EA	7	10+ years	
	Accessories	Boys near 108	430	SF	7	6-10 years	
	Ceiling - Exposed	Boys near 108	430	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Boys near 108	1	EA	7	10+ years	
	Floor - Concrete	Boys near 108	50	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Boys near 108	380	SF	6	6-10 years	
	Floor Drain	Boys near 108	1	EA	7	10+ years	
	Hand Dryer	Boys near 108	2	EA	7	6-10 years	
	Lavatory	Boys near 108	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys near 108	7	EA	7	6-10 years	
	Partitions	Boys near 108	2	EA	7	10+ years	
	Urinals	Boys near 108	4	EA	7	10+ years	
	Urinals	Boys near 108	1	EA	5	1-2 years	Out of order
	Walls - Plaster/Drywall	Boys near 108	550	SF	6	6-10 years	
	Walls - Structural Glazed Tile	Boys near 108	350	SF	6	6-10 years	
	Water Closet	Boys near 108	2	EA	7	10+ years	

Category · Classroom

Catego	Category : Classroom			uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Location	Quantity		Nalik	Replacement	Comments
Classroo	om #102 (Other Instructional Use)	_					
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	540	SF	6	10+ years	
	Doors - Transom Window	Basement	1	SF	6	10+ years	
	Floor - Tile	Basement	540	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	4	EA	7	6-10 years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Walls - Masonry	Basement	650	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	280	SF	6	10+ years	
Classroo	om #108 (Weight)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	795	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	Basement	795	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	8	EA	7	6-10 years	
	Storage/ Closet	Basement	173	SF	7	10+ years	
	Walls - Masonry	Basement	1,146	SF	6	10+ years	



Catego	ry : Classroom		В	Building : Main			
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassror	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	600	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	600	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	50	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	920	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	230	SF	6	6-10 years	
			200	0	0	0-10 years	
assroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	56	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	740	SF	5	2-5 years	Floor is worn in some areas
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	38	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	65	SF	7	10+ years	Locked no access
	Walls - Plaster/Drywall	2nd Floor	1,235	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	310	SF	6	6-10 years	
lassroc	m #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	56	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	735	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Cracks by wall ceiling intersection
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	740	SF	7	6-10 years	Floor is new
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	1 Ioon is new
	Marker Board	2nd Floor	65	LA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,235	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	310	SF	6	6-10 years	
		21011001	510	0	0	0-10 years	
assroc	m #207 (Science)						
	AC Units	2nd Floor	2	EA	7	10+ years	
	Casework	2nd Floor	72	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	7	SF	5	1-2 years	Cracks at wall ceiling intersection



Catego	ry : Classroom		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	777	SF	6	6-10 years	
	Gas Line	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	65	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	777	SF	7	10+ years	
	Storage/ Closet	2nd Floor	65	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,050	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	265	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	6-10 years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Wood	2nd Floor	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒA	7	6-10 years	
	Marker Board	2nd Floor	60	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,235	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	310	SF	6	6-10 years	
lassroo	om #301 (Science Lab Level 1)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	810	SF	6	6-10 years	
	Gas Line	3rd Floor	7	ĒA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	47	LF	7	6-10 years	
	Science Lab Elements	3rd Floor	810	SF	7	10+ years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,230	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	310	SF	6	6-10 years	
	Work Sink	3rd Floor	7	EA	7	10+ years	

Classroom #302 (Regular Classroom)



Catego	ry : Classroom		B	uilding	: Main		231 S Damen AVENUE, Chicago, IL 6060
calego				Bunding . Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
p	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	805	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years	
	Floor - Wood	3rd Floor	805	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒA	7	6-10 years	
	Marker Board	3rd Floor	38	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,250	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	315	SF	6	6-10 years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	3	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	355	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Cracks
	Doors - Transom Window	3rd Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	360	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	790	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	225	SF	6	6-10 years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	513	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	513	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	875	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	250	SF	6	6-10 years	
Classroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
				SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	740	0			
	Ceiling - Plaster/Drywall Doors - Transom Window	3rd Floor 3rd Floor	740 9				
	Doors - Transom Window	3rd Floor	740 9 1	SF	7	10+ years	
			9				



Catego	ry : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	34	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,235	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	310	SF	6	6-10 years	
lassroc	m #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	56	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ vears	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	6-10 years	
	Floor - Tile	3rd Floor	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	65	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,235	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	310	SF	6	6-10 years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
						, e e g e e e	
assroc	m #307 (Regular Classroom) AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	735	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor		SF	-		Creake in well exiling interpettion
	Doors - Transom Window		5	SF	5 7	1-2 years	Cracks in wall ceiling intersection
		3rd Floor	9			10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	65	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,235	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	310	SF	6	6-10 years	
lassroc	m #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	60	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,235	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	310	SF	6	6-10 years	



ategory : Classroom			В	uilding	: Main		
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	4th Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	805	SF	7	6-10 years	
	Doors - Transom Window	4th Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Eye Wash Station	4th Floor	1	EA	7	10+ years	
	Floor - Wood	4th Floor	805	SF	6	6-10 years	
	Gas Line	4th Floor	16	EA	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	12	EA	7	6-10 years	
	Marker Board	4th Floor	38	LF	7	6-10 years	
	Science Lab Elements	4th Floor	805	SF	7	10+ years	
	Science Lab Fume Hood	4th Floor	1	EA	7	10+ years	
	Science Lab Shower	4th Floor	1	EA	7	10+ years	
	Storage/ Closet	4th Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,245	SF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,245	SF	5	1-2 years	Cracks
	Walls - Vinyl Coated Gypsum Panel	4th Floor	315	SF	5 6	6-10 years	Clacks
	Work Sink	4th Floor	9	EA	7	•	
	WOR SINK	401 F1001	9	EA	1	10+ years	
assroc	m #402 (Regular Classroom)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	805	SF	7	6-10 years	
	Doors - Transom Window	4th Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Wood	4th Floor	805	SF	6	6-10 years	
	Lighting - Pendent/Surface	4th Floor	12	ĒA	7	6-10 years	
	Marker Board	4th Floor	38	LF	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,250	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	4th Floor	315	SF	6	6-10 years	
locaroa	m #403 (Regular Classroom)						
1222100	AC Units	4th Floor	4	Γ.	7	6.10 years	
			1	EA	7	6-10 years	
	Ceiling - Lay-in	4th Floor	740	SF	7	6-10 years	
	Doors - Transom Window	4th Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	6-10 years	
	Floor - Wood	4th Floor	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	4th Floor	12	EA	7	6-10 years	
	Marker Board	4th Floor	57	LF	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,230	SF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	5	SF	5	1-2 years	Crack in wall to wall intersection
	Walls - Vinyl Coated Gypsum Panel	4th Floor	310	SF	6	6-10 years	
assroo	m #404 (Regular Classroom)						
200100	AC Units	4th Floor	1	EA	7	6-10 years	
		4111 11001	I	EA	1	0-10 years	



							231 S Damen AVENUE, Chicago, IL 60608
Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	4th Floor	740	SF	6	6-10 years	
	Doors - Transom Window	4th Floor	36	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	6-10 years	
	Floor - Wood	4th Floor	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	4th Floor	12	EA	7	6-10 years	
	Marker Board	4th Floor	57	LF	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,225	SF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	10	SF	5	1-2 years	Water damage
	Walls - Vinyl Coated Gypsum Panel	4th Floor	310	SF	6	6-10 years	-
Classroo	om #405 (Regular Classroom)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	4th Floor	740	SF	6	6-10 years	
	Doors - Transom Window	4th Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Wood	4th Floor	740	SF	6	6-10 years	
	Lighting - Pendent/Surface	4th Floor	12	EA	7	6-10 years	
	Marker Board	4th Floor	65	LF	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,215	SF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	20	SF	5	1-2 years	Large crack in corner
	Walls - Vinyl Coated Gypsum Panel	4th Floor	310	SF	6	6-10 years	Large clack in comer
		40111001	510	0	0	0-10 years	
Classroo	om #406 (Regular Classroom)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	4	LF	6	6-10 years	
	Ceiling - Lay-in	4th Floor	864	SF	6	6-10 years	
	Doors - Transom Window	4th Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	ĒA	7	10+ years	
	Floor - Wood	4th Floor	864	SF	6	6-10 years	
	Lighting - Pendent/Surface	4th Floor	12	EA	7	6-10 years	
	Marker Board	4th Floor	84	LF	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	985	SF	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	4th Floor	250	SF	6	6-10 years	
Classroo	om #407 (Regular Classroom)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	64	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	772	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	5	SF	5	1-2 years	Cracks at wall/ceiling
	Doors - Transom Window	4th Floor	9	SF	7	10+ years	oraons at wail/ceiling
	Doors - Wood Doors inclu hw	4th Floor	9	EA	6	6-10 years	
	Floor - Wood Doors Inclu hw	4th Floor	777	SF	6	6-10 years	
	Lighting - Pendent/Surface	4th Floor	12	EA	6 7	•	
	Lighting - Fenden/Sunace		12	ËA	1	6-10 years	



1231 S Damen AVENUE, Chicago, IL 60608 **Building : Main Category : Classroom** Recommend Group Quantity Item - Type Location UOM Rank Replacement Comments Marker Board 4th Floor LF 65 6-10 years 7 Storage/ Closet 4th Floor 65 SF 7 10+ years Locked and blocked by furniture Walls - Plaster/Drywall 4th Floor 1,025 SF 6 6-10 years Walls - Vinyl Coated Gypsum Panel 300 SF 6 4th Floor 6-10 years Classroom #408 (Regular Classroom) AC Units 4th Floor 1 ΕA 7 6-10 years LF 4 Casework 4th Floor 6 6-10 years Ceiling - Plaster/Drywall 772 SF 7 4th Floor 6-10 years Ceiling - Plaster/Drywall SF 4th Floor 5 5 1-2 years Water damage Doors - Transom Window 4th Floor 9 SF 7 10+ years Doors - Wood Doors inclu hw 4th Floor 1 EΑ 7 10+ years Floor - Wood 4th Floor 777 SF 6-10 years 6 Lighting - Pendent/Surface 4th Floor 12 ΕA 7 6-10 years Marker Board 4th Floor 64 LF 7 6-10 years Storage/ Closet 4th Floor 175 SF 7 10+ years Blocked by furniture Walls - Plaster/Drywall SF 4th Floor 1.095 6 6-10 years Walls - Plaster/Drywall SF 5 4th Floor 5 1-2 years Water damage SF Walls - Vinyl Coated Gypsum Panel 300 4th Floor 6 6-10 years

Building : Main

Category : Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	2nd Floor	1,702	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,702	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	7	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	7	10+ years	
	Student Lockers - Two Tiers	2nd Floor	90	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,240	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,702	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,702	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	9	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	151	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,240	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	1,000	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	4th Floor	1	EA	7	10+ years	
	Floor - Wood	4th Floor	1,000	SF	6	6-10 years	
	Lighting - Pendent/Surface	4th Floor	[′] 11	EA	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	3,900	SF	6	6-10 years	
	Ceiling - Lay-in	Ground Floor and vestibules	1,172	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Ground Floor and vestibules	2,061	SF	6	6-10 years	



Category : InteriorBuilding : MainGroupItem - TypeLocationQuantityUOMRankReplacementDoors - Transom WindowGround Floor and vestibules118SF66-10 yearDoors - Wood Doors include hwGround Floor and vestibules1EA710+ yearsDrinking Fountains - Single FountainGround Floor and vestibules1EA710+ yearsFloor - Asphalt FloorGround Floor and vestibules1,741SF66-10 yearFloor - Asphalt FloorGround Floor and vestibules1,452SF76-10 yearFloor - Tile/SheetGround Floor and vestibules1,452SF76-10 yearLighting - Lay-inGround Floor and vestibules10EA76-10 yearLighting - Pendent/SurfaceGround Floor and vestibules110EA66-10 yearStudent Lockers - Two TiersGround Floor and vestibules110EA66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF51-2 yearsSafetyCamera Viewing Station1st Floor1EA76-10 yearMetal Detector1st Floor1EA710+ yearsSecurity Cameras1st Floor1EA76-10 year	nt Comments
GroupItem - TypeLocationQuantityUOMRankReplacementDoors - Transom WindowGround Floor and vestibules118SF66-10 yearDoors - Wood Doors include hwGround Floor and vestibules1EA66-10 yearDrinking Fountains - Single FountainGround Floor and vestibules1EA710+ yearsFloor - Asphalt FloorGround Floor and vestibules1,741SF66-10 yearFloor - Asphalt FloorGround Floor and vestibules1,452SF76-10 yearFloor - Tile/SheetGround Floor and vestibules1,452SF76-10 yearLighting - Lay-inGround Floor and vestibules10EA76-10 yearLighting - Pendent/SurfaceGround Floor and vestibules10EA76-10 yearStudent Lockers - Two TiersGround Floor and vestibules110EA66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules10SF51-2 yearsSafetyCamera Viewing Station1st Floor1EA76-10 yearMetal Detector1st Floor1EA710+ years	nt Comments
Doors - Transom WindowGround Floor and vestibules118SF66-10 yearDoors - Wood Doors include hwGround Floor and vestibules4EA66-10 yearDrinking Fountains - Single FountainGround Floor and vestibules1EA710+ yearsFloor - Asphalt FloorGround Floor and vestibules1,741SF66-10 yearFloor - Asphalt FloorGround Floor and vestibules1,741SF66-10 yearFloor - Asphalt FloorGround Floor and vestibules40SF41-2 yearsFloor - Tile/SheetGround Floor and vestibules1,452SF76-10 yearLighting - Lay-inGround Floor and vestibules10EA76-10 yearLighting - Pendent/SurfaceGround Floor and vestibules10EA76-10 yearStudent Lockers - Two TiersGround Floor and vestibules110EA66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules10SF51-2 yearsSafetyCamera Viewing StationMetal Detector1st Floor1EA76-10 yearNetal Detector1st Floor1EA710+ years	
Drinking Fountains - Single FountainGround Floor and vestibules1EA710+ yearsFloor - Asphalt FloorGround Floor and vestibules1,741SF66-10 yearFloor - Asphalt FloorGround Floor and vestibules40SF41-2 yearsFloor - Tile/SheetGround Floor and vestibules1,452SF76-10 yearLighting - Lay-inGround Floor and vestibules6EA76-10 yearLighting - Pendent/SurfaceGround Floor and vestibules10EA76-10 yearStudent Lockers - Two TiersGround Floor and vestibules110EA66-10 yearWalls - MasonryGround Floor and vestibules2,893SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules10SF51-2 yearsSafetyCamera Viewing Station1st Floor1EA76-10 yearMetal Detector1st Floor1EA710+ years	
Floor - Asphalt FloorGround Floor and vestibules1,741SF66-10 yearFloor - Asphalt FloorGround Floor and vestibules40SF41-2 yearsFloor - Tile/SheetGround Floor and vestibules1,452SF76-10 yearLighting - Lay-inGround Floor and vestibules6EA76-10 yearLighting - Pendent/SurfaceGround Floor and vestibules10EA76-10 yearStudent Lockers - Two TiersGround Floor and vestibules110EA66-10 yearWalls - MasonryGround Floor and vestibules2,893SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules10SF51-2 yearsSafetyCamera Viewing Station1st Floor1EA76-10 yearMetal Detector1st Floor1EA710+ years	
Floor - Åsphalt FloorGround Floor and vestibules1,741SF66-10 yearFloor - Asphalt FloorGround Floor and vestibules40SF41-2 yearsFloor - Tile/SheetGround Floor and vestibules1,452SF76-10 yearLighting - Lay-inGround Floor and vestibules6EA76-10 yearLighting - Pendent/SurfaceGround Floor and vestibules10EA76-10 yearStudent Lockers - Two TiersGround Floor and vestibules110EA66-10 yearWalls - MasonryGround Floor and vestibules2,893SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules10SF51-2 yearsSafetyCamera Viewing Station1st Floor1EA76-10 yearMetal Detector1st Floor1EA710+ years	
Floor - Tile/SheetGround Floor and vestibules1,452SF76-10 yearLighting - Lay-inGround Floor and vestibules6EA76-10 yearLighting - Pendent/SurfaceGround Floor and vestibules10EA76-10 yearStudent Lockers - Two TiersGround Floor and vestibules110EA66-10 yearWalls - MasonryGround Floor and vestibules2,893SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules10SF51-2 yearsSafetyCamera Viewing StationMetal Detector1st Floor1EA76-10 year1EA710+ years	
Lighting - Lay-in Lighting - Pendent/SurfaceGround Floor and vestibules6EA76-10 yearStudent Lockers - Two TiersGround Floor and vestibules10EA76-10 yearWalls - MasonryGround Floor and vestibules110EA66-10 yearWalls - Plaster/DrywallGround Floor and vestibules2,893SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules10SF51-2 yearsSafetyCamera Viewing Station1st Floor1EA76-10 yearMetal Detector1st Floor1EA710+ years	Cracked and chipped
Lighting - Pendent/Surface Ground Floor and vestibules 10 EA 7 6-10 year. Student Lockers - Two Tiers Ground Floor and vestibules 110 EA 6 6-10 year. Walls - Masonry Ground Floor and vestibules 2,893 SF 6 6-10 year. Walls - Plaster/Drywall Ground Floor and vestibules 1,435 SF 6 6-10 year. Walls - Plaster/Drywall Ground Floor and vestibules 10 SF 5 1-2 years Safety Camera Viewing Station 1st Floor 1 EA 7 6-10 year. Metal Detector 1st Floor 1 EA 7 10+ years	
Student Lockers - Two TiersGround Floor and vestibules110EA66-10 yearWalls - MasonryGround Floor and vestibules2,893SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 yearWalls - Plaster/DrywallGround Floor and vestibules10SF51-2 yearsSafetyCamera Viewing Station1st Floor1EA76-10 yearMetal Detector1st Floor1EA710+ years	
Walls - Masonry Walls - Plaster/DrywallGround Floor and vestibules Ground Floor and vestibules2,893 1,435SF66-10 year 6Walls - Plaster/DrywallGround Floor and vestibules1,435SF66-10 year 6SafetyCamera Viewing Station Metal Detector1st Floor1EA76-10 year 61EA710+ years	
Walls - Plaster/Drywall Ground Floor and vestibules 1,435 SF 6 6-10 year Walls - Plaster/Drywall Ground Floor and vestibules 10 SF 5 1-2 years Safety Camera Viewing Station 1st Floor 1 EA 7 6-10 year Metal Detector 1 st Floor 1 EA 7 10+ years	
Walls - Plaster/Drywall Ground Floor and vestibules 10 SF 5 1-2 years Safety	
Safety Camera Viewing Station 1st Floor 1 EA 7 6-10 year Metal Detector 1 EA 7 10+ years	
Camera Viewing Station1st Floor1 EA76-10 yearMetal Detector1st Floor1 EA710+ years	Cracked paint
Camera Viewing Station1st Floor1 EA76-10 yearMetal Detector1st Floor1 EA710+ years	
Metal Detector 1st Floor 1 EA 7 10+ years	
. ,	
Stairs	
Ceiling - Exposed East 810 SF 6 6-10 year	
Floor - Asphalt East 460 SF 6 6-10 year	
Handrails East 156 LF 7 10+ years	
Lighting - Pendent/Surface East 10 EA 7 6-10 year	
Stairs - Asphalt East 76 LF 6 6-10 year	
Walls - Plaster/Drywall East 1,310 SF 6 6-10 year	
Ceiling - Exposed West Stair 810 SF 6 6-10 year	
Floor - Asphalt West Stair 460 SF 6 6-10 year	
Handrails West Stair 156 LF 7 10+ years	
Lighting - Pendent/Surface West Stair 10 EA 7 6-10 year	
Stairs - Asphalt West Stair 50 LF 6 6-10 year	
Stairs - Asphalt West Stair 6 LF 4 1-2 years	Cracks and deterioration on treads
Walls - Plaster/DrywallWest Stair1,310SF66-10 year	
Vertical Conveyance	
Elevator - Hydraulic Elevator East side of Main 1 EA 6 6-10 year	



Category : Exterior Building : Addition Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Entrance #3 E FΑ Entrance Control - Audio and Video 1 6 2-5 years Exterior Doors - Exterior FRP Door #3 E FΑ 4 6 6-10 years #3 E 7 Power Door Operator and Controls 1 EΑ 6-10 years Exterior Doors - Exterior Steel Door #4 E 1 ΕA 6 6-10 years 1 F Exterior Stairs - Concrete #4 E 3 6 10+ years 3 ΕA 6-10 years Exterior Doors - Exterior Steel Door #5 Exit S 6 LF Exterior Stairs - Concrete #5 Exit S 9 6 6-10 years Exterior Doors - Exterior FRP Door #6 W 5 ΕA 6 6-10 vears Exterior Doors - Transom Lite #6 W 6 EΑ 6 6-10 years LF Exterior Stairs - Concrete #6 W 18 6 10+ vears Exterior Doors - Exterior Steel Door #7 W 3 EΑ 6 6-10 years 9 LF 6 Exterior Stairs - Concrete #7 W 10+ years Foundation LF 7 Foundation - Masonry Entire Building 508 10+ years 50 LF Foundation - Masonry Entire Building 6 1-2 years Water damage Superstructure - Heavy Timber Entire Building 34,914 SF 7 10+ years SF Superstructure - Slab on Grade Entire Building 1,377 7 10+ years Liahtina Exterior Lighting - Wall Mounted Entire Building 14 ΕA 7 6-10 years New Roof System Access Ladder - Metal 2 ΕA 7 Roof #5 10+ years Quantity changed to match current observations Coping - Terra Cotta LF Roof #5 428 7 10+ vears LF Downspouts - Interior Downspouts Roof #5 150 6 6-10 vears Parapet - 16" - 30" Height LF 7 10+ years Roof #5 128 Parapet - Parapet < 16" Height Roof #5 300 LF 7 10+ years Roof - Modified Bitumen Roof #5 9,588 SF 7 10+ years 2 ΕA Roof Hatch - Metal Roof #5 7 10+ years Quantity changed to match current observations SF Roof Structure - Heavy Timber Roof #5 9.588 7 10+ years Coping - Stone Roof #6 185 LF 7 10+ years LF Downspouts - Interior Downspouts Roof #6 40 6 10+ vears Parapet - 16" - 30" Height LF Roof #6 15 7 10+ years Parapet - Parapet < 16" Height 170 LF 6 10+ years Roof #6 Roof - Modified Bitumen SF 7 Roof #6 3,415 10+ years Roof Structure - Heavy Timber Roof #6 3.415 SF 7 10+ years LF Coping - Stone Roof #7 90 6 10+ years LF **Downspouts - Exterior Downspouts** 6 Roof #7 15 6-10 years



Catego	ry : Exterior		R	uilding	· Additi		231 S Damen AVENUE, Chicago, IL 60608
Oalcyo				unung	. Addition	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.00p	Parapet - 16" - 30" Height	Roof #7	90	LF	7	10+ years	
	Roof - Metal	Roof #7	150	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof #7	612	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof #7	612	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof #7	150	SF	7	10+ years	
	Concrete Topping		100	01		ior youro	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	172	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	1,400	LF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	20	SF	7	10+ years	Fixed
	Exterior Walls - Brick	Entire Building	17,965	SF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	100	SF	3	0-1 year	Open joints on the east side
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	200	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	2,315	SF	6	10+ years	
Vindows							
	Guard - Guards perforated	Entire Building	2,525	SF	6	6-10 years	
	Lintels - Steel	Entire Building	242	LF	6	10+ years	
	Lintels - Steel	Entire Building	29	LF	5	6-10 years	
	Lintels - Steel	Entire Building	9	LF	4	0-1 year	Rust damage
	Lintels - Stone	Entire Building	380	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,250	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System						
yer	Security System - CCTV	Entire Building	36,291	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	36,291	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	9	EA	6	6-10 years	
	Stairs	-	-		-	-	
	Emergency Battery Packs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,032	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	3,941	SF	6	10+ years	



<u> </u>	Schools	1231 S Damen AVENUE, Chicago, IL 60608					
Catego	ry : Electrical		Building : Addition				
Crown	Hom Tune	Leastion	Quantity	UOM	Denk	Recommend	Commonto
Group	Item - Type Emergency A/C Power - Students Toilets	Location Entire Building	Quantity 2,877	SF	Rank 6	Replacement 10+ years	Comments
	Emergency A/C Fower - Students Tollets	Entite Building	2,077	SF	0	10+ years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection	В	uilding	: Additi	on		
Ŭ						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m Fire Alarm Strobe Lights	Entire Building	36,291	SF	6	10+ years	
					-		
	Fire Alarm_System	Entire Building	36,291	SF	6	10+ years	
Sprinkler	System						
	Combination Wet and Dry Sprinkler System	Entire Building	36,291	SF	6	10+ years	
	Sprinkler Heads	Entire Building	36,291	SF	7	10+ years	
	Sprinkler Piping	Entire Building	36,291	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Hand	lling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	225	LF	6	10+ years	
	Zone Dampers	Mechanical Room	23	EA	6	6-10 years	
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	5	2-5 years	
	Gas Heating and DX Cooling Coil - 5 - 10 tons				-	,	
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	5	2-5 years	
	Gas Heating and DX Cooling Coil - 5 - 10 tons		·		0	2 0 yours	
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	5	2-5 years	
	Gas Heating and DX Cooling Coil - 5 - 10 tons		I	ĽA	5	2-5 years	



Building : Addition Category : Mechanical Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Roof Top Unit-Single Zone-Roof Mounted-ΕA Roof 5 2-5 years 1 Gas Heating and DX Cooling Coil - 5 - 10 tons Boiler Systems Condensate Pump 1 FΑ 5 Entire Building 6-10 years Piping - Condensate Pipe- Steel Entire Building 500 LF 5 6-10 years LF 5 Piping - Steam Pipe- Steel Entire Building 500 6-10 years ΕA 5 Steam Traps Entire Building 30 6-10 years Heating Devices Radiators - Steam 2nd Floor 1 ΕA 5 10+ years Paint required. Wall Heater - Electric Entire Building 3 ΕA 6 6-10 years Temperature Control DDC System Entire Building 36,291 SF 5 6-10 years Electric Thermostat Entire Building 4 ΕA 6 10+ years 2 ΕA 6-10 years Thermostats - DDC Entire Building 7 Thermostats - DDC Entire Building 25 ΕA 6 10+ years Ventilation Exhaust Fans- Roof Mounted - 500 - 1500 Roof 1 ΕA 6 10+ years CFM Exhaust Fans- Roof Mounted - Less than Roof 2 FΑ 6 10+ years 500 CFM

Category : Plumbing

Catego	alegory : Plumbing			Building : Addition				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Piping								
	Domestic Piping-Hot Water Return Lines	Entire Building	36,291	SF	6	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	36,291	SF	6	10+ years		
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	36,291	SF	6	10+ years	Pipes inside the wall	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	36,291	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	36,291	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	36,291	SF	6	10+ years	Pipes inside the wall	
	Sanitary Piping	Entire Building	36,291	SF	6	10+ years	Pipes inside the wall	
	Storm Piping	Entire Building	36,291	SF	6	10+ years	-	
	Vent Piping	Entire Building	36,291	SF	6	10+ years		

Building · Addition



Catego	ry : Plumbing		B	uilding	: Additi	on	
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0-1			-				
Catego	ry : Room		В	ullaing	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	7 1	Eocation	Quantity		INDIIK	Replacement	Comments
Administ	rative Suites/Offices		055	05	•	10	
	Ceiling - Plaster/Drywall	111 Conference room	255	SF	6	10+ years	
	Doors - Wood Doors inclu hw	111 Conference room	2	EA	6	10+ years	
	Floor - Tile	111 Conference room	255	SF	7	10+ years	
	Lighting - Pendent/Surface	111 Conference room	2	EA	7	6-10 years	
	Power Distribution	111 Conference room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	111 Conference room	584	SF	6	10+ years	
	Walls - Plaster/Drywall	111 Conference room	2	SF	5	1-2 years	Hole in wall
	Ceiling - Lay-in	118	498	SF	6	10+ years	
	Doors - Side-lite	118	10	SF	6	10+ years	
	Doors - Transom Window	118	5	SF	6	10+ years	
	Doors - Wood Doors inclu hw	118	1	EA	6	10+ years	
	Floor - Wood	118	498	SF	6	10+ years	
	Lighting - Lay-in	118	8	EA	7	6-10 years	
	Power Distribution	118	32	EA	7	10+ years	
	Storage/ Closet	118	10	SF	7	10+ years	
	Walls - Plaster/Drywall	118	1,038	SF	6	10+ years	
	Ceiling - Lay-in	118 Teacher's Kitchen	103	SF	6	10+ years	
	Doors - Wood Doors inclu hw	118 Teacher's Kitchen	1	EA	6	10+ years	
	Floor - Wood	118 Teacher's Kitchen	103	SF	7	10+ years	
	Lighting - Lay-in	118 Teacher's Kitchen	3	EA	7	6-10 years	
	Power Distribution	118 Teacher's Kitchen	6	EA	6	10+ years	
	Walls - Plaster/Drywall	118 Teacher's Kitchen	275	SF	6	10+ years	
	Work Sink	118 Teacher's Kitchen	1	EA	7	10+ years	
	Ceiling - Lay-in	118A in room 118	133	SF	6	10+ years	
	Doors - Wood Doors inclu hw	118A in room 118	135	EA	6		
	Floor - Wood	118A in room 118	133	SF	7	10+ years 10+ years	
		118A in room 118	2	EA	7		
	Lighting - Lay-in		12	EA		6-10 years	
	Power Distribution	118A in room 118		SF	7	6-10 years	
	Storage/ Closet	118A in room 118	66		7	10+ years	
	Walls - Plaster/Drywall	118A in room 118	233	SF	6	10+ years	
	Ceiling - Lay-in	118B in room 118	76	SF	6	10+ years	
	Doors - Wood Doors inclu hw	118B in room 118	1	EA	6	10+ years	
	Floor - Wood	118B in room 118	76	SF	7	10+ years	
	Lighting - Lay-in	118B in room 118	2	EA	7	6-10 years	
	Power Distribution	118B in room 118	8	EA	7	10+ years	
	Walls - Plaster/Drywall	118B in room 118	203	SF	6	10+ years	
	Ceiling - Lay-in	118C in room 118	76	SF	6	10+ years	
	Doors - Wood Doors inclu hw	118C in room 118	1	EA	6	10+ years	
	Floor - Wood	118C in room 118	76	SF	7	10+ years	



atego	ry : Room		В	uilding	: Additi	on	
_				_		Recommend	
Foup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	118C in room 118	2	EA	7	6-10 years	
	Power Distribution	118C in room 118	8	EA	7	10+ years	
	Walls - Plaster/Drywall	118C in room 118	203	SF	6	10+ years	
ymnasi				05			
	Ceiling - Plaster/Drywall	1st Floor	3,941	SF	6	6-10 years	No occupancy signage
	Doors - Steel Doors incl hw	1st Floor	5	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Wood	1st Floor	3,941	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	EA	6	6-10 years	
	Scoreboards	1st Floor	1	EA	5	1-2 years	Not functioning
	Sound System	1st Floor	1	EA	5	6-10 years	-
	Stage	1st Floor	420	SF	6	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	10	LF	6	10+ years	
	Walls - Masonry	1st Floor	1,937	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,829	SF	6	10+ years	
unch &	Multipurpose Room						
	AC Unit	Servery in between rooms 211, 209	1	EA	7	6-10 years	No occupancy signage
	Ceiling - Plaster/Drywall	Servery in between rooms 211, 209	261	SF	6	10+ years	
	Doors - Transom Window	Servery in between rooms 211, 209	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Servery in between rooms 211, 209	1	EA	6	10+ years	
	Floor - Terrazzo	Servery in between rooms 211, 209	261	SF	6	10+ years	
	Lighting - Pendent/Surface	Servery in between rooms 211, 209	6	EA	7	6-10 years	
	Serving Line	Servery in between rooms 211, 209	10	LF	6	10+ years	
	Walls - Plaster/Drywall	Servery in between rooms 211, 209	597	SF	6	10+ years	
achani	-	,,			-	, en geene	
ecnant	cal/ Service Rooms Air Intake Plenums	1st Floor	150	SF	7	10+ years	
	Air Intake Plenums	1st Floor	110	SF	7	10+ years	
	Air Intake Plenums	1st Floor	287	SF	7	10+ years	
	Boiler Room	1st Floor	1,000	SF	7	10+ years	
	Janitor's Closet	1st Floor	29	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	650	SF	7	10+ years	
	Storage Room	1st Floor	13	SF	7	10+ years	
	Janitor's Closet	2nd Floor	28	SF	5	10+ years	
	Storage Room	2nd Floor	12	SF	5	10+ years	
				~-	_		
	Janitor's Closet	3rd Floor	24	SF SF	5	10+ years	



Catego	ry : Room		В	uilding	: Additi	on		
-			Recommend					
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Restrool	n							
	Accessories	1st floor boys	180	SF	7	6-10 years		
	Ceiling - Lay-in	1st floor boys	125	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st floor boys	55	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st floor boys	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st floor boys	180	SF	6	10+ years		
	Floor Drain	1st floor boys	1	EA	7	10+ years		
	Hand Dryer	1st floor boys	1	EA	7	6-10 years		
	Lavatory	1st floor boys	1	EA	6	10+ years		
	Lighting - Pendent/Surface	1st floor boys	4	EA	7	6-10 years		
	Partitions	1st floor boys	1	EA	7	10+ years		
	Urinals	1st floor boys	2	EA	6	10+ years		
	Walls - Concrete Block	1st floor boys	130	SF	6	10+ years		
	Walls - Masonry	1st floor boys	55	SF	6	10+ years		
	Walls - Plaster/Drywall	1st floor boys	228	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st floor boys	85	SF	6	10+ years		
	Water Closet	1st floor boys	1	EA	6	10+ years		
	Accessories	1st floor girls	195	SF	7	6-10 years		
	Ceiling - Lay-in	1st floor girls	165	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st floor girls	30	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st floor girls	2	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st floor girls	195	SF	6	10+ years		
	Floor Drain	1st floor girls	1	EA	7	10+ years		
	Hand Dryer	1st floor girls	1	EA	7	6-10 years		
	Lavatory	1st floor girls	1	EA	6	10+ years		
	Lighting - Pendent/Surface	1st floor girls	6	EA	7	6-10 years		
	Partitions	1st floor girls	5	EA	7	10+ years		
	Walls - Plaster/Drywall	1st floor girls	215	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st floor girls	230	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st floor girls	60	SF	6	10+ years		
	Water Closet	1st floor girls	5	EA	6	10+ years		
	Accessories	2nd Floor Staff Restroom	35	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor Staff Restroom	35	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor Staff Restroom	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor Staff Restroom	35	SF	7	10+ years		
	Lavatory	2nd Floor Staff Restroom	1	EA	6	10+ years		
	Lighting - Chandelier, Incandescent	2nd Floor Staff Restroom	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor Staff Restroom	1	EA	7	6-10 years		
	Partitions	2nd Floor Staff Restroom	1	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor Staff Restroom	70	SF	6	10+ years		
	Water Closet	2nd Floor Staff Restroom	1	EA	6	10+ years		
	Accessories	2nd floor boys	220	SF	7	6-10 years		
	Ceiling - Lay-in	2nd floor boys	155	SF	6	10+ years		
			100	5	0	ior years		



Catego	ry : Room		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd floor boys	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor boys	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys	220	SF	6	10+ years	
	Floor Drain	2nd floor boys	1	EA	7	10+ years	
	Hand Dryer	2nd floor boys	1	EA	7	6-10 years	
	Lavatory	2nd floor boys	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor boys	5	EA	7	6-10 years	
	Partitions	2nd floor boys	1	EA	7	10+ years	
	Urinals	2nd floor boys	4	EA	6	10+ years	
	Walls - Masonry	2nd floor boys	185	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd floor boys	210	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor boys	115	SF	6	10+ years	
	Water Closet	2nd floor boys	1	EA	6	10+ years	
	Accessories	2nd floor girls	195	SF	7	6-10 years	
	Ceiling - Lay-in	2nd floor girls	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor girls	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor girls	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls	195	SF	6	10+ years	
	Floor Drain	2nd floor girls	1	EA	7	10+ years	
	Hand Dryer	2nd floor girls	1	EA	7	6-10 years	
	Lavatory	2nd floor girls	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor girls	6	EA	7	6-10 years	
	Partitions	2nd floor girls	5	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor girls	215	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor girls	230	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd floor girls	60	SF	6	10+ years	
	Water Closet	2nd floor girls	5	EA	6	10+ years	
	Accessories	3rd Floor Staff Restroom	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Staff Restroom	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Staff Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Staff Restroom	35	SF	7	10+ years	
	Lavatory	3rd Floor Staff Restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor Staff Restroom	1	EA	7	6-10 years	
	Partitions	3rd Floor Staff Restroom	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor Staff Restroom	70	SF	6	10+ years	
	Water Closet	3rd Floor Staff Restroom	1	EA	6	10+ years	
	Accessories	3rd floor boys	220	SF	7	6-10 years	
	Ceiling - Lay-in	3rd floor boys	155	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd floor boys	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor boys	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys	220	SF	6	10+ years	
	Floor Drain	3rd floor boys	1	EA	7	10+ years	
	Hand Dryer	3rd floor boys	1	EA	7	6-10 years	
	Lavatory	3rd floor boys	1	EA	6	10+ years	



Catego	ry : Room		В	uilding	: Additio	on	
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd floor boys	5	EA	7	6-10 years	
	Partitions	3rd floor boys	1	EA	7	10+ years	
	Urinals	3rd floor boys	4	EA	6	10+ years	
	Walls - Masonry	3rd floor boys	185	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor boys	210	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd floor boys	115	SF	6	10+ years	
	Water Closet	3rd floor boys	1	EA	6	10+ years	
	Accessories	3rd floor girls	195	SF	7	6-10 years	
	Ceiling - Lay-in	3rd floor girls	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd floor girls	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor girls	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor girls	195	SF	6	10+ years	
	Floor Drain	3rd floor girls	1	EA	7	10+ years	
	Hand Dryer	3rd floor girls	1	EA	7	6-10 years	
	Lavatory	3rd floor girls	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor girls	6	EA	7	6-10 years	
	Partitions	3rd floor girls	5	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor girls	215	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd floor girls	230	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd floor girls	60	SF	6	10+ years	
	Water Closet	3rd floor girls	5	EA	6	10+ years	
	Accessories	Restroom in rm 118	78	SF	7	6-10 years	
	Ceiling - Lay-in	Restroom in rm 118	58	SF	6	10+ years	
	Ceiling - Lay-in	Restroom in rm 118	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in rm 118	1	EA	6	10+ years	
	Floor - Tile	Restroom in rm 118	78	SF	7	10+ years	
	Floor Drain	Restroom in rm 118	1	EA	7	10+ years	
	Lavatory	Restroom in rm 118	1	EA	6	10+ years	
	Lighting - Lay-in	Restroom in rm 118	1	EA	7	6-10 years	
	Walls - Concrete Block	Restroom in rm 118	55	SF	6	10+ years	
	Walls - Masonry	Restroom in rm 118	40	SF	6	10+ years	
	Walls - Plaster/Drywall	Restroom in rm 118	55	SF	6	10+ years	
	Walls - Structural Glazed Tile	Restroom in rm 118	40	SF	6	10+ years	
	Water Closet	Restroom in rm 118	1	EA	6	10+ years	

Category : Classroom

Building : Addition

5 7					Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroom #109 (Music Room)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	820	SF	6	10+ years	
Doors - Side-lite	1st Floor	10	SF	6	10+ years	
Doors - Transom Window	1st Floor	5	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	Building : Addition					
	-			_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Carpet	1st Floor	820	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Sound System	1st Floor	1	EA	7	10+ years			
	Storage/ Closet	1st Floor	10	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,250	SF	6	10+ years			
Classroo	m #110 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st Floor	470	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	155	SF	6	10+ years			
	Doors - Transom Window	1st Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Carpet	1st Floor	625	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years			
	Marker Board	1st Floor	20	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	837	SF	6	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classroo	m #113 (Music Room)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	23	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	820	SF	6	10+ years			
	Doors - Side-lite	1st Floor	10	SF	6	10+ years			
	Doors - Transom Window	1st Floor	5	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	820	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Sound System	1st Floor	1	EA	7	10+ years			
	Storage/ Closet	1st Floor	10	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,250	SF	6	10+ years			
lassroo	m #209 (Art Room)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	22	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Wood	2nd Floor	1,080	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	30	EA	7	6-10 years			
	Marker Board	2nd Floor	34	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,819	SF	6	10+ years			



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #210 (Special Program)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,270	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,270	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	26	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,735	SF	6	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	 11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,080	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	30	ĒA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,819	SF	6	10+ years	
			.,	•	Ū.	let yeare	
Classroo	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	420	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	420	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,005	SF	6	10+ years	
Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	420	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	420	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,005	SF	6	10+ years	
Classroo	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	AC UNITS		1	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Additi	on	
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	575	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	575	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,130	SF	6	10+ years	
lassror	om #309 (Regular Classroom)						
1233100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	575	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
					-	,	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	565	SF	6	10+ years	Or we had to be a superior of a leader
	Floor - Wood	3rd Floor	10	SF	4	1-2 years	Gaps between wood planks
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,130	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	575	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	570	SF	6	10+ years	
	Floor - Wood	3rd Floor	5	SF	4	1-2 years	Damaged wood planks
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	5
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,130	SF	6	10+ years	
Classroo	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	420	SF	6	10+ years	
	Doors - Transom Window	3rd Floor		SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	420	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	420	EA	7	6-10 years	
	Marker Board	3rd Floor	9 22		7	6-10 years	
	Walker Board Walls - Plaster/Drywall	3rd Floor	1,005	SF	6		
	waiis - Plastel/Drywaii	310 F1001	1,005	эг	0	10+ years	
Classroc	m #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	575	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	



Catego	ry : Classroom		B	uildina	: Additi	on	
Jacogo				anding		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	j	EA	6	10+ years	
	Floor - Wood	3rd Floor	575	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,130	SF	6	10+ years	
Classroo	om #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	420	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	10+ years	
	Floor - Wood	3rd Floor	420	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,005	SF	6	10+ years	
Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	420	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	420	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,005	SF	6	10+ years	
Classroo	om #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	575	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	575	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,130	SF	6	10+ years	
Classroo	om #316 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	420	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	420	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,005	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #317 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	575	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	575	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,130	SF	6	10+ years	
Classroo	m #318 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	575	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	575	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,130	SF	6	10+ years	
Catego	ry : Interior		В	uildina	: Additi	on	

Category : Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	1,948	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	8	SF	4	0-1 year	Water damage.
	Doors - Wood Doors include hw	1st Floor	6	EA	6	10+ years	-
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,956	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	9	EA	6	10+ years	
	Student Lockers - Two Tiers	1st Floor	97	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,622	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	200	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor East	1,020	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor East	8	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor East	1,020	SF	7	10+ years	
	Lighting - Lay-in	1st Floor East	6	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor East	24	EA	7	10+ years	
	Student Lockers - Two Tiers	1st Floor East	70	EA	7	10+ years	
	Walls - Masonry	1st Floor East	1,210	SF	7	10+ years	



Catego	ry : Interior		B	uilding	: Additi	on	
J	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor East	190	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,038	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	3	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	2,038	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	14	EA	6	10+ years	
	Student Lockers - Two Tiers	2nd Floor	223	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,038	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	3	EA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	2,038	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	14	EA	6	10+ years	
	Student Lockers - Two Tiers	3rd Floor	223	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,280	SF	6	10+ years	
Safety							
	Metal Detector	Entire building	1	EA	7	6-10 years	
	Security Cameras	Entire building	20	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North Stairs	723	SF	6	10+ years	
	Floor - Asphalt	North Stairs	366	SF	6	10+ years	
	Floor - Tile/Sheet	North Stairs	178	SF	7	10+ years	
	Handrails	North Stairs	130	LF	7	10+ years	
	Handrails	North Stairs	130	LF	7	10+ years	
	Handrails	North Stairs	132	LF	7	10+ years	
	Lighting - Pendent/Surface	North Stairs	4	EA	7	6-10 years	
	Stairs - Asphalt	North Stairs	60	LF	6	10+ years	
	Walls - Plaster/Drywall	North Stairs	1,533	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South Stairs	723	SF	6	10+ years	
	Floor - Asphalt	South Stairs	366	SF	6	10+ years	
	Handrails	South Stairs	132	LF	7	10+ years	
	i la lu alis						
		South Stairs	4	EA	7	6-10 vears	
	Lighting - Lay-in Stairs - Asphalt	South Stairs South Stairs	4 60	EA LF	7 6	6-10 years 10+ years	



Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	6-10 years	
Fencing							
	Fencing - Chain Link	Entire Site	310	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	955	LF	6	6-10 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	102	LF	6	2-5 years	
Landsca)e						
•	Benches	Entire Site	10	EA	7	10+ years	
	Landscape - Crushed Stone	Entire Site	500	SF	7	10+ years	
	Landscape - Grass	Entire Site	3,980	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	7,516	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	1,600	SF	6	10+ years	Quantities combined
	Landscape - Hardscape- Concrete	Entire Site	400	SF	4	0-1 year	Cracking/sinking. Quantity changed to match current observations
	Landscape - Hardscape- Pavers	Entire Site	200	SF	7	10+ years	
	Parkway trees	Entire Site	21	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	770	SF	6	10+ years	
	Trash Receptacles	Entire Site	9	EA	7	6-10 years	
Parking L	ot						
Ũ	Concrete Curbs	Entire Site	385	LF	6	10+ years	
	Interior Plantings	Entire Site	83	LF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	3	EA	7	10+ years	New
	Surface - Asphalt	Entire Site	27,441	SF	6	6-10 years	
	Surface - Concrete	Entire Site	792	SF	6	10+ years	
	Trash Enclosure - Chain Links	Entire Site	244	SF	5	6-10 years	Quantity changed to match current observations
Service (Garage						
	Service Garage - Free-Standing	East	1	SF	4	0-1 year	Extensive damage inside and outside the storage
Sidewalk							
	Sidewalks - Perimeter Sidewalks	Entire Site	7,580	SF	6	10+ years	
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter	Entire Site	3	EA	7	10+ years	



¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Deem	Floor Plan	A	Glazed	Operable		Crossert
Current Hoore	Intended Llogge	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window	Smart- Board
Current Usage Building : Main	Intended Usage	Room Location	Number	Number	(37)	Area	Area	Stop	Боаго
Other Instructional Use	Lunch Room	Basement	102	Lunch Room	540	24	4	N	N
Regular Classroom	Library	3rd Floor	306	206	740	96	4	N	N
Regular Classroom	Other Instructional Use	3rd Floor	303	208	360	36	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	101	600	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	101	740	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	102	740	96	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	105	740	96	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	202	805	120	60	N	N
		3rd Floor	302	202	513	60	30	N	N
Regular Classroom	Regular Classroom					96			
Regular Classroom	Regular Classroom	3rd Floor	305	205	740		48	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	209	740	96	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	208	740	96	48	N	N
Regular Classroom	Regular Classroom	4th Floor	402	302	805	120	60	N	N
Regular Classroom	Regular Classroom	4th Floor	403	303	740	36	18	N	N
Regular Classroom	Regular Classroom	4th Floor	404	304	740	60	30	N	N
Regular Classroom	Regular Classroom	4th Floor	405	305	740	96	48	N	N
Regular Classroom	Regular Classroom	4th Floor	406	306	864	96	48	N	N
Regular Classroom	Regular Classroom	4th Floor	407	307	777	120	60	N	N
Regular Classroom	Regular Classroom	4th Floor	408	308	777	96	48	N	N
Science	Regular Classroom	2nd Floor	207	107	777	120	60	N	N
Science Lab Level 1	Regular Classroom	3rd Floor	301	201	810	120	60	N	N
Science Lab Level 2	Regular Classroom	4th Floor	401	301	805	120	60	N	N
Weight	Store Room	Basement	108	Store Rm	795	108	48	N	N
Building : Addition			-			-			
Art Room	Regular Classroom	2nd Floor	209	209	1,080	190	95	N	N
Music Room	Regular Classroom	1st Floor	109	109	820	108	48	N	N
Music Room	Regular Classroom	1st Floor	113	113	820	108	48	N	Y
Regular Classroom	Art Room	1st Floor	110	110	625	81	12	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	1,080	190	95	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	420	60	24	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	420	60	24	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	575	84	36	N	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	575	84	36	N	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	575	84	36	N	Y
Regular Classroom	Regular Classroom	3rd Floor	311	311	420	60	24	N	Ý
Regular Classroom	Regular Classroom	3rd Floor	312	312	575	84	36	N	Ň
Regular Classroom	Regular Classroom	3rd Floor	313	313	420	60	24	N	N



Classroom Summary

	Intended Lineare	Room Location	Room Number	Floor Plan Room Number	Area	Glazed Window	Operable Window	Window	Smart- Board
Current Usage	Intended Usage	Room Location	numper	Number	(SF)	Area	Area	Stop	Боаго
Regular Classroom	Regular Classroom	3rd Floor	314	314	420	60	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	315	315	575	84	36	N	Y
Regular Classroom	Regular Classroom	3rd Floor	316	316	420	60	24	N	Y
Regular Classroom	Regular Classroom	3rd Floor	317	317	575	84	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	575	84	36	N	Y
Special Program	Regular Classroom	2nd Floor	210	210	1,270	132	60	N	N