

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1944	3	41,728
Addition	1958	3	41,503
Campus Total			83,231

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Entrance</u>							
	Entrance Control - Audio and Video	Entrance 7-SE	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 7-SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 7-SE	1	EA	6	10+ years	
	Exterior Stairs - Stone	Entrance 7-SE	56	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 7-SE	26	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 8-SW / Gym vestibule	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 8-SW / Gym vestibule	165	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 8-SW / Gym vestibule	20	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	Entrance 9-South / Basement Boiler	1	EA	4	1-2 years	Old, damaged door
	Exterior Stairs - Concrete	Entrance 9-South / Basement Boiler	60	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 9-South / Basement Boiler	30	LF	6	10+ years	
	Entrance Control - Audio and Video	Main Entrance 1-SW	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Main Entrance 1-SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Main Entrance 1-SW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Main Entrance 1-SW	110	LF	5	10+ years	
	Power Door Operator and Controls	Main Entrance 1-SW	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	Main Entrance 1-SW	150	LF	6	10+ years	
	Ramps - Concrete	Main Entrance 1-SW	65	LF	7	6-10 years	
	Ramps - Concrete	Main Entrance 1-SW	5	LF	5	1-2 years	Cracked concrete
	Stair Handrail - Steel_Stair Handrail	Main Entrance 1-SW	35	LF	6	10+ years	

Foundation

Foundation - Concrete	Entire Building	520	LF	7	10+ years
-----------------------	-----------------	-----	----	---	-----------

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Superstructure - Steel with Clay Tile Arch	Entire Building	41,728	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	1-2 years	Roof lighting doesn't work
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	10+ years	
Roof System							
	Access Ladder - Metal	Roof 1	3	EA	7	10+ years	
	Coping - Metal	Roof 1	445	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	119	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	1	LF	5	1-2 years	Missing strainers
	Parapet - Parapet < 16" Height	Roof 1	445	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 1	10,230	SF	6	10+ years	
	Roof Hatch - Metal	Roof 1	2	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	10,230	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 2	50	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 2	30	LF	5	10+ years	
	Coping - Metal	Roof 2	230	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	105	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 2	20	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 2	210	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 2	3,735	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	3,735	SF	7	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	130	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	10	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	15,125	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	800	SF	7	6-10 years	Did not find any deficiency
	Exterior Walls - Brick	Entire Building	100	SF	4	1-2 years	Open joints, deteriorated mortar, cracked brick.
	Exterior Walls - Concrete Block	Entire Building	590	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,175	SF	5	10+ years	
Windows							
	Clerestory - Glass Single-Pane	Entire Building	400	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	1,150	SF	6	10+ years	
	Lintels - Steel	Entire Building	160	LF	7	10+ years	
	Lintels - Steel	Entire Building	8	LF	6	10+ years	
	Lintels - Stone	Entire Building	183	LF	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Windows - Casement Steel	Entire Building	110	SF	5	2-5 years	
	Windows - Louver	Entire Building	40	SF	6	10+ years	
	Windows - Sash Lexan	Entire Building	2,515	SF	7	10+ years	

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Emergency System</u>							
	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Security System - CCTV	Entire Building	41,730	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	41,730	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	1	EA	2	6-10 years	Exit sign was replaced
	Emergency Battery Packs - Corridors and Stairs	Entire Building	23	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	1	EA	6	6-10 years	I just saw one battery backup fixture
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,908	SF	6	10+ years	

Main Service

Main Electrical Service - 1600 A	Electrical Room	1	EA	7	10+ years	
120/208/3PH						
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
PA System	Entire Building	41,730	SF	6	6-10 years	

Power Distribution

Lighting and Power Panels - 100 A	Electrical Room	1	EA	7	10+ years	
Lighting and Power Panels - 100 A	Electrical Room	2	EA	7	10+ years	
Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	2-5 years	
Lighting and Power Panels - Above 100 A	Electrical Room	2	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Electrical Room	4	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Electrical Room	2	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	7	6-10 years	Electrical panel was replaced 2022

Category : Fire Protection
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alarm</u>							
	Fire ALarm Anunciator	Entire Building	41,730	EA	6	6-10 years	

Category : Fire Protection
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Entire Building	41,730	SF	6	10+ years	
	Fire Alarm_System	Entire Building	41,730	SF	6	10+ years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Air Handling Systems

Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Entire Building	1	EA	5	6-10 years	
Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Entire Building	2	EA	5	6-10 years	
Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	
Air Intake	Mechanical Room	1	EA	5	10+ years	
Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	
Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	7	EA	6	10+ years	
Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	
Zone Dampers	Mechanical Room	24	EA	7	10+ years	

Boiler Systems

Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	6	10+ years	
Chemical Feed System	Boiler Room	1	EA	6	10+ years	
Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
Combustion Dampers	Boiler Room	3	EA	6	10+ years	
Condensate Pump	Boiler Room	1	EA	6	10+ years	
Condensate Pump	Boiler Room	1	EA	6	6-10 years	
Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	10+ years	
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	10+ years	
Piping - Condensate Pipe- Steel	Boiler Room	300	LF	6	10+ years	
Piping - Condensate Pipe- Steel	Boiler Room	160	LF	6	10+ years	
Piping - Steam Pipe- Steel	Boiler Room	160	LF	6	10+ years	
Piping - Steam Pipe- Steel	Boiler Room	300	LF	6	10+ years	
Steam Traps	Boiler Room	26	EA	5	6-10 years	

Heating Devices

Wall Heater - Electric	Entire Building	4	EA	5	2-5 years	
------------------------	-----------------	---	----	---	-----------	--

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Radiators - Steam	Entire Building	10	EA	5	6-10 years	
	Radiators - Steam	Entire Building	3	EA	5	6-10 years	
	Fin Tube - Electric	Entire Building	20	LF	6	10+ years	

Temperature Control

Pneumatic System	Entire Building	41,730	SF	7	6-10 years	
Thermostats - Pneumatic	Entire Building	24	EA	6	6-10 years	

Ventilation

Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	

Piping

Domestic Piping-Hot Water Return Lines	Entire Building	41,730	SF	6	10+ years	
Domestic Piping-Hot Water Return Risers	Entire Building	41,730	SF	6	10+ years	
Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	41,730	SF	6	10+ years	
Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	41,730	SF	6	10+ years	
Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	41,730	SF	6	10+ years	
Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	41,730	SF	6	10+ years	
Sanitary Piping	Entire Building	1	SF	6	10+ years	
Storm Piping	Entire Building	41,730	SF	6	10+ years	
Vent Piping	Entire Building	41,730	SF	6	10+ years	

Pumps

Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	5	2-5 years	
Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	5	2-5 years	
Pumps - Ejector-Duplex	Entire Building	1	EA	5	0-1 year	Pump nonfunctional, pit has a submersible sump pump pumping water
Pumps - Sump-Simplex	Entire Building	1	EA	5	6-10 years	
Pumps - Sump-Simplex	Entire Building	1	EA	5	6-10 years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Administrative Suites/Offices

	AC Unit	101 Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	101 Main Office	447	SF	6	10+ years	
	Doors - Steel Doors incl hw	101 Main Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	101 Main Office	447	SF	7	10+ years	
	Lighting - Pendent/Surface	101 Main Office	13	EA	7	10+ years	
	Power Distribution	101 Main Office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	101 Main Office	1,110	SF	6	10+ years	
	AC Unit	101A Principal Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	101A Principal Office	127	SF	6	10+ years	
	Ceiling - Plaster/Drywall	101A Principal Office	60	SF	5	6-10 years	
	Doors - Steel Doors incl hw	101A Principal Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	101A Principal Office	187	SF	7	10+ years	
	Lighting - Pendent/Surface	101A Principal Office	4	EA	7	10+ years	
	Power Distribution	101A Principal Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	101A Principal Office	629	SF	6	10+ years	
	Ceiling - Plaster/Drywall	103A Office	71	SF	6	10+ years	
	Doors - Steel Doors incl hw	103A Office	1	EA	6	10+ years	
	Doors - Transom Window	103A Office	8	SF	7	10+ years	
	Floor - Tile/Sheet	103A Office	71	SF	5	10+ years	
	Lighting - Pendent/Surface	103A Office	1	EA	7	10+ years	
	Power Distribution	103A Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	103A Office	337	SF	6	10+ years	
	AC Unit	108 Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	108 Office	572	SF	7	10+ years	
	Doors - Steel Doors incl hw	108 Office	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	108 Office	6	EA	6	10+ years	
	Floor - Tile/Sheet	108 Office	572	SF	7	10+ years	
	Lighting - Pendent/Surface	108 Office	9	EA	7	6-10 years	
	Power Distribution	108 Office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	108 Office	1,306	SF	7	10+ years	
	Ceiling - Plaster/Drywall	200	244	SF	6	6-10 years	
	Doors - Steel Doors incl hw	200	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	200	1	EA	6	10+ years	
	Floor - Tile/Sheet	200	244	SF	5	6-10 years	
	Lighting - Pendent/Surface	200	2	EA	7	10+ years	
	Power Distribution	200	8	EA	7	10+ years	
	Storage/ Closet	200	24	SF	7	10+ years	
	Walls - Plaster/Drywall	200	730	SF	6	10+ years	
	AC Unit	Basement Engineer's Office	1	EA	7	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Exposed	Basement Engineer's Office	134	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Engineer's Office	1	EA	6	10+ years	
	Floor - Concrete	Basement Engineer's Office	134	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement Engineer's Office	2	EA	5	6-10 years	Missing covers
	Walls - Concrete Block	Basement Engineer's Office	577	SF	5	10+ years	
Gymnasium							
	Ceiling - Plaster/Drywall	100 Multi-Purpose	2,385	SF	6	10+ years	No occupancy signage
	Doors - Steel Doors incl hw	100 Multi-Purpose	2	EA	6	10+ years	No occupancy signage
	Floor - Wood	100 Multi-Purpose	2,385	SF	6	10+ years	No occupancy signage
	Lighting - Metal Halide/Sodium Vapor	100 Multi-Purpose	18	EA	7	10+ years	No occupancy signage
	Sound System	100 Multi-Purpose	1	EA	7	10+ years	No occupancy signage
	Stage	100 Multi-Purpose	379	SF	6	10+ years	No occupancy signage
	Stage Curtain	100 Multi-Purpose	1	EA	7	10+ years	No occupancy signage
	Stage Lift	100 Multi-Purpose	1	EA	7	10+ years	No occupancy signage
	Stage Lighting System	100 Multi-Purpose	1	EA	7	10+ years	No occupancy signage
	Stage-Stairs - Wood	100 Multi-Purpose	10	LF	6	10+ years	No occupancy signage
	Storage/ Closet	100 Multi-Purpose	120	SF	7	10+ years	No occupancy signage
	Walls - Structural Glazed Tile	100 Multi-Purpose	4,075	SF	6	10+ years	No occupancy signage
MDF_IDF							
	Doors - Steel Doors incl hw	103 MDF_IDF	1	EA	6	10+ years	
	Finishes	103 MDF_IDF	133	SF	7	10+ years	
	Window AC Unit	103 MDF_IDF	1	EA	7	6-10 years	
Mechanical/ Service Rooms							
	Janitor's Closet	1st Floor	120	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	55	SF	7	10+ years	
	Storage Room	1st Floor	250	SF	7	10+ years	
	Vaults	1st Floor	50	SF	7	10+ years	
	Janitor's Closet	2nd Floor	42	SF	5	10+ years	
	Janitor's Closet	3rd Floor	42	SF	5	10+ years	
	Boiler Room	Basement	2,450	SF	5	10+ years	
	Coal Room	Basement	1,250	SF	5	10+ years	
	Crawl Space - Unfinished	Basement	7,820	SF	5	10+ years	
	Janitor's Closet	Basement	50	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	1,370	SF	5	10+ years	
	Storage Room	Basement	250	SF	5	10+ years	
Prep Room							
	Casework	105A Prep Room	4	LF	6	10+ years	
	Ceiling - Plaster/Drywall	105A Prep Room	138	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105A Prep Room	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	105A Prep Room	6	SF	5	1-2 years	Damaged tiles
	Floor - Tile/Sheet	105A Prep Room	138	SF	7	10+ years	
	Lighting - Pendent/Surface	105A Prep Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	105A Prep Room	504	SF	6	10+ years	
	Work Sink	105A Prep Room	1	EA	7	10+ years	
<hr/>							
Restroom							
	Accessories	101B in 1st Floor Main Office	26	SF	7	10+ years	
	Ceiling - Plaster/Drywall	101B in 1st Floor Main Office	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101B in 1st Floor Main Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	101B in 1st Floor Main Office	26	SF	6	10+ years	
	Lavatory	101B in 1st Floor Main Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	101B in 1st Floor Main Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	101B in 1st Floor Main Office	190	SF	6	10+ years	
	Water Closet	101B in 1st Floor Main Office	1	EA	6	10+ years	
	Accessories	101D in 1st Floor Main Office	26	SF	7	10+ years	
	Ceiling - Plaster/Drywall	101D in 1st Floor Main Office	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101D in 1st Floor Main Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	101D in 1st Floor Main Office	26	SF	6	10+ years	
	Lavatory	101D in 1st Floor Main Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	101D in 1st Floor Main Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	101D in 1st Floor Main Office	190	SF	6	10+ years	
	Water Closet	101D in 1st Floor Main Office	1	EA	6	10+ years	
	Accessories	105B	25	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	105B	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105B	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	105B	25	SF	6	10+ years	
	Lighting - Pendent/Surface	105B	1	EA	7	10+ years	
	Walls - Plaster/Drywall	105B	96	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	105B	75	SF	6	10+ years	
	Water Closet	105B	1	EA	7	6-10 years	
	Accessories	1st Floor Boys - Across from Addition entrance 2	196	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Boys - Across from Addition entrance 2	196	SF	6	6-10 years	
	Doors - Side-lite	1st Floor Boys - Across from Addition entrance 2	42	SF	7	10+ years	
	Doors - Side-lite	1st Floor Boys - Across from Addition entrance 2	40	SF	7	10+ years	
	Floor - Tile	1st Floor Boys - Across from Addition entrance 2	5	SF	5	1-2 years	Damaged tiles
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys - Across from Addition entrance 2	196	SF	5	10+ years	
	Floor Drain	1st Floor Boys - Across from	1	EA	7	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Hand Dryer	Addition entrance 2 1st Floor Boys - Across from	1	EA	7	10+ years	
	Lavatory	Addition entrance 2 1st Floor Boys - Across from	1	EA	6	10+ years	
	Lavatory	Addition entrance 2 1st Floor Boys - Across from	1	EA	4	1-2 years	Missing faucet
	Lighting - Pendent/Surface	Addition entrance 2 1st Floor Boys - Across from	4	EA	6	10+ years	
	Partitions	Addition entrance 2 1st Floor Boys - Across from	1	EA	7	10+ years	
	Urinals	Addition entrance 2 1st Floor Boys - Across from	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Addition entrance 2 1st Floor Boys - Across from	144	SF	6	10+ years	
	Walls - Structural Glazed Tile	Addition entrance 2 1st Floor Boys - Across from	600	SF	6	10+ years	
	Water Closet	Addition entrance 2 1st Floor Boys - Across from	1	EA	6	10+ years	
	Accessories	Addition entrance 2 1st Floor Girls - across from 101	240	SF	7	10+ years	
	Ceiling - Plaster/Drywall	main office 1st Floor Girls - across from 101	240	SF	6	10+ years	
	Doors - Side-lite	main office 1st Floor Girls - across from 101	42	SF	7	10+ years	
	Doors - Transom Window	main office 1st Floor Girls - across from 101	40	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	main office 1st Floor Girls - across from 101	240	SF	6	10+ years	
	Floor Drain	main office 1st Floor Girls - across from 101	1	EA	7	10+ years	
	Hand Dryer	main office 1st Floor Girls - across from 101	1	EA	7	6-10 years	
	Lavatory	main office 1st Floor Girls - across from 101	2	EA	6	10+ years	
	Lighting - Pendent/Surface	main office 1st Floor Girls - across from 101	4	EA	7	10+ years	
	Partitions	main office 1st Floor Girls - across from 101	4	EA	7	10+ years	
	Walls - Plaster/Drywall	main office 1st Floor Girls - across from 101	154	SF	6	10+ years	
	Walls - Structural Glazed Tile	main office 1st Floor Girls - across from 101	620	SF	6	10+ years	
	Water Closet	main office 1st Floor Girls - across from 101	3	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	main office 1st Floor Girls - across from 101	1	EA	4	1-2 years	Not functioning
	Accessories	main office 2nd Floor Boys - next to 212A	196	SF	7	10+ years	
	Ceiling - Plaster/Drywall	janitors closet 2nd Floor Boys - next to 212A	136	SF	7	10+ years	
	Ceiling - Plaster/Drywall	janitors closet 2nd Floor Boys - next to 212A	60	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	janitors closet 2nd Floor Boys - next to 212A	194	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	janitors closet 2nd Floor Boys - next to 212A	2	SF	5	1-2 years	Damaged tiles
	Floor Drain	janitors closet 2nd Floor Boys - next to 212A	1	EA	7	6-10 years	
	Hand Dryer	janitors closet 2nd Floor Boys - next to 212A	1	EA	7	10+ years	
	Lavatory	janitors closet 2nd Floor Boys - next to 212A	2	EA	7	10+ years	
	Lighting - Pendent/Surface	janitors closet 2nd Floor Boys - next to 212A	4	EA	7	10+ years	
	Partitions	janitors closet 2nd Floor Boys - next to 212A	1	EA	7	10+ years	
	Urinals	janitors closet 2nd Floor Boys - next to 212A	3	EA	7	10+ years	
	Urinals	janitors closet 2nd Floor Boys - next to 212A	1	EA	5	0-1 year	Not functioning
	Walls - Plaster/Drywall	janitors closet 2nd Floor Boys - next to 212A	144	SF	6	10+ years	
	Walls - Structural Glazed Tile	janitors closet 2nd Floor Boys - next to 212A	600	SF	6	10+ years	
	Water Closet	janitors closet 2nd Floor Boys - next to 212A	1	EA	7	10+ years	
	Accessories	janitors closet 2nd Floor Girls - across from 201	240	SF	7	10+ years	
	Ceiling - Plaster/Drywall	classroom 2nd Floor Girls - across from 201	240	SF	6	10+ years	
	Doors - Transom Window	classroom 2nd Floor Girls - across from 201	28	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	classroom 2nd Floor Girls - across from 201	240	SF	5	10+ years	
	Floor Drain	classroom 2nd Floor Girls - across from 201	1	EA	7	10+ years	
	Hand Dryer	classroom 2nd Floor Girls - across from 201	1	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	classroom 2nd Floor Girls - across from 201	2	EA	6	10+ years	
	Lighting - Pendent/Surface	classroom 2nd Floor Girls - across from 201	4	EA	7	10+ years	
	Partitions	classroom 2nd Floor Girls - across from 201	6	EA	7	10+ years	
	Walls - Plaster/Drywall	classroom 2nd Floor Girls - across from 201	154	SF	6	10+ years	
	Walls - Structural Glazed Tile	classroom 2nd Floor Girls - across from 201	620	SF	6	10+ years	
	Water Closet	classroom 2nd Floor Girls - across from 201	5	EA	6	10+ years	
	Water Closet	classroom 2nd Floor Girls - across from 201	1	EA	4	0-1 year	Missing toilet seat
	Accessories	classroom 3rd Floor Boys - across from 307	196	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	classroom 3rd Floor Boys - across from 307	196	SF	6	10+ years	
	Doors - Side-lite	classroom 3rd Floor Boys - across from 307	42	SF	7	10+ years	
	Doors - Transom Window	classroom 3rd Floor Boys - across from 307	28	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	classroom 3rd Floor Boys - across from 307	10	SF	5	1-2 years	Damaged tiles
	Floor - Tile Ceramic/ Porcelain	classroom 3rd Floor Boys - across from 307	186	SF	5	10+ years	
	Floor Drain	classroom 3rd Floor Boys - across from 307	1	EA	7	6-10 years	
	Hand Dryer	classroom 3rd Floor Boys - across from 307	1	EA	7	6-10 years	
	Lavatory	classroom 3rd Floor Boys - across from 307	2	EA	6	10+ years	
	Lighting - Pendent/Surface	classroom 3rd Floor Boys - across from 307	4	EA	7	10+ years	
	Partitions	classroom 3rd Floor Boys - across from 307	1	EA	7	10+ years	
	Urinals	classroom 3rd Floor Boys - across from 307	3	EA	7	10+ years	
	Urinals	classroom 3rd Floor Boys - across from 307	1	EA	4	0-1 year	Not functioning
	Walls - Plaster/Drywall	classroom 3rd Floor Boys - across from 307	144	SF	6	10+ years	
	Walls - Structural Glazed Tile	classroom 3rd Floor Boys - across from 307	600	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	classroom 3rd Floor Boys - across from 307	1	EA	7	10+ years	
	Accessories	classroom 3rd Floor Girls - across from 301	240	SF	7	10+ years	
	Ceiling - Plaster/Drywall	classroom 3rd Floor Girls - across from 301	240	SF	6	10+ years	
	Doors - Transom Window	classroom 3rd Floor Girls - across from 301	28	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	classroom 3rd Floor Girls - across from 301	240	SF	6	10+ years	
	Floor Drain	classroom 3rd Floor Girls - across from 301	1	EA	7	10+ years	
	Hand Dryer	classroom 3rd Floor Girls - across from 301	1	EA	7	6-10 years	
	Lavatory	classroom 3rd Floor Girls - across from 301	2	EA	6	10+ years	
	Lighting - Pendent/Surface	classroom 3rd Floor Girls - across from 301	4	EA	7	10+ years	
	Partitions	classroom 3rd Floor Girls - across from 301	6	EA	7	10+ years	
	Walls - Plaster/Drywall	classroom 3rd Floor Girls - across from 301	154	SF	6	10+ years	
	Walls - Structural Glazed Tile	classroom 3rd Floor Girls - across from 301	620	SF	6	10+ years	
	Water Closet	classroom 3rd Floor Girls - across from 301	6	EA	6	10+ years	
	Accessories	Basement	33	SF	7	10+ years	
	Ceiling - Exposed	Basement	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	Basement	33	SF	5	1-2 years	Deteriorated
	Lavatory	Basement	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	7	6-10 years	
	Walls - Concrete Block	Basement	251	SF	6	10+ years	
	Water Closet	Basement	1	EA	6	2-5 years	
	Accessories	In Room 200	33	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	In Room 200	33	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	In Room 200	1	EA	6	10+ years	
	Floor - Tile	In Room 200	29	SF	5	6-10 years	
	Floor - Tile	In Room 200	4	SF	5	1-2 years	Damaged tile
	Lavatory	In Room 200	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Room 200	1	EA	7	10+ years	
	Walls - Plaster/Drywall	In Room 200	219	SF	6	6-10 years	
	Water Closet	In Room 200	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Classroom #104 (Regular Classroom)

	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	1-2 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	800	SF	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	100	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,379	SF	6	10+ years	

Classroom #105 (Science)

	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	814	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	814	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,262	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
	Work Sink	1st Floor	1	EA	5	1-2 years	Not functioning

Classroom #107 (Regular Classroom)

	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	40	LF	4	1-2 years	Damaged marker boards
	Walls - Plaster/Drywall	1st Floor	1,170	SF	6	10+ years	

Classroom #110 (Regular Classroom)

	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,106	SF	6	10+ years	
Classroom #201 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	586	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	100	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,106	SF	6	10+ years	
Classroom #203 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	686	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,106	SF	6	10+ years	
Classroom #204 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	686	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,106	SF	6	10+ years	
Classroom #205 (Science)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	686	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	43	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,106	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	24	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	5	1-2 years	Not functioning
Classroom #206 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	200	SF	6	10+ years	Peeling paint
	Ceiling - Plaster/Drywall	2nd Floor	486	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,106	SF	6	10+ years	
Classroom #207 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	505	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor	505	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	970	SF	6	10+ years	
Classroom #208 (Counseling Room)							

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	686	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	10+ years	
	Storage/ Closet	2nd Floor	25	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,106	SF	6	10+ years	
Classroom #210 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	586	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	100	SF	6	6-10 years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,106	SF	6	10+ years	
Classroom #301 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	686	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,106	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	24	SF	6	10+ years	
Classroom #303 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	686	SF	6	10+ years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,106	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	24	SF	6	10+ years	
Classroom #304 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	681	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	6	6-10 years	Peeling paint
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,106	SF	6	10+ years	
Classroom #305 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	686	SF	6	10+ years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,106	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	24	SF	6	10+ years	
Classroom #306 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	686	SF	6	10+ years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	1	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,106	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	24	SF	6	10+ years	
Classroom #307 (Faculty Lounge)							

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	505	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	505	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	7	EA	7	10+ years	
	Marker Board	3rd Floor	15	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	2,149	SF	6	10+ years	

Classroom #308 (Regular Classroom)

	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	686	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	10+ years	
	Marker Board	3rd Floor	50	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,106	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	24	SF	6	10+ years	

Classroom #310 (Regular Classroom)

	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	681	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	6-10 years	Peeling paint
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,106	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	24	SF	6	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	2,201	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	176	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,000	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	25	SF	4	0-1 year	Damaged floor
	Lighting - Pendent/Surface	1st Floor	20	EA	6	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Student Lockers - One Tier	1st Floor	105	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,036	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,054	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,828	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	64	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	8	EA	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	5	1-2 years	Not working
	Floor - Tile/Sheet	2nd Floor	1,828	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	125	EA	6	10+ years	
	Walls - Masonry	2nd Floor	300	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,583	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,375	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,428	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	19	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,428	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	10+ years	
	Student Lockers - One Tier	3rd Floor	125	EA	6	10+ years	
	Walls - Masonry	3rd Floor	300	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,287	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,930	SF	6	10+ years	

Safety

Camera Viewing Station	Entire Building	3	EA	7	6-10 years	
Metal Detector	Entire Building	2	EA	7	6-10 years	
Security Cameras	Entire Building	11	EA	7	6-10 years	Inside
Security Cameras	Entire Building	4	EA	7	6-10 years	Outside

Stairs

Ceiling - Plaster/Drywall	Basement	80	SF	7	10+ years	
Floor - Concrete	Basement	25	SF	5	10+ years	
Handrails	Basement	35	LF	7	10+ years	
Lighting - Pendent/Surface	Basement	1	EA	7	6-10 years	
Stairs - Concrete	Basement	145	LF	7	10+ years	
Walls - Plaster/Drywall	Basement	85	SF	6	10+ years	
Ceiling - Plaster/Drywall	Stairwell #1	825	SF	6	10+ years	
Floor - Terrazzo	Stairwell #1	716	SF	6	10+ years	
Handrails	Stairwell #1	120	LF	7	10+ years	
Lighting - Pendent/Surface	Stairwell #1	5	EA	7	10+ years	
Stairs - Terrazzo	Stairwell #1	264	LF	6	10+ years	

Category : Interior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	Stairwell #1	1,507	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell #1	1,006	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairwell #2	825	SF	6	10+ years	
	Floor - Terrazzo	Stairwell #2	716	SF	6	10+ years	
	Handrails	Stairwell #2	120	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell #2	4	EA	7	10+ years	
	Stairs - Terrazzo	Stairwell #2	264	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #2	1,507	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell #2	1,006	SF	6	10+ years	
Vertical Conveyance							
	Wheelchair Lift - Platform Lift	West	1	EA	5	0-1 year	Not used, not accessible, not functioning

Category : Exterior
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	Entrance 2-West	2	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 2-West	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 2-West	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 2-West	79	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 2-West	5	LF	5	1-2 years	Broken concrete step, cracked landing
	Ramp Handrail - Steel_Ramp Handrail	Entrance 2-West	70	LF	6	10+ years	
	Ramps - Concrete	Entrance 2-West	70	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 2-West	36	LF	5	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 3-North	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 3-North	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 3-North	40	LF	5	10+ years	
	Exterior Stairs - Stone	Entrance 3-North	6	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 3-North	12	LF	6	10+ years	
	Entrance Control - Audio and Video	Entrance 6-East	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 6-East	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 6-East	4	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 6-East	90	LF	5	1-2 years	Spalled, Cracked concrete
	Exterior Stairs - Stone	Entrance 6-East	14	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 4-NE / Lunchroom	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 4-NE / Lunchroom	32	LF	7	10+ years	
	Exterior Stairs - Stone	Exit 4-NE / Lunchroom	3	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Exit 4-NE / Lunchroom	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 5-NE / Lunchroom	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 5-NE / Lunchroom	3	LF	6	10+ years	
	Exterior Stairs - Concrete	Exit 5-NE / Lunchroom	29	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	Exit 5-NE / Lunchroom	20	LF	6	10+ years	
Foundation							
	Foundation - Concrete	Entire Building	680	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	41,503	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EA	6	0-1 year	Roof lights don't work
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	10+ years	
Roof System							
	Access Ladder - Metal	Roofs 3, 4	3	EA	7	10+ years	
	Chimney - Metal Flue	Roofs 3, 4	40	LF	6	10+ years	

Category : Exterior
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Coping - Metal	Roofs 3, 4	700	LF	6	10+ years	
	Coping - Stone	Roofs 3, 4	50	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roofs 3, 4	10	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roofs 3, 4	418	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roofs 3, 4	2	LF	5	1-2 years	Missing drain strainers
	Parapet - 16" - 30" Height	Roofs 3, 4	20	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roofs 3, 4	730	LF	6	10+ years	
	Parapet - Parapet > 30"	Roofs 3, 4	100	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Roofs 3, 4	10	SF	7	10+ years	Repaired
	Roof - Asphalt Gravel Ballast	Roofs 3, 4	20,760	SF	6	10+ years	
	Roof Hatch - Metal	Roofs 3, 4	1	EA	7	10+ years	
	Roof Structure - Concrete	Roofs 3, 4	20,770	SF	7	10+ years	

Walls

	Canopy - Concrete/ Stucco	Entire Building	210	SF	6	10+ years	
	Canopy - Metal	Entire Building	80	SF	7	10+ years	
	Cheek-Wall - Stone	Entire Building	8	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	60	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	18,335	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	50	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	4	1-2 years	Scattered small areas of open joints
	Exterior Walls - Stone-Cast	Entire Building	830	SF	5	10+ years	

Windows

	Curtain wall - Glazed Double Pane	Entire Building	530	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	320	SF	6	10+ years	
	Lintels - Steel	Entire Building	10	LF	7	10+ years	
	Lintels - Steel	Entire Building	1,110	LF	7	10+ years	
	Lintels - Stone	Entire Building	20	LF	7	10+ years	
	Windows - Decorative	Entire Building	75	SF	7	10+ years	
	Windows - Louver	Entire Building	75	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	135	SF	6	10+ years	
	Windows - Sash Lexan	Entire Building	6,630	SF	7	10+ years	

Category : Electrical
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergency System							
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	

Category : Electrical
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Security System - CCTV	Entire Building	41,503	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	41,503	SF	5	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,890	SF	6	10+ years	

Main Service

PA System	Entire Building	41,503	SF	6	6-10 years	
-----------	-----------------	--------	----	---	------------	--

Power Distribution

Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	

Category : Fire Protection
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	41,503	SF	7	10+ years	
	Fire Alarm_System	Entire Building	41,503	SF	6	10+ years	

Category : Mechanical
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Air Handling Systems</u>							
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	3rd Floor	1	EA	5	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Entire Building	1	EA	6	6-10 years	
	Air Intake	Entire Building	1	EA	6	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Entire Building	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Entire Building	12	EA	7	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Entire Building	100	LF	7	6-10 years	
	Zone Dampers	Entire Building	35	EA	6	6-10 years	

Boiler Systems

Condensate Pump	Boiler Room	1	EA	6	10+ years	
Piping - Condensate Pipe- Steel	Boiler Room	500	LF	6	10+ years	
Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	10+ years	

Category : Mechanical
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Steam Traps	Boiler Room	20	EA	5	6-10 years	
Heating Devices							
	Cabinet Heaters - With Electric Coil	1st Floor	2	EA	6	6-10 years	
	Fin Tube - Electric	Entire Building	80	LF	6	10+ years	
	Fin Tube - Steam	Entire Building	80	LF	6	10+ years	
	Unit Heater - Steam	Mechanical Room	1	EA	6	6-10 years	
	Wall Heater - Electric	Mechanical Room	4	EA	5	6-10 years	
Temperature Control							
	Pneumatic System	Entire Building	41,503	SF	7	10+ years	
	Thermostats - Pneumatic	Entire Building	9	EA	5	10+ years	
	Thermostats - Pneumatic	Entire Building	26	EA	4	10+ years	Engineer replaced all pneumatic thermostat for main and addition building between 2023-2024
Ventilation							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	1-2 years	Missing cover exhaust fan
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	6	EA	5	10+ years	

Category : Plumbing
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Water							
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	5	2-5 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	41,503	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	41,503	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	41,503	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	41,503	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	41,503	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	41,503	SF	7	10+ years	
	Sanitary Piping	Entire Building	41,503	SF	6	10+ years	

Category : Plumbing
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storm Piping	Entire Building	41,503	SF	6	10+ years	
	Vent Piping	Entire Building	41,503	SF	6	10+ years	

Pumps

Pumps - Sump-Simplex	Mechanical Room	1	EA	6	6-10 years	Sump pump located inside the elevator pit
Pumps - Sump-Simplex	Mechanical Room	1	EA	5	6-10 years	

Category : Room
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Administrative Suites/Offices</u>							
	AC Unit	118 Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	118 Office	300	SF	6	10+ years	
	Doors - Steel Doors incl hw	118 Office	1	EA	6	10+ years	
	Floor - Tile	118 Office	300	SF	6	10+ years	
	Lighting - Pendent/Surface	118 Office	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	118 Office	1	EA	5	1-2 years	Loose fixture
	Power Distribution	118 Office	8	EA	7	10+ years	
	Walls - Concrete Block	118 Office	668	SF	6	10+ years	
	AC Unit	220	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	220	300	SF	6	10+ years	
	Doors - Wood Doors inclu hw	220	2	EA	6	10+ years	
	Floor - Tile	220	300	SF	6	10+ years	
	Lighting - Pendent/Surface	220	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	220	1	EA	5	1-2 years	Loose
	Power Distribution	220	8	EA	7	10+ years	
	Walls - Concrete Block	220	668	SF	6	10+ years	
	Walls - Structural Glazed Tile	220	50	SF	6	10+ years	
	Ceiling - Plaster/Drywall	226	384	SF	6	10+ years	
	Doors - Wood Doors inclu hw	226	1	EA	6	10+ years	
	Floor - Carpet	226	384	SF	5	1-2 years	Worn and dirty
	Lighting - Pendent/Surface	226	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	226	1	EA	6	6-10 years	Missing cover
	Power Distribution	226	6	EA	7	10+ years	
	Walls - Concrete Block	226	812	SF	6	10+ years	
	Walls - Structural Glazed Tile	226	50	SF	6	10+ years	
	Ceiling - Plaster/Drywall	309	204	SF	6	10+ years	
	Doors - Wood Doors inclu hw	309	1	EA	6	10+ years	
	Floor - Tile	309	204	SF	6	10+ years	
	Lighting - Pendent/Surface	309	4	EA	7	6-10 years	
	Power Distribution	309	6	EA	7	10+ years	
	Walls - Concrete Block	309	580	SF	6	10+ years	
	AC Unit	320	1	EA	7	6-10 years	

Category : Room
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Plaster/Drywall	320	300	SF	6	10+ years	
	Doors - Wood Doors inclu hw	320	2	EA	6	10+ years	
	Floor - Tile	320	300	SF	6	10+ years	
	Lighting - Pendent/Surface	320	4	EA	7	6-10 years	
	Power Distribution	320	8	EA	7	10+ years	
	Walls - Concrete Block	320	668	SF	6	10+ years	
	Walls - Structural Glazed Tile	320	50	SF	6	10+ years	
	AC Unit	326	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	326	322	SF	6	10+ years	
	Doors - Steel Doors incl hw	326	1	EA	7	6-10 years	
	Floor - Concrete	326	322	SF	7	10+ years	
	Lighting - Pendent/Surface	326	5	EA	7	6-10 years	
	Power Distribution	326	4	EA	7	10+ years	
	Walls - Concrete Block	326	765	SF	6	10+ years	

Gymnasia

Ceiling - Splined	128 Scholar Cafe	3,464	SF	6	10+ years	Max occupancy sign not posted
Ceiling - Splined	128 Scholar Cafe	30	SF	4	0-1 year	Water damage
Doors - Steel Doors incl hw	128 Scholar Cafe	2	EA	6	10+ years	
Floor - Wood	128 Scholar Cafe	3,494	SF	6	10+ years	
Lighting - Lay-in	128 Scholar Cafe	12	EA	7	6-10 years	
Sound System	128 Scholar Cafe	1	EA	7	6-10 years	
Walls - Plaster/Drywall	128 Scholar Cafe	2,338	SF	6	10+ years	
Walls - Structural Glazed Tile	128 Scholar Cafe	2,338	SF	6	10+ years	

Kitchen

AC Unit	134	1	EA	4	0-1 year	Not functioning properly
Ceiling - Lay-in	134	492	SF	6	10+ years	
Ceiling - Lay-in	134	100	SF	4	1-2 years	Water damaged and buckling tiles
Doors - Steel Doors incl hw	134	1	EA	6	10+ years	
Floor - Tile Quarry	134	592	SF	6	10+ years	Changed tile type
Lighting - Pendent/Surface	134	18	EA	7	6-10 years	
Storage/ Closet	134	87	SF	7	10+ years	
Walls - Structural Glazed Tile	134	971	SF	6	10+ years	

Mechanical/ Service Rooms

Janitor's Closet	1st Floor	150	SF	7	10+ years	
Storage Room	1st Floor	78	SF	7	10+ years	Door has cracked glass
Janitor's Closet	2nd Floor	45	SF	5	1-2 years	Door off of 2 hinges
Mechanical/ Service Rooms	2nd Floor	529	SF	7	10+ years	
Storage Room	2nd Floor	75	SF	7	10+ years	
Janitor's Closet	3rd Floor	45	SF	7	10+ years	
Mechanical/ Service Rooms	3rd Floor	230	SF	7	10+ years	

Category : Room
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage Room	3rd Floor	75	SF	7	10+ years	
	Air Tunnel	Basement	1,560	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	8,950	SF	7	10+ years	
Restroom							
	Accessories	118A	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	118A	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	118A	1	EA	6	10+ years	
	Floor - Tile	118A	56	SF	6	10+ years	
	Lavatory	118A	1	EA	6	10+ years	
	Lighting - Pendent/Surface	118A	1	EA	6	6-10 years	
	Lighting - Wall Mounted	118A	1	EA	7	6-10 years	
	Partitions	118A	2	EA	7	10+ years	
	Walls - Concrete Block	118A	258	SF	6	10+ years	
	Water Closet	118A	2	EA	7	10+ years	
	Accessories	1st Floor Boys - across from 128 scholar cafe	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boys - across from 128 scholar cafe	267	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys - across from 128 scholar cafe	267	SF	6	10+ years	
	Floor Drain	1st Floor Boys - across from 128 scholar cafe	1	EA	4	1-2 years	Missing cover
	Hand Dryer	1st Floor Boys - across from 128 scholar cafe	1	EA	7	6-10 years	
	Lavatory	1st Floor Boys - across from 128 scholar cafe	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys - across from 128 scholar cafe	2	EA	7	6-10 years	
	Partitions	1st Floor Boys - across from 128 scholar cafe	1	EA	4	0-1 year	Frame and door bent- cannot close properly
	Urinals	1st Floor Boys - across from 128 scholar cafe	4	EA	7	10+ years	
	Urinals	1st Floor Boys - across from 128 scholar cafe	1	EA	4	1-2 years	Missing
	Walls - Concrete Block	1st Floor Boys - across from 128 scholar cafe	300	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys - across from 128 scholar cafe	442	SF	6	10+ years	
	Water Closet	1st Floor Boys - across from 128 scholar cafe	1	EA	7	10+ years	
	Accessories	1st Floor Girls - across from 117 classroom	260	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls - across from 117	260	SF	6	10+ years	

Category : Room
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	classroom 1st Floor Girls - across from 117	260	SF	6	10+ years	
	Floor Drain	classroom 1st Floor Girls - across from 117	1	EA	4	1-2 years	Missing cover
	Hand Dryer	classroom 1st Floor Girls - across from 117	1	EA	7	6-10 years	
	Lavatory	classroom 1st Floor Girls - across from 117	2	EA	6	10+ years	
	Lighting - Pendent/Surface	classroom 1st Floor Girls - across from 117	2	EA	7	6-10 years	
	Partitions	classroom 1st Floor Girls - across from 117	4	EA	7	10+ years	
	Walls - Concrete Block	classroom 1st Floor Girls - across from 117	288	SF	6	10+ years	
	Walls - Structural Glazed Tile	classroom 1st Floor Girls - across from 117	432	SF	6	10+ years	
	Water Closet	classroom 1st Floor Girls - across from 117	4	EA	6	10+ years	
	Accessories	220A	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	220A	51	SF	6	10+ years	
	Ceiling - Plaster/Drywall	220A	5	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	220A	1	EA	5	1-2 years	Closer broken and missing panel
	Floor - Tile	220A	56	SF	6	10+ years	
	Lavatory	220A	1	EA	6	10+ years	
	Lighting - Lay-in	220A	1	EA	6	6-10 years	
	Lighting - Wall Mounted	220A	1	EA	7	6-10 years	
	Partitions	220A	2	EA	7	10+ years	
	Walls - Concrete Block	220A	258	SF	6	10+ years	
	Walls - Structural Glazed Tile	220A	20	SF	6	10+ years	
	Water Closet	220A	2	EA	7	10+ years	
	Accessories	2nd Floor Boys - next to 222A	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	maintenance 2nd Floor Boys - next to 222A	253	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	maintenance 2nd Floor Boys - next to 222A	253	SF	6	10+ years	
	Floor Drain	maintenance 2nd Floor Boys - next to 222A	1	EA	7	1-2 years	Missing cover
	Hand Dryer	maintenance 2nd Floor Boys - next to 222A	1	EA	7	6-10 years	
	Lavatory	maintenance 2nd Floor Boys - next to 222A	1	EA	7	10+ years	
	Lavatory	maintenance 2nd Floor Boys - next to 222A	1	EA	4	1-2 years	Missing

Category : Room
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	maintenance 2nd Floor Boys - next to 222A	2	EA	7	6-10 years	
	Lighting - Wall Mounted	maintenance 2nd Floor Boys - next to 222A	1	EA	6	6-10 years	
	Partitions	maintenance 2nd Floor Boys - next to 222A	1	EA	7	10+ years	
	Urinals	maintenance 2nd Floor Boys - next to 222A	3	EA	7	10+ years	
	Urinals	maintenance 2nd Floor Boys - next to 222A	1	EA	4	1-2 years	Loose and askew
	Walls - Concrete Block	maintenance 2nd Floor Boys - next to 222A	288	SF	6	10+ years	
	Walls - Structural Glazed Tile	maintenance 2nd Floor Boys - next to 222A	432	SF	6	10+ years	
	Water Closet	maintenance 2nd Floor Boys - next to 222A	1	EA	7	6-10 years	
	Accessories	maintenance 2nd Floor Girls - next to 222A	260	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	maintenance 2nd Floor Girls - next to 222A	260	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	maintenance 2nd Floor Girls - next to 222A	260	SF	6	10+ years	
	Floor Drain	maintenance 2nd Floor Girls - next to 222A	1	EA	7	10+ years	
	Hand Dryer	maintenance 2nd Floor Girls - next to 222A	1	EA	7	6-10 years	
	Lavatory	maintenance 2nd Floor Girls - next to 222A	2	EA	6	10+ years	
	Lighting - Pendent/Surface	maintenance 2nd Floor Girls - next to 222A	2	EA	7	6-10 years	
	Partitions	maintenance 2nd Floor Girls - next to 222A	4	EA	7	10+ years	
	Walls - Concrete Block	maintenance 2nd Floor Girls - next to 222A	288	SF	6	10+ years	
	Walls - Structural Glazed Tile	maintenance 2nd Floor Girls - next to 222A	432	SF	6	10+ years	
	Water Closet	maintenance 2nd Floor Girls - next to 222A	2	EA	7	10+ years	
	Water Closet	maintenance 2nd Floor Girls - next to 222A	2	EA	4	0-1 year	Out of order
	Accessories	320A	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	320A	56	SF	6	10+ years	
	Doors - Wood Doors inclu hw	320A	1	EA	6	10+ years	

Category : Room
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	320A	56	SF	6	10+ years	
	Lavatory	320A	1	EA	7	10+ years	
	Lighting - Wall Mounted	320A	1	EA	7	6-10 years	
	Partitions	320A	2	EA	7	10+ years	
	Walls - Concrete Block	320A	258	SF	6	10+ years	
	Walls - Structural Glazed Tile	320A	20	SF	6	10+ years	
	Water Closet	320A	1	EA	7	10+ years	
	Water Closet	320A	1	EA	4	1-2 years	Missing toilet seat
	Accessories	3rd Floor Boys - across from 317 classroom	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Boys - across from 317 classroom	253	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Boys - across from 317 classroom	253	SF	6	10+ years	
	Floor Drain	3rd Floor Boys - across from 317 classroom	1	EA	7	10+ years	
	Hand Dryer	3rd Floor Boys - across from 317 classroom	1	EA	7	6-10 years	
	Lavatory	3rd Floor Boys - across from 317 classroom	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor Boys - across from 317 classroom	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor Boys - across from 317 classroom	1	EA	6	6-10 years	
	Lighting - Wall Mounted	3rd Floor Boys - across from 317 classroom	1	EA	6	6-10 years	
	Partitions	3rd Floor Boys - across from 317 classroom	1	EA	7	10+ years	
	Urinals	3rd Floor Boys - across from 317 classroom	4	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor Boys - across from 317 classroom	288	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Boys - across from 317 classroom	432	SF	6	10+ years	
	Water Closet	3rd Floor Boys - across from 317 classroom	1	EA	7	10+ years	
	Accessories	3rd Floor Girls - across from 317 classroom	260	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Girls - across from 317 classroom	260	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Girls - across from 317 classroom	260	SF	6	10+ years	
	Floor Drain	3rd Floor Girls - across from 317 classroom	1	EA	7	10+ years	

Category : Room
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Hand Dryer	3rd Floor Girls - across from 317 classroom	1	EA	7	6-10 years	
	Lavatory	3rd Floor Girls - across from 317 classroom	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor Girls - across from 317 classroom	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor Girls - across from 317 classroom	1	EA	6	6-10 years	
	Partitions	3rd Floor Girls - across from 317 classroom	4	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor Girls - across from 317 classroom	288	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Girls - across from 317 classroom	432	SF	6	10+ years	
	Water Closet	3rd Floor Girls - across from 317 classroom	3	EA	7	10+ years	
	Water Closet	3rd Floor Girls - across from 317 classroom	1	EA	4	1-2 years	Out of order
	Accessories	Next to room 211	75	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Next to room 211	75	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Next to room 211	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Next to room 211	75	SF	6	10+ years	
	Floor Drain	Next to room 211	1	EA	7	10+ years	
	Hand Dryer	Next to room 211	1	EA	7	6-10 years	
	Lavatory	Next to room 211	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Next to room 211	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Next to room 211	210	SF	6	10+ years	
	Walls - Structural Glazed Tile	Next to room 211	140	SF	6	10+ years	
	Water Closet	Next to room 211	1	EA	7	10+ years	

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #109 (Special Education)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	410	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	0-1 year	Water damage
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	418	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	1st Floor	4	SF	7	10+ years	Locked
	Walls - Concrete Block	1st Floor	641	SF	6	10+ years	
Classroom #111 (Faculty Lounge)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	778	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	697	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #113 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	778	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	697	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	1-2 years	
Classroom #114 (Science Lab Level 2)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	46	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	988	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	968	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	
	Gas Line	1st Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Science Lab Elements	1st Floor	988	SF	7	10+ years	
	Science Lab Fume Hood	1st Floor	1	EA	6	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	150	SF	7	10+ years	
							Relamp closet light

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Concrete Block	1st Floor	1,067	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	335	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
Classroom #115 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	778	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	697	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	1-2 years	Covered
Classroom #116 (Science Lab Level 2)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	46	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	918	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	918	SF	6	10+ years	
	Gas Line	1st Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Science Lab Fume Hood	1st Floor	1	EA	6	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	150	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,007	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	335	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
Classroom #117 (Regular Classroom)							
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	778	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	776	SF	6	10+ years	
	Floor - Tile	1st Floor	2	SF	5	1-2 years	Chipping
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Loose fixture
	Marker Board	1st Floor	42	LF	6	6-10 years	

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	697	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #119/121 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	32	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,570	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,570	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	42	LF	6	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	Locked or blocked
	Walls - Concrete Block	1st Floor	1,478	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroom #211/213 (Computer Lab)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Casework	2nd Floor	8	LF	4	1-2 years	Damaged
	Ceiling - Plaster/Drywall	2nd Floor	1,656	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,656	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	27	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	Blocked
	Walls - Concrete Block	2nd Floor	1,282	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	287	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroom #214 (Science Lab Level 3)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	794	SF	6	10+ years	
	Floor - Tile	2nd Floor	6	SF	5	1-2 years	Damaged
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	593	SF	6	10+ years	

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	163	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
	Work Sink	2nd Floor	2	EA	5	1-2 years	Not functioning
Classroom #215 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	778	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	6	10+ years	
Classroom #216 (Science Lab Level 3)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	778	SF	6	6-10 years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroom #217 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	778	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	6	10+ years	
Classroom #218 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	778	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	776	SF	6	10+ years	
	Floor - Tile	2nd Floor	2	SF	4	1-2 years	Chipping
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	6	10+ years	
Classroom #219 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	778	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	6	10+ years	
Classroom #221 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	792	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	Covered
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	792	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	5	SF	7	10+ years	Locked
	Walls - Concrete Block	2nd Floor	739	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	75	SF	6	10+ years	
Classroom #311 (Store Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	778	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	21	LF	7	6-10 years	

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	697	SF	6	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor	75	SF	6	6-10 years	
Classroom #313 (Weight)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	773	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	1-2 years	Cracked glass
	Floor - Tile	3rd Floor	6	SF	4	0-1 year	Damaged tiles in an area where there is no weight rm flooring at entrance door
	Floor - Weight/ Fitness Room Floor Matting	3rd Floor	772	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	697	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Water damage
	Walls - Structural Glazed Tile	3rd Floor	75	SF	6	10+ years	
Classroom #314 (Store Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	800	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	800	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	593	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	163	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	80	SF	6	10+ years	
Classroom #315 (Office)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	778	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Concrete Block	3rd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	75	SF	6	10+ years	
Classroom #316 (Music Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	778	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	535	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	162	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	75	SF	6	10+ years	
Classroom #317 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	778	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	770	SF	6	10+ years	
	Floor - Tile	3rd Floor	8	SF	5	0-1 year	Damaged tile
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	75	SF	6	10+ years	
Classroom #318 (Weight)							
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	778	SF	6	10+ years	
	Chalk Board	3rd Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	3rd Floor	778	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	70	SF	6	10+ years	
Classroom #319 (Other Instructional Use)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	778	SF	6	10+ years	
	Chalk Board	3rd Floor	42	LF	4	2-5 years	

Category : Classroom
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	778	SF	6	10+ years	Unfinished wood floor underlayment
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Exposed wiring
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	697	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	75	SF	6	10+ years	

Classroom #321 (Store Room)

	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	782	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	792	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	21	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	739	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	75	SF	6	10+ years	

Category : Interior
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	2,519	SF	6	10+ years	
	Doors - Store Front	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	109	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,400	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	10	SF	4	1-2 years	Missing or damaged
	Lighting - Pendent/Surface	1st Floor	28	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	160	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,837	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,478	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,449	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,449	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years	
	Stairs - Concrete Stairs	2nd Floor	3	LF	6	10+ years	
	Student Lockers - One Tier	2nd Floor	154	EA	6	10+ years	
	Walls - Metal Panel	2nd Floor	366	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,386	SF	6	10+ years	

Category : Interior
Building : Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Structural Glazed Tile	2nd Floor	2,159	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,449	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,447	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	3rd Floor	11	EA	7	6-10 years	
	Stairs - Terrazzo	3rd Floor	7	LF	6	10+ years	
	Student Lockers - One Tier	3rd Floor	154	EA	6	10+ years	
	Walls - Concrete Block	3rd Floor	366	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	366	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,189	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,753	SF	6	10+ years	
Safety							
	Security Cameras	Entire building	4	EA	7	6-10 years	
	Security Cameras	Entire building	5	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Stairwell #3	449	SF	6	10+ years	
	Floor - Terrazzo	Stairwell #3	449	SF	6	10+ years	
	Handrails	Stairwell #3	96	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell #3	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Stairwell #3	2	EA	6	6-10 years	Relamp or missing cover
	Stairs - Terrazzo	Stairwell #3	190	LF	6	10+ years	
	Stairs - Terrazzo	Stairwell #3	5	LF	5	1-2 years	Chipped
	Walls - Concrete Block	Stairwell #3	1,042	SF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #3	542	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell #3	1,006	SF	7	10+ years	
Vertical Conveyance							
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Athletic</u>							
	Surface - Asphalt	East	8,500	SF	6	10+ years	
	Lighting	West	15	EA	6	10+ years	
	Surface - Natural	West	115,305	SF	6	10+ years	
	Surface - Natural	West	6,200	SF	4	1-2 years	Diamond is full of weeds
<u>Civil/Drainage</u>							
	Civil/ Drainage - Catch Basin	Entire Site	11	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	6	10+ years	
<u>Fencing</u>							
	Fencing - Chain Link	Entire Site	1,200	LF	7	10+ years	
	Fencing - Chain Link	Entire Site	75	LF	5	1-2 years	Damage section of fencing, rails are off posts
	Fencing - Guard Rail	Entire Site	85	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	10	LF	5	1-2 years	Bent
	Fencing - New Standard Ornamental	Entire Site	1,620	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	30	LF	4	1-2 years	Fence is damaged due to impact
	Fencing - Old Standard Ornamental	Entire Site	30	LF	7	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	434	LF	6	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	32	LF	5	1-2 years	Missing sections of fencing
<u>Landscape</u>							
	Benches	Entire Site	8	EA	7	10+ years	
	Benches	Entire Site	1	EA	5	1-2 years	Bench not secure to surface
	Landscape - Grass	Entire Site	6,300	SF	7	10+ years	
	Landscape - Grass	Entire Site	26,750	SF	6	10+ years	
	Landscape - Grass	Entire Site	100	SF	5	1-2 years	No growth of grass
	Landscape - Grass	Entire Site	20	SF	4	0-1 year	Hole left from removed catch basin repair
	Landscape - Hardscape- Concrete	Entire Site	10,220	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	100	SF	6	2-5 years	
	Lighting - Pole Mounted	Entire Site	9	EA	6	10+ years	
	Lighting - Pole Mounted	Entire Site	1	EA	4	1-2 years	Lamp and cover damaged or missing
	Parkway trees	Entire Site	49	EA	6	10+ years	
	Parkway trees	Entire Site	2	EA	6	6-10 years	Repaired
	Parkway trees	Entire Site	3	EA	6	6-10 years	Repaired
	Planting Beds/ Area	Entire Site	6	SF	5	6-10 years	
	Retaining Wall - Concrete	Entire Site	40	SF	7	10+ years	
	Walking Path - Crushed Stone	Entire Site	9,000	SF	6	10+ years	

Parking Lot

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Surface - Asphalt	Parking Lot- East	29,268	SF	6	10+ years	
	Surface - Concrete	Parking Lot- East	400	SF	7	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- East	8	SF	7	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- East	16	SF	6	6-10 years	
	Trash Enclosure - Masonry	Parking Lot- East	640	SF	5	10+ years	
	Trash Enclosure - Masonry	Parking Lot- East	30	SF	4	0-1 year	Missing coping
	Concrete Curbs	Parking Lot- South	714	LF	6	10+ years	
	Interior Plantings	Parking Lot- South	500	LF	6	10+ years	
	Lighting - Pole Mounted	Parking Lot- South	2	EA	7	10+ years	
	Surface - Asphalt	Parking Lot- South	22,388	SF	6	10+ years	
	Surface - Asphalt	Parking Lot- South	200	SF	5	1-2 years	Cracks in surface

Sidewalks

	Sidewalks - Internal Walks	Entire Site	450	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	50	LF	4	1-2 years	Cracked concrete
	Sidewalks - Perimeter Sidewalks	Entire Site	16,200	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	75	SF	5	1-2 years	Cracking, displacement

Signage

	Marquee - Free Standing Back lighted w/ LED	Entire Site	2	EA	7	10+ years	
	Monument - Sign	Entire Site	1	EA	5	2-5 years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Building : Main									
Counseling Room	Regular Classroom	2nd Floor	208	206	686	120	54	N	N
Faculty Lounge	Regular Classroom	3rd Floor	307	307	505	80	36	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	900	190	81	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	686	80	36	N	N
Regular Classroom	Regular Classroom	1st Floor	110	108	686	120	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	686	120	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	686	120	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	686	120	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	686	120	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	505	80	36	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	686	120	54	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	686	120	54	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	686	120	54	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	686	120	54	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	686	120	54	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	686	120	54	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	686	120	54	N	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	686	120	54	N	N
Science	Regular Classroom	1st Floor	105	105	814	140	63	N	N
Science	Regular Classroom	2nd Floor	205	205	686	120	54	N	N

Building : Addition									
Computer Lab	Regular Classroom	2nd Floor	211/213	213	1,656	180	60	N	N
Faculty Lounge	Regular Classroom	1st Floor	111	111	778	180	60	N	N
Music Room	Regular Classroom	3rd Floor	316	326	778	60	20	N	N
Office	Regular Classroom	3rd Floor	315	315	778	180	60	N	N
Other Instructional Use	Regular Classroom	3rd Floor	319	319	778	180	60	N	N
Regular Classroom	Physical Education Room	2nd Floor	215	215	778	180	60	N	N
Regular Classroom	Regular Classroom	1st Floor	113	113	778	180	60	N	N
Regular Classroom	Regular Classroom	1st Floor	115	115	778	180	60	N	N
Regular Classroom	Regular Classroom	1st Floor	117	117	778	180	60	N	N
Regular Classroom	Regular Classroom	1st Floor	119/121	121	1,570	180	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	778	180	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	778	180	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	778	180	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	221	221	792	180	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	317	317	778	180	60	N	N
Science Lab Level 2	Regular Classroom	1st Floor	114	110	988	270	90	N	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Science Lab Level 2	Regular Classroom	1st Floor	116	114	918	270	90	N	Y
Science Lab Level 3	Regular Classroom	2nd Floor	214	214	800	180	60	N	N
Science Lab Level 3	Regular Classroom	2nd Floor	216	216	778	180	60	N	N
Special Education	Other Instructional Use	1st Floor	109	109	418	66	5	N	N
Store Room	Regular Classroom	3rd Floor	311	311	778	180	60	N	N
Store Room	Regular Classroom	3rd Floor	314	314	800	160	50	N	N
Store Room	Regular Classroom	3rd Floor	321	321	792	180	60	N	N
Weight	Regular Classroom	3rd Floor	313	313	778	172	55	N	N
Weight	Regular Classroom	3rd Floor	318	318	778	172	55	N	N