

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1958	2	25,067
Addition	1962	2	32,440
Campus Total			57,507

Catego	ry : Exterior		B	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	2						
	Entrance Control - Audio and Video	1 S	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	1 S	3	EA	7	10+ years	
	Exterior Doors - Side lite	1 S	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	1 S	3	EA	7	10+ years	
	Exterior Stairs - Concrete	1 S	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	11 - Boiler Room	2	EA	4	0-1 year	Corroded, damaged hardware
	Exterior Doors - Transom Lite	11 - Boiler Room	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	8 E	2	EA	7	10+ years	
	Exterior Doors - Side lite	8 E	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	8 E	2	EA	7	10+ years	
	Exterior Stairs - Concrete	8 E	14	LF	6	10+ years	
	Exterior Stairs - Concrete	8 E	10	LF	5	2-5 years	
Foundat	on						
	Foundation - Concrete	Entire Building	552	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	25,067	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	6-10 years	
_Roof Sys	stem						
_,	Access Ladder - Metal	Roof D	1	EA	7	10+ years	



							834 E 50th STREET, Chicago, IL 60615
Catego	ry : Exterior		В	uilding	: Main		
_				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Coping - Metal	Roof D	200	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof D	15	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof D	2,331	SF	4	1-2 years	Bubbling, cracking
	Roof Structure - Concrete	Roof D	2,331	SF	7	10+ years	3, 11 3
	Chimney - Metal Flue	Roof E	17	LF	7	6-10 years	
	Coping - Metal	Roof E	203	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof E	24	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof E	4,070	SF	4	0-1 year	Bubbling, cracking
	Roof Structure - Concrete	Roof E	4,070	SF	7	10+ years	3, 44 3
	Access Ladder - Metal	Roof F	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof F	28	LF	6	10+ years	
	Liner		20		0	ior youro	
	Coping - Metal	Roof F	428	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof F	72	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof F	9,333	SF	4	1-2 years	Plant growth, cracking, bubbling
	Roof Structure - Concrete	Roof F	9,333	SF	7	10+ years	r lant growth, cracking, bubbling
		Roon	9,000	51	'	IUT years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	192	SF	6	10+ years	
	Canopy - Metal	Entire Building	60	SF	6	2-5 years	
	Exterior Walls - Brick	Entire Building	5,542	SF	6	10+ years	
		Entire Duilding	5,542	01	0	TO+ years	
Windows	3						
	Curtain wall - Glazed Double Pane	Entire Building	1,002	SF	6	6-10 years	
	Curtain wall - Insulated Panel	Entire Building	273	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	3,647	SF	6	6-10 years	
	Lintels - Steel	Entire Building	282	LF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	5,158	SF	5	2-5 years	
	pane		0,100	•	Ũ	_ 0)00.0	
	Windows - Louver	Entire Building	73	SF	6	6-10 years	
				•	Ū	0 10 900.0	
Catego	ry : Electrical		В	uilding	: Main		
Croup	Itom Tuno	Location	Quantity	UOM	Bonk	Recommend Replacement	Commente
Group	Item - Type		Quantity	UOM	Rank	Replacement	Comments
-mergen		Frating Desilutions	57 507	05	-	0.40	
	Security System - CCTV	Entire Building	57,507	SF	5	6-10 years	Leasted in all dat flares
	Security System - Intrusion Detection	Entire Building	57,507	SF	5	6-10 years	Located in all 1st floor
	Emergency Battery Packs - Corridors and	Entire Building	5	EA	6	6-10 years	classes/hallways
	Stairs		5	ĽA	0	U-TU years	
	Emergency Battery Packs - Lunchrooms	Entire Building	0		e	6-10 years	
			2 5	EA	6		No omorgonou botton, podla install
	Emergency Battery Packs - Multipurpose	Entire Building	5	EA	6	6-10 years	No emergency battery packs installe
	Room						



							834 E 50th STREET, Chicago, IL 60
Catego	ory : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	No exit sign
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,426	SF	6	6-10 years	-
	Emergency A/C Power - Multipurpose Room	Entire Building	1,310	SF	6	10+ years	
Main Se	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	25,067	SF	6	6-10 years	
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ vears	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ory : Fire Protection		В	uilding	: Main		
-				Ū		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
- Fire Alar						•	
<u> </u>	Fire Alarm Panel	Electrical Room	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Electrical Room	25,067	SF	6	10+ years	
	Fire Alarm_System	Electrical Room		SF	6		
	File Alam_System	Electrical Room	25,067	55	0	10+ years	
Catego	ory : Mechanical		В	uilding	: Main	December	
Crown	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group							
Group Air Hanc							
	Aling Systems Air Handling Unit- Package Single Zone- Outdoor Roof Mounted- Electric and DX	Roof	1	EA	6	10+ years	
	dling Systems Air Handling Unit- Package Single Zone-	Roof	1	EA EA	6 6	10+ years 10+ years	



Catego	ry : Mechanical		В	uilding	: Main		
	•			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	1	ĒA	õ	10+ years	
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	2	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	Connected in parallel with boiler in addition building
Heating	Devices						
-	Fin Tube - Hot Water	Entire Building	154	LF	5	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	2	EA	5	6-10 years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	400	LF	7	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	
Tempera	ature Control						
	DDC System	Entire Building	25,227	SF	6	10+ years	BAS Serves both buildings. Located in addition.
	Electric Thermostat	Entire Building	6	EA	5	6-10 years	Serve cabinet heater in corridor. Per Engineer only located in addition building
	Thermostats - DDC	Entire Building	19	EA	6	10+ years	Per Engineer only located in addition building
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	19	EA	6	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
lot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	25,067	SF	6	10+ years	
	Sanitary Piping	Entire Building	25,067	SF	6	10+ years	
	Storm Piping	Entire Building	25,067	SF	6	10+ years	
	Vent Piping	Entire Building	25,067	SF	6	10+ years	
atego	ry : Room		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	Counselors Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Counselors Office	188	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselors Office	1	EA	6	10+ years	
	Floor - Tile	Counselors Office	188	SF	6	10+ years	
	Lighting - Lay-in	Counselors Office	4	EA	6	6-10 years	
	Walls - Concrete Block	Counselors Office	486	SF	6	10+ years	
	AC Unit	Main office	2	EA	7	6-10 years	
	Ceiling - Lay-in	Main office	412	SF	7	10+ years	
	Doors - Steel Doors incl hw	Main office	2	EA	7	10+ years	
	Floor - Tile	Main office	412	SF	7	10+ years	
	Lighting - Lay-in	Main office	7	EA	7	6-10 years	
	Storage/ Closet	Main office	8	SF	7	10+ years	
	Walls - Concrete Block	Main office	547	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office	325	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	6	10+ years	
	Floor - Tile	Principal's Office	325	SF	6	10+ years	
	Lighting - Lay-in	Principal's Office	6	EA	6	6-10 years	
	Walls - Concrete Block	Principal's Office	628	SF	6	10+ years	
litchen							



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	506	SF	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	100	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Serving Line	1st Floor	19	LF	6	10+ years	
	Walls - Tile	1st Floor	890	SF	6	10+ years	
cker/S	Shower Room						
	Accessories	Kitchen Locker Room/Restroom	63	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Locker Room/Restroom	41	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Locker Room/Restroom	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Locker Room/Restroom	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Kitchen Locker Room/Restroom	22	SF	6	10+ years	
	Floor - Tile/Sheet	Kitchen Locker Room/Restroom	41	SF	7	10+ years	
	Lavatory	Kitchen Locker Room/Restroom	1	EA	6	10+ years	
	Lighting - Lay-in	Kitchen Locker Room/Restroom	2	EA	6	6-10 years	
	Student Lockers - One Tier	Kitchen Locker Room/Restroom	7	EA	6	10+ years	
	Walls - Concrete Block	Kitchen Locker Room/Restroom	216	SF	6	10+ years	
	Walls - Structural Glazed Tile	Kitchen Locker Room/Restroom	153	SF	6	10+ years	
	Water Closet	Kitchen Locker Room/Restroom	1	EA	6	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,310	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	
	Floor - Tile	1st Floor	1,270	SF	6	10+ years	
	Floor - Tile	1st Floor	40	SF	4	1-2 years	Damaged
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	607	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	303	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	303	SF	6	10+ years	
echani	cal/ Service Rooms						
	Boiler Room	1st Floor	489	SF	7	10+ years	
	Janitor's Closet	1st Floor	39	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	15	SF	7	10+ years	
	Storage Room	1st Floor	60	SF	7	10+ years	
	Storage Room	1st Floor	65	SF	7	10+ years	
	Vaults	1st Floor	40	SF	7	10+ years	Rank changed to update/correct match current observation
	Janitor's Closet	2nd Floor	38	SF	7	10+ years	
	Storage Room	2nd Floor	33	SF	7	10+ years	



Catego	ry : Room		B	uilding	• Main		834 E SUTI STREET, Chicago, IL 60615
Galogo				unung	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	101A	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	101A	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	101A	1	EA	7	10+ years	
	Floor - Tile	101A	20	SF	6	10+ years	
	Lavatory	101A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	101A	1	EA	7	6-10 years	
	Walls - Concrete Block	101A	144	SF	7	10+ years	
	Water Closet	101A	1	EA	7	10+ years	
	Accessories	102A	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	102A	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	102A	20	SF	7	10+ years	
	Lavatory	102A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	102A	1	EA	7	6-10 years	
	Walls - Concrete Block	102A	144	SF	7	10+ years	
	Water Closet	102A	1	EA	7	10+ years	
	Accessories	109A	61	SF	7	10+ years	
	Ceiling - Plaster/Drywall	109A	61	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	109A	61	SF	7	10+ years	
	Floor Drain	109A	1	EA	7	10+ years	
	Hand Dryer	109A	1	EA	7	10+ years	
	Lavatory	109A	1	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	109A	2	EA	7	10+ years	
	Walls - Plaster/Drywall	109A	142	SF	7	10+ years	
	Walls - Structural Glazed Tile	109A	96	SF	7	10+ years	
	Water Closet	109A	1	EA	7	10+ years	
	Accessories	1st Floor Boys	175	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boys	175	SF	7	10+ years	Rank changed to update/correct to
							match current observation
	Doors - Wood Doors inclu hw	1st Floor Boys	1	EA	7	10+ years	Rank changed to update/correct to
							match current observation
	Floor - Terrazzo	1st Floor Boys	175	SF	7	10+ years	
	Floor Drain	1st Floor Boys	1	EA	7	10+ years	
	Lavatory	1st Floor Boys	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	3	EA	7	6-10 years	
	Partitions	1st Floor Boys	2	EA	7	10+ years	
	Urinals	1st Floor Boys	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Boys	234	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Boys	120	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys	234	SF	7	10+ years	
	Water Closet	1st Floor Boys	1	EA	7	10+ years	
	Accessories	1st Floor Girls	189	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	189	SF	7	10+ years	



Catego	ry : Room		R	uilding	• Main		834 E 50th STREET, Chicago, IL 60615
Jacyo				anang	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor Girls	1	EA	7	10+ years	Rank changed to update/correct to match current observation
	Floor - Terrazzo	1st Floor Girls	189	SF	7	10+ years	
	Floor Drain	1st Floor Girls	1	ĒA	7	10+ years	
	Lavatory	1st Floor Girls	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Girls	3	EA	7	6-10 years	
	Partitions	1st Floor Girls	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Girls	161	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Girls	125	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girls	161	SF	7	10+ years	
	Water Closet	1st Floor Girls	6	EA	7	10+ years	
	Accessories	1st Floor Unisex East	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Unisex East	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Unisex East	1	EA	7	10+ years	
	Floor - Tile	1st Floor Unisex East	20	SF	7	10+ years	
	Lavatory	1st Floor Unisex East	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Unisex East	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor Unisex East	144	SF	7	10+ years	
	Water Closet	1st Floor Unisex East	1	EA	7	10+ years	
	Accessories	1st Floor Unisex West	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Unisex West	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Unisex West	1	EA	7	10+ years	
	Floor - Tile	1st Floor Unisex West	20	SF	7	10+ years	
	Lavatory	1st Floor Unisex West	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Unisex West	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor Unisex West	144	SF	7	10+ years	
	Water Closet	1st Floor Unisex West	1	EA	7	10+ years	
	Accessories	2nd Floor Boys	175	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Boys	175	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Boys	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor Boys	175	SF	5	10+ years	
	Floor Drain	2nd Floor Boys	1	EA	7	10+ years	
	Lavatory	2nd Floor Boys	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Boys	3	EA	6	6-10 years	Demonstra
	Partitions	2nd Floor Boys	1	EA EA	4	0-1 year	Damaged
	Urinals	2nd Floor Boys	4	SF	6	10+ years	
	Walls - Concrete Block	2nd Floor Boys	236	SF	7 7	10+ years	
	Walls - Structural Glazed Tile Water Closet	2nd Floor Boys	236 1	EA	6	10+ years	
		2nd Floor Boys 2nd Floor Girl's		SF	6 7	10+ years	
	Accessories		181	SF	6	10+ years	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	2nd Floor Girl's	181	EA		10+ years	
	Floor - Terrazzo	2nd Floor Girl's 2nd Floor Girl's	1	EA SF	6	10+ years	
	Floor - Terrazzo Floor Drain	2nd Floor Girl's	181 1	EA	6 7	10+ years	
			I	EA	1	10+ years	



Catego	ry : Room		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	2nd Floor Girl's	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girl's	3	EA	6	6-10 years	
	Partitions	2nd Floor Girl's	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Girl's	240	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girl's	240	SF	6	10+ years	
	Water Closet	2nd Floor Girl's	5	EA	6	10+ years	
	Accessories	Counselor's Office	20	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Counselor's Office	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselor's Office	1	EA	6	10+ years	
	Floor - Tile	Counselor's Office	20	SF	6	10+ years	
	Lavatory	Counselor's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Counselor's Office	1	EA	6	6-10 years	
	Walls - Concrete Block	Counselor's Office	144	SF	6	10+ years	
	Water Closet	Counselor's Office	1	EA	6	10+ years	
	Accessories	Principal's Office	20	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	10+ years	
	Floor - Tile	Principal's Office	20	SF	6	10+ years	
	Lavatory	Principal's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Principal's Office	1	EA	6	6-10 years	
	Walls - Concrete Block	Principal's Office	158	SF	6	10+ years	
	Water Closet	Principal's Office	1	EA	6	10+ years	
Catego	rv : Classroom		В	uildina	: Main		

Calego	ry : Classroom		D	ullaing	. wam		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	••	Location	Quantity		ιτατικ	Replacement	comments
Classroc	om #101 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	29	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	847	SF	6	10+ years	
	Doors - Transom Window	1st Floor	96	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	847	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	17	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	888	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #102 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	Rank changed to update/correct to match current observation
	Ceiling - Lay-in	1st Floor	996	SF	6	10+ years	



Cataora				يت من ام ان ب	. Mair		834 E 50th STREET, Chicago, IL 6061
Latego	ry : Classroom		В	uilding	: wain	Decemany	
O	Kenne Turne	Leastien	Quantitu	UOM	Dank	Recommend	Commente
Group	Item - Type Doors - Side-lite	Location 1st Floor	Quantity 7	UOM SF	Rank 7	Replacement	Comments
	Doors - Transom Window	1st Floor	-	SF	7	10+ years	
	Doors - Wood Doors inclu hw		13			10+ years	
		1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	996	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	17	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	956	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroc	m #103 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	787	SF	7	10+ years	
	Doors - Transom Window	1st Floor	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	787	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	7	10+ years	
Classroo	m #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	7	10+ years	Rank changed to update/correct to match current observation
	Ceiling - Lay-in	1st Floor	787	SF	7	10+ years	
	Doors - Transom Window	1st Floor	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	787	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	17	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	7	10+ years	
		151 1001	780	56	'	TO+ years	
lassroo	m #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	6-10 years	Rank changed to update/correct to match current observation
	Ceiling - Lay-in	1st Floor	786	SF	7	10+ years	
	Doors - Transom Window	1st Floor	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	. <u>-</u> 1	EA	7	10+ years	
	Floor - Tile	1st Floor	771	SF	7	10+ years	
	Floor - Tile	1st Floor	15	SF	5	1-2 years	Cracked and broken floor tiles
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Warker Duaru		20	LF	U	0-10 years	



XYN S							834 E 50th STREET, Chicago, IL 60
atego	ry : Classroom		В	uilding	: Main		
					_	Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	779	SF	7	10+ years	
assroo	m #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	785	SF	7	10+ years	
	Doors - Transom Window	1st Floor	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	10+ years	
	Floor - Tile	1st Floor	785	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block		-	SF	7		
	Walls - Concrete Block	1st Floor	779	55	/	10+ years	
assroo	m #109 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	6	10+ years	Rank changed to update/correct match current observation
	Ceiling - Lay-in	1st Floor	787	SF	7	10+ years	
	Doors - Transom Window	1st Floor	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	787	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20				
			-		6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	Rank changed to update/correct match current observation
assroo	m #110 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	Rank changed to update/correct match current observation
	Ceiling - Lay-in	1st Floor	786	SF	7	10+ years	
	Doors - Transom Window	1st Floor	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	786	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20		6	6-10 years	
			779	SF	6 7	•	
	Walls - Concrete Block	1st Floor	779	55	1	10+ years	
assroo	m #112 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	13111001	10	SF	0	10+ years	



Catedo	ry : Classroom		B	uilding	: Main		
2.590	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
noup	Doors - Transom Window	1st Floor	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	788	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	779	SF	7	10+ years	
lassroo	om #114 (Multi Purpose Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	787	SF	7	10+ years	
	Doors - Transom Window	1st Floor	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	787	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	7	10+ years	
			100	01	,	ior youro	
lassroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	768	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	20	SF	4	1-2 years	Cracked damaged
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
lassroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
lassroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	



Catego	ry : Classroom		R	uilding	: Main		
outego				unung	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	768	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	20	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	788	SF	6	10+ years	
Classroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	38	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	7	10+ years	
Classroo	m #205 (Multi Purpose Room)						
0.000.00	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	20	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	12	ĒA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	. <u>-</u> 1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	38	SF	4	1-2 years	Cracked damaged
			12	EA	6	6-10 years	



Catego							834 E 50th STREET, Chicago, IL 600
oulogo	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
lassroo	om #207 (Regular Classroom)					0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	778	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	10	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
	11000 (Ot						
Jassroo	om #208 (Store Room) AC Units	2nd Floor	1	EA	7	6-10 years	
		2nd Floor					
	Ceiling - Lay-in		788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	8	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
atego	ry : Interior		B	uilding	Main		
				anang	mann	Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
roup		Location	Quantity	UOM	Rank	Replacement	Comments
iroup	Ceiling - Lay-in	1st Floor	2,300	SF	7	10+ years	
roup							
Group	Ceiling - Lay-in	1st Floor	2,300	SF	7	10+ years	Water stained ceiling tiles by mai
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front	1st Floor 1st Floor	2,300 12	SF SF	7 5	10+ years 1-2 years 10+ years	Water stained ceiling tiles by mai
iroup	Ceiling - Lay-in Ceiling - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor	2,300 12 9 3	SF SF EA EA	7 5 7 7	10+ years 1-2 years 10+ years 6-10 years	Water stained ceiling tiles by mai
roup	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front Drinking Fountains - Single Water Cooler Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,300 12 9 3 2,287	SF SF EA EA SF	7 5 7	10+ years 1-2 years 10+ years 6-10 years 10+ years	Water stained ceiling tiles by main entrance
roup	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front Drinking Fountains - Single Water Cooler Floor - Tile/Sheet Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,300 12 9 3 2,287 25	SF SF EA EA SF SF	7 5 7 7 7 4	10+ years 1-2 years 10+ years 6-10 years 10+ years 1-2 years	Water stained ceiling tiles by mai entrance
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front Drinking Fountains - Single Water Cooler Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,300 12 9 3 2,287 25 12	SF SF EA EA SF SF EA	7 5 7 7 7 4 7	10+ years 1-2 years 10+ years 6-10 years 10+ years 1-2 years 6-10 years	Water stained ceiling tiles by mai entrance Cracks in the floor tiles by the fro
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front Drinking Fountains - Single Water Cooler Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Walls - Concrete Block	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,300 12 9 3 2,287 25 12 847	SF SF EA EA SF SF EA SF	7 5 7 7 7 4 7 7 7	10+ years 1-2 years 10+ years 6-10 years 10+ years 1-2 years 6-10 years 10+ years	Water stained ceiling tiles by mai entrance Cracks in the floor tiles by the fro
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front Drinking Fountains - Single Water Cooler Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Walls - Concrete Block Walls - Masonry	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,300 12 9 3 2,287 25 12 847 300	SF SF EA EA SF SF EA SF SF	7 5 7 7 4 7 7 6	10+ years 1-2 years 10+ years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years	Water stained ceiling tiles by mai entrance Cracks in the floor tiles by the fro
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front Drinking Fountains - Single Water Cooler Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Walls - Concrete Block Walls - Masonry Walls - Structural Glazed Tile	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,300 12 9 3 2,287 25 12 847	SF SF EA EA SF SF EA SF	7 5 7 7 7 4 7 7 7	10+ years 1-2 years 10+ years 6-10 years 10+ years 1-2 years 6-10 years 10+ years	Water stained ceiling tiles by mai entrance Cracks in the floor tiles by the fro
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front Drinking Fountains - Single Water Cooler Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Walls - Concrete Block Walls - Masonry	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,300 12 9 3 2,287 25 12 847 300	SF SF EA EA SF SF EA SF SF	7 5 7 7 4 7 7 6	10+ years 1-2 years 10+ years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years	Water stained ceiling tiles by mai entrance Cracks in the floor tiles by the fro
Group Corridor	Ceiling - Lay-in Ceiling - Lay-in Doors - Store Front Drinking Fountains - Single Water Cooler Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Walls - Concrete Block Walls - Masonry Walls - Structural Glazed Tile	1st Floor 1st Floor	2,300 12 9 3 2,287 25 12 847 300 847	SF SF EA SF SF SF SF SF	7 5 7 7 4 7 7 6 7	10+ years 1-2 years 10+ years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Water stained ceiling tiles by main entrance Cracks in the floor tiles by the from



Catego	ry : Interior		В	uilding	: Main		
U				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	1st Floor West	701	SF	7	10+ years	
	Lighting - Lay-in	1st Floor West	6	EA	7	6-10 years	
	Walls - Masonry	1st Floor West	890	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,457	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,457	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	588	SF	6	10+ years	
	Walls - Masonry	2nd Floor	300	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,177	SF	6	10+ years	
Safety							
2	Security Cameras	1st Floor	10	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	East	419	SF	6	10+ years	
	Ceiling - Plaster/Drywall	East	90	SF	6	10+ years	
	Floor - Tile	East	486	SF	6	10+ years	
	Handrails	East	48	LF	7	10+ years	
	Lighting - Lay-in	East	3	EA	6	10+ years	
	Stairs - Tile	East	107	LF	6	10+ years	
	Walls - Masonry	East	878	SF	6	10+ years	
	Ceiling - Lay-in	West	295	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West	91	SF	6	10+ years	
	Ceiling - Splined	West	122	SF	6	10+ years	
	Floor - Tile	West	481	SF	6	10+ years	
	Floor - Tile	West	4	SF	4	0-1 year	Damaged
	Handrails	West	48	LF	7	10+ years	
	Lighting - Lay-in	West	3	EA	6	10+ years	
	Stairs - Tile	West	107	LF	6	6-10 years	
	Walls - Masonry	West	927	SF	6	10+ years	



Category : Exterior			В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	10 E	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	10 E	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	2 S	2	EA	7	10+ years	
	Exterior Doors - Side lite	2 S	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	2 S	2	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	3 N	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	3 N	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	4 - Parking Lot, Staff Entrance	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	4 - Parking Lot, Staff Entrance	4	EA	7	10+ years	
	Exterior Stairs - Concrete	4 - Parking Lot, Staff Entrance	12	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	5 W - Boiler Room Entrance	2	ĒA	6	10+ years	
	Exterior Doors - Side lite	5 W - Boiler Room Entrance	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	5 W - Boiler Room Entrance	2	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	6 N	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	6 N	4	EA	7	10+ years	
	Exterior Stairs - Concrete	6 N	12	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	7 E	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	7 E	4	EA	7	10+ years	
Foundatio	ion						
	Foundation - Concrete	Entire Building	635	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	32,440	SF	7	10+ years	
Lindation							
Lighting				Ξ.	0	0.40	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	5	2-5 years	
Roof Sys	stem						
	Access Ladder - Metal	Roof A	1	EA	7	6-10 years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof A	39	LF	3	0-1 year	Loose masonry, continuous cracking
	Coping - Metal	Roof A	472	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof A	72	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof A	12,480	SF	4	0-1 year	Cracking, bubbling
	Roof Hatch - Metal	Roof A	12,100	EA	7	6-10 years	Cracking, Subbing
		Roof A	12,480	SF	7	10+ years	
	ROOT STRUCTURE - CONCRETE		12,100	0.		ior yourd	
	Roof Structure - Concrete Access Ladder - Metal		. 1	FΑ	7	10+ vears	
	Access Ladder - Metal	Roof B		EA L F	7 6	10+ years 6-10 years	
	Access Ladder - Metal Coping - Metal	Roof B Roof B	280	LF	6	6-10 years	Sinking worn
	Access Ladder - Metal	Roof B					Sinking, worn Cracking, bubbling, wear



							834 E 50th STREET, Chicago, IL 60615
Catego	ry : Exterior		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	Roof C	1	EA	7	6-10 years	
	Coping - Metal	Roof C	65	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof C	48	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof C	3,557	SF	4	0-1 year	Cracking, bubbling
	Roof Hatch - Metal	Roof C	1	EA	7	6-10 years	
	Roof Structure - Concrete	Roof C	3,557	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	452	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10,113	SF	6	10+ years	
Windows	5						
	Curtain wall - Glazed Double Pane	Entire Building	416	SF	6	6-10 years	
	Curtain wall - Glazed Double Pane	Entire Building	8	SF	5	2-5 years	
	Curtain wall - Insulated Panel	Entire Building	98	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	2,252	SF	6	6-10 years	
	Lintels - Steel	Entire Building	289	LF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	3,316	SF	5	2-5 years	
	pane	Entito Danang	0,010	0.	Ũ	2 o youro	
	Windows - Decorative	Entire Building	483	SF	6	2-5 years	
	Windows - Louver	Entire Building	107	SF	5	2-5 years	
Catego	ry : Electrical		В	uilding	: Additi	on	
J	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ncy System						
	Emergency Battery Packs - Corridors and Stairs	Entire Building	9	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	5	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	5,778	SF	6	10+ years	
	Stairs		0,110	01	Ū	lor youro	
	Emergency A/C Power - Gym	Entire Building	4,219	SF	6	10+ years	
	Security System - CCTV	Entire Building	32,440	SF	5	6-10 years	Located In main building
	Security System - Intrusion Detection	Entire Building	32,440	SF	5	6-10 years	Locatoa in main building
Main Ser	rvice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	32,440	SF	5	6-10 years	



Categor	ry : Electrical		В	uilding	: Additie	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power Dis							
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp						
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	
	amp						
Categor	ry : Fire Protection		В	uilding	: Additie	on	
Ŭ	·			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarn	n						
	Fire Alarm Strobe Lights	Main	32,440	SF	6	10+ years	
	Fire Alarm_System	Main	32,440	SF	6	10+ years	
•			_				
Categor	ry : Mechanical		В	uilding	: Additie		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Boiler Sys		Loodion	Quantity	00111	Nam	Replacement	oon monto
Duller Sys	Boiler Auxiliary- Scotch Marine- Hot Water	Boiler Room	1	EA	5	6-10 years	
	Boiler - 3001 - 4000 MBH	Boller Room	I	EA	5	0-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10	
	Combustion Dampers	Boiler Room	2	EA	6 5	10+ years 10+ years	
	Non Condensing- Scotch Marine- Hot Water	Boiler Room	2	EA	5	6-10 years	Backup boilor
	Boiler - 3001 - 4000 MBH	Boller Room	I	EA	5	0-10 years	Backup boiler
	Water Fill System	Boiler Room	1	EA	5	6-10 years	
	Water I III System		I	LA	5	0-10 years	
Heating D	Devices						
Heating D	Devices Unit Heater - Electric	1st Floor	1	EA	6	10+ vears	
Heating [Unit Heater - Electric				6 5	10+ years 6-10 years	
Heating [Entire Building	1 57 13	EA LF EA	6 5 5	6-10 years	
Heating [Unit Heater - Electric Fin Tube - Hot Water		57	LF	5		
0	Unit Heater - Electric Fin Tube - Hot Water	Entire Building	57	LF	5	6-10 years	
0	Unit Heater - Electric Fin Tube - Hot Water Cabinet Heaters - With Hot Water Coil	Entire Building	57	LF	5	6-10 years 6-10 years	HWP-4
0	Unit Heater - Electric Fin Tube - Hot Water Cabinet Heaters - With Hot Water Coil cal Plumbing	Entire Building Entire Building	57 13	LF EA	5 5	6-10 years	HWP-4 HWP-3
0	Unit Heater - Electric Fin Tube - Hot Water Cabinet Heaters - With Hot Water Coil cal Plumbing Hot Water Pump - Less than 10	Entire Building Entire Building Boiler Room	57 13 1	LF EA EA	5 5 5	6-10 years 6-10 years 10+ years	
Mechanic	Unit Heater - Electric Fin Tube - Hot Water Cabinet Heaters - With Hot Water Coil cal Plumbing Hot Water Pump - Less than 10 Hot Water Pump - Less than 10 Hydronic Supply and Return - Steel	Entire Building Entire Building Boiler Room Boiler Room	57 13 1 1	LF EA EA EA	5 5 5 5 5	6-10 years 6-10 years 10+ years 10+ years	
Mechanic	Unit Heater - Electric Fin Tube - Hot Water Cabinet Heaters - With Hot Water Coil cal Plumbing Hot Water Pump - Less than 10 Hot Water Pump - Less than 10	Entire Building Entire Building Boiler Room Boiler Room	57 13 1 1	LF EA EA EA	5 5 5 5 5	6-10 years 6-10 years 10+ years 10+ years	



	ry : Mechanical		B	uilding	: Additie	on	834 E 50th STREET, Chicago, IL 60615
Calego	y . Mechanica			unung	. Auunn	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
e.eup	Electric Thermostat	Entire Building	4	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	15	EA	6	10+ years	
			10	L /(0	lot youro	
Jnit Ven							
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	15	EA	6	10+ years	
Ventilatio	n						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	5	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	5	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	3	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Additie	on	
-	· •			-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
							
Piping	Domestic Piping-Hot Water Return Lines	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	32,440	SF	6	10+ years	
	Fixtures	Entire Dullang	52,440	01	0	TO+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	32,440	SF	6	10+ years	
	Sanitary Piping	Entire Building	32,440	SF	6	10+ years	
	Storm Piping	Entire Building	32,440	SF	6	10+ years	
	Vent Piping	Entire Building	32,440	SF	6	10+ years	
Catego	ry : Room		R	uildina	: Additie	on	
				a		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	rative Suites/Offices						



Catego	ry : Room		В	uildina	: Additi	on	
				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	Engineers Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineers Office	53	SF	7	10+ years	
	Doors - Side-lite	Engineers Office	35	SF	7	10+ years	
	Doors - Transom Window	Engineers Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineers Office	1	EA	7	10+ years	
	Floor - Tile	Engineers Office	50	SF	7	10+ years	
	Floor - Tile	Engineers Office	3	SF	5	1-2 years	Missing floor tiles
	Lighting - Pendent/Surface	Engineers Office	1	EA	7	6-10 years	
	Walls - Concrete Block	Engineers Office	225	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym Office	98	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym Office	2	SF	4	1-2 years	Missing ceiling tiles
	Doors - Wood Doors inclu hw	Gym Office	1	EA	7	10+ years	
	Floor - Tile	Gym Office	100	SF	7	10+ years	
	Lighting - Lay-in	Gym Office	2	EA	6	6-10 years	
	Power Distribution	Gym Office	4	EA	7	10+ years	
	Walls - Concrete Block	Gym Office	250	SF	7	10+ years	
	Ceiling - Lay-in	Health Center - Conference Room	280	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Health Center - Conference Room	1	EA	7	10+ years	
	Floor - Carpet	Health Center - Conference Room	280	SF	7	6-10 years	
	Lighting - Lay-in	Health Center - Conference Room	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Health Center - Conference Room	406	SF	7	10+ years	
	Ceiling - Lay-in	Health Center - Office A	108	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Health Center - Office A	1	EA	7	10+ years	
	Floor - Carpet	Health Center - Office A	108	SF	7	6-10 years	
	Lighting - Lay-in	Health Center - Office A	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	Health Center - Office A	272	SF	7	10+ years	
	Ceiling - Lay-in	Health Center - Office B	165	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Health Center - Office B	1	EA	7	10+ years	
	Floor - Carpet	Health Center - Office B	165	SF	7	6-10 years	
	Lighting - Lay-in	Health Center - Office B	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Health Center - Office B	290	SF	7	10+ years	
	Ceiling - Lay-in	Health Center Office	170	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Health Center Office	213	SF	7	10+ years	
	Doors - Side-lite	Health Center Office	9	SF	7	10+ years	
	Doors - Transom Window	Health Center Office	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Health Center Office	1	EA	7	10+ years	
	Floor - Carpet	Health Center Office	170	SF	7	6-10 years	
	Floor - Tile/Sheet	Health Center Office	213	SF	7	10+ years	
	Lighting - Lay-in	Health Center Office	2	EA	7	6-10 years	
	Lighting - Lay-in	Health Center Office	9	EA	7	6-10 years	
	Storage/ Closet	Health Center Office	41	SF	7	10+ years	
	Walls - Plaster/Drywall	Health Center Office	684	SF	7	10+ years	

Clinic



Catego	ry : Room		B	uilding	: Additi	on	
Ū,	-			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Ceiling - Lay-in	Exam Room 1	153	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Exam Room 1	1	EA	7	10+ years	
	Floor - Tile/Sheet	Exam Room 1	153	SF	7	10+ years	
	Lighting - Lay-in	Exam Room 1	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Exam Room 1	343	SF	7	10+ years	
	Ceiling - Lay-in	Exam Room 2	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Exam Room 2	1	ĒA	7	10+ years	
	Floor - Tile/Sheet	Exam Room 2	100	SF	7	10+ years	
	Lighting - Lay-in	Exam Room 2	2	ĒA	7	6-10 years	
	Walls - Plaster/Drywall	Exam Room 2	320	SF	7	10+ years	
	Ceiling - Lay-in	Exam Room 3	123	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Exam Room 3	1	EA	7	10+ years	
	Floor - Tile/Sheet	Exam Room 3	123	SF	7	10+ years	
	Lighting - Lay-in	Exam Room 3	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Exam Room 3	302	SF	7	10+ years	
	Ceiling - Lay-in	Laboratory - Health Clinic	114	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Laboratory - Health Clinic	1	EA	7	10+ years	
	Floor - Tile/Sheet	Laboratory - Health Clinic	114	SF	7	10+ years	
	Lighting - Lay-in	Laboratory - Health Clinic	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Laboratory - Health Clinic	309	SF	7		
	Walls - Flastel/Drywall	Laboratory - Health Clinic	309	36	'	10+ years	
Symnasi	ia						
5	Ceiling - Exposed	1st Floor	4,099	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	120	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	ĒA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	4,219	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Stage	1st Floor	280	SF	7	10+ years	
	Stage Curtain	1st Floor	3	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Tile	1st Floor	20	LF	7	10+ years	
	Stage-Stairs - Wood	1st Floor	20	LF	7	10+ years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,690	SF	7	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	1st Floor	1,653	SF	7	10+ years	
			·			2	
unch &	Multipurpose Room			F ^	_	0.40	
	AC Unit	Teacher's Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Teacher's Room	630	SF	7	10+ years	Rank changed to update/correct to match current observation
	Doors - Wood Doors inclu hw	Teacher's Room	1	EA	7	10+ years	
				L/ \		i u youis	



					A . I . I***		834 E 50th STREET, Chicago, IL 606
Catego	ry : Room		В	uilding	: Additi		
-			• • • •			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Teacher's Room	10	EA	7	6-10 years	
	Walls - Concrete Block	Teacher's Room	743	SF	7	10+ years	
MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	144	SF	7	10+ years	
	Window AC Unit	2nd Floor	1	EA	5	2-5 years	
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	550	SF	7	10+ years	
	Janitor's Closet	1st Floor	23	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	280	SF	7	10+ years	
	Storage Room	1st Floor	35	SF	7	10+ years	
	Storage Room	1st Floor	60	SF	7	10+ years	
	Janitor's Closet	2nd Floor	70	SF	7	10+ years	
	Storage Room	2nd Floor	190	SF	7	10+ years	
Restroor		1st Floor - Men's	60	SF	7	6-10 years	
	Accessories			SF	7 7	•	
	Ceiling - Plaster/Drywall	1st Floor - Men's	60			10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Men's	1	EA SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men's	60		7	10+ years	
	Lavatory	1st Floor - Men's	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - Men's	1	EA	7	6-10 years	
	Partitions	1st Floor - Men's	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Men's	133	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Men's	133	SF	7	10+ years	
	Water Closet	1st Floor - Men's	1	EA	7	10+ years	
	Accessories	1st Floor - Women's Restroom	85	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Women's Restroom	85	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Women's Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women's Restroom	85	SF	7	10+ years	
	Floor Drain	1st Floor - Women's Restroom	1	EA	7	10+ years	
	Lavatory	1st Floor - Women's Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - Women's Restroom	2	EA	6	6-10 years	
	Partitions	1st Floor - Women's Restroom	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Women's Restroom	160	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Women's Restroom	160	SF	7	10+ years	
	Water Closet	1st Floor - Women's Restroom	2	EA	7	10+ years	
	Accessories	1st Floor Boys	188	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boys	188	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Boys	100	EA	6		
			•			10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	188	SF	6	10+ years	



Catego	ry : Room		B	uilding	: Additi	on	
U				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st Floor Boys	1	EA	7	10+ years	
	Hand Dryer	1st Floor Boys	2	EA	7	6-10 years	
	Lavatory	1st Floor Boys	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	2	EA	6	6-10 years	
	Partitions	1st Floor Boys	3	EA	7	10+ years	
	Urinals	1st Floor Boys	3	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Boys	236	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys	236	SF	6	10+ years	
	Water Closet	1st Floor Boys	2	EA	6	10+ years	
	Accessories	1st Floor Girls	188	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	188	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	188	SF	6	10+ years	
	Floor Drain	1st Floor Girls	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girls	1	EA	7	6-10 years	
	Lavatory	1st Floor Girls	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor Girls	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor Girls	1	EA	6	6-10 years	
	Partitions	1st Floor Girls	5	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Girls	236	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girls	236	SF	6	10+ years	
	Water Closet	1st Floor Girls	5	EA	6	10+ years	
	Accessories	2nd Floor - Toilet - All-Gender	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Toilet - All-Gender	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Toilet - All-Gender	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Toilet - All-Gender	40	SF	6	10+ years	
	Lavatory	2nd Floor - Toilet - All-Gender	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Toilet - All-Gender	1	EA	6	6-10 years	
	Partitions	2nd Floor - Toilet - All-Gender	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor - Toilet - All-Gender	116	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - Toilet - All-Gender	116	SF	7	10+ years	
	Water Closet	2nd Floor - Toilet - All-Gender	1	EA	6	10+ years	
	Accessories	2nd Floor Boys	307	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boys	307	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Boys	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys	307	SF	6	10+ years	
	Floor Drain	2nd Floor Boys	1	EA	7	10+ years	
	Lavatory	2nd Floor Boys	3	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor Boys	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Boys	4	EA	6	6-10 years	
	Partitions	2nd Floor Boys	3	EA	4	0-1 year	Damaged
	Urinals	2nd Floor Boys	3	EA	6	10+ years	5
	Walls - Concrete Block	2nd Floor Boys	257	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Boys	386	SF	6	10+ years	
	Water Closet	2nd Floor Boys	3	EA	7	10+ years	
			Ŭ		•	,	



					834 E 50th STREET, Chicago, IL 60615		
Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	2nd Floor Girl's	273	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girl's	273	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girl's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girl's	273	SF	6	10+ years	
	Floor Drain	2nd Floor Girl's	1	EA	7	10+ years	
	Lavatory	2nd Floor Girl's	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor Girl's	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Girl's	3	EA	7	6-10 years	
	Partitions	2nd Floor Girl's	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Girl's	257	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girl's	386	SF	6	10+ years	
	Water Closet	2nd Floor Girl's	5	ĒA	6	10+ years	
	Accessories	2nd Floor Women's	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Women's	90	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Women's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Women's	90	SF	6	10+ years	
	Floor Drain	2nd Floor Women's	1	EA	7	10+ years	
	Lavatory	2nd Floor Women's	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Women's	2	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor Women's	170	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Women's	170	SF	6	10+ years	
	Water Closet	2nd Floor Women's	1	EA	7	10+ years	
	Accessories	Engineer's Locker Room	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Locker Room	90	SF	7	10+ years	Rank changed to update/correct to
	Centrig Thaster/Drywan	Engineer 3 Eooker Noom	50	01	'	Tor years	match current observation
	Doors - Wood Doors inclu hw	Engineer's Locker Room	2	EA	7	10+ years	match current observation
	Floor - Tile	Engineer's Locker Room	48	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Engineer's Locker Room	42	SF	7	10+ years	
	Floor Drain	Engineer's Locker Room	42	EA	7	10+ years	
	Lavatory	Engineer's Locker Room	1	EA	6	10+ years	
	Lighting - Lay-in	Engineer's Locker Room	1	EA	7	6-10 years	
	Lighting - Pendent/Surface		2	EA	7	6-10 years	
		Engineer's Locker Room	2	EA	7		
	Showers	Engineer's Locker Room	3	EA		10+ years	
	Student Lockers - One Tier	Engineer's Locker Room	-	SF	6	10+ years	
	Walls - Concrete Block	Engineer's Locker Room	180	SF	7	10+ years	
	Walls - Structural Glazed Tile	Engineer's Locker Room	90		7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Engineer's Locker Room	90	SF	7	10+ years	
	Water Closet	Engineer's Locker Room	1	EA	7	10+ years	
	Accessories	Health Center	59	SF	7	6-10 years	
	Ceiling - Lay-in	Health Center	59	SF	7	10+ years	
	Doors - Steel Doors incl hw	Health Center	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Health Center	59	SF	7	10+ years	
	Floor Drain	Health Center	1	EA	7	10+ years	
	Hand Dryer	Health Center	1	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Additie		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lavatory	Health Center	1	EA	7	10+ years	
	Lighting - Lay-in	Health Center	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Health Center	120	SF	7	10+ years	Quantity changed to update/correct
	\$,	match current observation
	Walls - Tile Ceramic/ Porcelain	Health Center	120	SF	7	10+ years	Quantity changed to update/correct
						, , , , , , , , , , , , , , , , , , ,	match current observation
	Water Closet	Health Center	1	EA	7	10+ years	
Cotomo			Р	uilding			
Jatego	ry : Classroom		D	unaing	: Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #2 (Office)		· · · · ·			•	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	7	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	-0	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	803	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	30	LA	6	6-10 years	
	Storage/ Closet	1st Floor	30 10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	719	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	7	10+ years	
	Work Sink	1st Floor	190	EA	7	10+ years	
	Work Sink	13(1100)	I	LA	'	TOF years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	803	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	10	SF	4	1-2 years	Damaged
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
lacoror	om #212 (Regular Classroom)						
21022100		2nd Floor	1	EA	7	6 10 vooro	
	AC Units		1	EA	7	6-10 years	



Catego	ry : Classroom		R	uilding	: Additi	on	834 E SUIT STREET, Chicago, IL 60615
Juicgo				anang	. Adulti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	809	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4	SF	4	1-2 years	Damaged
	Lighting - Lay-in	2nd Floor	13	ĒA	6	6-10 years	2 4
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	m #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	-0	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	805	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	8	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	Oracica
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	400	SF	6	10+ years	
	Work Sink	2nd Floor	400	EA	7	10+ years	
Classra	m #214 (Regular Classroom)					,	
	AC Units	2nd Floor	4		7	0.10	
			1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	805	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	8	SF	4	1-2 years	Damaged
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	



Catego	y : Classroom		В	uilding	: Additi	on	
			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	803	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	10	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
Classroo	m #216 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	808	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	5	SF	4	1-2 years	Damaged
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	Ũ
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
Classroo	m #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	813	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	



Catego	ry : Classroom		R	uilding	: Additi	on	834 E 50th STREET, Chicago, IL 606
Jacyo				anang	. Adult	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	Comments
			100	0.	U	ier yeare	
Classroo	om #218 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	805	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	8	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
						,	
Classroo	om #219 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	22	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	645	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	215	SF	6	10+ years	
lassro	om #220 (Office)						
51055100	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	412	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	412	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	-12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LA	6	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	715	SF	6	10+ years	
		21011001	715	01	0	io+ years	



Catego	ry : Classroom		В	uilding	: Additi		
-			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #3 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	7	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	49	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	803	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	400	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	460	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #4 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	7	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	802	SF	7	10+ years	
	Floor - Tile	1st Floor	1	SF	4	1-2 years	Cracked floor tiles
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	719	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	7	10+ years	
Classroo	om #5 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	7	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	49	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor		EA	7	10+ years	
	Floor - Tile	1st Floor	793	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Cracked floor tiles
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	30	LA	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	670	SF	7	10+ years	
	Wails - CUILIELE DIUCK		670	эг	1	iut years	



<u> </u>	schools		_				834 E 50th STREET, Chicago, IL 60615
Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	1st Floor	190	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	Classroom #6 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	83	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	7	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	10+ years	
	Floor - Carpet	1st Floor	803	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	719	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	7	10+ years	
Classroo	om #8 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	. 9	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	6	10+ years	Quantity changed to update/correct to
	co			•	Ũ	, e , j eure	match current observation
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	49	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	803	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	719	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	7	10+ years	
	Work Sink	1st Floor	1	ËA	7	10+ years	
Catego	ry : Interior	В	uildina	: Additi	on		
J-	•			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	2,268	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	
	Doors - Store Front	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	5	1-2 years	Not working
	Floor - Tile/Sheet	1st Floor	2,268	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	Quantity changed to update/correct to



Catego	ry : Interior		B	uilding	: Additi	on	
Ŭ	•			Ū		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							match current observation
	Walls - Structural Glazed Tile	1st Floor	2,883	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	1,530	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	1,510	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	20	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Masonry	2nd Floor	100	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,869	SF	6	10+ years	
	Ceiling - Lay-in	Health Clinic	408	SF	7	10+ years	
	Doors - Steel Doors incl hw	Health Clinic	1	EA	7	10+ years	
	Doors - Wood Doors include hw	Health Clinic	1	EA	7	10+ years	
	Floor - Tile/Sheet	Health Clinic	408	SF	7	10+ years	
	Lighting - Lay-in	Health Clinic	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Health Clinic	684	SF	7	10+ years	
Stairs							
	Ceiling - Splined	North	663	SF	6	10+ years	
	Floor - Tile	North	663	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North	93	SF	6	10+ years	
	Handrails	North	50	LF	7	10+ years	
	Lighting - Lay-in	North	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	North	4	EA	7	6-10 years	
	Stairs - Tile	North	126	LF	6	10+ years	
	Walls - Masonry	North	1,664	SF	6	10+ years	
	Ceiling - Splined	South	663	SF	7	10+ years	
	Floor - Tile	South	661	SF	6	10+ years	
	Floor - Tile	South	2	SF	4	1-2 years	Damaged
	Floor - Tile Ceramic/ Porcelain	South	93	SF	6	10+ years	
	Handrails	South	50	LF	7	10+ years	
	Lighting - Lay-in	South	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	South	5	EA	6	6-10 years	
	Stairs - Tile	South	126	LF	6	10+ years	
	Walls - Masonry	South	1,662	SF	6	10+ years	



Catego	Category : Site			uilding			
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	7	6-10 years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	3	1-2 years	Sinking
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	6-10 years	
Fencing							
0	Fencing - Chain Link	Entire Site	405	LF	5	2-5 years	
	Fencing - Chain Link	Entire Site	598	LF	4	1-2 years	Leaning, corroded
	Fencing - Guard Rail	Entire Site	111	LF	7	10+ years	-
	Fencing - New Standard Ornamental	Entire Site	48	LF	6	6-10 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	223	LF	5	2-5 years	
Landsca	De						
	Benches	Entire Site	11	EA	6	6-10 years	
	Benches	Entire Site	1	EA	4	0-1 year	Deteriorated, warped
	Landscape - Grass	Entire Site	7,666	SF	6	10+ years	•
	Landscape - Hardscape- Concrete	Entire Site	4,352	SF	6	10+ years	
	Parkway trees	Entire Site	7	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	2,419	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	6,304	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	130	SF	6	10+ years	
Parking I	ot						
Ũ	Concrete Curbs	Site West	190	LF	6	6-10 years	
	Concrete Curbs	Site West	100	LF	4	0-1 year	Cracked, exposed rebar
	Surface - Asphalt	Site West	1,432	SF	5	6-10 years	•
	Surface - Asphalt	Site West	1,000	SF	4	0-1 year	Unpaved, holes spalling
Sidewalk	۲ <u>۶</u>						
	Sidewalks - Internal Walks	Entire Site	12	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	6	LF	4	0-1 year	Hole, spalling, wood over concrete
	Sidewalks - Perimeter Sidewalks	Entire Site	8,464	SF	6	10+ years	
Signage							
0 - 0 -	Flag Pole - Flag Pole	South	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	South	1	EA	6	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	intended Usage	Room Edeation	Number	Number		Alea	Alea	0.00	Doard
Kindergarten	Kindergarten	1st Floor	101	101	864	145	14	N	Y
Kindergarten	Regular Classroom	1st Floor	109	109	787	165	14	N	N.
Kindergarten	Regular Classroom	1st Floor	110	110	786	165	14	N	Y
Kindergarten	Regular Classroom	1st Floor	112	112	788	165	14	N	Ý
Multi Purpose Room	Regular Classroom	1st Floor	114	114	787	165	14	N	N
Multi Purpose Room	Regular Classroom	2nd Floor	205	205	788	165	14	N	N
Pre School	Pre School	1st Floor	102	102	996	118	6	N	Y
Regular Classroom	Regular Classroom	1st Floor	105	105	787	165	14	N	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	786	165	15	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	785	165	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	788	165	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	788	165	14	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	788	165	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	788	165	14	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	788	165	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	788	165	14	N	N
Store Room	Regular Classroom	1st Floor	103	103	787	165	14	N	N
Store Room	Regular Classroom	2nd Floor	208	208	788	165	14	N	N
Building : Addition				•					
Computer Lab	Regular Classroom	1st Floor	4	4	803	108	6	N	N
Office	Regular Classroom	1st Floor	2	2	803	118	6	N	N
Office	Regular Classroom	2nd Floor	216	216	813	118	6	N	Y
Office	Regular Classroom	2nd Floor	218	218	813	118	6	N	N
Office	Regular Classroom	2nd Floor	220	220	427	92	6	N	N
Regular Classroom	Regular Classroom	1st Floor	3	3	803	118	6	N	N
Regular Classroom	Regular Classroom	1st Floor	5	5	803	118	6	N	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	813	118	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	813	118	6	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	213	213	813	118	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	813	118	6	N	Y
Regular Classroom	Regular Classroom	2nd Floor	215	215	813	118	6	N	Y
Regular Classroom	Regular Classroom	2nd Floor	217	217	813	118	6	N	N
Store Room	Regular Classroom	1st Floor	6	6	803	118	6	N	N
Store Room	Regular Classroom	1st Floor	8	8	803	118	6	N	Ν
Store Room	Regular Classroom	2nd Floor	219	219	813	118	6	N	N