

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1928	3	60,570
Annex	2020	1	8,770
Linked Addition	1998	1	17,550
Campus Total			86,890

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Cell Equipment</u>							
	Cell Equipment - Antenna	Main upper roof	1	EA	7	10+ years	
	Cell Equipment - Cabinets	Main upper roof	1	EA	7	10+ years	
	Cell Equipment - Generator	Main upper roof	1	EA	7	10+ years	
<u>Entrance</u>							
	Entrance Control - Audio and Video	#1 - Main - NW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#1 - Main - NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - Main - NW	2	EA	6	10+ years	
	Exterior Stairs - Stone	#1 - Main - NW	106	LF	6	10+ years	Changed to match current observations
	Stair Handrail - Steel_Stair Handrail	#1 - Main - NW	21	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#10 - E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10 - E	1	EA	6	10+ years	
	Entrance Control - Audio and Video	#11 - NE	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#11 - NE	1	EA	6	10+ years	
	Exterior Doors - Side lite	#11 - NE	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	#11 - NE	1	EA	7	10+ years	
	Exterior Stairs - Concrete	#11 - NE	37	LF	7	10+ years	
	Exterior Stairs - Concrete	#11 - NE	5	LF	5	0-1 year	Cracking
	Stair Handrail - Steel_Stair Handrail	#11 - NE	25	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#12 - NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#12 - NW	1	EA	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Stairs - Stone	#12 - NW	66	LF	6	10+ years	Changed to match current observations
	Exterior Stairs - Stone	#12 - NW	2	LF	3	0-1 year	Cracking/chipping
	Stair Handrail - Steel_Stair Handrail	#12 - NW	12	LF	4	0-1 year	Corroded
	Exterior Doors - Exterior Steel Door	#2 - W	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - W	1	EA	6	10+ years	
	Exterior Stairs - Stone	#2 - W	3	LF	7	10+ years	
	Exterior Stairs - Stone	#2 - W	1	LF	5	0-1 year	Cracked/chipping
	Exterior Doors - Exterior Steel Door	#3 - SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - SW	2	EA	7	10+ years	
	Exterior Stairs - Stone	#3 - SW	106	LF	6	10+ years	Changed to match current observations
	Stair Handrail - Steel_Stair Handrail	#3 - SW	12	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#4 - SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - SW	2	EA	6	10+ years	
	Exterior Stairs - Stone	#4 - SW	50	LF	6	10+ years	
	Exterior Stairs - Stone	#4 - SW	6	LF	5	0-1 year	Cracking/chipping
	Stair Handrail - Steel_Stair Handrail	#4 - SW	14	LF	4	0-1 year	Rusted
	Exterior Doors - Exterior Steel Door	#5 - SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 - SE	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#5 - SE	20	LF	5	10+ years	
	Exterior Stairs - Stone	#5 - SE	48	LF	7	10+ years	
	Exterior Stairs - Stone	#5 - SE	2	LF	5	0-1 year	Cracking/chipping
	Stair Handrail - Steel_Stair Handrail	#5 - SE	20	LF	5	2-5 years	
	Exterior Doors - Overhead Rolling/ Garage Door	#9.1 - E	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9.2 - E	1	EA	6	10+ years	
Foundation							
	Foundation - Concrete	Entire Building	810	LF	7	10+ years	
	Foundation - Concrete	Entire Building	45	LF	5	0-1 year	Water seeping through the foundation. Cracking/deteriorating
	Superstructure - Concrete	Entire Building	25,500	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	30	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	7	10+ years	
Roof System							
	Coping - Terra Cotta	Boiler Room Roof	125	LF	7	10+ years	
	Downspouts - Interior Downspouts	Boiler Room Roof	36	LF	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Parapet - 16" - 30" Height	Boiler Room Roof	125	LF	7	10+ years	
	Roof - Modified Bitumen	Boiler Room Roof	1,765	SF	6	10+ years	
	Roof Structure - Concrete	Boiler Room Roof	1,765	SF	6	10+ years	
	Coping - Metal	Boiler Room, Low East	80	LF	5	10+ years	
	Downspouts - Interior Downspouts	Boiler Room, Low East	22	LF	6	10+ years	
	Parapet - 16" - 30" Height	Boiler Room, Low East	80	LF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	Boiler Room, Low East	825	SF	6	10+ years	
	Roof Structure - Concrete	Boiler Room, Low East	825	SF	7	10+ years	Inside the room is not accessible. Verizon property
	Coping - Terra Cotta	Low NW	20	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Low NW	11	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low NW	20	LF	7	10+ years	
	Roof - Modified Bitumen	Low NW	25	SF	6	10+ years	
	Roof Structure - Concrete	Low NW	25	SF	7	10+ years	
	Coping - Metal	Low SE, Courtyard	30	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Low SE, Courtyard	30	LF	6	10+ years	Corrected quantity
	Roof - Modified Bitumen	Low SE, Courtyard	96	SF	6	10+ years	
	Roof Structure - Concrete	Low SE, Courtyard	96	SF	7	10+ years	
	Coping - Terra Cotta	Low SW	20	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Low SW	11	LF	6	10+ years	Added to match current observations
	Parapet - 16" - 30" Height	Low SW	20	LF	7	10+ years	
	Roof - Modified Bitumen	Low SW	25	SF	6	10+ years	
	Roof Structure - Concrete	Low SW	25	SF	7	10+ years	
	Access Ladder - Metal	Main, Upper	1	EA	7	10+ years	
	Access Ladder - Metal	Main, Upper	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main, Upper	90	LF	6	10+ years	
	Coping - Terra Cotta	Main, Upper	455	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main, Upper	180	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main, Upper	25	LF	7	10+ years	Recombined quantities
	Parapet - Parapet > 30"	Main, Upper	421	LF	7	10+ years	
	Parapet - Parapet > 30"	Main, Upper	12	LF	4	0-1 year	Counter flashing is loose and falling
	Roof - Modified Bitumen	Main, Upper	11,020	SF	6	10+ years	
	Roof Hatch - Metal	Main, Upper	1	EA	7	10+ years	
	Roof Structure - Concrete	Main, Upper	11,020	SF	7	10+ years	
	Access Ladder - Metal	Mid South Roof, Gym	1	EA	7	10+ years	
	Coping - Terra Cotta	Mid South Roof, Gym	490	LF	6	10+ years	
	Downspouts - Interior Downspouts	Mid South Roof, Gym	116	LF	6	10+ years	
	Parapet - 16" - 30" Height	Mid South Roof, Gym	390	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Mid South Roof, Gym	100	LF	7	10+ years	
	Roof - Modified Bitumen	Mid South Roof, Gym	8,085	SF	5	6-10 years	
	Roof Hatch - Metal	Mid South Roof, Gym	1	EA	7	10+ years	Quantity changed to match current observations
	Roof Structure - Concrete	Mid South Roof, Gym	8,085	SF	7	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Access Ladder - Metal	North Mid-Roof, Auditorium	2	EA	7	10+ years	
	Coping - Terra Cotta	North Mid-Roof, Auditorium	265	LF	6	10+ years	
	Downspouts - Interior Downspouts	North Mid-Roof, Auditorium	58	LF	6	10+ years	
	Parapet - 16" - 30" Height	North Mid-Roof, Auditorium	235	LF	7	10+ years	
	Parapet - Parapet < 16" Height	North Mid-Roof, Auditorium	30	LF	7	10+ years	
	Roof - Modified Bitumen	North Mid-Roof, Auditorium	3,828	SF	6	6-10 years	
	Roof Hatch - Metal	North Mid-Roof, Auditorium	1	EA	7	10+ years	
	Roof Structure - Concrete	North Mid-Roof, Auditorium	3,828	SF	7	10+ years	

Walls

Cheek-Wall - Stone	Entire Building	154	SF	7	10+ years	Recombined quantities
Cheek-Wall - Stone	Entire Building	36	SF	5	1-2 years	Loose stones. Open joints
Cornice - Terra Cotta	Entire Building	995	LF	7	10+ years	
Exterior Walls - Brick	Entire Building	30,135	SF	7	10+ years	Recombined quantities
Exterior Walls - Stone-Cast	Entire Building	450	SF	7	10+ years	

Windows

Curtain wall - Glazed Double Pane	Entire Building	16	SF	7	10+ years	
Curtain wall - Louver	Entire Building	1,405	SF	7	10+ years	
Guard - Guards perforated	Entire Building	162	SF	7	10+ years	
Guard - Guards perforated	Entire Building	2,080	SF	6	10+ years	
Lintels - Steel	Entire Building	620	LF	7	10+ years	
Lintels - Terra Cotta	Entire Building	501	LF	7	10+ years	
Windows - Casement Aluminum Double-pane	Entire Building	22	SF	7	10+ years	
Windows - Casement Lexan	Entire Building	100	SF	7	10+ years	
Windows - Casement Steel	Entire Building	100	SF	7	10+ years	
Windows - Sash Aluminum Double-pane	Entire Building	13,696	SF	7	10+ years	
Windows - Sash Aluminum Double-pane	Entire Building	40	SF	7	10+ years	
Windows - Sash Aluminum Double-pane	Entire Building	40	SF	6	10+ years	

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Emergency System</u>							
	Emergency Battery Packs - Auditorium and Aisle Lighting	1st Floor	7	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	3	EA	6	6-10 years	
	Emergency Battery Packs - Gym	1st Floor	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	1st Floor	2	EA	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Emergency A/C Power - Auditorium and	Entire Building	2,748	SF	6	6-10 years	

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Aisle Lighting						
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,650	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2,983	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,298	SF	6	6-10 years	
	Exit Signs - Auditorium	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Signs repaired. Legible.
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	60,570	SF	6	6-10 years	

Main Service

	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	60,570	SF	6	6-10 years	Connected to addition and annex buildings on campus

Power Distribution

	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	3	EA	7	6-10 years	

Category : Fire Protection
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarm							
	Fire ALarm Annunciator	Boiler Room	1	EA	7	6-10 years	
	Fire Alarm Panel	Boiler Room	1	EA	7	6-10 years	Fire alarm panel is in good working condition. Fairly new serves main building and linked addition.
	Fire Alarm Strobe Lights	Boiler Room	60,570	SF	6	6-10 years	
	Fire Alarm_System	Boiler Room	60,570	SF	5	6-10 years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Handling Systems							
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	6	6-10 years	AHU 1 in good working condition
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	6	6-10 years	Auxiliaries in good condition
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	10	EA	6	6-10 years	In good working condition
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	200	LF	6	6-10 years	In good condition
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Basement	1	EA	6	6-10 years	AHU 2 in good working condition
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 4000 - 8000 cfm	Basement	1	EA	6	6-10 years	Auxiliaries in good condition
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	100	LF	6	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years	AHU 3 in good working condition
	Air Intake	Basement	1	EA	6	6-10 years	In good condition
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years	Auxiliaries in good working condition
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	100	LF	6	6-10 years	In good condition
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 8001 - 15000 cfm	Basement	1	EA	6	6-10 years	AHU 4 in good working condition
	Air Intake	Basement	1	EA	6	6-10 years	Looked to be in good condition
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	6	6-10 years	Auxiliaries in good working condition
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	4	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	50	LF	6	6-10 years	
Boiler Systems							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	6	6-10 years	Auxiliary in good working
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	Chemical feed system in good working condition
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	Chemical feeder in good working condition
	Combustion Dampers	Boiler Room	2	EA	4	1-2 years	Slight corrosion, observed, and combustion dampers
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Older, slight corrosion, but in good working condition per observation and engineer
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	Pumps in good working condition
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	6-10 years	Boilers in good working condition

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	6-10 years	Boilers in good working condition condition
	Non Condensing- Fire Tube- Scotch Marine-						
	Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	400	LF	6	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	56	EA	6	6-10 years	
	Steam Traps	Boiler Room					

Gas Booster

Gas Booster	Boiler Room	2	EA	6	6-10 years	
-------------	-------------	---	----	---	------------	--

Heating Devices

Radiators - Steam	1st and 2nd Floor	9	EA	6	6-10 years	In good working condition
Unit Heater - Gas	Boiler Room	1	EA	6	6-10 years	
Unit Heater - Steam	Boiler Room	1	EA	6	6-10 years	In good working condition
Fin Tube - Steam	Entire Building	84	LF	6	6-10 years	
Wall Heater - Electric	Entire Building	15	EA	6	6-10 years	

Temperature Control

Electric Thermostat	Entire Building	1	EA	6	6-10 years	
Pneumatic System	Entire Building	60,570	SF	6	6-10 years	
Thermostats - Pneumatic	Entire Building	26	EA	6	6-10 years	

Ventilation

Exhaust Fans- Indoor - 500 - 1500 CFM	Roof, East Facade, 1st and 2nd Floor	1	EA	6	6-10 years	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof, East Facade, 1st and 2nd Floor	3	EA	6	6-10 years	
Type II Exhaust Hood- Warming Kitchen	Roof, East Facade, 1st and 2nd Floor	1	EA	6	6-10 years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Hot Water</u>							
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
<u>Piping</u>							
	Domestic Piping-Hot Water Return Lines	Entire Building	60,570	SF	6	6-10 years	Piping appears to be in good condition. Pressure is good, per engineer.
	Domestic Piping-Hot Water Return Risers	Entire Building	60,570	SF	6	6-10 years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	60,570	SF	6	6-10 years	Piping appears to be in good condition. Pressure is good per engineer.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	60,570	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	60,570	SF	6	6-10 years	Piping appears to be in good condition. Pressure is good per engineer.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	60,570	SF	6	6-10 years	
	Sanitary Piping	Entire Building	60,570	SF	5	6-10 years	
	Storm Piping	Entire Building	60,570	SF	5	6-10 years	
	Vent Piping	Entire Building	60,570	SF	5	6-10 years	

Pumps

Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	6	6-10 years
Pumps - Sump-Duplex	Boiler Room	1	EA	6	6-10 years

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administrative Suites/Offices							
	Ceiling - Plaster/Drywall	1st Floor - Asst. Principal Office - SE End of Main Suite	147	SF	7	10+ years	
	Doors - Side-lite	1st Floor - Asst. Principal Office - SE End of Main Suite	32	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Asst. Principal Office - SE End of Main Suite	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Asst. Principal Office - SE End of Main Suite	2	EA	7	10+ years	
	Floor - Carpet	1st Floor - Asst. Principal Office - SE End of Main Suite	147	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Asst. Principal Office - SE End of Main Suite	1	EA	7	10+ years	
	Power Distribution	1st Floor - Asst. Principal Office - SE End of Main Suite	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Asst. Principal Office - SE End of Main Suite	600	SF	7	10+ years	
	AC Unit	1st Floor - Faculty Lounge - Room 104	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Faculty Lounge - Room 104	300	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Faculty Lounge - Room 104	9	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor - Faculty Lounge - Room 104	1	EA	7	10+ years	
	Floor - Wood	1st Floor - Faculty Lounge - Room 104	300	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Faculty Lounge - Room 104	4	EA	7	10+ years	
	Power Distribution	1st Floor - Faculty Lounge - Room 104	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Faculty Lounge - Room 104	368	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Gym	118	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Gym	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Gym	118	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Gym	2	EA	7	10+ years	
	Power Distribution	1st Floor - Gym	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Gym	540	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Lunchroom	38	SF	7	10+ years	
	Doors - Side-lite	1st Floor - Lunchroom	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Lunchroom	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Lunchroom	38	SF	7	10+ years	
	Lighting - Lay-in	1st Floor - Lunchroom	1	EA	7	10+ years	
	Power Distribution	1st Floor - Lunchroom	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Lunchroom	325	SF	7	10+ years	
	AC Unit	1st Floor - Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Main Office	386	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Main Office	2	EA	7	10+ years	
	Floor - Carpet	1st Floor - Main Office	260	SF	7	6-10 years	
	Floor - Tile	1st Floor - Main Office	106	SF	7	10+ years	
	Floor - Tile	1st Floor - Main Office	20	SF	4	1-2 years	Cracking tiles
	Lighting - Pendent/Surface	1st Floor - Main Office	4	EA	7	10+ years	
	Power Distribution	1st Floor - Main Office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Main Office	1,026	SF	7	10+ years	
	AC Unit	1st Floor - Principal - SW Corner of Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal - SW Corner of Main Office	158	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Principal - SW Corner of Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal - SW Corner of Main Office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor - Principal - SW Corner of Main Office	158	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Principal - SW Corner of	1	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Power Distribution	Main Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal - SW Corner of Main Office	650	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	94	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	94	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Power Distribution	2nd Floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	366	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6	SF	6	10+ years	Chipping paint
	Work Sink	2nd Floor	1	EA	7	10+ years	
	AC Unit	2nd floor- faculty lounge	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor- faculty lounge	341	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor- faculty lounge	1	EA	7	10+ years	
	Floor - Tile	2nd floor- faculty lounge	341	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd floor- faculty lounge	5	EA	7	10+ years	
	Power Distribution	2nd floor- faculty lounge	12	EA	7	6-10 years	
	Walls - Masonry	2nd floor- faculty lounge	290	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd floor- faculty lounge	436	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Upper Boiler Room - Engineers office	135	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Upper Boiler Room - Engineers office	1	EA	7	10+ years	
	Floor - Carpet	Basement - Upper Boiler Room - Engineers office	135	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement - Upper Boiler Room - Engineers office	1	EA	7	6-10 years	
	Power Distribution	Basement - Upper Boiler Room - Engineers office	4	EA	7	10+ years	
	Storage/ Closet	Basement - Upper Boiler Room - Engineers office	200	SF	7	10+ years	
	Storage/ Closet	Basement - Upper Boiler Room - Engineers office	180	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - Upper Boiler Room - Engineers office	435	SF	7	10+ years	
	AC Unit	Room 302	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 302	280	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 302	1	EA	7	10+ years	
	Floor - Wood	Room 302	280	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 302	5	EA	7	10+ years	
	Walls - Masonry	Room 302	286	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 302	610	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	Room 302	5	SF	6	10+ years	Chipped paint
Auditorium & Theater							
	Balcony Seating	1st Floor	101	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,748	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	7	EA	7	10+ years	
	Floor - Concrete	1st Floor	454	SF	7	10+ years	
	Floor - Tile	1st Floor	2,294	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	8	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	12	EA	7	10+ years	
	Main Floor Seating	1st Floor	126	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	539	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	20	LF	7	10+ years	
	Stairs - Terrazzo	1st Floor	130	LF	7	10+ years	
	Storage/ Closet	1st Floor	73	SF	7	10+ years	
	Storage/ Closet	1st Floor	439	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	172	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,506	SF	7	10+ years	
Gymnasium							
	Ceiling - Lay-in	1st Floor	2,983	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Wood	1st Floor	2,983	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	Engineer has requested several times to have lighting replaced with LED lights. Each time a bulb is replaced, he must rent a lift.
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Walls - Masonry	1st Floor	1,817	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,634	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	409	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	409	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	352	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	705	SF	7	10+ years	
Lunch & Multipurpose Room							
	AC Unit	1st Floor	4	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,298	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,298	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	22	EA	7	10+ years	
	Serving Line	1st Floor	20	LF	7	10+ years	
	Walls - Metal Panel	1st Floor	713	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,069	SF	7	10+ years	
Mechanical/ Service Rooms							
	Janitor's Closet	1st Floor	110	SF	5	10+ years	
	Janitor's Closet	2nd Floor	110	SF	5	10+ years	
	Janitor's Closet	3rd Floor	27	SF	7	10+ years	
	Air Tunnel	Basement	1,698	SF	7	10+ years	
	Air Tunnel	Basement	788	SF	7	10+ years	
	Auditorium Plenums	Basement	3,550	SF	7	10+ years	
	Boiler Room	Basement	1,944	SF	7	10+ years	
	Coal Room	Basement	600	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	135	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,454	SF	7	10+ years	
	Storage Room	Basement	414	SF	7	10+ years	
	Storage Room	Basement	530	SF	7	10+ years	
Restroom							
	Accessories	1st Floor	214	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	214	SF	7	10+ years	
	Doors - Transom Window	1st Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	4	1-2 years	Damaged doors
	Floor - Tile Ceramic/ Porcelain	1st Floor	214	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	10+ years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	4	EA	7	10+ years	
	Walls - Masonry	1st Floor	536	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	325	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	390	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	345	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	345	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	345	SF	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	10+ years	
	Partitions	1st Floor	7	EA	7	10+ years	
	Walls - Masonry	1st Floor	361	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	723	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	64	SF	7	10+ years	
	Water Closet	1st Floor	7	EA	7	10+ years	
	Accessories	1st Floor - Principal's Office	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office	19	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office	5	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal's Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Principal's Office	24	SF	7	10+ years	
	Lavatory	1st Floor - Principal's Office	1	EA	7	2-5 years	
	Lighting - Pendent/Surface	1st Floor - Principal's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal's Office	116	SF	6	10+ years	
	Water Closet	1st Floor - Principal's Office	1	EA	7	10+ years	
	Accessories	1st Floor - Unisex	125	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Unisex	125	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Unisex	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Unisex	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Unisex	125	SF	7	10+ years	
	Hand Dryer	1st Floor - Unisex	1	EA	7	6-10 years	
	Lavatory	1st Floor - Unisex	2	EA	6	2-5 years	
	Lighting - Pendent/Surface	1st Floor - Unisex	1	EA	7	10+ years	
	Partitions	1st Floor - Unisex	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Unisex	572	SF	7	10+ years	
	Water Closet	1st Floor - Unisex	2	EA	7	6-10 years	
	Accessories	2nd Floor	345	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	345	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	345	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	10+ years	
	Partitions	2nd Floor	7	EA	7	10+ years	
	Walls - Masonry	2nd Floor	360	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	426	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	6	10+ years	Cracked paint
	Walls - Tile Ceramic/ Porcelain	2nd Floor	64	SF	7	10+ years	
	Water Closet	2nd Floor	7	EA	7	10+ years	
	Accessories	2nd Floor	214	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	214	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	4	1-2 years	Damaged finish
	Floor - Tile Ceramic/ Porcelain	2nd Floor	214	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendant/Surface	2nd Floor	4	EA	7	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	4	EA	7	10+ years	
	Walls - Masonry	2nd Floor	268	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	268	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	536	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor - Unisex	125	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Unisex	124	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Unisex	1	SF	6	10+ years	Chipping paint
	Doors - Wood Doors inclu hw	2nd Floor - Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Unisex	125	SF	7	10+ years	
	Hand Dryer	2nd Floor - Unisex	1	EA	7	6-10 years	
	Lavatory	2nd Floor - Unisex	2	EA	7	2-5 years	
	Lighting - Pendant/Surface	2nd Floor - Unisex	1	EA	7	10+ years	
	Partitions	2nd Floor - Unisex	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Unisex	532	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Unisex	40	SF	6	10+ years	Damaged paint
	Water Closet	2nd Floor - Unisex	2	EA	7	10+ years	
	Accessories	3rd Floor	214	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	210	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	6	10+ years	Chipping
	Doors - Transom Window	3rd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	4	0-1 year	Damaged
	Floor - Tile Ceramic/ Porcelain	3rd Floor	214	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Pendant/Surface	3rd Floor	4	EA	7	10+ years	
	Partitions	3rd Floor	6	EA	7	10+ years	
	Walls - Masonry	3rd Floor	337	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Masonry	3rd Floor	10	SF	4	0-1 year	Missing masonry
	Walls - Plaster/Drywall	3rd Floor	665	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	6	10+ years	Cracked paint
	Walls - Tile Ceramic/ Porcelain	3rd Floor	30	SF	7	10+ years	
	Water Closet	3rd Floor	5	EA	7	10+ years	
	Water Closet	3rd Floor	1	EA	4	0-1 year	Out of order
	Accessories	3rd Floor	214	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	214	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	4	1-2 years	Damaged finish
	Floor - Tile Ceramic/ Porcelain	3rd Floor	214	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	10+ years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	4	EA	7	10+ years	
	Walls - Masonry	3rd Floor	357	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	315	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	6	10+ years	Cracked paint
	Walls - Structural Glazed Tile	3rd Floor	390	SF	7	10+ years	
	Water Closet	3rd Floor	2	EA	7	10+ years	
	Accessories	Basement - Engineer Office	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Engineer Office	28	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Engineer Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - Engineer Office	28	SF	7	10+ years	
	Lavatory	Basement - Engineer Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement - Engineer Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer Office	165	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer Office	10	SF	6	10+ years	
	Water Closet	Basement - Engineer Office	1	EA	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #106 (Kindergarten)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	576	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	576	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,240	SF	7	10+ years	
Classroom #107 (Art Room)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	11	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,160	SF	7	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
Classroom #108 (Office)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	237	SF	7	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	237	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	871	SF	7	10+ years	
Classroom #110 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	715	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,074	SF	7	10+ years	
Classroom #113 (Health)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	404	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	384	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Damaged tiles

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	800	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #115 (Kindergarten)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	715	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	6	10+ years	
Classroom #201 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	13	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	Cracks
	Walls - Plaster/Drywall	2nd Floor	1,070	SF	6	10+ years	
Classroom #203 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	13	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	710	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	6	10+ years	Chipping paint
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
Classroom #204 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,070	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	10+ years	Cracks
Classroom #205 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	13	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	715	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
Classroom #206 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	715	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
Classroom #207 (Kindergarten)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,070	SF	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	10+ years	Cracks
Classroom #208 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	715	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	10+ years	
Classroom #209 (Regular Classroom)							
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	72	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	Qty updated
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	6	6-10 years	Qty updated
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	Qty updated
	Marker Board	2nd Floor	25	LF	6	6-10 years	Qty updated
	Storage/ Closet	2nd Floor	8	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	996	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4	SF	6	10+ years	Cracks
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroom #210 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	31	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	605	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	6	10+ years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	610	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	7	SF	6	10+ years	Peeling paint
Classroom #211 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	670	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	2nd Floor	670	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	7	10+ years	
Classroom #212 (Office)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	31	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	300	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	300	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	814	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	Peeling paint
Classroom #301 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	700	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	15	SF	6	10+ years	Chipping
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,030	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	6	10+ years	Chipping paint
Classroom #303 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	700	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	15	SF	6	10+ years	Chipping
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,087	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	6	10+ years	Small cracks around door

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #304 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	40	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	705	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	6	10+ years	Chipping paint
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,090	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	10+ years	Cracks
Classroom #305 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	715	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,090	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	10+ years	Cracks
Classroom #306 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	40	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	710	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	6	10+ years	Chipping
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years	
	Floor - Wood	3rd Floor	715	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	125	SF	7	10+ years	Sq-footage adjusted
	Walls - Plaster/Drywall	3rd Floor	1,170	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	6	10+ years	Cracks
Classroom #307 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	3rd Floor	715	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	715	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,075	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	10+ years	Cracks

Classroom #308 (Regular Classroom)

	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	40	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	710	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	6	10+ years	Chipping
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	715	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,095	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	6	10+ years	Peeling paint

Classroom #310 (Special Program)

	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	27	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	300	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	300	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	10+ years	Relamp
	Marker Board	3rd Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,027	SF	6	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	3,574	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	6-10 years	Corrected type and quantity
	Floor - Terrazzo	1st Floor	894	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	2,680	SF	7	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	32	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	160	EA	7	10+ years	
	Walls - Masonry	1st Floor	4,774	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,182	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	58	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,228	SF	6	6-10 years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	Corrected type and quantity
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	Corrected quantity
	Floor - Terrazzo	2nd Floor	774	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,454	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	28	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	162	EA	6	10+ years	
	Walls - Masonry	2nd Floor	4,571	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3,047	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	116	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,848	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	500	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,348	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	98	EA	6	10+ years	
	Walls - Masonry	3rd Floor	2,590	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,316	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	116	SF	7	10+ years	

Safety

Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
Security Cameras	1st Floor	7	EA	7	6-10 years	

Stairs

Ceiling - Plaster/Drywall	North West	284	SF	7	10+ years	
Ceiling - Plaster/Drywall	North West	2	SF	6	10+ years	Chipping
Floor - Terrazzo	North West	256	SF	7	10+ years	
Handrails	North West	128	LF	7	10+ years	
Lighting - Pendent/Surface	North West	5	EA	7	10+ years	
Stairs - Terrazzo	North West	566	LF	7	10+ years	
Stairs - Terrazzo	North West	10	LF	5	6-10 years	Hairline cracks in treads
Walls - Masonry	North West	1,092	SF	7	10+ years	
Walls - Plaster/Drywall	North West	1,072	SF	7	10+ years	
Walls - Plaster/Drywall	North West	20	SF	6	10+ years	Cracking
Ceiling - Plaster/Drywall	South East	288	SF	7	10+ years	
Floor - Terrazzo	South East	256	SF	7	10+ years	
Handrails	South East	128	LF	7	10+ years	
Lighting - Pendent/Surface	South East	2	EA	7	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Stairs - Terrazzo	South East	576	LF	7	10+ years	
	Walls - Masonry	South East	1,092	SF	7	10+ years	
	Walls - Plaster/Drywall	South East	1,082	SF	7	10+ years	
	Walls - Plaster/Drywall	South East	10	SF	6	10+ years	Peeling paint
	Ceiling - Plaster/Drywall	South West	288	SF	7	10+ years	
	Floor - Terrazzo	South West	256	SF	7	10+ years	
	Handrails	South West	128	LF	7	10+ years	
	Lighting - Pendent/Surface	South West	5	EA	7	10+ years	
	Stairs - Terrazzo	South West	576	LF	7	10+ years	
	Walls - Masonry	South West	1,092	SF	7	10+ years	
	Walls - Plaster/Drywall	South West	1,062	SF	7	10+ years	
	Walls - Plaster/Drywall	South West	30	SF	5	10+ years	Cracking

Category : Exterior
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Entrance - 1	1	EA	7	6-10 years	
	Exterior Doors - Side lite	Entrance - 1	2	EA	7	10+ years	
	Exterior Doors - Store Front	Entrance - 1	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance - 1	2	EA	7	10+ years	
	Power Door Operator and Controls	Entrance - 1	1	EA	7	10+ years	
	Entrance Control - Audio and Video	Entrance - 2	1	EA	7	6-10 years	
	Exterior Doors - Store Front	Entrance - 2	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance - 2	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance - 3	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance - 4	1	EA	6	10+ years	
Foundation							
	Foundation - Concrete	Entire Building	412	LF	7	10+ years	
	Superstructure - Slab on Grade	Entire Building	8,770	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	10+ years	
Roof System							
	Access Ladder - Metal	Entire Building	1	EA	7	10+ years	
	Coping - Metal	Entire Building	412	LF	7	10+ years	
	Downspouts - Interior Downspouts	Entire Building	28	LF	6	10+ years	
	Parapet - 16" - 30" Height	Entire Building	412	LF	7	10+ years	
	Roof - Modified Bitumen	Entire Building	8,770	SF	6	10+ years	
	Roof Hatch - Metal	Entire Building	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Entire Building	8,770	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	98	SF	7	10+ years	Damaged board sections resulting from children's activities
	Exterior Walls - Hardie Board	Entire Building	5,712	SF	6	10+ years	
	Exterior Walls - Hardie Board	Entire Building	880	SF	3	0-1 year	
	Exterior Walls - Stone-Cast	Entire Building	1,030	SF	7	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	756	SF	7	10+ years	
	Windows - Casement Aluminum	Entire Building	756	SF	7	10+ years	
	Windows - Insulated Panel	Entire Building	112	SF	7	10+ years	

Category : Electrical
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergency System							
	Security System - CCTV	1st Floor	8,770	SF	6	6-10 years	PA is fed from main building. PA system is new.
	Security System - Intrusion Detection	1st Floor	8,770	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	1st Floor	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	1st Floor	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	1st Floor	1,900	SF	6	6-10 years	
Main Service							
	PA System	1st Floor	8,770	SF	7	6-10 years	PA is fed from main building. PA system is new.
	Main Electrical Service - 800 A and Less than 120/208/3PH	Electrical Room	1	EA	7	10+ years	
Power Distribution							
	Lighting and Power Panels - Above 100 A	1st Floor	3	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	1st Floor	1	EA	7	10+ years	

Category : Fire Protection
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alarm</u>							
	Fire ALarm Anunciator	1st Floor	1	EA	7	10+ years	
	Fire Alarm Panel	1st Floor	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	1st Floor	8,770	SF	7	10+ years	
	Fire Alarm_System	1st Floor	8,770	SF	7	10+ years	Connected to main building
<u>Sprinkler System</u>							
	Sprinkler Heads	Entire Building	8,770	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	8,770	SF	7	6-10 years	
	Wet Sprinkler System	Entire Building	8,770	SF	7	6-10 years	

Category : Mechanical
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Air Conditioning</u>							
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	6-10 years	
<u>Air Handling Systems</u>							

Category : Mechanical
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Air Handling Unit- Package Multi Zone- Outdoor Roof Mounted - Electric and DX Cooling Coil - Less than 6000 cfm	Roof	1	EA	7	10+ years	
	Air Handling Unit- Package Multi Zone- Outdoor Roof Mounted - Electric and DX Cooling Coil - Less than 6000 cfm	Roof	1	EA	7	10+ years	
	Air Intake	Roof	2	EA	7	10+ years	
	VAV Box	VAV Boxes	7	EA	7	10+ years	Located above ceiling

Heating Devices

Cabinet Heaters - With Electric Coil	1st Floor	2	EA	6	6-10 years
Wall Heater - Electric	1st Floor	2	EA	7	10+ years
Unit Heater - Electric	1st Floor	1	EA	7	10+ years

Temperature Control

DDC System	1st Floor	8,770	SF	7	10+ years
Electric Thermostat	1st Floor	1	EA	7	10+ years
Thermostats - DDC	1st Floor	10	EA	7	10+ years

Ventilation

Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	10+ years
---	------	---	----	---	-----------

Category : Plumbing
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Water							
	Electric Heater - Less than 20 KW	1st Floor	2	EA	7	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	8,770	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	8,770	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	8,770	SF	7	10+ years	
	Sanitary Piping	Entire Building	8,770	SF	7	10+ years	
	Storm Piping	Entire Building	8,770	SF	7	10+ years	
	Vent Piping	Entire Building	8,770	SF	7	10+ years	

Category : Room
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Administrative Suites/Offices</u>							
	Ceiling - Lay-in	504 Teacher's lounge	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	504 Teacher's lounge	1	EA	7	10+ years	
	Floor - Tile	504 Teacher's lounge	140	SF	7	10+ years	
	Lighting - Lay-in	504 Teacher's lounge	4	EA	7	6-10 years	
	Power Distribution	504 Teacher's lounge	8	EA	7	10+ years	
	Walls - Plaster/Drywall	504 Teacher's lounge	400	SF	7	10+ years	
	Ceiling - Lay-in	508 Workroom	126	SF	7	10+ years	
	Doors - Wood Doors inclu hw	508 Workroom	1	EA	7	10+ years	
	Floor - Tile/Sheet	508 Workroom	126	SF	7	10+ years	
	Lighting - Lay-in	508 Workroom	6	EA	7	6-10 years	
	Power Distribution	508 Workroom	4	EA	7	10+ years	
	Walls - Plaster/Drywall	508 Workroom	400	SF	7	10+ years	
	Ceiling - Lay-in	Clinician 508	192	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Clinician 508	1	EA	7	10+ years	
	Floor - Tile/Sheet	Clinician 508	192	SF	7	10+ years	
	Lighting - Lay-in	Clinician 508	4	EA	7	6-10 years	
	Power Distribution	Clinician 508	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Clinician 508	550	SF	7	10+ years	
<u>Kitchen</u>							
	Ceiling - Lay-in	513 Food Prep	288	SF	7	10+ years	
	Doors - Wood Doors inclu hw	513 Food Prep	1	EA	7	10+ years	
	Floor - Tile/Sheet	513 Food Prep	288	SF	7	10+ years	
	Lighting - Lay-in	513 Food Prep	8	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	513 Food Prep	700	SF	7	10+ years	
<u>MDF_IDF</u>							
	Doors - Wood Doors inclu hw	511 IDF	1	EA	7	10+ years	
	Finishes	511 IDF	72	SF	7	6-10 years	
	Other Cooling Unit	511 IDF	1	EA	7	6-10 years	Ductless split
<u>Mechanical/ Service Rooms</u>							
	Janitor's Closet	1st floor	105	SF	7	10+ years	
	Storage Room	1st floor	80	SF	7	10+ years	
<u>Restroom</u>							
	Accessories	500	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	500	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	500	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	500	65	SF	7	10+ years	
	Floor Drain	500	1	EA	7	10+ years	
	Hand Dryer	500	1	EA	7	6-10 years	

Category : Room
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	500	1	EA	7	10+ years	
	Lighting - Pendent/Surface	500	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	500	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	500	180	SF	7	10+ years	
	Water Closet	500	1	EA	7	10+ years	
	Accessories	501	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	501	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	501	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	501	65	SF	7	10+ years	
	Floor Drain	501	1	EA	7	10+ years	
	Hand Dryer	501	1	EA	7	6-10 years	
	Lavatory	501	1	EA	7	10+ years	
	Lighting - Pendent/Surface	501	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	501	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	501	180	SF	7	10+ years	
	Water Closet	501	1	EA	7	10+ years	
	Accessories	502	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	502	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	502	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	502	65	SF	7	10+ years	
	Floor Drain	502	1	EA	7	10+ years	
	Hand Dryer	502	1	EA	7	6-10 years	
	Lavatory	502	1	EA	7	10+ years	
	Lighting - Pendent/Surface	502	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	502	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	502	180	SF	7	10+ years	
	Water Closet	502	1	EA	7	10+ years	
	Accessories	503	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	503	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	503	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	503	65	SF	7	10+ years	
	Floor Drain	503	1	EA	7	10+ years	
	Hand Dryer	503	1	EA	7	6-10 years	
	Lavatory	503	1	EA	7	10+ years	
	Lighting - Pendent/Surface	503	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	503	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	503	180	SF	7	10+ years	
	Water Closet	503	1	EA	7	10+ years	
	Accessories	506	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	506	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	506	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	506	65	SF	7	10+ years	
	Floor Drain	506	1	EA	7	10+ years	
	Hand Dryer	506	1	EA	7	6-10 years	

Category : Room
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	506	1	EA	7	10+ years	
	Lighting - Pendent/Surface	506	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	506	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	506	180	SF	7	10+ years	
	Water Closet	506	1	EA	7	10+ years	
	Accessories	507	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	507	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	507	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	507	65	SF	7	10+ years	
	Floor Drain	507	1	EA	7	10+ years	
	Hand Dryer	507	1	EA	7	6-10 years	
	Lavatory	507	1	EA	7	10+ years	
	Lighting - Pendent/Surface	507	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	507	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	507	180	SF	7	10+ years	
	Water Closet	507	1	EA	7	10+ years	
	Accessories	Unisex RR East	80	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex RR East	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex RR East	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex RR East	80	SF	7	10+ years	
	Floor Drain	Unisex RR East	1	EA	7	10+ years	
	Hand Dryer	Unisex RR East	1	EA	7	6-10 years	
	Lavatory	Unisex RR East	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex RR East	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Unisex RR East	132	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex RR East	198	SF	7	10+ years	
	Water Closet	Unisex RR East	1	EA	7	10+ years	
	Accessories	Unisex west	80	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex west	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex west	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex west	80	SF	7	10+ years	
	Floor Drain	Unisex west	1	EA	7	10+ years	
	Hand Dryer	Unisex west	1	EA	7	6-10 years	
	Lavatory	Unisex west	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex west	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Unisex west	132	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex west	198	SF	7	10+ years	
	Water Closet	Unisex west	1	EA	7	10+ years	

Category : Classroom
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #500 (Pre School)							
	Casework	1st Floor	10	LF	7	10+ years	

Category : Classroom
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	1st Floor	792	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	792	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,045	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #501 (Pre School)							
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	792	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	792	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	1st Floor	1,045	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #502 (Pre School)							
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	728	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,020	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #503 (Pre School)							
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	728	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,020	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #506 (Pre School)							

Category : Classroom
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	728	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,020	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	

Classroom #507 (Pre School)

	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	728	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	728	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,020	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	

Category : Interior
Building : Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	1,152	SF	7	10+ years	Recombined quantities
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,152	SF	7	10+ years	Recombined quantities
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	350	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	2,400	SF	7	10+ years	

Safety

	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
	Security Cameras	1st Floor	6	EA	7	10+ years	Not previously assessed

Category : Exterior
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#6 - SE	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#6 - SE	2	EA	6	10+ years	Changed to match current observations
	Power Door Operator and Controls	#6 - SE	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#7 - S	2	EA	6	10+ years	Changed to match current observations
	Ramp Handrail - Steel_Ramp Handrail	#7 - S	40	LF	5	0-1 year	Corroded
	Ramp Handrail - Steel_Ramp Handrail	#7 - S	10	LF	5	0-1 year	Missing
	Ramps - Concrete	#7 - S	25	LF	5	0-1 year	Cracking
	Exterior Doors - Exterior FRP Door	#8 - N	2	EA	7	10+ years	Changed to match current observations. New door
	Ramp Handrail - Steel_Ramp Handrail	#8 - N	75	LF	5	0-1 year	Corroded and loose/disconnected
	Ramps - Concrete	#8 - N	35	LF	7	10+ years	Divided out damaged quantities
	Ramps - Concrete	#8 - N	5	LF	5	0-1 year	Cracking
	Exterior Doors - Exterior Steel Door	#9 - SW	1	EA	7	10+ years	
Foundation							
	Foundation - Concrete	Entire Building	760	LF	7	10+ years	
	Superstructure - Steel	Entire Building	17,550	SF	7	10+ years	Recombined quantities
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	16	EA	7	6-10 years	
Roof System							
	Chimney - Metal Flue	Linked Addition Main Roof	60	LF	7	10+ years	
	Coping - Metal	Linked Addition Main Roof	620	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Linked Addition Main Roof	84	LF	6	10+ years	
	Roof - Metal	Linked Addition Main Roof	16,800	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/Concrete Topping	Linked Addition Main Roof	16,800	SF	7	10+ years	
	Coping - Metal	Linked Roof	90	LF	7	10+ years	
	Downspouts - Interior Downspouts	Linked Roof	24	LF	6	10+ years	
	Parapet - 16" - 30" Height	Linked Roof	8	LF	6	10+ years	
	Roof - Modified Bitumen	Linked Roof	750	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/Concrete Topping	Linked Roof	750	SF	7	10+ years	
Walls							
	Canopy - Metal	Entire Building	54	SF	7	10+ years	Recombined quantities
	Cornice - Metal Projecting	Entire Building	760	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	5,292	SF	6	10+ years	

Category : Exterior
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Walls - Stone-Cast	Entire Building	80	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	228	SF	7	10+ years	

Windows

	Curtain wall - Louver	Entire Building	192	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	1,900	SF	7	10+ years	
	Lintels - Steel	Entire Building	266	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,900	SF	6	10+ years	

Category : Electrical
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Emergency System

	Emergency A/C Power - Corridors and Stairs	1st Floor	1,800	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	1st Floor	5	EA	6	6-10 years	Exit signs are legible
	Exit Signs - Corridors and Stairs	1st Floor	2	EA	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	17,550	SF	6	6-10 years	

Main Service

	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - 800 A and 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	17,555	SF	7	6-10 years	PA is fed from the main building. System is new.

Power Distribution

	Lighting and Power Panels - 100 A	Electrical Room and MDF Room	1	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Electrical Room and MDF Room	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Electrical Room and MDF Room	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Electrical Room and MDF Room	2	EA	7	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room and MDF Room	1	EA	7	6-10 years	

Category : Fire Protection
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Fire Alarm

	Fire Alarm Strobe Lights	Entire Building	17,550	SF	6	10+ years	
	Fire Alarm_System	Entire Building	17,550	SF	6	6-10 years	

Category : Fire Protection
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Sprinkler System</u>							
	Sprinkler Heads	Entire Building	17,550	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	17,550	SF	6	6-10 years	
	Wet Sprinkler System	Entire Building	17,550	SF	6	6-10 years	

Category : Mechanical
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Air Handling Systems</u>							
	Air Handling Unit-Package Single Zone-Indoor- Hot Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
<u>Boiler Systems</u>							
	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Mechanical Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Mechanical Room	1	EA	6	6-10 years	Glycol is fed into the system manually
	Combustion Dampers	Mechanical Room	2	EA	6	6-10 years	
	Glycol Feed System	Mechanical Room	1	EA	7	6-10 years	
	Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - 2001 - 3000 MBH	Mechanical Room	2	EA	6	6-10 years	
	Water Fill System	Mechanical Room	1	EA	6	6-10 years	
<u>Gas Booster</u>							
	Gas Booster	Mechanical Room	1	EA	6	6-10 years	
<u>Heating Devices</u>							
	Unit Heater - Hot Water	1st Floor	1	EA	6	6-10 years	Unit unit heater is functional
	Unit Heater - Hot Water	1st Floor	1	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	1st Floor	8	EA	6	6-10 years	Cabinet heaters in good working condition
	PTAC - Hot Water Heating and Self Contained Cooling	1st Floor	1	EA	6	6-10 years	
<u>Mechanical Plumbing</u>							
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	
<u>Temperature Control</u>							
	Electric Thermostat	Mechanical Room	2	EA	6	6-10 years	

Category : Mechanical
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Unit Ventilation</u>							
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	1st Floor	15	EA	6	6-10 years	
<u>Ventilation</u>							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	6-10 years	

Category : Plumbing
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Hot Water</u>							
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	7	10+ years	Looks as if hot water heater was recently replaced, since last assessment
<u>Piping</u>							
	Domestic Piping-Hot Water Return Lines	Entire Building	17,550	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	17,550	SF	7	6-10 years	
	Sanitary Piping	Entire Building	17,550	SF	6	10+ years	
	Storm Piping	Entire Building	17,550	SF	6	10+ years	
	Vent Piping	Entire Building	17,550	SF	6	10+ years	

Category : Classroom
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #400 (Regular Classroom)</u>							
	Casework	1st Floor	92	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	34	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	900	SF	7	10+ years	

Category : Classroom
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #401 (Regular Classroom)</u>							
	Casework	1st Floor	92	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	34	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	900	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
<u>Classroom #402 (Regular Classroom)</u>							
	Casework	1st Floor	92	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Student Lockers - Two Tiers	1st Floor	34	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
<u>Classroom #403 (Regular Classroom)</u>							
	Casework	1st Floor	92	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	898	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	34	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	526	SF	7	10+ years	
<u>Classroom #404 (Regular Classroom)</u>							
	Casework	1st Floor	92	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	

Category : Classroom
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	36	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	526	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #405 (Regular Classroom)							
	Casework	1st Floor	80	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	36	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	526	SF	7	10+ years	
Classroom #406 (Regular Classroom)							
	Casework	1st Floor	92	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	24	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	526	SF	7	10+ years	
Classroom #407 (Regular Classroom)							
	Casework	1st Floor	92	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	34	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	526	SF	7	10+ years	

Category : Classroom
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #408 (Regular Classroom)</u>							
	Casework	1st Floor	7	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Store Front	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	36	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	526	SF	7	10+ years	
<u>Classroom #409 (Regular Classroom)</u>							
	Casework	1st Floor	92	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	36	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	526	SF	7	10+ years	
<u>Classroom #410 (Music Room)</u>							
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,180	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,180	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	28	EA	6	6-10 years	
	Sound Panels	1st Floor	22	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,360	SF	7	6-10 years	
<u>Classroom #411 (Regular Classroom)</u>							
	Casework	1st Floor	92	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	526	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	526	SF	7	10+ years	

Category : Classroom
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Category : Room
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

MDF_IDE

	Doors - Hardware	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	64	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	

Mechanical/ Service Rooms

	Boiler Room	1st Floor	364	SF	7	10+ years	
	Janitor's Closet	1st Floor	49	SF	7	6-10 years	
	Mechanical/ Service Rooms	1st Floor	64	SF	7	10+ years	
	Storage Room	1st Floor	265	SF	7	10+ years	

Restroom

	Accessories	1st Floor	464	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	464	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	464	SF	7	6-10 years	
	Hand Dryer	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Partitions	1st Floor	3	EA	7	6-10 years	
	Urinals	1st Floor	7	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	900	SF	7	10+ years	
	Water Closet	1st Floor	3	EA	7	10+ years	
	Accessories	1st Floor	464	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	464	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	464	SF	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Partitions	1st Floor	11	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	900	SF	7	10+ years	
	Water Closet	1st Floor	11	EA	7	10+ years	
	Accessories	1st Floor	64	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	64	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	64	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	320	SF	7	10+ years	

Category : Room
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	64	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	64	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	64	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	320	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	

Category : Interior
Building : Linked Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Corridor</u>							
	Ceiling - Lay-in	1st Floor	2,514	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	7	EA	7	10+ years	Corrected Item Type and combined quantities
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	506	SF	7	10+ years	Corrected material
	Floor - Tile/Sheet	1st Floor	2,008	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	25	EA	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	60	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	4,800	SF	7	10+ years	
	Walls - Masonry	1st Floor	220	SF	7	10+ years	

Safety

Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
Security Cameras	1st Floor	3	EA	7	6-10 years	

Stairs

Ceiling - Lay-in	1st Floor	1,100	SF	7	10+ years	
Floor - Concrete	1st Floor	1,100	SF	7	10+ years	
Handrails	1st Floor	75	LF	7	10+ years	
Lighting - Lay-in	1st Floor	4	EA	7	6-10 years	
Stairs - Rubber	1st Floor	60	LF	7	10+ years	
Walls - Masonry	1st Floor	2,400	SF	7	10+ years	

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Athletic							
	Lighting	South East	6	EA	7	6-10 years	
	Surface - Synthetic	South East	18,400	SF	6	6-10 years	
Civil/Drainage							
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	1-2 years	Sinking
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	7	10+ years	
Fencing							
	Fencing - Guard Rail	Entire Site	200	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,060	LF	6	10+ years	
Landscape							
	Benches	Entire Site	3	EA	7	10+ years	
	Landscape - Grass	Entire Site	37,655	SF	7	10+ years	Recombined quantities
	Landscape - Hardscape- Asphalt	Entire Site	5,630	SF	4	0-1 year	Cracking/potholes
	Landscape - Hardscape- Concrete	Entire Site	5,265	SF	4	0-1 year	Cracking/potholes
	Parkway trees	Entire Site	49	EA	6	10+ years	Recombined quantities
	Planting Beds/ Area	Entire Site	3,200	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	330	SF	6	10+ years	Changed to match current observations. Recombined quantities
	Trash Receptacles	Entire Site	5	EA	6	10+ years	
Parking Lot							
	Concrete Curbs	North East	285	LF	6	10+ years	
	Interior Plantings	North East	90	LF	7	10+ years	
	Lighting - Pole Mounted	North East	4	EA	7	10+ years	
	Surface - Asphalt	North East	15,268	SF	6	10+ years	
	Trash Compactor	North East	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	North East	384	SF	6	10+ years	
	Trash Enclosure - Chain Links	North East	66	SF	4	0-1 year	Bending
	Vehicular Screening	North East	300	LF	7	10+ years	Corrected quantity
Playground							
	Equipment - Pre K 3-5	East	1	EA	7	10+ years	
	Equipment - School Age 5-12	East	1	EA	7	10+ years	Not previously assessed
	Surface - Poured Surface	East	2,125	SF	6	6-10 years	
	Equipment - Combo 3-12	North Courtyard	1	EA	6	10+ years	Divided out 2 types
	Equipment - Pre K 3-5	North Courtyard	1	EA	6	10+ years	Divided out 2 types

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Surface - Poured Surface	North Courtyard	4,960	SF	6	6-10 years	Changed to match current observations
Sidewalks							
	Sidewalks - Internal Walks	Entire Site	40	LF	7	10+ years	Recombined quantities
	Sidewalks - Internal Walks	Entire Site	250	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,375	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	375	SF	4	0-1 year	Cracking/uneven
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	4	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Building : Main									
Art Room	Other Instructional Use	1st Floor	107	107	840	140	56	N	N
Health	Regular Classroom	1st Floor	113	109	404	63	21		
Kindergarten	Kindergarten	1st Floor	106	106	576	60	30	N	N
Kindergarten	Regular Classroom	1st Floor	115	105	715	140	70	N	N
Kindergarten	Regular Classroom	2nd Floor	207	207	715	140	70	N	N
Office	Art Room	2nd Floor	212	210	300	84	42	N	N
Office	Other Instructional Use	1st Floor	108	108	237	45	18	N	N
Regular Classroom	Art Room	2nd Floor	210	210	610	140	70	N	N
Regular Classroom	Other Instructional Use	2nd Floor	211	211	670	3,710	185		
Regular Classroom	Regular Classroom	1st Floor	110	110	715	140	70	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	715	140	70	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	715	140	70	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	715	112	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	715	140	70	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	715	126	26	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	715	140	70	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	720	370	185	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	715	112	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	715	112	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	715	112	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	715	112	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	715	112	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	715	112	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	715	112	42	N	N
Special Program	Store Room	3rd Floor	310	310	300	19	10	N	N

Building : Linked Addition									
Music Room	Music Room	1st Floor	410	123	1,180	140	60	N	N
Regular Classroom	Regular Classroom	1st Floor	400	101	900	130	147	N	N
Regular Classroom	Regular Classroom	1st Floor	401	105	900	130	147	N	N
Regular Classroom	Regular Classroom	1st Floor	402	102	900	130	147	N	N
Regular Classroom	Regular Classroom	1st Floor	403	106	900	130	147	N	N
Regular Classroom	Regular Classroom	1st Floor	404	103	900	130	147	N	N
Regular Classroom	Regular Classroom	1st Floor	405	107	900	96	48	N	Y
Regular Classroom	Regular Classroom	1st Floor	406	104	900	130	147	N	N
Regular Classroom	Regular Classroom	1st Floor	407	108	900	130	147	N	N
Regular Classroom	Regular Classroom	1st Floor	408	121	900	130	147	N	N
Regular Classroom	Regular Classroom	1st Floor	409	122	900	130	65	N	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Regular Classroom	Regular Classroom	1st Floor	411	124	900	130	65	N	N

Building : Annex

Pre School	Pre School	1st Floor	500		792	75	0		
Pre School	Pre School	1st Floor	501		792	75	0		
Pre School	Pre School	1st Floor	502		728	60	0		
Pre School	Pre School	1st Floor	503		728	60	0		
Pre School	Pre School	1st Floor	506		728	60	0		
Pre School	Pre School	1st Floor	507		728	60	0		