

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1959	2	76,945
Campus Total			76,945

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance						_	
	Exterior Doors - Exterior Steel Door	10	1	EA	6	10+ years	
	Exterior Stairs - Concrete	10	3	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	11	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	11	3	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	12	2	EΑ	6	10+ years	
	Exterior Doors - Side lite	12	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	12	4	EΑ	6	10+ years	
	Exterior Stairs - Concrete	12	12	LF	6	6-10 years	Repaired
	Exterior Doors - Exterior Steel Door	13	2	EΑ	7	10+ years	New
	Ramps - Concrete	13	12	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	13.5	2	EΑ	4	1-2 years	Corroded doors
	Exterior Doors - Transom Lite	13.5	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	13.5	6	LF	4	0-1 year	Cracked/broken.
	Exterior Doors - Exterior Steel Door	14	1	EΑ	6	6-10 years	Corroded doors
	Exterior Doors - Transom Lite	14	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	14	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	15	2	EΑ	4	1-2 years	Corroded door and frames
	Exterior Doors - Side lite	15	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	15	3	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	16 - Courtyard	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	16 - Courtyard	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	3	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	3	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	4	1	EA	5	1-2 years	Corroded door frame



Assessment Date: 08/28/2023

Category : Exterior		В	uilding				
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Concrete	4	3	LF	5	1-2 years	Cracked concrete
	Entrance Control - Audio and Video	5	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	5	2	EA	5	1-2 years	Corroded door frames
	Exterior Doors - Side lite	5	1	EA	6	10+ years	
	Exterior Stairs - Concrete	5	14	LF	5	1-2 years	Several cracks in the concrete
	Exterior Doors - Exterior Steel Door	6	1	EA	6	10+ years	
	Exterior Stairs - Concrete	6	15	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	7	1	EA	7	10+ years	
	Exterior Stairs - Concrete	7	15	LF	7	10+ years	
	Entrance Control - Audio and Video	8	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	8	2	EA	6	10+ years	
	Exterior Doors - Side lite	8	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	8	3	EA	6	10+ years	
	Exterior Stairs - Concrete	8	8	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	8.5	2	EA	4	1-2 years	Corroded door and frames
	Exterior Doors - Exterior Steel Door	9	1	EA	6	10+ years	
	Exterior Stairs - Concrete	9	3	LF	5	2-5 years	
	Entrance Control - Audio and Video	Door 1 - Northwest	1	EA	7	6-10 years	
	Exterior Doors - Side lite	Door 1 - Northwest	1	EA	6	10+ years	
	Exterior Doors - Store Front	Door 1 - Northwest	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 1 - Northwest	5	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 1 - Northwest	12	LF	5	1-2 years	Cracked concrete
	Power Door Operator and Controls	Door 1 - Northwest	1	EA	7	6-10 years	
	Entrance Control - Audio and Video	Door 2 - Northeast	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 2 - Northeast	2	EA	6	10+ years	
	Exterior Doors - Side lite	Door 2 - Northeast	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 2 - Northeast	3	LF	5	1-2 years	Cracked, spalled, broken concrete
	Power Door Operator and Controls	Door 2 - Northeast	1	EA	7	6-10 years	
_Foundati							
	Foundation - Concrete	Entire Building	1,135	LF	7	10+ years	
	Foundation - Concrete	Entire Building	2	LF	5	1-2 years	Broken concrete with exposed rebar
	Superstructure - Metal Deck/ Concrete	Entire Building	76,945	SF	7	10+ years	
	Topping						
Liahtina							
	Exterior Lighting - Wall Mounted	Entire Building	42	EA	6	10+ years	
		99	12	_, .	Ü	. o . youro	
Roof Sys							
	Access Ladder - Metal	Roof 1	2	EA	7	6-10 years	
	Coping - Metal	Roof 1	1,020	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	4	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	175	LF	6	10+ years	
	· ·					-	





Category : Exterior			Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Roof 1	25,725	SF	6	6-10 years	
	Roof Hatch - Metal	Roof 1	1	EA	5	1-2 years	Broken lock
	Roof Hatch - Metal	Roof 1	1	EA	4	0-1 year	Hatch is corroded and missing
						-	hinges.
	Roof Structure - Concrete	Roof 1	25,725	SF	7	10+ years	
	Coping - Stone	Roof 2	315	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 2	60	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 2	300	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 2	15	LF	6	10+ years	Repaired
	Roof - Modified Bitumen	Roof 2	5,510	SF	6	6-10 years	
	Roof Structure - Concrete	Roof 2	5,510	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	2	EA	7	10+ years	
	Coping - Metal	Roof 3	550	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	59	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	1	LF	4	0-1 year	Broken drain strainer
	Roof - Modified Bitumen	Roof 3	14,172	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof 3	200	SF	4	1-2 years	Soft spots
	Roof Structure - Concrete	Roof 3	14,372	SF	7	10+ years	
	Access Ladder - Metal	Roof 4	1	EA	7	6-10 years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4	20	LF	6	6-10 years	
	Liner						
	Coping - Metal	Roof 4	178	LF	7	10+ years	
	Coping - Metal	Roof 4	20	LF	7	10+ years	Repaired
	Downspouts - Interior Downspouts	Roof 4	25	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	4,428	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof 4	700	SF	3	0-1 year	Soft spots
	Roof Structure - Concrete	Roof 4	5,128	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 5	31	LF	6	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 5	12	LF	5	0-1 year	Open joints
	Liner						
	Chimney - Metal Flue	Roof 5	8	LF	6	10+ years	
	Coping - Metal	Roof 5	12	LF	7	10+ years	Repaired
	Coping - Metal	Roof 5	68	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 5	15	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 5	2,000	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 5	2,000	SF	7	10+ years	
	Concrete Topping						
Walls							
	Canopy - Metal	Entire Building	280	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	22,315	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	4	1-2 years	Cracks, open joints
	Exterior Walls - Concrete Block	Entire Building	112	SF	7	10+ years	• •
		-				•	



Catego	ry : Exterior		В	uilding	: Main		1413 E 70th Office 11, Office 200, Te 00007
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Windows							
	Curtain wall - Glazed Double Pane	Entire Building	11,679	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	128	SF	5	1-2 years	Balancers not working, broken glass
	Curtain wall - Insulated Panel	Entire Building	4,858	SF	6	10+ years	Balancere net werking, broken glace
	Curtain wall - Louver	Entire Building	324	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	7,122	SF	6	10+ years	
	Lintels - Steel	Entire Building	7,122	LF	6	10+ years	
	Lintels - Stone	Entire Building	907	LF	6	10+ years	
Catedo	ry : Electrical		R	uilding	· Main		
catego	i y . Liecti icai		<u>_</u>	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Security System - CCTV	Entire Building	76,945	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	76,945	SF	5	2-5 years	
	Exit Signs - Corridors and Stairs	Entire Building	15	EA	6	2-5 years	
	Exit Signs - Gym	Entire Building	6	EA	6	2-5 years	
	Exit Signs - Lunchroom	Entire Building	4	EΑ	6	2-5 years	
	Emergency Battery Packs - Corridors and	Entire Building	34	EA	6	6-10 years	
	Stairs	F (•	^		0.40	
	Emergency Battery Packs - Gym	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	8	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,630	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	3,000	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,000	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,964	SF	6	6-10 years	
∕lain Seı	vice						
	Main Electrical Service - 2000 A	Electrical Room	1	EA	4	1-2 years	Heavy rust forming at bottom
	120/208/3PH	F (= 0.0:=	65	_	0.40	
	PA System	Entire Building	76,945	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Live front
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Exposed live parts



XY.	Schools						1415 E 70th STREET, Chicago, IL 60637
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	7	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	6-10 years	
	amp	S				,	
	•						
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar			•			•	
_ r ii C / viai	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	76,945	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	76,945	SF	6	6-10 years	
	The Alami_System	Entire Ballaing	70,343	Oi	O	0-10 years	
Catego	ry : Mechanical		R	uilding	· Main		
Calego	i y . Mechanicai		O O	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Location	Quantity	CON	IVALIA	Replacement	Comments
_Air Conc						0.40	
	Condensing Unit- Roof Mounted - Less	Lower Roof	1	EA	6	6-10 years	
	than 5 tons			_ ^	•	0.40	
	Condensing Unit- Roof Mounted - Less	Lower Roof	1	EA	6	6-10 years	
	than 5 tons						
_Air Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Electric	124 & 125	2	EA	6	6-10 years	124 & 125
	Air Handling Unit- Package Single Zone-	2nd Floor	1	EA	6	6-10 years	Second Floor.
	Indoor- Electric Coil - 8001-12000 cfm	- · -·			_		
	Air Intake	2nd Floor	1	EA	5	2-5 years	
	Air Handling Unit- Package Single Zone-	Boiler Room	1	EA	5	2-5 years	Boiler Room.
	Indoor- Steam Coils - 4000-8000 cfm				_		
	Air Intake	Boiler Room	1	EA	5	2-5 years	
	Air Handling Unit- Package Single Zone-	Gym	1	EA	5	6-10 years	Plywood covering a part of unit. Gym
	Indoor- Electric Coil - 8001-12000 cfm				_		
	Air Intake	Gym	1	EA	5	2-5 years	140.
	Air Handling Unit- Package Single Zone-	Kitchen	1	EA	6	6-10 years	Kitchen
	Indoor- Steam Coils - 4000-8000 cfm	120	4	_ ^	•	0.40	01 : 4 1 : 31 0 1 11 1 11 11
	Air Intake	Kitchen	1	EA	6	6-10 years	Shares intake with 2nd floor AHU
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	2-5 years	
	Pressure Boiler - 76 - 100 HP						
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	5	2-5 years	Heavily rusted
	Condensate Pump	Boiler Room	1	EA	6	2-5 years	
	Condensate Pump	Boiler Room	1	EA	6	2-5 years	

Page : 5 of 34



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	5	2-5 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	3	0-1 year	Currently both boilers did not pass
	Steam- Low Pressure Boiler - 76 - 100 HP					,	boiler inspection, repairs pending
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	3	0-1 year	Currently both boilers did not pass
	Steam- Low Pressure Boiler - 76 - 100 HP					,	boiler inspection, repairs pending
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	2-5 years	3
	Steam Traps	Boiler Room	32	ĒΑ	5	2-5 years	
	Vacuum Pump	Boiler Room	2	ĒΑ	6	2-5 years	
	·					•	
Gas Boo		Dellas Dans	0	Ε.Δ.		0.40	
	Gas Booster	Boiler Room	2	EA	6	6-10 years	
Heat Ex	changers						
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	1	EA	5	2-5 years	
	Туре					-	
_Heating	Davicas						
пеашу	Fin Tube - Hot Water	Entire Building	80	LF	6	6-10 years	
	Fin Tube - Steam	Entire Building	100	LF	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	100	EA	6	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	7	EA	6	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	1	EA	2	0-10 years 0-1 year	Not operational
	Cabillot Floaters With Cloam Com	Littilo Dallallig	·	_, .	_	o i you.	riot oporational
_Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EΑ	5	2-5 years	Heavily corroded
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	Heavily corroded
	Condensate-Steel or Galvanized	Entire Building	500	LF	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	800	LF	5	2-5 years	
Tompor	ature Control						
rember	Electric Thermostat	Entire Building	7	EA	4	0-1 year	Not operational
	Pneumatic System	Entire Building	76,945	SF	3	0-1 year	Not operational per last assessment
	Thermostats - Pneumatic	Entire Building	70,945 65	EA	5	2-5 years	Not operational per last assessment
	memostats - medmatic	Littile building	03	LA	3	2-5 years	
Unit Ven							
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	18	EA	5	2-5 years	
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	32	EA	5	2-5 years	
	Heating Coils Only	Entire Dullaning	32		J	2-5 years	
<u>Ventilati</u>							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	2-5 years	



Category : Mechanical			В				
0	Name Tamp	I anadian				Recommend	0
Group	Item - Type Exhaust Fans- Roof Mounted - 1501 - 8000	Location Entire Building	Quantity 1	UOM EA	Rank 6	Replacement 6-10 years	Comments
	CFM	Entire Building	ı	LA	O	0-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	3	0-1 year	Lunchroom fan not operational
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	7	EA	5	1-2 years	Noisy/excessive vibration
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	3	EA	3	0-1 year	2 Gym and 1 Kitchen hood fan not operational
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	operational
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	3	EA	5	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	2-5 years	Missing light.
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	4	2-5 years	Over 15 years old and beginning to deteriorate
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	1	EA	6	2-5 years	Gotolio i di
Piping							
<u> </u>	Domestic Piping-Hot Water Return Lines	Entire Building	76,945	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	76,945	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	76,945	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	76,945	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	76,945	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	76,945	SF	6	2-5 years	
	Sanitary Piping	Entire Building	76,945	SF	5	2-5 years	
	Storm Piping	Entire Building	76,945	SF	5	2-5 years	
	Vent Piping	Entire Building	76,945	SF	5	2-5 years	
_							
Pumps							



Catego	ry : Plumbing	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pumps - Sump-Duplex	1st Floor	1	EA	6	2-5 years	
	Pumps - Sump-Simplex	1st Floor	1	EA	6	6-10 years	Under elevator.

Catego	ry : Room	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Splined	2nd Floor-Teacher's Lounge	138	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Teacher's Lounge	1	EA	6	10+ years	
	Floor - Tile	2nd Floor-Teacher's Lounge	138	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor-Teacher's Lounge	2	EA	7	6-10 years	
	Power Distribution	2nd Floor-Teacher's Lounge	6	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor-Teacher's Lounge	210	SF	7	10+ years	
	AC Unit	Assistant Principal -store room	1	EA	7	10+ years	
	Ceiling - Splined	Assistant Principal -store room	385	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal -store room	1	EA	6	10+ years	
	Floor - Carpet	Assistant Principal -store room	385	SF	6	6-10 years	
	Lighting - Pendent/Surface	Assistant Principal -store room	4	EA	7	10+ years	
	Power Distribution	Assistant Principal -store room	6	EA	6	10+ years	
	Walls - Concrete Block	Assistant Principal -store room	608	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer Office	86	SF	6	10+ years	
	Doors - Hardware	Engineer Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	Engineer Office	86	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer Office	2	EA	7	6-10 years	
	Power Distribution	Engineer Office	4	EA	6	6-10 years	
	Walls - Concrete Block	Engineer Office	219	SF	6	10+ years	
	Ceiling - Splined	Faculty Lounge	473	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty Lounge	1	EA	6	10+ years	
	Floor - Tile	Faculty Lounge	473	SF	6	10+ years	
	Lighting - Pendent/Surface	Faculty Lounge	4	EA	7	6-10 years	
	Power Distribution	Faculty Lounge	6	EA	6	6-10 years	
	Walls - Concrete Block	Faculty Lounge	681	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym Office	75	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	7	10+ years	
	Floor - Concrete	Gym Office	75	SF	7	10+ years	
	Lighting - Pendent/Surface	Gym Office	1	EA	7	10+ years	
	Walls - Concrete Block	Gym Office	215	SF	7	10+ years	
	AC Unit	Main Office	1	EA	7	10+ years	
	Ceiling - Splined	Main Office	798	SF	6	10+ years	
	Doors - Transom Window	Main Office	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Carpet	Main Office	798	SF	4	0-1 year	Wearing out, some tears
	Lighting - Pendent/Surface	Main Office	14	EA	7	6-10 years	-
	Power Distribution	Main Office	6	EA	6	6-10 years	

Page: 8 of 34



<u> </u>							1415 E 70th STREET, Chicago, IL 60637
Catego	ry : Room		В	uilding	: Main		
	_				_	Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Main Office	779	SF	7	10+ years	
	AC Unit	Nurse Office in Main Office		EA	7	10+ years	
	Ceiling - Splined	Nurse Office in Main Office	144	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Nurse Office in Main Office		EA	6	10+ years	
	Floor - Carpet	Nurse Office in Main Office	144	SF	6	6-10 years	
	Lighting - Pendent/Surface	Nurse Office in Main Office	2	EA	7	6-10 years	
	Power Distribution	Nurse Office in Main Office	4	EA	6	6-10 years	
	Storage/ Closet	Nurse Office in Main Office	6	SF	7	10+ years	
	Walls - Concrete Block	Nurse Office in Main Office	335	SF	7	10+ years	
	AC Unit	Principal's Office	1	EA	7	10+ years	
	Ceiling - Splined	Principal's Office	217	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	10+ years	
	Floor - Carpet	Principal's Office	217	SF	6	6-10 years	
	Lighting - Pendent/Surface	Principal's Office	2	EA	7	6-10 years	
	Power Distribution	Principal's Office	6	EA	6	6-10 years	
	Walls - Concrete Block	Principal's Office	548	SF	7	10+ years	
_Gymnas							
	Ceiling - Exposed	1st Floor	4,400	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Wood	1st Floor	4,400	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	18	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	588	SF	6	10+ years	
	Stage Curtain	1st Floor	6	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Asphalt	1st Floor	12	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	6,072	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	500	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	70	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	570	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Serving Line	1st Floor	24	LF	7	10+ years	
	Storage/ Closet	1st Floor	150	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	740	SF	7	10+ years	
Libron							
Library	Casework	114	40	LF	e	101 2000	
		114	48	SF	6	10+ years	
	Ceiling - Splined Doors - Transom Window	114	1,536 24	SF SF	6 6	10+ years	
	DO012 - HAHSOHI WIHOOW	1 14	24	ЭF	0	10+ years	





Catego	ry : Room		В	uilding	· Main		1413 E 70111 3 TREET, Cliicago, IL 00037
Guiogo	, , , , , , , , , , , , , , , , , , ,			ananig	· Wani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	114	2	EA	6	10+ years	
	Floor - Tile/Sheet	114	1,536	SF	7	10+ years	
	Lighting - Pendent/Surface	114	36	ĒΑ	7	6-10 years	
	Storage/ Closet	114	12	SF	7	10+ years	
	Walls - Concrete Block	114	1,238	SF	7	10+ years	
	Traile Control Block		1,200	O.	•	.o. youro	
Lunch &	Multipurpose Room						
	Ceiling - Splined	1st Floor	2,400	SF	6	10+ years	
	Doors - Store Front	1st Floor	2	ĒΑ	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	2,400	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor	2,580	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	287	SF	7	10+ years	
	, ideita, 2 , j , i dii.		_0.	<u>.</u>	·	.o. you.o	
_MDF_ID							
	Doors - Steel Doors incl hw	2nd Floor-MDF, inside 219	1	EA	6	10+ years	
	Finishes	2nd Floor-MDF, inside 219	185	SF	7	10+ years	
	Window AC Unit	2nd Floor-MDF, inside 219	3	EA	5	6-10 years	
Maabaa	ical/ Service Rooms						
_wechan	Boiler Room	1st Floor	1,500	SF	7	10+ years	
	Janitor's Closet	1st Floor	50	SF	5		Water on floor
	Mechanical/ Service Rooms	1st Floor		SF SF	5 5	10+ years 10+ years	Electrical room, lights do not work
	Storage Room	1st Floor	144 150	SF	5 5		
	Janitor's Closet	2nd Floor	50	SF	5 5	10+ years	Water damage to ceiling
				SF SF	5 5	10+ years	
	Janitor's Closet	2nd Floor	144	SF SF		10+ years	
	Mechanical/ Service Rooms	2nd Floor	55	SF SF	7	10+ years	Updated to match current conditions
	Mechanical/ Service Rooms	2nd Floor	160	SF SF	5 5	10+ years	
	Storage Room	2nd Floor	150	SF	Э	10+ years	
Prep Ro	om						
•	Casework	2nd Floor-223 Prep Room 1	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor-223 Prep Room 1	105	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor-223 Prep Room 1	10	SF	4	1-2 years	Damaged
	Doors - Side-lite	2nd Floor-223 Prep Room 1	10	SF	6	10+ years	3
	Doors - Wood Doors inclu hw	2nd Floor-223 Prep Room 1	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor-223 Prep Room 1	115	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor-223 Prep Room 1	5	ĒΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor-223 Prep Room 1	218	SF	7	10+ years	
	Walls - Masonry	2nd Floor-223 Prep Room 1	60	SF	7	10+ years	
	Work Sink	2nd Floor-223 Prep Room 1	1	EA	7	10+ years	
	Casework	2nd Floor-223 Prep Room 2	24	LF	6	10+ years	
					•	,	





Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor-223 Prep Room 2	105	SF	6	10+ years	
	Doors - Side-lite	2nd Floor-223 Prep Room 2	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-223 Prep Room 2	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor-223 Prep Room 2	105	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor-223 Prep Room 2	5	EA	7	6-10 years	Quantity updated to match current observations
	Walls - Concrete Block	2nd Floor-223 Prep Room 2	206	SF	7	10+ years	
	Walls - Masonry	2nd Floor-223 Prep Room 2	46	SF	7	10+ years	
	Walls - Masonry	2nd Floor-223 Prep Room 2	40	SF	5	1-2 years	Water damage
	Work Sink	2nd Floor-223 Prep Room 2	1	ĒΑ	7	10+ years	3
Restroo	n						
	Accessories	124/125 restroom	60	SF	7	6-10 years	
	Ceiling - Lay-in	124/125 restroom	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	124/125 restroom	2	EA	6	10+ years	
	Floor - Tile	124/125 restroom	60	SF	7	10+ years	
	Lavatory	124/125 restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	124/125 restroom	1	EA	7	6-10 years	
	Walls - Concrete Block	124/125 restroom	156	SF	7	10+ years	
	Water Closet	124/125 restroom	1	EA	6	10+ years	
	Accessories	1st Floor-Boy's Restroom, across from Elevator	252	SF	7	6-10 years	
	Ceiling - Splined	1st Floor-Boy's Restroom, across from Elevator	252	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Boy's Restroom, across from Elevator	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom, across from Elevator	252	SF	6	10+ years	
	Floor Drain	1st Floor-Boy's Restroom, across from Elevator	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Boy's Restroom, across from Elevator	1	EA	7	10+ years	
	Lavatory	1st Floor-Boy's Restroom, across from Elevator	2	EA	6	10+ years	Updated quantity
	Lighting - Pendent/Surface	1st Floor-Boy's Restroom, across from Elevator	3	EA	7	6-10 years	
	Partitions	1st Floor-Boy's Restroom, across from Elevator	2	EA	7	10+ years	
	Urinals	1st Floor-Boy's Restroom, across from Elevator	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor-Boy's Restroom, across from Elevator	570	SF	7	10+ years	
	Water Closet	1st Floor-Boy's Restroom, across from Elevator	2	EA	7	10+ years	





Catego	ry : Room		Building : Main							
	_					Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Accessories	1st Floor-Boy's Restroom, near 122	230	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom, near 122	230	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-Boy's Restroom, near 122	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom, near 122	230	SF	6	10+ years				
	Floor Drain	1st Floor-Boy's Restroom, near 122	1	EA	7	10+ years				
	Hand Dryer	1st Floor-Boy's Restroom, near 122	1	EA	7	10+ years				
	Lavatory	1st Floor-Boy's Restroom, near 122	3	EA	6	10+ years				
	Lighting - Pendent/Surface	1st Floor-Boy's Restroom, near 122	3	EA	7	6-10 years				
	Partitions	1st Floor-Boy's Restroom, near 122	1	EA	7	10+ years				
	Partitions	1st Floor-Boy's Restroom, near 122	1	EA	5	1-2 years	Door handle missing			
	Urinals	1st Floor-Boy's Restroom, near 122	6	EA	6	10+ years				
	Walls - Structural Glazed Tile	1st Floor-Boy's Restroom, near 122	550	SF	6	10+ years				
	Water Closet	1st Floor-Boy's Restroom, near 122	2	EA	7	10+ years				
	Accessories	1st Floor-Girl's Restroom, next to 102	240	SF	7	6-10 years				
	Ceiling - Splined	1st Floor-Girl's Restroom, next to 102	240	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-Girl's Restroom, next to 102	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom, next to 102	240	SF	6	10+ years				
	Floor Drain	1st Floor-Girl's Restroom, next to 102	1	EA	7	10+ years				
	Hand Dryer	1st Floor-Girl's Restroom, next to 102	1	EA	7	6-10 years				
	Lavatory	1st Floor-Girl's Restroom, next to 102	3	EA	6	10+ years				
	Lighting - Pendent/Surface	1st Floor-Girl's Restroom, next to 102	3	EA	7	6-10 years				
	Partitions	1st Floor-Girl's Restroom, next to 102	4	EA	7	6-10 years				
	Partitions	1st Floor-Girl's Restroom, next to 102	1	EA	5	0-1 year	Door missing			
	Walls - Structural Glazed Tile	1st Floor-Girl's Restroom, next to 102	590	SF	6	10+ years				
	Water Closet	1st Floor-Girl's Restroom, next to 102	5	EA	7	10+ years				
	Accessories	1st Floor-Girl's Restroom, next to 122	230	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor-Girl's Restroom, next to 122	230	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-Girl's Restroom, next to 122	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom, next to	230	SF	6	10+ years				








Building: Main Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments 122 EΑ Floor Drain 1st Floor-Girl's Restroom, next to 7 1 10+ years EΑ Hand Dryer 1st Floor-Girl's Restroom, next to 7 6-10 years 122 Lavatory 1st Floor-Girl's Restroom, next to 2 EΑ 7 10+ years Lighting - Pendent/Surface 1st Floor-Girl's Restroom, next to 3 EΑ 7 10+ years 122 **Partitions** 1st Floor-Girl's Restroom, next to 4 FΑ 7 10+ years 122 Walls - Structural Glazed Tile 1st Floor-Girl's Restroom, next to 545 SF 6 10+ years 122 Water Closet 1st Floor-Girl's Restroom, next to 4 EΑ 7 10+ years 122 SF 7 Accessories 1st Floor-Unisex Staff Restroom, 62 6-10 years next to Elevator Ceiling - Splined 1st Floor-Unisex Staff Restroom, 62 SF 6 10+ years next to Elevator Doors - Wood Doors inclu hw 1st Floor-Unisex Staff Restroom, 1 EΑ 6 10+ years next to Elevator Floor - Tile Ceramic/ Porcelain 1st Floor-Unisex Staff Restroom, 62 SF 6 10+ years next to Elevator Hand Dryer 1st Floor-Unisex Staff Restroom, FΑ 7 6-10 years next to Elevator Lavatory 1st Floor-Unisex Staff Restroom. 1 FΑ 6 10+ years next to Elevator Lighting - Pendent/Surface 1st Floor-Unisex Staff Restroom, EΑ 7 1 6-10 years next to Elevator Lighting - Wall Mounted 1st Floor-Unisex Staff Restroom, 1 EΑ 7 6-10 years next to Elevator Walls - Concrete Block 1st Floor-Unisex Staff Restroom. 156 SF 6 10+ years next to Elevator Water Closet 1st Floor-Unisex Staff Restroom. FΑ 7 1 10+ years next to Elevator SF Accessories 2nd Floor-Boy's Restroom, across 252 7 6-10 years from 200A Ceiling - Splined 2nd Floor-Boy's Restroom, across 252 SF 6 10+ years from 200A Doors - Wood Doors inclu hw 2nd Floor-Boy's Restroom, across 1 EΑ 6 10+ years from 200A SF Floor - Tile Ceramic/ Porcelain 2nd Floor-Boy's Restroom, across 252 6 10+ years from 200A Floor Drain 2nd Floor-Boy's Restroom, across EΑ 10+ years







Building: Main Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments from 200A EΑ Hand Drver 2nd Floor-Boy's Restroom, across 7 6-10 years from 200A Lavatory 2nd Floor-Boy's Restroom, across EΑ 6 10+ years from 200A Lighting - Pendent/Surface 2nd Floor-Boy's Restroom, across 3 EΑ 7 6-10 years from 200A **Partitions** 2nd Floor-Boy's Restroom, across 2 EΑ 5 6-10 years from 200A Urinals 2nd Floor-Boy's Restroom, across 3 FΑ 6 10+ years from 200A Walls - Structural Glazed Tile 2nd Floor-Boy's Restroom, across 570 SF 7 10+ years from 200A Water Closet 2nd Floor-Boy's Restroom, across 2 EΑ 7 10+ years from 200A SF Accessories 2nd Floor-Boy's Restroom, across 230 7 6-10 years from 224 Ceiling - Plaster/Drywall 2nd Floor-Boy's Restroom, across 230 SF 7 10+ years from 224 Doors - Wood Doors inclu hw 2nd Floor-Boy's Restroom, across 1 EΑ 6 10+ years from 224 Floor - Tile Ceramic/ Porcelain 2nd Floor-Boy's Restroom, across 230 SF 6 10+ years from 224 Floor Drain 2nd Floor-Boy's Restroom, across FΑ 7 10+ years from 224 Hand Dryer 2nd Floor-Boy's Restroom, across 1 FΑ 7 6-10 years from 224 2nd Floor-Boy's Restroom, across EΑ Lavatory 2 6 10+ years from 224 Lighting - Pendent/Surface 2nd Floor-Boy's Restroom, across 3 EΑ 7 6-10 years from 224 **Partitions** 2nd Floor-Boy's Restroom, across 1 EΑ 7 10+ years from 224 2nd Floor-Boy's Restroom, across 5 FΑ 7 Urinals 10+ years from 224 Walls - Structural Glazed Tile 2nd Floor-Boy's Restroom, across 550 SF 6 10+ years from 224 Walls - Structural Glazed Tile 2nd Floor-Boy's Restroom, across 1 SF 4 1-2 years Damaged from 224 Water Closet 2nd Floor-Boy's Restroom, across 1 EΑ 7 10+ years from 224 SF 2nd Floor-Girl's Restroom, next to 7 Accessories 240 6-10 years Ceiling - Splined 2nd Floor-Girl's Restroom, next to 240 SF 6 10+ years







Building: Main Category: Room Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments 202 EΑ Doors - Wood Doors inclu hw 2nd Floor-Girl's Restroom, next to 6 1 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor-Girl's Restroom, next to 240 SF 6 10+ years 202 Floor Drain 2nd Floor-Girl's Restroom, next to EΑ 7 1 10+ years Hand Dryer 2nd Floor-Girl's Restroom, next to 1 EΑ 7 6-10 years 202 2nd Floor-Girl's Restroom, next to 3 FΑ Lavatory 6 6-10 years 202 Lighting - Pendent/Surface 2nd Floor-Girl's Restroom, next to 3 EΑ 7 6-10 years 202 **Partitions** 2nd Floor-Girl's Restroom, next to 5 EΑ 7 6-10 years 202 Walls - Structural Glazed Tile SF 2nd Floor-Girl's Restroom, next to 590 7 10+ years 202 Water Closet 2nd Floor-Girl's Restroom, next to 5 EΑ 7 10+ years 202 2nd Floor-Girl's Restroom, next to Accessories 230 SF 7 6-10 years 221 Ceiling - Plaster/Drywall 2nd Floor-Girl's Restroom, next to 230 SF 6 10+ years 221 Doors - Wood Doors inclu hw 2nd Floor-Girl's Restroom, next to FΑ 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor-Girl's Restroom, next to 230 SF 6 10+ years 221 Floor Drain EΑ 2nd Floor-Girl's Restroom, next to 1 7 10+ years Hand Dryer 2nd Floor-Girl's Restroom, next to EΑ 7 1 6-10 years 221 2nd Floor-Girl's Restroom, next to 2 EΑ 6 Lavatory 10+ years 221 Lighting - Pendent/Surface 2nd Floor-Girl's Restroom, next to 3 FΑ 7 6-10 years 221 **Partitions** 2nd Floor-Girl's Restroom, next to 4 EΑ 7 10+ years 221 Walls - Structural Glazed Tile 2nd Floor-Girl's Restroom, next to 545 SF 6 10+ years Water Closet 4 EΑ 6 2nd Floor-Girl's Restroom, next to 10+ years 221 SF 25 7 Accessories 2nd Floor-Men's Staff, near 223 6-10 years Ceiling - Plaster/Drywall 2nd Floor-Men's Staff, near 223 25 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor-Men's Staff, near 223 EΑ 10+ years







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile Ceramic/ Porcelain 2nd Floor-Men's Staff, near 223 25 SF 6 10+ years 2nd Floor-Men's Staff, near 223 EΑ 6 1 10+ years Lavatory Lighting - Pendent/Surface 2nd Floor-Men's Staff, near 223 1 FΑ 4 1-2 years Missing cover Walls - Concrete Block 2nd Floor-Men's Staff, near 223 SF 6 50 10+ years 7 Water Closet 2nd Floor-Men's Staff, near 223 1 EΑ 10+ years SF 35 7 Accessories 2nd Floor-Teacher's Lounge 10+ years Restroom SF Ceiling - Plaster/Drywall 2nd Floor-Teacher's Lounge 35 6 10+ years Restroom Doors - Wood Doors inclu hw 2nd Floor-Teacher's Lounge FΑ 1 6 10+ years Restroom Floor - Tile Ceramic/ Porcelain 2nd Floor-Teacher's Lounge 35 SF 6 10+ years Restroom Lavatory 2nd Floor-Teacher's Lounge 1 EΑ 6 10+ years Restroom 2nd Floor-Teacher's Lounge FΑ 7 Lighting - Pendent/Surface 1 6-10 years Restroom Walls - Concrete Block 2nd Floor-Teacher's Lounge 85 SF 6 10+ years Restroom Water Closet 2nd Floor-Teacher's Lounge 1 EΑ 6 10+ years Restroom SF Accessories Boiler Room 18 7 6-10 years SF Ceiling - Plaster/Drywall Boiler Room 18 6 10+ years Doors - Wood Doors inclu hw Boiler Room 1 FΑ 6 10+ years Floor - Tile Ceramic/ Porcelain 18 SF 6 Boiler Room 10+ years Lavatory Boiler Room 1 FΑ 6 10+ years Lighting - Pendent/Surface Boiler Room 1 EΑ 6 6-10 years Showers EΑ 7 Boiler Room 1 10+ years Walls - Concrete Block SF Boiler Room 35 6 10+ years Water Closet Boiler Room 1 EΑ 6 10+ years SF Accessories 24 7 6-10 years Engineer's Restroom SF Ceiling - Splined Engineer's Restroom 24 6 6-10 years FΑ Doors - Wood Doors inclu hw Engineer's Restroom 1 6 10+ years Floor - Tile Ceramic/ Porcelain Engineer's Restroom 24 SF 6 10+ years EΑ Lavatory Engineer's Restroom 1 6 10+ years Lighting - Pendent/Surface EΑ 6 Engineer's Restroom 1 6-10 years Walls - Concrete Block SF Engineer's Restroom 40 6 10+ years Water Closet Engineer's Restroom EΑ 10+ years 1 6 SF Accessories Inside 110 48 7 6-10 years SF Ceiling - Plaster/Drywall Inside 110 43 7 10+ years SF Ceiling - Plaster/Drywall Inside 110 5 5 1-2 years Vent cover missing, damage to ceiling around vent Doors - Wood Doors inclu hw Inside 110 1 EΑ 7 10+ years SF Floor - Tile Ceramic/ Porcelain Inside 110 48 7 10+ years







Category: Room		В	uilding	: Main			
						Recommend	
∂roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Inside 110	1	EA	7	10+ years	
	Hand Dryer	Inside 110	1	EΑ	7	6-10 years	
	Lavatory	Inside 110	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Inside 110	1	EΑ	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Inside 110	83	SF	7	10+ years	
	Water Closet	Inside 110	1	EA	7	10+ years	
	Accessories	Inside 111	60	SF	7	6-10 years	
	Ceiling - Lay-in	Inside 111	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Inside 111	2	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 111	60	SF	7	10+ years	
	Lavatory	Inside 111	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Inside 111	3	EΑ	7	6-10 years	
	Walls - Concrete Block	Inside 111	156	SF	7	10+ years	
	Water Closet	Inside 111	2	EA	7	10+ years	
	Accessories	Kitchen restroom	40	SF	7	6-10 years	
	Ceiling - Splined	Kitchen restroom	40	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Kitchen restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Kitchen restroom	40	SF	6	10+ years	
	Lavatory	Kitchen restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Kitchen restroom	1	EA	6	6-10 years	
	Partitions	Kitchen restroom	1	EA	7	6-10 years	
	Student Lockers - One Tier	Kitchen restroom	6	EA	6	6-10 years	
	Walls - Concrete Block	Kitchen restroom	80	SF	6	10+ years	
	Water Closet	Kitchen restroom	1	EA	6	10+ years	
	Accessories	Main Office	25	SF	7	6-10 years	
	Ceiling - Splined	Main Office	25	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office	25	SF	6	10+ years	
	Lavatory	Main Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Main Office	1	EA	5	0-1 year	Missing cover
	Walls - Concrete Block	Main Office	80	SF	6	10+ years	•
	Water Closet	Main Office	1	EA	6	10+ years	

Category: Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	m #101 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	10+ years	Continual knocking sound
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Doors - Side-lite	1st Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	





Catego	ory : Classroom		В	uilding	: Main		1413 E 7011 3 TREET, Chicago, IL 60637
Outogo	i y i Giacorcom		_	anamg	· wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	350	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Doors - Side-lite	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
	Work Sink	1st Floor	1,122	EA	7	10+ years	
						j	
Classroo	om #103 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Doors - Side-lite	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
Classroo	om #104 (Computer Lab)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Doors - Side-lite	1st Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	6	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
	Wireless System	1st Floor	1,122	EA	7	10+ years	
Ola	#405 (Decules Ol)						
_Classroo	om #105 (Regular Classroom)	4 . 🗔					
	AC Units	1st Floor	1	EA	7	10+ years	







atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Doors - Side-lite	1st Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
	vvalis - Coliciete block	151 [100]	1,122	SI	Ü	10+ years	
lassroc	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Splined	1st Floor	708	SF	6	10+ years	
	Ceiling - Splined	1st Floor	8	SF	4	0-1 year	Buckling tiles
	Doors - Side-lite	1st Floor	20	SF	7	10+ years	3
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	19	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	6	6-10 years	Relamp
	Marker Board	1st Floor	24	LF	7	10+ years	rtolamp
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
locaros	om #107 (Office)						
lassioc		4 . =1				4.0	
	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Doors - Side-lite	1st Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	556	SF	6	6-10 years	
	Floor - Tile	1st Floor	160	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	5	0-1 year	Does not work.
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
lassroo	om #108 (Regular Classroom)						
UC	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Splined	1st Floor		SF		-	
	Doors - Spilned		716		6	10+ years	
		1st Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	





Catego	ry : Classroom		В	uilding	: Main		1415 E 70(11 STREET, Chicago, IL 60037
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	24	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
			.,	-		, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #110 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Splined	1st Floor	1,465	SF	6	10+ years	
	Doors - Side-lite	1st Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,465	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	29	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	5	0-1 year	Does not work.
	Marker Board	1st Floor	22	LF	6	6-10 years	Does not work.
	Storage/ Closet	1st Floor	48	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,020	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	330	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
	WOLK SILIK	131 1001	2	LA	,	10+ years	
Classroo	om #111 (Pre School)						
	AC Units	1st Floor	2	EA	7	10+ years	
	Casework	1st Floor	32	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,472	SF	6	10+ years	
	Doors - Side-lite	1st Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,472	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	1st Floor	24	LF	7	10+ years	
	Storage/ Closet	1st Floor	26	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	998	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	240	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
						-	
Classroo	om #112 (Office)						
	AC Units	1st Floor	2	EA	7	10+ years	
	Ceiling - Splined	1st Floor	760	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	5	0-1 year	Does not work.
	Marker Board	1st Floor	24	LF	7	10+ years	
						-	





Catego	ry : Classroom		В	uilding	: Main		1413 E 70th OTNEET, Officago, ie 00007
Guiogo	.,		_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	818	SF	6	10+ years	
_Classroo	om #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
Classro	om #116 (Regular Classroom)						
Classion	AC Units	1st Floor	2	EA	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	. <u> </u>	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EΑ	5	0-1 year	Does not work.
	Marker Board	1st Floor	12	LF	7	10+ years	2000
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
01	(1447 (Danishan Olasana ana)						
_Classroo	om #117 (Regular Classroom)	4 . 🗔				40	
	AC Units	1st Floor	2	EA	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
Classroo	om #118 (Store Room)						
	AC Units	1st Floor	2	EA	7	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	





	ry : Classroom		R	uilding	· Main		1413 E 70111 3 TREET, Chicago, IL 60637
Julego				ananig	· maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	5	0-1 year	Does not work.
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
Classroo	om #119 (Store Room)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
Classroo	om #120 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	10+ years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
Classroo	om #121 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	





	ry . Classroom		D	uildina	. Mair		1413 E 70(11 STREET, CHICAGO, IL 60637
Catego	ry : Classroom		В	uilding	. wam	December	
0.00	Ham Time	Location	0	11014	Devil	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
Classroo	om #122 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Splined	1st Floor	716	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	•	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,122	SF	6	10+ years	
	vvalis - Concrete Block	1St Floor	1,122	SF	ь	10+ years	
Classroo	om #123 (Art Room)						
	AC Units	1st Floor	2	EA	7	10+ years	
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,140	SF	6	10+ years	
	Doors - Side-lite	1st Floor	20	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,140	SF	6	10+ years	
	Kiln	1st Floor	, 1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	38	EA	7	10+ years	
	Marker Board	1st Floor	15	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,300	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #124 (Kindergarten)						
CidooiOt	Casework	1st Floor	10	LF	6	10+ years	
	Casework Ceiling - Splined		1,321	SF			
		1st Floor		SF SF	6	10+ years	
	Doors - Side-lite	1st Floor	20		6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,321	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	42	EA	7	10+ years	
	Marker Board	1st Floor	14	LF	7	10+ years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,333	SF	6	10+ years	





Catego	Category : Classroom		В	uilding	1410 E 70tti OTIVEET, Officago, le 00007		
Outogo	, i ciacol com			anamg	· Wani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	1st Floor	1	EΑ	7	10+ years	
						·	
Classroo	om #125 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,248	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,248	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	40	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,308	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	18	LF	7	6-10 years	Does not work.
	Walls - Concrete Block	2nd Floor	1,130	SF	6	10+ years	
	Work Sink	2nd Floor	1,100	EA	7	10+ years	
						,,,,,,,	
_Classroo	om #202 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	6	6-10 years	_
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,130	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
						•	





Catego	ry : Classroom		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	18	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,130	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	5	0-1 years	Does not work.
	Marker Board	2nd Floor	18	LF	7	10+ years	Does not work.
	Walls - Concrete Block	2nd Floor	1,130	SF	7	10+ years	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	•	
	Lighting - Pendent/Surface	2nd Floor	4	EA	5	10+ years 0-1 year	Does not work.
		2nd Floor		LF	7	,	Does not work.
	Marker Board Walls - Concrete Block		18 1,130	SF	6	10+ years	
	Walls - Concrete block	2nd Floor	1,130	SF	0	10+ years	
_Classroo	om #206 (Regular Classroom)	0 15					
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	18	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,130	SF	6	10+ years	
	Marker Board	2nd Floor	18		7	10+ years	_ 300





Category : Classroom		В	uilding	: Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #207 (Faculty Lounge)	. —					
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	716	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	18	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,130	SF	6	10+ years	
lassroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EΑ	5	0-1 year	Does not work.
	Marker Board	2nd Floor	18	LF	7	10+ years	Boos not work.
	Walls - Concrete Block	2nd Floor	1,130	SF	6	10+ years	
laceroe	om #215 (Regular Classroom)						
JIASSIUU	AC Units	2nd Floor	2	EA	7	10+ years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Casework Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	646	SF	6	6-10 years	
	Floor - Carpet	2nd Floor	70	SF	4	0-10 years 0-1 year	Exposed floor, ripped carpet
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	Exposed floor, ripped carpet
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,100	SF	7	10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor 2nd Floor	200	SF SF	7	10+ years 10+ years	
	walls - Flaster/Drywall	2110 11001	200	SI	,	10+ years	
lassroc	nm #216 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	10+ years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	





Catego	ategory : Classroom			uilding	: Main	1410 E 70til OTIVEET, Officago, IE 00007	
Culogo	., ,		_	uag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	666	SF	6	6-10 years	
	Floor - Tile	2nd Floor	50	SF	4	1-2 years	Chipped tiles
	Lighting - Pendent/Surface	2nd Floor	19	ĒΑ	7	6-10 years	- 11
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	16	LF	7	6-10 years	2000
	Walls - Concrete Block	2nd Floor	1,300	SF	7	10+ years	
Classroo	om #218 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	10+ years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	706	SF	6	6-10 years	
	Ceiling - Splined	2nd Floor	10	SF	4	1-2 years	Water damage and chipped tiles
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	Water damage and empled tiles
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	716	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	19	EA	7	10+ years	
	Lighting Pendent/Surface	2nd Floor 2nd Floor			5	0-1 year	Door not work
	Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor	1	EA LF	5 7	•	Does not work.
	Walls - Concrete Block	2nd Floor 2nd Floor	16 1,300	SF	7	10+ years	
	Walls - Concrete Block	Ziid Flooi	1,300	SF	1	10+ years	
_Classroo	om #219 (Other Instructional Use)						
	AC Units	2nd Floor	3	EA	7	10+ years	
	Casework	2nd Floor	16	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	1,438	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	1,438	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	39	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,345	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	252	SF	6	10+ years	
_Classroo	om #220 (Regular Classroom)						
_	AC Units	2nd Floor	2	EA	7	10+ years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor 2nd Floor	716	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	20	EA	7	6-10 years	
	Lighting - I endem/ounde	2110 1 1001	20	ĽA	,	0-10 years	





Catego	ory : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,130	SF	7	10+ years	
Classro	om #221 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	10+ years	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	691	SF	5	2-5 years	
	Floor - Tile	2nd Floor	25	SF	4	1-2 years	Chips
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	22	LF	7	6-10 years	Bood flot Work.
	Walls - Concrete Block	2nd Floor	1,130	SF	7	10+ years	
	Work Sink	2nd Floor	1,130	EA	5	10+ years	
	Work Clink	2110 1 1001	•		Ü	101 youro	
_Classroo	om #222 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	10+ years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	716	SF	6	6-10 years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,130	SF	7	10+ years	
01	W000 (0 :						
_Classro	om #223 (Science Lab Level 1)	0 15					
	AC Units	2nd Floor	1	EΑ	7	10+ years	
	Casework	2nd Floor	55	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	977	SF	6	6-10 years	
	Ceiling - Splined	2nd Floor	5	SF	4	1-2 years	Missing tiles
	Doors - Side-lite	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	982	SF	7	10+ years	
	Gas Line	2nd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	982	SF	7	10+ years	
						•	





-							THE E TOUT CHILLET, CHICAGO, IL COCC
Catego	ry : Classroom		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Concrete Block	2nd Floor	1,150	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
Classroo	m #224 (Special Education)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	16	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	746	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	24	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	2nd Floor	746	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,180	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	-		·				
	Ceiling - Plaster/Drywall	1st Floor	90	SF	6	10+ years	
	Ceiling - Splined	1st Floor	9,806	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	9	ĒΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	5	1-2 years	Damaged
	Floor - Tile/Sheet	1st Floor	9,896	SF	7	10+ years	Č

roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	90	SF	6	10+ years	
	Ceiling - Splined	1st Floor	9,806	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	9	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	5	1-2 years	Damaged
	Floor - Tile/Sheet	1st Floor	9,896	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	52	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	161	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	10,795	SF	6	10+ years	
	Walls - Masonry	1st Floor	3,508	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	176	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	4,700	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	40	SF	4	1-2 years	Broken/missing tiles
	Drinking Fountains - Single Fountain	2nd Floor	7	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	5	1-2 years	Not working
	Floor - Tile/Sheet	2nd Floor	4,740	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	31	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	161	EA	6	10+ years	
	Student Lockers - One Tier	2nd Floor	5	EA	5	0-1 year	Missing hardware
	Walls - Concrete Block	2nd Floor	7,744	SF	6	10+ years	
	Walls - Masonry	2nd Floor	445	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	176	SF	6	10+ years	





Catego	Category : Interior				: Main		THO E TOWN OTHER T, Officeago, IE cocor
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Safety	, , , , , , , , , , , , , , , , , , ,		•			•	
	Camera Viewing Station	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	10	EA	7	6-10 years	
	Security Cameras	Entire Building	14	EA	7	6-10 years	
Stairs							
<u> Otano</u>	Ceiling - Splined	NE Stair	254	SF	6	10+ years	
	Floor - Tile	NE Stair	122	SF	6	10+ years	
	Handrails	NE Stair	60	LF	7	10+ years	
	Lighting - Pendent/Surface	NE Stair	2	ĒΑ	7	6-10 years	
	Stairs - Rubber	NE Stair	18	LF	6	10+ years	
	Walls - Masonry	NE Stair	510	SF	7	10+ years	
	Ceiling - Splined	NW Stair	215	SF	6	10+ years	
	Floor - Tile	NW Stair	85	SF	6	10+ years	
	Handrails	NW Stair	62	ĹF	7	10+ years	
	Lighting - Pendent/Surface	NW Stair	2	EA	7	6-10 years	
	Stairs - Rubber	NW Stair	18	LF	6	10+ years	
	Walls - Masonry	NW Stair	785	SF	7	10+ years	
	Ceiling - Splined	SE Stair	254	SF	6	10+ years	
	Floor - Tile	SE Stair	122	SF	6	10+ years	
	Handrails	SE Stair	60	LF	7	10+ years	
	Lighting - Lay-in	SE Stair	2	EA	7	6-10 years	
	Stairs - Concrete	SE Stair	18	LF	5	6-10 years	
	Walls - Masonry	SE Stair	510	SF	7	10+ years	
	Ceiling - Splined	SW Stair	160	SF	6	10+ years	
	Floor - Tile	SW Stair	60	SF	6	10+ years	
	Handrails	SW Stair	62	LF	7	10+ years	
	Lighting - Lay-in	SW Stair	2	EA	7	6-10 years	
	Stairs - Concrete	SW Stair	18	LF	6	10+ years	
	Walls - Masonry	SW Stair	775	SF	7	10+ years	
Vertical (Conveyance						
	Elevator - Elevator- Roped Holeless	North	1	EA	7	10+ years	
	Hydraulic		'	L, (•	ioi youio	
	Wheelchair Lift - Platform Lift	North	1	EA	7	10+ years	



Category : Site Building : Site

Catego	iy. Oile			Building . Site			
	W	1	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	10	EA	6	10+ years	
Fencing							
	Fencing - Chain Link	Entire Site	207	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	20	LF	4	1-2 years	missing section of chain-link fence
	Fencing - New Standard Ornamental	Entire Site	953	LF	6	10+ years	com.g cochen or chain min conce
	Fencing - New Standard Ornamental	Entire Site	270	LF	4	0-1 year	Corroding fence
	Fencing - New Standard Ornamental	Entire Site	40	LF	4	1-2 years	Damaged parking gate. Post has
	renemig from etandard emamental	Zimiro Ono			•	. L youro	been impacted and bent out of plumb
	Fencing - New Standard Ornamental	Entire Site	30	LF	4	1-2 years	Fence is very corroded with certain
	rending rew diamata dinamental	Entire one	30		7	1 Z yours	areas eaten through
							areas eater unough
Landooo	20						
_Landsca	•	Frating City	4.4	ΓΛ	7	40	
	Benches	Entire Site	14	EA	7	10+ years	
	Landscape - Grass	Entire Site	51,677	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	7,082	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	420	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	250	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	8	EA	6	2-5 years	
	Parkway trees	Entire Site	16	EΑ	6	10+ years	
	Parkway trees	Entire Site	15	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	9,366	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
	Walking Path - Crushed Stone	Entire Site	1,800	SF	7	10+ years	
Б							
_Parking		Davido a Lat. Cavith	405	1.5		10	
	Concrete Curbs	Parking Lot. South	495	LF	6	10+ years	
	Interior Plantings	Parking Lot- South	20	LF	6	6-10 years	
	Surface - Asphalt	Parking Lot- South	7,328	SF	6	6-10 years	All: material accordance and all materials a
	Surface - Asphalt	Parking Lot- South	900	SF	5	1-2 years	Alligatored surface, crack, potholes
	Surface - Concrete	Parking Lot- South	519	SF	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- South	680	SF	7	10+ years	
	Vehicular Screening	Parking Lot- South	40	LF	7	10+ years	
_Playgrou	and						
ayyıvı	Equipment - School Age 5-12	South	3	EA	7	10+ years	
	Surface - Poured Surface	South	2,888	SF	7	10+ years 10+ years	
				SF EA	7		
	Equipment - Pre K 3-5	West	1			10+ years	
	Equipment - School Age 5-12	West	1	EΑ	7	10+ years	
	Equipment - Swingset	West	1	EA	7	10+ years	



Catego	Category : Site			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Surface - Poured Surface	West	4,250	SF	7	10+ years	
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	134	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	100	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	9,000	SF	6	10+ years	
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Fig Dia		011	0		
			Daam	Floor Plan	A ====	Glazed	Operable	VA/i	Comment
Compant Hoose	Intended Heere	Doom Location	Room	Room	Area (SF)	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(51)	Area	Area	Stop	Board
Building : Main	Art De cre	4 o 4 🖂 o a v	400	400	4 4 4 0	450	00	l N	NI NI
Art Room	Art Room	1st Floor	123 104	123 104	1,140	156	26 32	N	N
Computer Lab	Regular Classroom	1st Floor			716	140		N	N
Faculty Lounge	Regular Classroom	1st Floor	122	122	716	120	24	N	N
Faculty Lounge	Regular Classroom	2nd Floor	207	207	716	140	32	N	N
Kindergarten	Kindergarten	1st Floor	103	103	716	140	32	Y	N
Kindergarten	Other Instructional Use	1st Floor	124	124	1,321	60	24	N	N
Kindergarten	Other Instructional Use	1st Floor	125	125	1,248	60	24	N	N
Kindergarten	Regular Classroom	1st Floor	101	101	716	140	32	N	N
Office	Regular Classroom	1st Floor	107	107	716	140	32	N	N
Office	Regular Classroom	1st Floor	112	112	760	120	24	N	N
Other Instructional Use	Regular Classroom	2nd Floor	202	202	716	140	32	N	Υ
Other Instructional Use	Regular Classroom	2nd Floor	219	217/219	1,438	280	80	N	N
Pre School	Kindergarten	1st Floor	110	110	1,465	228	90	N	N
Pre School	Kindergarten	1st Floor	111	111	1,472	200	80	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	716	140	32	N	Υ
Regular Classroom	Regular Classroom	1st Floor	105	105	716	140	32	N	Ν
Regular Classroom	Regular Classroom	1st Floor	106	106	716	140	32	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	716	140	32	N	N
Regular Classroom	Regular Classroom	1st Floor	115	115	716	120	24	N	N
Regular Classroom	Regular Classroom	1st Floor	116	116	716	120	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	117	117	716	120	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	120	120	716	120	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	716	140	32	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	716	140	32	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	716	140	32	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	716	140	32	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	716	140	32	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	716	140	32	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	716	140	32	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	716	140	32	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	716	140	32	N	Y
Regular Classroom	Regular Classroom	2nd Floor	220	220	716	140	32	N	Y
Regular Classroom	Regular Classroom	2nd Floor	221	221	716	140	32	N	Y
Regular Classroom	Regular Classroom	2nd Floor	222	222	716	140	32	N	N
Science Lab Level 1	Science	2nd Floor	223	223	982	200	80	N	N
Special Education	Special Education	2nd Floor	224	224	746	140	32	N	Y
Store Room	Regular Classroom	1st Floor	118	118	716	120	24	N	N
Store Room	Regular Classroom	1st Floor	119	119	716	120	24	N	N





Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Store Room	Regular Classroom	1st Floor	121	121	716	120	24	N	Υ

Campus Name: South Shore ES Page : 34 of 34 Assessment Date: 08/28/2023