

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1928	3	65,617
Addition	1952	2	4,984
Campus Total			70,601

Category : Exterior Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Chimney and Roof 4	9	EA	7	10+ years	
	Cell Equipment - Cabinets	Chimney and Roof 4	6	EA	7	10+ years	
Entrance							
	Exterior Doors - Exterior Steel Door	Door 1 - East - Auditorium	2	EA	7	6-10 years	
	Exterior Doors - Transom Lite	Door 1 - East - Auditorium	2	EA	7	6-10 years	
	Exterior Stairs - Stone	Door 1 - East - Auditorium	64	LF	6	10+ years	Repaired.
	Entrance Control - Audio	Door 2 - East - Main Entrance	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 2 - East - Main Entrance	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 2 - East - Main Entrance	2	EA	6	6-10 years	
	Exterior Stairs - Stone	Door 2 - East - Main Entrance	90	LF	7	6-10 years	
	Power Door Operator and Controls	Door 2 - East - Main Entrance	1	EA	7	6-10 years	
	Ramps - Concrete	Door 2 - East - Main Entrance	50	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 2 - East - Main Entrance	24	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 3 - East Center - Elevator	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 3 - East Center - Elevator	1	EA	7	6-10 years	
	Exterior Stairs - Stone	Door 3 - East Center - Elevator	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 4 - East	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 4 - East	2	EA	7	6-10 years	
	Exterior Stairs - Stone	Door 4 - East	96	LF	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 5 - Northeast - Gym	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 5 - Northeast - Gym	2	EA	7	6-10 years	
	Exterior Stairs - Stone	Door 5 - Northeast - Gym	40	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
	-			5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Entrance Control - Audio	Door 6 - Northwest	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 6 - Northwest	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 6 - Northwest	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 6 - Northwest	76	LF	7	10+ years	
	Power Door Operator and Controls	Door 6 - Northwest	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	Door 6 - Northwest	124	LF	7	10+ years	
	Ramps - Concrete	Door 6 - Northwest	62	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 6 - Northwest	60	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 6.5 - Boiler south	1	EA	4	0-1 year	Not used
	Exterior Doors - Overhead Rolling/ Garage	Door 6.7 - Boiler East	1	EA	6	10+ years	
	Door	Bool off Bollor Last	•		Ŭ	rot youro	
	Exterior Doors - Exterior Steel Door	Door 7 - Boiler north	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 7 - Boiler north	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 8 - Kitchen	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 8 - Kitchen	1	EA	7	6-10 years	
	Exterior Stairs - Concrete	Door 8 - Kitchen	40	LA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 8 - Kitchen	60	LF	7	6-10 years	
	Ramps - Concrete	Door 8 - Kitchen	30	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 8 - Kitchen	20	LF	7	6-10 years	
		Door 8 - Kitchen	20	LF	I	0-10 years	
Foundati	on						
	Foundation - Concrete	Entire Building	861	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	65,617	SF	7	10+ years	
		J				,	
ighting	Eutories Lighting Deserved on Deaf Mounted	Entire Duilding	40		6	6.40.0000	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	12	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	6-10 years	
Roof Sys							
	Access Ladder - Metal	Roof 1	2	EA	5	2-5 years	Access difficult
	Access Ladder - Wood	Roof 1	1	EA	4	0-1 year	Not attached, nails protruding
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	110	LF	6	10+ years	
	Liner						
	Coping - Terra Cotta	Roof 1	460	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	322	LF	6	6-10 years	
	Parapet - Parapet > 30"	Roof 1	460	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 1	11,285	SF	6	6-10 years	
	Roof - Metal	Roof 1	200	SF	5	10+ years	
	Roof Hatch - Metal	Roof 1	2	EA	5	2-5 years	
				SF	7	10+ years	
	Roof Structure - Concrete	ROOT	11.400	01			
		Roof 1 Roof 2	11,485 2	EA	4		Not used
	Roof Structure - Concrete Access Ladder - Wood Coping - Terra Cotta	Roof 2 Roof 2 Roof 2				0-1 year 10+ years	Not used



Catego	ry : Exterior		В	uilding	: Main		
				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	Roof 2	158	LF	6	6-10 years	
	Parapet - Parapet > 30"	Roof 2	201	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 2	7,827	SF	5	0-1 year	Minor vegetation growth in corners or roof.
	Roof Hatch - Metal	Roof 2	2	EA	5	0-1 year	Not used
	Roof Structure - Concrete	Roof 2	7,827	SF	7	10+ years	
	Access Ladder - Wood	Roof 3	1	EA	5	2-5 years	
	Coping - Terra Cotta	Roof 3	185	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 3	72	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 3	185	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 3	3,648	SF	6	6-10 years	
	Roof - Metal	Roof 3	50	SF	5	10+ years	
	Roof Hatch - Metal	Roof 3	1	EA	5	2-5 years	
	Roof Structure - Concrete	Roof 3	3,698	SF	7	10+ years	
	Access Ladder - Metal	Roof 4	-,	ĒA	7	10+ years	
	Coping - Terra Cotta	Roof 4	123	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4	50	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 4	123	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 4	1,713	SF	6	6-10 years	
	Roof Structure - Concrete	Roof 4	1,713	SF	7	10+ years	
	Coping - Terra Cotta	Roof 5	36	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Roof 5	4	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 5	32	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 5	47	SF	6	10+ years	Roof not accessible.
	Roof Structure - Concrete	Roof 5	47	SF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 6	30	LF	4	0-1 year	Missing
	Roof - Asphalt Gravel Ballast	Roof 6	231	SF	4	0-1 year	Plant growth, deterioration
	Roof Structure - Concrete	Roof 6	231	SF	7	10+ years	riant grown, detenoration
			201	0	1	TOT years	
Valls				05		10	
	Cheek-Wall - Stone	Entire Building	60	SF	6	10+ years	
	Cornice - Terra Cotta	Entire Building	747	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	26,965	SF	6	10+ years	Defening lange brief and a strange
	Exterior Walls - Brick	Entire Building	5,000	SF	3	0-1 year	Defacing, loose brick near entrance
	Exterior Walls - Stone-Cast	Entire Building	861	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,367	SF	6	10+ years	
Vindows							
	Curtain wall - Insulated Panel	Entire Building	3,173	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	1,846	SF	6	6-10 years	
	Lintels - Steel	Entire Building	625	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	194	LF	6	10+ years	
	Windows - Casement Steel	Entire Building	125	SF	6	6-10 years	
	Windows - Louver	Entire Building	12	SF	7	10+ years	



NO S							6239 N Leavitt STREET, Chicago, IL 6065
Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Windows - Sash Aluminum Double-pane	Entire Building	4,550	SF	6	6-10 years	
atego	ry : Electrical		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	ncy System						
0	Emergency A/C Power - Auditoium and Aisle Lighting	1st Floor, Entire Building	3,896	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	1st Floor, Entire Building	9,761	SF	6	6-10 years	
	Emergency A/C Power - Gym	1st Floor, Entire Building	3,016	SF	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	11	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	33	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	16	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	65,617	SF	6	6-10 years	There are only outdoor cameras, n indoor
	Security System - Intrusion Detection	Entire Building	65,617	SF	6	6-10 years	
lain Se	Nice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	65,617	SF	5	6-10 years	Some buttons are not working
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	-	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	· · · · · · · · · · · · · · · · · · ·		_				
-	ry : Fire Protection			uilding		_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



							6239 N Leavill STREET, Chicago, IL
						Replacement	
ire Alarr							
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	65,617	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	65,617	SF	6	6-10 years	
		5	,-			- ,	
Categor	y : Mechanical		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Condi	tioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	
Air Handl	ing Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils - Less than 4000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves gym
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - Less than 4000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU south
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room	16	EA	5	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU North
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	4	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	11	EA	5	6-10 years	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves Auditorium
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	

Boiler Systems



XCR S							6239 N Leavitt STREET, Chicago, IL 60659
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	6	6-10 years	
	Pressure Boiler - 101 - 150 HP						
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	6-10 years	
	Steam- Low Pressure Boiler - 101 - 150 HP						
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	6-10 years	
	Steam- Low Pressure Boiler - 101 - 150 HP						
	Piping - Condensate Pipe- Steel	Boiler Room	700	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	700	LF	6	6-10 years	
	Steam Traps	Boiler Room	95	EA	5	6-10 years	
						-	
Gas Boo	ster						
	Gas Booster	Boiler Room	2	EA	6	6-10 years	2, 1 per boiler.
					-	,	, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,
Heating [Devices						
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	24	EA	6	6-10 years	
	Radiators - Steam	Entire Building	2	EA	7	10+ years	Replaced in 2022
	Radiators - Steam	Entire Building	30	EA	5	6-10 years	
	Fin Tube - Electric	Entire Building	10	LF	6	10+ years	
	Fin Tube - Steam	Entire Building	20	LF	5	0-1 year	Covers damaged.
					-	- · , - · ·	
Tempera	ture Control						
•	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
	Pneumatic System	Entire Building	65,617	SF	6	6-10 years	Recently replaced, adjustments
	, ,	5	,			,	needed
	Thermostats - Pneumatic	Entire Building	30	EA	6	6-10 years	
		C C				2	
Ventilatio	ก						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	
	CFM	-				-	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	6-10 years	
	CFM						
•	_		_				
Catego	ry : Plumbing		В	uilding	: Main	Decomment	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity		ιτατικ	Replacement	Comments
Hot Wate	er Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	101 10000	2022 replaced
	Gas Healer - 130000 - 300000 DTU/TR		I	EA	1	10+ years	zuzz replaceu



	Schools						6239 N Leavitt STREET, Chicago, IL 606
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
. .							
Piping			05.047				
	Domestic Piping-Hot Water Return Lines	Entire Building	65,617	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	65,617	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	65,617	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	65,617	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	65,617	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	65,617	SF	6	6-10 years	
	Sanitary Piping	Entire Building	65,617	SF	6	6-10 years	
	Storm Piping	Entire Building	65,617	SF	6	10+ years	
	Vent Piping	Entire Building	65,617	SF	6	10+ years	
	ventriping	Entire Duilding	00,017	01	0	10+ years	
oumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	6	6-10 years	
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	10+ years	Under elevator.
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	trative Suites/Offices						
	AC Unit	108 care room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	108 care room	334	SF	7	10+ years	
	Doors - Transom Window	108 care room	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108 care room	1	EA	6	10+ years	
	Floor - Wood	108 care room	334	SF	7	10+ years	
	Lighting - Pendent/Surface	108 care room	5	EA	7	6-10 years	
	Power Distribution	108 care room	6	EA	7	10+ years	
	Walls - Concrete Block	108 care room	310	SF	7	10+ years	
	Walls - Plaster/Drywall	108 care room	448	SF	7	10+ years	
	AC Unit	1st Floor - Custodian Office inside Boiler Room	1	ĒA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Custodian Office inside Boiler Room	108	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Custodian Office inside Boiler Room	1	EA	7	6-10 years	
	Floor - Concrete	1st Floor - Custodian Office inside	108	SF	7	10+ years	

Lighting - Pendent/Surface

1

ΕA

7

Boiler Room

1st Floor - Custodian Office inside

6-10 years



							6239 N Leavitt STREET, Chicago, IL 60659
Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•		Boiler Room					
	Power Distribution	1st Floor - Custodian Office inside	4	EA	7	10+ years	
		Boiler Room				,	
	Walls - Plaster/Drywall	1st Floor - Custodian Office inside	100	SF	4	0-1 year	Water damaged plaster walls
	,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	Boiler Room		-		, , , , , , , , , , , , , , , , , , ,	311
	Walls - Plaster/Drywall	1st Floor - Custodian Office inside	225	SF	4	1-2 years	Damaged plaster walls
	······································	Boiler Room		•		,	
	Ceiling - Plaster/Drywall	1st Floor principal office	144	SF	7	10+ years	
	Doors - Transom Window	1st Floor principal office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor principal office	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor principal office	144	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor principal office	1	ĒA	7	6-10 years	
	Power Distribution	1st Floor principal office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor principal office	480	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor Assistant Principal	144	SF	7	10+ years	
	Doors - Transom Window	1st floor Assistant Principal	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor Assistant Principal	1	EA	6	10+ years	
	Floor - Tile	1st floor Assistant Principal	144	SF	7	10+ years	
	Lighting - Pendent/Surface	1st floor Assistant Principal	2	EA	7	6-10 years	
	Power Distribution	1st floor Assistant Principal	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor Assistant Principal	280	SF	7	10+ years	
	AC Unit	1st floor Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor Main Office	478	SF	7	10+ years	Quantity changed to update/correct to
			-			·	match current observation
	Doors - Transom Window	1st floor Main Office	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st floor Main Office	1	EA	6	10+ years	
	Floor - Tile	1st floor Main Office	192	SF	7	10+ years	Quantity changed to update/correct to
							match current observation
	Floor - Tile/Sheet	1st floor Main Office	286	SF	7	10+ years	Quantity changed to update/correct to
							match current observation
	Lighting - Pendent/Surface	1st floor Main Office	6	EA	7	6-10 years	
	Power Distribution	1st floor Main Office	18	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor Main Office	804	SF	7	10+ years	Quantity changed to update/correct to
							match current observation
	AC Unit	1st floor engineer's office inside	1	EA	7	6-10 years	
		boiler room- Basement				-	
	Ceiling - Plaster/Drywall	1st floor engineer's office inside	108	SF	6	10+ years	
	0	boiler room- Basement					
	Doors - Wood Doors inclu hw	1st floor engineer's office inside	1	EA	6	10+ years	
		boiler room- Basement				,	
	Floor - Tile	1st floor engineer's office inside	98	SF	7	10+ years	
	-	boiler room- Basement			-	,	
	Floor - Tile	1st floor engineer's office inside	10	SF	4	1-2 years	Missing floor tiles
	-	boiler room- Basement			-	,	0



Category : Room **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Lighting - Pendent/Surface 1st floor engineer's office inside FΑ 7 6-10 vears 1 boiler room- Basement Power Distribution 1st floor engineer's office inside 4 FΑ 10+ years 6 boiler room- Basement Walls - Plaster/Drywall 1st floor engineer's office inside 225 SF 6 10+ years boiler room- Basement AC Unit 202 ΕA 7 1 6-10 years Ceiling - Plaster/Drywall SF 202 334 7 10+ years Doors - Wood Doors inclu hw 202 1 EΑ 7 10+ years SF Floor - Tile 202 334 7 10+ vears Lighting - Pendent/Surface 202 5 ΕA 7 6-10 years Power Distribution 202 6 ΕA 6 6-10 years Walls - Plaster/Drywall 202 448 SF 6 10+ years SF Walls - Structural Glazed Tile 7 202 310 10+ years 309 - Store Room ΕA 7 AC Unit 1 6-10 years Ceiling - Plaster/Drywall 333 SF 309 - Store Room 6 10+ years Doors - Wood Doors inclu hw ΕA 309 - Store Room 1 6 10+ years SF Floor - Wood 309 - Store Room 333 6 10+ years ΕA Lighting - Pendent/Surface 309 - Store Room 6 6 6-10 years Power Distribution 309 - Store Room 8 EΑ 6 10+ years Walls - Plaster/Drywall 309 - Store Room 698 SF 6 10+ years Auditorium & Theater 1st Floor 75 ΕA 7 6-10 vears Balconv Seating Ceiling - Plaster/Drywall 1st Floor 3.896 SF 7 10+ years Doors - Wood Doors inclu hw 3 ΕA 7 10+ years 1st Floor SF 7 Floor - Concrete 1st Floor 930 10+ years Floor - Tile SF 1st Floor 6 6 10+ years Floor - Tile SF 6 1st Floor 2.496 10+ years SF Floor - Wood 1st Floor 464 6 10+ years Lighting - Pendent/Surface 1st Floor 11 ΕA 7 6-10 years Lighting - Wall Mounted 1st Floor 8 ΕA 7 6-10 years Main Floor Seating 1st Floor 198 ΕA 7 6-10 years Sound System ΕA 7 6-10 years 1st Floor 1 SF 7 10+ years Stage 1st Floor 464 Stage Curtain ΕA 7 1st Floor 4 10+ years Stage Lift 1st Floor 1 FΑ 7 10+ years Stage Lighting System FΑ 7 1st Floor 1 6-10 years LF Stage-Stairs - Wood 1st Floor 10 6 10+ vears LF Stairs - Terrazzo 7 10+ years 1st Floor 10 Storage/ Closet SF 7 1st Floor 80 10+ years Walls - Plaster/Drywall SF 1st Floor 5,921 7 10+ years

Gvmnasia



	ry : Room		D	uilding	• Main	·	6239 N Leavitt STREET, Chicago, IL 60659
Calego	ry . Room		D	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Ceiling - Plaster/Drywall	1st Floor	3,016	SF	7	10+ years	Comments
	Doors - Transom Window	1st Floor	12	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	3,016	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	3,010	EA	7	6-10 years	
	Scoreboards	1st Floor	0 1	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	390	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,472	SF	7	-	
	Walls - Flaster/Drywall Walls - Structural Glazed Tile	1st Floor	1,931	SF	7	10+ years	
	waiis - Structural Glazed The	IST FIOOI	1,931	SF	1	10+ years	
Kitchen							
	AC Unit	1st floor south of auditorium	1	EA	5	2-5 years	
	Ceiling - Plaster/Drywall	1st floor south of auditorium	336	SF	7	10+ years	
	Doors - Transom Window	1st floor south of auditorium	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor south of auditorium	2	EA	7	10+ years	
	Floor - Tile	1st floor south of auditorium	336	SF	6	10+ years	
	Lighting - Pendent/Surface	1st floor south of auditorium	4	EA	7	6-10 years	
	Storage/ Closet	1st floor south of auditorium	150	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor south of auditorium	418	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st floor south of auditorium	312	SF	7	10+ years	
Librony							
Library	AC Unit	209	4	EA	7	6-10 years	
	Casework	209	83	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	209	1,468	SF	6	•	
	Doors - Transom Window	209	1,400	SF	7	10+ years 6-10 years	
	Doors - Wood Doors inclu hw	209	2	EA	6	10+ years	
	Floor - Tile	209	1,468	SF	6	10+ years	
	Lighting - Pendent/Surface	209	28	EA	7	6-10 years	
	Walls - Plaster/Drywall	209	2,176	SF	7	10+ years	
	Walls - Flastel/Drywall	209	2,170	36	1	TOT years	
MDF_ID							
	Doors - Wood Doors inclu hw	in 202	1	EA	6	10+ years	
	Finishes	in 202	94	SF	5	10+ years	
	Other Cooling Unit	in 202	1	EA	7	6-10 years	Ductless split system.
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	98	SF	5	10+ years	
	Storage Room	1st Floor	250	SF	5	10+ years	
	Janitor's Closet	2nd Floor	98	SF	5	10+ years	
	Janitor's Closet	3rd Floor	34	SF	5	10+ years	
	Air Tunnel	Basement	4,000	SF	7	10+ years	Rank changed to update/correct to
		Dasement	4,000	0	1	io+ years	Rank changed to update/contect to



Catego	ry : Room		В	uilding	: Main		
Ŭ	·			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•						•	match current observation
	Boiler Room	Basement	1,600	SF	7	10+ years	Rank changed to update/correct to
						,	match current observation
	Crawl Space - Unfinished	Basement	8,436	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	980	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	875	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	128	SF	5	10+ years	
	Storage Room	Basement	462	SF	7	10+ years	
Restrool	m						
	Accessories	1st Floor - inside Custodian Office	30	SF	5	1-2 years	Old and outdated accessories
	Ceiling - Plaster/Drywall	1st Floor - inside Custodian Office	30	SF	7	10+ years	
	Floor - Tile	1st Floor - inside Custodian Office	30	SF	6	10+ years	
	Lavatory	1st Floor - inside Custodian Office	1	EA	4	0-1 year	Cracks in the fixture
	Lighting - Pendent/Surface	1st Floor - inside Custodian Office	1	EA	7	6-10 years	Rank changed to update/correct match current observation
	Walls - Plaster/Drywall	1st Floor - inside Custodian Office	92	SF	7	10+ years	
	Water Closet	1st Floor - inside Custodian Office	1	EA	7	10+ years	Rank changed to update/correct match current observation
	Accessories	1st floor Teachers (across 109)	126	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor Teachers (across 109)	126	SF	7	10+ years	
	Doors - Transom Window	1st floor Teachers (across 109)	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor Teachers (across 109)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor Teachers (across 109)	126	SF	7	10+ years	
	Hand Dryer	1st floor Teachers (across 109)	1	EA	7	6-10 years	
	Lavatory	1st floor Teachers (across 109)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor Teachers (across 109)	2	EA	7	6-10 years	
	Partitions	1st floor Teachers (across 109)	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor Teachers (across 109)	286	SF	7	10+ years	
	Water Closet	1st floor Teachers (across 109)	1	EA	7	10+ years	
	Accessories	1st floor at Auditorium lobby	136	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor at Auditorium lobby	136	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor at Auditorium lobby	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor at Auditorium lobby	136	SF	6	10+ years	
	Lavatory	1st floor at Auditorium lobby	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st floor at Auditorium lobby	1	EA	7	6-10 years	
	Partitions	1st floor at Auditorium lobby	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st floor at Auditorium lobby	177	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor at Auditorium lobby	197	SF	7	10+ years	
	Water Closet	1st floor at Auditorium lobby	1	EA	7	10+ years	
	Accessories	1st floor inside 101	219	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside 101	219	SF	7	10+ years	
	Doors - Transom Window	1st floor inside 101	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside 101	2	EA	6	10+ years	



Catego	ry : Room		P	uilding	· Main		6239 N Leavitt STREET, Chicago, IL 60659
Caleyo			D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Floor - Tile Ceramic/ Porcelain	1st floor inside 101	217	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside 101	2	SF	4	1-2 years	Cracks in the floor
	Floor Drain	1st floor inside 101	1	EA	7	10+ years	
	Lavatory	1st floor inside 101	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor inside 101	3	EA	7	6-10 years	
	Partitions	1st floor inside 101	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st floor inside 101	462	SF	7	10+ years	
	Water Closet	1st floor inside 101	1	EA	7	10+ years	
	Accessories	1st floor inside engineer's office	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside engineer's office	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside engineer's office	1	EA	6	10+ years	
	Floor - Tile	1st floor inside engineer's office	30	SF	6	10+ years	
	Lavatory	1st floor inside engineer's office	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st floor inside engineer's office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st floor inside engineer's office	98	SF	7	10+ years	
	Water Closet	1st floor inside engineer's office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside gym used as storage	71	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside gym used as storage	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside gym used as storage	71	SF	7	10+ years	
	Lighting - Pendent/Surface	1st floor inside gym used as storage	1	EA	7	6-10 years	
	Partitions	1st floor inside gym used as storage	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st floor inside gym used as storage	150	SF	7	10+ years	
	Accessories	1st floor inside main office suite	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside main office suite	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside main office suite	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside main office suite	30	SF	7	10+ years	
	Lavatory	1st floor inside main office suite	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor inside main office suite	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st floor inside main office suite	98	SF	7	10+ years	
	Water Closet	1st floor inside main office suite	1	EA	7	10+ years	
	Accessories	2nd Floor	346	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	346	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	346	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	9	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	272	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	304	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	130	SF	7	10+ years	
	Water Closet	2nd Floor	9	EA	7	6-10 years	
	Accessories	2nd Floor	185	SF	7	6-10 years	



Catego	ry : Room		B	uilding	• Main		6239 N Leavitt STREET, Chicago, IL 60639
oulogo				unung	· mann	Recommend	
Group	ltem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	185	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	185	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	1	EA	7	6-10 years	
	Urinals	2nd Floor	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	106	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	299	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	159	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	7	6-10 years	
	Accessories	2nd floor Unisex Staff across 209	126	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor Unisex Staff across 209	126	SF	7	10+ years	
	Doors - Transom Window	2nd floor Unisex Staff across 209	6	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd floor Unisex Staff across 209	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor Unisex Staff across 209	126	SF	6	10+ years	
	Hand Dryer	2nd floor Unisex Staff across 209	2	EA	7	6-10 years	
	Lavatory	2nd floor Unisex Staff across 209	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd floor Unisex Staff across 209	2	EA	7	6-10 years	
	Partitions	2nd floor Unisex Staff across 209	1	EA	7	6-10 years	
	Partitions	2nd floor Unisex Staff across 209	1	EA	5	2-5 years	
	Walls - Plaster/Drywall	2nd floor Unisex Staff across 209	286	SF	7	10+ years	
	Water Closet	2nd floor Unisex Staff across 209	2	EA	7	6-10 years	
	Accessories	First floor, boys near 104	185	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor, boys near 104	185	SF	7	10+ years	
	Doors - Transom Window	First floor, boys near 104	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor, boys near 104	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor, boys near 104	185	SF	7	10+ years	
	Floor Drain	First floor, boys near 104	1	EA	7	10+ years	
	Hand Dryer	First floor, boys near 104	1	EA	7	6-10 years	
	Lavatory	First floor, boys near 104	2	EA	7	10+ years	
	Lighting - Pendent/Surface	First floor, boys near 104	4	EA	7	6-10 years	
	Partitions	First floor, boys near 104	1	EA	7	10+ years	
	Urinals	First floor, boys near 104	3	EA	7	10+ years	
	Walls - Concrete Block	First floor, boys near 104	159	SF	7	10+ years	
	Walls - Plaster/Drywall	First floor, boys near 104	106	SF	7	10+ years	
	Walls - Structural Glazed Tile	First floor, boys near 104	299	SF	6	10+ years	
	Water Closet	First floor, boys near 104	1	EA	7	10+ years	
	Accessories	First floor, girls near 103	346	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor, girls near 103	346	SF	7	10+ years	



Catego	ry : Room		B	uilding	· Main		5239 N Leavin STREET, Chicago, IL 60659
Oalcyo				unung	. Mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cicup	Doors - Wood Doors inclu hw	First floor, girls near 103	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor, girls near 103	346	SF	7	10+ years	
	Floor Drain	First floor, girls near 103	1	EA	7	10+ years	
	Hand Dryer	First floor, girls near 103	2	EA	7	6-10 years	
	Lavatory	First floor, girls near 103	2	EA	7	10+ years	
	Lighting - Pendent/Surface	First floor, girls near 103	5	EA	7	6-10 years	
	Partitions	First floor, girls near 103	9	EA	7	10+ years	
	Walls - Concrete Block	First floor, girls near 103	304	SF	7	10+ years	
	Walls - Plaster/Drywall	First floor, girls near 103	272	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	First floor, girls near 103	130	SF	7	10+ years	
	Water Closet	First floor, girls near 103	9	EA	7	10+ years	
	Accessories	Third floor girls	277	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Third floor girls	277	SF	6	10+ years	
	Doors - Transom Window	Third floor girls	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Third floor girls	1	EA	6	10+ years	
	Floor - Tile	Third floor girls	20	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Third floor girls	257	SF	6	10+ years	
	Floor Drain	Third floor girls	1	EA	7	6-10 years	
	Hand Dryer	Third floor girls	1	EA	7	6-10 years	
	Lavatory	Third floor girls	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Third floor girls	4	EA	7	6-10 years	
	Partitions	Third floor girls	7	EA	7	6-10 years	
	Walls - Plaster/Drywall	Third floor girls	252	SF	6	10+ years	
	Walls - Structural Glazed Tile	Third floor girls	238	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Third floor girls	112	SF	6	10+ years	
	Water Closet	Third floor girls	7	EA	7	6-10 years	
	Accessories	Third floor, boys near 304	185	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Third floor, boys near 304	185	SF	6	10+ years	
	Doors - Transom Window	Third floor, boys near 304	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Third floor, boys near 304	1	EA	6	10+ years	
	Floor - Tile	Third floor, boys near 304	5	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Third floor, boys near 304	185	SF	6	10+ years	
	Floor Drain	Third floor, boys near 304	1	EA	7	6-10 years	
	Hand Dryer	Third floor, boys near 304	1	EA	7	6-10 years	
	Lavatory	Third floor, boys near 304	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Third floor, boys near 304	4	EA	7	6-10 years	
	Partitions	Third floor, boys near 304	1	EA	7	6-10 years	
	Urinals	Third floor, boys near 304	4	EA	7	6-10 years	
	Walls - Concrete Block	Third floor, boys near 304	159	SF	7	10+ years	
	Walls - Plaster/Drywall	Third floor, boys near 304	106	SF	6	10+ years	
	Walls - Structural Glazed Tile	Third floor, boys near 304	299	SF	7 7	10+ years	
	Water Closet	Third floor, boys near 304	1	EA	1	6-10 years	



Category : Classroom			B	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #101 (Fitness Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,164	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	1st Floor	1,164	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	7	6-10 years	
	Marker Board	1st Floor	48	LF	7	6-10 years	
	Storage/ Closet	1st Floor	118	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,507	SF	7	10+ years	
Classroo	m #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	38	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	7	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,175	SF	7	10+ years	
Classroo	m #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	38	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,185	SF	7	10+ years	
Classroo	m #106 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	



					N4 - 1		6239 N Leavitt STREET, Chicago, IL 60659
Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	4	LF	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,185	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	679	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6,0	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	679	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
				SF	7	•	
	Storage/ Closet	1st Floor	112	SF		10+ years	
	Walls - Plaster/Drywall	1st Floor	1,497	SF	7	10+ years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	825	SF	7	10+ years	
	Chalk Board	1st Floor	5	LF	4	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	7	6-10 years	
	Marker Board	1st Floor	21	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,277	SF	7	10+ years	
Classro	om #110 (Regular Classroom)						
01033100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	38		6	6-10 years	
				SF			
	Ceiling - Plaster/Drywall	1st Floor	703		7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	703	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	46	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,176	SF	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
				_ <i></i>	•	,	



Catarra				ي ما ام ال	Mair		6239 N Leavitt STREET, Chicago, IL 60659
Catego	ry : Classroom		В	uilding	: wan	Deceman !	
Group	Item - Type	Location	Quantity	UOM	Donk	Recommend Replacement	Comments
Group	Casework	2nd Floor	Quantity 8	LF	Rank 7	6-10 years	Comments
	Casework Ceiling - Plaster/Drywall	2nd Floor	725	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	33	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,191	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	6	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	23	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,211	SF	6	10+ years	
Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	715	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,191	SF	6	6-10 years	
Classroc	om #205 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	616	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	616	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	23	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,211	SF	6	10+ years	



Catego	ry : Classroom		R	uilding	: Main		6239 N Leavitt STREET, Chicago, IL 6065
oulego				unung	· main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	m #206 (Computer Lab)					•	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor		LF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	726	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	6	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	38	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	114	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,218	SF	7	10+ years	
	Wireless System	2nd Floor	. 1	EA	7	10+ years	
lassro	m #207 (Regular Classroom)						
21000100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,191	SF	7	10+ years	
Closeros	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1		7	6.10 veere	
		2nd Floor 2nd Floor	1	EA LF	7	6-10 years	
	Casework	2nd Floor 2nd Floor	8	SF	7	6-10 years	
	Ceiling - Plaster/Drywall Doors - Transom Window	2nd Floor 2nd Floor	713	SF	7 7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	12 2	EA	7	6-10 years	
		2nd Floor		SF	7	10+ years	
	Floor - Wood Lighting - Pendent/Surface	2nd Floor	713	EA		10+ years	
	Marker Board	2nd Floor 2nd Floor	14 22		7 7	6-10 years 6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,191	SF	7	6-10 years	
	-		1,101	0,			
Classroc	m #210 (Science Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	38	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	896	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	896	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
J	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,356	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	6-10 years	
			_		-		
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	719	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	6	10+ years	
	Floor - Wood	3rd Floor	719	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
	-		.,	•	Ū	let yeare	
lassroo	om #302 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	333	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	333	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Masonry	3rd Floor	402	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	596	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	715	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	715	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
~						-	
Jassroo	om #304 (Regular Classroom) AC Units	3rd Floor		Γ^	7	6 10	
			1	EA	7	6-10 years	
		3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	715	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	715	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
lassroc	om #305 (Regular Classroom)	- · -·					
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	652	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	652	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	44	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,201	SF	6	10+ years	
lassroo	om #306 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	726	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	726	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	38	LF	7	6-10 years	
	Storage/ Closet	3rd Floor		SF	7		
			114	SF		10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,218	SF	6	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	714	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	714	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	713	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6		
		310 F1001	2	EA	O	10+ years	



Catego	Category : Classroom				: Main			
						Recommend	.	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Wood	3rd Floor	713	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	22	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,201	SF	6	10+ years		

Category : Interior

Catego	Category : Interior			uilding			
Group	Itom Tuno	Location	Quantity	UOM	Rank	Recommend	Comments
Group Corridor	Item - Type	Location	Quantity		Rank	Replacement	Comments
Comdor	Ceiling - Plaster/Drywall	1st Floor	3,390	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	3,390	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	0	EA	7	6-10 years	
	Drinking Fountains - Double Vater Cooler	1st Floor	3	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	1,083	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,282	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,202	SF	4	1-2 years	Cracked floor tiles
	Lighting - Pendent/Surface	1st Floor	43	EA	7	6-10 years	Clacked hoor tiles
	Student Lockers - One Tier	1st Floor	161	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor		EA	7	•	
		1st Floor	7 4,269	SF	7	6-10 years	
	Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor	2,530	SF	7	10+ years	
		2nd Floor	2,530	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	•	EA	6 7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4		7	6-10 years	
	Drinking Fountains - Single Water Cooler Floor - Terrazzo			EA	7	6-10 years	
		2nd Floor	541	SF SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,601	SF	-	10+ years	Demonst
	Floor - Tile/Sheet	2nd Floor	34		4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	43	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	165	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	3,960	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	3,162	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,608	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	3rd Floor	4	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	7	6-10 years	
	Floor - Terrazzo	3rd Floor	477	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,131	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	30	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	108	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,980	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,558	SF	6	10+ years	
						•	

Safety



Catego	ory : Interior		B	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Camera Viewing Station	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Auditorium Stairs	30	SF	6	10+ years	
	Floor - Terrazzo	Auditorium Stairs	15	SF	6	10+ years	
	Handrails	Auditorium Stairs	28	LF	7	6-10 years	
	Stairs - Concrete	Auditorium Stairs	18	LF	6	10+ years	
	Walls - Plaster/Drywall	Auditorium Stairs	127	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North East	280	SF	6	10+ years	
	Floor - Terrazzo	North East	143	SF	6	10+ years	
	Handrails	North East	70	LF	7	6-10 years	
	Lighting - Pendent/Surface	North East	4	EA	7	6-10 years	
	Stairs - Terrazzo	North East	29	LF	7	10+ years	
	Walls - Plaster/Drywall	North East	604	SF	6	10+ years	
	Walls - Structural Glazed Tile	North East	803	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South East	286	SF	6	10+ years	
	Floor - Terrazzo	South East	429	SF	6	10+ years	
	Handrails	South East	171	LF	7	6-10 years	
	Lighting - Pendent/Surface	South East	9	EA	7	6-10 years	
	Stairs - Terrazzo	South East	71	LF	7	10+ years	
	Walls - Plaster/Drywall	South East	890	SF	6	10+ years	
	Walls - Structural Glazed Tile	South East	593	SF	7	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	6-10 years	



Catego	ry : Exterior		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Foundati							
	Foundation - Concrete Superstructure - Concrete	Entire Building Entire Building	137 4,984	LF SF	7 7	10+ years 10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	6	6-10 years	
Roof Sys	tem						
	Coping - Terra Cotta Downspouts - Interior Downspouts Parapet - 16" - 30" Height Roof - Asphalt Gravel Ballast Roof Structure - Concrete	Roof 7 Roof 7 Roof 7 Roof 7 Roof 7	137 45 137 2,278 2,278	LF LF SF SF	6 6 6 6	10+ years 6-10 years 6-10 years 6-10 years 10+ years	
Walls							
	Exterior Walls - Brick Exterior Walls - Brick Exterior Walls - Stone-Cast Exterior Walls - Terra Cotta	Entire Building Entire Building Entire Building Entire Building	5,091 800 137 137	SF SF SF SF	6 3 6 6	10+ years 0-1 year 10+ years 10+ years	Defacing brick, loose
Windows							
	Curtain wall - Insulated Panel Guard - Guards wire guard Lintels - Steel Lintels - Terra Cotta Windows - Casement Steel Windows - Sash Aluminum Double-pane	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	418 442 90 18 125 624	SF SF LF SF SF	6 6 6 6 6	6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years	
Catego	ry : Electrical		В	uilding	: Additi	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	icy System		4.664	05		0.40	
	Security System - Intrusion Detection	Entire Building	4,984	SF	6	6-10 years	
Main Sei	vice						
	PA System	Entire Building	4,984	SF	6	6-10 years	



Category : Fire Protection			В	uildina	: Additi		
	,		Recommen				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	4,984	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	4,984	SF	6	10+ years	
		Entire Banang	1,001	0.	Ũ	ior youro	
Catego	ry : Mechanical		В	uildina	: Additi	on	
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
<u>, in Fiana</u>	Reheat Boxes - Reheat Boxes with Steam	Mechanical Room	1	EA	5	6-10 years	Serves addition, functional - served
	Coil		I		0	o io years	by south AHU.
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	100	LF	6	6-10 years	Sy courrent.
	and Ducts		100		Ũ	e re jeare	
	Zone Dampers	Mechanical Room	6	EA	5	6-10 years	
	Lone Dampere		Ũ		Ũ	e le jeure	
Boiler Sy	/stems						
,	Piping - Condensate Pipe- Steel	Entire Building	30	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	30	LF	6	6-10 years	
	Steam Traps	Entire Building	1	EA	6	6-10 years	
					Ũ		
Tempera	ature Control						
	Electric Controls	Entire Building	4,984	SF	6	6-10 years	
	Pneumatic System	Entire Building	4,984	SF	4	1-2 years	Served by main building, manually
		-				-	operated, does not work well.
	Thermostats - Pneumatic	Entire Building	6	EA	6	6-10 years	
0-1	ma Dhambhin a		-				
Catego	ry : Plumbing		В	ullaing	: Additi		
Crown	Hom Tuno	Location	Quantitu	UOM	Rank	Recommend Replacement	Commonto
Group	Item - Type	Location	Quantity	UOINI	Rank	Replacement	Comments
Piping			4.004	05	0	0.40	
	Storm Piping	Entire Building	4,984	SF	6	6-10 years	
Catego	ry : Room		В	uildina	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	113 Counselor's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	113 Counselor's Office	304	SF	7	10+ years	
	Doors - Transom Window	113 Counselor's Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113 Counselor's Office	0	EA	7	-	
		The Courseion's Office	- I			10+ years	
	Floor Tile	110 Course alor's Office	004	0-		10	
	Floor - Tile	113 Counselor's Office	304	SF	7	10+ years	
	Floor - Tile Lighting - Pendent/Surface Power Distribution	113 Counselor's Office 113 Counselor's Office 113 Counselor's Office	304 5 8	SF EA EA	7 7 7	10+ years 6-10 years 10+ years	



Catego	ry : Room		В	Building : Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	113 Counselor's Office	708	SF	7	10+ years			
^ atoro	ry : Classroom		в	uilding	: Additi	n			
calego				unung	. Auun	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	om #111 (Regular Classroom)								
0.000.00	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	725	SF	7	10+ years			
	Doors - Transom Window	1st Floor	6	SF	7	-			
		1st Floor	0	EA		10+ years			
	Doors - Wood Doors inclu hw			SF	6	10+ years			
	Floor - Tile	1st Floor	725		6	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years			
	Marker Board	1st Floor	22	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,206	SF	7	10+ years			
Classroo	m #112 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	725	SF	7	10+ years			
	Doors - Transom Window	1st Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	725	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years			
	Marker Board	1st Floor	14		7				
	Walls - Plaster/Drywall	1st Floor	1,206	SF	6	6-10 years 10+ years			
			1,200	36	0	TOF years			
Classroo	m #211 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years			
	Doors - Transom Window	2nd Floor	6	SF	7	6-10 years			
	Floor - Tile	2nd Floor	725	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years			
	Marker Board	2nd Floor	22	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years			
Classro	m #212 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8						
	Casework Ceiling - Plaster/Drywall		-	SF	6	6-10 years			
		2nd Floor	725	SF SF	7	10+ years			
	Doors - Transom Window	2nd Floor	6	35	7	6-10 years			



Category : Classroom			В	Building : Addition					
5			3		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Tile	2nd Floor	725	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years			
	Marker Board	2nd Floor	22	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years			
			.,0	•		let yeare			
Classroc	om #213 (Office)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	304	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	304	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years			
	Marker Board	2nd Floor	6	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	708	SF	6	10+ years			
			P	به منام ان	. A al al 14:				
Jatego	ry : Interior	В	unaing	: Additi					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Corridor									
	Ceiling - Plaster/Drywall	1st Floor	122	SF	7	10+ years			
	Floor - Terrazzo	1st Floor	30	SF	7	10+ years			
	Floor - Tile/Sheet	1st Floor	82	SF	7	10+ years			
	Floor - Tile/Sheet	1st Floor	10	SF	4	1-2 years	Cracked floor tiles		
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	390	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	260	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	122	SF	6	10+ years			
	Floor - Terrazzo	2nd Floor	50	SF	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	72	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	290	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	160	SF	7	10+ years			
				•		. e · y eu. e			
Stairs									
	Ceiling - Plaster/Drywall	North West	286	SF	7	10+ years			
	Floor - Terrazzo	North West	429	SF	7	10+ years			
	Handrails	North West	171	LF	7	6-10 years			
			6	EA	7	6-10 years			
	Lighting - Pendent/Surface	North West	0		•	o io youio			
	Lighting - Pendent/Surface Stairs - Terrazzo	North West	71	LF	7	10+ years			





Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic	Baseball/Softball	16,323	SF	7	10+ years	Replaced.
	Surface - Asphalt	Basketball	4,691	SF	7	10+ years	
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	13	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	6	10+ years	
Fencing	Fencing - Chain Link	Entire Site	250	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,968	LF	6	10+ years	
	-					·	
Landsca	pe Benches	Entire Site	10	EA	6	6-10 years	
	Irrigation	Entire Site	61,130	SF	6	6-10 years	
	Landscape - Hardscape- Pavers	Entire Site	263	SF	4	0-1 year	Loose, broken pavers
	Landscape - Mulch	Entire Site	6,000	SF	6	6-10 years	Loose, bloken pavers
		Entire Site		EA		,	
	Lighting - Pole Mounted		2 34	EA	6	6-10 years	
	Parkway trees	Entire Site		SF	6	10+ years	
	Planting Beds/ Area	Entire Site	5,290		6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	33,674	SF	4	0-1 year	Cracking and uneven.
	Retaining Wall - Concrete	Entire Site	706	SF	6	10+ years	
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	3,665	SF	6	2-5 years	
Parking	Lot						
5	Concrete Curbs	Parking Lot- North	1,079	LF	6	6-10 years	
	Interior Plantings	Parking Lot- North	180	LF	6	6-10 years	
	Lighting - Pole Mounted	Parking Lot- North	3	EA	6	6-10 years	
	Lighting - Pole Mounted	Parking Lot- North	8	EA	6	6-10 years	
	Lighting - Pole Mounted	Parking Lot- North	4	EA	6	6-10 years	
	Surface - Asphalt	Parking Lot- North	19,479	SF	6	2-5 years	
	Surface - Concrete	Parking Lot- North	1,283	SF	6	10+ years	
	Trash Compactor	Parking Lot- North	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- North	1	SF	7	10+ years	
	Vehicular Screening	Parking Lot- North	248	LF	7	10+ years	
Playgrou	ind						
	Equipment - School Age 5-12	South	1	EA	6	10+ years	
	Equipment - Swingset	South	1	EA	7	10+ years	
		South	I	LA	ı	ior years	



Catego	Category : Site			uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Equipment - Swingset	South	1	EA	6	10+ years	
	Surface - Poured Surface	South	7,982	SF	4	0-1 year	Holes throughout.
Sidewall	(5						
	Sidewalks - Internal Walks	Entire Site	902	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	12,674	SF	6	10+ years	
_Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	4	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					- \- <i>\</i> -				
Art Room	Regular Classroom	1st Floor	106	106	728	150	75	N	Y
Computer Lab	Computer Lab	2nd Floor	206	206	726	102	50	N	N
Fitness Room	Kindergarten	1st Floor	101	101	1,164	240	120	N	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	728	150	75	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	728	150	75	N	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	679	115	45	N	Y
Regular Classroom	Regular Classroom	1st Floor	109	109	825	122	60	Y	Y
Regular Classroom	Regular Classroom	1st Floor	110	110	703	122	60	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	725	102	50	N	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	725	102	50	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	715	102	50	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	725	102	50	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	713	102	50	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	719	102	50	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	715	102	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	715	102	50	N	Y
Regular Classroom	Regular Classroom	3rd Floor	305	305	652	102	50	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	714	102	50	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	713	102	50	N	Y
Science Classroom	Regular Classroom	2nd Floor	210	210	896	122	60	N	Y
Science Classroom	Regular Classroom	3rd Floor	306	306	726	102	50	N	N
Special Education	Special Education	3rd Floor	302	302	333	40	20	N	N
Store Room	Regular Classroom	2nd Floor	205	205	616	102	50	N	Y
Building : Addition									
Office	Lunch Room	2nd Floor	213	Teacher	304	40	20	N	N
				lunch					<u> </u>
Regular Classroom	Regular Classroom	1st Floor	111	111	725	102	50	Y	Y
Regular Classroom	Regular Classroom	1st Floor	112	112	725	102	50	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	725	102	50	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	725	102	50	N	Y