

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1957	2	39,077
Campus Total			39,077

Category : Exterior Building : Main

		Recommend		_				
	Comments	Replacement	Rank	UOM	Quantity	Location	Item - Type	Group
							9	Entrance
		6-10 years	7	EA	1	#1 - Main East	Entrance Control - Audio and Video	
		6-10 years	6	EA	3	#1 - Main East	Exterior Doors - Exterior Steel Door	
		6-10 years	6	EA	3	#1 - Main East	Exterior Doors - Transom Lite	
		6-10 years	7	EA	1	#1 - Main East	Power Door Operator and Controls	
		10+ years	6	LF	187	#1 - Main East	Ramp Handrail - Steel_Ramp Handrail	
		10+ years	6	EA	3	#2 - N	Exterior Doors - Exterior Steel Door	
		10+ years	6	EA	3	#2 - N	Exterior Doors - Transom Lite	
		10+ years	6	LF	40	#2 - N	Exterior Stairs - Concrete	
		10+ years	6	LF	50	#2 - N	Ramp Handrail - Steel_Ramp Handrail	
	Minor cracks	10+ years	6	LF	20	#2 - N	Ramps - Concrete	
		10+ years	6	LF	5	#2 - N	Stair Handrail - Steel_Stair Handrail	
		-	6	EA	1	#3 - NW	Exterior Doors - Exterior Steel Door	
		10+ years	6	EA	1	#3 - NW	Exterior Doors - Transom Lite	
		10+ years	7	EA	1	#4 - NW	Exterior Doors - Exterior Steel Door	
		10+ years	6	LF	6	#4 - NW	Exterior Stairs - Concrete	
		10+ years	7	EA	1	#5 - SW	Exterior Doors - Exterior Steel Door	
		10+ years	7	EA	1	#5 - SW	Exterior Doors - Transom Lite	
		10+ years	6	LF	10	#5 - SW	Exterior Stairs - Concrete	
		6-10 years	6	EA	3	#6 - S	Exterior Doors - Exterior Steel Door	
		6-10 years	6	EA	3	#6 - S	Exterior Doors - Transom Lite	
		6-10 years	5	LF	60	#6 - S	Exterior Stairs - Concrete	
nal	Not operational	,	4	EA	1	#6 - S	Power Door Operator and Controls	
	•	-	6	LF	60	#6 - S		
		10+ years	6	LF	20	#6 - S	Ramps - Concrete	
nal	Not operational	10+ years 6-10 years 6-10 years 6-10 years 0-1 year 10+ years	6 6 7 6 7 6 6 6 5 4 6	EA EA EA EA EA EA EA EA LF EA LF	1 1 1 6 1 1 10 3 3 60 1 60	#3 - NW #3 - NW #4 - NW #4 - NW #5 - SW #5 - SW #5 - SW #6 - S #6 - S #6 - S #6 - S	Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Stairs - Concrete Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Doors - Transom Lite Exterior Stairs - Concrete Power Door Operator and Controls Ramp Handrail - Steel_Ramp Handrail	



Catego	ry : Exterior		В	uilding	: Main		
	•			<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ramps - Concrete	#6 - S	10	LF	4	0-1 year	Large cracking
	Stair Handrail - Steel_Stair Handrail	#6 - S	5	LF	6	10+ years	
oundati	on						
	Foundation - Concrete	Entire Building	738	LF	7	10+ years	
	Foundation - Concrete	Entire Building	15	LF	6	10+ years	
	Superstructure - Concrete	Entire Building	39,077	SF	7	10+ years	
	Caporell details Control	g	33,011	•	•	. o · you.o	
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	15	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	4	1-2 years	Not functional
Roof Sys	stem						
	Access Ladder - Metal	Main Roof	3	EA	7	10+ years	Quantity changed to match current observations
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	26	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	15	LF	4	1-2 years	Cracking bricks
	Coping - Stone	Main Roof	753	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	104	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	753	LF	5	1-2 years	Crumbling brick throughout
	Roof - Modified Bitumen	Main Roof	21,831	SF	5	2-5 years	3
	Roof Hatch - Metal	Main Roof	2	EA	7	6-10 years	Quantity changed to match curren observations
	Roof Hatch - Metal	Main Roof	1	EA	3	0-1 year	Broken/Not sealed
	Roof Structure - Concrete	Main Roof	21,831	SF	7	10+ years	Broker//Not sealed
	Noor Structure - Concrete	IVIAIIT ROOF	21,001	OI.	,	10+ years	
/alls							
	Canopy - Concrete/ Stucco	Entire Building	270	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	17,060	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,800	SF	6	10+ years	It's documented under roof parape Changed to match current
	Exterior Walls - Stone-Cast	Entire Building	720	SF	6	10+ years	observations
/indows							
	Curtain wall - Glazed Double Pane	Entire Building	366	SF	6	6-10 years	
	Curtain wall - Louver	Entire Building	36	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	5,659	SF	6	10+ years	
	Lintels - Steel	Entire Building	833	LF	6	10+ years	
	Lintels - Stone	Entire Building	6	LF	6	10+ years	



Categor	y : Exterior		В	uilding	: Main		
iroup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	-		-				
ategor	y : Electrical		В	uilding	: Main		
	Mana Tura	Laatian	Oa	ном	Donk	Recommend	Commonto
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
mergen	cy System						
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	4	2-5 years	Aged fixtures
	Exit Signs - Gym	Entire Building	4	EA	4	2-5 years	Aged fixtures
	Emergency Battery Packs - Corridors and Stairs	Entire Building	10	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	1	EA	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	39,077	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,435	SF	6	6-10 years	
/lain Ser	vice						
	Independent Electrical Service for emergency power	Boiler Room	1	EA	6	6-10 years	
	Main Electrical Service - 800 A and 120/240/3PH	Boiler Room	1	EA	6	6-10 years	
	PA System	Entire Building	39,077	SF	6	6-10 years	
ower Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
ategor	y : Fire Protection		В	uilding	: Main		
	_					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alarr							
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	Older panel. Board has malfunction
	Fire Alarm Strobe Lights	Entire Building	39,077	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	39,077	SF	6	6-10 years	
ategor	y : Mechanical		В	uilding	: Main		
	Itam Tuna	Lagation	O	LICM	Denle	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments



	Category : Mechanical		Building : Main				
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Entire Building	1	EA	6	6-10 years	
	Air Intake	Entire Building	1	EA	6	6-10 years	
Air Handl	ing Systems						
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	2nd Floor	2	EA	6	6-10 years	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	2nd Floor	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Entire Building	1	EA	6	6-10 years	
	Air Intake	Entire Building	1	EA	6	6-10 years	
Boiler Sy	stems						
j	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP	Entire Building	2	EA	6	10+ years	
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	
	Chemical Feeder	Entire Building	1	EA	6	6-10 years	
	Combustion Dampers	Entire Building	2	EA	6	6-10 years	
	Condensate Pump	Entire Building	1	EA	4	1-2 years	Motors are inoperable
	Feed Water Pumps and Tank	Entire Building	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Entire Building	1	EA	6	10+ years	Boiler 1
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Entire Building	1	EA	6	10+ years	Boiler 2
	Piping - Condensate Pipe- Steel	Entire Building	300	LF	5	2-5 years	
	Piping - Steam Pipe- Steel	Entire Building	300	LF	5	2-5 years	
	Steam Traps	Entire Building	14	EA	6	6-10 years	Defective steam trap have been replaced
	Vacuum Pump	Entire Building	1	EA	6	0-1 year	Motors are inoperable
Heating [Devices						
3	Cabinet Heaters - With Steam Coil	Entire Building	13	EA	5	2-5 years	
	Radiators - Steam	Entire Building	5	EA	5	2-5 years	
	Wall Heater - Electric	Restrooms and Teachers Lounge	5	EA	6	6-10 years	
_Tempera	ture Control						
•	Pneumatic System	Entire Building	39,077	SF	3	0-1 year	System is not functioning
	Thermostats - Pneumatic	Entire Building	27	EA	4	0-1 year	System is not functioning
_Unit Vent	ilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	25	EA	5	2-5 years	



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
o. cup	The state of the s	2004.0.1	quantity	•	raint	rtopiacomont	Commente
entilation							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof & 1st floor Kitchen	1	EA	7	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof & 1st floor Kitchen	4	EA	6	6-10 years	
	CFM	D (0.4.4) 10.1			•		D: 11 1 A 22 4 1
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof & 1st floor Kitchen	1	EA	3	0-1 year	Disassembled, Antiquated
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof & 1st floor Kitchen	1	EA	6	6-10 years	
	CFM					•	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof & 1st floor Kitchen	1	EA	7	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof & 1st floor Kitchen	1	EA	7	6-10 years	New exhaust hood
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Entire Building	1	EA	6	6-10 years	
Piping	B B					0.40	
	Domestic Piping-Hot Water Return Lines	Entire Building	39,077	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	39,077	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	39,077	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	39,077	SF	6	6-10 years	
	(Horizontal Lines)	Entire Building	00,011	O.	O	o io years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	39,077	SF	6	6-10 years	
	(Risers)	.	, -			, , , , , , , , , , , , , , , , , , , ,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	39,077	SF	6	6-10 years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	39,077	SF	6	6-10 years	
	Storm Piping	Entire Building	39,077	SF	6	6-10 years	
	Vent Piping	Entire Building	39,077	SF	6	6-10 years	
umps							
•	Pumps - Sump-Simplex	Crawlspace and Boiler Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Crawlspace and Boiler Room	1	EA	6	2-5 years	Cannot view
atego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	1st flr main office suite	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr main office suite	699	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr main office suite	4	EA	6	10+ years	
	Floor - Carpet	1st flr main office suite	350	SF	6	6-10 years	
	Floor - Tile	1st flr main office suite	349	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr main office suite	11	EA	6	10+ years	
	Power Distribution	1st flr main office suite	12	EA	6	10+ years	
	Storage/ Closet	1st flr main office suite	66	SF	7	10+ years	
	Walls - Concrete Block	1st flr main office suite	1,678	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Locker area	75	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Locker area	1	EA	6	10+ years	
	Floor - Tile	Engineer's Locker area	75	SF	6	6-10 years	
	Lighting - Pendent/Surface	Engineer's Locker area	1	EA	6	6-10 years	
	Power Distribution	Engineer's Locker area	2	EA	6	10+ years	
	Walls - Concrete Block	Engineer's Locker area	226	SF	6	10+ years	
	Work SInk	Engineer's Locker area	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office	85	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	85	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office	2	EA	6	10+ years	
	Walls - Concrete Block	Engineer's Office	212	SF	6	10+ years	
	Work SInk	Engineer's Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Teacher's Lounge, 2nd Floor	533	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Lounge, 2nd Floor	1	EA	6	10+ years	
	Floor - Tile	Teacher's Lounge, 2nd Floor	533	SF	6	6-10 years	
	Lighting - Pendent/Surface	Teacher's Lounge, 2nd Floor	7	EA	6	6-10 years	
	Power Distribution	Teacher's Lounge, 2nd Floor	8	EA	6	10+ years	
	Storage/ Closet	Teacher's Lounge, 2nd Floor	45	SF	7	10+ years	
	Walls - Concrete Block	Teacher's Lounge, 2nd Floor	930	SF	6	10+ years	
	Work SInk	Teacher's Lounge, 2nd Floor	1	EA	7	10+ years	
_							
_Gymnas	ia Ceiling - Splined	1st Floor	3,503	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3,303	EA	6	10+ years	
	Floor - Tile	1st Floor	3,503	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	12	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	725	SF	6	10+ years	
	Stage Curtain	1st Floor	725	EA	5	6-10 years	
	Stage Curtain Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lift Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	8	LF	6	10+ years	
	Olago-Olano - Wood	1301 1001	0	LI	U	10+ years	



Catego	ry : Room		В	uilding	· Main	000	0 3 FIIICEION AVENUE, CIIICAGO, IL 00020
Outego	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	97	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,308	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,308	SF	6	10+ years	
			,			, , , , , ,	
_Kitchen							
	Ceiling - Splined	1st Floor	688	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	688	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Serving Line	1st Floor	16	LF	6	10+ years	
	Storage/ Closet	1st Floor	48	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	314	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	734	SF	6	10+ years	
						j	
_MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Finishes	2nd Floor	74	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	10+ years	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	
_Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	60	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	97	SF	7	10+ years	
	Vaults	1st Floor	30	SF	7	10+ years	
	Janitor's Closet	2nd Floor	60	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	
	Storage Room	2nd Floor	90	SF	7	10+ years	
	Boiler Room	Basement	1,001	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	40,500	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	224	SF	7	10+ years	
	Storage Room	Basement	43	SF	7	10+ years	
D t	_						
_Restroor	M Accessories	1st Floor	345	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	345	SF SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	345	SF	6	10+ years	
	Hand Dryer	1st Floor	1	EA	7	•	
	Lavatory	1st Floor	2	EA	6	10+ years 10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7 7	6-10 years	
			5		-	•	
	Urinals Walls - Concrete Block	1st Floor 1st Floor	231	EA SF	6 6	6-10 years	
	Walls - Concrete Block Walls - Structural Glazed Tile	1st Floor	539	SF SF	6	10+ years 6-10 years	
	vvalis - Structural Glazeu Tile	13111001	339	J.	U	U-10 years	



Category : Room			Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Water Closet	1st Floor	2	EA	6	10+ years		
	Accessories	1st Floor	345	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	245	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	100	SF	5	1-2 years	Water damage	
	Floor - Tile Ceramic/ Porcelain	1st Floor	345	SF	6	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Hand Dryer	1st Floor	1	EΑ	7	10+ years		
	Lavatory	1st Floor	2	EΑ	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years		
	Partitions	1st Floor	6	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	234	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st Floor	546	SF	6	6-10 years		
	Water Closet	1st Floor	6	EA	6	10+ years		
	Ceiling - Plaster/Drywall	1st flr inside Office #104 (Now Storage)	19	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st flr inside Office #104 (Now Storage)	1	EA	6	10+ years		
	Floor - Tile	1st flr inside Office #104 (Now Storage)	19	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st flr inside Office #104 (Now Storage)	1	EA	6	6-10 years		
	Walls - Concrete Block	1st flr inside Office #104 (Now Storage)	144	SF	6	10+ years		
	Accessories	1st flr inside principal's office	41	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st flr inside principal's office	41	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st flr inside principal's office	1	EΑ	6	10+ years		
	Floor - Tile	1st flr inside principal's office	41	SF	5	10+ years		
	Lavatory	1st flr inside principal's office	1	EA	6	10+ years		
	Lighting - Pendent/Surface	1st flr inside principal's office	1	EΑ	6	6-10 years		
	Partitions	1st flr inside principal's office	1	EA	7	6-10 years		
	Walls - Concrete Block	1st flr inside principal's office	208	SF	6	10+ years		
	Water Closet	1st flr inside principal's office	1	EΑ	6	10+ years		
	Accessories	2nd Floor	345	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	345	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	345	SF	6	6-10 years		
	Floor Drain	2nd Floor	1	EA	7	10+ years		
	Hand Dryer	2nd Floor	1	EA	7	10+ years		
	Lavatory	2nd Floor	2	EA	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years		
	Partitions	2nd Floor	2	EA	7	10+ years		
	Urinals	2nd Floor	3	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	231	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	539	SF	6	10+ years		



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	2nd Floor	345	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	345	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	345	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	234	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	546	SF	6	10+ years	
	Water Closet	2nd Floor	5	EA	6	10+ years	
	Accessories	In Engineer's office	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Engineer's office	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Engineer's office	1	EA	6	10+ years	
	Floor - Tile	In Engineer's office	24	SF	4	1-2 years	Missing tiles
	Lighting - Pendent/Surface	In Engineer's office	1	EA	6	6-10 years	
	Walls - Concrete Block	In Engineer's office	156	SF	7	10+ years	
	Water Closet	In Engineer's office	1	EA	6	10+ years	
	Accessories	In Room 102	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 102	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Room 102	1	EA	6	10+ years	
	Floor - Tile	In Room 102	40	SF	6	10+ years	
	Lavatory	In Room 102	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Room 102	1	EA	7	6-10 years	
	Walls - Concrete Block	In Room 102	208	SF	6	10+ years	
	Water Closet	In Room 102	1	EA	6	10+ years	
	Accessories	In the Kitchen Area	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In the Kitchen Area	19	SF	6	10+ years	
	Ceiling - Plaster/Drywall	In the Kitchen Area	5	SF	6	1-2 years	Peeling paint
	Doors - Wood Doors inclu hw	In the Kitchen Area	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	In the Kitchen Area	24	SF	7	10+ years	
	Lavatory	In the Kitchen Area	1	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	In the Kitchen Area	1	EA	6	6-10 years	
	Student Lockers - One Tier	In the Kitchen Area	3	EA	5	2-5 years	Replace hardware
	Walls - Concrete Block	In the Kitchen Area	156	SF	6	10+ years	
	Water Closet	In the Kitchen Area	1	EA	6	2-5 years	
	Accessories	In worker's Office in Boiler Room	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In worker's Office in Boiler Room	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In worker's Office in Boiler Room	1	EA	6	10+ years	
	Floor - Tile	In worker's Office in Boiler Room	24	SF	6	10+ years	
	Lighting - Pendent/Surface	In worker's Office in Boiler Room	1	EA	6	6-10 years	
	Walls - Concrete Block	In worker's Office in Boiler Room	156	SF	6	10+ years	



Catego	Category : Room		В	uilding	: Main				
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Water Closet	In worker's Office in Boiler Room	1	EA	6	10+ years			
	Accessories	Men's Staff Restroom	91	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Men's Staff Restroom	91	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Men's Staff Restroom	1	EA	6	10+ years			
	Floor - Tile	Men's Staff Restroom	91	SF	6	6-10 years			
	Lavatory	Men's Staff Restroom	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Men's Staff Restroom	1	EA	6	6-10 years			
	Lighting - Wall Mounted	Men's Staff Restroom	1	EΑ	6	6-10 years			
	Partitions	Men's Staff Restroom	1	EA	7	10+ years			
	Urinals	Men's Staff Restroom	1	EA	6	10+ years			
	Walls - Concrete Block	Men's Staff Restroom	154	SF	6	10+ years			
	Water Closet	Men's Staff Restroom	1	ĒΑ	6	10+ years			
	Accessories	Unisex 1st Floor Near Classroom	50	SF	7	6-10 years			
	. 1000000.100	101	-	Ο.	•	o io you.o			
	Ceiling - Plaster/Drywall	Unisex 1st Floor Near Classroom 101	50	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Unisex 1st Floor Near Classroom 101	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Unisex 1st Floor Near Classroom 101	50	SF	7	10+ years			
	Floor Drain	Unisex 1st Floor Near Classroom 101	1	EA	7	10+ years			
	Lavatory	Unisex 1st Floor Near Classroom 101	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Unisex 1st Floor Near Classroom 101	1	EA	7	6-10 years			
	Walls - Concrete Block	Unisex 1st Floor Near Classroom 101	190	SF	7	10+ years			
	Water Closet	Unisex 1st Floor Near Classroom 101	1	EA	7	10+ years			
	Accessories	Women's Staff Restroom	91	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Women's Staff Restroom	71	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Women's Staff Restroom	20	SF	5	0-1 year	Condition remains		
	Doors - Wood Doors inclu hw	Women's Staff Restroom	1	EA	6	10+ years			
	Floor - Tile	Women's Staff Restroom	91	SF	7	6-10 years			
	Lavatory	Women's Staff Restroom	2	EA	6	10+ years			
	Lighting - Pendent/Surface	Women's Staff Restroom	1	EA	6	6-10 years			
	Lighting - Wall Mounted	Women's Staff Restroom	2	ΕA	6	6-10 years			
	Partitions	Women's Staff Restroom	2	ĒΑ	7	10+ years			
	Walls - Concrete Block	Women's Staff Restroom	154	SF	6	10+ years			
	Water Closet	Women's Staff Restroom	2	EA	6	10+ years			
Catego	ry : Classroom		В	uilding	: Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments		



					Replacement	
Classroom #101 (Office)					•	
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	8	LF	7	10+ years	
Ceiling - Plaster/Drywall	1st Floor	360	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
Floor - Carpet	1st Floor	360	SF	7	6-10 years	
Lighting - Pendent/Surface	1st Floor	8	ĒΑ	6	6-10 years	
Marker Board	1st Floor	24	LF	7	6-10 years	
Storage/ Closet	1st Floor	8	SF	7	10+ years	
Walls - Concrete Block	1st Floor	800	SF	6	10+ years	
Classroom #102 (Kindergarten)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	1,064	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1,004	EA	6	10+ years	
Floor - Tile	1st Floor	1,064	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	1,064	EA	7		
Marker Board			LF	7	6-10 years	
	1st Floor	18	SF		6-10 years	
Storage/ Closet	1st Floor	16		7	10+ years	
Walls - Concrete Block	1st Floor	1,450	SF	6	10+ years	
Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #104 (Office)						
AC Units	1st Floor	2	EΑ	7	6-10 years	
Casework	1st Floor	35	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	1,064	SF	6	10+ years	
Chalk Board	1st Floor	20	LF	4	2-5 years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Tile	1st Floor	1,064	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor	17	EA	6	6-10 years	
Storage/ Closet	1st Floor	22	SF	7	10+ years	
Walls - Concrete Block	1st Floor	1,111	SF	6	10+ years	
Work Sink	1st Floor	, 1	ĒΑ	7	10+ years	
Classroom #105 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	812	SF	6	10+ years	
Chalk Board	1st Floor	18	LF	4	2-5 years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	812	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
Marker Board	1st Floor	18	LF	7	2-5 years	
Storage/ Closet	1st Floor	16	SF	7		
Sidiage/ Glosel	ISLFIUUI	10	ЭF	1	10+ years	



SCHOOIS						00 S Princeton AVENUE, Chicago, IL 60620
					Replacement	
Walls - Concrete Block	1st Floor	930	SF	6	10+ years	
Work Sink	1st Floor	1	EA	7	10+ years	
					,	
Classroom #107 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	792	SF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Water damaged
Chalk Board	1st Floor	18	LF	4	2-5 years	water damaged
Doors - Wood Doors inclu hw	1st Floor	10	EA	6	10+ years	
Floor - Tile	1st Floor	812	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	12	EA	7		
Marker Board					6-10 years	
	1st Floor	18	LF	7	10+ years	
Storage/ Closet	1st Floor	16	SF	7	10+ years	
Walls - Concrete Block	1st Floor	930	SF	6	10+ years	
Work Sink	1st Floor	1	EA	7	10+ years	
01 "400 (D. 1. 0)						
_Classroom #108 (Regular Classroom)	4 . 🗖		Ε.Δ.		0.40	
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	812	SF	6	10+ years	
Chalk Board	1st Floor	20	LF	4	2-5 years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	812	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
Marker Board	1st Floor	20	LF	6	10+ years	
Storage/ Closet	1st Floor	16	SF	7	10+ years	
Walls - Concrete Block	1st Floor	957	SF	6	10+ years	
Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #110 (Regular Classroom)	=				0.40	
AC Units	1st Floor	1	EΑ	7	6-10 years	
Casework	1st Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	812	SF	6	10+ years	
Chalk Board	1st Floor	20	LF	4	2-5 years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	812	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
Marker Board	1st Floor	20	LF	6	6-10 years	
Storage/ Closet	1st Floor	16	SF	7	10+ years	
Walls - Concrete Block	1st Floor	957	SF	6	10+ years	
Work Sink	1st Floor	1	EA	7	10+ years	
01						
Classroom #112 (Computer Lab)	A at Elaa			-	0.40	
AC Units	1st Floor	1	EA	7	6-10 years	



Casework						
Casework					Replacement	
	1st Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	812	SF	6	10+ years	
Chalk Board	1st Floor	20	LF	4	2-5 years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	812	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	Relamp
Lighting - Pendent/Surface	1st Floor	10	EΑ	6	6-10 years	•
Marker Board	1st Floor	20	LF	6	6-10 years	
Storage/ Closet	1st Floor	16	SF	7	10+ years	
Walls - Concrete Block	1st Floor	957	SF	6	10+ years	
Wireless System	1st Floor	1	EA	7	6-10 years	
Work Sink	1st Floor	1	EΑ	7	10+ years	
Work Sink	1301 1001	'		,	101 years	
Classroom #114 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	812	SF	6	10+ years	
Chalk Board	1st Floor	20	LF	4	2-5 years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	812	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
Marker Board	1st Floor	20	LF	6	6-10 years	
Storage/ Closet	1st Floor	16	SF	7	10+ years	
Walls - Concrete Block	1st Floor	957	SF	6		
Work Sink		957	EA	7	10+ years	
WOIK SIIIK	1st Floor	ı	EA	,	10+ years	
Classroom #201 (Regular Classroom)						
AC Units	2nd Floor	1	EΑ	7	6-10 years	
Casework	2nd Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Water damage
Chalk Board	2nd Floor	18	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Tile	2nd Floor	812	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
Marker Board	2nd Floor	18	LF	7	10+ years	
				7	•	
Storage/ Closet	2nd Floor	16	SF SF	6	10+ years	
Walls - Concrete Block	2nd Floor	912	SF	О	10+ years	
Classroom #202 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	808	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	4	SF	5	1-2 years	Water damage
CEIIIIO - FIASIEI/I JIVWAII						
	2nd Floor	12	1 -	4	7-5 VAARG	
Chalk Board Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	18 1	LF EA	4 6	2-5 years 10+ years	



3010015					930	00 S Princeton AVENUE, Chicago, IL 606
					Replacement	
Floor - Tile	2nd Floor	812	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
Marker Board	2nd Floor	18	LF	7	10+ years	
Storage/ Closet	2nd Floor	16	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
Walls Collecte Block	2110 1 1001	330	O.	U	101 years	
assroom #203 (Computer Lab)						
	0. 151				0.40	
AC Units	2nd Floor	1	EΑ	7	6-10 years	
Casework	2nd Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Water damage
Chalk Board	2nd Floor	18	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Tile	2nd Floor	812	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
Marker Board	2nd Floor	18	LF	7	10+ years	
Storage/ Closet	2nd Floor	16	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	930	SF	6	•	
Walls - Concrete block	2110 F1001	930	SF	O	10+ years	
assroom #204 (Science)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	812	SF	6	10+ years	
Chalk Board	2nd Floor	20	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	•	
		· · · · · · · · · · · · · · · · · · ·			10+ years	
Eye Wash Station	2nd Floor	1	EA	6	10+ years	
Floor - Tile	2nd Floor	812	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
Marker Board	2nd Floor	20	LF	6	6-10 years	
Science Lab Elements	2nd Floor	812	SF	7	10+ years	
Storage/ Closet	2nd Floor	16	SF	7	6-10 years	
Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
Work Sink	2nd Floor	1	EA	7	10+ years	
ssroom #205 (Science Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	12	LF	6		
				_	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	811	SF	6	10+ years	_
Ceiling - Plaster/Drywall	2nd Floor	1	SF	5	1-2 years	Damage
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Tile	2nd Floor	812	SF	7	6-10 years	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
Marker Board	2nd Floor	18	LF	7	6-10 years	
Storage/ Closet	2nd Floor	16	SF	7	10+ years	
					ioi youis	
Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	



					Replacement	00 01 Tillectori Avenoe, Officago, ie 00020
Classroom #206 (Regular Classroom)					расстоп	
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	20	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	812	SF	6	10+ years	
Chalk Board	2nd Floor	12	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Eye Wash Station	2nd Floor	1	EΑ	7	10+ years	
Floor - Tile	2nd Floor	812	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
Marker Board	2nd Floor	20	LF	6	6-10 years	
Storage/ Closet	2nd Floor	16	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
Work Sink	2nd Floor	1	EA	7	10+ years	
Classroom #207 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	12	LF	6	10+ years	
Casework Ceiling - Plaster/Drywall	2nd Floor	811	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	1	SF	5	1-2 years	Domogo
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6		Damage
Floor - Tile	2nd Floor 2nd Floor		SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor 2nd Floor	812	EA	7	6-10 years	
Marker Board	2nd Floor 2nd Floor	12	LF		6-10 years	
		36	SF	7	6-10 years	
Storage/ Closet	2nd Floor	16		7	10+ years	
Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
Classroom #208 (Library)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Water damage
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	-
Floor - Carpet	2nd Floor	812	SF	6	6-10 years	
Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
Marker Board	2nd Floor	20	LF	6	6-10 years	
Storage/ Closet	2nd Floor	16	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
Classroom #210 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Water damage
Chalk Board	2nd Floor	20	LF	4	2-5 years	. a.o. damago
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
20010 11000 20010 III010 IIW	2110 1 1001	·	_, .	Ū	io. jouro	



oup rridor	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
			.			Recommend	
ego	y : Interior		В	uilding	: Main		
						,	
	Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Floor - Tile	2nd Floor	812	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor	812	SF	6	10+ years	
	Casework	2nd Floor	12	LF	6	10+ years	
	AC Units	2nd Floor	1	EA	7	6-10 years	
ssroo	m #216 (Regular Classroom)						
	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				-	,	
	Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Floor - Tile	2nd Floor	812	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor	812	SF	6	10+ years	
	Casework	2nd Floor	12	LF	6	10+ years	
	AC Units	2nd Floor	1	EA	7	6-10 years	
ssroo	m #214 (Regular Classroom)						
	Traile Concrete Block	2.10 1 100.	000	O.	ŭ	io. youro	
	Walls - Concrete Block	2nd Floor	930	SF	6	10+ years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	812	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	812	SF	6	10+ years	
	Casework	2nd Floor	20	LF	6	10+ years	
	AC Units	2nd Floor	1	EA	7	6-10 years	
ssroo	m #212 (Regular Classroom)						
	Walls - Concrete Block	211d F1001	930	SF	6	6-10 years	
	Walls - Concrete Block	2nd Floor 2nd Floor	930	SF SF	6	10+ years	
	Storage/ Closet	2nd Floor 2nd Floor	16	SF	7	-	
	Marker Board	2nd Floor 2nd Floor	20	LF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	12	EA	6	6-10 years	
	Floor - Tile	2nd Floor	812	SF	7	Replacement 6-10 years	



Category : Interior		Building : Main						
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	1st Floor	594	SF	6	10+ years		
	Ceiling - Splined	1st Floor	1,980	SF	6	10+ years		
	Doors - Store Front	1st Floor	3	EA	6	10+ years		
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years		
	Drinking Fountains - Double Water Cooler	1st Floor	1	EA	7	10+ years		
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	10+ years		
	Floor - Terrazzo	1st Floor	748	SF	6	10+ years		
	Floor - Tile/Sheet	1st Floor	1,826	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	8	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	28	EA	6	6-10 years		
	Student Lockers - One Tier	1st Floor	176	EA	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	928	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st Floor	2,864	SF	6	10+ years		
	Ceiling - Splined	2nd Floor	2,464	SF	6	10+ years		
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	6-10 years		
	Floor - Tile/Sheet	2nd Floor	2,464	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	38	EA	6	6-10 years		
	Student Lockers - One Tier	2nd Floor	199	EA	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,195	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	2,390	SF	6	10+ years		
Stairs								
	Ceiling - Plaster/Drywall	East	450	SF	6	10+ years		
	Ceiling - Splined	East	359	SF	6	10+ years		
	Floor - Terrazzo	East	659	SF	6	10+ years		
	Handrails	East	128	LF	7	10+ years		
	Lighting - Pendent/Surface	East	4	EA	6	6-10 years		
	Stairs - Terrazzo	East	60	LF	6	10+ years		
	Walls - Structural Glazed Tile	East	1,926	SF	6	10+ years		
	Ceiling - Plaster/Drywall	North	270	SF	6	10+ years		
	Ceiling - Splined	North	169	SF	6	10+ years		
	Floor - Terrazzo	North	369	SF	6	10+ years		
	Handrails	North	64	LF	7	10+ years		
	Lighting - Pendent/Surface	North	4	EA	6	6-10 years		
	Lighting - Wall Mounted	North	1	EA	6	6-10 years		
	Stairs - Terrazzo	North	30	LF	6	10+ years		
	Walls - Concrete Block	North	805	SF	6	10+ years		
	Walls - Structural Glazed Tile	North	805	SF	6	10+ years		
	Ceiling - Plaster/Drywall	South	270	SF	6	10+ years		
	Ceiling - Splined	South	169	SF	6	10+ years		
	Floor - Terrazzo	South	369	SF	6	10+ years		
	Handrails	South	64	LF	7	10+ years		
	Lighting - Pendent/Surface	South	4	EA	6	6-10 years		
	Lighting - Wall Mounted	South	1	EA	6	6-10 years		
						•		



0-1	Intonion		D	: - :	. Main				
Catego	ory : Interior		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Stairs - Terrazzo	South	30	LF	6	10+ years			
	Walls - Concrete Block	South	805	SF	6	10+ years			
	Walls - Structural Glazed Tile	South	805	SF	6	10+ years			
Vertical	Conveyance								
	Wheelchair Lift - Platform Lift	1st floor gym	1	EA	7	10+ years			
	Elevator - Elevator- Roped Holeless Hydraulic	2nd Floor	1	EA	6	10+ years			

Campus Name: Turner-Drew Page : 18 of 21 Assessment Date: 08/23/2023



Category : Site	Buil

Catego	ry : Site		Building : Site Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Civil/Dra								
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years		
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	6	10+ years		
Fencing								
Chong	Fencing - Chain Link	North	484	LF	4	1-2 years	Broken/Missing	
	Fencing - Old Standard Ornamental	North	335	LF	6	6-10 years	Separated the damaged parts from the entire fence	
	Fencing - Old Standard Ornamental	North	100	LF	4	0-1 year	Missing/Broken	
Landsca	pe							
	Benches	Entire Site	1	EA	7	10+ years		
	Landscape - Grass	Entire Site	15,245	SF	6	10+ years		
	Parkway trees	Entire Site	10	EA	7	10+ years		
	Planting Beds/ Area	Entire Site	982	SF	6	6-10 years		
	Play Area - Hardscape- Asphalt	Entire Site	4,519	SF	5	1-2 years	Cracking/Vegetation growth throughout	
Parking	Lot							
	Concrete Curbs	Parking Lot- North	1,486	LF	6	10+ years		
	Interior Plantings	Parking Lot- North	249	LF	6	10+ years		
	Lighting - Pole Mounted	Parking Lot- North	2	EA	7	6-10 years	Newly replaced	
	Surface - Asphalt	Parking Lot- North	24,091	SF	5	2-5 years	Cracking throughout	
	Vehicular Screening	Parking Lot- North	277	LF	6	10+ years	3 3	
Playgrou	und							
-,0	Equipment - Combo 3-12	South	1	EA	4	0-1 year	Rusted/Damaged throughout	
	Equipment - School Age 5-12	South	1	EA	4	1-2 years	Rusted/Damaged throughout	
	Equipment - Swingset	South	1	EA	4	1-2 years	Rusted and damaged	
	Surface - Poured Surface	South	6,400	SF	5	1-2 years	Holes/Cracks throughout	
Sidewall	ks							
	Sidewalks - Internal Walks	Entire Site	565	LF	6	10+ years		
	Sidewalks - Internal Walks	Entire Site	70	LF	4	1-2 years	Cracking by entrance 6	
	Sidewalks - Perimeter Sidewalks	Entire Site	150	SF	7	10+ years	Newly replaced	
	Sidewalks - Perimeter Sidewalks	Entire Site	4,079	SF	6	10+ years	Tromy ropidood	
Signage								
990	Flag Pole - Flag Pole	East	1	EA	7	10+ years		
	Marquee - Free Standing Back Lighted	East	1	EΑ	7	6-10 years		
	Monument - Building Mounted Cut Letter	East	1	EA	7	10+ years		
	3 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -					,		



Turner-Drew Elementary Language Academy

9300 S Princeton AVENUE, Chicago, IL 60620

Category : Site Building : Site

Recommend

Group Item - Type Location Quantity UOM Rank Replacement Comments


Sign

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Turner-Drew Page: 20 of 21 Assessment Date: 08/23/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Olassicom Gammary			D	Floor Plan	A	Glazed	Operable	Maries el econ	0
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window Stop	Smart- Board
Building : Main	on dougo		1101111001	1100000	(0.7	7	700	0.00	
Computer Lab	Regular Classroom	1st Floor	112	112	812	210	72	Υ	N
Computer Lab	Regular Classroom	2nd Floor	203	203	812	138	48	Y	Y
Kindergarten	Kindergarten	1st Floor	102	102	1,064	279	81	N	N
Library	Regular Classroom	2nd Floor	208	208	812	210	72	Y	N
Office	Kindergarten	1st Floor	104	104	1,064	315	108	Υ	N
Office	Regular Classroom	1st Floor	101	101	360	93	81	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	812	138	48	Υ	N
Regular Classroom	Regular Classroom	1st Floor	107	107	812	138	48	Υ	N
Regular Classroom	Regular Classroom	1st Floor	108	108	812	138	48	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	812	210	72	Υ	N
Regular Classroom	Regular Classroom	1st Floor	114	114	812	210	72	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	812	138	48	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	812	138	48	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	812	138	48	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	812	210	72	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	812	210	72	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	812	210	72	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	812	210	72	Υ	N
Regular Classroom	Science	2nd Floor	206	206	812	210	72	Υ	Υ
Science	Regular Classroom	2nd Floor	204	204	812	210	72	Υ	N
Science Classroom	Regular Classroom	2nd Floor	205	205	812	124	40	Υ	N