

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1957	3	214,541
Modular 1 (4-Classroom)	2002	1	4,750
Campus Total			219,291

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	13B	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	13B	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	13C	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	13C	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	14A	1	EA	6	10+ years	
	Exterior Stairs - Concrete	14A	9	LF	7	10+ years	
	Exterior Stairs - Concrete	14A	3	LF	5	1-2 years	Cracked landing
	Exterior Doors - Exterior Steel Door	22A East courtyard	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	22A East courtyard	1	EA	6	10+ years	
	Exterior Stairs - Concrete	22A East courtyard	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	23-Entrance Roof 5	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	24	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	24	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 13A	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 13A	3	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 13A	50	LF	5	10+ years	
	Exterior Stairs - Concrete	Entrance 13A	50	LF	5	1-2 years	Cracks, spalled concrete throughout
	Ramps - Concrete	Entrance 13A	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 14-SW	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 14-SW	10	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 14-SW	2	LF	5	1-2 years	Cracked concrete
	Exterior Doors - Exterior Steel Door	Entrance 15-E - Drivers Ed trailer	2	EA	6	2-5 years	Corroding
	Exterior Stairs - Wood	Entrance 15-E - Drivers Ed trailer	30	LF	7	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Stair Handrail - Steel_Stair Handrail	Entrance 15-E - Drivers Ed trailer	24	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	Entrance 16-W - Overhead door at boiler room	1	EA	6	10+ years	
	Ramps - Concrete	Entrance 16-W - Overhead door at boiler room	10	LF	6	6-10 years	
	Ramps - Concrete	Entrance 16-W - Overhead door at boiler room	6	LF	5	1-2 years	Cracked concrete
	Entrance Control - Audio and Video	Entrance 17-W	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 17-W	2	EA	7	10+ years	
	Exterior Doors - Side lite	Entrance 17-W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 17-W	1	EA	6	10+ years	
	Ramps - Concrete	Entrance 17-W	10	LF	6	10+ years	
	Ramps - Concrete	Entrance 17-W	5	LF	5	1-2 years	Cracked landing
	Entrance Control - Audio and Video	Entrance 19-NW	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 19-NW	4	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 19-NW	2	EA	7	10+ years	
	Exterior Doors - Side lite	Entrance 19-NW	12	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 19-NW	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 19-NW	100	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 19-NW	20	LF	5	1-2 years	Cracked, spalled with exposed rebar
	Power Door Operator and Controls	Entrance 19-NW	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 19-NW	8	LF	6	10+ years	
	Ramps - Concrete	Entrance 19-NW	16	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 19A - ComEd outside electrical vault	2	EA	6	10+ years	
	Entrance Control - Audio and Video	Entrance 2-NE	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 2-NE	2	EA	7	10+ years	
	Exterior Doors - Side lite	Entrance 2-NE	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 2-NE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 2-NE	7	LF	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 2-NE	8	LF	5	0-1 year	This is a slab approximately 30' x 15'. Large section of it are small and cracked.
	Exterior Doors - Exterior Steel Door	Entrance 20 - Outside Yard Storage	2	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	Entrance 21-West court	2	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 21-West court	8	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 21-West court	1	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	Entrance 21D - West Court	2	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 21D - West Court	8	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 21D - West Court	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 21D - West Court	11	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 21D - West Court	1	LF	5	1-2 years	Cracked concrete
	Exterior Doors - Exterior Steel Door	Entrance 22 - East Court	2	EA	7	10+ years	
	Exterior Doors - Side lite	Entrance 22 - East Court	8	EA	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Doors - Transom Lite	Entrance 22 - East Court	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 22 - East Court	12	LF	7	10+ years	
	Exterior Doors - Exterior Wood Door	Entrance 22B - East Court	2	EA	4	1-2 years	Delaminated wood, rotted
	Exterior Doors - Side lite	Entrance 22B - East Court	8	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 22B - East Court	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 22B - East Court	6	LF	6	10+ years	No concrete
	Exterior Doors - Exterior Steel Door	Entrance 6-SE	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 6-SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 6-SE	3	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 9-S	2	EA	7	10+ years	
	Exterior Doors - Side lite	Entrance 9-S	8	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 9-S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 9-S	9	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 9-S	1	LF	5	1-2 years	Cracked
	Exterior Doors - Exterior Steel Door	Exit 10-S	2	EA	6	10+ years	
	Exterior Doors - Side lite	Exit 10-S	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Exit 10-S	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Exit 10-S	11	LF	6	10+ years	
	Exterior Stairs - Concrete	Exit 10-S	1	LF	5	1-2 years	Cracked
	Exterior Doors - Exterior Steel Door	Exit 11-S	1	EA	4	1-2 years	Warped door
	Exterior Stairs - Concrete	Exit 11-S	6	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 12-S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 12-S	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 18-W	1	EA	5	1-2 years	Corroded frame
	Exterior Doors - Exterior Wood Door	Exit 21A-West Court	1	EA	4	1-2 years	Delaminated wood door
	Exterior Doors - Transom Lite	Exit 21A-West Court	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 21A-West Court	9	LF	7	10+ years	
	Exterior Stairs - Concrete	Exit 21A-West Court	1	LF	5	1-2 years	Cracked concrete
	Exterior Doors - Exterior Wood Door	Exit 21B - West Court	1	EA	4	1-2 years	Delaminated, rotted wood door
	Exterior Doors - Transom Lite	Exit 21B - West Court	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 21B - West Court	6	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	Exit 21C - West Court	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Exit 21C - West Court	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Exit 22A - East Court	2	EA	6	10+ years	
	Exterior Doors - Side lite	Exit 22A - East Court	16	EA	6	10+ years	
	Exterior Doors - Transom Lite	Exit 22A - East Court	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 22A - East Court	6	LF	6	10+ years	Verified quantity
	Exterior Doors - Exterior Steel Door	Exit 5-SE	2	EA	6	10+ years	
	Exterior Doors - Side lite	Exit 5-SE	4	EA	5	0-1 year	Damaged guard
	Exterior Doors - Transom Lite	Exit 5-SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 5-SE	15	LF	5	1-2 years	Entire landing approximately 15 x 30' is spalled cracked torn up, with exposed reinforcement, corroding.
	Exterior Doors - Exterior Steel Door	Exit 7-S	1	EA	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Doors - Transom Lite	Exit 7-S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 7-S	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 8-S	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Exit 8-S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 8-S	3	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Exits 3-E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Exits 3-E	6	LF	7	10+ years	
	Entrance Control - Audio and Video	Main Entrance 1-N	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Main Entrance 1-N	6	EA	7	10+ years	
	Exterior Doors - Side lite	Main Entrance 1-N	14	EA	6	10+ years	
	Exterior Doors - Transom Lite	Main Entrance 1-N	6	EA	6	10+ years	
	Exterior Stairs - Concrete	Main Entrance 1-N	50	LF	6	6-10 years	
	Exterior Stairs - Concrete	Main Entrance 1-N	100	LF	5	1-2 years	Spalled, cracked, exposed rebar

Foundation

	Foundation - Concrete	Entire Building	3,738	LF	7	10+ years	
	Foundation - Concrete	Entire Building	12	LF	6	0-1 year	These are minor deficiencies. Spalled, cracked concrete.
	Superstructure - Concrete	Entire Building	215,541	SF	7	10+ years	

Lighting

	Exterior Lighting - Lighting	Entire Building	19	EA	7	10+ years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	49	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	69	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	18	EA	4	1-2 years	Fixtures not working

Roof System

	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Coping - Metal	Roof 1	930	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 1	290	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	31,030	SF	7	10+ years	No key to the book room, per engineer information. Entire school is being re-keyed.
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years	
	Roof Structure - Concrete	Roof 1	31,030	SF	7	10+ years	
	Coping - Metal	Roof 10 - Outside yard storage	90	LF	5	1-2 years	No metal coping, rotting wood fascia
	Roof - Modified Bitumen	Roof 10 - Outside yard storage	485	SF	6	6-10 years	
	Roof Structure - Concrete	Roof 10 - Outside yard storage	485	SF	7	10+ years	
	Access Ladder - Metal	Roof 11	1	EA	7	10+ years	
	Access Ladder - Metal	Roof 11	1	EA	7	10+ years	Staircase is secure, not part of the roof
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 11	80	LF	3	0-1 year	Large, long cracks. Brick is pulled

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Liner						away with uneven surfaces, open joints
	Coping - Metal	Roof 11	510	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 11	300	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 11	13,230	SF	7	10+ years	
	Roof Hatch - Metal	Roof 11	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 11	13,230	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof 2	36	LF	6	10+ years	
	Coping - Metal	Roof 2	445	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 2	115	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	90	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	8,220	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 2	4,000	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 2	12,220	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	1	EA	7	10+ years	
	Coping - Metal	Roof 3	325	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	105	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	9,115	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	1,500	SF	7	10+ years	
	Roof Hatch - Metal	Roof 3	1	EA	7	10+ years	
	Roof Structure - Concrete	Roof 3	10,615	SF	7	10+ years	
	Access Ladder - Metal	Roof 4	1	EA	7	10+ years	
	Coping - Metal	Roof 4	420	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4	120	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	8,850	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4	8,850	SF	7	10+ years	
	Access Ladder - Metal	Roof 5	5	EA	7	10+ years	
	Access Ladder - Metal	Roof 5	1	EA	7	10+ years	
	Coping - Metal	Roof 5	1,490	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 5	445	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 5	53,650	SF	6	10+ years	
	Roof Structure - Concrete	Roof 5	53,650	SF	7	10+ years	
	Access Ladder - Metal	Roof 6	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof 6	32	LF	7	10+ years	
	Coping - Metal	Roof 6	55	LF	7	10+ years	
	Coping - Metal	Roof 6	1,650	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 6	255	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 6	55	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 6	47,490	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 6	100	SF	5	1-2 years	Damaged, torn roofing

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Roof Hatch - Metal	Roof 6	1	EA	7	10+ years	
	Roof Structure - Concrete	Roof 6	47,590	SF	7	10+ years	
	Access Ladder - Metal	Roof 7	1	EA	7	10+ years	
	Coping - Metal	Roof 7	240	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 7	50	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 7	3,560	SF	7	10+ years	
	Roof Structure - Concrete	Roof 7	3,560	SF	7	10+ years	
	Roof - Metal	Roof 9	900	SF	4	0-1 year	Corroded
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 9	900	SF	7	10+ years	

Walls

	Canopy - Concrete/ Stucco	Entire Building	6,425	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	47,265	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	4	1-2 years	Broken, missing, open joints
	Exterior Walls - Concrete Block	Entire Building	665	SF	7	10+ years	
	Exterior Walls - Concrete Block	Entire Building	435	SF	7	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	600	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	355	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	10	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	30	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	4,945	SF	6	10+ years	
	Exterior Walls - Vinyl Siding	Entire Building	440	SF	6	10+ years	

Windows

	Clerestory - Glass Double-Pane	Entire Building	3,090	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	19,645	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	110	SF	5	1-2 years	Broken seals
	Curtain wall - Insulated Panel	Entire Building	405	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	2,860	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	2,860	SF	5	1-2 years	Broken seals
	Guard - Guards wire guard	Entire Building	30	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	75	SF	6	10+ years	
	Lintels - Concrete	Entire Building	105	LF	6	10+ years	
	Lintels - Steel	Entire Building	152	LF	6	10+ years	
	Windows - Louver	Entire Building	380	SF	6	10+ years	

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergency System							
	Automatic Transfer Switch	Electrical Room	2	EA	7	6-10 years	
	Exit Signs - Auditorium	Entire Building	6	EA	5	2-5 years	Older signs with stained lenses

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exit Signs - Corridors and Stairs	Entire Building	57	EA	5	2-5 years	Older signs with stained lenses
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	4	2-5 years	Not illuminating
	Exit Signs - Gym	Entire Building	2	EA	5	2-5 years	Older signs with stained lenses
	Exit Signs - Lunchroom	Entire Building	7	EA	5	2-5 years	Older signs with stained lenses
	Exit Signs - Multipurpose Room	Entire Building	11	EA	5	2-5 years	Older signs with stained lenses
	Security System - CCTV	Entire Building	214,541	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	214,541	SF	5	6-10 years	
	Emergency Battery Packs - Auditorium and Aisle Lighting	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	58	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	7	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
	Emergency A/C Power - Auditorium and Aisle Lighting	Entire Building	7,150	SF	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	31,320	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	13,530	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	8,800	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	2,340	SF	6	10+ years	

Main Service

Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	CDP PANEL
Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	4	1-2 years	In switchgear room
Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	4	1-2 years	Switchgear
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
PA System	Entire Building	214,541	SF	7	6-10 years	

Power Distribution

Lighting and Power Panels - 100 A	Entire Building	2	EA	7	6-10 years	
Lighting and Power Panels - 100 A	Entire Building	12	EA	6	6-10 years	
Lighting and Power Panels - 100 A	Entire Building	3	EA	6	2-5 years	
Lighting and Power Panels - Above 100 A	Entire Building	11	EA	7	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	Cp1 and cp3 panel

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	6-10 years	Room 201
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	6-10 years	Room 201
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	DP AC PANEL
	Main Distribution Panels - 400 - 600 amp	Entire Building	6	EA	6	6-10 years	

Category : Fire Protection
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alarm</u>							
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	214,541	SF	6	10+ years	
	Fire Alarm_System	Entire Building	214,541	SF	6	10+ years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Air Conditioning</u>							
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	6-10 years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	6-10 years	
<u>Air Handling Systems</u>							
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	7	10+ years	Elevator room
	Roof Top Unit-Single Zone-Roof Mounted-Gas Heating and DX Cooling Coil - 11 - 20 tons	Roof	1	EA	7	10+ years	
	Roof Top Unit-Single Zone-Roof Mounted-Gas Heating and DX Cooling Coil - 11 - 20 tons	Roof	1	EA	7	10+ years	
	Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 4000-8000 cfm	Served cafeteria south side half	1	EA	5	6-10 years	
	Air Intake	Served cafeteria south side half	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 20001-30000 cfm	Serves Auditorium	1	EA	5	2-5 years	Serves auditorium
	Air Intake	Serves Auditorium	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone-Indoor- Steam Coils - 4000-8000 cfm	Serves North large gym	1	EA	5	2-5 years	
	Air Intake	Serves North large gym	1	EA	6	6-10 years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 12001-20000 cfm	Serves Pool	1	EA	5	2-5 years	
	Air Intake	Serves Pool	1	EA	7	10+ years	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Serves South side Gym	1	EA	5	2-5 years	Serves southside gym
	Air Intake	Serves South side Gym	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Serves lockers areas	1	EA	5	2-5 years	
	Air Intake	Serves lockers areas	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Serves north side half cafeteria	1	EA	5	2-5 years	
	Air Intake	Serves north side half cafeteria	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Serves serving line and kitchen.	1	EA	5	2-5 years	
	Air Intake	Serves serving line and kitchen.	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Serves small Gym	2	EA	7	2-5 years	
	Air Intake	Serves small Gym	2	EA	7	6-10 years	

Boiler Systems

Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Less than 50 HP	Boiler Room	2	EA	5	2-5 years	
Chemical Feed System	Boiler Room	1	EA	7	6-10 years	
Chemical Feeder	Boiler Room	1	EA	7	6-10 years	
Combustion Dampers	Boiler Room	3	EA	4	1-2 years	Corroded, manually controlled per engineer
Condensate Pump	Boiler Room	1	EA	6	2-5 years	
Feed Water Pumps and Tank	Boiler Room	1	EA	5	2-5 years	Damaged insulation
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Less than 50 HP	Boiler Room	1	EA	6	6-10 years	
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Less than 50 HP	Boiler Room	1	EA	6	6-10 years	
Piping - Condensate Pipe- Steel	Boiler Room	1,000	LF	6	6-10 years	
Piping - Steam Pipe- Steel	Boiler Room	1,000	LF	6	2-5 years	
Steam Traps	Boiler Room	94	EA	5	2-5 years	Older traps
Vacuum Pump	Boiler Room	1	EA	6	6-10 years	

Heating Devices

Wall Heater - Electric	1st Floor	4	EA	6	10+ years	
Wall Heater - Electric	1st Floor	1	EA	5	6-10 years	
Wall Heater - Electric	1st Floor	2	EA	4	0-1 year	Corroded cover
Unit Heater - Steam	Entire Building	2	EA	5	2-5 years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Unit Heater - Steam	Entire Building	2	EA	5	2-5 years	
	Unit Heater - Steam	Entire Building	1	EA	5	2-5 years	
	Fin Tube - Steam	Entire Building	250	LF	6	0-1 year	Deteriorated, occasionally leaks
	Fin Tube - Steam	Entire Building	1,950	LF	6	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	20	EA	6	2-5 years	
	Duct Heater - Hot Water	Mechanical Room	6		5	10+ years	Steam coil, not hot water.

Temperature Control

	Electric Thermostat	Entire Building	5	EA	6	10+ years	
	Pneumatic System	Entire Building	214,541	SF	6	1-2 years	Leaking and pneumatics not working properly
	Thermostats - Pneumatic	Entire Building	63	EA	6	2-5 years	
	Thermostats - Pneumatic	Entire Building	24	EA	4	1-2 years	Need cover plates, leaking and not calibrated

Unit Ventilation

	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	50	EA	5	2-5 years	Older but working per engineer
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	29	EA	4	1-2 years	Older, deteriorated

Ventilation

	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	6	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	14	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	10	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	5	EA	6	10+ years	
	Roof Mounted Duct Work	Entire Building	20	LF	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression system
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Hot Water</u>							
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	7	10+ years	Replaced
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	1	EA	4	1-2 years	Deteriorated

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	1	EA	4	1-2 years	Deteriorated
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Mechanical Room	1	EA	5	6-10 years	

Piping

	Domestic Piping-Hot Water Return Lines	Entire Building	214,541	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	214,541	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	214,541	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	214,541	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	214,541	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	214,541	SF	6	2-5 years	
	Sanitary Piping	Entire Building	214,541	SF	6	6-10 years	
	Storm Piping	Entire Building	214,541	SF	6	6-10 years	
	Vent Piping	Entire Building	214,541	SF	6	6-10 years	

Pool Systems

	Pool Drain Piping	1st Floor	100	LF	6	10+ years	Out of service
	Pool Filtration System including Pump	1st Floor	1	EA	5	6-10 years	
	Pool Hot Water Heater - Gas Fired	1st Floor	1	EA	3	0-1 year	
	Pool Supply and Return Piping	1st Floor	100	LF	6	10+ years	

Pumps

	Pumps - Ejector-Duplex	Basement	1	EA	6	10+ years	
	Pumps - Ejector-Duplex	Basement	1	EA	6	2-5 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administrative Suites/Offices							
	Ceiling - Lay-in	104B-1 - Library office	280	SF	6	10+ years	Water damage, quantity updated to match current observations
	Ceiling - Lay-in	104B-1 - Library office	25	SF	4	1-2 years	
	Doors - Wood Doors inclu hw	104B-1 - Library office	2	EA	6	10+ years	
	Floor - Wood	104B-1 - Library office	305	SF	6	10+ years	
	Lighting - Lay-in	104B-1 - Library office	4	EA	6	6-10 years	
	Power Distribution	104B-1 - Library office	8	EA	6	10+ years	
	Walls - Concrete Block	104B-1 - Library office	240	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	104B-1 - Library office	40	SF	6	10+ years	
	Ceiling - Splined	111 Teachers lounge	2,753	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Steel Doors incl hw	111 Teachers lounge	2	EA	6	10+ years	
	Doors - Wood Doors inclu hw	111 Teachers lounge	4	EA	6	10+ years	
	Floor - Sport Flooring	111 Teachers lounge	2,753	SF	7	10+ years	
	Lighting - Pendent/Surface	111 Teachers lounge	16	EA	6	6-10 years	
	Power Distribution	111 Teachers lounge	40	EA	7	10+ years	
	Walls - Concrete Block	111 Teachers lounge	3,112	SF	6	10+ years	
	Walls - Plaster/Drywall	111 Teachers lounge	60	SF	6	10+ years	
	AC Unit	111A Office	1	EA	7	6-10 years	
	Ceiling - Splined	111A Office	336	SF	6	10+ years	
	Doors - Wood Doors inclu hw	111A Office	3	EA	6	10+ years	
	Floor - Tile Quarry	111A Office	336	SF	6	10+ years	
	Lighting - Pendent/Surface	111A Office	8	EA	6	6-10 years	
	Power Distribution	111A Office	8	EA	6	10+ years	
	Walls - Plaster/Drywall	111A Office	250	SF	7	10+ years	
	Walls - Structural Glazed Tile	111A Office	420	SF	6	10+ years	
	Work Slnk	111A Office	1	EA	7	6-10 years	
	Ceiling - Splined	121A - Counselors waiting room	125	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A - Counselors waiting room	2	EA	6	10+ years	
	Floor - Tile	121A - Counselors waiting room	125	SF	6	10+ years	
	Lighting - Lay-in	121A - Counselors waiting room	3	EA	6	6-10 years	
	Walls - Concrete Block	121A - Counselors waiting room	248	SF	6	10+ years	
	Walls - Masonry	121A - Counselors waiting room	86	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	121A - Counselors waiting room	22	SF	6	10+ years	
	Ceiling - Lay-in	121A-2 Dean's Office	6	SF	7	6-10 years	
	Ceiling - Lay-in	121A-2 Dean's Office	119	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A-2 Dean's Office	2	EA	7	10+ years	
	Floor - Tile	121A-2 Dean's Office	125	SF	6	10+ years	
	Lighting - Pendent/Surface	121A-2 Dean's Office	3	EA	7	6-10 years	
	Power Distribution	121A-2 Dean's Office	4	EA	7	10+ years	
	Walls - Concrete Block	121A-2 Dean's Office	248	SF	7	10+ years	
	Ceiling - Splined	121A-3 - Counseling Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A-3 - Counseling Office	1	EA	6	10+ years	
	Floor - Tile	121A-3 - Counseling Office	146	SF	7	10+ years	
	Lighting - Pendent/Surface	121A-3 - Counseling Office	8	EA	6	6-10 years	
	Power Distribution	121A-3 - Counseling Office	4	EA	6	10+ years	
	Walls - Concrete Block	121A-3 - Counseling Office	350	SF	6	10+ years	
	Ceiling - Splined	121A-4 - Social worker Office	199	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A-4 - Social worker Office	2	EA	6	10+ years	
	Floor - Tile	121A-4 - Social worker Office	199	SF	6	10+ years	
	Lighting - Pendent/Surface	121A-4 - Social worker Office	4	EA	6	6-10 years	
	Power Distribution	121A-4 - Social worker Office	6	EA	6	10+ years	
	Walls - Concrete Block	121A-4 - Social worker Office	437	SF	6	10+ years	
	Ceiling - Splined	121A-5 - Counselors Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A-5 - Counselors Office	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	121A-5 - Counselors Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	121A-5 - Counselors Office	3	EA	6	6-10 years	
	Power Distribution	121A-5 - Counselors Office	4	EA	6	10+ years	
	Walls - Concrete Block	121A-5 - Counselors Office	350	SF	6	10+ years	
	Ceiling - Splined	121A-6 - Counselors Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A-6 - Counselors Office	1	EA	6	10+ years	
	Floor - Tile	121A-6 - Counselors Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	121A-6 - Counselors Office	3	EA	6	6-10 years	
	Power Distribution	121A-6 - Counselors Office	4	EA	6	10+ years	
	Walls - Concrete Block	121A-6 - Counselors Office	350	SF	6	10+ years	
	Ceiling - Splined	121A-7 - Counselors Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A-7 - Counselors Office	1	EA	6	10+ years	
	Floor - Tile	121A-7 - Counselors Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	121A-7 - Counselors Office	3	EA	6	6-10 years	
	Power Distribution	121A-7 - Counselors Office	4	EA	6	10+ years	
	Walls - Concrete Block	121A-7 - Counselors Office	350	SF	6	10+ years	
	Ceiling - Splined	121A-8 - Counselors Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A-8 - Counselors Office	1	EA	6	10+ years	
	Floor - Tile	121A-8 - Counselors Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	121A-8 - Counselors Office	3	EA	6	6-10 years	
	Power Distribution	121A-8 - Counselors Office	4	EA	6	10+ years	
	Walls - Concrete Block	121A-8 - Counselors Office	350	SF	7	10+ years	
	Ceiling - Splined	121A-9 - Attendance Office	206	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121A-9 - Attendance Office	2	EA	6	10+ years	
	Floor - Tile	121A-9 - Attendance Office	206	SF	6	10+ years	
	Lighting - Pendent/Surface	121A-9 - Attendance Office	8	EA	6	6-10 years	
	Power Distribution	121A-9 - Attendance Office	4	EA	6	10+ years	
	Storage/ Closet	121A-9 - Attendance Office	36	SF	5	10+ years	
	Walls - Concrete Block	121A-9 - Attendance Office	515	SF	7	10+ years	
	Ceiling - Plaster/Drywall	124 B - Science office	286	SF	6	10+ years	
	Doors - Side-lite	124 B - Science office	120	SF	7	10+ years	
	Doors - Transom Window	124 B - Science office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	124 B - Science office	1	EA	6	10+ years	
	Floor - Tile	124 B - Science office	286	SF	6	10+ years	
	Lighting - Pendent/Surface	124 B - Science office	3	EA	6	6-10 years	
	Power Distribution	124 B - Science office	8	EA	6	10+ years	
	Walls - Concrete Block	124 B - Science office	588	SF	6	10+ years	
	Walls - Plaster/Drywall	124 B - Science office	80	SF	6	10+ years	
	Work Slnk	124 B - Science office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	126B Prep Room	286	SF	6	10+ years	
	Doors - Side-lite	126B Prep Room	80	SF	7	10+ years	
	Doors - Transom Window	126B Prep Room	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	126B Prep Room	1	EA	6	10+ years	
	Floor - Tile	126B Prep Room	286	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	126B Prep Room	3	EA	6	6-10 years	
	Power Distribution	126B Prep Room	8	EA	6	10+ years	
	Walls - Concrete Block	126B Prep Room	588	SF	6	10+ years	
	Walls - Plaster/Drywall	126B Prep Room	80	SF	7	10+ years	
	Work Slnk	126B Prep Room	1	EA	7	6-10 years	
	Ceiling - Splined	127B - Office	379	SF	6	10+ years	
	Doors - Wood Doors inclu hw	127B - Office	2	EA	6	10+ years	Room is not accessible. Components of room are ranked based on similar rooms.
	Floor - Tile	127B - Office	379	SF	6	10+ years	Room is not accessible. Components of room are ranked based on similar rooms.
	Lighting - Pendent/Surface	127B - Office	10	EA	6	6-10 years	
	Power Distribution	127B - Office	6	EA	6	10+ years	
	Walls - Concrete Block	127B - Office	759	SF	6	10+ years	
	Work Slnk	127B - Office	1	EA	7	6-10 years	
	AC Unit	130A - Main office	1	EA	7	6-10 years	
	Ceiling - Splined	130A - Main office	931	SF	6	10+ years	
	Doors - Side-lite	130A - Main office	102	SF	7	10+ years	
	Doors - Store Front	130A - Main office	2	EA	7	10+ years	
	Doors - Transom Window	130A - Main office	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	130A - Main office	2	EA	7	10+ years	
	Floor - Tile	130A - Main office	931	SF	6	10+ years	
	Lighting - Pendent/Surface	130A - Main office	22	EA	6	6-10 years	
	Power Distribution	130A - Main office	26	EA	7	10+ years	
	Walls - Concrete Block	130A - Main office	480	SF	7	10+ years	
	Walls - Masonry	130A - Main office	237	SF	7	10+ years	
	Walls - Plaster/Drywall	130A - Main office	210	SF	7	10+ years	
	AC Unit	130D - Office	1	EA	7	6-10 years	
	Ceiling - Splined	130D - Office	150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	130D - Office	1	EA	6	10+ years	Room is not accessible. Components of room are ranked based on similar rooms.
	Floor - Tile	130D - Office	150	SF	6	10+ years	Room is not accessible. Components of room are ranked based on similar rooms.
	Lighting - Pendent/Surface	130D - Office	2	EA	6	6-10 years	
	Power Distribution	130D - Office	6	EA	7	10+ years	
	Walls - Concrete Block	130D - Office	350	SF	7	10+ years	
	AC Unit	130E - Office	1	EA	7	6-10 years	
	Ceiling - Splined	130E - Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	130E - Office	1	EA	7	10+ years	
	Floor - Tile	130E - Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	130E - Office	2	EA	6	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Power Distribution	130E - Office	4	EA	7	10+ years	
	Walls - Concrete Block	130E - Office	350	SF	7	10+ years	
	AC Unit	130F - Office	1	EA	7	6-10 years	
	Ceiling - Splined	130F - Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	130F - Office	1	EA	7	10+ years	
	Floor - Tile	130F - Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	130F - Office	2	EA	6	6-10 years	
	Power Distribution	130F - Office	4	EA	7	10+ years	
	Walls - Concrete Block	130F - Office	350	SF	7	10+ years	
	AC Unit	130H - Office	1	EA	7	6-10 years	
	Ceiling - Splined	130H - Office	146	SF	6	10+ years	Room is not accessible. Components of room are ranked based on similar rooms.
	Doors - Wood Doors inclu hw	130H - Office	1	EA	7	10+ years	Room is not accessible. Components of room are ranked based on similar rooms.
	Floor - Tile	130H - Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	130H - Office	4	EA	6	6-10 years	
	Power Distribution	130H - Office	4	EA	7	10+ years	
	Walls - Concrete Block	130H - Office	175	SF	7	10+ years	
	Walls - Masonry	130H - Office	175	SF	7	10+ years	
	AC Unit	130I - Office	1	EA	7	6-10 years	
	Ceiling - Splined	130I - Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	130I - Office	1	EA	7	10+ years	
	Floor - Tile	130I - Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	130I - Office	2	EA	6	6-10 years	
	Power Distribution	130I - Office	4	EA	7	10+ years	
	Walls - Concrete Block	130I - Office	350	SF	7	10+ years	
	Work Slnk	130I - Office	1	EA	7	10+ years	Not previously assessed
	AC Unit	130J Principal's Office	1	EA	7	10+ years	Not previously assessed
	Ceiling - Splined	130J Principal's Office	352	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	130J Principal's Office	1	EA	7	10+ years	Not previously assessed
	Floor - Tile	130J Principal's Office	352	SF	7	10+ years	Not previously assessed
	Lighting - Pendent/Surface	130J Principal's Office	6	EA	7	10+ years	Not previously assessed
	Power Distribution	130J Principal's Office	8	EA	7	10+ years	Not previously assessed
	Walls - Concrete Block	130J Principal's Office	500	SF	7	10+ years	Not previously assessed
	AC Unit	132 Copy Room	1	EA	7	6-10 years	
	Ceiling - Splined	132 Copy Room	325	SF	6	10+ years	
	Doors - Wood Doors inclu hw	132 Copy Room	1	EA	6	10+ years	
	Floor - Tile	132 Copy Room	325	SF	6	10+ years	
	Lighting - Pendent/Surface	132 Copy Room	8	EA	6	6-10 years	
	Lighting - Wall Mounted	132 Copy Room	1	EA	6	6-10 years	
	Power Distribution	132 Copy Room	12	EA	7	10+ years	
	Walls - Concrete Block	132 Copy Room	542	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Masonry	132 Copy Room	182	SF	7	10+ years	
	AC Unit	134B Social Room	1	EA	7	6-10 years	
	Ceiling - Splined	134B Social Room	944	SF	6	10+ years	
	Doors - Wood Doors inclu hw	134B Social Room	1	EA	7	10+ years	
	Floor - Tile	134B Social Room	944	SF	6	10+ years	
	Lighting - Pendent/Surface	134B Social Room	18	EA	6	6-10 years	
	Power Distribution	134B Social Room	28	EA	7	10+ years	
	Walls - Concrete Block	134B Social Room	1,065	SF	7	10+ years	
	Walls - Plaster/Drywall	134B Social Room	416	SF	6	10+ years	
	AC Unit	200A - Office	1	EA	7	6-10 years	
	Ceiling - Splined	200A - Office	407	SF	6	10+ years	
	Doors - Wood Doors inclu hw	200A - Office	1	EA	6	10+ years	
	Floor - Tile	200A - Office	407	SF	6	10+ years	
	Lighting - Pendent/Surface	200A - Office	5	EA	6	6-10 years	
	Lighting - Pendent/Surface	200A - Office	5	EA	6	6-10 years	Relamp
	Power Distribution	200A - Office	10	EA	7	10+ years	
	Storage/ Closet	200A - Office	205	SF	5	10+ years	Missing light switch cover
	Walls - Concrete Block	200A - Office	484	SF	6	10+ years	
	Walls - Plaster/Drywall	200A - Office	287	SF	6	10+ years	
	Ceiling - Splined	201A - Office	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201A - Office	2	EA	6	10+ years	
	Floor - Tile	201A - Office	72	SF	6	10+ years	
	Lighting - Lay-in	201A - Office	1	EA	6	6-10 years	
	Power Distribution	201A - Office	4	EA	6	10+ years	
	Walls - Concrete Block	201A - Office	171	SF	7	10+ years	
	Ceiling - Splined	206A - Office	43	SF	6	10+ years	
	Doors - Steel Doors incl hw	206A - Office	1	EA	6	10+ years	
	Floor - Tile	206A - Office	43	SF	6	10+ years	
	Lighting - Pendent/Surface	206A - Office	1	EA	6	6-10 years	
	Power Distribution	206A - Office	4	EA	6	10+ years	
	Walls - Concrete Block	206A - Office	47	SF	6	10+ years	
	Walls - Metal Panel	206A - Office	40	SF	7	10+ years	
	Ceiling - Splined	215 Office	244	SF	6	10+ years	
	Ceiling - Splined	215 Office	5	SF	5	1-2 years	Water damage
	Doors - Transom Window	215 Office	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	215 Office	1	EA	6	10+ years	
	Floor - Tile	215 Office	249	SF	6	10+ years	
	Lighting - Pendent/Surface	215 Office	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	215 Office	1	EA	6	6-10 years	Relamp
	Power Distribution	215 Office	8	EA	7	10+ years	
	Storage/ Closet	215 Office	75	SF	7	10+ years	
	Walls - Concrete Block	215 Office	492	SF	6	10+ years	
	Ceiling - Splined	Boys Gym Office 142	175	SF	6	10+ years	Room is not accessible. Components of room are ranked based on

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Transom Window	Boys Gym Office 142	9	SF	6	10+ years	previous assessment. Room is not accessible. Components of room are ranked based on previous assessment.
	Doors - Wood Doors inclu hw	Boys Gym Office 142	1	EA	6	10+ years	
	Floor - Tile	Boys Gym Office 142	175	SF	6	10+ years	
	Lighting - Lay-in	Boys Gym Office 142	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Boys Gym Office 142	1	EA	5	0-1 year	Does not work
	Power Distribution	Boys Gym Office 142	6	EA	7	10+ years	
	Walls - Concrete Block	Boys Gym Office 142	384	SF	7	10+ years	
	AC Unit	Community in Schools Office	1	EA	7	6-10 years	
	Ceiling - Splined	Community in Schools Office	194	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Community in Schools Office	1	EA	7	10+ years	
	Floor - Tile	Community in Schools Office	194	SF	6	10+ years	
	Lighting - Pendent/Surface	Community in Schools Office	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Community in Schools Office	2	EA	6	6-10 years	
	Power Distribution	Community in Schools Office	17	EA	7	10+ years	
	Walls - Concrete Block	Community in Schools Office	396	SF	7	10+ years	
	Walls - Plaster/Drywall	Community in Schools Office	103	SF	6	10+ years	
	AC Unit	Engineer's Office in Boiler Room	1	EA	7	6-10 years	
	Ceiling - Lay-in	Engineer's Office in Boiler Room	208	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office in Boiler Room	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office in Boiler Room	208	SF	6	6-10 years	
	Lighting - Lay-in	Engineer's Office in Boiler Room	2	EA	6	6-10 years	
	Power Distribution	Engineer's Office in Boiler Room	14	EA	7	10+ years	
	Walls - Concrete Block	Engineer's Office in Boiler Room	503	SF	6	10+ years	
	Ceiling - Lay-in	Girls Gym Office 140	70	SF	6	10+ years	
	Doors - Side-lite	Girls Gym Office 140	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls Gym Office 140	1	EA	6	10+ years	
	Floor - Tile	Girls Gym Office 140	70	SF	6	10+ years	
	Lighting - Lay-in	Girls Gym Office 140	1	EA	6	6-10 years	
	Lighting - Lay-in	Girls Gym Office 140	1	EA	5	1-2 years	Missing cover
	Power Distribution	Girls Gym Office 140	6	EA	6	10+ years	
	Storage/ Closet	Girls Gym Office 140	30	SF	7	10+ years	
	Storage/ Closet	Girls Gym Office 140	750	SF	7	10+ years	
	Walls - Concrete Block	Girls Gym Office 140	140	SF	7	10+ years	
	Ceiling - Splined	Janitor Room was Dressing Room	174	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Janitor Room was Dressing Room	3	EA	6	10+ years	
	Floor - Tile	Janitor Room was Dressing Room	174	SF	6	10+ years	
	Lighting - Pendent/Surface	Janitor Room was Dressing Room	2	EA	6	6-10 years	Relamp
	Power Distribution	Janitor Room was Dressing Room	4	EA	7	10+ years	
	Walls - Concrete Block	Janitor Room was Dressing Room	482	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen office	85	SF	6	10+ years	Room is not accessible. Components of room are ranked based on

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	Kitchen office	65	SF	6	10+ years	previous assessment.
	Doors - Transom Window	Kitchen office	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen office	1	EA	7	10+ years	
	Floor - Tile Quarry	Kitchen office	85	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen office	2	EA	6	6-10 years	
	Power Distribution	Kitchen office	4	EA	7	10+ years	
	Walls - Concrete Block	Kitchen office	25	SF	7	10+ years	Room is not accessible. Components of room are ranked based on previous assessment.
	Walls - Metal Panel	Kitchen office	43	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Kitchen office	126	SF	7	10+ years	
	AC Unit	Office in 128	1	EA	7	6-10 years	
	Ceiling - Lay-in	Office in 128	204	SF	6	10+ years	No key, previous assessment data used
	Doors - Wood Doors inclu hw	Office in 128	2	EA	7	10+ years	No key, previous assessment data used
	Floor - Tile	Office in 128	204	SF	6	10+ years	No key, previous assessment data used
	Lighting - Lay-in	Office in 128	6	EA	6	6-10 years	No key, previous assessment data used
	Power Distribution	Office in 128	6	EA	7	10+ years	No key, previous assessment data used
	Walls - Concrete Block	Office in 128	414	SF	7	10+ years	No key, previous assessment data used
	Ceiling - Splined	Office/Music Library near 136	194	SF	6	10+ years	Water damage
	Doors - Wood Doors inclu hw	Office/Music Library near 136	1	EA	7	10+ years	
	Floor - Carpet	Office/Music Library near 136	194	SF	6	6-10 years	
	Lighting - Pendent/Surface	Office/Music Library near 136	4	EA	6	6-10 years	
	Power Distribution	Office/Music Library near 136	6	EA	7	10+ years	
	Storage/ Closet	Office/Music Library near 136	16	SF	7	10+ years	
	Walls - Concrete Block	Office/Music Library near 136	370	SF	7	10+ years	
	Ceiling - Lay-in	Pool Office 146G	120	SF	6	10+ years	
	Ceiling - Lay-in	Pool Office 146G	6	SF	5	1-2 years	
	Doors - Side-lite	Pool Office 146G	15	SF	7	10+ years	
	Doors - Steel Doors incl hw	Pool Office 146G	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	Pool Office 146G	126	SF	7	10+ years	
	Lighting - Pendent/Surface	Pool Office 146G	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Pool Office 146G	1	EA	5	1-2 years	
	Power Distribution	Pool Office 146G	126	EA	7	10+ years	
	Walls - Concrete Block	Pool Office 146G	357	SF	7	10+ years	
	Work Slnk	Pool Office 146G	1	EA	7	10+ years	Missing cover
	Ceiling - Lay-in	Pool Office 146J	114	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	Pool Office 146J	12	SF	5	1-2 years	Missing, damaged
	Doors - Steel Doors incl hw	Pool Office 146J	1	EA	7	10+ years	
	Doors - Steel Doors incl hw	Pool Office 146J	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	Pool Office 146J	126	SF	7	10+ years	
	Lighting - Pendent/Surface	Pool Office 146J	2	EA	6	6-10 years	
	Power Distribution	Pool Office 146J	126	EA	7	10+ years	
	Walls - Concrete Block	Pool Office 146J	257	SF	7	10+ years	
	Ceiling - Splined	Practice Room A near 136	102	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice Room A near 136	1	EA	7	10+ years	
	Floor - Carpet	Practice Room A near 136	102	SF	6	6-10 years	
	Lighting - Pendent/Surface	Practice Room A near 136	1	EA	6	6-10 years	Carpet stained and bubbling throughout
	Power Distribution	Practice Room A near 136	2	EA	7	10+ years	
	Walls - Concrete Block	Practice Room A near 136	275	SF	7	10+ years	
	Ceiling - Splined	Practice Room B near 136	90	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice Room B near 136	1	EA	7	10+ years	
	Floor - Carpet	Practice Room B near 136	90	SF	5	1-2 years	
	Lighting - Pendent/Surface	Practice Room B near 136	1	EA	6	6-10 years	
	Power Distribution	Practice Room B near 136	2	EA	7	10+ years	
	Walls - Concrete Block	Practice Room B near 136	174	SF	7	10+ years	
	Ceiling - Splined	Practice Room C near 136	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice Room C near 136	1	EA	7	6-10 years	
	Floor - Carpet	Practice Room C near 136	100	SF	6	6-10 years	
	Lighting - Pendent/Surface	Practice Room C near 136	1	EA	6	10+ years	
	Power Distribution	Practice Room C near 136	2	EA	7	10+ years	
	Walls - Concrete Block	Practice Room C near 136	280	SF	6	10+ years	
	Ceiling - Splined	Practice Room D near 136	74	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice Room D near 136	1	EA	7	10+ years	
	Floor - Carpet	Practice Room D near 136	74	SF	6	6-10 years	
	Lighting - Pendent/Surface	Practice Room D near 136	1	EA	6	6-10 years	
	Power Distribution	Practice Room D near 136	2	EA	7	10+ years	
	Walls - Concrete Block	Practice Room D near 136	162	SF	7	10+ years	
	AC Unit	Principal's Office	1	EA	7	10+ years	
	Ceiling - Splined	Principal's Office	325	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	7	10+ years	
	Floor - Tile/Sheet	Principal's Office	325	SF	7	10+ years	
	Lighting - Pendent/Surface	Principal's Office	6	EA	7	10+ years	
	Power Distribution	Principal's Office	6	EA	7	10+ years	
	Walls - Concrete Block	Principal's Office	680	SF	7	10+ years	
	Ceiling - Splined	Security Office	146	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Security Office	2	EA	6	10+ years	
	Floor - Tile	Security Office	146	SF	6	10+ years	
	Lighting - Pendent/Surface	Security Office	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Security Office	3	EA	6	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Power Distribution	Security Office	8	EA	6	10+ years	
	Walls - Concrete Block	Security Office	194	SF	7	10+ years	
	Walls - Plaster/Drywall	Security Office	103	SF	6	10+ years	
	AC Unit	Wood Shop	1	EA	7	6-10 years	
	Ceiling - Splined	Wood Shop	350	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Wood Shop	1	EA	7	10+ years	
	Floor - Tile	Wood Shop	350	SF	6	10+ years	
	Lighting - Pendent/Surface	Wood Shop	6	EA	6	6-10 years	
	Power Distribution	Wood Shop	10	EA	7	10+ years	
	Walls - Concrete Block	Wood Shop	702	SF	7	10+ years	

Auditorium & Theater

	Ceiling - Plaster/Drywall	1st Floor	7,150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	6	10+ years	
	Floor - Tile	1st Floor	7,150	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	42	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	EA	6	6-10 years	
	Main Floor Seating	1st Floor	555	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	2,597	SF	6	10+ years	
	Stage Curtain	1st Floor	4	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	Updated quantity
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	8	LF	7	10+ years	
	Storage/ Closet	1st Floor	250	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	6,486	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,697	SF	7	10+ years	

Gymnasia

	Bleacher Seating	Large/Boys' Gym 140	270	EA	7	10+ years	
	Ceiling - Exposed	Large/Boys' Gym 140	8,790	SF	6	10+ years	
	Doors - Steel Doors incl hw	Large/Boys' Gym 140	3	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Large/Boys' Gym 140	4	EA	7	10+ years	
	Floor - Wood	Large/Boys' Gym 140	8,790	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	Large/Boys' Gym 140	39	EA	6	6-10 years	
	Scoreboards	Large/Boys' Gym 140	1	EA	7	6-10 years	
	Walls - Concrete Block	Large/Boys' Gym 140	9,186	SF	7	10+ years	
	Ceiling - Exposed	Small/Girls' Gym 142	7,051	SF	6	10+ years	No maximum occupancy sign
	Doors - Transom Window	Small/Girls' Gym 142	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Small/Girls' Gym 142	2	EA	7	10+ years	
	Floor - Wood	Small/Girls' Gym 142	7,051	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure	Small/Girls' Gym 142	32	EA	6	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sodium						
	Scoreboards	Small/Girls' Gym 142	1	EA	7	6-10 years	
	Storage/ Closet	Small/Girls' Gym 142	750	SF	7	10+ years	
	Walls - Concrete Block	Small/Girls' Gym 142	8,554	SF	7	10+ years	
	Ceiling - Splined	Weight Room on Pool Balcony	1,060	SF	6	10+ years	
	Floor - Carpet	Weight Room on Pool Balcony	1,030	SF	7	10+ years	Corrected materil
	Floor - Carpet	Weight Room on Pool Balcony	30	SF	5	1-2 years	Water stains and damage throughout
	Lighting - Pendent/Surface	Weight Room on Pool Balcony	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	Weight Room on Pool Balcony	4	EA	5	1-2 years	Missing cover
	Walls - Concrete Block	Weight Room on Pool Balcony	1,000	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	1,143	SF	6	10+ years	
	Ceiling - Splined	1st Floor	1,077	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	7	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	2,220	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	44	EA	6	6-10 years	
	Serving Line	1st Floor	70	LF	7	10+ years	
	Storage/ Closet	1st Floor	89	SF	7	10+ years	Updated quantity
	Storage/ Closet	1st Floor	460	SF	5	10+ years	Updated quantity, damage to wall tile
	Walls - Concrete Block	1st Floor	1,043	SF	7	10+ years	
	Walls - Masonry	1st Floor	212	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	1,380	SF	7	10+ years	
Library							
	Casework	1st Floor	508	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	5,608	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Wood	1st Floor	5,608	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	70	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	192	SF	6	10+ years	
	Walls - Masonry	1st Floor	2,161	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	208	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,334	SF	6	10+ years	
Locker/Shower Room							
	Accessories	Boys Gym Locker Room	2,450	SF	7	6-10 years	
	Benches, ped mounted	Boys Gym Locker Room	30	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Boys Gym Locker Room	2,400	SF	6	10+ years	
	Ceiling - Splined (Moister Resistance)	Boys Gym Locker Room	46	SF	6	10+ years	
	Ceiling - Splined (Moister Resistance)	Boys Gym Locker Room	4	SF	4	1-2 years	Missing tiles
	Doors - Wood Doors inclu hw	Boys Gym Locker Room	5	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys Gym Locker Room	630	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Boys Gym Locker Room	20	SF	5	1-2 years	Cracking and missing tiles
	Floor - Tile/Sheet	Boys Gym Locker Room	1,792	SF	7	10+ years	
	Floor - Tile/Sheet	Boys Gym Locker Room	8	SF	5	1-2 years	Chipping and broken tiles
	Floor Drain	Boys Gym Locker Room	12	EA	7	10+ years	
	Hand Dryer	Boys Gym Locker Room	1	EA	7	6-10 years	
	Lavatory	Boys Gym Locker Room	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys Gym Locker Room	24	EA	6	6-10 years	
	Partitions	Boys Gym Locker Room	1	EA	7	10+ years	
	Showers	Boys Gym Locker Room	24	EA	7	10+ years	
	Storage/ Closet	Boys Gym Locker Room	40	SF	7	10+ years	
	Student Lockers - One Tier	Boys Gym Locker Room	50	EA	6	10+ years	
	Student Lockers - Two Tier	Boys Gym Locker Room	98	EA	6	10+ years	
	Urinals	Boys Gym Locker Room	2	EA	7	10+ years	Updated quantity
	Urinals	Boys Gym Locker Room	1	EA	5	1-2 years	Out of order
	Walls - Concrete Block	Boys Gym Locker Room	2,780	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys Gym Locker Room	1,482	SF	7	10+ years	
	Water Closet	Boys Gym Locker Room	1	EA	7	10+ years	
	Accessories	Boys Pool Locker Room	1,646	SF	7	6-10 years	
	Benches, ped mounted	Boys Pool Locker Room	58	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Boys Pool Locker Room	6	SF	6	1-2 years	Unfinished plaster repair
	Ceiling - Plaster/Drywall	Boys Pool Locker Room	1,624	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Boys Pool Locker Room	16	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	Boys Pool Locker Room	6	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys Pool Locker Room	1,646	SF	6	10+ years	
	Floor Drain	Boys Pool Locker Room	1	EA	7	10+ years	
	Hand Dryer	Boys Pool Locker Room	1	EA	7	6-10 years	
	Lavatory	Boys Pool Locker Room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Boys Pool Locker Room	22	EA	6	6-10 years	
	Partitions	Boys Pool Locker Room	2	EA	7	10+ years	
	Showers	Boys Pool Locker Room	8	EA	7	10+ years	
	Student Lockers - Two Tier	Boys Pool Locker Room	147	EA	7	10+ years	
	Urinals	Boys Pool Locker Room	2	EA	7	10+ years	
	Walls - Concrete Block	Boys Pool Locker Room	2,070	SF	7	10+ years	
	Walls - Concrete Block	Boys Pool Locker Room	10	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys Pool Locker Room	600	SF	7	10+ years	
	Water Closet	Boys Pool Locker Room	4	EA	7	10+ years	
	Accessories	Girls Gym Locker Room	2,047	SF	7	6-10 years	
	Benches, ped mounted	Girls Gym Locker Room	88	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Girls Gym Locker Room	2,047	SF	6	10+ years	
	Doors - Steel Doors incl hw	Girls Gym Locker Room	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Girls Gym Locker Room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Gym Locker Room	839	SF	6	10+ years	
	Floor - Tile/Sheet	Girls Gym Locker Room	1,208	SF	7	10+ years	
	Floor Drain	Girls Gym Locker Room	15	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Hand Dryer	Girls Gym Locker Room	7	EA	7	6-10 years	
	Lavatory	Girls Gym Locker Room	5	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls Gym Locker Room	5	EA	6	6-10 years	Relamp
	Lighting - Pendent/Surface	Girls Gym Locker Room	50	EA	6	6-10 years	
	Partitions	Girls Gym Locker Room	2	EA	7	10+ years	
	Showers	Girls Gym Locker Room	24	EA	7	6-10 years	
	Storage/ Closet	Girls Gym Locker Room	74	SF	5	10+ years	Did not have access to
	Student Lockers - One Tier	Girls Gym Locker Room	26	EA	7	10+ years	
	Student Lockers - Two Tier	Girls Gym Locker Room	216	EA	7	10+ years	
	Walls - Concrete Block	Girls Gym Locker Room	2,600	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls Gym Locker Room	220	SF	7	10+ years	
	Water Closet	Girls Gym Locker Room	3	EA	7	10+ years	
	Accessories	Girls Pool Locker	1,646	SF	7	6-10 years	
	Benches, ped mounted	Girls Pool Locker	56	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Girls Pool Locker	1,646	SF	6	10+ years	
	Doors - Steel Doors incl hw	Girls Pool Locker	6	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Pool Locker	1,626	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Pool Locker	20	SF	5	1-2 years	Missing baseboard tiles
	Floor Drain	Girls Pool Locker	1	EA	7	10+ years	
	Hand Dryer	Girls Pool Locker	2	EA	7	6-10 years	
	Lavatory	Girls Pool Locker	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls Pool Locker	21	EA	6	6-10 years	
	Partitions	Girls Pool Locker	3	EA	7	10+ years	
	Showers	Girls Pool Locker	8	EA	7	10+ years	
	Storage/ Closet	Girls Pool Locker	240	SF	7	10+ years	
	Student Lockers - Two Tier	Girls Pool Locker	145	EA	7	10+ years	
	Walls - Concrete Block	Girls Pool Locker	2,080	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls Pool Locker	300	SF	7	10+ years	
	Water Closet	Girls Pool Locker	3	EA	7	10+ years	
	Accessories	Kitchen Locker Room Across from Kitchen	121	SF	7	6-10 years	
	Ceiling - Exposed	Kitchen Locker Room Across from Kitchen	121	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Locker Room Across from Kitchen	1	EA	6	10+ years	
	Floor - Tile/Sheet	Kitchen Locker Room Across from Kitchen	121	SF	7	10+ years	
	Floor Drain	Kitchen Locker Room Across from Kitchen	1	EA	7	10+ years	
	Lavatory	Kitchen Locker Room Across from Kitchen	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Kitchen Locker Room Across from Kitchen	2	EA	6	6-10 years	
	Partitions	Kitchen Locker Room Across from Kitchen	1	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Student Lockers - One Tier	Kitchen	16	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Locker Room Across from Kitchen	240	SF	7	10+ years	
	Water Closet	Kitchen Locker Room Across from Kitchen	1	EA	7	10+ years	
	Accessories	Pool Unisex Locker	116	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Pool Unisex Locker	116	SF	6	10+ years	
	Doors - Steel Doors incl hw	Pool Unisex Locker	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Pool Unisex Locker	116	SF	6	10+ years	
	Floor Drain	Pool Unisex Locker	1	EA	7	10+ years	
	Hand Dryer	Pool Unisex Locker	2	EA	7	6-10 years	
	Lavatory	Pool Unisex Locker	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Pool Unisex Locker	2	EA	6	6-10 years	
	Showers	Pool Unisex Locker	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Pool Unisex Locker	293	SF	6	10+ years	
	Water Closet	Pool Unisex Locker	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Team Locker 1	416	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Team Locker 1	1	EA	6	10+ years	
	Floor - Tile	Team Locker 1	416	SF	6	10+ years	
	Lighting - Pendent/Surface	Team Locker 1	6	EA	6	6-10 years	
	Power Distribution	Team Locker 1	4	EA	7	10+ years	
	Walls - Concrete Block	Team Locker 1	902	SF	7	10+ years	
	Ceiling - Splined	Team Locker 2	281	SF	6	10+ years	Private key, no access. Previous assessment data.
	Doors - Wood Doors inclu hw	Team Locker 2	1	EA	4	0-1 year	Damaged door per previous assessment, no access
	Floor - Tile	Team Locker 2	281	SF	6	10+ years	Private key, no access. Previous assessment data.
	Lighting - Pendent/Surface	Team Locker 2	4	EA	6	6-10 years	Private key, no access. Previous assessment data.
	Power Distribution	Team Locker 2	4	EA	7	10+ years	Private key, no access. Previous assessment data.
	Walls - Concrete Block	Team Locker 2	317	SF	7	10+ years	Private key, no access. Previous assessment data.
	Walls - Plaster/Drywall	Team Locker 2	311	SF	6	10+ years	Private key, no access. Previous assessment data.
Lunch & Multipurpose Room							
	Ceiling - Plaster/Drywall	1st Floor	462	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	5,330	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	
	Floor - Tile	1st Floor	50	SF	7	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	1st Floor	5,742	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	54	EA	6	6-10 years	
	Storage/ Closet	1st Floor	415	SF	5	10+ years	Did not have access to
	Walls - Masonry	1st Floor	1,668	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	793	SF	6	10+ years	
	AC Unit	Faculty	1	EA	7	6-10 years	No max occupancy sign
	Ceiling - Splined	Faculty	686	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty	1	EA	5	1-2 years	Damage around lock
	Floor - Tile	Faculty	686	SF	6	10+ years	
	Lighting - Pendent/Surface	Faculty	12	EA	6	6-10 years	
	Walls - Masonry	Faculty	647	SF	7	10+ years	

MDF_IDE

Doors - Side-lite	MDF Room in Library	16	SF	7	10+ years	
Doors - Transom Window	MDF Room in Library	6	SF	7	10+ years	
Doors - Wood Doors inclu hw	MDF Room in Library	1	EA	6	10+ years	
Finishes	MDF Room in Library	249	SF	5	10+ years	
Other Cooling Unit	MDF Room in Library	1	EA	7	6-10 years	Split system
Window AC Unit	MDF Room in Library	1	EA	7	6-10 years	

Mechanical/ Service Rooms

Janitor's Closet	1st Floor	8	SF	7	10+ years	
Janitor's Closet	1st Floor	178	SF	5	10+ years	
Janitor's Closet	1st Floor	32	SF	5	6-10 years	
Loading Docks	1st Floor	450	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	135	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	325	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	229	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	302	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	50	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	291	SF	7	10+ years	
Storage Room	1st Floor	195	SF	7	10+ years	
Storage Room	1st Floor	52	SF	7	10+ years	
Storage Room	1st Floor	143	SF	7	10+ years	Former Fan Room
Storage Room	1st Floor	110	SF	7	10+ years	
Storage Room	1st Floor	161	SF	7	10+ years	
Storage Room	1st Floor	260	SF	7	10+ years	
Storage Room	1st Floor	415	SF	7	10+ years	
Storage Room	1st Floor	1,022	SF	7	10+ years	
Storage Room	1st Floor	436	SF	7	10+ years	
Storage Room	1st Floor	516	SF	5	10+ years	
Janitor's Closet	2nd Floor	87	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage Room	2nd Floor	586	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	28,365	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	600	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	6,800	SF	7	10+ years	
Pool & Natatorium							
	Accessories	1st Floor	8,058	SF	7	6-10 years	
	Ceiling - Exposed	1st Floor	8,000	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	58	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	8,058	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor	14	EA	6	6-10 years	
	Pool Basin	1st Floor	3,601	SF	7	10+ years	
	Pool Deck	1st Floor	4,457	SF	6	10+ years	
	Pool Deck Drains	1st Floor	13	EA	7	10+ years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	No access
	Walls - Concrete Block	1st Floor	8,974	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	8,914	SF	7	10+ years	
Prep Room							
	Casework	127/129 Prep	50	LF	7	10+ years	Inaccessible, teacher has key and is out for the summer
	Ceiling - Plaster/Drywall	127/129 Prep	301	SF	6	10+ years	Inaccessible, teacher has key and is out for the summer
	Doors - Wood Doors inclu hw	127/129 Prep	2	EA	7	10+ years	Inaccessible, teacher has key and is out for the summer
	Floor - Tile	127/129 Prep	301	SF	6	2-5 years	Inaccessible, teacher has key and is out for the summer
	Lighting - Pendent/Surface	127/129 Prep	8	EA	6	6-10 years	Inaccessible, teacher has key and is out for the summer
	Walls - Concrete Block	127/129 Prep	617	SF	7	10+ years	Inaccessible, teacher has key and is out for the summer
	Work Sink	127/129 Prep	1	EA	7	6-10 years	Inaccessible, teacher has key and is out for the summer
	Casework	Room 135A prep rm	50	LF	6	10+ years	
	Ceiling - Lay-in	Room 135A prep rm	296	SF	6	10+ years	
	Ceiling - Lay-in	Room 135A prep rm	5	SF	5	1-2 years	Water damage around vent
	Doors - Wood Doors inclu hw	Room 135A prep rm	3	EA	6	10+ years	
	Floor - Tile	Room 135A prep rm	301	SF	6	10+ years	
	Lighting - Lay-in	Room 135A prep rm	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room 135A prep rm	617	SF	6	10+ years	
	Work Sink	Room 135A prep rm	1	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Restroom							
	Accessories	103B - Unisex Toilet	21	SF	7	6-10 years	
	Ceiling - Splined	103B - Unisex Toilet	21	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103B - Unisex Toilet	1	EA	6	10+ years	
	Floor - Tile	103B - Unisex Toilet	21	SF	6	10+ years	
	Lavatory	103B - Unisex Toilet	1	EA	6	10+ years	
	Lighting - Wall Mounted	103B - Unisex Toilet	1	EA	6	6-10 years	
	Walls - Concrete Block	103B - Unisex Toilet	42	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	103B - Unisex Toilet	23	SF	6	10+ years	
	Water Closet	103B - Unisex Toilet	1	EA	6	10+ years	
	Accessories	106A - Unisex Toilet	21	SF	7	6-10 years	
	Ceiling - Splined	106A - Unisex Toilet	20	SF	6	10+ years	
	Ceiling - Splined	106A - Unisex Toilet	1	SF	4	0-1 year	Damaged tile
	Doors - Wood Doors inclu hw	106A - Unisex Toilet	1	EA	6	10+ years	
	Floor - Tile	106A - Unisex Toilet	21	SF	6	10+ years	
	Lavatory	106A - Unisex Toilet	1	EA	6	10+ years	
	Lighting - Wall Mounted	106A - Unisex Toilet	1	EA	6	6-10 years	
	Walls - Concrete Block	106A - Unisex Toilet	42	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	106A - Unisex Toilet	23	SF	6	10+ years	
	Water Closet	106A - Unisex Toilet	1	EA	6	10+ years	
	Accessories	108A - Unisex Toilet	21	SF	5	6-10 years	
	Ceiling - Splined	108A - Unisex Toilet	19	SF	6	10+ years	
	Ceiling - Splined	108A - Unisex Toilet	2	SF	5	0-1 year	Water damage, rank updated to match current observations
	Doors - Wood Doors inclu hw	108A - Unisex Toilet	1	EA	6	10+ years	
	Floor - Tile	108A - Unisex Toilet	21	SF	6	10+ years	
	Lavatory	108A - Unisex Toilet	1	EA	6	10+ years	
	Lighting - Wall Mounted	108A - Unisex Toilet	1	EA	4	0-1 year	Broken
	Walls - Concrete Block	108A - Unisex Toilet	42	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	108A - Unisex Toilet	23	SF	6	10+ years	
	Water Closet	108A - Unisex Toilet	1	EA	4	1-2 years	Out of order
	Accessories	114A - Boy's Toilet	310	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	114A - Boy's Toilet	310	SF	6	10+ years	
	Doors - Wood Doors inclu hw	114A - Boy's Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	114A - Boy's Toilet	310	SF	6	10+ years	
	Floor Drain	114A - Boy's Toilet	1	EA	7	10+ years	
	Hand Dryer	114A - Boy's Toilet	1	EA	7	6-10 years	
	Lavatory	114A - Boy's Toilet	3	EA	6	10+ years	
	Lighting - Pendent/Surface	114A - Boy's Toilet	5	EA	6	6-10 years	
	Partitions	114A - Boy's Toilet	2	EA	7	10+ years	
	Urinals	114A - Boy's Toilet	5	EA	6	10+ years	
	Walls - Concrete Block	114A - Boy's Toilet	325	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	114A - Boy's Toilet	352	SF	6	10+ years	
	Water Closet	114A - Boy's Toilet	2	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Accessories	114C - Women's Toilet	39	SF	7	6-10 years	Cracking
	Ceiling - Lay-in	114C - Women's Toilet	39	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114C - Women's Toilet	1	EA	6	10+ years	
	Floor - Tile	114C - Women's Toilet	35	SF	6	10+ years	
	Floor - Tile	114C - Women's Toilet	4	SF	4	1-2 years	
	Lavatory	114C - Women's Toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	114C - Women's Toilet	1	EA	6	6-10 years	
	Walls - Concrete Block	114C - Women's Toilet	79	SF	7	10+ years	
	Water Closet	114C - Women's Toilet	1	EA	6	10+ years	
	Accessories	114D - Girl's Toilet	343	SF	7	6-10 years	Constantly running
	Ceiling - Plaster/Drywall	114D - Girl's Toilet	343	SF	6	10+ years	
	Doors - Wood Doors inclu hw	114D - Girl's Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	114D - Girl's Toilet	343	SF	6	10+ years	
	Floor Drain	114D - Girl's Toilet	1	EA	7	10+ years	
	Hand Dryer	114D - Girl's Toilet	1	EA	7	6-10 years	
	Lavatory	114D - Girl's Toilet	3	EA	6	10+ years	
	Lighting - Pendent/Surface	114D - Girl's Toilet	5	EA	6	6-10 years	
	Partitions	114D - Girl's Toilet	6	EA	7	10+ years	
	Walls - Concrete Block	114D - Girl's Toilet	231	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	114D - Girl's Toilet	387	SF	6	10+ years	
	Water Closet	114D - Girl's Toilet	6	EA	6	10+ years	
	Accessories	125A - Boy's Toilet	285	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	125A - Boy's Toilet	285	SF	6	10+ years	
	Doors - Wood Doors inclu hw	125A - Boy's Toilet	1	EA	6	10+ years	
	Floor - Tile	125A - Boy's Toilet	44	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	125A - Boy's Toilet	241	SF	6	10+ years	
	Floor Drain	125A - Boy's Toilet	1	EA	7	10+ years	
	Hand Dryer	125A - Boy's Toilet	1	EA	7	6-10 years	
	Lavatory	125A - Boy's Toilet	3	EA	6	10+ years	
	Lighting - Pendent/Surface	125A - Boy's Toilet	5	EA	6	6-10 years	
	Partitions	125A - Boy's Toilet	2	EA	7	10+ years	
	Urinals	125A - Boy's Toilet	3	EA	6	10+ years	
	Walls - Concrete Block	125A - Boy's Toilet	545	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	125A - Boy's Toilet	30	SF	6	10+ years	
	Water Closet	125A - Boy's Toilet	1	EA	6	1-2 years	
	Water Closet	125A - Boy's Toilet	1	EA	6	10+ years	
	Accessories	125C - Unisex Toilet	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	125C - Unisex Toilet	90	SF	6	10+ years	
	Doors - Wood Doors inclu hw	125C - Unisex Toilet	1	EA	6	10+ years	
	Floor - Tile	125C - Unisex Toilet	90	SF	6	10+ years	
	Floor Drain	125C - Unisex Toilet	1	EA	7	10+ years	
	Hand Dryer	125C - Unisex Toilet	1	EA	7	6-10 years	
	Lavatory	125C - Unisex Toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	125C - Unisex Toilet	2	EA	6	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Concrete Block	125C - Unisex Toilet	12	SF	7	10+ years	
	Water Closet	125C - Unisex Toilet	1	EA	6	10+ years	
	Accessories	125D - Women's Toilet	104	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	125D - Women's Toilet	104	SF	6	10+ years	
	Doors - Wood Doors inclu hw	125D - Women's Toilet	1	EA	6	10+ years	
	Floor - Tile	125D - Women's Toilet	104	SF	6	10+ years	
	Floor Drain	125D - Women's Toilet	1	EA	7	10+ years	
	Lavatory	125D - Women's Toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	125D - Women's Toilet	3	EA	6	6-10 years	
	Partitions	125D - Women's Toilet	2	EA	7	10+ years	
	Walls - Concrete Block	125D - Women's Toilet	209	SF	7	10+ years	
	Water Closet	125D - Women's Toilet	2	EA	6	10+ years	
	Accessories	125E - Girl's Toilet	263	SF	7	6-10 years	
	Ceiling - Lay-in	125E - Girl's Toilet	68	SF	6	10+ years	
	Ceiling - Plaster/Drywall	125E - Girl's Toilet	195	SF	6	10+ years	
	Doors - Wood Doors inclu hw	125E - Girl's Toilet	1	EA	6	10+ years	
	Floor - Tile	125E - Girl's Toilet	68	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	125E - Girl's Toilet	195	SF	6	10+ years	
	Floor Drain	125E - Girl's Toilet	1	EA	7	10+ years	
	Hand Dryer	125E - Girl's Toilet	1	EA	7	6-10 years	
	Lavatory	125E - Girl's Toilet	3	EA	6	10+ years	
	Lighting - Pendent/Surface	125E - Girl's Toilet	5	EA	6	6-10 years	
	Partitions	125E - Girl's Toilet	4	EA	7	10+ years	
	Walls - Concrete Block	125E - Girl's Toilet	553	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	125E - Girl's Toilet	30	SF	6	10+ years	
	Water Closet	125E - Girl's Toilet	4	EA	6	10+ years	
	Accessories	129B - Girl's Toilet (across from main office)	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	129B - Girl's Toilet (across from main office)	263	SF	6	10+ years	
	Doors - Wood Doors inclu hw	129B - Girl's Toilet (across from main office)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	129B - Girl's Toilet (across from main office)	263	SF	6	10+ years	
	Floor Drain	129B - Girl's Toilet (across from main office)	1	EA	7	10+ years	
	Hand Dryer	129B - Girl's Toilet (across from main office)	1	EA	7	6-10 years	
	Lavatory	129B - Girl's Toilet (across from main office)	3	EA	7	10+ years	
	Lighting - Pendent/Surface	129B - Girl's Toilet (across from main office)	6	EA	6	6-10 years	
	Partitions	129B - Girl's Toilet (across from main office)	5	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Concrete Block	129B - Girl's Toilet (across from main office)	231	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	129B - Girl's Toilet (across from main office)	287	SF	7	10+ years	
	Water Closet	129B - Girl's Toilet (across from main office)	5	EA	7	10+ years	
	Accessories	129C - Boy's Toilet (across from main office)	209	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	129C - Boy's Toilet (across from main office)	209	SF	6	10+ years	
	Doors - Wood Doors inclu hw	129C - Boy's Toilet (across from main office)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	129C - Boy's Toilet (across from main office)	209	SF	6	10+ years	
	Floor Drain	129C - Boy's Toilet (across from main office)	1	EA	7	10+ years	
	Hand Dryer	129C - Boy's Toilet (across from main office)	1	EA	7	6-10 years	
	Lavatory	129C - Boy's Toilet (across from main office)	3	EA	7	10+ years	
	Lighting - Pendent/Surface	129C - Boy's Toilet (across from main office)	6	EA	6	6-10 years	
	Partitions	129C - Boy's Toilet (across from main office)	1	EA	7	10+ years	
	Urinals	129C - Boy's Toilet (across from main office)	4	EA	7	10+ years	
	Walls - Concrete Block	129C - Boy's Toilet (across from main office)	144	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	129C - Boy's Toilet (across from main office)	261	SF	7	10+ years	
	Water Closet	129C - Boy's Toilet (across from main office)	1	EA	7	10+ years	
	Accessories	201A - Staff Toilet	39	SF	7	6-10 years	
	Ceiling - Splined	201A - Staff Toilet	39	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201A - Staff Toilet	1	EA	6	10+ years	
	Floor - Tile	201A - Staff Toilet	39	SF	6	10+ years	
	Lavatory	201A - Staff Toilet	1	EA	6	10+ years	
	Lighting - Wall Mounted	201A - Staff Toilet	1	EA	6	6-10 years	
	Walls - Concrete Block	201A - Staff Toilet	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	201A - Staff Toilet	190	SF	7	10+ years	
	Water Closet	201A - Staff Toilet	1	EA	6	10+ years	
	Accessories	201C - Boy's Toilet	263	SF	7	6-10 years	
	Ceiling - Splined	201C - Boy's Toilet	263	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201C - Boy's Toilet	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	201C - Boy's Toilet	263	SF	6	10+ years	
	Floor Drain	201C - Boy's Toilet	1	EA	7	10+ years	
	Hand Dryer	201C - Boy's Toilet	1	EA	7	6-10 years	
	Lavatory	201C - Boy's Toilet	2	EA	6	10+ years	
	Lighting - Pendent/Surface	201C - Boy's Toilet	5	EA	6	6-10 years	
	Partitions	201C - Boy's Toilet	2	EA	7	10+ years	
	Urinals	201C - Boy's Toilet	4	EA	6	10+ years	
	Walls - Concrete Block	201C - Boy's Toilet	184	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	201C - Boy's Toilet	1	SF	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	201C - Boy's Toilet	239	SF	6	10+ years	
	Water Closet	201C - Boy's Toilet	2	EA	6	10+ years	
	Accessories	201E - Girl's Toilet	263	SF	7	6-10 years	
	Ceiling - Splined	201E - Girl's Toilet	263	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201E - Girl's Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	201E - Girl's Toilet	263	SF	6	10+ years	
	Floor Drain	201E - Girl's Toilet	1	EA	7	10+ years	
	Hand Dryer	201E - Girl's Toilet	1	EA	7	6-10 years	
	Lavatory	201E - Girl's Toilet	2	EA	6	10+ years	
	Lighting - Pendent/Surface	201E - Girl's Toilet	6	EA	6	6-10 years	
	Partitions	201E - Girl's Toilet	5	EA	7	10+ years	
	Walls - Concrete Block	201E - Girl's Toilet	231	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	201E - Girl's Toilet	387	SF	6	10+ years	
	Water Closet	201E - Girl's Toilet	5	EA	6	10+ years	
	Accessories	215B - Girl's Toilet	240	SF	7	6-10 years	
	Ceiling - Lay-in	215B - Girl's Toilet	47	SF	6	10+ years	
	Ceiling - Plaster/Drywall	215B - Girl's Toilet	193	SF	6	10+ years	
	Doors - Wood Doors inclu hw	215B - Girl's Toilet	1	EA	6	10+ years	
	Floor - Tile	215B - Girl's Toilet	47	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	215B - Girl's Toilet	193	SF	6	10+ years	
	Floor Drain	215B - Girl's Toilet	1	EA	7	10+ years	
	Hand Dryer	215B - Girl's Toilet	1	EA	7	6-10 years	
	Lavatory	215B - Girl's Toilet	3	EA	6	10+ years	
	Lighting - Pendent/Surface	215B - Girl's Toilet	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	215B - Girl's Toilet	1	EA	6	6-10 years	Relamp
	Partitions	215B - Girl's Toilet	4	EA	7	10+ years	
	Walls - Concrete Block	215B - Girl's Toilet	445	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	215B - Girl's Toilet	30	SF	6	10+ years	
	Water Closet	215B - Girl's Toilet	4	EA	6	10+ years	
	Accessories	215C - Women's Toilet	104	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	215C - Women's Toilet	104	SF	6	10+ years	
	Doors - Wood Doors inclu hw	215C - Women's Toilet	1	EA	6	10+ years	
	Floor - Tile	215C - Women's Toilet	104	SF	6	10+ years	
	Floor Drain	215C - Women's Toilet	1	EA	7	10+ years	
	Lavatory	215C - Women's Toilet	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	215C - Women's Toilet	3	EA	6	6-10 years	
	Partitions	215C - Women's Toilet	2	EA	7	10+ years	
	Walls - Concrete Block	215C - Women's Toilet	259	SF	6	10+ years	
	Water Closet	215C - Women's Toilet	2	EA	6	10+ years	
	Accessories	215D - Boy's Toilet	215	SF	7	6-10 years	
	Ceiling - Lay-in	215D - Boy's Toilet	47	SF	6	10+ years	
	Ceiling - Plaster/Drywall	215D - Boy's Toilet	168	SF	6	10+ years	
	Doors - Wood Doors inclu hw	215D - Boy's Toilet	1	EA	6	10+ years	
	Floor - Tile	215D - Boy's Toilet	47	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	215D - Boy's Toilet	168	SF	6	10+ years	
	Floor Drain	215D - Boy's Toilet	1	EA	7	10+ years	
	Hand Dryer	215D - Boy's Toilet	1	EA	7	6-10 years	
	Lavatory	215D - Boy's Toilet	3	EA	6	10+ years	
	Lighting - Pendent/Surface	215D - Boy's Toilet	1	EA	6	6-10 years	Very dim
	Lighting - Pendent/Surface	215D - Boy's Toilet	4	EA	6	6-10 years	
	Partitions	215D - Boy's Toilet	2	EA	7	10+ years	
	Urinals	215D - Boy's Toilet	3	EA	6	10+ years	
	Walls - Concrete Block	215D - Boy's Toilet	345	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	215D - Boy's Toilet	30	SF	6	10+ years	
	Water Closet	215D - Boy's Toilet	2	EA	6	10+ years	
	Accessories	215E - Men's Toilet	104	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	215E - Men's Toilet	104	SF	6	10+ years	
	Doors - Transom Window	215E - Men's Toilet	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	215E - Men's Toilet	1	EA	6	10+ years	
	Floor - Tile	215E - Men's Toilet	104	SF	6	10+ years	
	Floor Drain	215E - Men's Toilet	1	EA	7	10+ years	
	Lavatory	215E - Men's Toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	215E - Men's Toilet	3	EA	6	6-10 years	
	Partitions	215E - Men's Toilet	1	EA	7	10+ years	
	Urinals	215E - Men's Toilet	1	EA	6	10+ years	
	Walls - Concrete Block	215E - Men's Toilet	209	SF	7	10+ years	
	Water Closet	215E - Men's Toilet	1	EA	6	10+ years	
	Accessories	246D Women at Pool Balcony	88	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	246D Women at Pool Balcony	68	SF	6	10+ years	
	Ceiling - Plaster/Drywall	246D Women at Pool Balcony	20	SF	4	1-2 years	Water damage
	Doors - Steel Doors incl hw	246D Women at Pool Balcony	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	246D Women at Pool Balcony	88	SF	6	10+ years	
	Floor Drain	246D Women at Pool Balcony	1	EA	7	10+ years	
	Lavatory	246D Women at Pool Balcony	1	EA	7	10+ years	
	Lighting - Pendent/Surface	246D Women at Pool Balcony	1	EA	7	10+ years	
	Lighting - Pendent/Surface	246D Women at Pool Balcony	1	EA	6	6-10 years	Relamp
	Partitions	246D Women at Pool Balcony	2	EA	7	10+ years	
	Partitions	246D Women at Pool Balcony	1	EA	5	1-2 years	Missing door
	Walls - Concrete Block	246D Women at Pool Balcony	221	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	246D Women at Pool Balcony	2	EA	7	10+ years	
	Water Closet	246D Women at Pool Balcony	1	EA	4	1-2 years	Not in use
	Accessories	246F Men at Pool Balcony	88	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	246F Men at Pool Balcony	88	SF	6	10+ years	
	Doors - Steel Doors incl hw	246F Men at Pool Balcony	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	246F Men at Pool Balcony	88	SF	6	10+ years	
	Floor Drain	246F Men at Pool Balcony	1	EA	7	10+ years	
	Lavatory	246F Men at Pool Balcony	1	EA	7	10+ years	
	Lighting - Pendent/Surface	246F Men at Pool Balcony	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	246F Men at Pool Balcony	1	EA	6	6-10 years	Relamp
	Partitions	246F Men at Pool Balcony	1	EA	7	10+ years	
	Urinals	246F Men at Pool Balcony	2	EA	7	10+ years	
	Walls - Concrete Block	246F Men at Pool Balcony	216	SF	7	10+ years	
	Walls - Concrete Block	246F Men at Pool Balcony	5	SF	4	1-2 years	Missing CMU
	Water Closet	246F Men at Pool Balcony	1	EA	7	10+ years	
	Accessories	Boys Room 160	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys Room 160	192	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boys Room 160	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys Room 160	192	SF	6	10+ years	
	Floor Drain	Boys Room 160	1	EA	7	10+ years	
	Hand Dryer	Boys Room 160	1	EA	7	6-10 years	
	Lavatory	Boys Room 160	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys Room 160	5	EA	6	6-10 years	
	Partitions	Boys Room 160	2	EA	7	10+ years	
	Urinals	Boys Room 160	3	EA	6	10+ years	
	Walls - Concrete Block	Boys Room 160	190	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys Room 160	260	SF	7	10+ years	
	Water Closet	Boys Room 160	2	EA	7	10+ years	
	Accessories	Boys Room next to 138	100	SF	7	6-10 years	
	Ceiling - Splined	Boys Room next to 138	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boys Room next to 138	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys Room next to 138	100	SF	6	10+ years	
	Floor Drain	Boys Room next to 138	1	EA	7	10+ years	
	Lavatory	Boys Room next to 138	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys Room next to 138	2	EA	6	6-10 years	
	Partitions	Boys Room next to 138	1	EA	7	10+ years	
	Urinals	Boys Room next to 138	1	EA	7	10+ years	
	Walls - Concrete Block	Boys Room next to 138	100	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys Room next to 138	135	SF	7	10+ years	
	Water Closet	Boys Room next to 138	1	EA	7	10+ years	
	Accessories	Engineer Locker Room	129	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer Locker Room	129	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer Locker Room	1	EA	6	10+ years	
	Floor - Tile	Engineer Locker Room	129	SF	6	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor Drain	Engineer Locker Room	1	EA	7	10+ years	
	Lavatory	Engineer Locker Room	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Engineer Locker Room	3	EA	6	6-10 years	
	Partitions	Engineer Locker Room	1	EA	7	10+ years	
	Showers	Engineer Locker Room	1	EA	5	1-2 years	Out of order
	Student Lockers - One Tier	Engineer Locker Room	4	EA	6	6-10 years	
	Walls - Concrete Block	Engineer Locker Room	260	SF	7	10+ years	
	Water Closet	Engineer Locker Room	1	EA	6	10+ years	
	Accessories	Girls Restroom 187	215	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls Restroom 187	215	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls Restroom 187	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Restroom 187	215	SF	6	10+ years	
	Floor Drain	Girls Restroom 187	1	EA	7	10+ years	
	Hand Dryer	Girls Restroom 187	1	EA	7	6-10 years	
	Lavatory	Girls Restroom 187	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls Restroom 187	5	EA	6	6-10 years	
	Partitions	Girls Restroom 187	4	EA	7	10+ years	
	Walls - Concrete Block	Girls Restroom 187	202	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls Restroom 187	269	SF	7	10+ years	
	Water Closet	Girls Restroom 187	2	EA	7	10+ years	
	Water Closet	Girls Restroom 187	2	EA	4	1-2 years	Out of order
	Accessories	Girls Room next to 138	101	SF	7	6-10 years	
	Ceiling - Splined	Girls Room next to 138	101	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls Room next to 138	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Room next to 138	101	SF	6	10+ years	
	Floor Drain	Girls Room next to 138	1	EA	7	10+ years	
	Lavatory	Girls Room next to 138	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls Room next to 138	2	EA	6	6-10 years	
	Partitions	Girls Room next to 138	2	EA	7	6-10 years	
	Walls - Concrete Block	Girls Room next to 138	102	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls Room next to 138	139	SF	7	10+ years	
	Water Closet	Girls Room next to 138	2	EA	7	10+ years	
	Accessories	In Office for Gym 140	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Office for Gym 140	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Office for Gym 140	1	EA	6	10+ years	
	Floor - Terrazzo	In Office for Gym 140	7	SF	6	10+ years	
	Floor - Tile	In Office for Gym 140	29	SF	6	10+ years	
	Floor Drain	In Office for Gym 140	1	EA	7	10+ years	
	Lavatory	In Office for Gym 140	1	EA	6	10+ years	
	Lighting - Lay-in	In Office for Gym 140	1	EA	7	10+ years	
	Showers	In Office for Gym 140	1	EA	7	6-10 years	
	Walls - Concrete Block	In Office for Gym 140	72	SF	7	10+ years	
	Water Closet	In Office for Gym 140	1	EA	7	6-10 years	Mold
	Accessories	In Principal's Office	65	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Splined	In Principal's Office	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Principal's Office	1	EA	7	10+ years	
	Floor - Tile/Sheet	In Principal's Office	65	SF	7	10+ years	
	Lavatory	In Principal's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Principal's Office	1	EA	7	10+ years	Very dim
	Walls - Concrete Block	In Principal's Office	110	SF	7	10+ years	
	Water Closet	In Principal's Office	1	EA	7	10+ years	
	Accessories	Kitchen	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kitchen	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen	1	EA	7	10+ years	
	Floor - Tile Quarry	Kitchen	54	SF	6	10+ years	
	Floor Drain	Kitchen	1	EA	7	10+ years	
	Lavatory	Kitchen	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Kitchen	1	EA	6	6-10 years	
	Partitions	Kitchen	1	EA	7	10+ years	
	Student Lockers - One Tier	Kitchen	2	EA	6	10+ years	Updated quantity, one missing lock
	Walls - Concrete Block	Kitchen	108	SF	7	10+ years	
	Water Closet	Kitchen	1	EA	7	10+ years	
	Accessories	Restroom in janitor closet next to 114	30	SF	7	6-10 years	
	Ceiling - Lay-in	Restroom in janitor closet next to 114	30	SF	7	6-10 years	Deficiency fixed
	Doors - Wood Doors inclu hw	Restroom in janitor closet next to 114	1	EA	6	10+ years	
	Floor - Tile	Restroom in janitor closet next to 114	30	SF	6	10+ years	
	Floor Drain	Restroom in janitor closet next to 114	1	EA	7	10+ years	
	Lavatory	Restroom in janitor closet next to 114	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Restroom in janitor closet next to 114	1	EA	6	2-5 years	
	Partitions	Restroom in janitor closet next to 114	1	EA	5	10+ years	
	Walls - Concrete Block	Restroom in janitor closet next to 114	190	SF	6	10+ years	
	Water Closet	Restroom in janitor closet next to 114	1	EA	6	10+ years	
	Accessories	Unisex Toilet inside 121A-9	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex Toilet inside 121A-9	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex Toilet inside 121A-9	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Toilet inside 121A-9	65	SF	6	10+ years	
	Floor Drain	Unisex Toilet inside 121A-9	1	EA	7	10+ years	
	Hand Dryer	Unisex Toilet inside 121A-9	1	EA	7	6-10 years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	Unisex Toilet inside 121A-9	1	EA	6	10+ years	
	Lighting - Wall Mounted	Unisex Toilet inside 121A-9	1	EA	6	6-10 years	
	Walls - Concrete Block	Unisex Toilet inside 121A-9	120	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex Toilet inside 121A-9	26	SF	6	10+ years	
	Water Closet	Unisex Toilet inside 121A-9	1	EA	6	10+ years	
	Accessories	Unisex inside 146G	37	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex inside 146G	37	SF	6	10+ years	
	Doors - Steel Doors incl hw	Unisex inside 146G	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex inside 146G	37	SF	6	10+ years	
	Lavatory	Unisex inside 146G	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Unisex inside 146G	1	EA	6	6-10 years	
	Walls - Concrete Block	Unisex inside 146G	95	SF	7	10+ years	
	Water Closet	Unisex inside 146G	1	EA	7	10+ years	
	Accessories	Unisex inside 146J	36	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex inside 146J	36	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	Unisex inside 146J	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex inside 146J	36	SF	6	10+ years	
	Lavatory	Unisex inside 146J	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Unisex inside 146J	1	EA	7	10+ years	
	Walls - Concrete Block	Unisex inside 146J	32	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex inside 146J	26	SF	6	10+ years	
	Water Closet	Unisex inside 146J	1	EA	6	10+ years	
	Accessories	Wood Shop	25	SF	7	6-10 years	
	Ceiling - Splined	Wood Shop	13	SF	6	10+ years	
	Ceiling - Splined	Wood Shop	12	SF	4	0-1 year	Missing
	Doors - Wood Doors inclu hw	Wood Shop	1	EA	7	10+ years	
	Floor - Tile	Wood Shop	25	SF	6	10+ years	
	Lavatory	Wood Shop	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Wood Shop	2	EA	7	6-10 years	
	Showers	Wood Shop	1	EA	5	1-2 years	Not in use
	Walls - Concrete Block	Wood Shop	110	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Wood Shop	80	SF	6	10+ years	
	Water Closet	Wood Shop	1	EA	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #100 (Art Room)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	150	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,024	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,024	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	6	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Concrete Block	1st Floor	1,250	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroom #102 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,024	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,024	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,250	SF	7	10+ years	
Classroom #103 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Splined	1st Floor	926	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	911	SF	6	10+ years	
	Floor - Tile	1st Floor	15	SF	4	1-2 years	Chipping and cracked
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,050	SF	7	10+ years	
Classroom #104A (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	913	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	913	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,249	SF	7	10+ years	
Classroom #104B (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	443	SF	6	10+ years	
	Doors - Side-lite	1st Floor	150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	1st Floor	443	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	724	SF	6	10+ years	
Classroom #105 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Splined	1st Floor	917	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	917	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,028	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #105B (Special Education)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Splined	1st Floor	450	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	438	SF	6	10+ years	
	Floor - Tile	1st Floor	12	SF	4	1-2 years	Cracking and chipping tiles, quantity updated to match current observations
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	852	SF	7	10+ years	
Classroom #106 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Splined	1st Floor	926	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	918	SF	6	10+ years	
	Floor - Tile	1st Floor	8	SF	4	0-1 year	Chipped/cracked tiles
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,050	SF	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #107 (Computer Lab)</u>							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,368	SF	6	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,368	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	EA	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,260	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	40	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
<u>Classroom #108 (Regular Classroom)</u>							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	45	LF	4	1-2 years	Damaged casework
	Ceiling - Splined	1st Floor	926	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	926	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	19	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,050	SF	7	10+ years	
<u>Classroom #110 (Pre School)</u>							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Splined	1st Floor	926	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	926	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,050	SF	7	10+ years	
<u>Classroom #112 (Regular Classroom)</u>							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Splined	1st Floor	926	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	926	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,050	SF	7	10+ years	
Classroom #113 (Art Room)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	134	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,535	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,535	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	31	EA	6	6-10 years	
	Marker Board	1st Floor	14	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	800	SF	7	10+ years	
	Work Sink	1st Floor	3	EA	7	6-10 years	
Classroom #114 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	45	LF	6	10+ years	
	Ceiling - Splined	1st Floor	926	SF	6	10+ years	
	Chalk Board	1st Floor	54	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	926	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,050	SF	7	10+ years	
Classroom #115 (Art Room)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	134	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,535	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,535	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	31	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	800	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	6-10 years	
Classroom #116 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Splined	1st Floor	928	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	928	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,068	SF	7	10+ years	
Classroom #117 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,216	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,216	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	25	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,129	SF	7	10+ years	
	Walls - Masonry	1st Floor	150	SF	6	10+ years	
Classroom #118 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Splined	1st Floor	928	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	928	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,068	SF	7	10+ years	
Classroom #119 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Splined	1st Floor	915	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	915	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	5	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Concrete Block	1st Floor	1,076	SF	7	10+ years	
Classroom #120 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Splined	1st Floor	928	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	928	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,068	SF	7	10+ years	
Classroom #121 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Splined	1st Floor	915	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	915	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,076	SF	7	10+ years	
Classroom #122 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Splined	1st Floor	928	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	928	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,068	SF	7	10+ years	
Classroom #123 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	807	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,000	SF	7	10+ years	

Classroom #124 (Science Lab Level 2)

	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	100	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,277	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Transom Window	1st Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,277	SF	6	10+ years	
	Gas Line	1st Floor	8	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Science Lab Elements	1st Floor	1,277	SF	7	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,188	SF	7	10+ years	
	Work Sink	1st Floor	4	EA	7	6-10 years	Quantity updated to match current observations

Classroom #125 (Regular Classroom)

	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	807	SF	6	10+ years	
	Chalk Board	1st Floor	26	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,000	SF	6	10+ years	

Classroom #126 (Science Lab Level 3)

	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	100	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,277	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	1st Floor	14	SF	6	10+ years	
	Doors - Transom Window	1st Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,277	SF	6	10+ years	
	Gas Line	1st Floor	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Science Lab Elements	1st Floor	1,277	SF	7	10+ years	Not previously assessed
	Science Lab Shower	1st Floor	1	EA	7	10+ years	Not previously assessed
	Walls - Concrete Block	1st Floor	1,188	SF	6	10+ years	
	Work Sink	1st Floor	4	EA	7	10+ years	
Classroom #127 (Science Lab Level 1)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	98	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,628	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	1,628	SF	6	10+ years	
	Gas Line	1st Floor	9	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	40	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Science Lab Fume Hood	1st Floor	1	EA	6	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,382	SF	7	10+ years	
	Work Sink	1st Floor	5	EA	7	10+ years	Quantity updated to match current observations
Classroom #128 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,940	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,940	SF	7	10+ years	Type changed to match current observations
	Lighting - Lay-in	1st Floor	34	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	3,700	SF	7	10+ years	
Classroom #129 (Science Lab Level 1)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	98	LF	7	10+ years	
	Ceiling - Splined	1st Floor	1,628	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Eye Wash Station	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	1,628	SF	6	10+ years	
	Gas Line	1st Floor	8	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	40	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Science Lab Fume Hood	1st Floor	1	EA	7	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,382	SF	6	10+ years	
	Work Sink	1st Floor	5	EA	7	10+ years	Quantity updated to match current observations

Classroom #130 (Science Lab Level 3)

AC Units	1st Floor	1	EA	7	6-10 years
Ceiling - Splined	1st Floor	1,628	SF	6	10+ years
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years
Floor - Tile	1st Floor	1,628	SF	6	10+ years
Lighting - Pendent/Surface	1st Floor	40	EA	7	6-10 years
Marker Board	1st Floor	16	LF	7	6-10 years
Walls - Concrete Block	1st Floor	837	SF	7	10+ years
Walls - Plaster/Drywall	1st Floor	545	SF	6	10+ years
Work Sink	1st Floor	5	EA	7	10+ years

Classroom #131 (Regular Classroom)

AC Units	1st Floor	1	EA	7	6-10 years
Casework	1st Floor	20	LF	6	10+ years
Ceiling - Splined	1st Floor	928	SF	6	10+ years
Chalk Board	1st Floor	6	LF	4	2-5 years
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years
Floor - Tile	1st Floor	928	SF	6	10+ years
Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years
Marker Board	1st Floor	20	LF	7	6-10 years
Storage/ Closet	1st Floor	16	SF	7	10+ years
Walls - Concrete Block	1st Floor	1,068	SF	7	10+ years
Work Sink	1st Floor	1	EA	7	10+ years

Classroom #133 (Science Lab Level 3)

AC Units	1st Floor	1	EA	7	6-10 years
Casework	1st Floor	25	LF	7	10+ years
Ceiling - Splined	1st Floor	1,231	SF	6	10+ years
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years
Floor - Tile	1st Floor	1,231	SF	6	10+ years
Lighting - Pendent/Surface	1st Floor	26	EA	6	6-10 years

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,321	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	Updated quantity
Classroom #134A (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	557	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	557	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	508	SF	6	10+ years	
Classroom #135 (Science Lab Level 1)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	100	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,499	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,499	SF	6	10+ years	
	Gas Line	1st Floor	16	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Science Lab Elements	1st Floor	1,499	SF	7	6-10 years	
	Science Lab Fume Hood	1st Floor	1	EA	6	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	599	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,067	SF	6	10+ years	
	Work Sink	1st Floor	11	EA	7	6-10 years	
	Work Sink	1st Floor	1	EA	5	1-2 years	Dripping
Classroom #136 (Band Room)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,946	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	1,946	SF	4	1-2 years	Worn and stained throughout
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Sound Panels	1st Floor	682	EA	7	10+ years	
	Storage/ Closet	1st Floor	443	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,090	SF	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #138 (Band Room)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	1,409	SF	6	10+ years	
	Ceiling - Splined	1st Floor	5	SF	5	1-2 years	Water damage
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	544	SF	6	10+ years	
	Floor - Wood	1st Floor	870	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	42	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Risers	1st Floor	90	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	1,826	SF	7	10+ years	
Classroom #139 (Dance Room)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Splined	1st Floor	917	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	917	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Wall Mirrors	1st Floor	48	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,028	SF	7	10+ years	
Classroom #141 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Splined	1st Floor	917	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	917	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,028	SF	7	10+ years	
Classroom #200 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	1-2 years	Damage around window
	Floor - Tile	2nd Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	740	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	10	SF	4	0-1 year	Metal panel over heating and cooling unit loose
	Walls - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
Classroom #201 (Computer Lab)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	1,259	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,259	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	30	EA	6	6-10 years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	983	SF	6	10+ years	
Classroom #202 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	972	SF	7	10+ years	
Classroom #203 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	972	SF	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #204 (Computer Lab)</u>							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,216	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,206	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Cracking and chipping tiles
	Lighting - Pendent/Surface	2nd Floor	30	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,179	SF	7	10+ years	
<u>Classroom #205 (Regular Classroom)</u>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	972	SF	7	10+ years	
<u>Classroom #206 (Regular Classroom)</u>							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	68	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,216	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,216	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	30	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,179	SF	7	10+ years	
<u>Classroom #207 (Regular Classroom)</u>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	Some damage to veneer
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	972	SF	7	10+ years	
Classroom #208 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	821	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	821	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	992	SF	6	10+ years	
Classroom #209 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	972	SF	7	10+ years	
Classroom #210 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	Loose and fallen tiles
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	801	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	20	SF	5	0-1 year	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	821	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Storage/ Closet	2nd Floor	115	SF	5	6-10 years	Updated quantity, water damage and damaged floor tiling
	Walls - Concrete Block	2nd Floor	992	SF	7	10+ years	
Classroom #211 (Regular Classroom)							

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	Relamp
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	972	SF	7	10+ years	
Classroom #213 (Special Education)							
	AC Units	2nd Floor	1	EA	7	6-10 years	Broken tile
	Ceiling - Splined	2nd Floor	530	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	529	SF	6	10+ years	
	Floor - Tile	2nd Floor	1	SF	5	1-2 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	993	SF	7	10+ years	
Classroom #214 (Faculty Lounge)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	539	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	539	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	765	SF	7	10+ years	
	Walls - Masonry	2nd Floor	275	SF	6	10+ years	
Classroom #216 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	812	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	812	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	Relamp, bulb strobing
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	962	SF	6	10+ years	
Classroom #217 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	797	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Missing tiles
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	972	SF	7	10+ years	
Classroom #218 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	812	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	812	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	962	SF	7	10+ years	
Classroom #219 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	807	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	972	SF	6	10+ years	

Classroom #220 (Regular Classroom)

	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	812	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	812	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	962	SF	7	10+ years	

Classroom #222 (Regular Classroom)

	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	812	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	812	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	962	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	8	SF	4	0-1 year	Loose metal paneling around heating and cooling unit

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	5,150	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,090	SF	6	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Splined	1st Floor	21,715	SF	6	10+ years	
	Doors - Side-lite	1st Floor	240	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	10+ years	
	Doors - Transom Window	1st Floor	85	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	6	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	11	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	5	6-10 years	
	Floor - Carpet	1st Floor	650	SF	6	6-10 years	
	Floor - Terrazzo	1st Floor	25,840	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,500	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	25	SF	4	1-2 years	Cracked and chipping tiles
	Lighting - Lay-in	1st Floor	86	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	8	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	470	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Student Lockers - One Tier	1st Floor	986	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	330	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	11,155	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	5	SF	5	10+ years	
	Walls - Masonry	1st Floor	20,000	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,100	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	280	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	96	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	4,600	SF	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,696	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	100	EA	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	363	EA	6	10+ years	
	Walls - Masonry	2nd Floor	3,027	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3,027	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Metal Detector	Entire Building	5	EA	7	6-10 years	
	Security Cameras	Entire Building	7	EA	7	6-10 years	
	Security Cameras	Entire Building	48	EA	7	6-10 years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	
Stairs							
	Ceiling - Exposed	Basement	80	SF	6	10+ years	
	Handrails	Basement	60	LF	7	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	
	Stairs - Concrete	Basement	30	LF	6	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Concrete Block	Basement	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Pool Stair East	126	SF	6	6-10 years	
	Handrails	Pool Stair East	52	LF	7	10+ years	
	Lighting - Wall Mounted	Pool Stair East	1	EA	7	6-10 years	
	Stairs - Concrete	Pool Stair East	126	LF	6	10+ years	
	Walls - Concrete Block	Pool Stair East	252	SF	6	10+ years	
	Ceiling - Lay-in	Pool Stair West	126	SF	6	10+ years	
	Handrails	Pool Stair West	52	LF	7	10+ years	
	Lighting - Wall Mounted	Pool Stair West	1	EA	6	6-10 years	
	Stairs - Concrete	Pool Stair West	126	LF	6	10+ years	
	Walls - Concrete Block	Pool Stair West	252	SF	6	10+ years	
	Ceiling - Splined	Stair # 1	200	SF	6	10+ years	
	Floor - Terrazzo	Stair # 1	280	SF	6	10+ years	
	Handrails	Stair # 1	44	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair # 1	2	EA	6	6-10 years	
	Stairs - Terrazzo	Stair # 1	22	LF	6	10+ years	
	Walls - Masonry	Stair # 1	508	SF	6	10+ years	
	Ceiling - Splined	Stair # 2	605	SF	6	10+ years	
	Floor - Terrazzo	Stair # 2	280	SF	6	10+ years	
	Handrails	Stair # 2	44	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair # 2	2	EA	6	6-10 years	
	Stairs - Terrazzo	Stair # 2	22	LF	6	10+ years	
	Walls - Masonry	Stair # 2	650	SF	6	10+ years	
	Ceiling - Splined	Stair # 3	605	SF	6	10+ years	
	Floor - Terrazzo	Stair # 3	280	SF	6	10+ years	
	Handrails	Stair # 3	44	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair # 3	2	EA	7	6-10 years	
	Stairs - Terrazzo	Stair # 3	22	LF	6	10+ years	
	Walls - Masonry	Stair # 3	650	SF	6	10+ years	
	Ceiling - Splined	Stair # 4	161	SF	6	10+ years	
	Floor - Terrazzo	Stair # 4	228	SF	6	10+ years	
	Handrails	Stair # 4	46	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair # 4	2	EA	6	6-10 years	
	Stairs - Terrazzo	Stair # 4	23	LF	6	10+ years	
	Walls - Masonry	Stair # 4	637	SF	6	10+ years	

Vertical Conveyance

Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years
-------------------------------	-----------	---	----	---	-----------

Category : Exterior
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Entrance</u>							
	Entrance Control - Audio	Entrance 4-N,S	1	EA	4	2-5 years	Old
	Exterior Doors - Exterior Steel Door	Entrance 4-N,S	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 4-N,S	2	EA	6	6-10 years	Repaired
	Exterior Stairs - Concrete	Entrance 4-N,S	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 4-N,S	25	LF	6	10+ years	
<u>Foundation</u>							
	Foundation - Masonry	Entire Building	267	LF	6	6-10 years	
	Foundation - Masonry	Entire Building	5	LF	5	1-2 years	Open joints
	Superstructure - Steel	Entire Building	4,750	SF	7	10+ years	
<u>Lighting</u>							
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	6-10 years	
<u>Roof System</u>							
	Coping - Metal	Roof 8	272	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Roof 8	185	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	Roof 8	4,750	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 8	4,750	SF	7	10+ years	
<u>Walls</u>							
	Exterior Walls - Hardie Board	Entire Building	1,200	SF	7	10+ years	New
	Exterior Walls - Hardie Board	Entire Building	1,060	SF	6	10+ years	
<u>Windows</u>							
	Guard - Guards wire guard	Entire Building	360	SF	7	10+ years	New or repaired
	Windows - Sash Aluminum Double-pane	Entire Building	360	SF	6	6-10 years	

Category : Electrical
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Emergency System</u>							
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	6	0-1 year	Not illuminated
	Emergency Battery Packs - Corridors and Stairs	Entire Building	12	EA	6	6-10 years	
	Security System - CCTV	Entire Building	4,750	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	4,750	SF	5	6-10 years	

Category : Electrical
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Main Service</u>							
	PA System	Entire Building	4,750	SF	5	6-10 years	
	Main Electrical Service - 800 A and Less than 120/208/3PH	Entire Building	1	EA	7	10+ years	
<u>Power Distribution</u>							
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	

Category : Fire Protection
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alarm</u>							
	Fire Alarm_System	Entire Building	4,750	SF	5	0-1 year	No strobe lights detected
<u>Sprinkler System</u>							
	Sprinkler Heads	Entire Building	4,750	SF	7	10+ years	
	Sprinkler Piping	Entire Building	4,750	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	4,750	SF	6	10+ years	

Category : Mechanical
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Temperature Control</u>							
	Electric Thermostat	Entire Building	4	EA	6	6-10 years	
<u>Unit Ventilation</u>							
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	1	EA	7	2-5 years	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	3	EA	7	2-5 years	
<u>Ventilation</u>							
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	6	EA	6	6-10 years	

Category : Plumbing
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Hot Water</u>							
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	6-10 years	

Category : Plumbing
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	4,750	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	4,750	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	4,750	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	4,750	SF	6	10+ years	
	Sanitary Piping	Entire Building	4,750	SF	6	10+ years	
	Storm Piping	Entire Building	4,750	SF	6	10+ years	

Category : Classroom
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #301 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	783	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	713	SF	6	10+ years	
	Floor - Tile	1st Floor	70	SF	4	1-2 years	Cracked and chipped
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	71	SF	5	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	823	SF	6	10+ years	
Classroom #302 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	763	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	20	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	733	SF	6	10+ years	
	Floor - Tile	1st Floor	50	SF	4	1-2 years	Chipped and damaged tiles
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	783	SF	6	10+ years	
Classroom #303 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	783	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	71	SF	5	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	823	SF	6	10+ years	

Category : Classroom
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #304 (Regular Classroom)</u>							
	Casework	1st Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	743	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	20	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	763	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Science Lab Elements	1st Floor	763	SF	7	10+ years	
	Storage/ Closet	1st Floor	166	SF	5	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	800	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	

Category : Room
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Mechanical/ Service Rooms</u>							
	Mechanical/ Service Rooms	1st Floor	52	SF	5	10+ years	
<u>Restroom</u>							
	Accessories	Across from boys room	182	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Across from boys room	167	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Across from boys room	15	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	Across from boys room	1	EA	6	10+ years	
	Floor - Tile/Sheet	Across from boys room	182	SF	5	10+ years	
	Floor Drain	Across from boys room	1	EA	7	10+ years	
	Lavatory	Across from boys room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Across from boys room	2	EA	6	6-10 years	
	Partitions	Across from boys room	4	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Across from boys room	360	SF	6	10+ years	
	Water Closet	Across from boys room	4	EA	6	10+ years	
	Accessories	Boys restroom next to room 001	138	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys restroom next to room 001	120	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Boys restroom next to room 001	18	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	Boys restroom next to room 001	1	EA	6	10+ years	
	Floor - Tile/Sheet	Boys restroom next to room 001	138	SF	7	10+ years	
	Floor Drain	Boys restroom next to room 001	1	EA	7	10+ years	
	Lavatory	Boys restroom next to room 001	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Boys restroom next to room 001	1	EA	6	6-10 years	
	Partitions	Boys restroom next to room 001	1	EA	7	10+ years	
	Urinals	Boys restroom next to room 001	3	EA	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Boys restroom next to room 001	260	SF	6	10+ years	

Category : Room
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	Boys restroom next to room 001	1	EA	6	10+ years	

Category : Interior
Building : Modular 1 (4-Classroom)

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	582	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	462	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	120	SF	4	0-1 year	Cracked and missing tiles
	Lighting - Lay-in	1st Floor	8	EA	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,085	SF	6	10+ years	

Safety

Security Cameras	Entire Building	1	EA	7	6-10 years	
Security Cameras	Entire Building	1	EA	7	6-10 years	

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Civil/Drainage</u>							
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	6	10+ years	
<u>Fencing</u>							
	Fencing - Chain Link	Entire Site	850	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	20	LF	4	0-1 year	Broken, torn
	Fencing - Guard Rail	Entire Site	40	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,014	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,026	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	853	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	24	LF	4	0-1 year	Fence and gate post damaged by impact
<u>Landscape</u>							
	Benches	Entire Site	2	EA	7	10+ years	
	Benches	Entire Site	2	EA	7	10+ years	
	Benches	Entire Site	2	EA	6	10+ years	
	Landscape - Grass	Entire Site	140,780	SF	6	10+ years	
	Landscape - Grass	Entire Site	3,000	SF	4	0-1 year	Bare soil
	Landscape - Hardscape- Asphalt	Entire Site	3,240	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	7,685	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	150	SF	5	1-2 years	Cracked, spalled, broken
	Lighting - Pole Mounted	Entire Site	9	EA	6	10+ years	
	Parkway trees	Entire Site	25	EA	6	10+ years	
	Parkway trees	Entire Site	5	EA	4	0-1 year	Missing trees
	Planting Beds/ Area	Entire Site	16,000	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	60	SF	6	10+ years	
	Retaining Wall - Masonry	Entire Site	60	SF	6	10+ years	
	Retaining Wall - Masonry	Entire Site	60	SF	6	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
<u>Parking Lot</u>							
	Concrete Curbs	SE of site	155	LF	7	10+ years	
	Surface - Asphalt	SE of site	24,565	SF	7	10+ years	
	Concrete Curbs	West	455	LF	7	10+ years	
	Lighting - Pole Mounted	West	2	EA	6	10+ years	
	Surface - Asphalt	West	500	SF	7	10+ years	
	Surface - Asphalt	West	31,075	SF	6	6-10 years	
	Trash Enclosure - Chain Links	West	5,200	SF	6	10+ years	
	Vehicular Screening	West	185	LF	6	10+ years	

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Sidewalks</u>							
	Sidewalks - Internal Walks	Entire Site	1,825	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	50	LF	4	1-2 years	Cracked, broken, spalled. Sidewalks are in good to fair condition. Consolidated some numbers.
	Sidewalks - Perimeter Sidewalks	Entire Site	12,950	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	50	SF	4	0-1 year	Cracked, broken, upheaved. Some new areas since previous assessment. Consolidated numbers.
<u>Signage</u>							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	4	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Building : Main									
Art Room	Art Room	1st Floor	100	101	1,024	370	70	N	Y
Art Room	Art Room	1st Floor	113	113	1,535	420	112	N	N
Art Room	Art Room	1st Floor	115	115	1,535	420	112	N	N
Band Room	Band Room	1st Floor	136	136	1,946	306	78	N	N
Band Room	Choral Room	1st Floor	138	138	1,414	282	72	N	N
Computer Lab	Computer Lab	1st Floor	107	107	1,368	364	96	N	Y
Computer Lab	Computer Lab	2nd Floor	201	201	1,259	532	96	N	N
Computer Lab	Computer Lab	2nd Floor	204	204	1,216	336	96	N	N
Dance Room	Regular Classroom	1st Floor	139	139	917	252	64	N	N
Faculty Lounge	Computer Lab	2nd Floor	214	214	539	12	6	N	N
Pre School	Regular Classroom	1st Floor	110	110	926	224	48	N	N
Regular Classroom	Computer Lab	2nd Floor	206	206	1,216	336	96	N	N
Regular Classroom	Culinary	1st Floor	128	128	1,940	144	36		
Regular Classroom	Regular Classroom	1st Floor	102	102	1,024	280	70	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	926	224	48	N	N
Regular Classroom	Regular Classroom	1st Floor	104A	104	913	16	30	N	N
Regular Classroom	Regular Classroom	1st Floor	104B	104	443	8	15	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	917	252	64	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	926	224	48	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	926	224	48	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	926	224	48	N	N
Regular Classroom	Regular Classroom	1st Floor	114	114	926	224	48	N	N
Regular Classroom	Regular Classroom	1st Floor	116	116	928	232	64	N	N
Regular Classroom	Regular Classroom	1st Floor	117	117	1,216	336	96	N	N
Regular Classroom	Regular Classroom	1st Floor	118	118	928	232	64	N	N
Regular Classroom	Regular Classroom	1st Floor	119	119	915	224	128	N	N
Regular Classroom	Regular Classroom	1st Floor	120	120	928	232	64	N	N
Regular Classroom	Regular Classroom	1st Floor	121	121	915	224	128	N	N
Regular Classroom	Regular Classroom	1st Floor	122	122	928	232	64	N	N
Regular Classroom	Regular Classroom	1st Floor	123	123	807	200	72	N	N
Regular Classroom	Regular Classroom	1st Floor	125	125	807	200	72	N	N
Regular Classroom	Regular Classroom	1st Floor	131	131	928	232	64	N	N
Regular Classroom	Regular Classroom	1st Floor	134A	134A	557	164	9	N	Y
Regular Classroom	Regular Classroom	1st Floor	141	141	917	252	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	807	200	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	807	200	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	807	200	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	807	200	72	N	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Regular Classroom	Regular Classroom	2nd Floor	207	207	807	200	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	821	200	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	807	200	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	821	200	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	807	200	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	812	200	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	807	200	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	812	200	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	807	200	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	220	812	224	64	N	N
Regular Classroom	Regular Classroom	2nd Floor	222	222	812	224	64	N	N
Science Lab Level 1	Science Lab Level 1	1st Floor	127	127	1,628	448	256	N	N
Science Lab Level 1	Science Lab Level 1	1st Floor	129	129	1,628	448	256	N	N
Science Lab Level 1	Science Lab Level 1	1st Floor	135	135	1,499	200	18	N	N
Science Lab Level 2	Science Lab Level 2	1st Floor	124	124	1,277	336	96	N	N
Science Lab Level 3	Science Lab Level 3	1st Floor	126	126	1,277	336	96	N	N
Science Lab Level 3	Science Lab Level 3	1st Floor	130	130	1,628	448	256	N	N
Science Lab Level 3	Science Lab Level 3	1st Floor	133	133	1,231	252	64	N	N
Special Education	Special Education	1st Floor	105B	105	450	120	32	N	N
Special Education	Special Education	2nd Floor	213	213	530	12	6	N	N

Building : Modular 1 (4-Classroom)

Regular Classroom	Regular Classroom	1st Floor	301	1	783	60	24	N	N
Regular Classroom	Regular Classroom	1st Floor	302	2	783	60	24	N	N
Regular Classroom	Regular Classroom	1st Floor	303	3	783	60	24	N	N
Regular Classroom	Science Lab Level 1	1st Floor	304	NA	763	60	24	N	N