

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1969	3	38,482
Linked Addition	1976	1	7,998
Campus Total			46,480

Catego	ry : Exterior	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	1	2	EA	6	10+ years	
	Exterior Stairs - Concrete	1	24	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	11	1	EA	6	10+ years	
	Exterior Stairs - Concrete	11	6	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	11	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	12-Roof Access Door	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	1	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	2	40	LF	7	10+ years	
	Ramps - Concrete	2	25	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	2.5	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	3	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	4	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	4.5	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	5	1	EA	6	10+ years	
	Exterior Doors - Side lite	5	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	6	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	7	1	EA	6	10+ years	
	Exterior Doors - Side lite	7	1	EA	6	10+ years	
oundati	on						
	Foundation - Concrete	Entire Building	721	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	82	SF	7	10+ years	



NIA :			_				409 W 80th STREET, Chicago, IL 60620
Catego	ry : Exterior		В	uilding			
_			<b>•</b>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Superstructure - Concrete	Entire Building	38,400	SF	7	10+ years	
Lighting							
	Exterior Lighting - Lighting	Entire Building	5	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	10+ years	
Roof Sys	stem						
-	Access Ladder - Metal	Roof A	1	EA	7	10+ years	
	Coping - Metal	Roof A	516	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof A	72	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof A	8,220	SF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	Roof A	6,040	SF	4	0-1 year	Large amount of blistering, soft spot
	Roof Structure - Concrete	Roof A	14,260	SF	7	10+ years	Verified dimension.
	Access Ladder - Metal	Roof B	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof B	30	LF	7	10+ years	
	Coping - Metal	Roof B	310	LF	6	10+ years	Verified dimension.
	Downspouts - Interior Downspouts	Roof B	48	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof B	4,751	SF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	Roof B	2,664	SF	4	0-1 year	Large amount of blistering, old roof
	Roof Structure - Concrete	Roof B	7,415	SF	7	10+ years	Verified dimension.
	Coping - Metal	Roof E	40	LF	6	10+ years	Verified dimension.
	Downspouts - Interior Downspouts	Roof E	12	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof E	650	SF	4	1-2 years	Blistered throughout, much
	·						vegetation growth. Verified
							dimension.
	Roof Structure - Concrete	Roof E	650	SF	7	10+ years	Verified dimension.
						,	
Valls							
	Exterior Walls - Brick	Entire Building	17,004	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,000	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	126	SF	4	0-1 year	Cracked, displaced brick, open join
							Consolidated numbers.
Vindows	3						
	Guard - Guards perforated	Entire Building	627	SF	6	10+ years	
	Lintels - Steel	Entire Building	855	LF	6	10+ years	
	Windows - Casement Aluminum	Entire Building	1,048	SF	6	10+ years	
	Windows - Decorative	Entire Building	2,484	SF	6	10+ years	
	Windows - Louver	Entire Building	429	SF	6	10+ years	



Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Security System - CCTV	Entire Building	38,482	SF	4	2-5 years	Exterior only, dated cameras
	Security System - Intrusion Detection	Entire Building	38,482	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	9	EA	4	1-2 years	Dated signs fading, using incandescent bulbs
	Exit Signs - Gym	Entire Building	5	EA	4	1-2 years	Dated signs fading, using incandescent bulbs
	Exit Signs - Lunchroom	Entire Building	2	EA	4	2-5 years	Dated signs using incandescent bulb
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,006	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,665	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,665	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,287	SF	6	6-10 years	
	Emergency Battery Packs - Gym	Gym	2	EA	6	6-10 years	
	Automatic Transfer Switch	Lunchroom Office	1	EA	6	6-10 years	
	Emergency Generator- Outdoor- Diesel - Below 60 KW	Site South	1	EA	2	0-1 year	Not working per engineer
Main Ser	vice						
	Main Electrical Service - Greater than 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	46,480	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Old fuse type, missing fuses
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	38,482	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	38,482	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



X Schools						409 W 80th STREET, Chicago, IL 60620
					Replacement	
Air Conditioning						
Condensing Unit- Roof Mounted - 11-20 tons	Lower Roof	1	EA	5	6-10 years	CU 1, Serves gym, serves AHU-1 in main building.
Condensing Unit- Roof Mounted - 11-20 tons	Lower Roof	1	EA	5	6-10 years	CU 2, Serves cafeteria, serves AHU 2 in main building.
Air Handling Systems						
Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 4000- 8000 cfm	Mechanical Room - AHU1	1	EA	6	6-10 years	AHU-1
Air Intake	Mechanical Room - AHU1	1	EA	6	6-10 years	
Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 8001- 12000 cfm	Mechanical Room - AHU2	1	EA	6	6-10 years	AHU2, Serves cafeteria and kitchen area.
Air Intake	Mechanical Room - AHU2	1	EA	6	6-10 years	
Heating Devices						
Wall Heater - Electric	Entire Building	23	EA	6	6-10 years	
Wall Heater - Electric	Entire Building	5	EA	4	0-1 year	Dated and deteriorated
PTAC - Electric Heating and Self Contained Cooling	Entire Building	6	EA	6	6-10 years	
PTAC - Electric Heating and Self Contained Cooling	Entire Building	2	EA	6	2-5 years	
Duct Heater - Electric	Mechanical Room	3		6	6-10 years	
Temperature Control						
DDC System	Entire Building	1,868	SF	5	2-5 years	Controls AHUs only
Electric Controls	Entire Building	36,614	SF	5	6-10 years	,
Electric Thermostat	Entire Building	2	ĒA	5	6-10 years	
Thermostats - DDC	Entire Building	10	EA	4	0-1 year	Not operational
Unit Ventilation						
Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	27	EA	5	6-10 years	
Ventilation						
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EA	6	6-10 years	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	
Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	2	EA	6	6-10 years	
Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression over high temp



						Replacement	
							cookware
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	5				· · <b>)</b> · · · ·	
Catego	ry : Plumbing		В	uilding	• Main		
Jaiogo	, y . i . ianibing			anang	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	21	Location	Quantity		Nank	Replacement	Comments
Hot Wat							
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	7	10+ years	
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	4	2-5 years	2004 installation, old, not reliable
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	38,482	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	38,482	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	38,482	SF	6	6-10 years	
	Fixtures	Entire Building	00,402	0	0	o io years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	38,482	SF	6	6-10 years	
	(Horizontal Lines)		30,40Z	ЭГ	U	0-10 years	
		Entiro Building	20 /02	SF	6	6 10 vooro	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	38,482	эг	Ö	6-10 years	
	(Risers)	Fusting Duilding	00,400	05	~	0.40	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	38,482	SF	6	6-10 years	
	(from Risers to Fixtures)			0-	_	4.0	
	Sanitary Piping	Entire Building	38,482	SF	5	10+ years	
	Storm Piping	Entire Building	38,482	SF	5	10+ years	
	Vent Piping	Entire Building	38,482	SF	5	10+ years	
Pumps							
umps	Pumps - Domestic Booster Pump-Simplex	1st Floor	1	EA	2	0-1 year	Pump broken per engineer, not
							operational
Catego	ry : Room		В	uilding	: Main		
	· , · · · · · ·					Recommend	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	trative Suites/Offices					Replacement	Comments
	trative Suites/Offices Ceiling - Lay-in	200 - Counselor Office	232	SF	6	Replacement 10+ years	Comments
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw	200 - Counselor Office 200 - Counselor Office	232 1	SF EA	6 6	Replacement 10+ years 10+ years	Comments
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile	200 - Counselor Office 200 - Counselor Office 200 - Counselor Office	232 1 232	SF EA SF	6 6 6	Replacement 10+ years 10+ years 10+ years	Comments
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	200 - Counselor Office 200 - Counselor Office 200 - Counselor Office 200 - Counselor Office	232 1 232 2	SF EA SF EA	6 6 6	Replacement 10+ years 10+ years 10+ years 6-10 years	Comments
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution	200 - Counselor Office 200 - Counselor Office 200 - Counselor Office 200 - Counselor Office 200 - Counselor Office	232 1 232 2 4	SF EA SF EA EA	6 6 6 6	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block	200 - Counselor Office 200 - Counselor Office	232 1 232 2 4 493	SF EA SF EA EA SF	6 6 6 6 6	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	Comments
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block Walls - Structural Glazed Tile	200 - Counselor Office 200 - Counselor Office 200 - Counselor Office 200 - Counselor Office 200 - Counselor Office	232 1 232 2 4	SF EA SF EA EA SF SF	6 6 6 6 6 7	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Lay-in	200 - Counselor Office 200 - Counselor Office	232 1 232 2 4 493	SF EA SF EA EA SF	6 6 6 6 6	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block Walls - Structural Glazed Tile	200 - Counselor Office 200 - Counselor Office	232 1 232 2 4 493 45	SF EA SF EA EA SF SF	6 6 6 6 6 7	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	Comments No access per engineer. No key
	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Lay-in	200 - Counselor Office 200 - Counselor Office 300 Office APR Coordinator	232 1 232 2 4 493 45 232	SF EA SF EA SF SF SF	6 6 6 6 6 7 6	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
Group Administ	trative Suites/Offices Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Lay-in	200 - Counselor Office 200 - Counselor Office 300 Office APR Coordinator	232 1 232 2 4 493 45 232	SF EA SF EA SF SF SF	6 6 6 6 6 7 6	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	No access per engineer. No key



							409 W 80th STREET, Chicago, IL 60620
Catego	ry : Room		В	uilding	: Main	_	
•			0			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	300 Office APR Coordinator	4	EA	6	10+ years	
	Walls - Concrete Block	300 Office APR Coordinator	493	SF	6	10+ years	
	Walls - Structural Glazed Tile	300 Office APR Coordinator	45	SF	7	10+ years	
	Ceiling - Lay-in	Assistant Principal Office	235	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal Office	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal Office	1	EA	6	10+ years	
	Floor - Carpet	Assistant Principal Office	235	SF	6	6-10 years	
	Lighting - Lay-in	Assistant Principal Office	3	EA	6	6-10 years	
	Power Distribution	Assistant Principal Office	4	EA	6	10+ years	
	Storage/ Closet	Assistant Principal Office	12	SF	7	10+ years	
	Walls - Concrete Block	Assistant Principal Office	493	SF	6	10+ years	
	Ceiling - Lay-in	Engineer's Office	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	65	SF	6	10+ years	
	Lighting - Lay-in	Engineer's Office	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office	4	EA	7	10+ years	
	Walls - Concrete Block	Engineer's Office	130	SF	7	10+ years	
	Ceiling - Lay-in	Faculty Room - 1st Floor	253	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty Room - 1st Floor	3	EA	6	10+ years	
	Floor - Tile	Faculty Room - 1st Floor	253	SF	6	10+ years	
	Lighting - Lay-in	Faculty Room - 1st Floor	4	EA	7	6-10 years	
	Power Distribution	Faculty Room - 1st Floor	6	EA	7	10+ years	
	Storage/ Closet	Faculty Room - 1st Floor	85	SF	7	10+ years	
	Walls - Concrete Block	Faculty Room - 1st Floor	430	SF	7	10+ years	
	Walls - Structural Glazed Tile	Faculty Room - 1st Floor	50	SF	7	10+ years	
	Ceiling - Lay-in	Gym Office	97	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	6	10+ years	
	Floor - Tile	Gym Office	97	SF	7	10+ years	
		Gym Office	97	EA	7		
	Lighting - Lay-in	Gym Office		EA		6-10 years	
	Power Distribution		4	SF	7	10+ years	
	Storage/ Closet	Gym Office	32		7	10+ years	
	Walls - Concrete Block	Gym Office	268	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Office	76	SF	6	10+ years	Inaccessible, engineer doesn't have key
	Doors - Side-lite	Kitchen Office	16	SF	7	10+ years	Inaccessible, engineer doesn't have key
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	7	10+ years	Inaccessible, engineer doesn't have key
	Floor - Tile	Kitchen Office	76	SF	6	10+ years	Inaccessible, engineer doesn't have key
	Lighting - Lay-in	Kitchen Office	1	EA	7	6-10 years	Inaccessible, engineer doesn't have key
	Power Distribution	Kitchen Office	4	EA	7	10+ years	Inaccessible, engineer doesn't have



atego	ry : Room		В	uilding	: Main			
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•						•	key	
	Walls - Concrete Block	Kitchen Office	160	SF	6	10+ years	Inaccessible, engineer doesn't hav	
	Ceiling - Plaster/Drywall	Library Office 2nd Floor	164	SF	6	10+ years	key	
	Doors - Wood Doors inclu hw	Library Office 2nd Floor	1	EA	6	10+ years		
	Floor - Tile	Library Office 2nd Floor	164	SF	6	10+ years		
	Lighting - Lay-in	Library Office 2nd Floor	2	ĒA	6	6-10 years		
	Power Distribution	Library Office 2nd Floor	4	EA	6	10+ years		
	Walls - Concrete Block	Library Office 2nd Floor	206	SF	6	10+ years		
	Ceiling - Lay-in	Main Office 1st Floor	507	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Main Office 1st Floor	2	EA	7	10+ years		
	Floor - Carpet	Main Office 1st Floor	507	SF	6	6-10 years		
	Lighting - Lay-in	Main Office 1st Floor	10	EA	7	6-10 years		
	Power Distribution	Main Office 1st Floor	10	EA	7	10+ years		
	Storage/ Closet	Main Office 1st Floor	126	SF	7	10+ years		
	Walls - Concrete Block	Main Office 1st Floor	822	SF	7	10+ years		
	Walls - Structural Glazed Tile	Main Office 1st Floor	125	SF	7	10+ years		
	Ceiling - Lay-in	Principal's Office	289	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Principal's Office	209	EA	7	10+ years		
	Floor - Carpet	Principal's Office	289	SF	6	6-10 years		
	Lighting - Lay-in	Principal's Office	209	EA	7			
	Power Distribution	Principal's Office	4	EA	7	6-10 years 10+ years		
	Storage/ Closet	•	4 12	SF	7			
	Walls - Concrete Block	Principal's Office	276	SF	7	10+ years		
		Principal's Office	-	SF		10+ years		
	Ceiling - Lay-in	Safe Passage Office (in Lunchroom)	193	SF	6	10+ years		
	Doors - Side-lite	Safe Passage Office (in Lunchroom)	18		7	10+ years		
	Doors - Wood Doors inclu hw	Safe Passage Office (in Lunchroom)	1	EA	7	10+ years		
	Floor - Tile	Safe Passage Office (in Lunchroom)	193	SF	6	10+ years		
	Lighting - Lay-in	Safe Passage Office (in Lunchroom)	2	EA	7	6-10 years		
	Power Distribution	Safe Passage Office (in Lunchroom)	6	EA	7	10+ years		
	Walls - Concrete Block	Safe Passage Office (in Lunchroom)	423	SF	7	10+ years		
mnas								
	Ceiling - Lay-in	1st Floor	4,650	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor	15	SF	4	0-1 year	Broken	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	5	EA	7	10+ years		
	Floor - Concrete	1st Floor	48	SF	7	10+ years		
	Floor - Tile	1st Floor	3,921	SF	6	10+ years		
	Floor - Wood	1st Floor	696	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	54	EA	6	6-10 years	Quantity and rank updated to mat current observations	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years		
	Sound System	1st Floor	1	EA	7	6-10 years		



-	Schools						409 W 80th STREET, Chicago, IL 60620
Catego	ry : Room		В	uilding	: Main		
0	Hanna Tama	l ti	0		Daula	Recommend	0
Group	Item - Type	Location	Quantity	UOM SF	Rank	Replacement	Comments
	Stage	1st Floor	696		7	10+ years	
	Stage Curtain	1st Floor	3	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	35	LF	7	10+ years	
	Storage/ Closet	1st Floor	84	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	6,333	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	350	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	983	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	40	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st Floor	25	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	1,023	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	ËA	7	6-10 years	
	Serving Line	1st Floor	25	LF	7	10+ years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,227	SF	7	10+ years	
Library							
,	Casework	207/209 Library	127	LF	6	10+ years	
	Ceiling - Lay-in	207/209 Library	1,799	SF	6	10+ years	
	Ceiling - Lay-in	207/209 Library	8	SF	4	1-2 years	Missing tile
	Doors - Wood Doors inclu hw	207/209 Library	3	EA	6	10+ years	Wildeling the
	Floor - Carpet	207/209 Library	1,757	SF	6	6-10 years	
	Floor - Carpet	207/209 Library	50	SF	4	1-2 years	Carpet damaged
	Lighting - Lay-in	207/209 Library	30	EA	4 6	6-10 years	Carper damaged
	Walls - Concrete Block	207/209 Library	1,306	SF	7		
	Walls - Concrete Block	207/209 Library	1,306	55	7	10+ years	
Locker/S	Shower Room						
	Accessories	1st Floor	236	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	236	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	236	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Showers	1st Floor	5	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor	52	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	472	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	Kitchen Staff	101	SF	7	6-10 years	
	70060001160		101	0	ı	0-10 years	



Catego	ry : Room		R	uilding	• Main	409 W 80th STREET, Chicago, IL 6062	
Jacyo				anang	. mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Joup	Ceiling - Plaster/Drywall	Kitchen Staff	101	SF	7	10+ years	Commonito
	Doors - Wood Doors inclu hw	Kitchen Staff	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Kitchen Staff	19	SF	7	10+ years	
	Floor - Tile/Sheet	Kitchen Staff	82	SF	7	10+ years	
	Lavatory	Kitchen Staff	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Kitchen Staff	2	EA	7	6-10 years	
	Student Lockers - One Tier	Kitchen Staff	12	EA	6	6-10 years	
	Walls - Concrete Block	Kitchen Staff	202	SF	7	•	
			202	EA	7	10+ years	
	Water Closet	Kitchen Staff	1	EA	1	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,665	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile	1st Floor	1,665	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,126	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	205	SF	7	10+ years	
IDF_ID	r.						
יחר_וח	Doors - Wood Doors inclu hw	2nd in library	1	EA	6	10+ years	
	Finishes	2nd in library 2nd in library	210	SF	7	10+ years	
	Other Cooling Unit	2nd in library 2nd in library	210	EA	7	6-10 years	PTAC
		Zhu in library	I	LA	'	0-10 years	TIAC
lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Janitor's Closet	1st Floor	35	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	150	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	45	SF	7	10+ years	
	Storage Room	1st Floor	85	SF	7	10+ years	
	Storage Room	1st Floor	85	SF	5	10+ years	
	Janitor's Closet	2nd Floor	35	SF	5	10+ years	Ceiling water damaged
	Mechanical/ Service Rooms	2nd Floor	1,868	SF	7	10+ years	3
	Storage Room	2nd Floor	97	SF	7	10+ years	
	Janitor's Closet	3rd Floor	35	SF	7	10+ years	
estrooi	n						
Control	Accessories	104A	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	104A	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	104A	20	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	104A	26	SF	7		
						10+ years	
	Lavatory	104A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	104A	1	EA	7	6-10 years	
	Walls - Concrete Block	104A	53	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main					
-			•			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Water Closet	104A	1	EA	7	10+ years				
	Accessories	106A	26	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	106A	26	SF	7	10+ years				
	Doors - Wood Doors inclu hw	106A	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	106A	26	SF	7	10+ years				
	Lavatory	106A	1	EA	7	10+ years				
	Lighting - Pendent/Surface	106A	1	EA	7	6-10 years				
	Walls - Concrete Block	106A	53	SF	7	10+ years				
	Water Closet	106A	1	EA	7	10+ years				
	Accessories	Boys 1st Floor	247	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Boys 1st Floor	247	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Boys 1st Floor	2	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Boys 1st Floor	247	SF	7	10+ years				
	Floor Drain	Boys 1st Floor	1	EA	7	10+ years				
	Lavatory	Boys 1st Floor	2	EA	7	10+ years				
	Lighting - Pendent/Surface	Boys 1st Floor	4	EA	7	6-10 years				
	Partitions	Boys 1st Floor	2	EA	7	10+ years				
	Urinals	Boys 1st Floor	3	EA	7	10+ years				
	Walls - Concrete Block	Boys 1st Floor	366	SF	7	10+ years				
	Walls - Plaster/Drywall	Boys 1st Floor	200	SF	6	10+ years				
	Water Closet	Boys 1st Floor	2	EA	6	10+ years				
	Accessories	Boys 2nd Floor	247	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Boys 2nd Floor	247	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Boys 2nd Floor	4	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Boys 2nd Floor	237	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Boys 2nd Floor	10	SF	4	1-2 years	Missing tiles			
	Floor Drain	Boys 2nd Floor	1	EA	7	10+ years				
	Lavatory	Boys 2nd Floor	2	EA	6	10+ years				
	Lighting - Pendent/Surface	Boys 2nd Floor	4	EA	6	6-10 years				
	Partitions	Boys 2nd Floor	2	EA	7	10+ years				
	Urinals	Boys 2nd Floor	3	EA	6	10+ years				
	Walls - Concrete Block	Boys 2nd Floor	561	SF	7	10+ years				
	Walls - Concrete Block	Boys 2nd Floor	5	SF	5	1-2 years	Broken concrete block			
	Water Closet	Boys 2nd Floor	2	EA	6	10+ years				
	Accessories	Boys 3rd Floor	247	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Boys 3rd Floor	247	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Boys 3rd Floor	4	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Boys 3rd Floor	247	SF	6	10+ years				
	Floor Drain	Boys 3rd Floor	1	EA	7	10+ years				
	Lavatory	Boys 3rd Floor	1	EA	6	10+ years				
	Lavatory	Boys 3rd Floor	1	EA	4	0-1 year	Missing.			
	Lighting - Pendent/Surface	Boys 3rd Floor	4	EA	6	6-10 years	č			
	Partitions	Boys 3rd Floor	2	EA	7	10+ years				
	Urinals	Boys 3rd Floor	3	EA	6	10+ years				
						2				



atego	ry : Room		В	uilding	: Main		
Ŭ	•			U		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Concrete Block	Boys 3rd Floor	556	SF	7	10+ years	
	Walls - Concrete Block	Boys 3rd Floor	10	SF	5	1-2 years	Damage from previous lavatory installation
	Water Closet	Boys 3rd Floor	2	EA	6	10+ years	
	Accessories	Engineer's Office	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office	25	SF	7	10+ years	
	Doors - Hardware	Engineer's Office	1	EA	6	1-2 years	No hardware
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Engineer's Office	25	SF	7	10+ years	
	Lavatory	Engineer's Office	1	EA	7	6-10 years	Deficiency fixed
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	6-10 years	
	Walls - Concrete Block	Engineer's Office	47	SF	7	10+ years	
	Water Closet	Engineer's Office	1	EA	7	10+ years	
	Accessories	Girls 1st Floor	247	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls 1st Floor	247	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Girls 1st Floor	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls 1st Floor	247	SF	7	10+ years	
	Floor Drain	Girls 1st Floor	1	EA	7	10+ years	
	Lavatory	Girls 1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls 1st Floor	4	EA	7	6-10 years	
	Partitions	Girls 1st Floor	5	EA	7	10+ years	
	Walls - Concrete Block	Girls 1st Floor	366	SF	7	10+ years	
	Walls - Plaster/Drywall	Girls 1st Floor	200	SF	6	10+ years	
	Water Closet	Girls 1st Floor	5	EA	7	10+ years	
	Accessories	Girls 2nd Floor	247	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls 2nd Floor	247	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls 2nd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls 2nd Floor	244	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls 2nd Floor	3	SF	4	1-2 years	Missing tiles
	Floor Drain	Girls 2nd Floor	1	EA	7	10+ years	
	Lavatory	Girls 2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girls 2nd Floor	4	EA	6	6-10 years	
	Partitions	Girls 2nd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	Girls 2nd Floor	366	SF	7	10+ years	
	Walls - Plaster/Drywall	Girls 2nd Floor	200	SF	6	10+ years	
	Water Closet	Girls 2nd Floor	5	EA	6	10+ years	
	Accessories	Girls 3rd Floor	247	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls 3rd Floor	247	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls 3rd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls 3rd Floor	247	SF	6	10+ years	
	Floor Drain	Girls 3rd Floor	1	EA	7	10+ years	
	Lavatory	Girls 3rd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girls 3rd Floor	4	EA	6	6-10 years	
	Partitions	Girls 3rd Floor	5	EA	7	10+ years	



Category : Room		Building : Main								
oulogo				unung	· main	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
0.000	Walls - Concrete Block	Girls 3rd Floor	566	SF	6	10+ years				
	Water Closet	Girls 3rd Floor	5	EA	6	10+ years				
	Accessories	Gym Office	25	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Gym Office	25	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Gym Office	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Gym Office	25	SF	7	10+ years				
	Lavatory	Gym Office	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Gym Office	1	EA	7	6-10 years				
	Walls - Concrete Block	Gym Office	. 47	SF	7	10+ years				
	Water Closet	Gym Office		EA	7	10+ years				
	Accessories	Main Office Restroom	32	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Main Office Restroom	32	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Main Office Restroom	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Main Office Restroom	32	SF	7	10+ years				
	Lavatory	Main Office Restroom	1	EA	7	10+ years				
	Lighting - Pendent/Surface	Main Office Restroom	1	EA	7	6-10 years				
	Walls - Concrete Block	Main Office Restroom	72	SF	7	10+ years				
	Walls - Concrete Block	Main Office Restroom	1	EA	7	10+ years				
			28	SF	7	,				
	Accessories	Men's Staff 1st Floor	28 28	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Men's Staff 1st Floor	20 1	EA	7	10+ years				
	Doors - Wood Doors inclu hw	Men's Staff 1st Floor				10+ years				
	Floor - Tile Ceramic/ Porcelain	Men's Staff 1st Floor	28	SF	7	10+ years				
	Lavatory	Men's Staff 1st Floor Men's Staff 1st Floor	1 1	EA EA	7 7	10+ years				
	Lighting - Pendent/Surface					6-10 years				
	Walls - Concrete Block	Men's Staff 1st Floor	55	SF	7	10+ years				
	Water Closet	Men's Staff 1st Floor	1	EA SF	7 7	10+ years				
	Accessories	Staff 2nd Floor	36	SF		6-10 years				
	Ceiling - Plaster/Drywall	Staff 2nd Floor	36		6	10+ years				
	Doors - Wood Doors inclu hw	Staff 2nd Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Staff 2nd Floor	36	SF	6	10+ years				
	Lavatory	Staff 2nd Floor	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Staff 2nd Floor	1	EA	6	6-10 years				
	Partitions	Staff 2nd Floor	1	EA	7	10+ years				
	Walls - Concrete Block	Staff 2nd Floor	93	SF	7	10+ years				
	Water Closet	Staff 2nd Floor	1	EA	6	10+ years				
	Accessories	Staff 3rd Floor	36	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Staff 3rd Floor	36	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Staff 3rd Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Staff 3rd Floor	36	SF	6	10+ years				
	Lavatory	Staff 3rd Floor	1	EA	7	10+ years				
	Lighting - Pendent/Surface	Staff 3rd Floor	1	EA	6	6-10 years				
	Partitions	Staff 3rd Floor	1	EA	7	10+ years				
	Walls - Concrete Block	Staff 3rd Floor	93	SF	7	10+ years				
	Water Closet	Staff 3rd Floor	1	EA	6	10+ years				



409 W 80th STREET, Chicago, IL 60620

Category : Room			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Women's Staff 1st Floor	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's Staff 1st Floor	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women's Staff 1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Staff 1st Floor	28	SF	7	10+ years	
	Lavatory	Women's Staff 1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's Staff 1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	Women's Staff 1st Floor	55	SF	7	10+ years	
	Water Closet	Women's Staff 1st Floor	1	EA	7	10+ years	

**Building : Main** 

#### **Category : Classroom**

Recommend Location Quantity Group Item - Type UOM Rank Replacement Comments Classroom #101 (Faculty Lounge) Casework 1st Floor 26 LF 6 10+ years SF Ceiling - Lay-in 1st Floor 700 6 10+ years Doors - Wood Doors inclu hw 1st Floor ΕA 6 10+ years 1 Floor - Tile SF 7 1st Floor 700 10+ years Lighting - Lay-in 7 6-10 years 1st Floor 10 EΑ Marker Board 1st Floor 16 LF 6 6-10 years Walls - Concrete Block SF 1st Floor 785 7 10+ years Walls - Structural Glazed Tile 1st Floor 114 SF 7 10+ years Classroom #102 (Kindergarten) Casework 1st Floor LF 26 6 10+ years Ceiling - Lay-in 1st Floor 700 SF 10+ years 6 Doors - Wood Doors inclu hw 1st Floor ΕA 7 10+ years 1 Floor - Tile 1st Floor 700 SF 7 10+ years Lighting - Lay-in 7 1st Floor 10 EΑ 6-10 years Marker Board LF 1st Floor 15 6 6-10 years SF Walls - Concrete Block 1st Floor 785 7 10+ years Walls - Structural Glazed Tile SF 7 1st Floor 114 10+ years Work Sink 1st Floor 1 ΕA 7 10+ years Classroom #104 (Pre School) Casework 1st Floor LF 21 6 10+ years Casework 1st Floor 17 LF 6 10+ years 1,027 SF Ceiling - Lay-in 1st Floor 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 ΕA 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 ΕA 7 10+ years Floor - Tile 1st Floor 1.027 SF 6 10+ years 7 Lighting - Lay-in 1st Floor 14 EΑ 6-10 years Marker Board LF 1st Floor 8 6-10 years 6 SF Storage/ Closet 1st Floor 94 7 10+ years



	Schools						409 W 80th STREET, Chicago, IL 60620
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	914	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	175	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
0							
Jassroo	om #106 (Pre School)						
	Casework	1st Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	997	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	30	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,027	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	914	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	145	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Neeeroo	om #201 (Regular Classroom)						
Jassio	,		07	LF	0	40	
	Casework	1st Floor	27		6	10+ years	
	Ceiling - Lay-in	1st Floor	725	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	715	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Chipping tiles
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	662	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	198	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	114	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	Casework	2nd Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	796	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	796	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	ĒA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	860	SF	6	10+ years	
lassro	om #203 (Regular Classroom)						
21033100	Casework	2nd Floor	27	LF	6	10+ years	
	Casework		21	LF	U	iut years	



	Schools						409 W 80th STREET, Chicago, IL 60620
Catego	Category : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Ceiling - Lay-in	2nd Floor	725	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	5	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	5	EA	5	1-2 years	Nonfunctional
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	114	SF	6	10+ years	
Classroo	om #204/206 (Regular Classroom)						
	Casework	2nd Floor	59	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,521	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,521	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	10+ years	
	Storage/ Closet	2nd Floor	75	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,324	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	396	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	140	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #205 (Regular Classroom)						
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	725	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	114	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #208/210 (Regular Classroom)						
	Casework	2nd Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,185	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
		21011001	10	-1	т		



<u> </u>	Schools						409 W 80th STREET, Chicago, IL 6062
Catego	Category : Classroom			uilding	: Main		
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,193	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,066	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	140	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroo	om #212 (Regular Classroom)						
	Casework	2nd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	717	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Missing tile
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	114	SF	7	10+ years	
Classroo	om #301 (Regular Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
lassroo	om #302 (Regular Classroom)						
2000100	Casework	3rd Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
				LF			
	Marker Board	3rd Floor	12	LF SF	6	6-10 years	Lookod
	Storage/ Closet	3rd Floor	71		7	10+ years	Locked
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	



Catego	ory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #303 (Regular Classroom)						
	Casework	3rd Floor	21	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
Closero	om #304 (Regular Classroom)						
01855100	Casework	3rd Floor	16	LF	6	101 10070	
	Casework Ceiling - Lay-in	3rd Floor 3rd Floor	725	SF	6 6	10+ years 10+ years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	4 6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	•	
	Lighting - Lay-in	3rd Floor	10	EA	6 6	10+ years 6-10 years	
	Storage/ Closet	3rd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	662	SF	6	•	
	Walls - Metal Panel	3rd Floor	198	SF	-	10+ years	
	Work Sink	3rd Floor	198	EA	6 7	10+ years	
	WOR SIIK	314 1001	I	LA	1	10+ years	
Classroo	om #305 (Regular Classroom)						
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classro	om #306 (Regular Classroom)						
0/03310(	Casework	3rd Floor	12	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	28	LF	6 4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	20	EA	4		
	Floor - Tile	3rd Floor 3rd Floor		SF	6 6	10+ years	
		3rd Floor 3rd Floor	725 10	EA	6 6	10+ years	
	Lighting - Lay-in	310 FI001	10	EA	0	6-10 years	



Category : Classroom		B	uilding	: Main			
	- ,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.00p	Walls - Concrete Block	3rd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	100	SF	6	10+ years	
			100	01	0	Tor years	
Classroc	om #307 (Regular Classroom)						
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Doors - Hardware	3rd Floor	1	EA	6	1-2 years	Loose hardware
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
Classroc	om #308 (Regular Classroom)						
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	10+ years	
	Floor - Tile	3rd Floor	700	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	96	SF	7	10+ years	
Classroc	om #309 (Regular Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	. <u>-</u> 1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
Classroo	om #310 (Regular Classroom)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	453	SF	7	10+ years	
	Chalk Board	3rd Floor	403	LF	4	2-5 years	
				EA			Missing same bardware
	Doors - Hardware	3rd Floor	1		6	1-2 years	Missing some hardware
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	453	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years	



	ichools						409 W 80th STREET, Chicago, IL 6062
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	1	EA	5	0-1 year	Does not work.
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	327	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	70	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	m #311 (Regular Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	700	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	6	10+ years	
Classroo	m #312 (Regular Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	700	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	6	10+ years	
		310 1001	114	36	0	10+ years	
Catego	ry : Interior		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor			-			•	
	Ceiling - Lay-in	1st Floor	3,288	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	112	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,152	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	40	SF	4	0-1 year	Cracked and chipped tiles, quantity updated to match current observations



	3010013						409 W 80th STREET, Chicago, IL 60620
Catego	Category : Interior			uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Lay-in	1st Floor	23	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	4,792	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,722	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	1	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,722	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	, 8	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	2,240	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,678	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	, 1	EA	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	1	EA	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,678	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	8	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	2,182	SF	6	10+ years	
			_,	0.	Ũ	i o i goulo	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Metal Detector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
	Security Cameras	ISt FIOD	4	EA	1	0-10 years	
Ctains							
Stairs	Cailing Low in	East	250	00	7	10, , , , , , , , , , , , , , , , , , ,	
	Ceiling - Lay-in		350 150	SF SF	7	10+ years	
	Ceiling - Plaster/Drywall	East		SF	7	10+ years	
	Floor - Terrazzo	East	416		7	10+ years	
	Floor - Tile	East	712	SF	7	10+ years	
	Handrails	East	112	LF	7	10+ years	
	Lighting - Lay-in	East	10	EA	7	6-10 years	
	Lighting - Wall Mounted	East	8	EA	7	6-10 years	
	Stairs - Terrazzo	East	314	LF	7	10+ years	
	Stairs - Tile	East	204	LF	7	10+ years	
	Walls - Concrete Block	East	1,584	SF	7	10+ years	
	Ceiling - Lay-in	West	1,136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	150	SF	6	10+ years	
	Floor - Terrazzo	West	416	SF	6	10+ years	
	Floor - Tile	West	712	SF	6	10+ years	
	Handrails	West	112	LF	7	10+ years	
	Lighting - Lay-in	West	10	EA	6	6-10 years	
	Lighting - Wall Mounted	West	8	EA	6	6-10 years	
	Stairs - Terrazzo	West	314	LF	6	10+ years	
	Stairs - Tile	West	204	LF	6	10+ years	
	Walls - Concrete Block	West	1,584	SF	6	10+ years	



Catego	ry : Exterior		Building : Linked Addition Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance								
	Exterior Doors - Exterior Steel Door	10	2	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	10	_ 1	EA	4	0-1 year	Corroded doors	
	Exterior Doors - Exterior Steel Door	8	3	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	9	2	EA	5	0-1 year	Corroding	
Foundat	ion							
	Foundation - Concrete	Entire Building	392	LF	7	10+ years		
	Superstructure - Concrete	Entire Building	7,998	SF	7	10+ years		
Lighting								
5 5	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years		
Roof Sy:	stem							
	Coping - Metal	Roof C	104	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof C	44	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof C	104	LF	6	10+ years		
	Roof - Modified Bitumen	Roof C	1,014	SF	4	0-1 year	Surface is pulling away at the parapets	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof C	1,014	SF	7	10+ years		
	Chimney - Metal Flue	Roof D	15	LF	6	10+ years		
	Coping - Metal	Roof D	312	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof D	56	LF	6	10+ years		
	Parapet - Parapet < 16" Height	Roof D	312	LF	7	10+ years		
	Parapet - Parapet > 30"	Roof D	45	LF	7	10+ years		
	Roof - Modified Bitumen	Roof D	6,884	SF	5	2-5 years		
	Roof - Modified Bitumen	Roof D	100	SF	4	0-1 year	Visible size of ponding area, open seams/soft spots.	
	Roof Structure - Concrete	Roof D	6,984	SF	7	10+ years		
Nalls								
	Exterior Walls - Brick	Entire Building	4,838	SF	7	10+ years		
	Exterior Walls - Brick	Entire Building	200	SF	6	10+ years		
Windows	S							
	Guard - Guards perforated	Entire Building	480	SF	7	10+ years		
	Lintels - Steel	Entire Building	102	LF	7	10+ years		
	Windows - Casement Aluminum Double- pane	Entire Building	480	SF	6	10+ years		



	Schools						409 W 80th STREET, Chicago, IL 60620
Catego	ory : Electrical		В	uilding	d Addition		
_						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
	Security System - Intrusion Detection	1st Floor	7,998	SF	5	2-5 years	
	Emergency Battery Packs - Corridors and	Corridors and Stairs	5	EA	6	2-5 years	
	Stairs	Fatian Duildin a	4		4	1.0	Detectorized a second a second built
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	4	1-2 years	Dated signs using incandescent bulk
Main Se	rvice						
	PA System	Entire Building	7,998	SF	5	2-5 years	
	Main Electrical Service - 800 A and Less than 120/240/3PH	South Facade	1	EA	6	6-10 years	
Power D	Distribution						
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	10+ years	
Catego	ory : Fire Protection		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Ala							
	Fire Alarm Strobe Lights	1st Floor	7,998	SF	6	6-10 years	
	Fire Alarm_System	1st Floor	7,998	SF	6	6-10 years	
Sprinkle	r System						
	Sprinkler Heads	Entire Building	7,998	SF	7	10+ years	
	Sprinkler Piping	Entire Building	7,998	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	7,998	SF	6	10+ years	
Catego	ory : Mechanical		В	uildina	: Linked	d Addition	
J	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
0	Wall Heater - Electric	Entire Building	3	EA	5	6-10 years	
Tempera	ature Control						
•	Electric Thermostat	1st Floor	6	EA	5	6-10 years	
Unit Ver	ntilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Facade	6	EA	5	2-5 years	
Ventilati	on						
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	6	EA	6	6-10 years	



<u> </u>							403 W 0001 011(EET, 0110ag0, 12 00020
Catego	Category : Mechanical		В	uildina	: Linked	d Addition	
	•			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
Group	CFM	Location	Quantity		Nain	Replacement	Ovinitients
•	<b>_</b>		_				
Catego	ry : Plumbing		B	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	6-10 years	
Piping							
1 0	Domestic Piping-Hot Water Return Lines	Entire Building	7,998	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	7,998	SF	6	10+ years	
	(Horizontal Lines)		1,000	51	U	ior yours	
	Sanitary Piping	Entire Building	7,998	SF	6	10+ years	
		5		-	-		
	Storm Piping	Entire Building	7,998	SF	6	10+ years	
	Vent Piping	Entire Building	7,998	SF	6	10+ years	
Catego	ry : Classroom		B	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	om #111 (Computer Lab)						
			700	05	7	40	
	Ceiling - Lay-in	1st Floor	790	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years	Rank updated to match current
							observations
	Storage/ Closet	1st Floor	91	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
	- ,						
Classrer	om #112 (Computer Lab)						
			700	0-	-	10	
	Ceiling - Lay-in	1st Floor	790	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	73	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
	2					<b>,</b>	
Closerer	m #112 (Pagular Classroom)						
	om #113 (Regular Classroom)			. –			
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	780	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	10	SF	4	0-1 year	Water damage, rank and quantity



Catego	ry : Classroom		В	uilding	: Linked	Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							updated to match current
							observations
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	91	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #114 (Regular Classroom)						
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	790	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	73	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #115 (Office)						
	Ceiling - Lay-in	1st Floor	778	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
Classroo	om #116 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	782	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	0-1 year	Stained and bent tiles, rank change to match current observations
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
				SF			



			uilding	409 W 80th STREET, Chicago, IL 806			
Category : Room							
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
IDF_ID	F						
	Doors - Wood Doors inclu hw	Room 111	1	EA	7	10+ years	
	Finishes	Room 111	84	SF	7	6-10 years	
	Other Cooling Unit	Room 111	1	EA	7	6-10 years	Central air
lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	51	SF	7	10+ years	
estroor	n						
001	Accessories	Men's 1st Floor	167	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's 1st Floor	167	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men's 1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's 1st Floor	167	SF	7	10+ years	
	Floor Drain	Men's 1st Floor	1	EA	7	10+ years	
	Hand Dryer	Men's 1st Floor	1	EA	7	6-10 years	
	Lavatory	Men's 1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Men's 1st Floor	1	EA	7	6-10 years	
	Partitions	Men's 1st Floor	2	EA	7	10+ years	
	Urinals	Men's 1st Floor	2	EA	7	10+ years	
	Walls - Metal Panel	Men's 1st Floor	420	SF	7	10+ years	
	Water Closet	Men's 1st Floor	2	EA	7	10+ years	
	Accessories	Women's 1st Floor	185	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's 1st Floor	185	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women's 1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's 1st Floor	185	SF	7	10+ years	
	Floor Drain	Women's 1st Floor	1	EA	7	10+ years	
	Hand Dryer	Women's 1st Floor	1	EA	7	6-10 years	
	Lavatory	Women's 1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's 1st Floor	2	EA	7	6-10 years	
	Partitions	Women's 1st Floor	4	EA	7	10+ years	
	Walls - Metal Panel	Women's 1st Floor	443	SF	7	10+ years	
	Water Closet	Women's 1st Floor	4	EA	7	10+ years	
atego	ry : Interior		В	uildina	: Linked	d Addition	
Ŭ	•			Ŭ		Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	Corridors & Vestibules	1,643	SF	7	10+ years	
	Doors - Steel Doors incl hw	Corridors & Vestibules	6	EA	7	10+ years	
	Doors - Wood Doors include hw	Corridors & Vestibules	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	Corridors & Vestibules	2	EA	7	10+ years	
	Floor - Tile/Sheet	Corridors & Vestibules	1,623	SF	7	10+ years	
	Floor - Tile/Sheet	Corridors & Vestibules	20	SF	4	1-2 years	Cracks



_										
	Category : Interior			В	uilding	: Linked				
				Recommend						
	Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		Lighting - Lay-in	Corridors & Vestibules	19	EA	7	6-10 years			
		Walls - Plaster/Drywall	Corridors & Vestibules	2,396	SF	7	10+ years			



Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Natural	South Site	41,680	SF	6	6-10 years	
	Surface - Asphalt	South Site	13,120	SF	6	2-5 years	
	Surface - Asphalt	South Site	600	SF	4	0-1 year	Verified large cracks, verified area of damage
	Surface - Asphalt	South Site	10,482	SF	6	2-5 years	5
	Surface - Asphalt	South Site	200	SF	4	0-1 year	Large cracks with growing vegetation
Civil/Drai	nage						
	Civil/ Drainage - Bioswale	Entire Site	3	SF	7	10+ years	
	Civil/ Drainage - Bioswale	Entire Site	3	SF	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	6	10+ years	
Fencing							
0	Fencing - Chain Link	Entire Site	684	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	12	LF	4	0-1 year	Broken or removed top rails, rolled links
	Fencing - New Standard Ornamental	Entire Site	132	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	132	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	2,156	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	16	LF	4	1-2 years	Fence bent, and damaged by impace Bent out of shape.
Landsca							
anusca	Benches	Entire Site	10	EA	6	10+ years	
	Landscape - Grass	Entire Site	107,585	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	400	SF	7	10+ years	New
	Landscape - Hardscape- Concrete	Entire Site	3,635	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	5,400	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	9	EA	6	10+ years	
	Lighting - Pole Mounted	Entire Site	9	EA	6	10+ years	
	Parkway trees	Entire Site	3	EA	6	10+ years	Trimmed
	Parkway trees	Entire Site	63	EA	6	10+ years	
	Parkway trees	Entire Site	3	EA	6	10+ years	Repaired, trimmed
	Planting Beds/ Area	Entire Site	810	SF	6	10+ years	Ropanou, unimou
	Play Area - Hardscape- Asphalt	Entire Site	2,280	SF	7	10+ years	
	Trash Receptacles	Entire Site	2,200	EA	6	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	200	SF	7	10+ years	
Parking L	ot						
_ uning t	Concrete Curbs	Parking Lot- West	757	LF	7	10+ years	



							409 W 6011 STREET, Chicago, IL 60620
Category : Site			В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Interior Plantings	Parking Lot- West	308	LF	6	10+ years	
	Lighting - Pole Mounted	Parking Lot- West	4	EA	6	10+ years	
	Surface - Asphalt	Parking Lot- West	20,859	SF	6	6-10 years	
	Surface - Asphalt	Parking Lot- West	500	SF	4	0-1 year	Large cracks and some depressions
	Surface - Concrete	Parking Lot- West	2,542	SF	7	10+ years	
	Trash Compactor	Parking Lot- West	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- West	481	SF	7	10+ years	
Playgrou	Ind						
	Equipment - Pre K 3-5	North Site	1	EA	6	10+ years	
	Surface - Poured Surface	North Site	1,767	SF	4	0-1 year	Tears, cracks, and holes.
	Equipment - School Age 5-12	South Site	1	EA	7	10+ years	
	Surface - Poured Surface	South Site	2,865	SF	6	10+ years	
	Surface - Poured Surface	South Site	50	SF	4	0-1 year	Torn, broken surface
Sidewall	(5						
	Sidewalks - Internal Walks	Entire Site	2,002	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	50	LF	4	0-1 year	Consolidated numbers, broken, cracked
	Sidewalks - Perimeter Sidewalks	Entire Site	14,974	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	4	0-1 year	Upheaved, broken
Signage							
3 3-	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	4	0-1 year	Deteriorated sign, not in use
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	10+ years	-
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



#### **Classroom Summary**

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		1							
Faculty Lounge	Regular Classroom	1st Floor	101	127	700	92	10	Y	N
Kindergarten	Regular Classroom	1st Floor	102	130	700	97	10	Y	Y
Pre School	Kindergarten	1st Floor	104	128	1,027	114	15	Y	Y
Pre School	Kindergarten	1st Floor	106	124	1,027	114	15	Y	Y
Regular Classroom	Regular Classroom	1st Floor	201	231	725	97	10	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	230	796	97	10	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	203	229	725	97	10	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204/206	224/226	1,521	194	20	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	205	227	725	97	10	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	208/210	224/222	1,193	193	20	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	212	228	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	301	331	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	302	329	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	304	328	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	305	327	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	306	326	725	97	10	Y	N
Regular Classroom	Regular Classroom	3rd Floor	307	325	725	68	17	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	324	700	97	10		Y
Regular Classroom	Regular Classroom	3rd Floor	309	323	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	310	32s	453	53	5		N
Regular Classroom	Regular Classroom	3rd Floor	311	321	700	97	10	N	Y
Regular Classroom	Regular Classroom	3rd Floor	312	320	700	97	10	Y	Y
Building : Linked Addition									
Computer Lab	Regular Classroom	1st Floor	111	001	790	78	26	N	Y
Computer Lab	Regular Classroom	1st Floor	112	003	790	78	26	N	N
Office	Regular Classroom	1st Floor	112	003	790	78	26	N	N
Regular Classroom			113	009	790	78	26	N	Y
0	Regular Classroom	1st Floor 1st Floor	113	002		78		N	Y Y
Regular Classroom	Regular Classroom			004	790		26		Y Y
Regular Classroom	Regular Classroom	1st Floor	116		790	78	26	N	Ý